SZS CONSULTING GROUP

OREGON STATE UNIVERSITY (OSU)

DRYDEN HALL

ADA ASSESSMENT & SURVEY



Sacramento Office 770 L Street, Suite 950 Sacramento, CA 95814 Tel: 916.669.8750 Fax: 888.211.7441

Silicon Valley Office 2225 E. Bayshore Road, Suite 200 Palo Alto CA 94303 Tel: 866.694.7637 www.szs-consulting.com

April 20, 2017



GABRIEL MERRELL DIRECTOR, ACCESS AND AFFIRMATIVE ACTION OFFICE OF EQUAL OPPORTUNITY AND ACCESS **OREGON STATE UNIVERSITY** 330 SNELL HALL CORVALLIS, OR 97331

Re: ADA Accessibility Survey and Assessment – Dryden Hall

Dear Gabriel,

We are pleased to submit this report for Dryden Hall. This report is part of our project to provide a Campus Accessibility Survey and Assessment for Oregon State University. It is our hope that this report will assist OSU in improving access to people with disabilities to campus facilities.

SZS has been pleased to be a part of this effort to evaluate campus buildings using federal and state statutes and regulations, as well as universal design principles in order to create performance standards that will guide design, construction and maintenance on campus.

We look forward to discussing our findings with your team.

Regards,

Syroun Z. Sanossian, Principal

Syn Z. Son.

SZS Consulting Group LLC

TABLE OF CONTENTS

1.	EXECUTI	VE SUMMARY OF FINDINGS	p. 1
	a.	Pedestrian Facilities and Exterior Spaces Analyzed	p. 2
	b.	Building Entrances	p. 3
2.	INTERIOR	R SPACES	
		First Floor	p. 3
		Second Floor	p. 5
		Third Floor	p. 5
3.	BARRIE	R DATA RECORDS	
		Exterior Area Barriers	p. 6
		Interior Area Barriers	p. 16
		Cost Estimate	n 24

1. EXECUTIVE SUMMARY OF FINDINGS

The field investigation for the interior spaces began on January 28, 2017. The exterior site elements were assessed originally as part of the pedestrian facilities assessment, in June to September 2011, and are included as an essential part of this report. Images of each physical element identified in this report were captured in HD digital photos while manual measurements were taken to establish as-built conditions to facilitate the process of cost estimating. Digital photographs are provided within the report for each barrier to access, to facilitate the review of the data collected. We have found that technical data can be difficult to interpret without a visual component; the photos provide a clear connection between the technical data and each barrier to access.

Dryden Hall is a historic structure and many barriers to access were identified in the building. That is quite typical, as barriers to access exist in virtually every building, whether new or existing.

No "perfect" building exists in the real world.

This ADA Assessment and Survey report is intended to not only identify barriers to access, but to provide solutions. The basis for this ADA Assessment and Survey process is the underlying desire on the part of OSU to improve access by relying on higher standards than the minimum requirements in state and federal building codes. SZS intends to provide the information in this report in a clear and easy to understand format. The information in this report is compiled for use by designated OSU staff and other interested persons, so the content is designed to be understood by professionals and laymen alike.

The findings presented are both narrative and technical in nature; barriers to access identified during the field investigation process are documented in two ways;

Narrative Analysis: The analysis of findings is contained in an executive summary in a
narrative form that not only describes each type of barrier identified, but also provides a
discussion that analyses the functionality of physical elements. We also provide the
reasoning and research behind the identification of barriers that conflict with universal
design principles. This analysis may be accompanied by digital photographs or
diagrams, where applicable.

NOTE: Understanding building function and usage is essential when interpreting the findings held in this report. The narrative is intended to facilitate this process.

2. <u>Barrier Data Records:</u> Individual barriers to access are entered into the SZS database so that technical information on the barriers can be provided as barrier data records. These barrier data records include digital photographs of each barrier identified, code references that determine the barrier to access, as-built measurements, barrier severity ratings, budgetary cost estimates, recommended solutions for barrier removal and a priority for barrier removal. The information is formatted with two barriers on each report page.

In order to consolidate the report data, some of the more typical barriers found in multiple locations have been grouped within the barrier data records with a description of the locations in which they were found.

A. Pedestrian Facilities and Exterior Spaces Analyzed

This report provides information on campus pedestrian facilities that serve Dryden Hall. Many physical elements are part of the comprehensive whole that creates a pedestrian facility. The fundamental elements evaluated as to whether they provide accessible pedestrian facilities include the following:

- Sidewalks
- Walkways
- Ramps
- Curb Ramps
- Blended Transitions
- Signalized Intersections
- Stairways (94% of people with disabilities are not mobility impaired)
- Benches and other Seating Elements
- Picnic Facilities

The descriptions provided for physical elements in this report are intended to clearly describe the differences between each physical element, such as when a pedestrian route is a sidewalk, rather than a walkway. The descriptions are intended to explain how the elements interact to form a cohesive pedestrian facility. Other more specific information described within this section intends to provide guidance on determinations made in this report.

The key to providing accessible pedestrian facilities is in recognizing that different people with disabilities have different needs. Setting policies that speak to the entire group is essential, rather than focusing on one particular subset of the overall group. Universal design principles govern here – physical elements should be usable to everyone that visits campus without having to resort to any adaptation or specialized design.

In summary, an accessible route exists within a building, property boundary or interior space and is separate from the PROW. Pedestrian walkways are similar to sidewalks as paved surfaces improved for use by pedestrians, but walkways are not located along or adjacent to the curb line, gutter or roadway and walkways are generally not considered part of the PROW. The pedestrian facility is the combination of the PROW and the accessible route, which functions as a whole to provide pedestrian access to facility entrances.

As a public building that was constructed prior to the passage of the ADA, Dryden Hall should have at least one accessible entrance. An accessible entrance was identified on the west side of the building. This entrance was identified with a sloped walkway that leads to the first floor main entrance and a corridor where an elevator can be used by passengers to reach all floors.

Dryden Hall has an accessible route provided within the site from accessible parking spaces and accessible passenger loading zones; public streets and sidewalks; and public transportation stops to the accessible building or facility entrance they serve¹ as compared to the 2010 ADA Standard for Accessible Design. Details on barriers identified in that route are provided within the ADA Assessment and Survey of the pedestrian facilities (provided as a separate report) as well as in the following records. Please see the barrier data records for details.

B. Building Entrances

The building is located along SW 30th Street across from Campus Intramural Field within campus. Parking is provided on-site. An exterior pedestrian ramp is provided as part of an accessible route from the existing parking to the accessible building entrance. An accessible grade level pedestrian entrance to the building is provided on the east and west side of the building although the east side door lacked an ISA sign. Also, BHMA signage is needed where automatic doors are installed. Stairways and ramps are located at several locations around the building and ISA directional signage is recommended for these locations to help ensure that pedestrians seeking an accessible entrance are not forced to retrace their steps. As a performance standard, it is recommended that where a powered door is provided in a building or facility, a sign displaying the International Symbol of Accessibility (ISA) measuring at least 4" x 4" should accompany the automatic door actuating mechanism and that signage needs to provide a 70% contrast against the background wall surface (dark-on-light or light-on-dark).

INTERIOR SPACES

FIRST FLOOR

Dryden Hall is a three-story historic structure built in 1927. It is a pre-ADA building but alterations have been performed in the building several times. The first floor provides classrooms, biology classrooms, wet laboratories, a sterilization room, graduate student offices, a break room, a reading room, and a men and women's restroom.

An elevator provides vertical access through the building. The elevator car is large enough to carry passengers using wheelchairs but it was identified with older emergency controls located at 28" high within a cabinet involving voice communication, which may not be possible for the deaf and speech impaired users. Also, visual and audible signals were not identified outside of the elevator. Additional functional issues identified at the elevator included a lack of a door delay when the doors meet an obstruction and reopens, and car call buttons were not within reach range.

The main entrance was identified with an automatic door opening device. The automatic devices were functional, but the doors lacked BHMA signs meant as a safety precaution for able-bodied people to identify the doors as automatic. Doors leading to other exit doors lacked tactile exit signage. The hall and entry vestibule were identified with a fire pull that

_

¹ 2010 ADA Standards for Accessible Design, Section 206.2.1 Site Arrival Points

was not accessible, a heater created protruding objects within the circulation route and doormats were not secured.

As a performance standard, it is recommended that lobby identification signage be provided on each floor in each central corridor that indicates the floor plan, the location of the person viewing the sign and the location of accessible features such as restrooms, elevators and drinking fountains in proximity to the location of the person reading the sign. The lobby is attached to a stairway and the exit door is directly connected to accessible parking lots.

The only stairway in the building was located centrally and was outdated due to its non-accessible handrails and guardrails. No stairway level identification signage or contrasting color was identified at the stairway treads, which is needed for the visually impaired, and the stairway riser height was not consistent from step to step. This can cause difficulty for pedestrians with disabilities. As a performance standard, it is highly recommended to provide contrasting color at stairway treads to improve visibility for all users.

One drinking fountain was installed within the lobby area, but it was not located within an alcove or otherwise provided with detectable warnings. The fountain was a low fountain intended to be wheelchair accessible, but no fountain is provided on the first floor for people with bending and stooping injuries.

Most of the common use spaces on this floor lacked visual signal appliances (strobes), although horns connected to the fire alarm system were installed in central corridor. Lobby and restroom areas lacked both visual and audible signal appliances (strobes and horn).

The classrooms, break room, reading room, laboratory and graduate office were often identified with adequate space, but were filled with desks and tables that could obstruct passageway for able-bodied people, as well as those with mobility impairments. Some of the rooms lacked entry doors that operated with accessible opening force. Also, controls such as electrical switches and outlets were not located within accessible reach ranges. Visual and tactile signage was provided at the classroom and laboratory door, on this level, but the signs were designed with sharp and abrasive edges.

The breakroom and reading room were also identified with non-accessible counters, sinks and tables and no horn/strobes were provided. Classrooms and wet laboratories lacked an accessible ISA sign, door operating force where closers were installed, door maneuvering clearance and view panels. The clear floor space needed to enable use of fume hoods, biosafety cabinets, and equipment was often blocked by furniture or stored items (in some locations). The spaces generally lacked accessible light switches and outlets, accessible desks, microscopes, computer workstations, coat hooks and strobe devices. The sinks were not accessible for wheelchair users and short people.

The men and women's restrooms were identified with automatic door opening devices on the first floor. These devices were functional, but lacked BHMA signs. The restrooms were identified with a high level of access, but barriers were noted such as a push-button faucet that did not remain open for at least 2 seconds, protruding paper towel dispensers and a free-standing counter within the circulation path. The wheelchair accessible toilet stall was identified without a door closing device, which is a functional issue for people with disabilities. The toilet room also lacked a horn device, to warn the visually impaired, and a strobe device, to warn the hearing impaired.

Many *staff use only* areas were identified in the building. These spaces included IT rooms, janitorial rooms, private faculty offices and associated spaces. Signage at the door and doorway to these spaces were included in this report as it was located along the public circulation route of travel, but these interior spaces were not investigated as part of this assessment process. In general, institutions and organizations make staff use only areas accessible as needed through the reasonable accommodation iterative process between the employer and employee.

SECOND FLOOR

This floor was identified with a waiting room, classrooms, a biology lab, and women's restroom. No room informational signs, horn or visual signal appliances were identified but tactile exit sign, and evacuation plans were provided. The second floor had many laboratories used by graduate students where equipment such as fume hoods, workstations, counters and sinks were not accessible. In addition, entry doors were not accessible and there was inadequate maneuvering space available for the number of physical elements or instruments placed inside these classrooms, laboratories or practice areas.

One drinking fountain was installed on this floor, but it was not located within an alcove or otherwise provided with detectable warnings. The fountain was a low fountain intended to be wheelchair accessible, but the bubbler height was too high (non-accessible) for people who are short or who use wheelchairs, and too low for people with bending and stooping injuries. Otherwise, the barriers identified on this floor were similar to those detailed on the first floor.

THIRD FLOOR

The areas on the third floor were included in this scope of work because public spaces included a central hall, stairway and unisex restroom. Barriers identified on the third floor were similar to the second floor noted above. A hi-low drinking fountain unit was identified in the third floor corridor, but the fixture was not located in an alcove and the location, adjacent to an ice machine, encroached into the clear floor space needed by people using wheelchairs. The unisex restroom had two adjacent spaces with a lavatory, mirror and dispensers in the first space (entered from the central hallway), and toilet stalls and a wheelchair accessible stall located in the second space. The entry doors to each of these spaces were identified with heavy doors and a maneuvering clearance that was not wheelchair accessible, as well as door hardware and door view panels that were not accessible. Maneuvering clearance was not wheelchair accessible in both of the restroom spaces.

The following barrier data records provide more detailed information on the barriers described above.





Field Date:	7/22/2011 Report Date 7/22/2011 Barrier #: 2586A
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Location:	Exterior - North Entrance Stairway
X Coordinate:	7476351.841 Y Coordinate: 339374.79
Barrier Area:	Stairways
Barrier Type:	Handrail - Both Sides
Code References:	OSSC 1109.8.6 and 2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built : 225
Barrier Description:	No handrail provided at both sides of stairway
Findings:	No handrail provided at both sides
Rec. Solution:	Provide accessible handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/22/2011 Report Date 7/22/2011 Barrier #: 2586B
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Location:	Exterior - North Entrance Stairway
X Coordinate:	7476351.841 Y Coordinate: 339374.79
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code References:	2010 ADAS Advisory 504.4
Performance Sta	ndard: Yes Quantity: LF or TR As-built: 35
Barrier Description:	No contrasting color on each tread of exterior stairway
Findings:	No contrasting color provided
Rec. Solution:	Consider providing contrasting color on each tread
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	7/22/2011 Report Date 7/22/2011 Barrier #: 2586C
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Location:	Exterior - North Entrance Stairway
X Coordinate:	7476351.841 Y Coordinate: 339374.79
Barrier Area:	Stairways
Barrier Type:	Vertical Access - Directional Sign
Code References:	2010 ADAS 403.1
Performance Sta	andard: No Quantity: EACH As-built: 125
Barrier Description:	No form of vertical access provided at stairway to reach entry door or upper floors
Findings:	No information on alternate accessible entrance to building
Rec. Solution:	Provide directional sign leading to accessible entry
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/22/2011 Report Date 7/22/2011 Barrier #: 2587
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Location:	Exterior - North Entrance
X Coordinate:	7476351.559 Y Coordinate: 339370.818
Barrier Area:	Doors or Gates
Barrier Type:	Door/Gate Landing - Existing (2.1% to 3.0%)
Code References:	2010 ADAS 404.2.4.4
Performance Sta	andard: No Quantity: SF As-built: 125
Barrier Description:	Door or gate lacks landing on both sides of door
Findings:	2.9% slope
Rec. Solution:	Demolish and reconstruct level landing
Rec. Solution: Barrier Severity:	
	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	7/22/2011 Report Date 7/22/2011 Barrier #: 2588
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Location:	Exterior - North Walkway
X Coordinate:	7476347.584 Y Coordinate: 339380.277
Barrier Area:	Walkways
Barrier Type:	Detectable Warnings - Incorrect Application
Code References:	Performance Standard 113422-0530
Performance Sta	ndard: Yes Quantity: JOB As-built : 500
Barrier Description:	Detectable warning (truncated domes) incorrectly installed
Findings:	Incorrect placement of detectable warning in parking lot
Rec. Solution:	Remove truncated domes where no hazardous situation exists
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/22/2011 Report Date 7/22/2011 Barrier #: 2589A
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Location:	Exterior - North Walkway
X Coordinate:	7476344.633 Y Coordinate: 339389.866
Barrier Area:	Signage
Barrier Type:	Directional Sign
Code References:	2010 ADAS 216.4.3 and 703.5
Performance Sta	ndard: No Quantity: EACH As-built : 250
Barrier Description:	No directional signage provided where accessible route diverges from main route
Findings:	No signage provided
Rec. Solution:	Provide accessible directional signage
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	7/22/2011 Report Date 7/22/2011 Barrier #: 2589B
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Location:	Exterior - North Walkway
X Coordinate:	7476344.633 Y Coordinate: 339389.866
Barrier Area:	Walkways
Barrier Type:	Construction Site - No Access
Code References:	MUTCD Section 6D.01
Performance Sta	andard: No Quantity: LF As-built : 45
Barrier Description:	Construction site creates barriers to pedestrians where no alternate route is provided
Findings:	No detectable warning provided at construction barricade
Rec. Solution:	Provide cane detectable warning across the full width of sidewalk
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes: People	with disabilities may be forced to retrace their steps
Field Date:	7/22/2011 Report Date 7/22/2011 Barrier #: 2590
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Location:	Exterior - North Walkway
X Coordinate:	7476378.751 Y Coordinate: 339384.772
Barrier Area:	Walkways
Barrier Type:	Clear Width - ADA Existing (less than 30")
Code References:	OSSC 1109.4.2 and 2010 ADAS 403.5.1
Performance Sta	andard: No Quantity: EACH As-built : 250
Barrier Description:	Pedestrian route is not min. 36" wide (less than 30")
Findings:	0" clear width due to foliage growth
Rec. Solution:	Trim foliage to provide min. 36" clear width
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	7/22/2011 Report Date 7/22/2011 Barrier #: 2591A
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Location:	Exterior - East Entrance Stairway
X Coordinate:	7476418.057 Y Coordinate: 339321.248
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code References:	2010 ADAS Advisory 504.4
Performance Sta	ndard: Yes Quantity: LF or TR As-built: 35
Barrier Description:	No contrasting color on each tread of exterior stairway
Findings:	No contrasting color provided
Rec. Solution:	Consider providing contrasting color on each tread
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/22/2011 Report Date 7/22/2011 Barrier #: 2591B
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Location:	Exterior - East Entrance Stairway
X Coordinate:	7476418.057 Y Coordinate: 339321.248
Barrier Area:	Stairways
Barrier Type:	Handrail Grip
Code References:	OSSC 1109.8.6
Performance Sta	ndard: No Quantity: LF As-built: 225
Barrier Description:	Handrail grip is not 1-1/4" - 1-1/2" in diameter
Findings:	4-1/2" rectangular handrail grip perimeter
Rec. Solution:	Provide accessible handrails at both sides of stairway
Barrier Severity:	Cost Fet 60.00
	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	



Field Date:	7/22/2011 Report Date 7/22/2011 Barrier #: 2591C
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Location:	Exterior - East Entrance Stairway
X Coordinate:	7476418.057 Y Coordinate: 339321.248
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Top
Code References:	OSSC 1109.8.6.(2)
Performance Sta	ndard: No Quantity: LF As-built : 225
Barrier Description:	Top Handrail extension not parallel to ground/floor surface
Findings:	Top handrail extension not parallel to ground surface
Rec. Solution:	Provide accessible handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/22/2011 Report Date 7/22/2011 Barrier #: 2591C
Bldg Name:	
DIUS Maille.	Dryden Hall Reference Dwg: 1 of 1
Location:	Dryden Hall Reference Dwg: 1 of 1 Exterior - East Entrance Stairway
_	
Location:	Exterior - East Entrance Stairway
Location: X Coordinate:	Exterior - East Entrance Stairway 7476418.057 Y Coordinate: 339321.248
Location: X Coordinate: Barrier Area:	Exterior - East Entrance Stairway 7476418.057 Y Coordinate: 339321.248 Stairways
Location: X Coordinate: Barrier Area: Barrier Type: Code	Exterior - East Entrance Stairway 7476418.057 Y Coordinate: 339321.248 Stairways Vertical Access - Directional Sign 2010 ADAS 403.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Exterior - East Entrance Stairway 7476418.057 Y Coordinate: 339321.248 Stairways Vertical Access - Directional Sign 2010 ADAS 403.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Exterior - East Entrance Stairway 7476418.057 Y Coordinate: 339321.248 Stairways Vertical Access - Directional Sign 2010 ADAS 403.1 ndard: No Quantity: EACH As-built: 125
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Exterior - East Entrance Stairway 7476418.057 Y Coordinate: 339321.248 Stairways Vertical Access - Directional Sign 2010 ADAS 403.1 ndard: No Quantity: EACH As-built: 125 No form of vertical access provided at stairway to reach entry door or upper floors
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Exterior - East Entrance Stairway 7476418.057 Y Coordinate: 339321.248 Stairways Vertical Access - Directional Sign 2010 ADAS 403.1 ndard: No Quantity: EACH As-built: 125 No form of vertical access provided at stairway to reach entry door or upper floors No information on alternate accessible entrance to building
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Exterior - East Entrance Stairway 7476418.057 Y Coordinate: 339321.248 Stairways Vertical Access - Directional Sign 2010 ADAS 403.1 ndard: No Quantity: EACH As-built: 125 No form of vertical access provided at stairway to reach entry door or upper floors No information on alternate accessible entrance to building Provide directional sign leading to accessible entry 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	7/22/2014 Poport Data 7/22/2014 Parrier #: 2502
	7/22/2011 Report Date 7/22/2011 Barrier #: 2592
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Location:	Exterior - Southwest Entrance Walkway
	7476332.733 Y Coordinate: 339256.459
Barrier Area:	Ivvaikways
Barrier Type:	Running Slope - Existing (5.0% - 8.2%)
Code References:	OSSC 1103.2.4.3 and 2010 ADAS 403.3
Performance Sta	ndard: No Quantity: LF As-built : 45
Barrier Description:	Walkway running slope exceeds 5.0% (5.0% - 5.5%)
Findings:	5.6% running slope
Rec. Solution:	Provide accessible handrails at both sides with landings where needed
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/22/2011 Report Date 7/22/2011 Barrier #: 2593A
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Location:	Exterior - Southwest Entrance Stairway
X Coordinate:	7476334.814 Y Coordinate: 339257.402
	7470554.614 1 Coordinate.
Barrier Area:	Stairways
Barrier Area: Barrier Type:	170
	Stairways
Barrier Type: Code	Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4
Barrier Type: Code References:	Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4
Barrier Type: Code References: Performance Sta Barrier	Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 ndard: Yes Quantity: LF or TR As-built: 35
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 ndard: Yes Quantity: LF or TR As-built: 35 No contrasting color on each tread of exterior stairway
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 ndard: Yes Quantity: LF or TR As-built: 35 No contrasting color on each tread of exterior stairway No contrasting color provided
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 ndard: Yes Quantity: LF or TR As-built: 35 No contrasting color on each tread of exterior stairway No contrasting color provided Consider providing contrasting color on each tread 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open




Ciald Date:	
Field Date:	7/22/2011 Report Date 7/22/2011 Barrier #: 2593B
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Location:	Exterior - Southwest Entrance Stairway
X Coordinate:	7476334.814 Y Coordinate: 339257.402
Barrier Area:	Stairways
Barrier Type:	Handrail - Both Sides
Code References:	OSSC 1109.8.6 and 2010 ADAS 505.10.2
Performance Sta	andard: No Quantity: LF As-built : 225
Barrier Description:	No handrail provided at both sides of stairway
Findings:	No handrail provided at both sides
Rec. Solution:	Provide accessible handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/22/2011 Report Date 7/22/2011 Barrier #: 2593C
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Location:	Exterior - Southwest Entrance Stairway
Location: X Coordinate:	Exterior - Southwest Entrance Stairway 7476334.814 Y Coordinate: 339257.402
X Coordinate:	7476334.814 Y Coordinate: 339257.402
X Coordinate: Barrier Area:	7476334.814 Y Coordinate: 339257.402 Stairways
X Coordinate: Barrier Area: Barrier Type: Code	7476334.814 Y Coordinate: 339257.402 Stairways Vertical Access - Directional Sign 2010 ADAS 403.1
X Coordinate: Barrier Area: Barrier Type: Code References:	7476334.814 Y Coordinate: 339257.402 Stairways Vertical Access - Directional Sign 2010 ADAS 403.1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	7476334.814 Y Coordinate: 339257.402 Stairways Vertical Access - Directional Sign 2010 ADAS 403.1 andard: No Quantity: EACH As-built: 125
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	7476334.814 Y Coordinate: 339257.402
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	7476334.814 Y Coordinate: 339257.402 Stairways Vertical Access - Directional Sign 2010 ADAS 403.1 andard: No Quantity: EACH As-built: 125 No form of vertical access provided at stairway to reach entry door or upper floors No information on alternate accessible entrance to building Provide directional sign leading to accessible entry
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	7476334.814 Y Coordinate: 339257.402 Stairways Vertical Access - Directional Sign 2010 ADAS 403.1 Andard: No Quantity: EACH As-built: 125 No form of vertical access provided at stairway to reach entry door or upper floors No information on alternate accessible entrance to building Provide directional sign leading to accessible entry 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	7/22/2011 Report Date 7/22/2011 Barrier #: 2594
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Location:	Exterior - Southwest Entrance
X Coordinate:	7476336.115 Y Coordinate: 339257.251
Barrier Area:	Doors or Gates
Barrier Type:	Door/Gate Landing - New Construction
Code References:	2010 ADAS 404.2.4.4
Performance Sta	andard: No Quantity: SF As-built: 125
Barrier Description:	Door/Gate landing is not level on both sides of door
Findings:	3.3% slope
Rec. Solution:	Provide level landing
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/22/2011 Report Date 7/22/2011 Barrier #: 2595A
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Location:	Exterior - Northwest Entrance Ramp
X Coordinate:	7476327.168 Y Coordinate: 339299.157
Barrier Area:	Ramps
Barrier Type:	Running Slope - Existing (8.6% - 8.9%)
Code References:	OSSC 1109.7.2 and 2010 ADAS 405.3
Performance Sta	ndard: No Quantity: LF As-built: 200
Barrier Description:	Running slope exceeds 8.33% (8.6% - 8.9%)
•	
Findings:	8.8% running slope
·	
Findings:	8.8% running slope Demolish existing and construct new ramp
Findings: Rec. Solution:	8.8% running slope Demolish existing and construct new ramp 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	7/22/2011 Report Date 7/22/2011 Barrier #: 2595B
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Location:	Exterior - Northwest Entrance Ramp
X Coordinate:	7476327.168 Y Coordinate: 339299.157
Barrier Area:	Ramps
Barrier Type:	Handrail Height
Code References:	OSSC 1109.7.6 and 2010 ADAS 505.4
Performance Sta	indard: No Quantity: LF As-built: 225
Barrier Description:	Handrails not 34"-38" high
Findings:	32" handrail grip height
Rec. Solution:	Provide accessible handrails at both sides of ramp
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/29/2011 Report Date 7/29/2011 Barrier #: 2596
ricia Date.	1//29/2011 Report Date 1//29/2011 Barrier #. 2596
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Bldg Name:	Dryden Hall Reference Dwg: 1 of 1
Bldg Name: Location:	Dryden Hall Reference Dwg: 1 of 1 Exterior - West Sidewalk
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 1 of 1 Exterior - West Sidewalk 7476433.423 Y Coordinate: 339374.499
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 1 of 1 Exterior - West Sidewalk 7476433.423 Y Coordinate: 339374.499 Sidewalks
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Exterior - West Sidewalk 7476433.423 Y Coordinate: 339374.499 Sidewalks Cross Slope - Existing (3.1% to 4.0%) OSSC 1109.4.4 and 2010 ADAS 403.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Exterior - West Sidewalk 7476433.423 Y Coordinate: 339374.499 Sidewalks Cross Slope - Existing (3.1% to 4.0%) OSSC 1109.4.4 and 2010 ADAS 403.3 Indard: No Quantity: LF As-built: 45
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dryden Hall Exterior - West Sidewalk 7476433.423 Y Coordinate: 339374.499 Sidewalks Cross Slope - Existing (3.1% to 4.0%) OSSC 1109.4.4 and 2010 ADAS 403.3 Indard: No Quantity: LF As-built: 45 Cross slope exceeds 2.0% (3.1% to 4.0%)
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Exterior - West Sidewalk 7476433.423 Y Coordinate: 339374.499 Sidewalks Cross Slope - Existing (3.1% to 4.0%) OSSC 1109.4.4 and 2010 ADAS 403.3 Indard: No Quantity: LF As-built: 45 Cross slope exceeds 2.0% (3.1% to 4.0%) 3.6% cross slope Demolish existing and construct new route
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall Reference Dwg: 1 of 1 Exterior - West Sidewalk 7476433.423 Y Coordinate: 339374.499 Sidewalks Cross Slope - Existing (3.1% to 4.0%) OSSC 1109.4.4 and 2010 ADAS 403.3 Indard: No Quantity: LF As-built: 45 Cross slope exceeds 2.0% (3.1% to 4.0%) 3.6% cross slope Demolish existing and construct new route 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open





Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 1A
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry Vestibule L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 1B
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry Vestibule L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Sign
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: JOB As-built : 2
Barrier Description:	ISA symbol at automatic door opening device not min. 4" x 4" in size
Findings:	Existing symbol 1-3/4" high. Not visible from a distance
Rec. Solution:	Recommended: Provide ISA symbol min. 4" x 4" in size
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 1C
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry Vestibule L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - BHMA Sign
Code References:	ANSI/BHMA A156.10-1999
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No sign on door visible from both sides reading, "AUTOMATIC DOOR"
Findings:	No sign provided
Rec. Solution:	Provide new sign on both sides of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 1D
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry Vestibule L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Timing
Code References:	2010 ADAS 404.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Door does not remain open for at least 6 seconds
Findings:	Door closes after 5 seconds
Rec. Solution:	Repair actuation device
Barrier Severity:	1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 1E
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry Vestibule L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Timing
Code References:	2010 ADAS 404.3
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Door does not re-open when encountering an obstruction other than the door jamb
Findings:	Door does not re-open
Rec. Solution:	Repair actuation device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 1F
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry Vestibule L0101
X Coordinate:	
	N/A Y Coordinate: N/A
Barrier Area:	N/A Y Coordinate: N/A Doors or Gates
Barrier Area: Barrier Type:	
	Doors or Gates
Barrier Type: Code	Doors or Gates Door 10" Bottom Surface - Door Hardware 2010 ADAS 404.2.10
Barrier Type: Code References:	Doors or Gates Door 10" Bottom Surface - Door Hardware 2010 ADAS 404.2.10
Barrier Type: Code References: Performance Sta Barrier	Doors or Gates Door 10" Bottom Surface - Door Hardware 2010 ADAS 404.2.10 ndard: No Quantity: EACH As-built: 1
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Doors or Gates Door 10" Bottom Surface - Door Hardware 2010 ADAS 404.2.10 ndard: No Quantity: EACH As-built: 1 Door hardware interrupts min. 10" smooth bottom surface
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Doors or Gates Door 10" Bottom Surface - Door Hardware 2010 ADAS 404.2.10 ndard: No Quantity: EACH As-built: 1 Door hardware interrupts min. 10" smooth bottom surface Door hardware extends into bottom 10" of door
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Doors or Gates Door 10" Bottom Surface - Door Hardware 2010 ADAS 404.2.10 ndard: No Quantity: EACH As-built: 1 Door hardware interrupts min. 10" smooth bottom surface Door hardware extends into bottom 10" of door Remove element at bottom of door at push side for use in the case of an emergency 1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 1G
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry Vestibule L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Doormat
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance Sta	andard: No Quantity: EACH As-built : 4
Barrier Description:	Doormat not anchored to floor (possible trip hazard)
Findings:	Door mat not secured
Rec. Solution:	Secure exiting doormats or replace
Barrier Severity:	1 Necessary Cost Est \$2,000.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 1H
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry Vestibule L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Heater protrudes 9" at 58" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 11
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry Vestibule L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Door
Code References:	2010 ADAS 216.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Ground floor doors that exit to exterior lacks tactile exit sign
Findings:	Exit door with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT" at exit side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 2A
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	ISA - Accessible Entry Door
Code References:	2010 ADAS 216.6
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No sign identifying door as accessible where all doors are not accessible
Findings:	No sign provided to indicate that entrance is accessible
Rec. Solution:	Provide ISA at accessible entrance door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 2B
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Sign
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: JOB As-built : 1
Barrier Description:	ISA symbol at automatic door opening device not min. 4" x 4" in size
Findings:	Existing symbol 1-3/4" high. Not visible from a distance
Rec. Solution:	Recommended: Provide ISA symbol min. 4" x 4" in size
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 2C
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - BHMA Sign
Code References:	ANSI/BHMA A156.10-1999
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No sign on door visible from both sides reading, "AUTOMATIC DOOR"
Findings:	No sign provided
Rec. Solution:	Provide new sign on both sides of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 2D
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Timing
Code References:	2010 ADAS 404.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Door does not remain open for at least 6 seconds
Findings:	Door closes after 5 seconds
Rec. Solution:	Repair actuation device
Barrier Severity:	1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 2E
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Timing
Code References:	2010 ADAS 404.3
Performance Sta	ndard: No Quantity: JOB As-built: 0
Barrier Description:	Door does not re-open when encountering an obstruction other than the door jamb
Findings:	Door does not re-open
Rec. Solution:	Repair actuation device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 2F
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - To Exit Door
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Exit door leading directly to an exit to the exterior lacks tactile exit sign
Findings:	Door leading to exit door to exterior lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT ROUTE" at exit side of door
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 2G
Field Date: Bldg Name:	1/28/2017 Report Date 3/23/2017 Barrier #: 2G Dryden Hall Reference Dwg: 2 of 4
Bldg Name:	
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Hall H0101
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Hall H0101 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Hall H0101 N/A Y Coordinate: N/A Alarms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Hall H0101 N/A Y Coordinate: N/A Alarms Fire Pull - Operation 2010 ADAS 309.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Hall H0101 N/A Y Coordinate: N/A Alarms Fire Pull - Operation 2010 ADAS 309.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Hall H0101 N/A Y Coordinate: N/A Alarms Fire Pull - Operation 2010 ADAS 309.4 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Hall H0101 N/A Alarms Fire Pull - Operation 2010 ADAS 309.4 ndard: No Quantity: EACH As-built: 1 Fire pull has no fist operable hardware
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Hall H0101 N/A Y Coordinate: N/A Alarms Fire Pull - Operation 2010 ADAS 309.4 ndard: No Quantity: EACH As-built: 1 Fire pull has no fist operable hardware Fire pull not fist operable
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Hall H0101 N/A Y Coordinate: N/A Alarms Fire Pull - Operation 2010 ADAS 309.4 ndard: No Quantity: EACH As-built: 1 Fire pull has no fist operable hardware Fire pull not fist operable Replace fire pull when remodeling 4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 2H
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull - Height
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built: 0
Barrier Description:	Fire pulls not between 42" and 48" high
Findings:	60-1/2" high
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 21
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	No strobe provided in corridor where horn is provided where fire alarm exists in building
Findings:	No strobe where horn is provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$11,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 2J
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Alcove - Existing (pre-1992)
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: JOB As-built: 1
Barrier Description:	Fountain with a leading edge between 27" and 80" high protrudes more than 4" into the circulation path.
Findings:	No alcove provided
Rec. Solution:	Provide wing walls as detectable warning (existing unit only)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 2K
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Hi-Low Unit
Code References:	2010 ADAS 211.2 & 602.7
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	No hi-low drinking fountain provided on each floor of building
Findings:	No high fountain provided on first floor
Rec. Solution:	Provide min. one hi-low fountain on each floor
Barrier Severity:	1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 2L
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Lobby Info Sign
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built : 1
Barrier Description:	No lobby informational sign with location of accessible elements
Findings:	Accessible sign not provided
Rec. Solution:	Provide lobby informational sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 2M
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	
Implementation	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 2N
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Raised Characters - Sharp Edges
Code References:	2010 ADAS Advisory 703.2
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	Signs that are designed to be read by touch have sharp or abrasive edges.
Findings:	Existing sign not accessible at Rooms 101A and 101B
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 20
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	26-3/4" high knee clearance at study table
Rec. Solution:	Provide min. 1 accessible table. Avoid pedestal base tables.
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	
	1/28/2017 Report Date 3/23/2017 Barrier #: 3A
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0105
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Main er	ntry and door to room 106 (Sign states 105B)
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 3B
Field Date: Bldg Name:	1/28/2017 Report Date 3/23/2017 Barrier #: 3B Dryden Hall Reference Dwg: 2 of 4
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0105
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0105 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0105 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0105 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0105 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0105 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 andard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0105 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0105 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 andard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not operable with a closed fist Replace hardware
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 3C	
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4	
Location:	Floor 1 - Grad Student Room 0105	
X Coordinate:	N/A Y Coordinate: N/A	
Barrier Area:	Doors or Gates	
Barrier Type:	Vision Lights - Existing	
Code References:	2010 ADAS 404.2.11	
Performance Sta	andard: No Quantity: EACH As-built : 1	
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground	
Findings:	49-1/2" high	
Rec. Solution:	Replace door/gate or vision panel	
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open	
Implementation	Priority: 2 Implementation Phase: Implementation Date:	
Notes:		
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 3D	
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4	
Location:	Floor 1 - Grad Student Room 0105	
X Coordinate:	N/A Y Coordinate: N/A	
Barrier Area:	Doors or Gates	
Barrier Type:	Front App/pull 18" SEC - Blocked	
Code References:	2010 ADAS Figure 404.2.4.1	
Performance Sta	andard: No Quantity: ADMINI As-built : 1	
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side	
Findings:	Fire extinguisher blocks strike edge clearance	
Rec. Solution:	Remove stored item	
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open	
Implementation Priority: 2 Implementation Phase: Implementation Date:		
Notes:		



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 3E
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0105
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 3F
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0105
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Turning Space
Barrier Type:	T-Shaped Turning Space
Code References:	2010 ADAS 304.3.2
Performance Sta	ndard: No Quantity: SF As-built : 0
Barrier Description:	T-shaped turning space not 60" at base at min. 36" at each arm
Findings:	37-1/2" x 46" with chairs in path. 53" x 46" without chairs
Rec. Solution:	Remove chairs
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 3G
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0105
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Turning Space
Barrier Type:	Circular Turning Space - Min. 60"
Code References:	2010 ADAS 304.3.1
Performance Sta	andard: No Quantity: SF As-built : 0
Barrier Description:	Circular turning space not minimum of 60" in diameter (including toe/knee space)
Findings:	48" wide path along wall at study carrels
Rec. Solution:	Rearrange furniture to provide accessible turning space at end of path
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 3H
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0105
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Heater controls 66" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 3
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0105
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4A
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Reception Room 0106
Location:	Floor 1 - Reception Room 0106
Location: X Coordinate:	Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Signage
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4B
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Reception Room 0106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	14 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4C
Field Date: Bldg Name:	1/28/2017 Report Date 3/23/2017 Barrier #: 4C Dryden Hall Reference Dwg: 2 of 4
	The second secon
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Reception Room 0106
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame 2 second sweep
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4D
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Reception Room 0106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	55-1/2" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4E
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Reception Room 0106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Door Stop
Code References:	2010 ADAS 404.2.10
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door stop interrupts min.10" smooth bottom surface
Findings:	Door stop at bottom of door can create trapping condition
Rec. Solution:	Remove door stop or other element at bottom of door at push side for use in case of an emerg
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4F
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Reception Room 0106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Desk blocks electrical switch clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4G
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Reception Room 0106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	51" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4H
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Reception Room 0106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Printer blocks desk clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
e: 11e :	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4
Field Date: Bldg Name:	1/28/2017 Report Date 3/23/2017 Barrier #: 4
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Reception Room 0106
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Counters and Tables
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Counters and Tables Desk - Knee Clearance 2010 ADAS 902.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Counters and Tables Desk - Knee Clearance 2010 ADAS 902.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Counters and Tables Desk - Knee Clearance 2010 ADAS 902.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Counters and Tables Desk - Knee Clearance 2010 ADAS 902.3 Indard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Counters and Tables Desk - Knee Clearance 2010 ADAS 902.3 Indard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide 28" wide knee clearance at mail desk
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Reception Room 0106 N/A Y Coordinate: N/A Counters and Tables Desk - Knee Clearance 2010 ADAS 902.3 Indard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide 28" wide knee clearance at mail desk Provide min. one accessible desk or workstation 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4J
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Reception Room 0106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Shelves or Cabinets
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Shelf or cabinet not mounted max. 48" above floor or ground
Findings:	Shelf or cabinet not accessible
Rec. Solution:	Provide additional shelf at accessible height or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4K
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Reception Room 0106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	23" high knee clearance
Rec. Solution:	Provide min. one accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	
Notes: May be	employee area



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4L
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Reception Room 0106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	13" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4M
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Reception Room 0106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Hi/low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Use of control involves low reach of less than 15" above floor or more than 48" high
Findings:	AED cabinet control 65" high
Rec. Solution:	Relocate to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4N
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Reception Room 0106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Findings:	AED protrudes 5" at 57-1/2" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 40
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Reception Room 0106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	29" wide circulation route between tables
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4P
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Reception Room 0106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Pedestal Base
Code References:	2010 ADAS 306.2.2 & 306.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	Pedestal base blocks knee clearance
Rec. Solution:	Provide min. 1 accessible table. Avoid pedestal base tables.
Barrier Severity:	2 Recommended Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4Q
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Reception Room 0106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Table blocks shelving unit and trash receptacles clear floor space
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4R
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Reception Room 0106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Shelves or Cabinets
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Shelf or cabinet not mounted max. 48" above floor or ground
Findings:	Shelf or cabinet not accessible
Rec. Solution:	Provide additional shelf at accessible height or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4S
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Reception Room 0106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Heater and door swing blocks whiteboard clear floor space
Findings:	Theater and door swing blocks withteboard clear floor space
_	Move stored items
_	Move stored items
Rec. Solution:	Move stored items 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4T
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Reception Room 0106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard (2010 ADAS 904.3.3)
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 44" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 4U
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Reception Room 0106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Staff Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobe in staff areas
Findings:	No device provided
Rec. Solution:	Provide horn/strobe
Barrier Severity:	3 Hindrance Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 5A
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Both en	tries from Reception 106 (signs states 106A and 108)
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 5B
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not operable with a closed fist
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$600.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 5C
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	6" strike edge clearance and blocked by stored items on both sides of door
Rec. Solution:	No remediation recommended. The second door to this area can be made accessible
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: South er	ntrance from 106
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 5D
Field Date: Bldg Name:	1/28/2017 Report Date 3/23/2017 Barrier #: 5D Dryden Hall Reference Dwg: 2 of 4
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0106A
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0106A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0106A N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0106A N/A Y Coordinate: N/A Doors or Gates Front App/push 48" 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0106A N/A Y Coordinate: N/A Doors or Gates Front App/push 48" 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0106A N/A Y Coordinate: N/A Doors or Gates Front App/push 48" 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0106A N/A Y Coordinate: N/A Doors or Gates Front App/push 48" 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 1 Door/Gate at push side with min. 18" lacks min. 48" perpendicular to door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0106A N/A Y Coordinate: N/A Doors or Gates Front App/push 48" 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 1 Door/Gate at push side with min. 18" lacks min. 48" perpendicular to door 30-1/2" between wall and structural column. Copier blocks approach at latch side.
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0106A N/A Y Coordinate: N/A Doors or Gates Front App/push 48" 2010 ADAS Figure 404.2.4.1 Door/Gate at push side with min. 18" lacks min. 48" perpendicular to door 30-1/2" between wall and structural column. Copier blocks approach at latch side. Move copier and other elements to provide accessible maneuvering clearance at door 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 5E
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built: 1
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	Trash bin blocks strike edge clearance
Rec. Solution:	Remove stored item
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 5F
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 5G
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	71" high
Rec. Solution:	Provide additional hook in accessible location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 5H
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	13" high
i iliuliigs.	15 High
_	Relocate outlet to area at min. 15" or max. 48" high
_	
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 51
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not operable with a closed fist at Entrance from 0105
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 5J
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Area: Barrier Type:	
	Doors or Gates
Barrier Type: Code	Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1
Barrier Type: Code References:	Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1
Barrier Type: Code References: Performance Sta Barrier	Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 1
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 1 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 1 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer Trash bin blocks strike edge clearance
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 Indard: No Quantity: ADMINI As-built: 1 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer Trash bin blocks strike edge clearance Remove stored item 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 5K
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	Partition reduces strike edge clearance to 15"
Rec. Solution:	Rearrange cubicle partitions to provide accessible maneuvering clearance at door
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 5L
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Ratio
Code References:	2010 ADAS 902
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	At least 1 desk or 5% of all desks are not accessible
Findings:	22 desks provided with no accessible desks
Rec. Solution:	Provide min. 2 accessible desks or workstations
Barrier Severity:	3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 5M
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	27" - 28" wide knee clearance at all desks
Rec. Solution:	Provide min. 2 accessible desks or workstations
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 5N
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Turning Space
Barrier Type:	Circular Turning Space - Min. 60"
Code References:	2010 ADAS 304.3.1
D C+ -	
Performance Sta	andard: No Quantity: SF As-built: 0
Performance Sta Barrier Description:	As-built: 0 Circular turning space not minimum of 60" in diameter (including toe/knee space)
Barrier	
Barrier Description:	Circular turning space not minimum of 60" in diameter (including toe/knee space) 42" wide between chairs and 49" wide between desks. No space to turn and exit for people in
Barrier Description: Findings:	Circular turning space not minimum of 60" in diameter (including toe/knee space) 42" wide between chairs and 49" wide between desks. No space to turn and exit for people in wheelchairs Rearrange furniture to provide accessible circulation path
Barrier Description: Findings: Rec. Solution:	Circular turning space not minimum of 60" in diameter (including toe/knee space) 42" wide between chairs and 49" wide between desks. No space to turn and exit for people in wheelchairs Rearrange furniture to provide accessible circulation path 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 50
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	29" wide circulation route between partitions. Door swing reduces clearance to less than 29" wide.
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 5P
Field Date: Bldg Name:	1/28/2017 Report Date 3/23/2017 Barrier #: 5P Dryden Hall Reference Dwg: 2 of 4
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0106A
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0106A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0106A N/A Y Coordinate: N/A Clear Floor Space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0106A N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0106A N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0106A N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0106A N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 ndard: No Quantity: JOB As-built: 1 Circulation route not min. 36" wide between elements
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Grad Student Room 0106A N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 ndard: No Quantity: JOB As-built: 1 Circulation route not min. 36" wide between elements 33" - 47" wide circulation route
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Ploor 1 - Grad Student Room 0106A N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 Circulation route not min. 36" wide between elements 33" - 47" wide circulation route Rearrange furniture to provide accessible circulation path 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 5Q
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Turning Space
Barrier Type:	Circular Turning Space - Min. 60"
Code References:	2010 ADAS 304.3.1
Performance Sta	andard: No Quantity: SF As-built : 25
Barrier Description:	Circular turning space not minimum of 60" in diameter (including toe/knee space)
Findings:	33" - 47" wide
Rec. Solution:	Rearrange furniture to provide accessible turning space at end of path
Barrier Severity:	2 Recommended Cost Est \$1,875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 5R
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Turning Space
Barrier Type:	Circular Turning Space - Min. 60"
Code References:	2010 ADAS 304.3.1
Performance Sta	andard: No Quantity: SF As-built: 1
Barrier Description:	Circular turning space not minimum of 60" in diameter (including toe/knee space)
Findings:	30" - 53" wide
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	2 Recommended Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 55
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Grad Student Room 0106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Staff Area
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	No horn/strobe in staff areas
Findings:	No device provided
Rec. Solution:	Provide horn/strobe
Barrier Severity:	3 Hindrance Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 6A
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Study-Reading Room 0108A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Clear Width Clear Width
Code References:	2010 ADAS 404.2.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Clear width passage through door, sliding/folding door or gate is not min. 32"
Findings:	29" wide at each leaf
Rec. Solution:	Replace door or gate and frame to provide min. 1 leaf with at least 32" clear width
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 6B
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Study-Reading Room 0108A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 60" - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at with min. 18" at pull side lacks min. 60" perpendicular to door
Findings:	36" perpendicular to table
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 6C
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Study-Reading Room 0108A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 48"
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at push side with min. 18" lacks min. 48" perpendicular to door
Findings:	36" perpendicular to table within room
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 6D
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Study-Reading Room 0108A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 6E
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Study-Reading Room 0108A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 305
Performance Sta	andard: No Quantity: JOB As-built: 1
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	30" turning space
Rec. Solution:	Rearrange furniture to provide accessible maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 6F
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Study-Reading Room 0108A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Shelves or Cabinets
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 2
Barrier Description:	Shelf or cabinet not mounted max. 48" above floor or ground
Findings:	Shelf or cabinet not accessible
Rec. Solution:	Provide additional shelf at accessible height or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 6G
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Study-Reading Room 0108A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
implementation	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 7A
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Break Room 0107C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 4
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door at both entries and rooms 107A,107B within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$1,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 7B
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Break Room 0107C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	Pedestal based table reduces circulation route into room
Rec. Solution:	
	Rearrange furniture to provide accessible circulation path
Barrier Severity:	
Barrier Severity: Implementation	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 7C
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Break Room 0107C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 7D
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Break Room 0107C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	64" high
Rec. Solution:	Provide additional hook in accessible location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 7E
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Break Room 0107C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Rim or Countertop
Code References:	2010 ADAS 606.3
Performance Sta	ndard: No Quantity: LF As-built: 3
Barrier Description:	No accessible section of counter at max 34" high provided
Findings:	36" high
Rec. Solution:	Reposition existing sink or provide additional sink for use in area
Barrier Severity:	1 Necessary Cost Est \$1,110.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 7F
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Break Room 0107C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Knee Clearance
Code References:	2010 ADAS 606.2 & 306
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	No knee clearance
Rec. Solution:	Replace cabinet and remount sink
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 7G
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Break Room 0107C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Forward Reach Obstructed (10"-25")
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44"
Findings:	Faucet 45" high and 22" deep over 36" counter
Rec. Solution:	Relocate control or mechanism to max. 44" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 7H
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Break Room 0107C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Forward Reach Obstructed (10"-25")
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44"
Findings:	Paper towel and soap dispenser 51" - 55" high and 11" - 22-1/2" deep over an obstruction 36" high
Rec. Solution:	Relocate control or mechanism to max. 44" high
Barrier Severity:	3 Hindrance Cost Est \$1,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 71
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Break Room 0107C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Surface Height
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No section at least 3 feet long between 28" and 34" provided at existing counter
Findings:	36" high
Rec. Solution:	Provide min. 3 ft long section of counter at max. 34" high
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 7J
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Break Room 0107C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	No knee clearance
Rec. Solution:	Provide min. 3 ft segment of accessible counter. Flip-up counters, adiacent tables and similar de
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 7K
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Break Room 0107C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Table blocks refrigerator and electrical outlet clear floor space
Rec. Solution:	Rearrange furniture to provide accessible clear floor space at fridge
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 7L
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Break Room 0107C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Forward Reach Obstructed (10"-25")
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Outlet located over an 10" to 25" obstruction max. 34" high located above 44"
Findings:	48" high and 17" deep over an obstruction 36" counter
Rec. Solution:	Relocate control or mechanism to max. 44" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 7M
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Break Room 0107C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Table blocks shelves clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 7N
Field Date: Bldg Name:	1/28/2017 Report Date 3/23/2017 Barrier #: 7N Dryden Hall Reference Dwg: 2 of 4
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Break Room 0107C
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Break Room 0107C N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Break Room 0107C N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Break Room 0107C N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Break Room 0107C N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Break Room 0107C N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 andard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Break Room 0107C N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 andard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 70
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Break Room 0107C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Shelves protrude 12" at 52" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 7P
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Break Room 0107C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Mailbox - High Reach Range
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	Mailbox opening is above 48" high
Findings:	58" - 62" high in rooms 107A & 107B
Rec. Solution:	Relocate to provide opening at max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$1,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 7Q
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Break Room 0107C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 8A
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Elevator E0101
Location: X Coordinate:	Floor 1 - Elevator E0101 N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Elevators
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Elevators Doorjamb marking - Raised Star 2010 ADAS 407.2.3.1
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Elevators Doorjamb marking - Raised Star 2010 ADAS 407.2.3.1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	N/A Y Coordinate: N/A Elevators Doorjamb marking - Raised Star 2010 ADAS 407.2.3.1 Indard: No Quantity: EACH As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Elevators Doorjamb marking - Raised Star 2010 ADAS 407.2.3.1 Indard: No Quantity: EACH As-built: 1 Elevator landing door jamb signage at grade level lacks a raised five pointed star
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Elevators Doorjamb marking - Raised Star 2010 ADAS 407.2.3.1 Indard: No Quantity: EACH As-built: 1 Elevator landing door jamb signage at grade level lacks a raised five pointed star No raised star provided Replace door jamb signage
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Flevators Doorjamb marking - Raised Star 2010 ADAS 407.2.3.1 Indard: No Quantity: EACH As-built: 1 Elevator landing door jamb signage at grade level lacks a raised five pointed star No raised star provided Replace door iamb signage 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 8B
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Elevator E0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Hall lanterns - Visible at Entry
Code References:	2010 ADAS 407.2.2.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Visual and audible signals not provided at each hoist way entrance to answer calls
Findings:	Hall lanterns not visible from outer side of elevator
Rec. Solution:	Provide hall lanterns visible from outer side of elevator
Barrier Severity:	1 Necessary Cost Est \$3,675.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 8C
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Elevator E0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Audible Signals
Code References:	2010 ADAS 407.2.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Audible signals or verbal announcement does not sound when the car passes a floor or stops
Findings:	No audible signals provided
Rec. Solution:	Replace car controls
Barrier Severity:	2 Recommended Cost Est \$2,750.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 8D
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Elevator E0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Reopening Device
Code References:	2010 ADAS 407.3.3.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Door-reopening devices does not remain effective for at least 20 seconds
Findings:	1 second
Rec. Solution:	Repair or adjust reopening device
Barrier Severity:	1 Necessary Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 8E
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Elevator E0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Emergency Controls - Cabinet
Code References:	2010 ADAS 407.4.6.4.1 & 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Cabinet housing emergency controls lacks accessible hardware
Findings:	Cabinet hardware not fist operable
Rec. Solution:	Replace cabinet hardware
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
	Trecessary cost 25t 5250.00 radiity randion. radiit
Implementation	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 8F
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Elevator E0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Emergency Controls
Code References:	2010 ADAS 407.4.7.1.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Emergency telephone handset not identified by a raised telephone symbol & Braille
Findings:	No tactile information provided
Rec. Solution:	Replace emergency system
Barrier Severity:	1 Necessary Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 8G
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Elevator E0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Emergency Controls
Code References:	2010 ADAS 407.4.6.4.1
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Emergency controls (incl. emergency stop and alarm) are located below 35"
Findings:	
Findings:	28" on center
_	Replace emergency controls
_	
Rec. Solution:	Replace emergency controls 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 8H
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Elevator E0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Grip
Code References:	2010 ADAS 505.10.2
Performance Sta	andard: No Quantity: LF As-built : 14
Barrier Description:	Handrail grip is not continuous
Findings:	Handrail supports force users to open grip at each support
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$3,150.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 9A
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom 0104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Raised Characters - Sharp Edges
Code References:	2010 ADAS Advisory 703.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Signs that are designed to be read by touch have sharp or abrasive edges.
Findings:	Accessible sign not provided
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 9B
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom 0104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Door Vision Lights
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	45" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 9C
Dida Nama	
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom 0104
_	2 2130
Location:	Floor 1 - Classroom 0104
Location: X Coordinate:	Floor 1 - Classroom 0104 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 1 - Classroom 0104 N/A Y Coordinate: N/A Doors or Gates
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 1 - Classroom 0104 N/A Y Coordinate: N/A Doors or Gates Recessed Door - Push Side 2010 ADAS 404.2.4.3
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 1 - Classroom 0104 N/A Y Coordinate: N/A Doors or Gates Recessed Door - Push Side 2010 ADAS 404.2.4.3
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 1 - Classroom 0104 N/A Y Coordinate: N/A Doors or Gates Recessed Door - Push Side 2010 ADAS 404.2.4.3 Indard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 1 - Classroom 0104 N/A Y Coordinate: N/A Doors or Gates Recessed Door - Push Side 2010 ADAS 404.2.4.3 andard: No Quantity: EACH As-built: 1 Door recessed by more than 8" lacks at least 12" clearance at push side of door
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - Classroom 0104 N/A Y Coordinate: N/A Doors or Gates Recessed Door - Push Side 2010 ADAS 404.2.4.3 Indard: No Quantity: EACH As-built: 1 Door recessed by more than 8" lacks at least 12" clearance at push side of door 12" deep recess. No strike edge clearance Provide automatic door opening device
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 1 - Classroom 0104 N/A Y Coordinate: N/A Doors or Gates Recessed Door - Push Side 2010 ADAS 404.2.4.3 andard: No Quantity: EACH As-built: 1 Door recessed by more than 8" lacks at least 12" clearance at push side of door 12" deep recess. No strike edge clearance Provide automatic door opening device 1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 9D
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom 0104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 9E
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom 0104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Thermometer control 49" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 9F
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom 0104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24" high and 11" deep knee clearance at prep desk
Rec. Solution:	Provide min. 1 accessible table. Avoid pedestal base tables.
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 9G
Field Date: Bldg Name:	1/28/2017 Report Date 3/23/2017 Barrier #: 9G Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom 0104
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom 0104 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom 0104 N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom 0104 N/A Y Coordinate: N/A Classrooms Clear Floor Space - Stored Elements 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom 0104 N/A Y Coordinate: N/A Classrooms Clear Floor Space - Stored Elements 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom 0104 N/A Y Coordinate: N/A Classrooms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom 0104 N/A Y Coordinate: N/A Classrooms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom 0104 N/A Y Coordinate: N/A Classrooms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Table and chair blocks whiteboard clear floor space in 4 locations
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Ploor 1 - Classroom 0104 N/A Y Coordinate: N/A Classrooms Clear Floor Space - Stored Elements 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Table and chair blocks whiteboard clear floor space in 4 locations Move stored items 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 9H
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom 0104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Accessible Route - Cords
Code References:	2010 ADAS 303.3
Performance Sta	ndard: No Quantity: JOB As-built: 1
Barrier Description:	Change in level greater than 1/2" in clear floor space at cords
Findings:	Cords create trip hazard
Rec. Solution:	Provide accessible cord cover or otherwise remove barrier to access
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 9
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom 0104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Podium - Knee Clearance
Code References:	2010 ADAS 504.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Podium knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	16-3/4" deep knee clearance to pedestal base
Rec. Solution:	Provide min. 1 accessible podium
Barrier Severity:	4 Low Severity Cost Est \$1,275.00 Facility Function: Public Status: Open
Implementation	· — · — — · — — ·
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 9J
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom 0104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Phone 49" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 9K
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom 0104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Protruding Object - Wall-mounted
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Wall mounted object protrudes more than 4" from wall
Findings:	Phone protrudes 5" at 46" high
Rec. Solution:	Remove object or provide detectable warning for the visually impaired
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 9L
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom 0104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Projector screen switch 50" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 9M
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom 0104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built: 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Podium blocks projector screen switch clear floor space
Rec. Solution:	Rearrange furniture to provide accessible circulation path to whiteboard and podium
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 9N
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom 0104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Passageway is not min. 36" wide
Findings:	26" wide between desks
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 90
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom 0104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Alarm - Strobe Mounting Height
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Strobe not mounted at 80" AFF or 96" high, whichever is lower
Findings:	79-1/2" high
Rec. Solution:	
	Relocate strobe to min. 80" high
Barrier Severity:	
	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 10A
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry Hall H0100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Touch screen centerline 64" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 10B
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry Hall H0100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Panel protrudes 4-1/2" at 52-1/4" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 10C
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry Hall H0100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Door
Code References:	2010 ADAS 216.4.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Ground floor doors that exit to exterior lacks tactile exit sign
Findings:	Exit door with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT" at exit side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 10D
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry Hall H0100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Exterior Adjustment
Code References:	Performance Standard
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 8.5 lbf
Findings:	15 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 10E
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry Hall H0100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not operable with a closed fist
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 10F
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry Hall H0100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Doormat
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Doormat not anchored to floor (possible trip hazard)
Findings:	Door mat not secured
Rec. Solution:	Secure exiting doormat or replace
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 10G
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry Hall H0100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Relocate Door
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	15" strike edge clearance
Rec. Solution:	Provide automatic door opening device that simultaneously opens both doors
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 10H
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry Hall H0100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Recessed Door - Push Side
Code References:	2010 ADAS 404.2.4.3
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door recessed by more than 8" lacks at least 12" clearance at push side of door
Findings:	21" deep recess and no strike edge clearance
Rec. Solution:	Provide automatic door opening device that simultaneously opens both doors
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 101
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry Hall H0100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	ISA - Non-Accessible Entry
Code References:	2010 ADAS 216.6
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Sign directing people to accessible entrance needed where all doors are not accessible
Findings:	ISA directional sign not provided at non-accessible door
Rec. Solution:	Provide ISA directional sign with arrow directing people to accessible entrance
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11A
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	ISA - Non-Accessible Entry
Code References:	2010 ADAS 216.6
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Sign directing people to accessible entrance needed where all doors are not accessible
Findings:	ISA directional sign not provided at non-accessible door
Rec. Solution:	Provide ISA directional sign with arrow directing people to accessible entrance
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11B
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Door Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Operating controls involve tight grasping, pinching or twisting
Findings:	Hardware not operable with a closed fist
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11C
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Door Clearance Blocked
Code References:	2010 ADAS Figure 404.2.4.3
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Trash bin or stored items block strike edge clearance at exit side of door
Findings:	7" strike edge clearance blocked by workstation
Rec. Solution:	Provide automatic door opening device that simultaneously opens both doors
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11D
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Location - Within 18" of Door
Code References:	2010 ADAS 703.4.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Approach to tactile characters on sign not centered at 18" minimum from door swing
Findings:	Signs located at hinge side of door, not latch side
Rec. Solution:	Relocate sign or replace
Barrier Severity:	1 Necessary Cost Est \$150.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11E
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Door Closer - Automatic Device
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	15 lbf
Rec. Solution:	Provide automatic door opening device at one door and ISA sign at other
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11F
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	2 second sweep
Rec. Solution:	Provide automatic door opening device at one door and ISA sign at other
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11G
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	44-1/2" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11H
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	ISA - Accessible Entry Door
Code References:	2010 ADAS 216.6
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No sign identifying door as accessible where all doors are not accessible
Findings:	No sign provided to indicate that entrance is accessible
Rec. Solution:	Provide ISA at accessible entrance door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 111
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Door Closer - Automatic Device
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built: 0
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	20 lbf
Rec. Solution:	Provide automatic door opening device at one door and ISA sign at other
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
	Taciney Function: Fubility States: Open
Implementation	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11J
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	2 second sweep
Rec. Solution:	Provide automatic door opening device at one door and ISA sign at other
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11K
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	44-1/2" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	
	1/29/2017 Report Date 3/23/2017 Barrier #: 11L
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	14-1/2" strike edge clearance to trash bin
Rec. Solution:	Remove stored item
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11M
Field Date: Bldg Name:	1/29/2017 Report Date 3/23/2017 Barrier #: 11M Dryden Hall Reference Dwg: 2 of 4
	100
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 0101
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A Laboratory Facilities
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A Laboratory Facilities Clear Floor Space - Controls 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A Laboratory Facilities Clear Floor Space - Controls 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A Laboratory Facilities Clear Floor Space - Controls 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A Laboratory Facilities Clear Floor Space - Controls 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space of min. 30" by 48" not provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11N
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 110
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Clear Floor Space - Controls
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Refrigerator blocks fire extinguisher clear floor space
Rec. Solution:	Move stored items at control or mechanism
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
1	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11P
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Wall mounted object (dispensers) protrudes more than 4" from wall
Findings:	Pump valve protrudes 7" at 73" high
Rec. Solution:	Relocate, remove object (dispenser) or provide detectable warning for the visually impaired
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11Q
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Sink - Knee Clearance
Code References:	2010 ADAS 606.2 & 306
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	Stored items block knee clearance at sink that is otherwise accessible
Rec. Solution:	Remove stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11R
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Electrical Outlets - Forward Reach Obstructed (10"-25")
Code References:	2010 ADAS 306.3.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Outlet located over an 10" to 25" obstruction max. 34" high located above 44"
Findings:	48" high and 27" deep over an obstruction 34" high
Rec. Solution:	Relocate control or mechanism to max. 44" high
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 115
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Shelves or Cabinet
Code References:	2010 ADAS 603.4
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Shelf or cabinet not mounted between 40" and 48" above floor or ground
Findings:	54" - 79" high
Rec. Solution:	Provide additional shelf/cabinet at accessible height or provide assistance
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11T
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Binary HPLC pump control 54" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11U
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Shelves or Cabinet
Code References:	2010 ADAS 603.4
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Shelf or cabinet not mounted between 40" and 48" above floor or ground
Findings:	57-1/2" - 72-1/2" high
Rec. Solution:	Provide additional shelf/cabinet at accessible height or provide assistance
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11V
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	GelDoc machine control 60" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11W
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
	interial diagnostic, wet tabliately died
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	
	N/A Y Coordinate: N/A
Barrier Area:	N/A Y Coordinate: N/A Laboratory Facilities
Barrier Area: Barrier Type: Code	N/A Laboratory Facilities Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3
Barrier Area: Barrier Type: Code References:	N/A Laboratory Facilities Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Laboratory Facilities Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Laboratory Facilities Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Control or mechanism not at min. 15" or max. 48" high
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Laboratory Facilities Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 andard: No Quantity: EACH As-built: 1 Control or mechanism not at min. 15" or max. 48" high Microscope control 51" high Provide min. 1 accessible microscope in lab
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Laboratory Facilities Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Control or mechanism not at min. 15" or max. 48" high Microscope control 51" high Provide min. 1 accessible microscope in lab 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11X
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 603.4
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	69" high
Rec. Solution:	Provide additional hook in new location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11Y
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Fume Hood - Work Surface Rim
Code References:	2010 ADAS 902
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Work surface height exceeds 34" high
Findings:	39" work surface height
Rec. Solution:	Replace workstation or provide alternative accessible workstation
Barrier Severity:	3 Hindrance Cost Est \$12,450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11Z
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Fume Hood - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	4-1/4" deep knee clearance
Rec. Solution:	Reposition hood to provide knee clearance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11AA
Field Date: Bldg Name:	1/29/2017 Report Date 3/23/2017 Barrier #: 11AA Dryden Hall Reference Dwg: 2 of 4
Bldg Name:	
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 0101
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A Laboratory Facilities
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A Laboratory Facilities Actuator or Control - Operation 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A Laboratory Facilities Actuator or Control - Operation 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A Laboratory Facilities Actuator or Control - Operation 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A Laboratory Facilities Actuator or Control - Operation 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Control or mechanism not usable with a closed fist
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A Laboratory Facilities Actuator or Control - Operation 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Control or mechanism not usable with a closed fist Spigot not fist operable
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A Laboratory Facilities Actuator or Control - Operation 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Control or mechanism not usable with a closed fist Spigot not fist operable Replace operating control 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11AB
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Spigot 58" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11AC
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	TOTAL BEAUTIFUL TO THE PARTY OF
	Floor 1 - Classroom/Wet Laboratory 0101
	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A Laboratory Facilities
X Coordinate: Barrier Area: Barrier Type: Code	Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A Laboratory Facilities Electrical Switches - High Unobstructed 2010 ADAS 308.2.1
X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A Laboratory Facilities Electrical Switches - High Unobstructed 2010 ADAS 308.2.1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A Laboratory Facilities Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 ndard: No Quantity: EACH As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A Laboratory Facilities Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A Laboratory Facilities Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high Fume switch 71" high
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 1 - Classroom/Wet Laboratory 0101 N/A Y Coordinate: N/A Laboratory Facilities Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high Fume switch 71" high Relocate switch box top edge to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11AD
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Raised Characters - Sharp Edges
Code References:	2010 ADAS Advisory 703.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Signs that are designed to be read by touch have sharp or abrasive edges.
Findings:	Existing sign at room 101A not accessible
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11AE
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard (2010 ADAS 904.3.3)
Performance Sta	andard: Yes Quantity: EACH As-built: 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 52-1/2" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11AF
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	26" high knee clearance at one of 2 desks in lab. 36-1/2" surface height at second desk
Rec. Solution:	Provide min. one accessible desk or workstation in lab
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11AG
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Shelves or Cabinet
Code References:	2010 ADAS 603.4
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Shelf or cabinet not mounted between 40" and 48" above floor or ground
Findings:	Shelves at desk 58" - 90" high
Rec. Solution:	Provide additional shelf/cabinet at accessible height or provide assistance
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 11AH
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 603.4
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	69" high
Rec. Solution:	Provide additional hook in new location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12A
Field Date: Bldg Name:	1/29/2017 Report Date 3/23/2017 Barrier #: 12A Dryden Hall Reference Dwg: 2 of 4
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A Signage Location - Within 18" of Door 2010 ADAS 703.4.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A Signage Location - Within 18" of Door 2010 ADAS 703.4.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A Signage Location - Within 18" of Door 2010 ADAS 703.4.2 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A Signage Location - Within 18" of Door 2010 ADAS 703.4.2 Approach to tactile characters on sign not centered at 18" minimum from door swing Sign location prevents the visually impaired from approaching the sign to read by touch. Door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12B
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Door Closer - Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	14 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12C
Field Date: Bldg Name:	1/29/2017 Report Date 3/23/2017 Barrier #: 12C Dryden Hall Reference Dwg: 2 of 4
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A Laboratory Facilities
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A Laboratory Facilities Door Closer - Sweep 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A Laboratory Facilities Door Closer - Sweep 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A Laboratory Facilities Door Closer - Sweep 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A Laboratory Facilities Door Closer - Sweep 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12D
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Doors - Vision Lights
Code References:	2010 ADAS 404.2.11
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	44-1/2" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12E
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Door Clearance Blocked
Code References:	2010 ADAS Figure 404.2.4.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Trash bin or stored items block strike edge clearance at exit side of door
Findings:	Machine blocks strike edge clearance
Rec. Solution:	Relocate machine
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12F
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	S. J. I.
	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Clear Floor Space - Controls
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Machine blocks electrical switch clear floor space
Rec. Solution:	Move stored items at control or mechanism
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12G
Field Date: Bldg Name:	1/29/2017 Report Date 3/23/2017 Barrier #: 12G Dryden Hall Reference Dwg: 2 of 4
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A Laboratory Facilities
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A Laboratory Facilities Electrical Switches - High Unobstructed 2010 ADAS 308.2.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A Laboratory Facilities Electrical Switches - High Unobstructed 2010 ADAS 308.2.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A Laboratory Facilities Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A Laboratory Facilities Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A Laboratory Facilities Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Classroom/Wet Laboratory 100 N/A Y Coordinate: N/A Laboratory Facilities Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high So-1/2" high Relocate switch box top edge to max. 48" high Relocate switch box top edge to max. 48" high Relocate Switch box top edge to max. 48" high Relocate Switch box top edge to max. 48" high Relocate Switch box top edge to max. 48" high



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12H
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 603.4
Performance St	andard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	74" high clothing rod
Rec. Solution:	Provide additional hook or clothing rod in new location
Barrier Severity	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 121
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - Wheelchair Use
Code References:	2010 ADAS 305
Performance St	andard: No Quantity: JOB As-built: 1
Barrier	Clear floor space of min. 30" by 48" not provided
Description:	
	Clear floor space at refrigerator not centered at 24" from opening side of unit
Description:	Clear floor space at refrigerator not centered at 24" from opening side of unit Provide assistance
Description: Findings:	Provide assistance
Description: Findings: Rec. Solution:	Provide assistance 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12J
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Thermostat control 61" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12K
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Fisher scientific incubator control 13" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12L
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Sink - Rim or Countertop
Code References:	2010 ADAS 606.3
Performance Sta	andard: No Quantity: LF As-built: 3
Barrier Description:	Sink rim or surface not max. 34" high
Findings:	37" high
Rec. Solution:	Reposition existing sink or provide additional sink for use in area
Barrier Severity:	1 Necessary Cost Est \$1,110.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12M
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Sink - Knee Clearance
Code References:	2010 ADAS 606.2 & 306
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	No knee clearance
Rec. Solution:	Replace cabinet and remount sink
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12N
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Workstation - Surface
Code References:	2010 ADAS 902
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Table or workstation surface height exceeds 34" high
Findings:	37" workstation surface height
Rec. Solution:	Provide min. 1 accessible workstation of each type or overall 5%
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 120
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Actuator/Control - Forward Reach Obstructed (10"-25")
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44"
Findings:	Lab machines and equipment controls 44" - 52" high and 12" - 15" deep over an obstruction 37" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12P
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Actuator/Control - Forward Reach Obstructed (10"-25")
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44"
Findings:	Printer 51" high and 36" deep over an obstruction 31" high. Work station accessible
Rec. Solution:	Relocate control or mechanism to max. 44" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12Q
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Shelves or Cabinet
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Shelf or cabinet not mounted between 40" and 48" above floor or ground
Findings:	51" - 82" high
Rec. Solution:	Provide additional shelf/cabinet at accessible height or provide assistance
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
Notes:	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12R
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Wall mounted object (dispensers) protrudes more than 4" from wall
Findings:	Shelves protrudes 14-1/2" at 48-1/4" high
Rec. Solution:	Relocate, remove object (dispenser) or provide detectable warning for the visually impaired
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12S
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Fume Hood - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	26-7/8" high knee clearance at 4 Biosafety cabinets
Rec. Solution:	Provide min. 1 fume hood or biosafety cabinet with accessible knee clearance
Barrier Severity:	3 Hindrance Cost Est \$12,450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	
i leiu Date.	1/29/2017 Report Date 3/23/2017 Barrier #: 12T
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Biosafety Cabinet Reach Range - High
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at max. 48" high for side reach
Findings:	Biosafety cabinet controls 60" high
Rec. Solution:	Provide extension for control to provide reach range
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12U
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	IN/A I Cooldinate. IN/A
Darrier Area.	Laboratory Facilities
Barrier Type:	
	Laboratory Facilities
Barrier Type: Code	Laboratory Facilities Electrical Outlets - Forward Reach Obstructed (10"-25") 2010 ADAS 306.3.2
Barrier Type: Code References:	Laboratory Facilities Electrical Outlets - Forward Reach Obstructed (10"-25") 2010 ADAS 306.3.2
Barrier Type: Code References: Performance Sta Barrier	Laboratory Facilities Electrical Outlets - Forward Reach Obstructed (10"-25") 2010 ADAS 306.3.2 andard: No Quantity: EACH As-built: 1
Barrier Type: Code References: Performance Sta Barrier Description:	Laboratory Facilities Electrical Outlets - Forward Reach Obstructed (10"-25") 2010 ADAS 306.3.2 andard: No Quantity: EACH As-built: 1 Outlet located over an 10" to 25" obstruction max. 34" high located above 44"
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Laboratory Facilities Electrical Outlets - Forward Reach Obstructed (10"-25") 2010 ADAS 306.3.2 andard: No Quantity: EACH As-built: 1 Outlet located over an 10" to 25" obstruction max. 34" high located above 44" 39-1/4" high and 26" deep over an obstruction 31" high inside cabinet Relocate control or mechanism to max. 44" high
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Laboratory Facilities Electrical Outlets - Forward Reach Obstructed (10"-25") 2010 ADAS 306.3.2 andard: No Quantity: EACH As-built: 1 Outlet located over an 10" to 25" obstruction max. 34" high located above 44" 39-1/4" high and 26" deep over an obstruction 31" high inside cabinet Relocate control or mechanism to max. 44" high 2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12V
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Clear Floor Space - Controls
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Fume hood blocks electrical outlet clear floor space
Rec. Solution:	Move stored items at control or mechanism
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12W
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Freezer controls 29" - 63" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12X
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Accessible Route - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space at element does not adjoin an accessible route or another space
Findings:	Cabinets reduce passage way to 29"
Rec. Solution:	Move elements to provide connection to accessible route
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12Y
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	23" knee clearance
Rec. Solution:	Provide min. 3 ft segment of accessible counter. Flip-up counters, adiacent tables and similar de
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12Z
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Clear Floor Space - Controls
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Gas tank blocks lab equipment clear floor space
Rec. Solution:	Move stored items at control or mechanism
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12AA
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Lab equipment on counter controls 42" - 52" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 12AB
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Classroom/Wet Laboratory 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/strobe
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 13A
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Sterilizing Room 0100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Raised Characters - Sharp Edges
Code References:	2010 ADAS Advisory 703.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Signs that are designed to be read by touch have sharp or abrasive edges
Findings:	Existing sign not accessible
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 13B
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Sterilizing Room 0100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Front App/pull 18" SEC - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	Items block strike edge clearance
Rec. Solution:	Remove stored item
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 13C
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Sterilizing Room 0100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Clear Floor Space - Controls
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Items block electrical switch clear floor space
Rec. Solution:	Move stored items at control or mechanism
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
•	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 13D
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Sterilizing Room 0100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 13E
Plda Namo	
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Sterilizing Room 0100A
Location:	
Location:	Floor 1 - Sterilizing Room 0100A
Location: X Coordinate:	Floor 1 - Sterilizing Room 0100A N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 1 - Sterilizing Room 0100A N/A Y Coordinate: N/A Clear Floor Space
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 1 - Sterilizing Room 0100A N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 1 - Sterilizing Room 0100A N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 1 - Sterilizing Room 0100A N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 ndard: No Quantity: JOB As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - Sterilizing Room 0100A N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 ndard: No Quantity: JOB As-built: 1 Circulation route not min. 36" wide between elements
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - Sterilizing Room 0100A N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 ndard: No Quantity: JOB As-built: 1 Circulation route not min. 36" wide between elements 32" wide circulation route
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 1 - Sterilizing Room 0100A N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 ndard: No Quantity: JOB As-built: 1 Circulation route not min. 36" wide between elements 32" wide circulation route Rearrange furniture to provide accessible circulation path 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 13F
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Sterilizing Room 0100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 305
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	37" turning space at end of space
Rec. Solution:	Move stored items blocking maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 13G
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Sterilizing Room 0100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Sink - Rim or Countertop
Code References:	2010 ADAS 606.3
Performance Sta	andard: No Quantity: LF As-built: 3
Barrier Description:	Sink rim or surface not max. 34" high
Findings:	37" high
Rec. Solution:	Reposition existing sink or provide additional sink for use in area
Barrier Severity:	1 Necessary Cost Est \$1,110.00 Facility Function: Public Status: Open
Implementation	· — · — · — · — —
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 13H
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Sterilizing Room 0100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Sink - Knee Clearance
Code References:	2010 ADAS 606.2 & 306
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	No knee clearance
Rec. Solution:	Replace cabinet and remount sink
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 13I
Field Date: Bldg Name:	1/29/2017 Report Date 3/23/2017 Barrier #: 13I Dryden Hall Reference Dwg: 2 of 4
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Sterilizing Room 0100A
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Sterilizing Room 0100A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Sterilizing Room 0100A N/A Y Coordinate: N/A Laboratory Facilities
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Sterilizing Room 0100A N/A Y Coordinate: N/A Laboratory Facilities Workstation - Surface 2010 ADAS 902
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Sterilizing Room 0100A N/A Y Coordinate: N/A Laboratory Facilities Workstation - Surface 2010 ADAS 902
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Sterilizing Room 0100A N/A Y Coordinate: N/A Laboratory Facilities Workstation - Surface 2010 ADAS 902 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Sterilizing Room 0100A N/A Y Coordinate: N/A Laboratory Facilities Workstation - Surface 2010 ADAS 902 ndard: No Quantity: EACH As-built: 1 Table or workstation surface height exceeds 34" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Sterilizing Room 0100A N/A Y Coordinate: N/A Laboratory Facilities Workstation - Surface 2010 ADAS 902 ndard: No Quantity: EACH As-built: 1 Table or workstation surface height exceeds 34" high 37" workstation surface height
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Sterilizing Room 0100A N/A Y Coordinate: N/A Laboratory Facilities Workstation - Surface 2010 ADAS 902 ndard: No Quantity: EACH As-built: 1 Table or workstation surface height exceeds 34" high 37" workstation surface height Provide min. 1 accessible workstation of each type or overall 5% 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 13J
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Sterilizing Room 0100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Workstation - Knee Clearance
Code References:	2010 ADAS 902
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	No knee clearance
Rec. Solution:	Provide min. 1 accessible workstation of each type or overall 5%
Barrier Severity:	1 Necessary Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 13K
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Sterilizing Room 0100A
X Coordinate:	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Area: Barrier Type:	Laboratory Facilities Shelves or Cabinet
	Laboratory Facilities
Barrier Type: Code	Laboratory Facilities Shelves or Cabinet 2010 ADAS 603.4
Barrier Type: Code References:	Laboratory Facilities Shelves or Cabinet 2010 ADAS 603.4
Barrier Type: Code References: Performance Sta Barrier	Laboratory Facilities Shelves or Cabinet 2010 ADAS 603.4 Indard: No Quantity: EACH As-built: 1
Barrier Type: Code References: Performance Sta Barrier Description:	Laboratory Facilities Shelves or Cabinet 2010 ADAS 603.4 Indard: No Quantity: EACH As-built: 1 Shelf or cabinet not mounted between 40" and 48" above floor or ground
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Laboratory Facilities Shelves or Cabinet 2010 ADAS 603.4 Indard: No Quantity: EACH As-built: 1 Shelf or cabinet not mounted between 40" and 48" above floor or ground 57" - 89" high Provide additional shelf/cabinet at accessible height or provide assistance
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Laboratory Facilities Shelves or Cabinet 2010 ADAS 603.4 Indard: No Quantity: EACH As-built: 1 Shelf or cabinet not mounted between 40" and 48" above floor or ground 57" - 89" high Provide additional shelf/cabinet at accessible height or provide assistance 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 13L
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Sterilizing Room 0100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Clear Floor Space - Controls
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Cart blocks control panel clear floor space at C600 sterilizer
Rec. Solution:	Move stored items at control or mechanism
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 13M
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Sterilizing Room 0100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Panel View C600 controls 61" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 13N
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Sterilizing Room 0100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/strobe
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 14A
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Women's Restroom 0103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Raised Characters - Sharp Edges
Code References:	2010 ADAS Advisory 703.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Signs that are designed to be read by touch have sharp or abrasive edges.
Findings:	Existing sign not accessible
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 14B
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Women's Restroom 0103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Sign
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: JOB As-built: 2
Barrier Description:	ISA symbol at automatic door opening device not min. 4" x 4" in size
Findings:	Existing symbol 1-3/4" high. Not visible from a distance
Rec. Solution:	Recommended: Provide ISA symbol min. 4" x 4" in size
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 14C
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Women's Restroom 0103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - BHMA Sign
Code References:	ANSI/BHMA A156.10-1999
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	No sign on door visible from both sides reading, "AUTOMATIC DOOR"
Findings:	No sign provided
Rec. Solution:	Provide new sign on both sides of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 14D
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Women's Restroom 0103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Timing
Code References:	2010 ADAS 404.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Door does not re-open when encountering an obstruction other than the door jamb
Findings:	Door does not re-open
Rec. Solution:	Repair actuation device
Barrier Severity:	1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 14E
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Women's Restroom 0103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Height
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Dispenser control point or operating mechanism not max. 48" AFF
Findings:	Paper towel dispenser 50" high
Rec. Solution:	Remount no higher than 48" above floor
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	implementation ridge.



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 14F
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Women's Restroom 0103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	Protruding dispenser creates protruding object in path of travel
Findings:	Soap and paper towel dispensers protrude 5" and 10" at 39" and 51" high
Rec. Solution:	Relocate dispenser or provide cane-detectable warning
Barrier Severity:	2 Recommended Cost Est \$1,100.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 14G
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Women's Restroom 0103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Counter or table in route of travel protrudes more than 4" above 27" high
Findings:	Free-standing counter protrudes 24" at 30" high in path of travel
Rec. Solution:	Provide cane-detectable warning that reaches below 27" high for the visually impaired
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 14H
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Women's Restroom 0103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Faucet
Code References:	2010 ADAS 606.4
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Lavatory faucet does not remain open for at least 10 seconds
Findings:	2 second sweep
Rec. Solution:	Replace faucet
Barrier Severity:	1 Necessary Cost Est \$375.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 14I
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Women's Restroom 0103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Drainpipes
Code References:	2010 ADAS 606.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hot water and drainpipes accessible under lavatory not insulated or covered
Findings:	Insulation is damaged
Rec. Solution:	Insulate drainpipes and hot water pipes
Barrier Severity:	2 Recommended Cost Est \$220.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 14J
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Women's Restroom 0103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Electrical Outlets
Code References:	2010 ADAS 205.1 & 309.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves reach of more than 10" over an obstruction
Findings:	46" high and 17" deep
Rec. Solution:	Relocate outlet to area with max. 10 reach
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 14K
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Women's Restroom 0103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Door Closer
Code References:	2010 ADAS 604.8.1.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Stall door not equipped with an automatic closing device
Findings:	Door does not self-close
Rec. Solution:	
	Replace compartment hinge with adjustable mechanism
Barrier Severity:	
	2 Recommended Cost Est \$1,650.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 14L
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Women's Restroom 0103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Stall - Door Hardware
Code References:	2010 ADAS 604.8.1.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Outside of compartment door lacks a loop or U-pull below latch
Findings:	No U-pull provided
Rec. Solution:	Provide hardware
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 14M
Field Date: Bldg Name:	1/28/2017 Report Date 3/23/2017 Barrier #: 14M Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Women's Restroom 0103
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Women's Restroom 0103 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Women's Restroom 0103 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Women's Restroom 0103 N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Women's Restroom 0103 N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Women's Restroom 0103 N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Women's Restroom 0103 N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 ndard: No Quantity: EACH As-built: 1 Inside of compartment door lacks a loop or U-pull below latch
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Women's Restroom 0103 N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 ndard: No Quantity: EACH As-built: 1 Inside of compartment door lacks a loop or U-pull below latch No U-pull provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Women's Restroom 0103 N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 Inside of compartment door lacks a loop or U-pull below latch No U-pull provided Provide hardware 1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 14N
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Women's Restroom 0103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Entry - Front App/push 48"
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: SF As-built : 120
Barrier Description:	Stall door at push side min. 12" lacks strike edge clearance
Findings:	5" strike edge clearance
Rec. Solution:	Redesign toilet room to provide maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$66,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 140
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Women's Restroom 0103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Stall - Coat Hook
Code References:	2010 ADAS 603.4
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	66" high
Rec. Solution:	Provide additional hook
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 14P
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Women's Restroom 0103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
	Restrooms
Barrier Type:	Toilet Paper Dispenser
Code References:	2010 ADAS 604.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Toilet tissue dispenser not within 7" to 9" from front edge of toilet
Findings:	14" from rim
Rec. Solution:	Reposition or replace toilet paper dispenser
Barrier Severity:	3 Hindrance Cost Est \$225.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 15A
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Men's Restroom 0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Raised Characters - Sharp Edges
Code References:	2010 ADAS Advisory 703.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Signs that are designed to be read by touch have sharp or abrasive edges.
Findings:	Existing sign not accessible
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 15B
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Men's Restroom 0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Sign
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: JOB As-built : 2
Barrier Description:	ISA symbol at automatic door opening device not min. 4" x 4" in size
Findings:	Existing symbol 1-3/4" high. Not visible from a distance
Rec. Solution:	Recommended: Provide ISA symbol min. 4" x 4" in size
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 15C
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Men's Restroom 0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - BHMA Sign
Code References:	ANSI/BHMA A156.10-1999
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	No sign on door visible from both sides reading, "AUTOMATIC DOOR"
Findings:	No sign provided
Rec. Solution:	Provide new sign on both sides of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 15D
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Men's Restroom 0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Timing
Code References:	2010 ADAS 404.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Door does not remain open for at least 6 seconds
Findings:	Door closes after 5 seconds
Rec. Solution:	Repair actuation device
Barrier Severity:	1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 15E
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Men's Restroom 0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Timing
Code References:	2010 ADAS 404.3
Performance Sta	andard: No Quantity: JOB As-built : 0
Barrier Description:	Door does not re-open when encountering an obstruction other than the door jamb
Findings:	Door does not re-open
Rec. Solution:	Repair actuation device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 15F
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Men's Restroom 0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	Counter or table in route of travel protrudes more than 4" above 27" high
Findings:	Counter protrudes 24" at 30" high within path of travel
Rec. Solution:	Provide cane-detectable warning that reaches below 27" high for the visually impaired
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 15G
Field Date: Bldg Name:	1/28/2017 Report Date 3/23/2017 Barrier #: 15G Dryden Hall Reference Dwg: 2 of 4
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Men's Restroom 0102
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Men's Restroom 0102 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Men's Restroom 0102 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Men's Restroom 0102 N/A Y Coordinate: N/A Restrooms Lavatory - Faucet 2010 ADAS 606.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Men's Restroom 0102 N/A Y Coordinate: N/A Restrooms Lavatory - Faucet 2010 ADAS 606.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Men's Restroom 0102 N/A Y Coordinate: N/A Restrooms Lavatory - Faucet 2010 ADAS 606.4 Indard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Men's Restroom 0102 N/A Y Coordinate: N/A Restrooms Lavatory - Faucet 2010 ADAS 606.4 Indard: No Quantity: JOB As-built: 1 Lavatory faucet does not remain open for at least 10 seconds
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Men's Restroom 0102 N/A Y Coordinate: N/A Restrooms Lavatory - Faucet 2010 ADAS 606.4 Indard: No Quantity: JOB As-built: 1 Lavatory faucet does not remain open for at least 10 seconds 2 second sweep Replace faucet
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Ploor 1 - Men's Restroom 0102 N/A Y Coordinate: N/A Restrooms Lavatory - Faucet 2010 ADAS 606.4 Indard: No Quantity: JOB As-built: 1 Lavatory faucet does not remain open for at least 10 seconds 2 second sweep Replace faucet 1 Necessary Cost Est \$375.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 15H
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Men's Restroom 0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Electrical Outlets
Code References:	2010 ADAS 205.1 & 309.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves reach of more than 10" over an obstruction
Findings:	46" high and 20" deep
Rec. Solution:	Relocate outlet to area with max. 10 reach
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 15I
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Men's Restroom 0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Height
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Dispenser control point or operating mechanism not max. 48" AFF
Findings:	Paper towel dispenser 51" high
Rec. Solution:	Remount no higher than 48" above floor
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 15J
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Men's Restroom 0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding dispenser creates protruding object in path of travel
Findings:	Paper towel dispenser protrudes 10" at 51" high
Rec. Solution:	Relocate dispenser or provide cane-detectable warning
Barrier Severity:	2 Recommended Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 15K
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Men's Restroom 0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Accessible Route
Code References:	2010 ADAS 402 & 403
Performance Sta	andard: No Quantity: SF As-built : 0
Barrier Description:	Accessible route to sanitary facility blocked by stored items
Findings:	Trash bin reduces accessible route to stall
Rec. Solution:	Remove stored item
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 15L
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Men's Restroom 0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Door Closer
Code References:	2010 ADAS 604.8.1.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Stall door not equipped with an automatic closing device
Findings:	Door does not self-close
Rec. Solution:	Replace compartment hinge with adjustable mechanism
Barrier Severity:	2 Recommended Cost Est \$1,650.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
-	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 15M
Field Date: Bldg Name:	1/28/2017 Report Date 3/23/2017 Barrier #: 15M Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Men's Restroom 0102
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Men's Restroom 0102 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Men's Restroom 0102 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Men's Restroom 0102 N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Men's Restroom 0102 N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Men's Restroom 0102 N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Men's Restroom 0102 N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 ndard: No Quantity: EACH As-built: 1 Outside of compartment door lacks a loop or U-pull below latch
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Men's Restroom 0102 N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 ndard: No Quantity: EACH As-built: 1 Outside of compartment door lacks a loop or U-pull below latch No U-pull provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Men's Restroom 0102 N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 ndard: No Quantity: EACH As-built: 1 Outside of compartment door lacks a loop or U-pull below latch No U-pull provided Provide hardware 1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 15N
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Men's Restroom 0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Stall - Door Hardware
Code References:	2010 ADAS 604.8.1.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Inside of compartment door lacks a loop or U-pull below latch
Findings:	No U-pull provided
Rec. Solution:	Provide hardware
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 150
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Men's Restroom 0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Stall - Coat Hook
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	66" high
Rec. Solution:	Provide additional hook
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 15P
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Men's Restroom 0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Paper Dispenser
Code References:	2010 ADAS 604.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Toilet tissue dispenser not within 7" to 9" from front edge of toilet
Findings:	11" from rim
Rec. Solution:	Reposition or replace toilet paper dispenser
Barrier Severity:	3 Hindrance Cost Est \$225.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 16A
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - To Exit Door
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Exit door leading directly to an exit to the exterior lacks tactile exit sign
Findings:	Door leading to exit door to exterior lacks tactile exit sign
Rec. Solution:	
	Provide sign stating "EXIT ROUTE" at exit side of door
Barrier Severity:	Provide sign stating "EXIT ROUTE" at exit side of door 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Barrier Severity: Implementation	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 16B
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	ISA - Accessible Entry Door
Code References:	2010 ADAS 216.6
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No sign identifying door as accessible where all doors are not accessible
Findings:	No sign provided to indicate that entrance is accessible
Rec. Solution:	Provide ISA at accessible entrance door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 16C
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Sign
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: JOB As-built : 2
Barrier Description:	ISA symbol at automatic door opening device not min. 4" x 4" in size
Findings:	Existing symbol 1-3/4" high. Not visible from a distance
Rec. Solution:	Recommended: Provide ISA symbol min. 4" x 4" in size
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 16D
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - BHMA Sign
Code References:	ANSI/BHMA A156.10-1999
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No sign on door visible from both sides reading, "AUTOMATIC DOOR"
Findings:	No sign provided
Rec. Solution:	Provide new sign on both sides of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 16E
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Timing
Code References:	2010 ADAS 404.3
Performance Sta	ndard: No Quantity: JOBf4e As-built : 1
Barrier Description:	Door does not re-open when encountering an obstruction other than the door jamb
Findings:	Door does not re-open
Rec. Solution:	Repair actuation device
Barrier Severity:	1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 16F
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Doormat
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Doormat not anchored to floor (possible trip hazard)
Findings:	Door mat not secured
Rec. Solution:	Secure exiting doormat or replace
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 16G
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Vending Machine - High Reach Range
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Vending machine point of control not at max. 48" high for side reach
Findings:	52" high
Rec. Solution:	Contact vendor to obtain replacement
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 16H
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Lobby Info Sign
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	No lobby informational sign with location of accessible elements
Findings:	Existing sign not accessible
Rec. Solution:	Provide lobby informational sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 16I
Field Date: Bldg Name:	1/28/2017 Report Date 3/23/2017 Barrier #: 16I Dryden Hall Reference Dwg: 2 of 4
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Lobby L0102
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Hi/low Reach 2010 ADAS 308.2.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Hi/low Reach 2010 ADAS 308.2.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Hi/low Reach 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Hi/low Reach 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 1 Use of control involves low reach of less than 15" above floor or more than 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Hi/low Reach 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 1 Use of control involves low reach of less than 15" above floor or more than 48" high Hand sanitizer dispenser 50" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Ploor 1 - Lobby L0102 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Hi/low Reach 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 1 Use of control involves low reach of less than 15" above floor or more than 48" high Hand sanitizer dispenser 50" high Relocate to area at min. 15" or max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 16J
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 16K
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 2 of 4 Floor 1 - Lobby L0102
_	
Location:	Floor 1 - Lobby L0102
Location: X Coordinate:	Floor 1 - Lobby L0102 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Signage
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Door 2010 ADAS 216.4.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Door 2010 ADAS 216.4.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 1 - Lobby L0102 N/A Signage Tactile Exit Signs - Door 2010 ADAS 216.4.1 andard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Door 2010 ADAS 216.4.1 andard: No Quantity: EACH As-built: 1 Ground floor doors that exit to exterior lacks tactile exit sign
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Door 2010 ADAS 216.4.1 andard: No Quantity: EACH As-built: 1 Ground floor doors that exit to exterior lacks tactile exit sign Exit door with low level illuminated sign lacks tactile exit sign Provide sign stating "EXIT" at exit side of door
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Door 2010 ADAS 216.4.1 andard: No Quantity: EACH As-built: 1 Ground floor doors that exit to exterior lacks tactile exit sign Exit door with low level illuminated sign lacks tactile exit sign Provide sign stating "EXIT" at exit side of door 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 16L
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Sign
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: JOB As-built : 2
Barrier Description:	ISA symbol at automatic door opening device not min. 4" x 4" in size
Findings:	Existing symbol 1-3/4" high. Not visible from a distance
Rec. Solution:	Recommended: Provide ISA symbol min. 4" x 4" in size
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 16M
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - BHMA Sign
Code References:	ANSI/BHMA A156.10-1999
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No sign on door visible from both sides reading, "AUTOMATIC DOOR"
Findings:	No sign provided
Rec. Solution:	Provide new sign on both sides of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 16N
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Timing
Code References:	2010 ADAS 404.3
Performance Sta	andard: No Quantity: JOBf4e As-built : 1
Barrier Description:	Door does not re-open when encountering an obstruction other than the door jamb
Findings:	Door does not re-open
Rec. Solution:	Repair actuation device
Barrier Severity:	1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 160
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Doormat
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Doormat not anchored to floor (possible trip hazard)
Findings:	Door mat not secured
Rec. Solution:	Secure exiting doormat or replace
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 17A
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry V0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door to Room 112 within door landing
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 17B
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Entry V0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 18A
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Exit Stairway S0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Sign - Enclosed Exit Stairway Discharge
Code References:	ICC A117.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Tactile stairway signage not provided to indicate stair level or discharge level
Findings:	No sign provided
Rec. Solution:	Provide sign indicating stair level and discharge level (raised star) where applicable
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 18B
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Exit Stairway S0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail - Both Sides
Code References:	ADAAG 4.9.4* & 2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built : 73
Barrier Description:	No handrail provided at both sides of stairway
Findings:	No handrail provided at both sides
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$16,425.00 Facility Function: Public Status: Open
Implementation	
	Priority: 3 Implementation Phase: Implementation Date:



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 18C
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Exit Stairway S0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Height
Code References:	2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built: 73
Barrier Description:	Handrail grip measured at center not 34"- 38" high
Findings:	32" handrail grip height
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$16,425.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Outer ra	ail
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 18D
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Exit Stairway S0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Bottom
Code References:	2010 ADAS 505.10.3
Performance Sta	ndard: No Quantity: LF As-built : 8
Barrier Description:	Extension not sloped for length of one tread beyond the last riser nosing
Findings:	Extension not sloped for the length of one tread long
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$1,800.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 18E
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Exit Stairway S0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Top
Code References:	2010 ADAS 505.10.2
Performance Sta	andard: No Quantity: LF As-built : 8
Barrier Description:	Extension does not extend horizontally above landing for min. 12" from first riser nosing
Findings:	Extension not sloped for the length of one tread long
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$1,800.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 18F
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Exit Stairway S0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail - Opening Limitations
Code References:	Performance Standard
Performance Sta	andard: No Quantity: LF As-built: 73
Barrier Description:	Guard or handrail have openings that allow passage of a 4" sphere
Findings:	4-1/4" opening and guardrail grip height 29"
Rec. Solution:	Replace handrails
Barrier Severity:	1 Necessary Cost Est \$16,425.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/28/2017 Report Date 3/23/2017 Barrier #: 18G
Bldg Name:	Dryden Hall Reference Dwg: 2 of 4
Location:	Floor 1 - Exit Stairway S0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code References:	2010 ADAS Advisory 504.4
Performance Sta	andard: Yes Quantity: LF or TR As-built: 58
Barrier Description:	No contrasting color on each tread of interior stairway
Findings:	Treads lack contrasting color defined as 70% contrast
Rec. Solution:	Recommended: Consider providing contrasting color on each tread
Barrier Severity:	2 Recommended Cost Est \$2,030.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 19A
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 1 - Exit Stairway S0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Sign - Enclosed Exit Stairway Door
Code References:	2010 ADAS 216.4.1
Performance Sta	andard: Yes Quantity: EACH As-built: 1
Barrier Description:	Door leading directly into an exit stairway lacks tactile exit sign
Findings:	Door to exit stair with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT STAIR DOWN (or UP)" at latch side of door
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 19B
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 1 - Exit Stairway S0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	11 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$900.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 19C
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 1 - Exit Stairway S0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built: 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	2 second sweep
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 19D
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 1 - Exit Stairway S0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	48" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 19E
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 1 - Exit Stairway S0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Sign - Enclosed Exit Stairway Level
Code References:	ICC A117.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Tactile stairway signage not provided to indicate floor level
Findings:	No sign provided
Rec. Solution:	Provide sign
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 19F
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 1 - Exit Stairway S0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 19G
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 1 - Exit Stairway S0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Card swipe control 57" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 19H
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 1 - Exit Stairway S0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 20A
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Elevator E0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Audible Signals
Code References:	2010 ADAS 407.2.2.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Audible signals or verbal announcement does not sound when the car passes a floor or stops
Findings:	No audible signals provided
Rec. Solution:	Replace car controls
Barrier Severity:	2 Recommended Cost Est \$2,750.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 20B
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Elevator E0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Hall lanterns - Visible at Entry
Code References:	2010 ADAS 407.2.2.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Visual and audible signals not provided at each hoistway entrance to answer calls
Findings:	Hall lanterns not visible from outer side of elevator
Rec. Solution:	Provide hall lanterns visible from outer side of elevator
Barrier Severity:	1 Necessary Cost Est \$3,675.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 21A
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Sign - Permanent Room/Space
Code References:	2010 ADAS 703.1
Performance Sta	andard: No Quantity: EACH As-built : 14
Barrier Description:	No sign with raised characters and Braille at permanent room or space with visual sign
Findings:	No tactile info on sign with visual information
Rec. Solution:	Provide sign at latch side of entry door, where possible
Barrier Severity:	1 Necessary Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Rooms 2	214, 215, 211, 210, 209, 208A, 208, 207, 206, 216, 205, 204, 201, 200



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 21B
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Evacuation Plan
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built : 1
Barrier Description:	No evacuation plan provided
Findings:	No evacuation sign provided
Rec. Solution:	Provide evacuation sign usable by the visually impaired
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 21C
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 21D
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Alcove - Existing (pre-1992)
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: JOB As-built: 1
Barrier Description:	Fountain with a leading edge between 27" and 80" high protrudes more than 4" into the circulation path.
Findings:	No alcove provided
Rec. Solution:	Provide wing walls as detectable warning (existing unit only)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 21E
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Drinking Fountains for Standing Persons
Code References:	2010 ADAS 602.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Spout outlets of drinking fountains for standing persons not 38" minimum and 43" maximum above floor or ground
Findings:	Wheelchair accessible unit not usable for persons with bending/stooping injuries
Rec. Solution:	Provide one hi-low fountain or separate fixtures serving both groups of people
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 21F
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Bubbler height
Code References:	2010 ADAS 602.4
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Bubbler height exceeds 36"
Findings:	37-1/4" bubbler height
Rec. Solution:	Replace drinking fountain with wheelchair accessible unit or remount existing
Barrier Severity:	1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 21G
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	No strobe provided in corridor where horn is provided where fire alarm exists in building
Findings:	No strobe where horn is provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$11,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 21H
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull - Operation
Code References:	2010 ADAS 309.4
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Fire pull has no fist operable hardware
Findings:	Fire pull not fist operable
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 211
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull - Height
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Fire pulls not between 42" and 48" high
Findings:	61-1/2" high
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 21J
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Panel protrudes 6" at 55" high. Fire extinguisher protrudes 4-1/4" at 44" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$1,100.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 21K
	3,23,2017
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Hall H0201
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Hall H0201 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Corridors Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Corridors Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Corridors Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Corridors Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Control or mechanism not at min. 15" or max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Hall H0201 N/A Corridors Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Control or mechanism not at min. 15" or max. 48" high Fire blanket cabinet controls 56" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Corridors Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Control or mechanism not at min. 15" or max. 48" high Fire blanket cabinet controls 56" high Relocate control or mechanism to min. 15" or max. 48" high Relocate control or mechanism to min. 15" or max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 21L
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Turning Space
Barrier Type:	Circular Turning Space - Min. 60"
Code References:	2010 ADAS 304.3.1
Performance Sta	andard: No Quantity: SF As-built : 25
Barrier Description:	Circular turning space not minimum of 60" in diameter (including toe/knee space)
Findings:	59" turning space at fire blanket cabinet
Rec. Solution:	Relocate to location where accessible turning circle is provided
Barrier Severity:	2 Recommended Cost Est \$1,875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 22A
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Waiting Room 0213
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 22B
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Waiting Room 0213
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - Wheelchair Use
Code References:	2010 ADAS 305
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Waiting area lacks resting space for wheelchair users that his not part of a door swing
Rec. Solution:	Rearrange furniture to provide accessible waiting area for people using wheelchairs
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 22C
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Waiting Room 0213
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Strobe Height - Existing
Code References:	2010 ADAS 702
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	Strobe not mounted at 80" AFF or 96" high, whichever is lower
Findings:	79" high
Rec. Solution:	
	Relocate strobe to min. 80" high
Barrier Severity:	
Barrier Severity: Implementation	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 22D
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Waiting Room 0213
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull - Operation
Code References:	2010 ADAS 309.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Fire pull has no fist operable hardware
Findings:	Fire pull not fist operable
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 22E
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Waiting Room 0213
X Coordinate:	V Coordinates N/A
	N/A Y Coordinate: N/A
Barrier Area:	Signage Y Coordinate: JN/A
Barrier Area: Barrier Type:	
	Signage
Barrier Type: Code	Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Barrier Type: Code References:	Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Barrier Type: Code References: Performance Sta Barrier	Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 4
Barrier Type: Code References: Performance Sta Barrier Description:	Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 4 No tactile characters at sign identifying permanent rooms and spaces with visual signs
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 4 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 4 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign 1 Necessary Cost Est \$1,000.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 22F
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Waiting Room 0213
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Pedestal Base
Code References:	2010 ADAS 306.2.2 & 306.2.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	Pedestal base blocks knee clearance
Rec. Solution:	Provide min. 1 accessible table. Avoid pedestal base tables.
Barrier Severity:	2 Recommended Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 22G
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Waiting Room 0213
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Extinguisher - Cabinet Hardware
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Fire extinguisher door hardware not usable by those with hand impairments
Findings:	Cabinet door hardware not accessible and clear floor space blocked by table
Rec. Solution:	Relocate fire extinguisher hardware
Barrier Severity:	4 Low Severity Cost Est \$1,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 22H
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Waiting Room 0213
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Extinguisher - Side Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: JOB As-built: 0
Barrier Description:	Fire extinguisher forward or side reach exceeds 48"
Findings:	Hammer used to break glass on door and access extinguisher located on top of fire extinguisher at 62" high
Rec. Solution:	Relocate hammer for fire extinguisher
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 221
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Waiting Room 0213
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Extinguisher - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: JOB As-built: 1
Barrier Description:	Fire extinguisher protrudes into circulation path more than 4" between 27" and 80"
Findings:	Fire extinguisher protrudes 6-1/2" at 44" high
Rec. Solution:	Remount extinguisher with leading edge below 27" or provide detectable warning
Barrier Severity:	4 Low Severity Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 22J
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Waiting Room 0213
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Mailbox - High Reach Range
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Mailbox opening is above 48" high
Findings:	54" high mail drop
Rec. Solution:	Relocate to provide opening at max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 23A
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Classroom 0212B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Treecosti y
Implementation	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 23B
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Classroom 0212B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Door Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Operating controls involve tight grasping, pinching or twisting
Findings:	Hardware not operable with a closed fist
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 23C
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Classroom 0212B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 23D
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Classroom 0212B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Protruding Object - Wall-mounted
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Wall mounted object protrudes more than 4" from wall
Findings:	Monitor protrudes 5" at 80" high
Rec. Solution:	Remove object or provide detectable warning for the visually impaired
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 23E
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Classroom 0212B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Accessible Route - Cords
Code References:	2010 ADAS 303.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Change in level greater than 1/2" in clear floor space at cords
Findings:	Cords create trip hazard
Rec. Solution:	Provide accessible cord cover or otherwise remove barrier to access
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 23F
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Classroom 0212B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Heater control 63" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 23G
Field Date: Bldg Name:	1/29/2017 Report Date 3/23/2017 Barrier #: 23G Dryden Hall Reference Dwg: 3 of 4
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Classroom 0212B
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Classroom 0212B N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Classroom 0212B N/A Y Coordinate: N/A Clear Floor Space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Classroom 0212B N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Classroom 0212B N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Classroom 0212B N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Classroom 0212B N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 ndard: No Quantity: JOB As-built: 1 Circulation route not min. 36" wide between elements
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Classroom 0212B N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 ndard: No Quantity: JOB As-built: 1 Circulation route not min. 36" wide between elements 33" wide circulation route around table due to coat rack
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Classroom 0212B N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 Circulation route not min. 36" wide between elements 33" wide circulation route around table due to coat rack Rearrange furniture to provide accessible circulation path 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 23H
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Classroom 0212B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Coat Hook - Clear Space
Code References:	2010 ADAS 603.4
Performance Sta	andard: No Quantity: EACH As-built: 0
Barrier Description:	Clothing hooks not located within 30" x 48" clear floor space
Findings:	Clear floor space not provided at clothing rack
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 231
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Classroom 0212B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 603.4
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	74" high clothing rack
Rec. Solution:	Provide additional hook in new location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 23J
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Classroom 0212B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Table blocks fan switch clear floor space
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 23K
Field Date: Bldg Name:	1/29/2017 Report Date 3/23/2017 Barrier #: 23K Dryden Hall Reference Dwg: 3 of 4
	- COALL
Bldg Name: Location:	Dryden Hall Reference Dwg: 3 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Classroom 0212B
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Classroom 0212B N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Classroom 0212B N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Classroom 0212B N/A Y Coordinate: N/A Classrooms Electrical Switches - High Unobstructed 2010 ADAS 308.2.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Classroom 0212B N/A Y Coordinate: N/A Classrooms Electrical Switches - High Unobstructed 2010 ADAS 308.2.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Classroom 0212B N/A Y Coordinate: N/A Classrooms Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Classroom 0212B N/A Y Coordinate: N/A Classrooms Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Classroom 0212B N/A Y Coordinate: N/A Classrooms Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high Fan switch 66" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Classroom 0212B N/A Y Coordinate: N/A Classrooms Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high Fan switch 66" high Relocate switch box top edge to max. 48" high Relocate switch box top edge to max. 48" high A Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



F: 115 ·	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 23L
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Classroom 0212B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Alarm - No Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/strobe
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 24A
Bldg Name:	Defending During
J	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0203
•	
Location:	Floor 2 - Lab 0203
Location: X Coordinate:	Floor 2 - Lab 0203 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 2 - Lab 0203 N/A Y Coordinate: N/A Signage
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 2 - Lab 0203 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 2 - Lab 0203 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 2 - Lab 0203 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 2 - Lab 0203 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 2 - Lab 0203 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 2 - Lab 0203 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 24B
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Door Closer - Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	16 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 24C
Field Date: Bldg Name:	1/29/2017 Report Date 3/23/2017 Barrier #: 24C Dryden Hall Reference Dwg: 3 of 4
	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0203
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0203
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0203 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0203 N/A Y Coordinate: N/A Laboratory Facilities
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0203 N/A Y Coordinate: N/A Laboratory Facilities Door Closer - Sweep 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0203 N/A Y Coordinate: N/A Laboratory Facilities Door Closer - Sweep 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0203 N/A Y Coordinate: N/A Laboratory Facilities Door Closer - Sweep 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0203 N/A Y Coordinate: N/A Laboratory Facilities Door Closer - Sweep 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0203 N/A Y Coordinate: N/A Laboratory Facilities Door Closer - Sweep 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period 2 second sweep
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0203 N/A Y Coordinate: N/A Laboratory Facilities Door Closer - Sweep 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period 2 second sweep Replace or adjust existing closer 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 24D
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Door Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Operating controls involve tight grasping, pinching or twisting
Findings:	Hardware not operable with a closed fist
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 24E
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Doors - Vision Lights
Code References:	2010 ADAS 404.2.11
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	49" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 24F
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Clear Floor Space - Controls
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Stored items and fume hood block electrical switch clear floor space
Rec. Solution:	Move stored items at control or mechanism
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 24G
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	52" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 24H
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 305
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	36" turning space
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 24I
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Fume Hood - Work Surface Rim
Code References:	2010 ADAS 902
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Work surface height exceeds 34" high
Findings:	37" work surface height
Rec. Solution:	Replace workstation or provide alternative accessible workstation
Barrier Severity:	3 Hindrance Cost Est \$12,450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 24J
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Fume Hood - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built: 0
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	Stored items block knee clearance
Rec. Solution:	Move stored objects
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 24K
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Fume Hood Reach Range - High
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Control or mechanism not at max. 48" high for side reach
Findings:	Spigot 49" high
Rec. Solution:	Provide extension for control to provide reach range
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 24L
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Fume Hood Reach Range - High
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at max. 48" high for side reach
Findings:	Fume hood controls 50-1/2" high
Rec. Solution:	Provide extension for control to provide reach range
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 24M
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	75" high
Rec. Solution:	Provide additional hook in new location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 24N
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - Wheelchair Use
Code References:	2010 ADAS 305
Performance Sta	andard: No Quantity: JOB As-built: 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Heater blocks refrigerator strike edge clearance
Rec. Solution:	Move stored items at control or mechanism
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 240
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Clear Floor Space - Controls
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Clear floor space not provided at heater, incubator located in corner, grey VWR machine and microscope
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 24P
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24-1/2" high and blocked by items knee clearance
Rec. Solution:	Provide min. 1 accessible table. Avoid pedestal base tables.
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 24Q
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built: 0
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Grey VWR machine controls 69-1/2" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 24R
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/strobe
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Firld Barr	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 25A
Bldg Name:	1/29/2017 Report Date 3/23/2017 Barrier #: 25A
	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202
Bldg Name: Location:	Dryden Hall Reference Dwg: 3 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202 N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202 N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 25B
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Door Closer - Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	24 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 25C
Field Date: Bldg Name:	1/29/2017 Report Date 3/23/2017 Barrier #: 25C Dryden Hall Reference Dwg: 3 of 4
	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202 N/A Y Coordinate: N/A Laboratory Facilities
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202 N/A Y Coordinate: N/A Laboratory Facilities Door Closer - Sweep 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202 N/A Y Coordinate: N/A Laboratory Facilities Door Closer - Sweep 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202 N/A Y Coordinate: N/A Laboratory Facilities Door Closer - Sweep 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202 N/A Y Coordinate: N/A Laboratory Facilities Door Closer - Sweep 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202 N/A V Coordinate: N/A Laboratory Facilities Door Closer - Sweep 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period 2 second sweep
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Pryden Hall Reference Dwg: 3 of 4 Floor 2 - Lab 0202 N/A Laboratory Facilities Door Closer - Sweep 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period 2 second sweep Replace or adjust existing closer 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 25D
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Door Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Operating controls involve tight grasping, pinching or twisting
Findings:	Hardware not operable with a closed fist
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 25E
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Doors - Vision Lights
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Description:	
Pescription: Findings:	49" high
Findings:	49" high Replace door/gate or vision panel
Findings:	Replace door/gate or vision panel
Findings:	Replace door/gate or vision panel 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open



Ciald Data	1/20/2017 Percet Date 2/22/2017 Persion Ht. 255
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 25F
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Door Clearance Blocked
Code References:	2010 ADAS Figure 404.2.4.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Trash bin or stored items block strike edge clearance at exit side of door
Findings:	Refrigerator blocks strike edge clearance
Rec. Solution:	Relocate fridge to alternate location
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 25G
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Clear Floor Space - Controls
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Refrigerator blocks electrical switch clear floor space
Rec. Solution:	Move stored items at control or mechanism
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 25H
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Wall mounted object (dispensers) protrudes more than 4" from wall
Findings:	Mechanical box protrudes 6" at 40-1/4" high
Rec. Solution:	Relocate, remove object (dispenser) or provide detectable warning for the visually impaired
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Door to	room 203 not in use.
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 25I
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Clear Floor Space - Controls
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Bucket and refrigerator blocks table and heater clear floor space
Rec. Solution:	
	Move stored items at control or mechanism
Barrier Severity:	
Barrier Severity: Implementation	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 25J
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	25" high knee clearance and blocked by stored items
Rec. Solution:	Provide min. 1 accessible table. Avoid pedestal base tables.
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 25K
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Heater controls 56" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 25L
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Fume Hood - Work Surface Rim
Code References:	2010 ADAS 902
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Work surface height exceeds 34" high
Findings:	35" work surface height
Rec. Solution:	Replace workstation or provide alternative accessible workstation
Barrier Severity:	3 Hindrance Cost Est \$12,450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 25M
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Fume Hood - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built: 0
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	Knee clearance blocked by stored items
Rec. Solution:	Move stored objects
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 25N
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Fume Hood - Electrical Switches
Code References:	2010 ADAS 308.2.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	Fume hood controls 48-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 250
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Accessible Route - Cords
Code References:	2010 ADAS 303.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Change in level greater than 1/2" in clear floor space at cords
Findings:	Cords create trip hazard
Rec. Solution:	Provide accessible cord cover or otherwise remove barrier to access
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 25P
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	19" wide circulation route to storage area
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 25Q
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Clear Floor Space - Controls
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Items block electrical clear floor space
Rec. Solution:	Move stored items at control or mechanism
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 25R
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	ADAAG 4.9.4* & 2010 ADAS 505.10.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	49" high
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 25S
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab 0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/strobe
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 26A
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab Room 0217
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 26B
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab Room 0217
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Door Closer - Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	22 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 26C
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab Room 0217
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Door Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Operating controls involve tight grasping, pinching or twisting
Findings:	Hardware not operable with a closed fist
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 26D
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab Room 0217
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Door Threshold (Replace)
Code References:	2010 ADAS 404.2.5
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate threshold height exceeds 1/2"
Findings:	7/8" high metal threshold
Rec. Solution:	Provide new door threshold
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 26E
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab Room 0217
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Door Clearance Blocked
Code References:	2010 ADAS Figure 404.2.4.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Trash bin or stored items block strike edge clearance at exit side of door
Findings:	Cabinet blocks strike edge clearance and 52" perpendicular from door to cart
Rec. Solution:	Relocate cabinet
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 26F
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab Room 0217
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Clear Floor Space - Controls
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Cabinet blocks electrical switch clear floor space
Rec. Solution:	Move stored items at control or mechanism
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 26G
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab Room 0217
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 26H
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab Room 0217
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 305
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	52" turning space at entry
Rec. Solution:	Move stored items blocking maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 261
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab Room 0217
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	31" wide circulation route and no turning space
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 26J
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab Room 0217
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Clear Floor Space
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Clear floor space 30" x 48" not provided at desk
Findings:	Clear floor space not provided at desks and book case
Rec. Solution:	Provide min. 1 accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 26K
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab Room 0217
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	25-3/4" high knee clearance and 28" wide knee clearance at 2 desks in room
Rec. Solution:	Provide min. one accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 26L
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab Room 0217
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Clear Floor Space - Controls
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built: 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Desk blocks electrical outlet clear floor space
Rec. Solution:	Move stored items at control or mechanism
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 26M
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab Room 0217
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Shelves or Cabinet
Code References:	2010 ADAS 603.4
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Shelf or cabinet not mounted between 40" and 48" above floor or ground
Findings:	53" high
Rec. Solution:	Provide additional shelf/cabinet at accessible height or provide assistance
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 26N
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Lab Room 0217
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/strobe
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 27A
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - No Braille/tactile Sign
Code References:	2010 ADAS 703.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No Braille/tactile sign at latch side of door
Findings:	No sign provided
Rec. Solution:	Provide Braille/tactile sign at latch side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 27B
Field Date: Bldg Name:	1/29/2017 Report Date 3/23/2017 Barrier #: 27B Dryden Hall Reference Dwg: 3 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 3 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218 N/A Y Coordinate: N/A Restrooms Sign - ISA at Accessible Restroom 2010 ADAS 216.8
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218 N/A Y Coordinate: N/A Restrooms Sign - ISA at Accessible Restroom 2010 ADAS 216.8
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218 N/A Y Coordinate: N/A Restrooms Sign - ISA at Accessible Restroom 2010 ADAS 216.8 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218 N/A Y Coordinate: N/A Restrooms Sign - ISA at Accessible Restroom 2010 ADAS 216.8 ndard: No Quantity: EACH As-built: 0 No ISA symbol on wall sign posted at accessible toilet room
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218 N/A Y Coordinate: N/A Restrooms Sign - ISA at Accessible Restroom 2010 ADAS 216.8 ndard: No Quantity: EACH As-built: 0 No ISA symbol on wall sign posted at accessible toilet room No sign provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218 N/A Y Coordinate: N/A Restrooms Sign - ISA at Accessible Restroom 2010 ADAS 216.8 No Quantity: EACH As-built: 0 No ISA symbol on wall sign posted at accessible toilet room No sign provided Provide ISA symbol on restroom wall sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 27C
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	17 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 27D
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	2 second sweep
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 27E
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Operating controls involve tight grasping, pinching or twisting
Findings:	Hardware not operable with a closed fist
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 27F
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	49-1/2" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 27G
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Recessed Door - Pull Side
Code References:	2010 ADAS 404.2.4.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door recessed by more than 8" lacks at least 18" clearance at pull side of door
Findings:	Recess 10" with 3-1/2" strike edge clearance
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 27H
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218
	Floor 2 - Women's Restroom 0218 N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Controls and Mechanisms
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Trash bin blocks electrical switch clear floor space
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Trash bin blocks electrical switch clear floor space Move stored items 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 27I
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Electrical Switches
Code References:	2010 ADAS 205.1 & 309.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 27J
Field Date: Bldg Name:	1/29/2017 Report Date 3/23/2017 Barrier #: 27J Dryden Hall Reference Dwg: 3 of 4
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218 N/A Y Coordinate: N/A Clear Floor Space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 305
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 305
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 305 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 305 ndard: No Quantity: JOB As-built: 1 Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 305 ndard: No Quantity: JOB As-built: 1 Clear floor space of min. 60" in diameter not provided where 360 degree turn is made 50" turning space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Ploor 2 - Women's Restroom 0218 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 305 Indiand: No Quantity: JOB As-built: 1 Clear floor space of min. 60" in diameter not provided where 360 degree turn is made 50" turning space Move stored items blocking maneuvering clearance 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 27K
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Sanitary Products
Code References:	2010 ADAS 603.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Sanitary product dispenser not usable with a closed fist
Findings:	Dispenser not fist operable
Rec. Solution:	Replace sanitary napkin dispenser
Barrier Severity:	1 Necessary Cost Est \$650.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 27L
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding dispenser creates protruding object in path of travel
Findings:	Sanitary product dispenser protrudes 6" at 30" high
Rec. Solution:	Relocate dispenser or provide cane-detectable warning
Barrier Severity:	2 Recommended Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 27M
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Coat Hook
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not located within 30" x 48" clear floor space
Findings:	Shelves and door swing block coat hook clear floor space
Rec. Solution:	Relocate hook or provide additional hook
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 27N
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Coat Hook
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	78" high
Rec. Solution:	Provide additional hook in new location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 270
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding dispenser creates protruding object in path of travel
Findings:	Paper towel dispenser protrudes 10" at 40" high
Rec. Solution:	Relocate dispenser or provide cane-detectable warning
Barrier Severity:	2 Recommended Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 27P
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Rim Height
Code References:	2010 ADAS 606.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Lavatory rim or counter edge is higher than 34" AFF
Findings:	35" high
Rec. Solution:	
Rec. Solution.	Provide min. 1 accessible lavatory
Barrier Severity:	
	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 27Q
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Mirror
Code References:	2010 ADAS 603.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface
Findings:	41" high
Rec. Solution:	Replace or remount mirror
Barrier Severity:	3 Hindrance Cost Est \$375.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 27R
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/strobe in sanitary facility
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	
	Priority: 3 Implementation Phase: Implementation Date:



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 28A
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - No Braille/tactile Sign
Code References:	2010 ADAS 703.2.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No Braille/tactile sign at latch side of door
Findings:	No sign provided
Rec. Solution:	Provide Braille/tactile sign at latch side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 28B
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - ISA at Accessible Restroom
Code References:	2010 ADAS 216.8
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	No ISA symbol on wall sign posted at accessible toilet room
Findings:	No sign provided
Rec. Solution:	Provide ISA symbol on restroom wall sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 28C
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	25 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 28D
Field Date: Bldg Name:	1/29/2017 Report Date 3/23/2017 Barrier #: 28D Dryden Hall Reference Dwg: 3 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 3 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218A
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218A N/A Y Coordinate: N/A Restrooms Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218A N/A Y Coordinate: N/A Restrooms Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218A N/A Y Coordinate: N/A Restrooms Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218A N/A Y Coordinate: N/A Restrooms Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218A N/A Y Coordinate: N/A Restrooms Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame 1/2 second sweep
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218A N/A Y Coordinate: N/A Restrooms Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame 1/2 second sweep Provide automatic door opening device 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 28E
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	50" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 28F
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Clearance - Pull Side
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: EACH As-built: 0
Barrier Description:	Door lacks min. 18" strike edge clearance at pull side
Findings:	10-1/2" strike edge clearance at pull side
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 28G
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Maneuvering Clearance
Code References:	2010 ADAS 603.2.1
Performance Sta	andard: No Quantity: SF As-built : 120
Barrier Description:	Entry door encroaches into min. 60" turning space by more than 12"
Findings:	56" turning space
Rec. Solution:	Remodel toilet room
Barrier Severity:	2 Recommended Cost Est \$69,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 28H
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Stall - Door Hardware
Code References:	2010 ADAS 604.8.1.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Inside of compartment door lacks a loop or U-pull below latch
Findings:	No U-pull provided
Rec. Solution:	Provide hardware
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 281
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Stall - Coat Hook
Code References:	2010 ADAS 603.4 & 305
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not within 30" x 48" wheelchair space
Findings:	30" deep
Rec. Solution:	Relocate hook or provide additional hook
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 28J
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Transfer - Floor-mounted
Code References:	2010 ADAS 604.8.1.1
Performance Sta	ndard: No Quantity: SF As-built: 0
Barrier Description:	Min. 60" wide x 59" deep clear floor space not provided at floor-mounted fixture
Findings:	70" wide x 58" deep
Rec. Solution:	Remodel to provide front transfer space
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 28K
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Grab Bars
Code References:	2010 ADAS 604.5 & 609.8
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Grab bars not secure or cannot bear min. 250 N of force
Findings:	Side grab located on partition wall
Rec. Solution:	Replace grab bars with reinforcement
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 28L
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Flush Handle
Code References:	2010 ADAS 604.6
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Handle does not point to wide side of stall or compartment
Findings:	Handle pointing towards small side of stall/room
Rec. Solution:	Provide min. 1 wheelchair accessible closet
Barrier Severity:	1 Necessary Cost Est \$850.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 28M
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Centerline
Code References:	2010 ADAS 604.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Water closet centerline not between 16" and 18" O. C.
Findings:	19" on center
Rec. Solution:	Relocate water closet
Barrier Severity:	3 Hindrance Cost Est \$850.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 28N
Field Date: Bldg Name:	1/29/2017Report Date3/23/2017Barrier #:28NDryden HallReference Dwg:3 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 3 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218A
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218A N/A Y Coordinate: N/A Restrooms Toilet Paper Dispenser 2010 ADAS 604.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218A N/A Y Coordinate: N/A Restrooms Toilet Paper Dispenser 2010 ADAS 604.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218A N/A Y Coordinate: N/A Restrooms Toilet Paper Dispenser 2010 ADAS 604.7 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218A N/A Y Coordinate: N/A Restrooms Toilet Paper Dispenser 2010 ADAS 604.7 ndard: No Quantity: EACH As-built: 1 Toilet tissue dispenser not within 7" to 9" from front edge of toilet
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 3 of 4 Floor 2 - Women's Restroom 0218A N/A Restrooms Toilet Paper Dispenser 2010 ADAS 604.7 Toilet tissue dispenser not within 7" to 9" from front edge of toilet 15" from rim
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Ploor 2 - Women's Restroom 0218A N/A N/A Y Coordinate: N/A Restrooms Toilet Paper Dispenser 2010 ADAS 604.7 Toilet tissue dispenser not within 7" to 9" from front edge of toilet 15" from rim Reposition or replace toilet paper dispenser 3 Hindrance Cost Est \$225.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 280
Bldg Name:	Dryden Hall Reference Dwg: 3 of 4
Location:	Floor 2 - Women's Restroom 0218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/strobe in sanitary facility
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 29A
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Exit Stairway S0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Sign - Enclosed Exit Stairway Door
Code References:	2010 ADAS 216.4.1
Performance Sta	andard: Yes Quantity: EACH As-built : 1
Barrier Description:	Door leading directly into an exit stairway lacks tactile exit sign
Findings:	Door to exit stair with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT STAIR DOWN (or UP)" at latch side of door
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	
	Priority: 3 Implementation Phase: Implementation Date:



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 29B
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Exit Stairway S0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	12 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 29C
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Exit Stairway S0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	3 second sweep
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 29D
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Exit Stairway S0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Sign - Enclosed Exit Stairway Level
Code References:	ICC A117.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Tactile stairway signage not provided to indicate floor level
Findings:	No sign provided
Rec. Solution:	Provide sign
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 29E
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Exit Stairway S0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 29F
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Exit Stairway S0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail - Opening Limitations
Code References:	Performance Standard
Performance Sta	andard: No Quantity: LF As-built: 13
Barrier Description:	Guard or handrail have openings that allow passage of a 4" sphere
Findings:	4-1/2" openings
Rec. Solution:	Replace handrails
Barrier Severity:	1 Necessary Cost Est \$2,925.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 29G
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Exit Stairway S0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	61" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 29H
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Exit Stairway S0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Card swipe 57" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 29I
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Exit Stairway S0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 30A
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Elevator E0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Hall Call Buttons - 42" High
Code References:	2010 ADAS 407.2.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	The centerline of the hall call buttons not max. 42" above the floor
Findings:	42-1/2" on center
Rec. Solution:	Replace hall call buttons
Barrier Severity:	1 Necessary Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 30B
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Elevator E0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Audible Signals
Code References:	2010 ADAS 407.2.2.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Audible signals or verbal announcement does not sound when the car passes a floor or stops
Findings:	No audible signals provided
Rec. Solution:	Replace car controls
Barrier Severity:	2 Recommended Cost Est \$2,750.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 30C
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Elevator E0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Hall lanterns - Visible at Entry
Code References:	2010 ADAS 407.2.2.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Visual and audible signals not provided at each hoistway entrance to answer calls
Findings:	Hall lanterns not visible from outer side of elevator
Rec. Solution:	Provide hall lanterns visible from outer side of elevator
Barrier Severity:	1 Necessary Cost Est \$3,675.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31A
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Sign - Permanent Room/Space
Code References:	2010 ADAS 703.1
Performance Sta	andard: No Quantity: EACH As-built : 14
Barrier Description:	No sign with raised characters and Braille at permanent room or space with visual sign
Findings:	No tactile info on sign with visual information
Rec. Solution:	Provide sign at latch side of entry door, where possible
Barrier Severity:	
barrier severity.	1 Necessary Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31B
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31C
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Alcove - Existing (pre-1992)
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Fountain with a leading edge between 27" and 80" high protrudes more than 4" into the circulation path.
Findings:	No alcove provided
Rec. Solution:	Provide wing walls as detectable warning (existing unit only)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31D
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Hi-Low Unit
Code References:	2010 ADAS 211.2 & 602.7
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	No hi-low drinking fountain provided on each floor of building
Findings:	No hi fountain provided
Rec. Solution:	Provide min. one hi-low fountain on each floor
Barrier Severity:	1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31E
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Maneuvering Clearance
Code References:	2010 ADAS 602.2
Performance Sta	andard: No Quantity: SF As-built: 1
Barrier Description:	Level wheelchair space of min. 30" x 48" not located at fountain centered at 15"
Findings:	Ice machine blocks drinking fountain clear floor space
Rec. Solution:	Move ice machine to ensure that min. 15" of clearance is provided on each side measured from
Barrier Severity:	2 Recommended Cost Est \$100.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31F
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 3
Barrier Description:	No strobe provided in corridor where horn is provided where fire alarm exists in building
Findings:	No strobe where horn is provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$16,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31G
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 205.1 & 309.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	60" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31H
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Clear Floor Space - Controls
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Recycling bin blocks eye wash clear floor space
Rec. Solution:	Move stored items at control or mechanism
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 311
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Eye Wash - Bubbler Height
Code References:	2010 ADAS 602.4
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Eye wash bubbler height not max. 36"
Findings:	43" high
Rec. Solution:	Reposition eve wash or provide additional eve wash for use in area
Barrier Severity:	1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31J
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Eye Wash - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Wall mounted eye wash protrudes more than 4" from wall with no detectable warning
Findings:	Eyewash bowl protrudes 15" at 42" high
Rec. Solution:	Provide alcove or detectable warning for the visually impaired on both sides of eve wash
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31K
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Laboratory Facilities
Barrier Type:	Emergency Shower - High Reach Range
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at max. 48" high for side reach
Findings:	71" high
Rec. Solution:	Relocate element to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31L
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Extinguisher - Side Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Fire extinguisher forward or side reach exceeds 48"
Findings:	52" high
Rec. Solution:	Relocate fire extinguisher
Barrier Severity:	4 Low Severity Cost Est \$1,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31M
Field Date: Bldg Name:	1/29/2017 Report Date 3/23/2017 Barrier #: 31M Dryden Hall Reference Dwg: 4 of 4
	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Hall H0301
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Hall H0301
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Hall H0301 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Alarms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Hall H0301 N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2 ndard: No Quantity: JOB As-built: 1 Fire extinguisher protrudes into circulation path more than 4" between 27" and 80"
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Hall H0301 N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2 Indard: No Quantity: JOB As-built: 1 Fire extinguisher protrudes into circulation path more than 4" between 27" and 80" Fire extinguisher protrudes 4-1/2" at 36" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Ploor 3 - Hall H0301 N/A Y Coordinate: N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2 Index of the extinguisher protrudes into circulation path more than 4" between 27" and 80" Fire extinguisher protrudes 4-1/2" at 36" high Remount extinguisher with leading edge below 27" or provide detectable warning 4 Low Severity Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31N
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Panel protrudes 6" at 54" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 310
Field Date: Bldg Name:	1/29/2017 Report Date 3/23/2017 Barrier #: 310 Dryden Hall Reference Dwg: 4 of 4
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Hall H0301
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Hall H0301 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Alarms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Alarms Fire Pull - Operation 2010 ADAS 309.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Alarms Fire Pull - Operation 2010 ADAS 309.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Alarms Fire Pull - Operation 2010 ADAS 309.4 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Alarms Fire Pull - Operation 2010 ADAS 309.4 Indard: No Quantity: EACH As-built: 1 Fire pull has no fist operable hardware
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Hall H0301 N/A Alarms Fire Pull - Operation 2010 ADAS 309.4 mdard: No Quantity: EACH As-built: 1 Fire pull has no fist operable hardware Fire pull not fist operable Replace fire pull when remodeling
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Alarms Fire Pull - Operation 2010 ADAS 309.4 Indard: No Quantity: EACH As-built: 1 Fire pull has no fist operable hardware Fire pull not fist operable Replace fire pull when remodeling A Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31P
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull - Height
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built: 0
Barrier Description:	Fire pulls not between 42" and 48" high
Findings:	66" high
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31Q
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Fire blanket 50" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31R
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Fire blanket protrudes 11" at 50" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31S
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Items block clear floor space at spill cleanup kit
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31T
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Spill cleanup kit 63" - 78" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31U
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Spill cleanup kit protrudes 8" at 54" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 31V
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Evacuation Plan
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built : 1
Barrier Description:	No evacuation plan provided
Findings:	Sign not provided
Rec. Solution:	Provide evacuation sign usable by the visually impaired
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 32A
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Unisex Restroom 0314
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Braille - On Door
Code References:	2010 ADAS 703.4.2
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Sign containing Braille/tactile info located on a door
Findings:	Tactile sign on door could present a problem for the visually impaired when reading
Rec. Solution:	Move sign to wall at latch side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Also, Br	aille on tactile sign 1/4" below raised characters and ISA on sign not 4" x 4"



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 32B
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Unisex Restroom 0314
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	15 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 32C
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Unisex Restroom 0314
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Operating controls involve tight grasping, pinching or twisting
Findings:	Hardware not operable with a closed fist
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 32D
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Unisex Restroom 0314
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Clearance - Pull Side
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door lacks min. 18" strike edge clearance at pull side
Findings:	6" strike edge clearance
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 32E
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Unisex Restroom 0314
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Electrical Switches
Code References:	2010 ADAS 205.1 & 309.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
	S Hilliance Cost Est 5750.00 Tacinty Function. Public Status. Open
Implementation	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 32F
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Unisex Restroom 0314
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Maneuvering Clearance
Code References:	2010 ADAS 603.2.1
Performance Sta	andard: No Quantity: SF As-built : 25
Barrier Description:	No 60" turning circle provided in toilet facility (min. 27" high above floor)
Findings:	51" turning space
Rec. Solution:	Remodel to provide accessible turning space
Barrier Severity:	2 Recommended Cost Est \$14,375.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 32G
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Unisex Restroom 0314
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Rim Height
Code References:	2010 ADAS 606.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Lavatory rim or counter edge is higher than 34" AFF
Findings:	34-1/4" high
Rec. Solution:	Provide min. 1 accessible lavatory
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 32H
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Unisex Restroom 0314
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Mirror
Code References:	2010 ADAS 603.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface
Findings:	41" high
Rec. Solution:	Replace or remount mirror
Barrier Severity:	3 Hindrance Cost Est \$375.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 321
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Unisex Restroom 0314
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	Protruding dispenser creates protruding object in path of travel
Findings:	Soap and paper towel dispenser protrudes 5-3/4" - 10" at 38" - 41" high
Rec. Solution:	Relocate dispenser or provide cane-detectable warning
Barrier Severity:	2 Recommended Cost Est \$1,100.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 32J
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Unisex Restroom 0314
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Panel protrudes 6" - 8" at 28" - 61" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$1,100.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: White b	ox next to paper towel dispenser and grey box next to floor to ceiling electrical panel
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 32K
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Unisex Restroom 0314
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/strobe in sanitary facility
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 33A
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Unisex Restroom 0314A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - No Braille/tactile Sign
Code References:	2010 ADAS 703.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No Braille/tactile sign at latch side of door
Findings:	No sign provided
Rec. Solution:	Provide Braille/tactile sign at latch side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 33B
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Unisex Restroom 0314A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - ISA at Accessible Restroom
Code References:	2010 ADAS 216.8
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No ISA symbol on wall sign posted at accessible toilet room
Findings:	No sign ISA provided
Rec. Solution:	Provide ISA symbol on restroom wall sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 33C
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Unisex Restroom 0314A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	49-1/2" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 33D
Field Date: Bldg Name:	1/29/2017 Report Date 3/23/2017 Barrier #: 33D Dryden Hall Reference Dwg: 4 of 4
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Bldg Name: Location:	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Unisex Restroom 0314A
Bldg Name: Location: X Coordinate:	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Unisex Restroom 0314A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Unisex Restroom 0314A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Unisex Restroom 0314A N/A Y Coordinate: N/A Restrooms Urinal - Clear Floor Space 2010 ADAS 605.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Unisex Restroom 0314A N/A Y Coordinate: N/A Restrooms Urinal - Clear Floor Space 2010 ADAS 605.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Unisex Restroom 0314A N/A Y Coordinate: N/A Restrooms Urinal - Clear Floor Space 2010 ADAS 605.3 Indard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Unisex Restroom 0314A N/A Y Coordinate: N/A Restrooms Urinal - Clear Floor Space 2010 ADAS 605.3 Indard: No Quantity: JOB As-built: 1 Urinal lacks min. 30" x 48" clear floor space in front of fixture
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dryden Hall Reference Dwg: 4 of 4 Floor 3 - Unisex Restroom 0314A N/A Y Coordinate: N/A Restrooms Urinal - Clear Floor Space 2010 ADAS 605.3 Indard: No Quantity: JOB As-built: 1 Urinal lacks min. 30" x 48" clear floor space in front of fixture 12-1/2" on center at lower urinal adjacent to stall wall Relocate accessible urinal to provide clear floor space for people using wheelchairs
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Providen Hall Reference Dwg: 4 of 4 Floor 3 - Unisex Restroom 0314A N/A Y Coordinate: N/A Restrooms Urinal - Clear Floor Space 2010 ADAS 605.3 Indard: No Quantity: JOB As-built: 1 Urinal lacks min. 30" x 48" clear floor space in front of fixture 12-1/2" on center at lower urinal adjacent to stall wall Relocate accessible urinal to provide clear floor space for people using wheelchairs 2 Recommended Cost Est \$800.00 Facility Function: Public Status: Open



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 33E
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Unisex Restroom 0314A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lockers - Ratio
Code References:	2010 ADAS 803
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No accessible locker provided in locker room
Findings:	3 lockers and no accessible locker provided
Rec. Solution:	Provide min. 1 accessible locker or 5% overall
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 33F
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4
Location:	Floor 3 - Unisex Restroom 0314A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lockers - Control
Code References:	2010 ADAS 803.5
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Locker mechanism not operable with fist or involves turning and grasping
Findings:	Locker not fist operable
Rec. Solution:	Provide min. 1 accessible locker or 5% overall
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 33G					
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4					
Location:	Floor 3 - Unisex Restroom 0314A					
X Coordinate:	N/A Y Coordinate: N/A					
Barrier Area:	Restrooms					
Barrier Type:	Stall Door Closer					
Code References:	2010 ADAS 604.8.1.2					
Performance Sta	andard: No Quantity: JOB As-built : 1					
Barrier Description:	Stall door not equipped with an automatic closing device					
Findings:	Door does not self-close					
Rec. Solution:	Replace compartment hinge with adjustable mechanism					
Barrier Severity:	2 Recommended Cost Est \$1,650.00 Facility Function: Public Status: Open					
Implementation	Priority: 3 Implementation Phase: Implementation Date:					
Notes:						
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 33H					
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4					
Location:	Floor 3 - Unisex Restroom 0314A					
X Coordinate:	N/A Y Coordinate: N/A					
Barrier Area:	Restrooms					
Barrier Type:	Stall Entry - Front App/push 48"					
Code References:	2010 ADAS Figure 404.2.4.1					
Performance Sta	andard: No Quantity: SF As-built : 40					
Barrier Description:	Stall door at push side min. 12" lacks strike edge clearance					
Findings:	3-1/2" strike edge clearance					
Rec. Solution:	Redesign toilet room to provide maneuvering clearance					
Barrier Severity:	1 Necessary Cost Est \$22,000.00 Facility Function: Public Status: Open					
Implementation	Priority: 3 Implementation Phase: Implementation Date:					
Notes:						



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 33I				
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4				
Location:	Floor 3 - Unisex Restroom 0314A				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Restrooms				
Barrier Type:	Toilet Stall - Door Hardware				
Code References:	2010 ADAS 604.8.1.2				
Performance Sta	ndard: No Quantity: EACH As-built : 1				
Barrier Description:	Outside of compartment door lacks a loop or U-pull below latch				
Findings:	No U-pull provided				
Rec. Solution:	Provide hardware				
Barrier Severity:	: 1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open				
Implementation	Priority: 3 Implementation Phase: Implementation Date:				
Notes:					
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 33J				
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4				
Location:	Floor 3 - Unisex Restroom 0314A				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Restrooms				
Barrier Type:	Toilet Stall - Door Hardware				
Code References:	2010 ADAS 604.8.1.2				
Performance Sta	ndard: No Quantity: EACH As-built : 1				
Barrier Description:	Inside of compartment door lacks a loop or U-pull below latch				
Findings:	No U-pull provided				
Rec. Solution:	Provide hardware				
Barrier Severity:	r Severity: 1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open				
Implementation	Priority: 3 Implementation Phase: Implementation Date:				
Notes:					



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 33K				
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4				
Location:	Floor 3 - Unisex Restroom 0314A				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Restrooms				
Barrier Type:	Toilet Stall - Coat Hook				
Code References:	2010 ADAS 603.4 & 305				
Performance Sta	andard: No Quantity: EACH As-built : 1				
Barrier Description:	Clothing hooks not within 30" x 48" wheelchair space				
Findings:	Pipe blocks coat hook clear floor space				
Rec. Solution:	Relocate hook or provide additional hook				
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open				
Implementation	Priority: 3 Implementation Phase: Implementation Date:				
Notes:					
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 33L				
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4				
Location:	Floor 3 - Unisex Restroom 0314A				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Restrooms				
Barrier Type:	Toilet - Flush Handle				
Code References:	2010 ADAS 604.6				
Performance Sta	andard: No Quantity: JOB As-built : 1				
Barrier Description:	Handle does not point to wide side of stall or compartment				
Findings:	Handle pointing towards small side of stall/room				
Rec. Solution:	Provide min. 1 wheelchair accessible closet				
Barrier Severity:	1 Necessary Cost Est \$850.00 Facility Function: Public Status: Open				
Implementation	Priority: 3 Implementation Phase: Implementation Date:				
Notes:					



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 33M				
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4				
Location:	Floor 3 - Unisex Restroom 0314A				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Restrooms				
Barrier Type:	Toilet Paper Dispenser				
Code References:	2010 ADAS 604.7				
Performance Sta	andard: No Quantity: EACH As-built : 1				
Barrier Description:	Toilet tissue dispenser not within 7" to 9" from front edge of toilet				
Findings:	11" from rim				
Rec. Solution:	Reposition or replace toilet paper dispenser				
Barrier Severity:	3 Hindrance Cost Est \$225.00 Facility Function: Public Status: Open				
Implementation	Priority: 3 Implementation Phase: Implementation Date:				
Notes:					
Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 33N				
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4				
Location:	Floor 3 - Unisex Restroom 0314A				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Restrooms				
Barrier Type:	Seat Cover Dispenser				
Code References:	2010 ADAS 307.2				
Performance Sta	andard: No Quantity: EACH As-built : 1				
Barrier Description:	Seat cover dispenser not located on an accessible route. Blocked by water closet				
Findings:	Access to dispenser blocked by water closet				
Rec. Solution:	Replace or remount dispenser on an accessible route with clear floor space				
Barrier Severity: 2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open					
Implementation	Priority: 3 Implementation Phase: Implementation Date:				
Notes:					



Field Date:	1/29/2017 Report Date 3/23/2017 Barrier #: 330					
Bldg Name:	Dryden Hall Reference Dwg: 4 of 4					
Location:	Floor 3 - Unisex Restroom 0314A					
X Coordinate:	N/A Y Coordinate: N/A					
Barrier Area:	Restrooms					
Barrier Type:	Alarm - Horn/Strobe					
Code References:	2010 ADAS 702.1					
Performance Sta	ndard: No Quantity: EACH As-built : 1					
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided					
Findings:	No device provided					
Rec. Solution:	Provide horn/strobe in sanitary facility					
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open					
Implementation	Priority: 3 Implementation Phase: Implementation Date:					
Notes:						





SUMMARY REPORT

Cost Estimate Total	\$685,305.00		
Cost Estimate - Priority 1:	\$38,550.00	% of Total Cost Estimate:	5.63%
Cost Estimate - Priority 2:	\$323,280.00	% of Total Cost Estimate:	47.17%
Cost Estimate - Priority 3:	\$323,475.00	% of Total Cost Estimate:	47.20%