SZS CONSULTING GROUP

GILMORE HALL

ADA ASSESSMENT & SURVEY



Sacramento Office 770 L Street, Suite 950 Sacramento, CA 95814 Tel: 916.669.8750 Fax: 888.211.7441

Silicon Valley Office 2225 E. Bayshore Road, Suite 200 Palo Alto CA 94303 Tel: 866.694.7637 www.szs-consulting.com

September 16, 2019



GABRIEL MERRELL DIRECTOR, ACCESS AND AFFIRMATIVE ACTION OFFICE OF EQUAL OPPORTUNITY AND ACCESS OREGON STATE UNIVERSITY 330 SNELL HALL Corvallis, or 97331

Re: ADA Accessibility Survey and Assessment – Gilmore Hall

Dear Gabriel,

We are pleased to submit this report for Gilmore Hall. This report is part of our project to provide a Campus Accessibility Survey and Assessment for Oregon State University. It is our hope that this report will assist OSU in improving access to people with disabilities to campus facilities.

SZS has been pleased to be a part of this effort to evaluate campus buildings using federal and state statutes and regulations, as well as universal design principles in order to create performance standards that will guide design, construction and maintenance on campus.

We look forward to discussing our findings with your team.

Regards,

Syroun Z. Sanossian, Principal

Syn Z. Son.

SZS Consulting Group LLC

TABLE OF CONTENTS

1.	EXECUII	VE SUMMARY OF FINDINGS	p. 1
	a.	Pedestrian Facilities and Exterior Spaces Analyzed	p. 2
	b.	Building Entrances	<i>p.</i> 3
2.	INTERIOR	R SPACES	
		Basement and First Floor	p. 3
		Second Floor	p. 4
3.	BARRIE	R DATA RECORDS	
		Exterior Area Barriers	p. 6
		Interior Area Barriers	p. 12
		Cost Estimate	p. 165

1. EXECUTIVE SUMMARY OF FINDINGS

The field investigation for the interior spaces began on June 24, 2019. The exterior site elements were assessed originally as part of the pedestrian facilities assessment in June-September 2011 and are included as an essential part of this report. Images of each physical element identified in this report were captured in HD digital photos while manual measurements were taken to establish as-built conditions to facilitate the process of cost estimating. Digital photographs are provided within the report for each barrier to access, to facilitate the review of the data collected. We have found that technical data can be difficult to interpret without a visual component; the photos provide a clear connection between the technical data and each barrier to access.

Gilmore Hall is a historic structure and many barriers to access were identified in the building. That is quite typical, as barriers to access exist in virtually every building, whether new or existing.

No "perfect" building exists in the real world.

This ADA Assessment and Survey report is intended to not only identify barriers to access, but to provide solutions. The basis for this ADA Assessment and Survey process is the underlying desire on the part of OSU to improve access by relying on higher standards than the minimum requirements in state and federal building codes. SZS intends to provide the information in this report in a clear and easy to understand format. The information in this report is compiled for use by designated OSU staff and other interested persons, so the content is designed to be understood by professionals and laymen alike.

The findings presented are both narrative and technical in nature; barriers to access identified during the field investigation process are documented in two ways;

Narrative Analysis: The analysis of findings is contained in an executive summary in a
narrative form that not only describes each type of barrier identified, but also provides a
discussion that analyses the functionality of physical elements. We also provide the
reasoning and research behind the identification of barriers that conflict with universal
design principles. This analysis may be accompanied by digital photographs or
diagrams, where applicable.

NOTE: Understanding building function and usage is essential when interpreting the findings held in this report. The narrative is intended to facilitate this process.

2. <u>Barrier Data Records:</u> Individual barriers to access are entered into the SZS database so that technical information on the barriers can be provided as barrier data records. These barrier data records include digital photographs of each barrier identified, code references that determine the barrier to access, as-built measurements, barrier severity ratings, budgetary cost estimates, recommended solutions for barrier removal and a priority for barrier removal. The information is formatted with two barriers on each report page.

In order to consolidate the report data, some of the more typical barriers found in multiple locations have been grouped within the barrier data records with a description of the locations in which they were found.

A. Pedestrian Facilities and Exterior Spaces Analyzed

This report provides information on campus pedestrian facilities that serve Gilmore Hall. Many physical elements are part of the comprehensive whole that creates a pedestrian facility. The fundamental elements evaluated as to whether they provide accessible pedestrian facilities include the following:

- Sidewalks
- Walkways
- Ramps
- Curb Ramps
- Blended Transitions
- Signalized Intersections
- Stairways (94% of people with disabilities are not mobility impaired)
- Benches and other Seating Elements
- Picnic Facilities

The descriptions provided for physical elements in this report are intended to clearly describe the differences between each physical element, such as when a pedestrian route is a sidewalk, rather than a walkway. The descriptions are intended to explain how the elements interact to form a cohesive pedestrian facility. Other more specific information described within this section intends to provide guidance on determinations made in this report.

The key to providing accessible pedestrian facilities is in recognizing that different people with disabilities have different needs. Setting policies that speak to the entire group is essential, rather than focusing on one particular subset of the overall group. Universal design principles govern here – physical elements should be usable to everyone that visits campus without having to resort to any adaptation or specialized design.

In summary, an accessible route exists within a building, property boundary or interior space and is separate from the PROW. Pedestrian walkways are similar to sidewalks as paved surfaces improved for use by pedestrians, but walkways are not located along or adjacent to the curb line, gutter or roadway and walkways are generally not considered part of the PROW. The pedestrian facility is the combination of the PROW and the accessible route, which functions as a whole to provide pedestrian access to facility entrances.

As a public building that was constructed prior to the passage of the ADA, Gilmore Hall should have at least one accessible entrance, which was identified at the west entrance. This entrance was provided with a sloped walkway that led to the first-floor main entrance and a corridor. No elevator was provided to carry passengers to reach all floors.

Gilmore Hall has an accessible route provided within the site from accessible parking spaces and accessible passenger loading zones; public streets and sidewalks; and public

transportation stops to the accessible building or facility entrance they serve¹ as compared to the 2010 ADA Standard for Accessible Design. Details on barriers identified in that route are provided within the ADA Assessment and Survey of the pedestrian facilities (provided as a separate report) as well as in the following records. Please see the barrier data records for details.

B. Building Entrances

The building is located along SW Campus Way and SW 26th Street within the campus. Accessible parking is located south of the building in an off-street surface lot. A walkway is provided to the building entrance but was not at least 36" wide due to overgrown foliage. A sloped walkway led to the entrance and was identified with a 9.2% running slope, which is defined as a ramp and needs handrails and level landings at the bottom and top of the ramp. An exit stairway leading to an exterior door located at the south side of the building lacked contrasting color on each tread and accessible handrails. Additionally, the stairway had open risers which may create a tripping problem. ISA directional signage is recommended for these locations to help ensure that pedestrians seeking an accessible entrance are not forced to retrace their steps.

INTERIOR SPACES

BASEMENT AND FIRST FLOOR

Gilmore Hall is a two-story building that was constructed in 1912. In 1938, the building was heavily damaged by fire, although repairs and an expansion were completed in 1939. The building houses the agricultural engineering department and provides classrooms, graduate student labs and offices, conference rooms, and administrative services or department offices. The building has no elevator or other form of vertical access between floors.

The accessible entrance was located at the west side of the building within the off-street parking lot, which is considered the rear entrance. Additional entrances were provided on the east side of the building and the north side of the building where stairways are the only form of vertical access. The accessible entrance led directly to the ground level, whereas the other entrances led to Floor 2. An ISA sign was provided to identify the accessible entrance doors, but the door operating force and hardware were not accessible. The pathway leading to the entrance doors was also identified with a slope that exceeds the slope allowed for a ramp. Doormats were not recessed and could create tripping objects and tactile exit signs were not provided. The lobby was identified with non-accessible fire pulls, mailbox and a fire extinguisher that created a protruding object within the circulation route. No lobby informational signage was provided to indicate where accessible features provided in the building were located.

The central corridor was identified with fire alarm actuators and fire extinguishers that were not accessible, as well as a drinking fountain which was identified as a single high fountain that was not located in an alcove or otherwise provided with protection for people with vision impairments who cannot see the protruding fountains before they make body

_

¹ 2010 ADA Standards for Accessible Design, Section 206.2.1 Site Arrival Points

contact. The high drinking fountain provided was accessible for those with stooping injuries, but an accessible drinking fountain for people who use wheelchairs or who are short was not provided.

Faculty spaces and conference rooms used for student meetings, lacked accessible entry door hardware, operating force where closers are installed, signage and view panels usable by short people or people who use wheelchairs. Conference rooms also lacked assistive listening systems. The clear floor space needed to enable use of whiteboards and the chalkboards was blocked by furniture or stored items in some locations and the spaces generally lacked accessible light switches and outlets, coat racks and strobe devices.

The student lounge was identified with similar barriers to access including furniture on the pull side of the door that blocked door maneuvering clearance.

The multi-accommodation men's and women's restroom was identified multiple barriers to access including a lack of space to approach the tactile sign needed to allow reading by touch, and the door closers needed more force than is considered accessible. The men's restroom lacked sufficient door maneuvering clearance and accessible urinals. Both restrooms were identified with non-accessible lavatories, dispensers and water closets lacked sufficient transfer space for people who use a mobility device.

No vertical access was provided in this building. The stairway connecting floor 1 with floor 2 lacked accessible handrails, although contrasting colors were provided at the top and bottom tread of each of the stairways.

Many *staff use only* areas were identified in the building. These spaces include IT rooms, janitorial rooms, private faculty offices and associated spaces. Signage at the door/doorway to these spaces was included in this report as it is located along the public circulation route of travel, but these interior spaces were not investigated as part of this assessment process. In general, institutions and organizations make staff-use-only areas accessible as needed through the reasonable accommodation iterative process between the employer and employee.

SECOND FLOOR

Barriers in common use areas on this floor were similar to those identified on the first floor, including a lack of tactile room informational signs, tactile exit signs, accessible fire pulls and fire cabinets, and accessible drinking fountains. The second floor provided many public spaces including graduate student offices, one classroom, and one break room.

A breakroom located on the second floor was identified with an entry door with similar barriers to access as those identified on the first floor and the table in the center of the breakroom had a pedestal base that would prevent use by a person using a wheelchair where the base blocks accessible knee and toe clearance. The sink was identified with a surface height greater than 34" high and was located within a cabinet with no knee clearance. The sink and dispensers were not identified as accessible.

One classroom was provided on the second floor. Tactile signage was provided at the entrance door, but the sign was not mounted in an accessible position. All desks provided in the classroom were identified as accessible, although the classroom was not arranged with an unobstructed 36" wide clear path. Graduate student offices on this floor were not

identified with tactile signs, accessible door hardware and view panels or accessible electrical outlets. In some cases, the furniture in the room blocked maneuvering space for people who use mobility devices.

Men's and women's restrooms on this floor could not be considered accessible, as they lacked accessible signage, entrances, lavatories, dispensers, mirrors, urinals and toilet stalls. The drinking fountain identified on this floor had been removed at some point before the field investigation.

The following barrier data records provide more detailed information on the barriers described above.





Field Date:	7/14/2011 Report Date 7/14/2011 Barrier #: 2253
Bldg Name:	Gilmore Hall Reference Dwg: 1 of 3
Location:	Exterior - Gilmore Annex
X Coordinate:	7477551.722 Y Coordinate: 340556.972
Barrier Area:	Walkways
Barrier Type:	Clear Width - ADA Existing (less than 30")
Code References:	OSSC 1109.4.2 and 2010 ADAS 403.5.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Pedestrian route is not min. 36" wide (less than 30")
Findings:	24" clear width due to foliage growth
Rec. Solution:	Trim foliage to provide min. 36" clear width
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/14/2011 Report Date 7/14/2011 Barrier #: 2256
Bldg Name:	Gilmore Hall Reference Dwg: 1 of 3
Location:	Exterior - Gilmore Hall
X Coordinate:	7477625.33 Y Coordinate: 340532.035
Barrier Area:	Walkways
Barrier Type:	Running Slope - Existing (8.3% or more)
Code References:	OSSC 1103.2.4.3 and 2010 ADAS 403.3
Performance Sta	andard: No Quantity: LF As-built: 10
Barrier Description:	Walkway running slope exceeds 5.0% (8.3% or more)
Findings:	9.2% running slope
Findings: Rec. Solution:	9.2% running slope Demolish and reconstruct walkway to make accessible
_	Demolish and reconstruct walkway to make accessible
Rec. Solution:	Demolish and reconstruct walkway to make accessible 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	7/14/2011 Report Date 7/14/2011 Barrier #: 2257
Bldg Name:	Gilmore Hall Reference Dwg: 1 of 3
Location:	Exterior - Gilmore Hall
X Coordinate:	7477627.073 Y Coordinate: 340528.743
Barrier Area:	Doors or Gates
Barrier Type:	Abrupt Change in Level - Step at Landing
Code References:	OSSC 1109.9.3 and 2010 ADAS 303.3
Performance Sta	andard: No Quantity: SF As-built: 30
Barrier Description:	Change in level greater than 1/2" leading to door
Findings:	5" step
Rec. Solution:	Construct ramp to provide access to door landing
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/14/2011 Report Date 7/14/2011 Barrier #: 2258
Bldg Name:	Gilmore Hall Reference Dwg: 1 of 3
Location:	Exterior - Gilmore Hall
X Coordinate:	7477669.674 Y Coordinate: 340493.542
Barrier Area:	Walkways
Barrier Type:	Cross Slope - Existing (5.0% or more)
Code References:	OSSC 1103.2.4.3 and 2010 ADAS 403.3
Performance Sta	andard: No Quantity: LF As-built : 22
Barrier Description:	Cross slope exceeds 2.0% (5.0% or more)
Findings:	5.6% cross slope
Rec. Solution:	Demolish existing and construct new route
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	7/14/2011 Report Date 7/14/2011 Barrier #: 2260A
Bldg Name:	Gilmore Hall Reference Dwg: 1 of 3
Location:	Exterior - SW 26th St - Corner A
X Coordinate:	7477734.722 Y Coordinate: 340492.732
Barrier Area:	Curb Ramps
Barrier Type:	Running Slope - Existing (9.5% or more)
Code References:	OSSC 1103.2.2.1 and 2010 ADAS 406.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Ramp running slope exceeds 8.3% (9.5% or more)
Findings:	14.9% running slope
Rec. Solution:	Demolish existing and construct new curb ramp
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes: Two - w	ay intersection corners A,B
Field Date:	7/14/2011 Report Date 7/14/2011 Barrier #: 2260B
Bldg Name:	Gilmore Hall Reference Dwg: 1 of 3
Location:	Exterior - SW 26th St - Corner A
X Coordinate:	7477734.722 Y Coordinate: 340492.732
Barrier Area:	Curb Ramps
Barrier Type:	Detectable Warnings - Truncated Domes
Code References:	OSSC 1103.2.3.1 and 2010 ADAS 705.1.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No truncated domes provided at curb ramp
Findings:	No detectable warnings at curb ramp
Rec. Solution:	To make accessible provide truncated domes as detectable warning
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes: Two - w	ay intersection corners A,B




Field Date:	7/14/2011 Report Date 7/14/2011 Barrier #: 2262
Bldg Name:	Gilmore Hall Reference Dwg: 1 of 3
Location:	Exterior - Gilmore Hall
X Coordinate:	7477561.765 Y Coordinate: 340469.786
Barrier Area:	Doors or Gates
Barrier Type:	Door/Gate Landing - Existing (≥ 5.0%)
Code References:	2010 ADAS 404.2.4.4
Performance Sta	andard: No Quantity: SF As-built : 25
Barrier Description:	Door or gate lacks landing on both sides of door
Findings:	11.1%
Rec. Solution:	Demolish and reconstruct level landing
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/14/2011 Report Date 7/14/2011 Barrier #: 2263A
Bldg Name:	Gilmore Hall Reference Dwg: 1 of 3
Location:	Exterior - Gilmore Hall
X Coordinate:	7477532.667 Y Coordinate: 340498.604
Barrier Area:	Stairways
Barrier Type:	Open Riser - Existing
Code References:	OSSC 1109.8.2 and 2010 ADAS 504.3
Performance Sta	andard: No Quantity: SF As-built : 92
Barrier Description:	Existing open risers present a tripping object
Findings:	Stair has open risers
Rec. Solution:	Demolish and construct new to make accessible stairway
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	7/14/2011 Report Date 7/14/2011 Barrier #: 2263B
Bldg Name:	Gilmore Hall Reference Dwg: 1 of 3
Location:	Exterior - Gilmore Hall
X Coordinate:	7477532.667 Y Coordinate: 340498.604
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Bottom
Code References:	OSSC 1109.8.6.(2)
Performance Sta	ndard: No Quantity: LF As-built : 2
Barrier Description:	Bottom handrail extension not level for min. 12"
Findings:	Bottom handrail extension not level for min. 12"
Rec. Solution:	Provide accessible handrails at both sides of stairway
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	11/16/2011 Report Date ######## Barrier #: 2264
Bldg Name:	Gilmore Hall Reference Dwg: 1 of 3
Location:	Exterior - Gilmore Hall
X Coordinate:	7477528.113 Y Coordinate: 340477.686
Barrier Area:	Curb Ramps
Barrier Type:	Running Slope - New Construction
Code References:	OSSC 1103.2.2.1 and 2010 ADAS 406.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Ramp running slope exceeds 8.3%
Findings:	14.9% running slope
Rec. Solution:	Demolish existing and construct new curb ramp
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	11/16/2011 Report Date ######## Barrier #: 2265
Bldg Name:	Gilmore Hall Reference Dwg: 1 of 3
Location:	Exterior - Gilmore Hall
X Coordinate:	7477531.385 Y Coordinate: 340481.594
Barrier Area:	Walkways
Barrier Type:	Running Slope - New Construction
Code References:	OSSC 1103.2.4.3 and 2010 ADAS 403.3
Performance Sta	ndard: No Quantity: LF As-built : 8
Barrier Description:	Walkway running slope exceeds 5.0%
Findings:	5.7% running slope
Rec. Solution:	Provide accessible handrails at both sides with landings where needed
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	Report Date Barrier #:
Bldg Name:	Gilmore Hall Reference Dwg:
Location:	
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
Barrier Type:	
Code References:	
Performance Sta	ndard: Quantity: As-built :
Barrier Description:	
Findings:	
Rec. Solution:	
Barrier Severity:	Cost Est Facility Function: Public Status: Open
Implementation	Priority: Implementation Phase: Implementation Date:
Notes: Barrier r	ecord intentionally left blank to facilitate printing





Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 1A
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule V102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at entrance door and mechanical room adjacent to entrance door
Rec. Solution:	Provide accessible signs
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 1B
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule V102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Exterior Adjustment
Code References:	Performance Standard
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 8.5 lbf
Findings:	7 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	· _ · <u> </u>
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 1C
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule V102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Exterior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	3 second sweep
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 1D
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule V102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible where thumb activation and simultaneous pulling is needed
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	implementation rhase.



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 1E
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule V102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Door Hardware
Code References:	2010 ADAS 404.2.10
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door hardware interrupts min. 10" smooth bottom surface
Findings:	Door hardware extends into bottom 10" of door
Rec. Solution:	Remove element at bottom of door at push side
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 1F
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule V102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Doormat
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance Sta	ndard: No Quantity: EACH As-built : 3
Barrier Description:	Doormat not anchored to floor (possible tripping object)
Findings:	Door mat not secured
Rec. Solution:	Secure exiting doormat or replace
Barrier Severity:	
	1 Necessary Cost Est \$1,500.00 Facility Function: Public Status: Open
Implementation	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 1G
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule V102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Door
Code References:	2010 ADAS 216.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Ground floor doors that exit to exterior lacks tactile exit sign
Findings:	Exit door with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT" at exit side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 2A
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Lobby L101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 2B
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Lobby L101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	10 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 2C
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Lobby L101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built: 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	1 second sweep
Rec. Solution:	Replace or adjust existing closer
Rec. Solution: Barrier Severity:	
	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 2D
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Lobby L101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Door Stop
Code References:	2010 ADAS 404.2.10
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	Door stop interrupts min.10" smooth bottom surface
Findings:	Door stop at bottom of door can create trapping condition
Rec. Solution:	Remove door stop or other element at bottom of door at push side
Barrier Severity:	1 Necessary Cost Est \$150.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 2E
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Lobby L101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - To Exit Door
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built : 1
Barrier Description:	Exit door leading directly to an exit to the exterior lacks tactile exit sign
Findings:	Door leading to exit door to exterior lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT ROUTE" at exit side of door
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 2F
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Lobby L101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Fire Alarm - Pull Actuator Operation
Code References:	2010 ADAS 309.4
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Fire pull has no usable hardware
Findings:	Hardware not accessible
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 2G
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Lobby L101
	PHOOL 1 - FORDA FIOL
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	
	N/A Y Coordinate: N/A
Barrier Area:	N/A Y Coordinate: N/A Corridors
Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Corridors Fire Alarm - Pull Actuator Height 2010 ADAS 308.2.2
Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Corridors Fire Alarm - Pull Actuator Height 2010 ADAS 308.2.2
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Y Coordinate: N/A Corridors Fire Alarm - Pull Actuator Height 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 0
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Y Coordinate: N/A Corridors Fire Alarm - Pull Actuator Height 2010 ADAS 308.2.2 andard: No Quantity: EACH As-built: 0 Fire pulls not between 42" and 48" high
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Corridors Fire Alarm - Pull Actuator Height 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 0 Fire pulls not between 42" and 48" high 60-1/2" high Replace fire pull when remodeling
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Corridors Fire Alarm - Pull Actuator Height 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 0 Fire pulls not between 42" and 48" high Replace fire pull when remodeling 4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 2H
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Lobby L101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Lobby Info Sign
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built : 1
Barrier Description:	No lobby informational sign with location of accessible elements
Findings:	Accessible sign not provided
Rec. Solution:	Provide lobby informational sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 21
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Lobby L101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route at room 118
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 2J
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Lobby L101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Extinguisher - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Fire extinguisher protrudes into circulation path more than 4" between 27" and 80"
Findings:	Fire extinguisher protrudes 5-1/2" at 28-3/4" high
Rec. Solution:	Remount extinguisher with leading edge below 27" or provide detectable warning
Barrier Severity:	4 Low Severity Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 2K
Field Date: Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 2K Gilmore Hall Reference Dwg: 2 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Lobby L101
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Lobby L101 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Lobby L101 N/A Y Coordinate: N/A Clear Floor Space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Lobby L101 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" 2010 ADAS 403.5.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Lobby L101 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" 2010 ADAS 403.5.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Lobby L101 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" 2010 ADAS 403.5.1 ndard: No Quantity: LF As-built: 6
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Lobby L101 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" 2010 ADAS 403.5.1 ndard: No Quantity: LF As-built: 6 Circulation route not min. 36" wide between elements
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Lobby L101 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" 2010 ADAS 403.5.1 ndard: No Quantity: LF As-built: 6 Circulation route not min. 36" wide between elements 35-1/2" passageway due to installation of black wall guard Alter area to provide min. 36" clear width for 2 feet or min. 32" point-to-point
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Lobby L101 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" 2010 ADAS 403.5.1 ndard: No Quantity: LF As-built: 6 Circulation route not min. 36" wide between elements 35-1/2" passageway due to installation of black wall guard Alter area to provide min. 36" clear width for 2 feet or min. 32" point-to-point 1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: Barrier Severity:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Lobby L101 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" 2010 ADAS 403.5.1 ndard: No Quantity: LF As-built: 6 Circulation route not min. 36" wide between elements 35-1/2" passageway due to installation of black wall guard Alter area to provide min. 36" clear width for 2 feet or min. 32" point-to-point 1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 2L
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Lobby L101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Hi/low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Use of control involves low reach of less than 15" above floor or more than 48" high
Findings:	49" high mail box slots
Rec. Solution:	Relocate to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 3A
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Staff Room 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 3B
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Staff Room 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	13 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 3C
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Staff Room 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
	Doors or Gates
Barrier Type:	Doors or Gates Door Closer - Interior Sweep Period
Barrier Type: Code	Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Barrier Type: Code References:	Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Barrier Type: Code References: Performance Sta Barrier	Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 andard: No Quantity: EACH As-built: 0
Barrier Type: Code References: Performance Sta Barrier Description:	Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame 2 second sweep Replace or adjust existing closer
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame 2 second sweep Replace or adjust existing closer 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 3D
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Staff Room 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 3E
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Staff Room 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	
remoninance sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Barrier	
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Barrier Description: Findings:	View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel 47" high Replace door/gate or vision panel
Barrier Description: Findings: Rec. Solution:	View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel 47" high Replace door/gate or vision panel 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 3F
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Staff Room 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Passage
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Exit thru an exit enclosure/exit passageway lacks tactile exit sign
Findings:	Passageway to exterior exit with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT ROUTE" at exit side of door
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 3G
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Staff Room 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Chairs block electrical switch clear floor space
Rec. Solution:	Rearrange chairs to provide access
Barrier Severity:	1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 3H
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Staff Room 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - Wheelchair Use
Code References:	2010 ADAS 305
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	No space in waiting provided for people who use mobility device
Rec. Solution:	Rearrange furniture to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 3I
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Staff Room 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Surface Height
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No section at least 3 feet long between 28" and 34" provided at existing counter
Findings:	41-1/4" high
Rec. Solution:	Provide min. 3 ft long section of counter at max. 34" high
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 3J
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Staff Room 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 4
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route at rooms 116A, 116D, 116C, and office of Rachel Jones
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$1,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 3K
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Staff Room 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - Wheelchair Use
Code References:	2010 ADAS 305
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Clear floor space not provided at water dispenser
Rec. Solution:	Rearrange furniture to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 3L
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Staff Room 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 4A
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Conference Room 116B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 4B
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Conference Room 116B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 4C
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Conference Room 116B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
	Assembly Areas
Barrier Type:	
Barrier Type: Code References:	Assembly Areas
Code	Assembly Areas Shared Assistive Listening System Performance Standard
Code References:	Assembly Areas Shared Assistive Listening System Performance Standard
Code References: Performance Sta Barrier	Assembly Areas Shared Assistive Listening System Performance Standard Indard: Yes Quantity: EACH As-built: 1
Code References: Performance Sta Barrier Description:	Assembly Areas Shared Assistive Listening System Performance Standard Indard: Yes Quantity: EACH As-built: 1 No shared assistive listening system for room with min. 10 seats
Code References: Performance Sta Barrier Description: Findings:	Assembly Areas Shared Assistive Listening System Performance Standard Indard: Yes Quantity: EACH As-built: 1 No shared assistive listening system for room with min. 10 seats No system provided Provide shared ALS system with signage
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Assembly Areas Shared Assistive Listening System Performance Standard Indard: Yes Quantity: EACH As-built: 1 No shared assistive listening system for room with min. 10 seats No system provided Provide shared ALS system with signage 2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 4D	
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3	
Location:	Floor 1 - Conference Room 116B	
X Coordinate:	N/A Y Coordinate: N/A	
Barrier Area:	Classrooms	
Barrier Type:	Clear Floor Space	
Code References:	2010 ADAS 305.3	
Performance Sta	ndard: No Quantity: JOB As-built : 1	
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism	
Findings:	Stored items block white board clear floor space	
Rec. Solution:	Remove stored items	
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open	
Implementation Priority: 3 Implementation Phase: Implementation Date:		
Notes:		
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 4E	
Field Date: Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 4E Gilmore Hall Reference Dwg: 2 of 3	
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3	
Bldg Name: Location:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Conference Room 116B	
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Conference Room 116B N/A Y Coordinate: N/A	
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Conference Room 116B N/A Y Coordinate: N/A Classrooms	
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Conference Room 116B N/A Y Coordinate: N/A Classrooms Electrical Outlets - Hi/Low Reach 2010 ADAS 205.1 & 309.3	
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Conference Room 116B N/A Y Coordinate: N/A Classrooms Electrical Outlets - Hi/Low Reach 2010 ADAS 205.1 & 309.3	
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Conference Room 116B N/A Y Coordinate: N/A Classrooms Electrical Outlets - Hi/Low Reach 2010 ADAS 205.1 & 309.3 Indard: No Quantity: EACH As-built: 1	
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Conference Room 116B N/A Y Coordinate: N/A Classrooms Electrical Outlets - Hi/Low Reach 2010 ADAS 205.1 & 309.3 Indard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high	
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Conference Room 116B N/A Y Coordinate: N/A Classrooms Electrical Outlets - Hi/Low Reach 2010 ADAS 205.1 & 309.3 Indard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 12" high Relocate outlet to area at min. 15" or max. 48" high	
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Conference Room 116B N/A Y Coordinate: N/A Classrooms Electrical Outlets - Hi/Low Reach 2010 ADAS 205.1 & 309.3 Indard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 12" high Relocate outlet to area at min. 15" or max. 48" high 2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 4F
	0/24/2015 Report Bate 5/15/2015 Barrier III. 41
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Conference Room 116B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24-7/8" high knee clearance
Rec. Solution:	Provide min. 1 accessible table. Avoid pedestal base tables.
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Notes: Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 4G
	6/24/2019 Report Date 9/13/2019 Barrier #: 4G Gilmore Hall Reference Dwg: 2 of 3
Field Date:	
Field Date: Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Field Date: Bldg Name: Location:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Conference Room 116B
Field Date: Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Conference Room 116B N/A Y Coordinate: N/A
Field Date: Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Conference Room 116B N/A Y Coordinate: N/A Classrooms
Field Date: Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Conference Room 116B N/A Y Coordinate: N/A Classrooms Protruding Object - Wall-mounted 2010 ADAS 307.2
Field Date: Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Conference Room 116B N/A Y Coordinate: N/A Classrooms Protruding Object - Wall-mounted 2010 ADAS 307.2
Field Date: Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Conference Room 116B N/A Y Coordinate: N/A Classrooms Protruding Object - Wall-mounted 2010 ADAS 307.2 andard: No Quantity: EACH As-built: 1
Field Date: Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance State Barrier	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Conference Room 116B N/A Y Coordinate: N/A Classrooms Protruding Object - Wall-mounted 2010 ADAS 307.2 andard: No Quantity: EACH As-built: 1 Wall mounted object protrudes more than 4" from wall
Field Date: Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Conference Room 116B N/A Y Coordinate: N/A Classrooms Protruding Object - Wall-mounted 2010 ADAS 307.2 andard: No Quantity: EACH As-built: 1 Wall mounted object protrudes more than 4" from wall Cabinet protrudes 12-1/2" at 52-1/2" high Remove protruding object or provide detectable warning for the visually impaired
Field Date: Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance State Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Conference Room 116B N/A Y Coordinate: N/A Classrooms Protruding Object - Wall-mounted 2010 ADAS 307.2 andard: No Quantity: EACH As-built: 1 Wall mounted object protrudes more than 4" from wall Cabinet protrudes 12-1/2" at 52-1/2" high Remove protruding object or provide detectable warning for the visually impaired I Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 4H	
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3	
Location:	Floor 1 - Conference Room 116B	
X Coordinate:	N/A Y Coordinate: N/A	
Barrier Area:	Classrooms	
Barrier Type:	Shelves or Cabinets	
Code References:	2010 ADAS 603.4	
Performance Sta	andard: No Quantity: EACH As-built : 1	
Barrier Description:	Shelf or cabinet not mounted between 40" and 48" above floor or ground	
Findings:	Shelf and cabinet not accessible	
Rec. Solution:	Provide additional shelf at accessible height or provide assistance	
Barrier Severity:	2 Recommended Cost Est \$75.00 Facility Function: Public Status: Open	
Implementation	Priority: 3 Implementation Phase: Implementation Date:	
Notes:		
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 4	
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3	
Location:	Floor 1 - Conference Room 116B	
X Coordinate:	N/A Y Coordinate: N/A	
Barrier Area:	Classrooms	
Barrier Type:	Alarm - No Horn/Strobe	
Code References:	2010 ADAS 702.1	
Performance Sta	andard: No Quantity: EACH As-built: 1	
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided	
Findings:	No device provided	
Rec. Solution:	Provide horn/strobe	
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open	
Implementation Priority: 3 Implementation Phase: Implementation Date:		
Notes:		



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 5A
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 3
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route at rooms 122, 121, and 108
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 5B
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Fire Alarm - Pull Actuator Operation
Code References:	2010 ADAS 309.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Fire pull has no usable hardware
Findings:	Hardware not accessible
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 5C
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Fire Alarm - Pull Actuator Height
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Fire pulls not between 42" and 48" high
Findings:	63-1/2" high
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 5D
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No strobe provided in corridor where horn is provided where fire alarm exists in building
Findings:	No strobe where horn is provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 5E
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Flyer holder protrudes 4-1/2" at 36" high
Rec. Solution:	Remove protruding object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 5F
Field Date: Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 5F Gilmore Hall Reference Dwg: 2 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H101
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H101 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H101 N/A Y Coordinate: N/A Drinking Fountains
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H101 N/A Y Coordinate: N/A Drinking Fountains Hi-Low Unit 2010 ADAS 211.2 & 602.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H101 N/A Y Coordinate: N/A Drinking Fountains Hi-Low Unit 2010 ADAS 211.2 & 602.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H101 N/A Y Coordinate: N/A Drinking Fountains Hi-Low Unit 2010 ADAS 211.2 & 602.7 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H101 N/A Y Coordinate: N/A Drinking Fountains Hi-Low Unit 2010 ADAS 211.2 & 602.7 Indard: No Quantity: EACH As-built: 1 No hi-low drinking fountain provided on each floor of building
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H101 N/A Y Coordinate: N/A Drinking Fountains Hi-Low Unit 2010 ADAS 211.2 & 602.7 Indard: No Quantity: EACH As-built: 1 No hi-low drinking fountain provided on each floor of building One fountain is provided and meets criteria for hi fountain Provide additional accessible low fountain
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H101 N/A Y Coordinate: N/A Drinking Fountains Hi-Low Unit 2010 ADAS 211.2 & 602.7 Indard: No Quantity: EACH As-built: 1 No hi-low drinking fountain provided on each floor of building One fountain is provided and meets criteria for hi fountain Provide additional accessible low fountain 1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 5G
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Bubbler height
Code References:	2010 ADAS 602.4
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Bubbler height exceeds 36"
Findings:	43" bubbler height
Rec. Solution:	Provide additional accessible low fountain
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 5H
Field Date: Bldg Name:	Gilmore Hall Report Date 9/13/2019 Barrier #: 5H Gilmore Hall Reference Dwg: 2 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H101
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H101 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H101 N/A Y Coordinate: N/A Drinking Fountains
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H101 N/A Y Coordinate: N/A Drinking Fountains Knee Clearance 2010 ADAS 306.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H101 N/A Y Coordinate: N/A Drinking Fountains Knee Clearance 2010 ADAS 306.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H101 N/A Y Coordinate: N/A Drinking Fountains Knee Clearance 2010 ADAS 306.3 andard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H101 N/A V Coordinate: N/A Drinking Fountains Knee Clearance 2010 ADAS 306.3 andard: No Quantity: EACH As-built: 0 Knee clearance under fountain not min. 27" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H101 N/A Y Coordinate: N/A Drinking Fountains Knee Clearance 2010 ADAS 306.3 Andard: No Quantity: EACH As-built: 0 Knee clearance under fountain not min. 27" high 20-3/4" high knee clearance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H101 N/A Y Coordinate: N/A Drinking Fountains Knee Clearance 2010 ADAS 306.3 Indard: No Quantity: EACH As-built: 0 Knee clearance under fountain not min. 27" high 20-3/4" high knee clearance Provide additional accessible low fountain 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 6A
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route at rooms 107 and 104
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 6B
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Surface Height
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No section at least 3 feet long between 28" and 34" provided at existing counter
Findings:	38" high
Rec. Solution:	Provide min. 3 ft long section of counter at max. 34" high
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 7A
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule Entrance V101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - To Exit Door
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Exit door leading directly to an exit to the exterior lacks tactile exit sign
Findings:	Door leading to exit door to exterior lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT ROUTE" at exit side of door
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: This ent of door	rance is identified as the non-accessible entrance. ISA directional sign provided on exterior side
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 7B
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule Entrance V101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Eindings	12 lbf
Findings:	
Rec. Solution:	Replace or adjust existing closer
_	Replace or adjust existing closer
Rec. Solution:	Replace or adjust existing closer 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 7C
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule Entrance V101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	3 second sweep
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 7D
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Bldg Name: Location:	
	Gilmore Hall Reference Dwg: 2 of 3
Location:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Vestibule Entrance V101
Location: X Coordinate:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Vestibule Entrance V101 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Vestibule Entrance V101 N/A Y Coordinate: N/A Doors or Gates
Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Vestibule Entrance V101 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Door Stop 2010 ADAS 404.2.10
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Vestibule Entrance V101 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Door Stop 2010 ADAS 404.2.10
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Vestibule Entrance V101 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Door Stop 2010 ADAS 404.2.10 Indard: No Quantity: EACH As-built: 2
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Vestibule Entrance V101 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Door Stop 2010 ADAS 404.2.10 Indard: No Quantity: EACH As-built: 2 Door stop interrupts min.10" smooth bottom surface
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Vestibule Entrance V101 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Door Stop 2010 ADAS 404.2.10 Indard: No Quantity: EACH As-built: 2 Door stop interrupts min.10" smooth bottom surface Door stop at bottom of door can create trapping condition Remove door stop or other element at bottom of door at push side
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Vestibule Entrance V101 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Door Stop 2010 ADAS 404.2.10 Indard: No Quantity: EACH As-built: 2 Door stop interrupts min.10" smooth bottom surface Door stop at bottom of door can create trapping condition Remove door stop or other element at bottom of door at push side 1 Necessary Cost Est \$150.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 7E
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule Entrance V101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Abrupt Change in Level
Code References:	2010 ADAS 303.3
Performance Sta	andard: No Quantity: LF As-built : 1
Barrier Description:	Change in level greater than 1/2" leading to door
Findings:	3/8" lip
Rec. Solution:	Repair to remove tripping object
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 7F
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule Entrance V101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 7G
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule Entrance V101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Side Reach Obstructed (≤10")
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge over an obstruction max. 34" high located above 48"
Findings:	49-1/4" high
Rec. Solution:	Relocate control or mechanism to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 7H
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule Entrance V101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	
Code	Actuator/Control - Side Reach High Unobstructed
References:	2010 ADAS 305.3
	2010 ADAS 305.3
References:	2010 ADAS 305.3
References: Performance Sta Barrier	2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1
References: Performance Sta Barrier Description: Findings:	2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Control or mechanism not at min. 15" or max. 48" high
References: Performance Sta Barrier Description: Findings:	2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Control or mechanism not at min. 15" or max. 48" high 49-1/4" high hand sanitizer dispenser
References: Performance Sta Barrier Description: Findings: Rec. Solution:	ndard: No Quantity: EACH As-built: 1 Control or mechanism not at min. 15" or max. 48" high 49-1/4" high hand sanitizer dispenser Relocate control or mechanism to min. 15" or max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 7I
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule Entrance V101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Door
Code References:	2010 ADAS 216.4.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Ground floor doors that exit to exterior lacks tactile exit sign
Findings:	Exit door with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT" at exit side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 7J
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule Entrance V101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Exterior Adjustment
Code References:	Performance Standard
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 8.5 lbf
Findings:	12 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Pate:
Notes:	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 7K
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule Entrance V101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Exterior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	3 second sweep
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 7L
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule Entrance V101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware needed thumb activation and simultaneous pulling to use
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 7M
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule Entrance V101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Door Hardware
Code References:	2010 ADAS 404.2.10
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door hardware interrupts min. 10" smooth bottom surface
Findings:	Door hardware extends into bottom 10" of door
Rec. Solution:	Remove element at bottom of door at push side
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 7N
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule Entrance V101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Doormat
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	Doormat not anchored to floor (possible tripping object)
Findings:	Door mat not secured
Rec. Solution:	Secure exiting doormat or replace
Barrier Severity:	1 Necessary Cost Est \$1,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 70
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule Entrance V101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: This ent	rance is identified as the non-accessible entrance. ISA directional sign provided on door
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 8
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Vestibule V100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Corridor
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in corridor
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 9A
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Student Lounge 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 9B
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Student Lounge 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	7 lbf
Findings: Rec. Solution:	7 lbf Replace or adjust existing closer
J	Replace or adjust existing closer
Rec. Solution:	Replace or adjust existing closer 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 9C
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Student Lounge 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	1 second sweep
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	C/24/2040 Papert Data 10/42/2040 Parrier #4 10D
i icia Date.	6/24/2019 Report Date 9/13/2019 Barrier #: 9D
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Student Lounge 100
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Student Lounge 100 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Student Lounge 100 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Student Lounge 100 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Student Lounge 100 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Student Lounge 100 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 andard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Student Lounge 100 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 Indard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Student Lounge 100 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 Indard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel 53-1/4" high Replace door/gate or vision panel
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Student Lounge 100 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 Indard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel 53-1/4" high Replace door/gate or vision panel 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 9E
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Student Lounge 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 9F
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Student Lounge 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	Shelf reduces strike edge clearance to 7-1/2" and desk reduces perpendicular clearance to 34" deep
Rec. Solution:	Rearrange furniture to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 9G
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Student Lounge 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Shelf blocks electrical switch clear floor space
Rec. Solution:	Rearrange furniture to provide access
Barrier Severity:	1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 9H
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Student Lounge 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	54-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	· _ · <u> </u>
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 91
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Student Lounge 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Surface Height
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No section at least 3 feet long between 28" and 34" provided at existing counter
Findings:	37-7/8" high
Rec. Solution:	Provide min. 3 ft long section of counter at max. 34" high
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 9J
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Student Lounge 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Counter or table in route of travel protrudes more than 4" above 27" high
Findings:	Counter protrudes 6-1/4" at 37-1/8" high
Rec. Solution:	Provide cane-detectable warning that reaches below 27" high for the visually impaired
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 9K
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Student Lounge 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Side Reach Obstructed (10")
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism over an obstruction max. 34" high located above 48"
Findings:	63" high phone operating point over and obstruction 29" deep and 28-3/4" high
Rec. Solution:	Relocate control or mechanism to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 9L
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Student Lounge 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Protruding Object
Code References:	2010 ADAS 902.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Table creates protruding object in accessible route
Findings:	Table edge protrudes 15" at 28-1/2" high
Rec. Solution:	Remove table or provide detectable warning for the visually impaired
Barrier Severity:	2 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 9M
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Student Lounge 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: SF As-built: 0
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Table block outlet clear floor space
Rec. Solution:	Rearrange table to provide access
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 9N
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Student Lounge 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	14" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 90
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Student Lounge 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Shelves or Cabinets
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Shelf or cabinet not mounted max. 48" above floor or ground
Findings:	Shelf not accessible
Rec. Solution:	Provide additional shelf at accessible height or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 9P
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Student Lounge 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Stored items block white board clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 9Q
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Student Lounge 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	68" high marker operating point
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 9R
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Student Lounge 100
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10A
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Men's Restroom 100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Braille - On Door
Code References:	2010 ADAS 703.4.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Sign containing Braille/tactile info located on a door
Findings:	Tactile sign on door could present a issue for the visually impaired when reading
Rec. Solution:	Move sign to wall at latch side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10B
Field Date: Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 10B Gilmore Hall Reference Dwg: 2 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 12 lbf Provide automatic door opening device to compensate for lack of maneuvering clearance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 12 lbf Provide automatic door opening device to compensate for lack of maneuvering clearance 1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10C
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Men's Restroom 100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	3 second sweep
Rec. Solution:	Provide automatic door opening device to compensate for lack of maneuvering clearance
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10D
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Men's Restroom 100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	9-1/4" strike edge clearance
Rec. Solution:	Provide automatic door opening device to compensate for lack of maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10E
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Men's Restroom 100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Front App/pull 18" SEC - Relocate Door
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	9-1/4" strike edge clearance
Rec. Solution:	Provide automatic door opening device to compensate for lack of maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10F
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Men's Restroom 100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	53-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10G
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Men's Restroom 100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Clear Floor Space
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: SF As-built: 12
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Door swings into electrical switch clear floor space
Rec. Solution:	Remodel area to provide wheelchair space at control or mechanism
Barrier Severity:	3 Hindrance Cost Est \$6,900.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10H
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Men's Restroom 100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Mirror
Code References:	2010 ADAS 603.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Mirror not at lavatory/countertop not max. 35" AFF at edge of reflecting surface
Findings:	40-7/8" high
Rec. Solution:	Replace or remount mirror
Barrier Severity:	3 Hindrance Cost Est \$375.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10I
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Men's Restroom 100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Drainpipes
Code References:	2010 ADAS 606.5
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Hot water and drainpipes accessible under lavatory not insulated or covered
Findings:	Partial insulation provided
Rec. Solution:	Insulate drainpipes and hot water pipes
Barrier Severity:	2 Recommended Cost Est \$220.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10J
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Men's Restroom 100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	Protruding dispenser creates protruding object in path of travel
Findings:	Paper towel dispensers protrude 9" at 32-1/2" high
Rec. Solution:	Relocate dispenser or provide cane-detectable warning
Barrier Severity:	2 Recommended Cost Est \$1,100.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10K
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Men's Restroom 100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Rim
Code References:	2010 ADAS 605.2
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Urinal not max. 17" above the floor
Findings:	23" high
Rec. Solution:	Replace urinal
Barrier Severity:	2 Recommended Cost Est \$800.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10L
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Men's Restroom 100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Rim
Code References:	2010 ADAS 605.2
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Min. 1 urinal has no elongated rim projecting at least 13-1/2" from wall
Findings:	12-1/2" from wall
Rec. Solution:	Replace urinal
Barrier Severity:	
•	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10M
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Men's Restroom 100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Flush Controls
Code References:	2010 ADAS 309
Performance Sta	andard: No Quantity: JOB As-built : 0
Barrier Description:	Urinal flush controls mounted higher than 48" above the floor
Findings:	53-1/2" high
Rec. Solution:	Replace urinal controls where possible or entire urinal
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10N
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Men's Restroom 100A
X Coordinate:	N/A Y Coordinate: N/A
D	
Barrier Area:	Restrooms
Barrier Area: Barrier Type:	Restrooms Stall Door Hardware
Barrier Type: Code	Stall Door Hardware 2010 ADAS 604.8.1.2
Barrier Type: Code References:	Stall Door Hardware 2010 ADAS 604.8.1.2
Barrier Type: Code References: Performance Sta Barrier	Stall Door Hardware 2010 ADAS 604.8.1.2 andard: No Quantity: EACH As-built: 1
Barrier Type: Code References: Performance Sta Barrier Description:	Stall Door Hardware 2010 ADAS 604.8.1.2 andard: No Quantity: EACH As-built: 1 Stall door hardware involves tight grasping/pinching to close and no U-pull provided
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Stall Door Hardware 2010 ADAS 604.8.1.2 andard: No Quantity: EACH As-built: 1 Stall door hardware involves tight grasping/pinching to close and no U-pull provided No inner U-pull Provide U-pull hardware on outside and inside of stall door
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Stall Door Hardware 2010 ADAS 604.8.1.2 andard: No Quantity: EACH As-built: 1 Stall door hardware involves tight grasping/pinching to close and no U-pull provided No inner U-pull Provide U-pull hardware on outside and inside of stall door 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 100
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Men's Restroom 100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Transfer - Floor-mounted
Code References:	2010 ADAS 604.8.1.1
Performance Sta	ndard: No Quantity: SF As-built: 120
Barrier Description:	Min. 60" wide x 59" deep clear floor space not provided at floor-mounted fixture
Findings:	57" deep
Rec. Solution:	Remodel to provide wheelchair access
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	C/24/2010 Penert Date 0/42/2010 Parrier #: 40D
ricia bate.	6/24/2019 Report Date 9/13/2019 Barrier #: 10P
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 2 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms Coat Hook 2010 ADAS 603.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms Coat Hook 2010 ADAS 603.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms Coat Hook 2010 ADAS 603.4 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms Coat Hook 2010 ADAS 603.4 Indard: No Quantity: EACH As-built: 1 Clothing hooks not max. 48" high AFF
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms Coat Hook 2010 ADAS 603.4 Indard: No Quantity: EACH As-built: 1 Clothing hooks not max. 48" high AFF 52" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms Coat Hook 2010 ADAS 603.4 Indard: No Quantity: EACH As-built: 1 Clothing hooks not max. 48" high AFF 52" high Provide additional hook in new location 2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10Q
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Men's Restroom 100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Coat Hook
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not located within 30" x 48" clear floor space
Findings:	30" clear space not provided in front of toilet
Rec. Solution:	Relocate hook or provide additional hook
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10R
Field Date: Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 10R Gilmore Hall Reference Dwg: 2 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms Toilet - Rear Grab Bar 2010 ADAS 604.5.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms Toilet - Rear Grab Bar 2010 ADAS 604.5.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms Toilet - Rear Grab Bar 2010 ADAS 604.5.2 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms Toilet - Rear Grab Bar 2010 ADAS 604.5.2 ndard: No Quantity: JOB As-built: 1 Rear grab bar not centered 12" from wall and 24" on the other side of WC
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms Toilet - Rear Grab Bar 2010 ADAS 604.5.2 ndard: No Quantity: JOB As-built: 1 Rear grab bar not centered 12" from wall and 24" on the other side of WC 12-1/2" OC Replace grab bars with reinforcement
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Men's Restroom 100A N/A Y Coordinate: N/A Restrooms Toilet - Rear Grab Bar 2010 ADAS 604.5.2 ndard: No Quantity: JOB As-built: 1 Rear grab bar not centered 12" from wall and 24" on the other side of WC 12-1/2" OC Replace grab bars with reinforcement 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10S
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Men's Restroom 100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Side Grab Bar
Code References:	2010 ADAS 604.5.1
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Side grab bar does not extend min. 54" from rear wall
Findings:	50-1/2" from rear wall
Rec. Solution:	Replace grab bars with reinforcement
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10T
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Men's Restroom 100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Paper Dispenser
Code References:	2010 ADAS 604.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Toilet tissue dispenser not within 7" to 9" from front edge of toilet
Findings:	4" from rim
Rec. Solution:	Reposition or replace toilet paper dispenser
Barrier Severity:	3 Hindrance Cost Est \$225.00 Facility Function: Public Status: Open
Implementation	·
	Priority: 3 Implementation Phase: Implementation Date:



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10U
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Men's Restroom 100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Seat Cover Dispenser
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Seat cover dispenser not located on an accessible route. Blocked by water closet
Findings:	30" clear space not provided in front of toilet
Rec. Solution:	Replace or remount dispenser on an accessible route with clear floor space
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 10V
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Men's Restroom 100A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 11A
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Women's Restroom 101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Braille - On Door
Code References:	2010 ADAS 703.4.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Sign containing Braille/tactile info located on a door
Findings:	Tactile sign on door could present a issue for the visually impaired when reading
Rec. Solution:	Move sign to wall at latch side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 11B
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Women's Restroom 101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
	7 lbf
Findings:	
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Barrier Severity: Implementation	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 11C
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Women's Restroom 101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	2 second sweep
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 11D
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Women's Restroom 101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	Trash bin blocks strike edge clearance
Rec. Solution:	Move trash bin
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 11E
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Women's Restroom 101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 0
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Trash bin blocks electrical switch clear floor space
Rec. Solution:	Move trash bin
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 11F
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Women's Restroom 101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Electrical Switches
Code References:	2010 ADAS 205.1 & 309.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	53-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 11G
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Women's Restroom 101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Knee Clearance
Code References:	2010 ADAS 606.2 & 306
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Lavatory bottom apron/edge not at least 27" high
Findings:	26-1/4" high knee clearance
Rec. Solution:	Replace lavatory
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 11H
Field Date: Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 11H Gilmore Hall Reference Dwg: 2 of 3
Bldg Name:	
Bldg Name: Location:	Gilmore Hall Reference Dwg: 2 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 101
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 101 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 101 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 101 N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 101 N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 101 N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 101 N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 ndard: No Quantity: EACH As-built: 1 Hot water and drainpipes accessible under lavatory not insulated or covered
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 101 N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 ndard: No Quantity: EACH As-built: 1 Hot water and drainpipes accessible under lavatory not insulated or covered No insulation provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 101 N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 Indard: No Quantity: EACH As-built: 1 Hot water and drainpipes accessible under lavatory not insulated or covered No insulation provided Insulate drainpipes and hot water pipes 2 Recommended Cost Est \$220.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 111
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Women's Restroom 101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Mirror
Code References:	2010 ADAS 603.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface
Findings:	40-1/2" high
Rec. Solution:	Replace or remount mirror
Barrier Severity:	3 Hindrance Cost Est \$375.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 11J
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Women's Restroom 101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Accessible Route
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Dispenser not located on an accessible route
Findings:	Door swing obstructs paper towel dispenser clear floor space
Rec. Solution:	Replace or remount dispenser
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 11K
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Women's Restroom 101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding dispenser creates protruding object in path of travel
Findings:	Sanitary dispenser protrudes 6" at 40" high
Rec. Solution:	Relocate dispenser or provide cane-detectable warning
Barrier Severity:	2 Recommended Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 11L
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Women's Restroom 101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Sanitary Products
Code References:	2010 ADAS 603.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Sanitary product dispenser not usable with a closed fist
Findings:	Dispenser needed twisting motion
	·
Rec. Solution:	Replace sanitary napkin dispenser
Rec. Solution: Barrier Severity:	
	1 Necessary Cost Est \$650.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 11M
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Women's Restroom 101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Door Hardware
Code References:	2010 ADAS 604.8.1.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Stall door hardware involves tight grasping/pinching to close and no U-pull provided
Findings:	Inner U-pull provided
Rec. Solution:	Provide U-pull hardware on outside and inside of stall door
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 11N
Field Date: Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 11N Gilmore Hall Reference Dwg: 2 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 101
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 101 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 101 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 101 N/A Y Coordinate: N/A Restrooms Stall Entry - Front Approach -Pull 2010 ADAS 604.8.1.2 & Table 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 101 N/A Y Coordinate: N/A Restrooms Stall Entry - Front Approach -Pull 2010 ADAS 604.8.1.2 & Table 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 101 N/A Y Coordinate: N/A Restrooms Stall Entry - Front Approach -Pull 2010 ADAS 604.8.1.2 & Table 404.2.4.1 andard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 101 N/A Y Coordinate: N/A Restrooms Stall Entry - Front Approach -Pull 2010 ADAS 604.8.1.2 & Table 404.2.4.1 Indard: No Quantity: JOB As-built: 1 Door with front approach corridor (pull side) lacks min. 60" space perpendicular to door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 101 N/A Y Coordinate: N/A Restrooms Stall Entry - Front Approach -Pull 2010 ADAS 604.8.1.2 & Table 404.2.4.1 Indard: No Quantity: JOB As-built: 1 Door with front approach corridor (pull side) lacks min. 60" space perpendicular to door 26-1/4" perpendicular from stall partition to lavatory Replace compartment
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 101 N/A Y Coordinate: N/A Restrooms Stall Entry - Front Approach -Pull 2010 ADAS 604.8.1.2 & Table 404.2.4.1 Indard: No Quantity: JOB As-built: 1 Door with front approach corridor (pull side) lacks min. 60" space perpendicular to door 26-1/4" perpendicular from stall partition to lavatory Replace compartment 2 Recommended Cost Est \$1,650.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 110
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Women's Restroom 101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Transfer - Floor-mounted
Code References:	2010 ADAS 604.8.1.1
Performance Sta	ndard: No Quantity: SF As-built : 120
Barrier Description:	Min. 60" wide x 59" deep clear floor space not provided at floor-mounted fixture
Findings:	57" deep
Rec. Solution:	Remodel to provide wheelchair access
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 11P
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Women's Restroom 101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Rear Grab Bar
Code References:	2010 ADAS 604.5.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Rear grab bar not centered 12" from wall and 24" on the other side of WC
Findings:	12-1/2" OC
Rec. Solution:	Replace grab bars with reinforcement
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	
	Priority: 3 Implementation Phase: Implementation Date:



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 11Q
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Women's Restroom 101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Side Grab Bar
Code References:	2010 ADAS 604.5.1
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Side grab bar does not extend min. 54" from rear wall
Findings:	52-1/2" from rear wall
Rec. Solution:	Replace grab bars with reinforcement
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 11R
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Women's Restroom 101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Seat Height
Code References:	2010 ADAS 604.4
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Water closet seat not between 17" to 19" high
Findings:	19-1/2" high
Rec. Solution:	Replace water closet
Barrier Severity:	2 Recommended Cost Est \$850.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 11S
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Women's Restroom 101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Seat Cover Dispenser
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Seat cover dispenser not located on an accessible route. Blocked by water closet
Findings:	56" high
Rec. Solution:	Replace or remount dispenser on an accessible route with clear floor space
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 11T
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Women's Restroom 101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 12A
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 12B
Field Date: Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 12B Gilmore Hall Reference Dwg: 2 of 3
	Gilmore Hall Reference Dwg: 2 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H103
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H103 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H103 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H103 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Adjustment 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H103 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Adjustment 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H103 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Adjustment 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H103 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Adjustment 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H103 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Adjustment 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 11 lbf Replace or adjust existing closer
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H103 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Adjustment 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 11 lbf Replace or adjust existing closer I Necessary Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 12C
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built: 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	1 second sweep
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 12D
Field Date: Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 12D Gilmore Hall Reference Dwg: 2 of 3
	Gilmore Hall Reference Dwg: 2 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H103
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H103 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H103 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H103 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H103 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H103 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H103 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H103 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not accessible Provide new hardware
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Corridor H103 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not accessible Provide new hardware 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 12E
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	3-1/2" strike edge clearance
Rec. Solution:	Install automatic door opening device to compensate for lack of maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 12F
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Passage
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built : 1
Barrier Description:	Exit thru an exit enclosure/exit passageway lacks tactile exit sign
Findings:	Passageway to exterior exit with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT ROUTE" at exit side of door
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 12G
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 6
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route at rooms 102A, 102B, 105A, 102C, 105, 103
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$1,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 12H
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Mechanical box protrudes 6" at 40-7/8" high. Alarm box protrudes 4-3/4" at 44-3/4" high
Rec. Solution:	Remove protruding object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 12I
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H103
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Abrupt Change in Level
Code References:	2010 ADAS 303.3
Performance Sta	ndard: No Quantity: LF As-built : 1
Barrier Description:	Change in level greater than 1/2" leading in circulation path
Findings:	1" high door stop is a tripping object in the circulation path
Rec. Solution:	Repair to remove tripping object
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 13A
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - Wheelchair Use
Code References:	2010 ADAS 305
Performance Sta	ndard: No Quantity: SF As-built: 12
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Door swing blocks fire pull clear floor space
Rec. Solution:	Remodel area to provide wheelchair space
Barrier Severity:	2 Recommended Cost Est \$2,100.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 13B
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Fire Alarm - Pull Actuator Operation
Code References:	2010 ADAS 309.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Fire pull has no usable hardware
Findings:	Hardware not accessible
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 13C
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Fire Alarm - Pull Actuator Height
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Fire pulls not between 42" and 48" high
Findings:	60-1/2" high
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 13D
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Door
Code References:	2010 ADAS 216.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Ground floor doors that exit to exterior lacks tactile exit sign
Findings:	Exit door with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT" at exit side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 13E
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Exterior Adjustment
Code References:	Performance Standard
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 8.5 lbf
Findings:	12 lbf
Rec. Solution:	Adiust door closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 13F
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Exterior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built: 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	2 second sweep
Rec. Solution:	Adjust door closer
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 13G
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	View panel 46-1/4" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 13H
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Replace hardware on emergency egress door
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 13I
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Change Swing
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	3-1/2" strike edge clearance
Rec. Solution:	Change door swing to open in direction of egress
Parriar Cavarity	
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	· _ · _ · _ · _ · · _ · · · · · · · · ·



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 13J
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Landing - Existing (≥ 5.0%)
Code References:	2010 ADAS 404.2.4.4
Performance Sta	andard: No Quantity: SF As-built : 0
Barrier Description:	Door or gate lacks landing on both sides of door
Findings:	12.6% slope
Rec. Solution:	Provide ISA directional sign with arrow directing people to accessible entrance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 13K
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	No strike edge clearance provided
Rec. Solution:	Provide ISA directional sign with arrow directing people to accessible entrance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 13L
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 48"
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	indard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at push side with min. 18" lacks min. 48" perpendicular to door
Findings:	37-1/2" deep
Rec. Solution:	Provide ISA directional sign with arrow directing people to accessible entrance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 13M
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 13N
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Corridor H104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	No strobe provided in corridor where horn is provided where fire alarm exists in building
Findings:	No strobe where horn is provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 14A
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 2 of 3 Floor 1 - Stairway S101
_	
Location:	Floor 1 - Stairway S101
Location: X Coordinate:	Floor 1 - Stairway S101 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 1 - Stairway S101 N/A Y Coordinate: N/A Stairways
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 1 - Stairway S101 N/A Y Coordinate: N/A Stairways Handrail - Both Sides ADAAG 4.9.4* & 2010 ADAS 505.10.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 1 - Stairway S101 N/A Y Coordinate: N/A Stairways Handrail - Both Sides ADAAG 4.9.4* & 2010 ADAS 505.10.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 1 - Stairway S101 N/A Y Coordinate: N/A Stairways Handrail - Both Sides ADAAG 4.9.4* & 2010 ADAS 505.10.2 ndard: No Quantity: LF As-built: 25
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - Stairway S101 N/A Y Coordinate: N/A Stairways Handrail - Both Sides ADAAG 4.9.4* & 2010 ADAS 505.10.2 ndard: No Quantity: LF As-built: 25 No handrail provided at both sides of stairway
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - Stairway S101 N/A Y Coordinate: N/A Stairways Handrail - Both Sides ADAAG 4.9.4* & 2010 ADAS 505.10.2 ndard: No Quantity: LF As-built: 25 No handrail provided at both sides of stairway No handrail provided at both sides
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 1 - Stairway S101 N/A Y Coordinate: N/A Stairways Handrail - Both Sides ADAAG 4.9.4* & 2010 ADAS 505.10.2 ndard: No Quantity: LF As-built: 25 No handrail provided at both sides of stairway No handrail provided at both sides Provide handrails at both sides of stairway 2 Recommended Cost Est \$5,625.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 14B
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Stairway S101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Bottom
Code References:	2010 ADAS 505.10.3
Performance Sta	ndard: No Quantity: LF As-built: 0
Barrier Description:	Extension not sloped for length of one tread beyond the last riser nosing
Findings:	Extension not sloped for the length of one tread long
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 14C
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Stairway S101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code References:	2010 ADAS Advisory 504.4
Performance Sta	ndard: Yes Quantity: LF or TR As-built : 6
Barrier Description:	No contrasting color on each tread of interior stairway
Findings:	Treads lack contrasting color defined as 70% contrast
Rec. Solution:	Recommended: Consider providing contrasting color on each tread
Barrier Severity:	2 Recommended Cost Est \$210.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 14D
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Stairway S101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail - Both Sides
Code References:	ADAAG 4.9.4* & 2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built : 25
Barrier Description:	No handrail provided at both sides of stairway
Findings:	No handrail provided on outer guardrail
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$5,625.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 14E
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Stairway S101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail - Opening Limitations
Code References:	Performance Standard
Performance Sta	indard: No Quantity: LF As-built : 0
Barrier Description:	Guard or handrail have openings that allow passage of a 4" sphere
Findings:	6-1/4" openings
Rec. Solution:	Replace handrails
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 14F
Bldg Name:	Gilmore Hall Reference Dwg: 2 of 3
Location:	Floor 1 - Stairway S101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Vertical Access - Elevator
Code References:	2010 ADAS 403.1
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	No form of vertical access provided at stairway to reach upper floors
Findings:	No vertical access provided
Rec. Solution:	Provide a passenger elevator to reach upper floors
Barrier Severity:	1 Necessary Cost Est \$250,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 15A
Field Date: Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 15A Gilmore Hall Reference Dwg: 3 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Lobby L202/Corridor H203
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Lobby L202/Corridor H203 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Lobby L202/Corridor H203 N/A Y Coordinate: N/A Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Lobby L202/Corridor H203 N/A Y Coordinate: N/A Stairways Handrail - Opening Limitations Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Lobby L202/Corridor H203 N/A Y Coordinate: N/A Stairways Handrail - Opening Limitations Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Lobby L202/Corridor H203 N/A Y Coordinate: N/A Stairways Handrail - Opening Limitations Performance Standard andard: No Quantity: LF As-built: 8
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Lobby L202/Corridor H203 N/A Y Coordinate: N/A Stairways Handrail - Opening Limitations Performance Standard andard: No Quantity: LF As-built: 8 Guard or handrail have openings that allow passage of a 4" sphere
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Lobby L202/Corridor H203 N/A Y Coordinate: N/A Stairways Handrail - Opening Limitations Performance Standard andard: No Quantity: LF As-built: 8 Guard or handrail have openings that allow passage of a 4" sphere 22-1/2" opening along guard rail Replace handrails
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Lobby L202/Corridor H203 N/A Y Coordinate: N/A Stairways Handrail - Opening Limitations Performance Standard andard: No Quantity: LF As-built: 8 Guard or handrail have openings that allow passage of a 4" sphere 22-1/2" opening along guard rail Replace handrails 1 Necessary Cost Est \$1,800.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 15B
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Lobby L202/Corridor H203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 3
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route at room 232,233, and 240
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 16A
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Classroom 234
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Location - 48" to 60" high
Code References:	2010 ADAS 703.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor
Findings:	61-3/4" high and Braille 1/4" below raised characters
Rec. Solution:	Provide Braille/tactile sign at latch side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 16B
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Classroom 234
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	View panel 47" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 16C
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Classroom 234
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Desk blocks electrical switch clear floor space
Rec. Solution:	Rearrange desk to provide access
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 16D
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Classroom 234
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-3/4" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 16E
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Classroom 234
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Assembly Areas
Barrier Type:	Shared Assistive Listening System
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built : 1
Barrier Description:	No shared assistive listening system for room with min. 10 seats
Findings:	No system provided
Rec. Solution:	Provide shared ALS system with signage
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	· <u> </u>
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 16F
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Classroom 234
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36"
Code References:	2010 ADAS 403.5.1
Performance Sta	andard: No Quantity: LF As-built: 0
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	24" wide circulation route
Rec. Solution:	Rearrange desk to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 16G
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Classroom 234
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	26-5/8" high knee clearance at instructor's desk where students may give presentations
Rec. Solution:	Reposition desk to provide knee clearance
Barrier Severity:	1 Necessary Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 16H
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Classroom 234
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	54-1/2" high pencil sharpener
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 16I
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Classroom 234
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	50" high emergency phone
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 16J
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Classroom 234
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard (2010 ADAS 904.3.3)
Performance Sta	andard: Yes Quantity: EACH As-built: 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 40" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 16K
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Classroom 234
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Alarm - No Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/strobe
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 17A
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 5
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route at rooms 200, 231, 201, 202, 203
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 17B
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No strobe provided in corridor where horn is provided where fire alarm exists in building
Findings:	No strobe where horn is provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	· <u> </u>
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 17C
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Fire Alarm - Pull Actuator Operation
Code References:	2010 ADAS 309.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Fire pull has no usable hardware
Findings:	Hardware not accessible
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 17D
Field Date: Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 17D Gilmore Hall Reference Dwg: 3 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H201
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H201 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H201 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H201 N/A Y Coordinate: N/A Corridors Fire Alarm - Pull Actuator Height 2010 ADAS 308.2.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H201 N/A Y Coordinate: N/A Corridors Fire Alarm - Pull Actuator Height 2010 ADAS 308.2.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H201 N/A Y Coordinate: N/A Corridors Fire Alarm - Pull Actuator Height 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H201 N/A Y Coordinate: N/A Corridors Fire Alarm - Pull Actuator Height 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 0 Fire pulls not between 42" and 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H201 N/A Y Coordinate: N/A Corridors Fire Alarm - Pull Actuator Height 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 0 Fire pulls not between 42" and 48" high 60-3/4" high Replace fire pull when remodeling
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H201 N/A Y Coordinate: N/A Corridors Fire Alarm - Pull Actuator Height 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 0 Fire pulls not between 42" and 48" high 60-3/4" high Replace fire pull when remodeling A Low Severity Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 17E
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Extinguisher - Cabinet Hardware
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Fire extinguisher door hardware not usable by those with hand impairments
Findings:	Cabinet door hardware not accessible
Rec. Solution:	Relocate fire extinguisher hardware
Barrier Severity:	4 Low Severity Cost Est \$1,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 17F
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Extinguisher - Side Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Fire extinguisher forward or side reach exceeds 48"
Findings:	56" high
Rec. Solution:	
Rec. Solution.	Relocate fire extinguisher
Barrier Severity:	
	4 Low Severity Cost Est \$1,500.00 Facility Function: Public Status: Open



F: 115 ·	Printerior B. A. D. A. D. A. C. A. C.
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 17G
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 205.1 & 309.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18A
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - No Braille/tactile Sign
Code References:	2010 ADAS 703.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No Braille/tactile sign at latch side of door
Findings:	No tactile sign provided
Rec. Solution:	Provide Braille/tactile sign at latch side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18B
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	6 lbf
Rec. Solution:	Install automatic door opening device to compensate for lack of maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18C
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	1 second sweep
Rec. Solution:	Install automatic door opening device to compensate for lack of maneuvering clearance
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18D
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	View panel 47" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18E
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Latch App/pull 54"
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	indard: No Quantity: EACH As-built: 0
	madra. No Quantity. EACH As bant. 0
Barrier Description:	Door/Gate with latch approach with closer at pull side lacks min. 54" perpendicular to door
Description:	Door/Gate with latch approach with closer at pull side lacks min. 54" perpendicular to door
Description: Findings:	Door/Gate with latch approach with closer at pull side lacks min. 54" perpendicular to door 37-1/2" perpendicular to door Install automatic door opening device to compensate for lack of maneuvering clearance
Description: Findings: Rec. Solution:	Door/Gate with latch approach with closer at pull side lacks min. 54" perpendicular to door 37-1/2" perpendicular to door Install automatic door opening device to compensate for lack of maneuvering clearance 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18F
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: SF As-built: 12
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Door swing obstructs electrical switch clear floor space
Rec. Solution:	Remodel area to provide wheelchair space at control or mechanism or install automatic sensor
Barrier Severity:	3 Hindrance Cost Est \$6,900.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18G
Bldg Name:	Deference During S. Co.
DINE MAILLE.	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
•	
Location:	Floor 2 - Women's Restroom 203A
Location: X Coordinate:	Floor 2 - Women's Restroom 203A N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 2 - Women's Restroom 203A N/A Y Coordinate: N/A Controls and Mechanisms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 2 - Women's Restroom 203A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 2 - Women's Restroom 203A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 2 - Women's Restroom 203A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 2 - Women's Restroom 203A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 2 - Women's Restroom 203A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 53-1/2" high Relocate switch box top edge to max. 48" high
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 2 - Women's Restroom 203A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 Indianate: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 53-1/2" high Relocate switch box top edge to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18H
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Bench - Seat Depth
Code References:	Performance standard
Performance Sta	ndard: Yes Quantity: EACH As-built: 1
Barrier Description:	Bench seat not 20" to 24" deep
Findings:	15" deep
Rec. Solution:	Provide min. one accessible bench
Barrier Severity:	3 Hindrance Cost Est \$1,100.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18I
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Knee Clearance
Code References:	2010 ADAS 606.2 & 306
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Lavatory bottom apron/edge not at least 27" high
Findings:	24-1/2" high knee clearance
Rec. Solution:	Replace lavatory
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18J
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Drainpipes
Code References:	2010 ADAS 606.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hot water and drainpipes accessible under lavatory not insulated or covered
Findings:	No insulation provided
Rec. Solution:	Insulate drainpipes and hot water pipes
Barrier Severity:	2 Recommended Cost Est \$220.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18K
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Faucet
Code References:	2010 ADAS 606.4 & 309
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Lavatory faucet involves tight grasping, pinching or twisting of the wrist
Findings:	Faucet not operable with a closed fist
Rec. Solution:	Replace faucet
Barrier Severity:	1 Necessary Cost Est \$375.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18L
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Sanitary Products
Code References:	2010 ADAS 603.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Sanitary product dispenser not usable with a closed fist
Findings:	Sanitary dispenser not fist operable
Rec. Solution:	Replace sanitary napkin dispenser
Barrier Severity:	1 Necessary Cost Est \$650.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18M
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding dispenser creates protruding object in path of travel
Findings:	Sanitary dispense protrudes 5-1/2" at 40" high
Rec. Solution:	Relocate dispenser or provide cane-detectable warning
Barrier Severity:	2 Recommended Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18N
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Mirror
Code References:	2010 ADAS 603.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface
Findings:	57" high
Rec. Solution:	Replace or remount mirror
Barrier Severity:	3 Hindrance Cost Est \$375.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 180
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Door Closer
Code References:	2010 ADAS 604.8.1.2
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Stall door not equipped with an automatic closing device
Findings:	Stall door not self closing
Rec. Solution:	Replace compartment hinge with adjustable mechanism
Barrier Severity:	2 Recommended Cost Est \$1,650.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18P
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Stall - Door Hardware
Code References:	2010 ADAS 604.8.1.2
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	Inside of compartment door lacks a loop or U-pull below latch
Findings:	No inner or outer U-pulls provided
Rec. Solution:	Provide hardware
Barrier Severity:	1 Necessary Cost Est \$150.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18Q
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Clear Width
Code References:	2010 ADAS 404.2.3
Performance Sta	andords N. Oventitus FACU. As built a
	indard: No Quantity: EACH As-built : 0
Barrier Description:	Door clear width is not min. 32"
Barrier	
Barrier Description:	Door clear width is not min. 32"
Barrier Description: Findings:	Door clear width is not min. 32" Stall door 24-1/4" clear width Replace door
Barrier Description: Findings: Rec. Solution:	Door clear width is not min. 32" Stall door 24-1/4" clear width Replace door 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18R
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Entry - Front App/pull 18" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: SF As-built: 120
Barrier Description:	Stall door at pull side lacks min. 18" strike edge clearance
Findings:	8-1/4" strike edge clearance
Rec. Solution:	Redesign toilet room to provide maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$66,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18S
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Entry - Front Approach -Pull
Code References:	2010 ADAS 604.8.1.2 & Table 404.2.4.1
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Door with front approach corridor (pull side) lacks min. 60" space perpendicular to door
Findings:	30" perpendicular to door to toilet
Rec. Solution:	Replace compartment
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18T
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Coat Hook
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	70" high
Rec. Solution:	Provide additional hook in new location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18U
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Transfer - Floor-mounted
Code References:	2010 ADAS 604.8.1.1
Performance Sta	ndard: No Quantity: SF As-built : 0
Barrier Description:	Min. 60" wide x 59" deep clear floor space not provided at floor-mounted fixture
Findings:	34" wide x 55-1/2" deep
Rec. Solution:	Remodel to provide front transfer space
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18V
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Grab Bars
Code References:	2010 ADAS 604.5
Performance Sta	andard: No Quantity: JOB As-built : 2
Barrier Description:	No grab bars provided at water closet
Findings:	No grab bars provided
Rec. Solution:	Provide side and rear grab bars with reinforcement
Barrier Severity:	1 Necessary Cost Est \$1,800.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18W
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Seat Height
Code References:	2010 ADAS 604.4
Performance Sta	andard: No Quantity: JOB As-built: 1
Barrier Description:	Water closet seat not between 17" to 19" high
Findings:	15-1/2" high
Rec. Solution:	Replace water closet
Barrier Severity:	2 Recommended Cost Est \$850.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18X
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Flush Handle
Code References:	2010 ADAS 604.6
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Handle does not point to wide side of stall or compartment
Findings:	Handle pointing towards small side of stall/room
Rec. Solution:	Replace water closet
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18Y
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Paper Dispenser
Code References:	2010 ADAS 604.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Toilet tissue dispenser not within 7" to 9" from front edge of toilet
Findings:	Toilet paper directly next to toilet
Rec. Solution:	Reposition or replace toilet paper dispenser
Barrier Severity:	3 Hindrance Cost Est \$225.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18Z
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Seat Cover Dispenser
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Seat cover dispenser not located on an accessible route. Blocked by water closet
Findings:	Access to dispenser blocked by water closet and operating point is 50" high
Rec. Solution:	Replace or remount dispenser on an accessible route with clear floor space
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 18AA
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Women's Restroom 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/strobe in sanitary facility
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Ciald Data.	G/O / /OCCO. Powert Date O / O / OCCO. Powier # 1
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 19A
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route at rooms 204, 230, 205, 228A, 228, 206, 212, 225
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$2,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 19B
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Hi-Low Unit
Code References:	2010 ADAS 211.2 & 602.7
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	No hi-low drinking fountain provided on each floor of building
Findings:	No hi-low drinking fountain provided
Rec. Solution:	Provide min. one hi-low fountain on each floor
Barrier Severity:	1 Necessary Cost Est \$1,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 19C
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Bubbler height
Code References:	2010 ADAS 602.4
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Bubbler height exceeds 36"
Findings:	Drinking fountain has been removed but surface is greater than 36" high
Rec. Solution:	Provide min. one hi-low fountain on each floor
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 19D
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Knee Clearance
Code References:	2010 ADAS 306.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Knee clearance under fountain not min. 27" high
Findings:	No knee clearance
Rec. Solution:	Provide min. one hi-low fountain on each floor
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
	Thecessary Cost Est 50.00 Tacinty Function. Public Status. Open
Implementation	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 19E
Bldg Name:	
Location:	Floor 2 - Corridor H204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Operation - Manual (Fist)
Code References:	2010 ADAS 602.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Operating mechanism at fountain is not operable with a fist
Findings:	Fountain has been removed
Rec. Solution:	Provide min. one hi-low fountain on each floor
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 19F
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Sign protrudes 17" at 76-1/2" high
Rec. Solution:	Remove protruding object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	· _ · <u> </u>
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 19G
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 205.1 & 309.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 19H
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No strobe provided in corridor where horn is provided where fire alarm exists in building
Findings:	No strobe where horn is provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 19I
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Extinguisher - Cabinet Hardware
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Fire extinguisher door hardware not usable by those with hand impairments
Findings:	Cabinet door hardware not accessible
Rec. Solution:	Relocate fire extinguisher hardware
Barrier Severity:	4 Low Severity Cost Est \$1,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 19J
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Extinguisher - Side Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Fire extinguisher forward or side reach exceeds 48"
Findings:	55-3/4" high. No hose in cabinet
Rec. Solution:	Relocate fire extinguisher
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 19K
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail - Both Sides
Code References:	ADAAG 4.9.4* & 2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built : 5
Barrier Description:	No handrail provided at both sides of stairway
Findings:	No handrail provided at both sides
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$1,125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 19L
Field Date: Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 19L Gilmore Hall Reference Dwg: 3 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H204
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H204 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H204 N/A Y Coordinate: N/A Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H204 N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H204 N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H204 N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 Indard: Yes Quantity: LF or TR As-built: 2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H204 N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 Indard: Yes Quantity: LF or TR As-built: 2 No contrasting color on each tread of interior stairway
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H204 N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 Indard: Yes Quantity: LF or TR As-built: 2 No contrasting color on each tread of interior stairway Treads lack contrasting color defined as 70% contrast Recommended: Consider providing contrasting color on each tread
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H204 N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 Indard: Yes Quantity: LF or TR As-built: 2 No contrasting color on each tread of interior stairway Treads lack contrasting color defined as 70% contrast Recommended: Consider providing contrasting color on each tread 2 Recommended Cost Est \$70.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20A
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - No Braille/tactile Sign
Code References:	2010 ADAS 703.2.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No Braille/tactile sign at latch side of door
Findings:	No tactile sign provided
Rec. Solution:	Provide Braille/tactile sign at latch side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20B
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Door opening force exceeds 5 lbf
	6 lbf
Findings:	ld ibi
Findings: Rec. Solution:	Install automatic door opening device to compensate for lack of maneuvering clearance
J	Install automatic door opening device to compensate for lack of maneuvering clearance
Rec. Solution:	Install automatic door opening device to compensate for lack of maneuvering clearance 1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20C
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	1 second sweep
Rec. Solution:	Install automatic door opening device to compensate for lack of maneuvering clearance
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20D
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	View panel 47" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20E
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Change Swing
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	5" strike edge clearance
Rec. Solution:	Install automatic door opening device to compensate for lack of maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20F
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: SF As-built: 12
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Door swing obstructs electrical switch clear floor space
Rec. Solution:	Remodel area to provide wheelchair space at control or mechanism
Barrier Severity:	3 Hindrance Cost Est \$6,900.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20G
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	52-5/8" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20H
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Knee Clearance
Code References:	2010 ADAS 606.2 & 306
Performance Sta	ndard: No Quantity: JOB As-built : 1
Performance Sta Barrier Description:	Indard: No Quantity: JOB As-built: 1 Lavatory bottom apron/edge not at least 27" high
Barrier	
Barrier Description:	Lavatory bottom apron/edge not at least 27" high
Barrier Description: Findings:	Lavatory bottom apron/edge not at least 27" high 24" high knee clearance Replace lavatory
Barrier Description: Findings: Rec. Solution:	Lavatory bottom apron/edge not at least 27" high 24" high knee clearance Replace lavatory 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20I
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Drainpipes
Code References:	2010 ADAS 606.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hot water and drainpipes accessible under lavatory not insulated or covered
Findings:	No insulation provided
Rec. Solution:	Insulate drainpipes and hot water pipes
Barrier Severity:	2 Recommended Cost Est \$220.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20J
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Faucet
Code References:	2010 ADAS 606.4 & 309
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Lavatory faucet involves tight grasping, pinching or twisting of the wrist
Findings:	Faucet not operable with a closed fist
Rec. Solution:	Replace faucet
Barrier Severity:	1 Necessary Cost Est \$375.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20K
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Rim
Code References:	2010 ADAS 605.2
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Urinal not max. 17" above the floor
Findings:	24-3/4" high
Rec. Solution:	Replace urinal
Barrier Severity:	2 Recommended Cost Est \$800.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20L
Field Date: Bldg Name:	Gilmore Hall Report Date 9/13/2019 Barrier #: 20L Reference Dwg: 3 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Urinal - Rim 2010 ADAS 605.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Urinal - Rim 2010 ADAS 605.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Urinal - Rim 2010 ADAS 605.2 andard: No Quantity: JOB As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Urinal - Rim 2010 ADAS 605.2 andard: No Quantity: JOB As-built: 0 Min. 1 urinal has no elongated rim projecting at least 13-1/2" from wall
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Urinal - Rim 2010 ADAS 605.2 Min. 1 urinal has no elongated rim projecting at least 13-1/2" from wall 12-1/2" from wall Replace urinal
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Urinal - Rim 2010 ADAS 605.2 Indiard: No Quantity: JOB As-built: 0 Min. 1 urinal has no elongated rim projecting at least 13-1/2" from wall 12-1/2" from wall Replace urinal Replace urinal Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20M
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Flush Controls
Code References:	2010 ADAS 309
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Urinal flush controls mounted higher than 48" above the floor
Findings:	54" high
Rec. Solution:	Replace urinal controls where possible or entire urinal
Barrier Severity:	2 Recommended Cost Est \$800.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20N
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Mirror
Code References:	2010 ADAS 603.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Mirror not at lavatory/countertop not max. 35" AFF at edge of reflecting surface
Findings:	57-1/2" high
Rec. Solution:	Replace or remount mirror
Barrier Severity:	3 Hindrance Cost Est \$375.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 200
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Door Closer
Code References:	2010 ADAS 604.8.1.2
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Stall door not equipped with an automatic closing device
Findings:	Stall door not self closing
Rec. Solution:	Replace compartment hinge with adjustable mechanism
Barrier Severity:	2 Recommended Cost Est \$1,650.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20P
Field Date: Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 20P
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 andard: No Quantity: EACH As-built: 2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 Indard: No Quantity: EACH As-built: 2 Inside of compartment door lacks a loop or U-pull below latch
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 Inside of compartment door lacks a loop or U-pull below latch No inner or outer U-pull provided Provide hardware
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 Inside of compartment door lacks a loop or U-pull below latch No inner or outer U-pull provided Provide hardware 1 Necessary Cost Est \$150.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20Q
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Clear Width
Code References:	2010 ADAS 404.2.3
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Door clear width is not min. 32"
Findings:	Stall door 24-1/4" clear width
Rec. Solution:	Replace door/gate and frame
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20R
Field Date: Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 20R Gilmore Hall Reference Dwg: 3 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Stall Entry - Front App/pull 18" SEC 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Stall Entry - Front App/pull 18" SEC 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Stall Entry - Front App/pull 18" SEC 2010 ADAS Figure 404.2.4.1 andard: No Quantity: SF As-built: 120
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Stall Entry - Front App/pull 18" SEC 2010 ADAS Figure 404.2.4.1 Indard: No Quantity: SF As-built: 120 Stall door at pull side lacks min. 18" strike edge clearance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Stall Entry - Front App/pull 18" SEC 2010 ADAS Figure 404.2.4.1 Indard: No Quantity: SF As-built: 120 Stall door at pull side lacks min. 18" strike edge clearance 8-1/4" strike edge clearance at pull side Redesign toilet room to provide maneuvering clearance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Stall Entry - Front App/pull 18" SEC 2010 ADAS Figure 404.2.4.1 andard: No Quantity: SF As-built: 120 Stall door at pull side lacks min. 18" strike edge clearance 8-1/4" strike edge clearance at pull side Redesign toilet room to provide maneuvering clearance 1 Necessary Cost Est \$66,000.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20S
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Entry - Front Approach -Pull
Code References:	2010 ADAS 604.8.1.2 & Table 404.2.4.1
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Door with front approach corridor (pull side) lacks min. 60" space perpendicular to door
Findings:	28" perpendicular to door to toilet
Rec. Solution:	Replace compartment
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20T
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Coat Hook
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	70" high
Rec. Solution:	Provide additional hook in new location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	mponentation in the second sec



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20U
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Transfer - Floor-mounted
Code References:	2010 ADAS 604.8.1.1
Performance Sta	andard: No Quantity: SF As-built : 0
Barrier Description:	Min. 60" wide x 59" deep clear floor space not provided at floor-mounted fixture
Findings:	34" wide x 55-1/2" deep
Rec. Solution:	Remodel to provide front transfer space
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20V
Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 20V
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Toilet - Grab Bars 2010 ADAS 604.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Toilet - Grab Bars 2010 ADAS 604.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Toilet - Grab Bars 2010 ADAS 604.5 andard: No Quantity: JOB As-built: 2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Toilet - Grab Bars 2010 ADAS 604.5 Indard: No Quantity: JOB As-built: 2 No grab bars provided at water closet
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Toilet - Grab Bars 2010 ADAS 604.5 Andard: No Quantity: JOB As-built: 2 No grab bars provided at water closet No grab bars provided Provide side and rear grab bars with reinforcement
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Toilet - Grab Bars 2010 ADAS 604.5 Andard: No Quantity: JOB As-built: 2 No grab bars provided at water closet No grab bars provided Provide side and rear grab bars with reinforcement 1 Necessary Cost Est \$1,800.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20W
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Seat Height
Code References:	2010 ADAS 604.4
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Water closet seat not between 17" to 19" high
Findings:	16" high
Rec. Solution:	Replace water closet
Barrier Severity:	2 Recommended Cost Est \$850.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Ciald Data	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20X
Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 20X
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Toilet Paper Dispenser 2010 ADAS 604.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Toilet Paper Dispenser 2010 ADAS 604.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Toilet Paper Dispenser 2010 ADAS 604.7 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Toilet Paper Dispenser 2010 ADAS 604.7 Indard: No Quantity: EACH As-built: 1 Toilet tissue dispenser not within 7" to 9" from front edge of toilet
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Toilet Paper Dispenser 2010 ADAS 604.7 Indard: No Quantity: EACH As-built: 1 Toilet tissue dispenser not within 7" to 9" from front edge of toilet Toilet paper directly next to toilet Reposition or replace toilet paper dispenser
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Men's Restroom 205A N/A Y Coordinate: N/A Restrooms Toilet Paper Dispenser 2010 ADAS 604.7 Indard: No Quantity: EACH As-built: 1 Toilet tissue dispenser not within 7" to 9" from front edge of toilet Toilet paper directly next to toilet Reposition or replace toilet paper dispenser 3 Hindrance Cost Est \$225.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20Y
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Seat Cover Dispenser
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Seat cover dispenser not located on an accessible route. Blocked by water closet
Findings:	Access to dispenser blocked by water closet and operating point 49" high
Rec. Solution:	Replace or remount dispenser on an accessible route with clear floor space
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 20Z
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Men's Restroom 205A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/strobe in sanitary facility
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 21A
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 227
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	ISA - Non-Accessible Entry
Code References:	2010 ADAS 216.6
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Sign directing people to accessible entrance needed where all doors are not accessible
Findings:	ISA directional sign not provided at non-accessible door
Rec. Solution:	Provide ISA directional sign indicating location of accessible entrance where two entry doors ar
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 21B
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 227
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
	Signage
Barrier Type:	ISA - Accessible Entry Door
Barrier Type: Code References:	119
Code	ISA - Accessible Entry Door 2010 ADAS 216.6
Code References: Performance Sta Barrier	ISA - Accessible Entry Door 2010 ADAS 216.6
Code References:	ISA - Accessible Entry Door 2010 ADAS 216.6 Indard: No Quantity: EACH As-built: 1
Code References: Performance Sta Barrier Description:	ISA - Accessible Entry Door 2010 ADAS 216.6 Indard: No Quantity: EACH As-built: 1 No sign identifying door as accessible where all doors are not accessible
Code References: Performance Sta Barrier Description: Findings:	ISA - Accessible Entry Door 2010 ADAS 216.6 Indard: No Quantity: EACH As-built: 1 No sign identifying door as accessible where all doors are not accessible No sign provided to indicate that entrance is accessible Provide ISA directional sign at one door where two entry doors are provided and ISA sign at oth
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	ISA - Accessible Entry Door 2010 ADAS 216.6 Indard: No Quantity: EACH As-built: 1 No sign identifying door as accessible where all doors are not accessible No sign provided to indicate that entrance is accessible Provide ISA directional sign at one door where two entry doors are provided and ISA sign at oth 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 21C
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 227
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 21D
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 227
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	View panel 47-1/2" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$4,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 21E
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 227
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 21F
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 227
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Passage
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built : 2
Barrier Description:	Exit thru an exit enclosure/exit passageway lacks tactile exit sign
Findings:	Passageway to exterior exit with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT ROUTE" at exit side of door
Barrier Severity:	2 Recommended Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 21G
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 227
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	52" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 21H
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 227
V Capadina i	N/A Y Coordinate: N/A
X Coordinate:	IN/A T COSTAINACE. IN/A
X Coordinate: Barrier Area:	Controls and Mechanisms
Barrier Area:	Controls and Mechanisms
Barrier Area: Barrier Type: Code	Controls and Mechanisms Electrical Outlets - Hi/Low Reach 2010 ADAS 308.2.2
Barrier Area: Barrier Type: Code References:	Controls and Mechanisms Electrical Outlets - Hi/Low Reach 2010 ADAS 308.2.2
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Controls and Mechanisms Electrical Outlets - Hi/Low Reach 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Controls and Mechanisms Electrical Outlets - Hi/Low Reach 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Controls and Mechanisms Electrical Outlets - Hi/Low Reach 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 12" high Relocate outlet to area at min. 15" or max. 48" high
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Controls and Mechanisms Electrical Outlets - Hi/Low Reach 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 12" high Relocate outlet to area at min. 15" or max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 211
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 227
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Shelves or Cabinets
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Shelf or cabinet not mounted max. 48" above floor or ground
Findings:	Shelf not accessible
Rec. Solution:	Provide additional shelf at accessible height or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 21J
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 227
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route at room 228
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 21K
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 227
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 22A
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 226
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 22B
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 226
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	View panel 47-1/2" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	C /2 4 /2040 Deport Date 0 /42 /2040 Develop Ht. 220
i iciu Dale.	6/24/2019 Report Date 9/13/2019 Barrier #: 22C
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 226
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 226 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 226 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 226 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 226 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 226 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 226 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 226 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 mdard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not accessible Provide new hardware
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 226 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not accessible Provide new hardware 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 22D
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 226
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: SF As-built : 0
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Cabinet block electrical switch and knob clear floor space
Rec. Solution:	Rearrange furniture to provide access
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 22E
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 226
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Fist Operable
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not usable with a closed fist
Findings:	Twist knob not fist operable
Rec. Solution:	Replace operating control
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 22F
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 226
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route at rooms 227/226
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 22G
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 226
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	View panel 47-1/2" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 22H
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 226
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 22I
Field Date: Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 22I Gilmore Hall Reference Dwg: 3 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 226
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 226 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 226 N/A Y Coordinate: N/A Clear Floor Space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 226 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 226 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 226 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 226 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 Indard: No Quantity: JOB As-built: 1 Circulation route not min. 36" wide between elements
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 226 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 Indard: No Quantity: JOB As-built: 1 Circulation route not min. 36" wide between elements Room is currently used as storage space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 226 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 ndard: No Quantity: JOB As-built: 1 Circulation route not min. 36" wide between elements Room is currently used as storage space Rearrange room to provide access when room is put to use 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 22J
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 226
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24-1/2" - 25-1/2" high knee clearance
Rec. Solution:	Provide min. one accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 22K
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 226
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
	No. 10. No. 10. Phys.
Findings:	No device provided
Findings: Rec. Solution:	Provide strobe in common use area
_	Provide strobe in common use area
Rec. Solution:	Provide strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 23A
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	ISA - Non-Accessible Entry
Code References:	2010 ADAS 216.6
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Sign directing people to accessible entrance needed where all doors are not accessible
Findings:	ISA directional sign not provided at non-accessible door
Rec. Solution:	Provide ISA directional sign indicating location of accessible entrance where two entry doors ar
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 23B
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	ISA - Accessible Entry Door
Code References:	2010 ADAS 216.6
Performance Sta	ndard: No Quantity: EACH As-built : 1
Performance Sta Barrier Description:	ndard: No Quantity: EACH As-built: 1 No sign identifying door as accessible where all doors are not accessible
Barrier	
Barrier Description:	No sign identifying door as accessible where all doors are not accessible
Barrier Description: Findings:	No sign identifying door as accessible where all doors are not accessible No sign provided to indicate that entrance is accessible
Barrier Description: Findings: Rec. Solution:	No sign identifying door as accessible where all doors are not accessible No sign provided to indicate that entrance is accessible Provide ISA directional sign at one door where two entry doors are provided and ISA sign at oth 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 23C
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 23D
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	andard: No Quantity: EACH As-built : 2
Performance Sta Barrier Description:	Indard: No Quantity: EACH As-built : 2 View panels in or adjacent to doors or gates not max. 43" above floor or ground
Barrier	
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Barrier Description: Findings:	View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel 47-1/2" high Replace door/gate or vision panel
Barrier Description: Findings: Rec. Solution:	View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel 47-1/2" high Replace door/gate or vision panel 3 Hindrance Cost Est \$4,500.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 23E
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 23F
Field Date: Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 23F Gilmore Hall Reference Dwg: 3 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 208
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 andard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance State Barrier Description:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 Andard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Sofa blocks electrical switch and projector remote clear floor space Rearrange furniture to provide access
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Sofa blocks electrical switch and projector remote clear floor space Rearrange furniture to provide access 1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 23G
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	52" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 23H
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Hi/low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of control involves low reach of less than 15" above floor or more than 48" high
Findings:	Phone located on floor and not within accessible reach range
Rec. Solution:	Relocate to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	
	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 23I
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	51 0 0 1 1 0 0 1 1 0 0 0 0 0 0 0 0 0 0 0
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	
Code	Actuator/Control - Hi/low Reach
References:	2010 ADAS 308.2.2
Performance Sta	
Barrier Description:	Use of control involves low reach of less than 15" above floor or more than 48" high
Findings:	63" high projector remote
Rec. Solution:	Relocate to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 23J
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 208
Location:	Floor 2 - Graduate Student Office 208
Location: X Coordinate:	Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Controls and Mechanisms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Movable white board blocks electrical outlet clear floor space Move stored items
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Movable white board blocks electrical outlet clear floor space Move stored items 1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 23K
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 23L
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Protruding Object - Wall-mounted
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Wall mounted object protrudes more than 4" from wall
Findings:	Projector protrudes 25" at 79-1/2" high
Rec. Solution:	Remove protruding object or provide detectable warning for the visually impaired
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 23M
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Passageway - Min. 36"
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Passageway is not min. 36" wide
Findings:	31" wide between desks
Rec. Solution:	Rearrange desks to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 23N
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	25" - 26" knee clearance and 25" wide knee clearances at all desks
Rec. Solution:	Provide min. one accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 230
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Shelves or Cabinets
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Shelf or cabinet not mounted max. 48" above floor or ground
Findings:	Shelf not accessible
Rec. Solution:	Provide additional shelf at accessible height or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
·	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 23P
Field Date: Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 23P Gilmore Hall Reference Dwg: 3 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 208
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Clear Floor Space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 ndard: No Quantity: EACH As-built: 0 Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Mo Quantity: EACH As-built: 0 Protruding object in circulation path protrudes more than 4" between 27" and 80" high Electrical wires protrudes at 49" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Graduate Student Office 208 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Protruding object in circulation path protrudes more than 4" between 27" and 80" high Electrical wires protrudes at 49" high Remove protruding object 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 23Q
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Graduate Student Office 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
First I Broke	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 24A
Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 24A
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H205
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H205 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H205 N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H205 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H205 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H205 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H205 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 2 No tactile characters at sign identifying permanent rooms and spaces with visual signs
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H205 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route at rooms 210 and 212 Provide accessible sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H205 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 2 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route at rooms 210 and 212 Provide accessible sign 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 24B
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H205
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Shelves or Cabinets
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Shelf or cabinet not mounted max. 48" above floor or ground
Findings:	Flyers not accessible
Rec. Solution:	Provide additional shelf at accessible height or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 24C
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H205
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 24D
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H205
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Stairway
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built : 1
Barrier Description:	Door leading directly into an exit stairway lacks tactile exit sign
Findings:	Door to exit stair with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT STAIR DOWN (or UP)" at latch side of door
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 24E
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H205
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Exterior Adjustment
Code References:	Performance Standard
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier	Door opening force exceeds 8.5 lbf
Description:	
Description: Findings:	10 lbf
·	
Findings:	10 lbf Adiust door closer
Findings: Rec. Solution:	10 lbf Adiust door closer 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 24F
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H205
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Exterior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	2 second sweep
Rec. Solution:	Adjust door closer
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 24G
Field Date: Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 24G Gilmore Hall Reference Dwg: 3 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H205
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H205 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H205 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H205 N/A Y Coordinate: N/A Doors or Gates Abrupt Change in Level 2010 ADAS 303.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H205 N/A Y Coordinate: N/A Doors or Gates Abrupt Change in Level 2010 ADAS 303.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H205 N/A Y Coordinate: N/A Doors or Gates Abrupt Change in Level 2010 ADAS 303.3 Indard: No Quantity: LF As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H205 N/A Y Coordinate: N/A Doors or Gates Abrupt Change in Level 2010 ADAS 303.3 Indard: No Quantity: LF As-built: 0 Change in level greater than 1/2" leading to door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H205 N/A Y Coordinate: N/A Doors or Gates Abrupt Change in Level 2010 ADAS 303.3 Indard: No Quantity: LF As-built: 0 Change in level greater than 1/2" leading to door 7/8" leading from stair grate to actual threshold No remediation needed at emergency egress door threshold encountered only when entering
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Corridor H205 N/A Y Coordinate: N/A Doors or Gates Abrupt Change in Level 2010 ADAS 303.3 Indard: No Quantity: LF As-built: 0 Change in level greater than 1/2" leading to door 7/8" leading from stair grate to actual threshold No remediation needed at emergency egress door threshold encountered only when entering 4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Closed



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 24H
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H205
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 24I
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Corridor H205
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	ISA - Non-Accessible Entry
Code References:	2010 ADAS 216.6
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Sign directing people to accessible entrance needed where all doors are not accessible
Findings:	ISA directional sign not provided at non-accessible door
Rec. Solution:	Provide ISA directional sign with arrow directing people to accessible entrance
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 25A
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Breakroom 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 25B
Field Date: Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel 47-1/2" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel 47-1/2" high Replace door/gate or vision panel 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 25C
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Breakroom 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 25D
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Breakroom 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Change Swing
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	15-1/2" strike edge clearance and blocked by trash bins
Rec. Solution:	Change door swing to provide accessible maneuvering clearance and remove trash bins
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 25E
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Breakroom 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Trash bins block electrical switch clear floor space
Rec. Solution:	Remove trash bins
Barrier Severity:	1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 25F
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Breakroom 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	51-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 25G
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Breakroom 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Clear Floor Space
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Clear floor space 30" x 48" not provided at table
Findings:	Clear floor space not accessible
Rec. Solution:	Provide table in accessible location
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 25H
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Breakroom 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Pedestal Base
Code References:	2010 ADAS 306.2.2 & 306.2.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	Pedestal base blocks knee clearance
Rec. Solution:	Provide min. 1 accessible table. Avoid pedestal base tables.
Barrier Severity:	2 Recommended Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 25I
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Breakroom 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	14" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 25J
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Breakroom 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	33-1/2" wide between shelf and table
Rec. Solution:	Rearrange furniture to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 25K
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Breakroom 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Kitchens
Barrier Type:	Sink - Clear Floor Space
Code References:	2010 ADAS 606.2
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Clear floor space of min. 30" by 48" not provided in front of a sink to allow forward approach
Findings:	32-1/2" deep
Rec. Solution:	Rearrange furniture to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 25L
Field Date: Bldg Name:	6/24/2019 Report Date 9/13/2019 Barrier #: 25L Gilmore Hall Reference Dwg: 3 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Kitchens
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Kitchens Sink - Clear Floor Space 2010 ADAS 606.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Kitchens Sink - Clear Floor Space 2010 ADAS 606.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Kitchens Sink - Clear Floor Space 2010 ADAS 606.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Kitchens Sink - Clear Floor Space 2010 ADAS 606.2 ndard: No Quantity: EACH As-built: 1 Clear floor space of min. 30" by 48" not provided in front of a sink to allow forward approach
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Kitchens Sink - Clear Floor Space 2010 ADAS 606.2 ndard: No Quantity: EACH As-built: 1 Clear floor space of min. 30" by 48" not provided in front of a sink to allow forward approach 11" center line
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Kitchens Sink - Clear Floor Space 2010 ADAS 606.2 ndard: No Quantity: EACH As-built: 1 Clear floor space of min. 30" by 48" not provided in front of a sink to allow forward approach 11" center line Relocate sink 1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 25M
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Breakroom 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Kitchens
Barrier Type:	Sink - Rim
Code References:	2010 ADAS 606.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Sinks not mounted with the counter or rim no higher than 34" above the finish floor
Findings:	35" high
Rec. Solution:	Remount sink
Barrier Severity:	1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 25N
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Breakroom 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Kitchens
Barrier Type:	Sink - Knee Clearance
Code References:	2010 ADAS 804.4 & 606.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	No knee clearance
Rec. Solution:	Replace cabinet and remount sink if needed
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 250
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Breakroom 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Hi/low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	Use of control involves low reach of less than 15" above floor or more than 48" high
Findings:	54" high paper towel dispenser and 53" high soap dispenser
Rec. Solution:	Relocate to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$1,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 25P
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Breakroom 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Paper towel dispenser protrudes 10" at 54" high
Rec. Solution:	Remove protruding object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 25Q
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Location:	Floor 2 - Breakroom 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Kitchens
Barrier Type:	Countertop
Code References:	2010 ADAS 804.3
Performance Sta	ndard: No Quantity: LF As-built: 3
Barrier Description:	No accessible section of counter at max 34" high provided
Findings:	35" high
Rec. Solution:	Provide min. 30" of accessible counter at sink or work surface
Barrier Severity:	1 Necessary Cost Est \$1,110.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/24/2019 Report Date 9/13/2019 Barrier #: 25R
	0/24/2015 Hepot 5 at 8 5/15/2015 5/11/6 He
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name:	Gilmore Hall Reference Dwg: 3 of 3
Bldg Name: Location:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211
Bldg Name: Location: X Coordinate:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Alarms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Alarms Horn/Strobe - Common Use Area 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Alarms Horn/Strobe - Common Use Area 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Alarms Horn/Strobe - Common Use Area 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Alarms Horn/Strobe - Common Use Area 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Alarms Horn/Strobe - Common Use Area 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas No device provided Provide strobe in common use area
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: Barrier Severity:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Alarms Horn/Strobe - Common Use Area 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas No device provided Provide strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Gilmore Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 211 N/A Y Coordinate: N/A Alarms Horn/Strobe - Common Use Area 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas No device provided Provide strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open





SUMMARY REPORT

Cost Estimate Total	\$687,195.00		
Cost Estimate - Priority 1:	\$8,425.00	% of Total Cost Estimate:	1.23%
Cost Estimate - Priority 2:	\$410,710.00	% of Total Cost Estimate:	59.77%
Cost Estimate - Priority 3:	\$268,060.00	% of Total Cost Estimate:	39.01%