SZS CONSULTING GROUP

MORELAND HALL

ADA ASSESSMENT & SURVEY



Sacramento Office 770 L Street, Suite 950 Sacramento, CA 95814 Tel: 916.669.8750 Fax: 888.211.7441

Silicon Valley Office 2225 E. Bayshore Road, Suite 200 Palo Alto CA 94303 Tel: 866.694.7637 www.szs-consulting.com

April 20, 2017



GABRIEL MERRELL DIRECTOR, ACCESS AND AFFIRMATIVE ACTION OFFICE OF EQUAL OPPORTUNITY AND ACCESS OREGON STATE UNIVERSITY 330 SNELL HALL Corvallis, or 97331

Re: ADA Accessibility Survey and Assessment – Moreland Hall

Dear Gabriel,

We are pleased to submit this report for Moreland Hall. This report is part of our project to provide a Campus Accessibility Survey and Assessment for Oregon State University. It is our hope that this report will assist OSU in improving access to people with disabilities to campus facilities.

SZS has been pleased to be a part of this effort to evaluate campus buildings using federal and state statutes and regulations, as well as universal design principles in order to create performance standards that will guide design, construction and maintenance on campus.

We look forward to discussing our findings with your team.

Regards,

Syroun Z. Sanossian, Principal

Syn Z. Son.

SZS Consulting Group LLC

TABLE OF CONTENTS

1.	EXECUTI	VE SUMMARY OF FINDINGS	p. 1
	<i>a.</i>	Pedestrian Facilities and Exterior Spaces Analyzed	p. 2
	b.	Building Entrances	p. 3
2.	INTERIOR	R SPACES	
		First Floor	p. 3
		Second Floor	p. 4
		Third Floor	p. 5
3.	BARRIE	R DATA RECORDS	
		Exterior Area Barriers	p. 6
		Interior Area Barriers	p. 25
		Cost Estimate	n 42

1. EXECUTIVE SUMMARY OF FINDINGS

The field investigation for the interior spaces began on February 1, 2017. The exterior site elements were assessed originally as part of the pedestrian facilities assessment, in June to September 2011, and are included as an essential part of this report. Images of each physical element identified in this report were captured in HD digital photos while manual measurements were taken to establish as-built conditions to facilitate the process of cost estimating. Digital photographs are provided within the report for each barrier to access, to facilitate the review of the data collected. We have found that technical data can be difficult to interpret without a visual component; the photos provide a clear connection between the technical data and each barrier to access.

Moreland Hall is a historic structure and many barriers to access were identified in the building. That is quite typical, as barriers to access exist in virtually every building, whether new or existing.

No "perfect" building exists in the real world.

This ADA Assessment and Survey report is intended to not only identify barriers to access, but to provide solutions. The basis for this ADA Assessment and Survey process is the underlying desire on the part of OSU to improve access by relying on higher standards than the minimum requirements in state and federal building codes. SZS intends to provide the information in this report in a clear and easy to understand format. The information in this report is compiled for use by designated OSU staff and other interested persons, so the content is designed to be understood by professionals and laymen alike.

The findings presented are both narrative and technical in nature; barriers to access identified during the field investigation process are documented in two ways;

Narrative Analysis: The analysis of findings is contained in an executive summary in a
narrative form that not only describes each type of barrier identified, but also provides a
discussion that analyses the functionality of physical elements. We also provide the
reasoning and research behind the identification of barriers that conflict with universal
design principles. This analysis may be accompanied by digital photographs or
diagrams, where applicable.

NOTE: Understanding building function and usage is essential when interpreting the findings held in this report. The narrative is intended to facilitate this process.

2. <u>Barrier Data Records:</u> Individual barriers to access are entered into the SZS database so that technical information on the barriers can be provided as barrier data records. These barrier data records include digital photographs of each barrier identified, code references that determine the barrier to access, as-built measurements, barrier severity ratings, budgetary cost estimates, recommended solutions for barrier removal and a priority for barrier removal. The information is formatted with two barriers on each report page.

In order to consolidate the report data, some of the more typical barriers found in multiple locations have been grouped within the barrier data records with a description of the locations in which they were found.

A. Pedestrian Facilities and Exterior Spaces Analyzed

This report provides information on campus pedestrian facilities that serve Moreland Hall. Many physical elements are part of the comprehensive whole that creates a pedestrian facility. The fundamental elements evaluated as to whether they provide accessible pedestrian facilities include the following:

- Sidewalks
- Walkways
- Ramps
- **Curb Ramps**
- **Blended Transitions**
- Signalized Intersections
- Stairways (94% of people with disabilities are not mobility impaired)
- Benches and other Seating Elements
- Picnic Facilities

The descriptions provided for physical elements in this report are intended to clearly describe the differences between each physical element, such as when a pedestrian route is a sidewalk, rather than a walkway. The descriptions are intended to explain how the elements interact to form a cohesive pedestrian facility. Other more specific information described within this section intends to provide guidance on determinations made in this report.

The key to providing accessible pedestrian facilities is in recognizing that different people with disabilities have different needs. Setting policies that speak to the entire group is essential, rather than focusing on one particular subset of the overall group. Universal design principles govern here - physical elements should be usable to everyone that visits campus without having to resort to any adaptation or specialized design.

In summary, an accessible route exists within a building, property boundary or interior space and is separate from the PROW. Pedestrian walkways are similar to sidewalks as paved surfaces improved for use by pedestrians, but walkways are not located along or adjacent to the curb line, gutter or roadway and walkways are generally not considered part of the PROW. The pedestrian facility is the combination of the PROW and the accessible route, which functions as a whole to provide pedestrian access to facility entrances.

As a public building that was constructed prior to the passage of the ADA, Moreland Hall should have at least one accessible entrance. The accessible entrance was identified as the south entrance. This entrance was provided with a ramp and a stairway that leads to the main entrance on the first floor and a central corridor where an elevator is used to transport passengers to reach all floors.

Moreland Hall has an accessible route provided within the site from accessible parking spaces and accessible passenger loading zones; public streets and sidewalks; and public transportation stops to the accessible building or facility entrance they serve as compared to the 2010 ADA Standard for Accessible Design. Details on barriers identified in that route are provided within the ADA Assessment and Survey of the pedestrian facilities (provided as a separate report) as well as in the following records. Please see the barrier data records for details.

B. Building Entrances

The building is located at the corner of SW 26th street and SW Jefferson Avenue, within campus. On-site parking is provided on the southwest of the building and was identified with non-accessible slopes. An abrupt change in level was identified in the path to the entrance. A ramp, on the south side of the building, led to the first floor but the ramp lacked accessible handrails and running slope. Emergency exit stairways were located at several locations around the building. These stairways were in original condition and lacked accessible handrails and contrasting colors at stairway treads. ISA directional signage is recommended in locations at junctions in the accessible route to help ensure that pedestrians seeking an accessible entrance are not forced to retrace their steps.

INTERIOR SPACES

FIRST FLOOR

Moreland Hall is a three-story building that has classrooms, graduate student offices, and faculty offices. The main, and only, entry door had automatic door opening devices. These devices were functional, but lacked BHMA signs on each side of the doors meant as a safety precaution for able-bodied people to identify the doors as automatic. The main entry is directly connected to SW Jefferson Way and the campus pedestrian facility.

The lobby was not identified with an identification sign that indicates where accessible features are located. As a performance standard, it is recommended that lobby identification signage be provided on each floor in each central corridor that indicates the floor plan, the location of the person viewing the sign and the location of accessible features such as restrooms, elevator and drinking fountains in proximity to the location of the person reading the sign. Fire pulls were not accessible, and fire extinguishers and mechanical boxes created protruding objects in some locations within the circulation route. A drinking fountain was installed within the lobby area, but the fountain appeared to be original to the building and lacked knee clearance for those in a wheelchair and a bubbler height that short people could access. An interior ramp, that provided access to the east side of the building, was identified with a 1" lip at the bottom of the ramp transition from the corridor surface which could prevent access for people using wheelchairs or create a tripping situation for able-bodied people. The ramp also lacked a compliant slope and handrails.

A men's restroom and two unisex restrooms were provided on the first floor, but the spaces appeared to be in original condition with entry vestibules leading to toilet rooms. The entry

¹ 2010 ADA Standards for Accessible Design, Section 206.2.1 Site Arrival Points

doors were identified with non-accessible signage, heavy doors and non-accessible door hardware. Paper towel dispensers protruded into the circulation path with no detectable warning and the men's restroom lacked an accessible lavatory and urinal. Toilet stalls were also in original condition and lacked adequate clear width or maneuvering clearance to allow a wheelchair user to enter past a privacy wall or enter into any of the multiple stalls. Additionally, a support rail was installed at 76" high above the toilet stall entry doors resulting in a protruding hazard. The two unisex restrooms had adequate space to be made compliant, but at present, lacked an accessible lavatory and toilet. The toilet was removed in toilet room 120A, during the time of the field investigation, due to scheduled maintenance.

Graduate offices on this floor carried many of the same barriers. Doors did not have accessible hardware, strike edge clearance, and necessary headroom. In many cases, light switches and outlets were not located within an accessible reach range. Clear floor space needed to enable use shelves and coat hook was blocked by furniture or stored items. Due to this, maneuvering clearances were also reduced.

An elevator provided vertical access to all floors. The elevator lacked accessible signage on doorjambs, indicating the discharge level, and visual and audible signals were not provided in the elevator lobby on any floor. Other barriers to access included hall call buttons that were not fully illuminated for those with visual impairments, and emergency car control buttons that were not grouped together at the bottom of the control panel.

Stairways in the building appeared to have original handrails that lacked accessible extensions, grip height, and appeared to lack slip resistant surfaces. No contrasting color was identified at the stairway treads, which can be important to those with low vision. As a performance standard, it is highly recommended to provide contrasting color at stairway treads to improve visibility for all users.

Many staff use only areas were identified in the building. These spaces included IT rooms, janitorial rooms, private faculty offices and associated spaces. Signage at the door and doorway to these spaces were included in this report since they were located along the public circulation route of travel, but these interior spaces were not investigated as part of this assessment process. In general, institutions and organizations make staff use only areas accessible as needed through the reasonable accommodation iterative process between the employer and employee.

SECOND FLOOR

The second floor was identified with a waiting room, classroom, staff area, lounge, and a women's restroom. A high-low drinking fountain was provided in the main lobby, although the fixture was not located within an alcove or otherwise protected for those with visual impairments traveling through the lobby area. The second floor provided many public spaces including central lobby, a lounge and a waiting room. Tables, desks and counters provided in these areas were not identified as accessible. In addition, entry doors were not located directly within the path of the stairway which created a protruding object within the path of travel.

Corridors on this floor were identified with non-accessible cross slopes. The central stairway was not enclosed and was identified as lacking a horn or strobe device, stair level identification signage and compliant handrails and guardrails. An emergency exit could be

made accessible to most people who use the building with the remediation of some barriers, although it will not be possible to connect the exit to an accessible route usable by people who use mobility assist devices. Other barriers on this floor were similar to those described on the first floor.

THIRD FLOOR

The third floor was identified with a classroom, staff area, lounge, graduate student office and men's restroom. Corridors on this floor were identified with non-accessible cross slopes. The restroom on this floor was identified with no accessible fixtures similar to those described on other floors. The door landing and floor slope at the restroom, some classrooms and hallways, were also identified with a significant running slope. A high drinking fountain was installed within the hall area but no low fountain was provided for people who are short or who use wheelchairs. The women's restroom provided on this floor was identified with barriers similar to those described in other restrooms, including a nonaccessible entry door and fixtures.

The following barrier data records provide more detailed information on the barriers described above.





Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1237A
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - North Entrance Stairway
X Coordinate:	7477873.434 Y Coordinate: 339747.813
Barrier Area:	Stairways
Barrier Type:	Handrail Height
Code References:	OSSC 1109.8.6.(5) and 2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built : 225
Barrier Description:	Handrail grip measured at center not 34"- 38" high
Findings:	32" handrail grip height
Rec. Solution:	Provide accessible handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1237B
Field Date: Bldg Name:	7/28/2011 Report Date 7/28/2011 Barrier #: 1237B Moreland Hall Reference Dwg: 1 of 5
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 1 of 5 Exterior - North Entrance Stairway
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 1 of 5 Exterior - North Entrance Stairway 7477873.434 Y Coordinate: 339747.813
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 1 of 5 Exterior - North Entrance Stairway 7477873.434 Y Coordinate: 339747.813 Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 1 of 5 Exterior - North Entrance Stairway 7477873.434 Y Coordinate: 339747.813 Stairways Handrail Extension - Bottom OSSC 1109.8.6.(2)
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 1 of 5 Exterior - North Entrance Stairway 7477873.434 Y Coordinate: 339747.813 Stairways Handrail Extension - Bottom OSSC 1109.8.6.(2)
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 1 of 5 Exterior - North Entrance Stairway 7477873.434 Y Coordinate: 339747.813 Stairways Handrail Extension - Bottom OSSC 1109.8.6.(2) ndard: No Quantity: LF As-built: 225
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 1 of 5 Exterior - North Entrance Stairway 7477873.434
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 1 of 5 Exterior - North Entrance Stairway 7477873.434 Y Coordinate: 339747.813 Stairways Handrail Extension - Bottom OSSC 1109.8.6.(2) ndard: No Quantity: LF As-built: 225 Botttom handrail extension not level for min. 12" No level bottom handrail extension provided Provide accessible handrails at both sides of stairway
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 1 of 5 Exterior - North Entrance Stairway 7477873.434 Y Coordinate: 339747.813 Stairways Handrail Extension - Bottom OSSC 1109.8.6.(2) ndard: No Quantity: LF As-built: 225 Botttom handrail extension not level for min. 12" No level bottom handrail extension provided Provide accessible handrails at both sides of stairway 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1237C
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - North Entrance Stairway
X Coordinate:	7477873.434 Y Coordinate: 339747.813
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Top
Code References:	OSSC 1109.8.6.(2)
Performance Sta	ndard: No Quantity: LF As-built: 225
Barrier Description:	Top Handrail extension not parallel to ground/floor surface
Findings:	Top handrail extension not parallel to ground surface
Rec. Solution:	Provide accessible handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1237D
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - North Entrance Stairway
X Coordinate:	7477873.434 Y Coordinate: 339747.813
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code References:	2010 ADAS Advisory 504.4
_	
Performance Sta	ndard: Yes Quantity: LF or TR As-built: 35
Performance Sta Barrier Description:	ndard: Yes Quantity: LF or TR As-built: 35 No contrasting color on each tread of exterior stairway
Barrier	
Barrier Description: Findings:	No contrasting color on each tread of exterior stairway
Barrier Description: Findings:	No contrasting color on each tread of exterior stairway No contrasting color provided
Barrier Description: Findings: Rec. Solution:	No contrasting color on each tread of exterior stairway No contrasting color provided Consider providing contrasting color on each tread Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1237E
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - North Entrance Stairway
X Coordinate:	7477873.434 Y Coordinate: 339747.813
Barrier Area:	Stairways
Barrier Type:	Handrail Location
Code References:	OSSC 1109.8.6.(3)
Performance Sta	ndard: No Quantity: LF As-built : 225
Barrier Description:	Handrail grip not an absolute 1-1/2" from wall
Findings:	2" from wall
Rec. Solution:	Provide accessible handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1238
Field Date: Bldg Name:	7/28/2011 Report Date 7/28/2011 Barrier #: 1238
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 1 of 5 Exterior - North Entrance
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 1 of 5 Exterior - North Entrance 7477871.453 Y Coordinate: 339728.076
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 1 of 5 Exterior - North Entrance 7477871.453 Y Coordinate: 339728.076 Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 1 of 5 Exterior - North Entrance 7477871.453 Y Coordinate: 339728.076 Doors or Gates Abrupt Change in Level - Step at Landing OSSC 1109.9.3 and 2010 ADAS 303.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 1 of 5 Exterior - North Entrance 7477871.453 Y Coordinate: 339728.076 Doors or Gates Abrupt Change in Level - Step at Landing OSSC 1109.9.3 and 2010 ADAS 303.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 1 of 5 Exterior - North Entrance 7477871.453 Y Coordinate: 339728.076 Doors or Gates Abrupt Change in Level - Step at Landing OSSC 1109.9.3 and 2010 ADAS 303.3 Indard: No Quantity: SF As-built: 125
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 1 of 5 Exterior - North Entrance 7477871.453 Y Coordinate: 339728.076 Doors or Gates Abrupt Change in Level - Step at Landing OSSC 1109.9.3 and 2010 ADAS 303.3 Indard: No Quantity: SF As-built: 125 Change in level greater than 1/2" leading to door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 1 of 5 Exterior - North Entrance 7477871.453 Y Coordinate: 339728.076 Doors or Gates Abrupt Change in Level - Step at Landing OSSC 1109.9.3 and 2010 ADAS 303.3 ndard: No Quantity: SF As-built: 125 Change in level greater than 1/2" leading to door 2" lip
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 1 of 5 Exterior - North Entrance 7477871.453 Y Coordinate: 339728.076 Doors or Gates Abrupt Change in Level - Step at Landing OSSC 1109.9.3 and 2010 ADAS 303.3 Indard: No Quantity: SF As-built: 125 Change in level greater than 1/2" leading to door 2" lip Construct ramp to provide access to door landing 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1243A
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southeast Stairway
X Coordinate:	7477913.96 Y Coordinate: 339650.59
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Top
Code References:	OSSC 1109.8.6.(2)
Performance Sta	andard: No Quantity: LF As-built : 225
Barrier Description:	Top Handrail extension not parallel to ground/floor surface
Findings:	Top handrail extension not parallel to ground surface
Rec. Solution:	Provide accessible handrails at both sides of stairway
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1243B
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southeast Stairway
X Coordinate:	7477913.96 Y Coordinate: 339650.59
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Bottom
Code References:	OSSC 1109.8.6.(2)
Performance Sta	andard: No Quantity: LF As-built : 225
Barrier Description:	Botttom handrail extension not level for min. 12"
Findings:	No level bottom handrail extension provided
Rec. Solution:	Provide accessible handrails at both sides of stairway
Barrier Severity:	
Darrier Severity.	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	



Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1243C
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southeast Stairway
X Coordinate:	7477913.96 Y Coordinate: 339650.59
Barrier Area:	Stairways
Barrier Type:	Abrupt Change in Level
Code References:	2010 ADAS 504.4
Performance Sta	andard: No Quantity: LF As-built : 250
Barrier Description:	Change in level greater than 1/2" in landing
Findings:	1" lip
Rec. Solution:	Grind or repair to remove trip hazard
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1243D
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southeast Stairway
X Coordinate:	7477913.96 Y Coordinate: 339650.59
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code References:	2010 ADAS Advisory 504.4
Performance Sta	andard: Yes Quantity: LF or TR As-built: 35
Barrier Description:	No contrasting color on each tread of exterior stairway
Findings:	No contrasting color provided
Rec. Solution:	Consider providing contrasting color on each tread
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1240A
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - South Entrance Ramp
X Coordinate:	7477877.155 Y Coordinate: 339658.813
Barrier Area:	Ramps
Barrier Type:	Handrail Extension - Length
Code References:	OSSC 1109.7.6 and 2010 ADAS 505.10
Performance Sta	ndard: No Quantity: LF As-built : 225
Barrier Description:	Handrail extension not min. 12" long
Findings:	Top handrail extension not min. 12" long
Rec. Solution:	Provide accessible handrails at both sides of ramp
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1240B
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 1 of 5 Exterior - South Entrance Ramp
_	
Location:	Exterior - South Entrance Ramp
Location: X Coordinate:	Exterior - South Entrance Ramp 7477877.155 Y Coordinate: 339658.813
Location: X Coordinate: Barrier Area:	Exterior - South Entrance Ramp 7477877.155 Y Coordinate: 339658.813 Ramps
Location: X Coordinate: Barrier Area: Barrier Type: Code	Exterior - South Entrance Ramp 7477877.155 Y Coordinate: 339658.813 Ramps Handrail Height OSSC 1109.7.6 and 2010 ADAS 505.4
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Exterior - South Entrance Ramp 7477877.155 Y Coordinate: 339658.813 Ramps Handrail Height OSSC 1109.7.6 and 2010 ADAS 505.4
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Exterior - South Entrance Ramp 7477877.155 Y Coordinate: 339658.813 Ramps Handrail Height OSSC 1109.7.6 and 2010 ADAS 505.4 Indard: No Quantity: LF As-built: 225
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Exterior - South Entrance Ramp 7477877.155 Y Coordinate: 339658.813 Ramps Handrail Height OSSC 1109.7.6 and 2010 ADAS 505.4 ndard: No Quantity: LF As-built: 225 Handrails not 34"-38" high
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Exterior - South Entrance Ramp 7477877.155 Y Coordinate: 339658.813 Ramps Handrail Height OSSC 1109.7.6 and 2010 ADAS 505.4 ndard: No Quantity: LF As-built: 225 Handrails not 34"-38" high 31" handrail grip height
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Exterior - South Entrance Ramp 7477877.155 Y Coordinate: 339658.813 Ramps Handrail Height OSSC 1109.7.6 and 2010 ADAS 505.4 Indard: No Quantity: LF As-built: 225 Handrails not 34"-38" high 31" handrail grip height Provide accessible handrails at both sides of ramp 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1240C
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - South Entrance Ramp
X Coordinate:	7477877.155 Y Coordinate: 339658.813
Barrier Area:	Ramps
Barrier Type:	Ramp - Barrier Curb
Code References:	2010 ADAS 405.9.2
Performance Sta	ndard: No Quantity: LF As-built : 200
Barrier Description:	Ramp lacks min. 4" barrier at bottom of ramp handrail
Findings:	No min. 4" barrier provided at the bottom of ramp handrail
Rec. Solution:	Demolish existing and construct new ramp
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1240D
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 1 of 5 Exterior - South Entrance Ramp
Location:	Exterior - South Entrance Ramp
Location: X Coordinate:	Exterior - South Entrance Ramp 7477877.155 Y Coordinate: 339658.813
Location: X Coordinate: Barrier Area:	Exterior - South Entrance Ramp 7477877.155 Y Coordinate: 339658.813 Ramps
Location: X Coordinate: Barrier Area: Barrier Type: Code	Exterior - South Entrance Ramp 7477877.155 Y Coordinate: 339658.813 Ramps Running Slope - Existing (>9.5% or more) OSSC 1109.7.2 and 2010 ADAS 405.3
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Exterior - South Entrance Ramp 7477877.155 Y Coordinate: 339658.813 Ramps Running Slope - Existing (>9.5% or more) OSSC 1109.7.2 and 2010 ADAS 405.3
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Exterior - South Entrance Ramp 7477877.155 Y Coordinate: 339658.813 Ramps Running Slope - Existing (>9.5% or more) OSSC 1109.7.2 and 2010 ADAS 405.3 Indard: No Quantity: LF As-built: 200
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Exterior - South Entrance Ramp 7477877.155 Y Coordinate: 339658.813 Ramps Running Slope - Existing (>9.5% or more) OSSC 1109.7.2 and 2010 ADAS 405.3 ndard: No Quantity: LF As-built: 200 Running slope exceeds 8.33% (>9.5% or more)
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Exterior - South Entrance Ramp 7477877.155 Y Coordinate: 339658.813 Ramps Running Slope - Existing (>9.5% or more) OSSC 1109.7.2 and 2010 ADAS 405.3 Indard: No Quantity: LF As-built: 200 Running slope exceeds 8.33% (>9.5% or more) 10.6% running slope Demolish existing and construct new ramp
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Exterior - South Entrance Ramp 7477877.155 Y Coordinate: 339658.813 Ramps Running Slope - Existing (>9.5% or more) OSSC 1109.7.2 and 2010 ADAS 405.3 Indard: No Quantity: LF As-built: 200 Running slope exceeds 8.33% (>9.5% or more) 10.6% running slope Demolish existing and construct new ramp 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1240E
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - South Entrance Ramp
X Coordinate:	7477877.155 Y Coordinate: 339658.813
Barrier Area:	Ramps
Barrier Type:	Ramp Surface - Extended
Code References:	2010 ADAS 405.9.1
Performance Sta	andard: No Quantity: LF As-built : 200
Barrier Description:	Sides of ramp not extended min. 12" to prevent wheels from slipping off ramp
Findings:	No min. 12" extension provided at sides of ramp
Rec. Solution:	Demolish existing and construct new ramp or provide wheelguides at both sides of ramp
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1241
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - South Entrance
X Coordinate:	7477866.598 Y Coordinate: 339658.018
Barrier Area:	Doors or Gates
Barrier Type:	Door/Gate Landing - Existing (≥ 5.0%)
Code References:	2010 ADAS 404.2.4.4
Performance Sta	andard: No Quantity: SF As-built: 125
Barrier Description:	Door or gate lacks landing on both sides of door
Findings:	7.8% slope at automatic door actuator
Rec. Solution:	Demolish and reconstruct level landing
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1242A
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - South Entrance Stairway
X Coordinate:	7477864.547 Y Coordinate: 339655.256
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Top
Code References:	OSSC 1109.8.6.(2)
Performance Sta	ndard: No Quantity: LF As-built : 225
Barrier Description:	Top Handrail extension not parallel to ground/floor surface
Findings:	Top handrail extension not parallel to ground surface
Rec. Solution:	Provide accessible handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1242B
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - South Entrance Stairway
X Coordinate:	7477864.547 Y Coordinate: 339655.256
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Bottom
Code References:	OSSC 1109.8.6.(2)
Performance Sta	ndard: No Quantity: LF As-built : 225
Barrier Description:	Botttom handrail extension not level for min. 12"
Findings:	No level bottom handrail extension provided
Rec. Solution:	Provide accessible handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
	Priority: 1 Implementation Phase: Implementation Date:



Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1242C
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - South Entrance Stairway
X Coordinate:	7477864.547 Y Coordinate: 339655.256
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code References:	2010 ADAS Advisory 504.4
Performance Sta	ndard: Yes Quantity: LF or TR As-built : 35
Barrier Description:	No contrasting color on each tread of exterior stairway
Findings:	Contrasting color provided not on entire tread
Rec. Solution:	Consider providing contrasting color on each tread
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1242D
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - South Entrance Stairway
X Coordinate:	7477864.547 Y Coordinate: 339655.256
Barrier Area:	Stairways
Barrier Type:	Handrail Height
Code References:	OSSC 1109.8.6.(5) and 2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built: 225
Barrier Description:	Handrail grip measured at center not 34"- 38" high
Findings:	30" handrail grip height
Rec. Solution:	Provide accessible handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1250A
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southwest Walkway
X Coordinate:	7477749.628 Y Coordinate: 339649.739
Barrier Area:	Curb Ramps
Barrier Type:	Running Slope - Existing (9.5% or more)
Code References:	OSSC 1103.2.2.1 and 2010 ADAS 406.1
Performance Sta	ndard: No Quantity: EACH As-built : 3000
Barrier Description:	Ramp running slope exceeds 8.3% (9.5% or more)
Findings:	11.3% running slope
Rec. Solution:	Demolish existing and construct new curb ramp
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes: Two - wa	ay intersection corners B,C
Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1250B
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southwest Walkway
X Coordinate:	7477749.628 Y Coordinate: 339649.739
Barrier Area:	Curb Ramps
Barrier Type:	Flares - Existing (11.1% or more)
Code References:	OSSC 1103.2.2.3 and 2010 ADAS 406.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Ramp flare slope exceeds 10.0% (11.1% or more)
Findings:	21.5% flare slope
Rec. Solution:	Demolish existing and construct new curb ramp
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes: Two - wa	ay intersection corners B,C



Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1250C
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southwest Walkway
X Coordinate:	7477749.628 Y Coordinate: 339649.739
Barrier Area:	Curb Ramps
Barrier Type:	Detectable Warnings - Truncated Domes
Code References:	OSSC 1103.2.3.1 and 2010 ADAS 705.1.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	No truncated domes provided at curb ramp
Findings:	No detectable warnings at curb ramp
Rec. Solution:	Provide accessible truncated domes
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes: Two - wa	ay intersection corners B,C
Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1244
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southwest Parking Lot
X Coordinate:	7477760.373 Y Coordinate: 339614.369
Barrier Area:	Parking
Barrier Type:	
	Van Accessible Stall
Code References:	Van Accessible Stall OSSC 1104.1 and ORS 447.233.2.(b)
	OSSC 1104.1 and ORS 447.233.2.(b)
References:	OSSC 1104.1 and ORS 447.233.2.(b)
References: Performance Sta Barrier	OSSC 1104.1 and ORS 447.233.2.(b) ndard: No Quantity: EACH As-built : 475
References: Performance Sta Barrier Description: Findings:	OSSC 1104.1 and ORS 447.233.2.(b) ndard: No Quantity: EACH As-built: 475 No van accessible stall provided in parking lot/structure
References: Performance Sta Barrier Description: Findings:	OSSC 1104.1 and ORS 447.233.2.(b) ndard: No Quantity: EACH As-built: 475 No van accessible stall provided in parking lot/structure No van accessible stall provided
References: Performance Sta Barrier Description: Findings: Rec. Solution:	OSSC 1104.1 and ORS 447.233.2.(b) ndard: No Quantity: EACH As-built: 475 No van accessible stall provided in parking lot/structure No van accessible stall provided Provide min. one van accessible stall 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1245
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southwest Parking Lot
X Coordinate:	7477778.944 Y Coordinate: 339629.554
Barrier Area:	Parking
Barrier Type:	Stall Dimensions - Existing (5.0% or more)
Code References:	OSSC 1104.4.3
Performance Sta	andard: No Quantity: SF As-built: 100
Barrier Description:	Accessible stall & aisle not max. 2.0% in all directions (5.0% or more)
Findings:	5.0% slope
Rec. Solution:	Regrade stall to make level and restripe
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1246
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southwest Parking Lot
X Coordinate:	7477793.277 Y Coordinate: 339630.73
Barrier Area:	Parking
Barrier Type:	Stall Dimensions - Existing (5.0% or more)
Code References:	OSSC 1104.4.3
Performance Sta	andard: No Quantity: SF As-built: 100
Barrier Description:	Accessible stall & aisle not max. 2.0% in all directions (5.0% or more)
Findings:	5.3% slope
Rec. Solution:	Regrade stall to make level and restripe
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1252
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southwest Parking Lot Walkway
X Coordinate:	7477759.055 Y Coordinate: 339644.428
Barrier Area:	Walkways
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)
Code References:	OSSC 1103.2.4.3 and 2010 ADAS 403.3
Performance Sta	indard: No Quantity: LF As-built : 45
Barrier Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)
Findings:	3.3% cross slope
Rec. Solution:	Demolish existing and construct new route
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1253A
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southwest Parking Lot Walkway
X Coordinate:	7477789.261 Y Coordinate: 339644.785
Barrier Area:	
Barrier Type:	Curb Ramps
	Running Slope - Existing (9.5% or more)
Code References:	
Code	Running Slope - Existing (9.5% or more) OSSC 1103.2.2.1 and 2010 ADAS 406.1
Code References:	Running Slope - Existing (9.5% or more) OSSC 1103.2.2.1 and 2010 ADAS 406.1
Code References: Performance Sta Barrier	Running Slope - Existing (9.5% or more) OSSC 1103.2.2.1 and 2010 ADAS 406.1 Indard: No Quantity: EACH As-built: 3000
Code References: Performance Sta Barrier Description:	Running Slope - Existing (9.5% or more) OSSC 1103.2.2.1 and 2010 ADAS 406.1 Indard: No Quantity: EACH As-built: 3000 Ramp running slope exceeds 8.3% (9.5% or more)
Code References: Performance Sta Barrier Description: Findings:	Running Slope - Existing (9.5% or more) OSSC 1103.2.2.1 and 2010 ADAS 406.1 Indard: No Quantity: EACH As-built: 3000 Ramp running slope exceeds 8.3% (9.5% or more) 11.9% running slope Demolish existing and construct new curb ramp
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Running Slope - Existing (9.5% or more) OSSC 1103.2.2.1 and 2010 ADAS 406.1 Indard: No Quantity: EACH As-built: 3000 Ramp running slope exceeds 8.3% (9.5% or more) 11.9% running slope Demolish existing and construct new curb ramp 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1253B
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southwest Parking Lot Walkway
X Coordinate:	7477789.261 Y Coordinate: 339644.785
Barrier Area:	Curb Ramps
Barrier Type:	Flares - Existing (11.1% or more)
Code References:	OSSC 1103.2.2.3 and 2010 ADAS 406.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Ramp flare slope exceeds 10.0% (11.1% or more)
Findings:	14.7% flare slope
Rec. Solution:	Demolish existing and construct new curb ramp
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1253C
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southwest Parking Lot Walkway
X Coordinate:	7477789.261 Y Coordinate: 339644.785
X Coordinate: Barrier Area:	7477789.261 Y Coordinate: 339644.785 Curb Ramps
Barrier Area:	Curb Ramps
Barrier Area: Barrier Type: Code	Curb Ramps Detectable Warnings - Truncated Domes OSSC 1103.2.3.1 and 2010 ADAS 705.1.3
Barrier Area: Barrier Type: Code References:	Curb Ramps Detectable Warnings - Truncated Domes OSSC 1103.2.3.1 and 2010 ADAS 705.1.3
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Curb Ramps Detectable Warnings - Truncated Domes OSSC 1103.2.3.1 and 2010 ADAS 705.1.3 ndard: No Quantity: EACH As-built: 1400
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Curb Ramps Detectable Warnings - Truncated Domes OSSC 1103.2.3.1 and 2010 ADAS 705.1.3 ndard: No Quantity: EACH As-built: 1400 No truncated domes provided at curb ramp
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Curb Ramps Detectable Warnings - Truncated Domes OSSC 1103.2.3.1 and 2010 ADAS 705.1.3 ndard: No Quantity: EACH As-built: 1400 No truncated domes provided at curb ramp No detectable warnings at curb ramp
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Curb Ramps Detectable Warnings - Truncated Domes OSSC 1103.2.3.1 and 2010 ADAS 705.1.3 Indard: No Quantity: EACH As-built: 1400 No truncated domes provided at curb ramp No detectable warnings at curb ramp Provide accessible truncated domes 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1254
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southwest Parking Lot Walkway
X Coordinate:	7477797.042 Y Coordinate: 339644.602
Barrier Area:	Walkways
Barrier Type:	Cross Slope - Existing (2.1% to 3.0%)
Code References:	OSSC 1103.2.4.3 and 2010 ADAS 403.3
Performance Sta	ndard: No Quantity: LF As-built : 45
Barrier Description:	Cross slope exceeds 2.0% (2.1% to 3.0%)
Findings:	2.8% cross slope
Rec. Solution:	Low severity barrier - no remediation recommended
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1257
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southwest Parking Lot Walkway
X Coordinate:	7477811.209 Y Coordinate: 339641.03
Barrier Area:	Walkways
Barrier Type:	Cross Slope - Existing (5.0% or more)
Code References:	OSSC 1103.2.4.3 and 2010 ADAS 403.3
Performance Sta	ndard: No Quantity: LF As-built : 45
Barrier Description:	Cross slope exceeds 2.0% (5.0% or more)
Findings:	5.3% cross slope
Rec. Solution:	Demolish existing and construct new route
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	




Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1255A
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southwest Parking Lot Walkway
X Coordinate:	7477809.525 Y Coordinate: 339643.617
Barrier Area:	Curb Ramps
Barrier Type:	Running Slope - Existing (9.5% or more)
Code References:	OSSC 1103.2.2.1 and 2010 ADAS 406.1
Performance Sta	ndard: No Quantity: EACH As-built : 3000
Barrier Description:	Ramp running slope exceeds 8.3% (9.5% or more)
Findings:	10.5% running slope
Rec. Solution:	Demolish existing and construct new curb ramp
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes: Two - w	ay intersection corners A,B
Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1255B
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southwest Parking Lot Walkway
X Coordinate:	7477809.525 Y Coordinate: 339643.617
Barrier Area:	Curb Ramps
Barrier Type:	Flares - Existing (11.1% or more)
Code References:	OSSC 1103.2.2.3 and 2010 ADAS 406.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Ramp flare slope exceeds 10.0% (11.1% or more)
Findings:	12.0% flare slope
Rec. Solution:	Demolish existing and construct new curb ramp
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
Notes: Two - w	Priority: 1 Implementation Phase: Implementation Date:



Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1255C
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southwest Parking Lot Walkway
X Coordinate:	7477809.525 Y Coordinate: 339643.617
Barrier Area:	Curb Ramps
Barrier Type:	Detectable Warnings - Truncated Domes
Code References:	OSSC 1103.2.3.1 and 2010 ADAS 705.1.3
Performance Sta	ndard: No Quantity: EACH As-built : 1400
Barrier Description:	No truncated domes provided at curb ramp
Findings:	No detectable warnings at curb ramp
Rec. Solution:	Provide accessible truncated domes
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes: Two - w	ay intersection corners A,B
Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1256A
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southwest Parking Lot Walkway
X Coordinate:	7477845.165 Y Coordinate: 339629.212
Barrier Area:	Curb Ramps
Barrier Type:	Flares - Existing (11.1% or more)
Code References:	OSSC 1103.2.2.3 and 2010 ADAS 406.3
Performance Sta	ndard: No Quantity: EACH As-built : 3000
Barrier Description:	Ramp flare slope exceeds 10.0% (11.1% or more)
Findings:	11.2% flare slope
Rec. Solution:	Demolish existing and construct new curb ramp
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
Notes: Two - w	mplementation rade.



Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1256B
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southwest Parking Lot Walkway
X Coordinate:	7477845.165 Y Coordinate: 339629.212
Barrier Area:	Curb Ramps
Barrier Type:	Detectable Warnings - Truncated Domes
Code References:	OSSC 1103.2.3.1 and 2010 ADAS 705.1.3
Performance Sta	ndard: No Quantity: EACH As-built : 1400
Barrier Description:	No truncated domes provided at curb ramp
Findings:	No detectable warnings at curb ramp
Rec. Solution:	Provide accessible truncated domes
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes: Two - w	ay intersection corners A,B
Field Date:	7/28/2011 Report Date 7/28/2011 Barrier #: 1258
Bldg Name:	Moreland Hall Reference Dwg: 1 of 5
Location:	Exterior - Southwest Parking Lot Walkway
X Coordinate:	7477845.66 Y Coordinate: 339624.313
Barrier Area:	Walkways
Barrier Type:	Cross Slope - Existing (5.0% or more)
Code References:	OSSC 1103.2.4.3 and 2010 ADAS 403.3
Performance Sta	ndard: No Quantity: LF As-built : 45
Barrier Description:	Cross slope exceeds 2.0% (5.0% or more)
Findings:	5.4% cross slope
Rec. Solution:	Demolish existing and construct new route
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	





Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1A
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1B
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Landing - Control or Mechanism
Code References:	2010 ADAS 305.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Control or mechanism not located on a level landing
Findings:	2.3% slope at automatic door opening device actuator
Rec. Solution:	Relocate device to level location
Barrier Severity:	1 Necessary Cost Est \$400.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date	2/4/2047 Poport Data 2/22/2047 Parrier #1 4.0
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1C
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Sign
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: JOB As-built: 1
Barrier Description:	ISA symbol at automatic door opening device not min. 4" x 4" in size
Findings:	Existing symbol 1-3/4" high. Nor visible from a distance
Rec. Solution:	Recommended: Provide ISA symbol min. 4" x 4" in size
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1D
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - BHMA Sign
Code References:	ANSI/BHMA A156.10-1999
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Sign on door reading "AUTOMATIC DOOR" not visible from both sides
Findings:	No sign provided
Rec. Solution:	Provide new sign on both sides of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1E
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Timing
Code References:	2010 ADAS 404.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Door does not remain open for at least 6 seconds
Findings:	Door closes after 3 seconds
Rec. Solution:	Repair actuation device
Barrier Severity:	1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1F
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Timing
Code References:	2010 ADAS 404.3
Performance Sta	andard: No Quantity: JOB As-built : 0
Barrier Description:	Door does not re-open when encountering an obstruction other than the door jamb
Findings:	Door does not re-open
Rec. Solution:	Repair actuation device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	·
	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1G
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Doormat
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Doormat not anchored to floor (possible trip hazard)
Findings:	Doormat not secured
Rec. Solution:	Secure exiting doormat or replace
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1H
Field Date: Bldg Name:	2/1/2017 Report Date 3/23/2017 Barrier #: 1H Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Entry Lobby L0101
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Entry Lobby L0101 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Entry Lobby L0101 N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Entry Lobby L0101 N/A Y Coordinate: N/A Signage Tactile Exit Signs - To Exit Door Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Entry Lobby L0101 N/A Y Coordinate: N/A Signage Tactile Exit Signs - To Exit Door Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Entry Lobby L0101 N/A Y Coordinate: N/A Signage Tactile Exit Signs - To Exit Door Performance Standard ndard: Yes Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Entry Lobby L0101 N/A Y Coordinate: N/A Signage Tactile Exit Signs - To Exit Door Performance Standard ndard: Yes Quantity: EACH As-built: 1 Exit door leading directly to an exit to the exterior lacks tactile exit sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Entry Lobby L0101 N/A Y Coordinate: N/A Signage Tactile Exit Signs - To Exit Door Performance Standard ndard: Yes Quantity: EACH As-built: 1 Exit door leading directly to an exit to the exterior lacks tactile exit sign Door leading to exit door to exterior lacks tactile exit sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Entry Lobby L0101 N/A Y Coordinate: N/A Signage Tactile Exit Signs - To Exit Door Performance Standard ndard: Yes Quantity: EACH As-built: 1 Exit door leading directly to an exit to the exterior lacks tactile exit sign Door leading to exit door to exterior lacks tactile exit sign Provide sign stating "EXIT ROUTE" at exit side of door 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 11
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Lobby Info Sign
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: EACH As-built: 1
Barrier Description:	No lobby informational sign with location of accessible elements
Findings:	Accessible sign not provided
Rec. Solution:	Provide lobby informational sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1J
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
	Corridors
Barrier Type:	Corridors Sign - Permanent Room/Space
Barrier Type: Code References:	
Code	Sign - Permanent Room/Space 2010 ADAS 703.1
Code References:	Sign - Permanent Room/Space 2010 ADAS 703.1
Code References: Performance Sta Barrier	Sign - Permanent Room/Space 2010 ADAS 703.1 Indard: No Quantity: EACH As-built: 3
Code References: Performance Sta Barrier Description:	Sign - Permanent Room/Space 2010 ADAS 703.1 Indard: No Quantity: EACH As-built: 3 No sign with raised characters and Braille at permanent room or space with visual sign
Code References: Performance Sta Barrier Description: Findings:	Sign - Permanent Room/Space 2010 ADAS 703.1 Indard: No Quantity: EACH As-built: 3 No sign with raised characters and Braille at permanent room or space with visual sign No tactile info on signs with visual information Provide signs at latch side of entry door, where possible
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Sign - Permanent Room/Space 2010 ADAS 703.1 Indard: No Quantity: EACH As-built: 3 No sign with raised characters and Braille at permanent room or space with visual sign No tactile info on signs with visual information Provide signs at latch side of entry door, where possible 1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1K
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1L
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	N/A V Canadinata: N/A
	N/A Y Coordinate: N/A
	Alarms Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Area: Barrier Type: Code	Alarms Fire Pull - Operation 2010 ADAS 309.4
Barrier Area: Barrier Type: Code References:	Alarms Fire Pull - Operation 2010 ADAS 309.4
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Alarms Fire Pull - Operation 2010 ADAS 309.4 ndard: No Quantity: EACH As-built: 1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Alarms Fire Pull - Operation 2010 ADAS 309.4 ndard: No Quantity: EACH As-built: 1 Fire pull has no fist operable hardware
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Alarms Fire Pull - Operation 2010 ADAS 309.4 ndard: No Quantity: EACH As-built: 1 Fire pull has no fist operable hardware Fire pull not fist operable
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Alarms Fire Pull - Operation 2010 ADAS 309.4 ndard: No Quantity: EACH As-built: 1 Fire pull has no fist operable hardware Fire pull not fist operable Replace fire pull when remodeling 4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1M
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull - Height
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Fire pulls not between 42" and 48" high
Findings:	64" high
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1N
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	JEIOOF 1 - EHRY LODDY LOTOT
A Coordinate.	N/A Y Coordinate: N/A
Barrier Area:	
	N/A Y Coordinate: N/A
Barrier Area:	N/A Y Coordinate: N/A Clear Floor Space
Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307
Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 ndard: No Quantity: EACH As-built: 1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 ndard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Clear Floor Space Protruding Object 2010 ADAS 307 ndard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high Mechanical pipe protrudes 5" - 19" at 66" - 75" high
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Clear Floor Space Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high Mechanical pipe protrudes 5" - 19" at 66" - 75" high Provide detectable warning (wing walls) 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 10
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Fire riser protrudes 11" at 59-3/4" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1P
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	
	N/A Y Coordinate: N/A
Barrier Area:	N/A Y Coordinate: N/A Clear Floor Space
Barrier Area: Barrier Type:	
	Clear Floor Space
Barrier Type: Code	Clear Floor Space Protruding Object 2010 ADAS 307
Barrier Type: Code References:	Clear Floor Space Protruding Object 2010 ADAS 307
Barrier Type: Code References: Performance Sta Barrier	Clear Floor Space Protruding Object 2010 ADAS 307 Indard: No Quantity: LF As-built: 24
Barrier Type: Code References: Performance Sta Barrier Description:	Clear Floor Space Protruding Object 2010 ADAS 307 Indard: No Quantity: LF As-built: 24 Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Clear Floor Space Protruding Object 2010 ADAS 307 Indard: No Quantity: LF As-built: 24 Protruding object in circulation path protrudes more than 4" between 27" and 80" high Stairway leading edge 69" high Provide detectable warning (railing) with cane detectable edge centered at 6" from floor and to
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Clear Floor Space Protruding Object 2010 ADAS 307 Indard: No Quantity: LF As-built: 24 Protruding object in circulation path protrudes more than 4" between 27" and 80" high Stairway leading edge 69" high Provide detectable warning (railing) with cane detectable edge centered at 6" from floor and to 1 Necessary Cost Est \$5,400.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1Q
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No strobe provided in corridor where horn is provided where fire alarm exists in building
Findings:	No strobe where horn is provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1R
Field Date: Bldg Name:	2/1/2017 Report Date 3/23/2017 Barrier #: 1R Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Entry Lobby L0101
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Entry Lobby L0101 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Entry Lobby L0101 N/A Y Coordinate: N/A Clear Floor Space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Entry Lobby L0101 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Entry Lobby L0101 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Entry Lobby L0101 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Entry Lobby L0101 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 ndard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Entry Lobby L0101 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Protruding object in circulation path protrudes more than 4" between 27" and 80" high Mechanical boxes at door jamb protrude 4-1/2" at 59-1/2"-68-1/2" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Entry Lobby L0101 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Protruding object in circulation path protrudes more than 4" between 27" and 80" high Mechanical boxes at door jamb protrude 4-1/2" at 59-1/2"-68-1/2" high Remove object or provide detectable warning (wing walls) Remove Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1S
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Bubbler height
Code References:	2010 ADAS 602.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Bubbler height exceeds 36"
Findings:	39" bubbler height
Rec. Solution:	Replace drinking fountain with wheelchair accessible unit or remount existing
Barrier Severity:	1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1T
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Spout Location
Code References:	2010 ADAS 602.4
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Spout not located at max. 5" from rim or max 15" from backsplash
Findings:	45 degree and 2" from rim
Rec. Solution:	Replace fountain with accessible unit
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1U
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Knee Clearance
Code References:	2010 ADAS 306.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Knee clearance under fountain not min. 27" high
Findings:	No knee clearance
Rec. Solution:	Replace drinking fountain with accessible unit or remount existing
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 1V
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Entry Lobby L0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	ISA at Non-Acc Fountain
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Non-accessible fountain lacks ISA directional sign
Findings:	No information at non-accessible fountain indicating location of wheelchair accessible fountain
	on this floor
Rec. Solution:	Provide ISA directional sign indicating location of and route to accessible fountain
Rec. Solution: Barrier Severity:	Provide ISA directional sign indicating location of and route to accessible fountain
	Provide ISA directional sign indicating location of and route to accessible fountain 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 2A
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Stairway S0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail - Both Sides
Code References:	ADAAG 4.9.4* & 2010 ADAS 505.10.2
Performance Sta	andard: No Quantity: LF As-built : 29
Barrier Description:	No handrail provided at both sides of stairway
Findings:	No handrail on inner guardrail
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$6,525.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 2B
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Stairway S0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Height
Code References:	2010 ADAS 505.10.2
Performance Sta	andard: No Quantity: LF As-built: 0
Barrier Description:	Handrail grip measured at center not 34"- 38" high
Findings:	31" handrail grip height
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 2C
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Stairway S0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Bottom
Code References:	2010 ADAS 505.10.3
Performance Sta	ndard: No Quantity: LF As-built : 1
Barrier Description:	Extension not sloped for length of one tread beyond the last riser nosing
Findings:	10" from first riser nosing
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$225.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 2D
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Stairway S0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Grip
Code References:	2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built : 0
Barrier Description:	Handrail grip is not continuous
Findings:	Handrail forces users to open grip while traveling
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 2E
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Stairway S0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Height
Code References:	2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built : 0
Barrier Description:	Handrail grip measured at center not 34"- 38" high
Findings:	31-1/2" guardrail grip height
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 2F
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Stairway S0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code References:	2010 ADAS Advisory 504.4
Performance Sta	ndard: Yes Quantity: LF or TR As-built : 26
Barrier Description:	No contrasting color on each tread of interior stairway
Findings:	Treads lack contrasting color defined as 70% contrast
Rec. Solution:	Recommended: Consider providing contrasting color on each tread
Barrier Severity:	
barrier severity.	2 Recommended Cost Est \$910.00 Facility Function: Public Status: Open
Implementation	



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 2G
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Stairway S0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 3A
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - No Braille/tactile Sign
Code References:	2010 ADAS 703.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No Braille/tactile sign at latch side of door
Findings:	No tactile sign at latch side of vestibule entry door
Rec. Solution:	Provide Braille/tactile sign at latch side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	
	Priority: 3 Implementation Phase: Implementation Date:



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 3B
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - ISA at Accessible Restroom
Code References:	2010 ADAS 216.8
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No ISA symbol on wall sign posted at accessible toilet room
Findings:	No ISA sign at vestibule entry door
Rec. Solution:	Provide ISA symbol on restroom wall sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 3C
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	9 lbf at entry vestibule door
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 3D
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	1 second sweep at entry vestibule door
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 3E
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Operating controls involve tight grasping, pinching or twisting
Findings:	Hardware not operable with a closed fist
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 3F
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	43-1/2" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 3G
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	ity/
Darrier Area.	Doors or Gates
Barrier Type:	
	Doors or Gates
Barrier Type: Code	Doors or Gates Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1
Barrier Type: Code References:	Doors or Gates Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1
Barrier Type: Code References: Performance Sta Barrier	Doors or Gates Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0
Barrier Type: Code References: Performance Sta Barrier Description:	Doors or Gates Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Doors or Gates Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side 12-3/4" strike edge clearance and recessed 7-3/4" at push side of vestibule entry door
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Doors or Gates Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1 Indard: No Quantity: EACH As-built: 0 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side 12-3/4" strike edge clearance and recessed 7-3/4" at push side of vestibule entry door Provide automatic door opening device 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 3H
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Electrical Switches
Code References:	2010 ADAS 205.1 & 309.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-1/4" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 4A
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Decree of Decree /Conserve Toutile Channels on
Code	Permanent Room/Space - Tactile Characters
References:	2010 ADAS 216.2
	2010 ADAS 216.2
References:	2010 ADAS 216.2
References: Performance Sta Barrier	2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1
References: Performance Sta Barrier Description: Findings:	2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs
References: Performance Sta Barrier Description: Findings:	2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route at entry door
References: Performance Sta Barrier Description: Findings: Rec. Solution:	ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route at entry door Provide accessible sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 4B
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Flush Controls
Code References:	2010 ADAS 309
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Urinal flush controls mounted higher than 48" above the floor
Findings:	52" high
Rec. Solution:	Replace urinal controls where possible or entire urinal
Barrier Severity:	2 Recommended Cost Est \$800.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 4C
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Rim
Code References:	2010 ADAS 605.2
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Urinal not max. 17" above the floor
Findings:	24-1/2" high
Findings: Rec. Solution:	24-1/2" high Replace urinal
_	Replace urinal
Rec. Solution:	Replace urinal 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 4D
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Rim Height
Code References:	2010 ADAS 606.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Lavatory rim or counter edge is higher than 34" AFF
Findings:	34-3/4" high at both lavatories
Rec. Solution:	Provide min. 1 accessible lavatory
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 4E
Field Date: Bldg Name:	2/1/2017 Report Date 3/23/2017 Barrier #: 4E Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148A
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148A N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148A N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148A N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148A N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 ndard: No Quantity: EACH As-built: 1 Hot water and drainpipes accessible under lavatory not insulated or covered
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148A N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 ndard: No Quantity: EACH As-built: 1 Hot water and drainpipes accessible under lavatory not insulated or covered No insulation provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148A N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 Indard: No Quantity: EACH As-built: 1 Hot water and drainpipes accessible under lavatory not insulated or covered No insulation provided Insulate drainpipes and hot water pipes 2 Recommended Cost Est \$220.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 4F
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Surfaces
Code References:	2010 ADAS 606.5
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Lavatory has sharp or abrasive surfaces on edge, rim or apron
Findings:	Hose beneath lavatory identified with sharp surfaces
Rec. Solution:	Replace lavatory
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 4G
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Mirror
Code References:	2010 ADAS 603.3
D C+ -	
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	ndard: No Quantity: EACH As-built: 1 Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface
Barrier	
Barrier Description:	Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface
Barrier Description: Findings:	Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface 52" high
Barrier Description: Findings: Rec. Solution:	Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface 52" high Replace or remount mirror 3 Hindrance Cost Est \$375.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 4H
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Table blocks paper towel dispenser clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 4
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Height
Code References:	
Code	Dispensers - Height 2010 ADAS 307.2
Code References:	Dispensers - Height 2010 ADAS 307.2
Code References: Performance Sta Barrier	Dispensers - Height 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 1
Code References: Performance Sta Barrier Description: Findings:	Dispensers - Height 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 1 Dispenser control point or operating mechanism not max. 48" AFF
Code References: Performance Sta Barrier Description: Findings:	Dispensers - Height 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 1 Dispenser control point or operating mechanism not max. 48" AFF Paper towel dispenser 60" high
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dispensers - Height 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 1 Dispenser control point or operating mechanism not max. 48" AFF Paper towel dispenser 60" high Remount no higher than 48" above floor 2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 4J
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding dispenser creates protruding object in path of travel
Findings:	Paper towel dispenser protrudes 10" at 60" high
Rec. Solution:	Relocate dispenser or provide cane-detectable warning
Barrier Severity:	2 Recommended Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 5A
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Clear Width
Code References:	2010 ADAS 404.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door clear width is not min. 32"
Findings:	29-7/8" clear width
•	25 776 siedi widu.
Rec. Solution:	Replace door/gate and frame
Rec. Solution: Barrier Severity:	
	Replace door/gate and frame 1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 5B
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Maneuvering Clearance
Code References:	2010 ADAS 603.2.1
Performance Sta	ndard: No Quantity: SF As-built: 120
Barrier Description:	T-shaped turning space not 36" wide turning into 36" space
Findings:	32-1/2" wide x 32-1/2" wide turning space
Rec. Solution:	Remodel toilet room
Barrier Severity:	2 Recommended Cost Est \$69,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
-	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 5C
Field Date: Bldg Name:	2/1/2017 Report Date 3/23/2017 Barrier #: 5C Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Accessible Route 2010 ADAS 402 & 403
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Accessible Route 2010 ADAS 402 & 403
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Accessible Route 2010 ADAS 402 & 403 ndard: No Quantity: LF As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Accessible Route 2010 ADAS 402 & 403 ndard: No Quantity: LF As-built: 0 Accessible route not provided to restroom (min. 36" clear width)
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Accessible Route 2010 ADAS 402 & 403 ndard: No Quantity: LF As-built: 0 Accessible route not provided to restroom (min. 36" clear width) 32-1/2" wide between privacy wall and stall walls
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Restrooms Accessible Route 2010 ADAS 402 & 403 Accessible route not provided to restroom (min. 36" clear width) 32-1/2" wide between privacy wall and stall walls Relocate restroom or redesign 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 5D
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: SF As-built: 3
Barrier Description:	Object protrudes more than 4" into pedestrian way
Findings:	Silver rail leading edge 77" high above stall entry doors
Rec. Solution:	Alter area to remove object
Barrier Severity:	1 Necessary Cost Est \$1,650.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 5E
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Door Closer
Code References:	2010 ADAS 604.8.1.2
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Stall door not equipped with an automatic closing device
Findings:	Door does not self-close
Rec. Solution:	Replace compartment hinge with adjustible mechanism
Barrier Severity:	
	2 Recommended Cost Est \$1,650.00 Facility Function: Public Status: Open
Implementation	



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 5F
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Single Accommodation - In-swinging Door
Code References:	2010 ADAS 603.2.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Space in room not adequate to allow wheelchair user to enter and close door
Findings:	Door swings into clear floor space
Rec. Solution:	Remodel to provide access
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 5G
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Door Hardware
Code References:	2010 ADAS 604.8.1.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Stall door hardware involves tight grasping/pinching to close and no U-pull provided
Findings:	No outer U-pull provided
Rec. Solution:	Provide U-pull hardware on outside and inside of stall door
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 5H
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Door Hardware
Code References:	2010 ADAS 604.8.1.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Stall door hardware involves tight grasping/pinching to close and no U-pull provided
Findings:	No inner U-pull provided
Rec. Solution:	Provide U-pull hardware on outside and inside of stall door
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 51
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Clear Width
Code References:	2010 ADAS 404.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door clear width is not min. 32"
Findings:	24-3/4" clear width
Rec. Solution:	Replace door/gate and frame
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 5J
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Entry - Front App/pull 18" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: SF As-built : 0
Barrier Description:	Stall door at pull side lacks min. 18" strike edge clearance
Findings:	4-7/8" strike edge clearance
Rec. Solution:	Redesign toilet room to provide maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 5K
Field Date: Bldg Name:	2/1/2017Report Date3/23/2017Barrier #:5KMoreland HallReference Dwg:2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Toilet Transfer - Floor-mounted 2010 ADAS 604.8.1.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Toilet Transfer - Floor-mounted 2010 ADAS 604.8.1.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Toilet Transfer - Floor-mounted 2010 ADAS 604.8.1.1 ndard: No Quantity: SF As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Toilet Transfer - Floor-mounted 2010 ADAS 604.8.1.1 ndard: No Quantity: SF As-built: 0 Min. 60" wide x 59" deep clear floor space not provided at floor-mounted fixture
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Toilet Transfer - Floor-mounted 2010 ADAS 604.8.1.1 ndard: No Quantity: SF As-built: 0 Min. 60" wide x 59" deep clear floor space not provided at floor-mounted fixture 36-1/2" wide x 54-1/4" deep
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Toilet Transfer - Floor-mounted 2010 ADAS 604.8.1.1 ndard: No Quantity: SF As-built: 0 Min. 60" wide x 59" deep clear floor space not provided at floor-mounted fixture 36-1/2" wide x 54-1/4" deep Remodel to provide front transfer space 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 5L
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Grab Bars
Code References:	2010 ADAS 604.5
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	No grab bars provided at water closet
Findings:	No grab bars provided
Rec. Solution:	Provide side and rear grab bars with reinforcement
Barrier Severity:	1 Necessary Cost Est \$900.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 5M
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Seat Height
Code References:	2010 ADAS 604.4
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Water closet seat not between 17" to 19" high
Findings:	16-3/4" high
Rec. Solution:	Replace water closet
Barrier Severity:	2 Recommended Cost Est \$850.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 5N
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Centerline
Code References:	2010 ADAS 604.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Water closet centerline not between 16" and 18" O. C.
Findings:	19-1/2" on center
Rec. Solution:	Relocate water closet
Barrier Severity:	3 Hindrance Cost Est \$850.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 50
Bldg Name:	2/1/2017 Report Date 3/23/2017 Barrier #: 50 Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Seat Cover Dispenser 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Seat Cover Dispenser 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Seat Cover Dispenser 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Seat Cover Dispenser 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 1 Seat cover dispenser not located on an accessible route. Blocked by water closet
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Restrooms Seat Cover Dispenser 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 1 Seat cover dispenser not located on an accessible route. Blocked by water closet Access to dispenser blocked by water closet
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A P Coordinate: N/A Restrooms Seat Cover Dispenser 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 1 Seat cover dispenser not located on an accessible route. Blocked by water closet Access to dispenser blocked by water closet Replace or remount dispenser on an accessible route with clear floor space 2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 5P
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Water closet blocks shelves clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 5Q
	1 0/15/151
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	
_	Moreland Hall Reference Dwg: 2 of 5
Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B
Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Shelves 2010 ADAS 603.4
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Shelves 2010 ADAS 603.4
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Shelves 2010 ADAS 603.4 ndard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Shelves 2010 ADAS 603.4 ndard: No Quantity: EACH As-built: 1 Shelf provided not mounted between 40" and 48" above floor or ground
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Shelves 2010 ADAS 603.4 ndard: No Quantity: EACH As-built: 1 Shelf provided not mounted between 40" and 48" above floor or ground 68-1/4" high
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Provided not mounted between 40" and 48" above floor or ground Provide additional shelf at accessible height Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Provided N/A Restrooms Shelves 2010 ADAS 603.4 Shelf provided not mounted between 40" and 48" above floor or ground Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 5R
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Men's Restroom 148B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: SF As-built: 1
Barrier Description:	Object protrudes more than 4" into pedestrian way
Findings:	Shelf protrudes 7-1/2" at 67-1/2" high
Rec. Solution:	Alter area to remove object
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 5S
Field Date: Bldg Name:	2/1/2017 Report Date 3/23/2017 Barrier #: 5S Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Alarm - Horn/Strobe 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Alarm - Horn/Strobe 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Alarm - Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Alarm - Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 Where a fire alarm is installed, no horn/strobe provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Alarm - Horn/Strobe 2010 ADAS 702.1 mdard: No Quantity: EACH As-built: 1 Where a fire alarm is installed, no horn/strobe provided No device provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Men's Restroom 148B N/A Y Coordinate: N/A Restrooms Alarm - Horn/Strobe 2010 ADAS 702.1 where a fire alarm is installed, no horn/strobe provided No device provided Provide horn/stobe in sanitary facility 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6A
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door Closer - Interior Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	10 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6B
Field Date: Bldg Name:	2/1/2017 Report Date 3/23/2017 Barrier #: 6B Gamma Gam
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0101
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0101 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0101 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0101 N/A Y Coordinate: N/A Corridors Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0101 N/A Y Coordinate: N/A Corridors Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0101 N/A Y Coordinate: N/A Corridors Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0101 N/A Corridors Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0101 N/A Y Coordinate: N/A Corridors Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame 2 second sweep
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0101 N/A Y Coordinate: N/A Corridors Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame 2 second sweep Replace or adjust existing closer 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6C
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door - Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Door knob not accessible
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
I	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6D
Field Date: Bldg Name:	2/1/2017 Report Date 3/23/2017 Barrier #: 6D Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0101
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0101 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0101 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0101 N/A Y Coordinate: N/A Corridors Vision Lights in Doors 2010 ADAS 404.2.11
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0101 N/A Y Coordinate: N/A Corridors Vision Lights in Doors 2010 ADAS 404.2.11
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0101 N/A Y Coordinate: N/A Corridors Vision Lights in Doors 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0101 N/A Y Coordinate: N/A Corridors Vision Lights in Doors 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1 Doors or gates with view panels or side lights adjacent to doors not max. 43" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0101 N/A Corridors Vision Lights in Doors 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1 Doors or gates with view panels or side lights adjacent to doors not max. 43" high 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0101 N/A Y Coordinate: N/A Corridors Vision Lights in Doors 2010 ADAS 404.2.11 Doors or gates with view panels or side lights adjacent to doors not max. 43" high Replace door or vision panel in door 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6E
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Sign - Permanent Room/Space
Code References:	2010 ADAS 703.1
Performance Sta	ndard: No Quantity: EACH As-built : 5
Barrier Description:	No sign with raised characters and Braille at permanent room or space with visual sign
Findings:	No tactile info on signs with visual information
Rec. Solution:	Provide signs at latch side of entry door, where possible
Barrier Severity:	1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Rooms 1	32, 134, 138, 136, 136A
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6F
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101 COGNITION AND ACTION IN
X Coordinate:	N/A Y Coordinate: N/A REAL & VIRTUAL ENVIRONMENTS
Barrier Area:	Corridors (CARVE) LAB
Barrier Type:	Sign - Braille Multi-lined
Code References:	2010 ADAS .2.3.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Braille not placed below all multi-lined tactile characters in one line together
Findings:	Existing sign not accessible
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	
Notes: Room 14	40



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6G
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Panel protrudes 4-1/2" at 43-3/4" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6H
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - Wheelchair Use
Code References:	2010 ADAS 305
Performance Sta	andard: No Quantity: SF As-built : 0
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Pencil sharpener clear floor space located on ramp
Rec. Solution:	Relocate control or mechanism
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 61
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Pencil sharpener 59" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6J
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Pencil sharpener protrudes 4-1/2" at 53" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6K
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Ramps
Barrier Type:	Abrupt Change in Level
Code References:	2010 ADAS 303.3
Performance Sta	ndard: No Quantity: LF As-built : 8
Barrier Description:	Change in level greater than 1/2"
Findings:	1" lip in ramp surface at bottom transition
Rec. Solution:	Repair to remove trip hazard
Barrier Severity:	1 Necessary Cost Est \$2,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6L
	The second of th
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0101
_	
Location:	Floor 1 - Hall H0101
Location: X Coordinate:	Floor 1 - Hall H0101 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 1 - Hall H0101 N/A Y Coordinate: N/A Ramps
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 1 - Hall H0101 N/A Y Coordinate: N/A Ramps Running Slope - Existing (9.0% - 9.4%) 2010 ADAS 405.3
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 1 - Hall H0101 N/A Y Coordinate: N/A Ramps Running Slope - Existing (9.0% - 9.4%) 2010 ADAS 405.3
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 1 - Hall H0101 N/A Y Coordinate: N/A Ramps Running Slope - Existing (9.0% - 9.4%) 2010 ADAS 405.3 Indard: No Quantity: LF As-built: 4
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 1 - Hall H0101 N/A Y Coordinate: N/A Ramps Running Slope - Existing (9.0% - 9.4%) 2010 ADAS 405.3 ndard: No Quantity: LF As-built: 4 Running slope exceeds 8.33% (9.0% - 9.4%)
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - Hall H0101 N/A Y Coordinate: N/A Ramps Running Slope - Existing (9.0% - 9.4%) 2010 ADAS 405.3 Indard: No Quantity: LF As-built: 4 Running slope exceeds 8.33% (9.0% - 9.4%) 9.3% running slope Demolish existing and construct new ramp
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 1 - Hall H0101 N/A Y Coordinate: N/A Ramps Running Slope - Existing (9.0% - 9.4%) 2010 ADAS 405.3 ndard: No Quantity: LF As-built: 4 Running slope exceeds 8.33% (9.0% - 9.4%) 9.3% running slope Demolish existing and construct new ramp 2 Recommended Cost Est \$800.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6M
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Ramps
Barrier Type:	Handrail
Code References:	2010 ADAS 505.2
Performance Sta	ndard: No Quantity: LF As-built : 5
Barrier Description:	No handrail provided at both sides
Findings:	Ramp lacks handrail at both sides
Rec. Solution:	Replace handrails at both sides of ramp
Barrier Severity:	1 Necessary Cost Est \$1,125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6N
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101
Location: X Coordinate:	Floor 1 - Hall H0101 N/A Y Coordinate: N/A N/A Y Coordinate: N/A N/A
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Alarms
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Y Coordinate: N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2 ndard: No Quantity: JOB As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2 ndard: No Quantity: JOB As-built: 1 Fire extinguisher protrudes into circulation path more than 4" between 27" and 80"
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2 ndard: No Quantity: JOB As-built: 1 Fire extinguisher protrudes into circulation path more than 4" between 27" and 80" Fire extinguisher protrudes 4-3/4" at 32-3/4" high
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Y Coordinate: N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2 Indard: No Quantity: JOB As-built: 1 Fire extinguisher protrudes into circulation path more than 4" between 27" and 80" Fire extinguisher protrudes 4-3/4" at 32-3/4" high Remount extinguisher with leading edge below 27" or provide detectable warning 4 Low Severity Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 60
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Thermostat 56" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6P
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Door closer protrudes 12" at 77" high
	Book dieser productes 12 de // mgm
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Rec. Solution: Barrier Severity:	
	Remove object or provide detectable warning (wing walls) 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6Q
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Sign - Tactile Exit Sign at Door
Code References:	2010 ADAS 216.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Ground floor doors that exit directly to the exterior lacks tactile exit sign
Findings:	No sign provided
Rec. Solution:	Provide new sign stating "EXIT" at exiting side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6R
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door Closer - Exterior Adjustment
Code References:	Performance Standard
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 8.5 lbf
Findings:	16 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6S
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door Closer - Exterior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	3 second sweep
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6T
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	11" strike edge clearance and recessed 7-1/2" deep
Rec. Solution:	Relocate door or gate to provide maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6U
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Recessed Door - Min. 18" at Pull Side
Code References:	2010 ADAS Figure 404.2.4.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door in alcove deeper than 8" does not have min. 18" strike edge clearance
Findings:	Recessed 9"
Rec. Solution:	Redesign door to provide strike edge clearance
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6V
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door Mat
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Recessed doormat not anchored to floor (possible trip hazard)
Findings:	Doormat not secured
Rec. Solution:	Replace door mat
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 6W
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Horn/Strobe Device
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn or strobe in corridor where fire alarm exists in building
Findings:	No horn/strobe provided
Rec. Solution:	Provide horn/strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 7A
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - No Braille/tactile Sign
Code References:	2010 ADAS 703.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No Braille/tactile sign at latch side of door
Findings:	No tactile sign
Rec. Solution:	Provide Braille/tactile sign at latch side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 7B
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - ISA at Accessible Restroom
Code References:	2010 ADAS 216.8
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No ISA symbol on wall sign posted at accessible toilet room
Findings:	ISA sign on door 1-1/2" high. Not visible from a distance
Rec. Solution:	Provide ISA symbol on restroom wall sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 7C
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	14 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 7D
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	3 second sweep
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 7E
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 7E Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side 7" strike edge clearance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side 7" strike edge clearance Provide automatic door opening device 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 7F
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Electrical Switches
Code References:	2010 ADAS 205.1 & 309.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 7G
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 7G Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Coat Hook 2010 ADAS 603.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Coat Hook 2010 ADAS 603.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Coat Hook 2010 ADAS 603.4 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Coat Hook 2010 ADAS 603.4 ndard: No Quantity: EACH As-built: 1 Clothing hooks not max. 48" high AFF
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Coat Hook 2010 ADAS 603.4 Indard: No Quantity: EACH As-built: 1 Clothing hooks not max. 48" high AFF 64" high on door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Coat Hook 2010 ADAS 603.4 Clothing hooks not max. 48" high AFF 64" high on door Provide additional hook in accessible location 2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 7H
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding dispenser creates protruding object in path of travel
Findings:	Paper towel dispenser protrudes 10" at 37-1/2" high
Rec. Solution:	Relocate dispenser or provide cane-detectable warning
Barrier Severity:	2 Recommended Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 7I
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 7I Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Lavatory - Clear Floor Space 2010 ADAS 606.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Lavatory - Clear Floor Space 2010 ADAS 606.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Lavatory - Clear Floor Space 2010 ADAS 606.2 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Lavatory - Clear Floor Space 2010 ADAS 606.2 ndard: No Quantity: JOB As-built: 1 No clear floor space 30" x 48" at lavatory to allow forward approach
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Restrooms Lavatory - Clear Floor Space 2010 ADAS 606.2 ndard: No Quantity: JOB As-built: 1 No clear floor space 30" x 48" at lavatory to allow forward approach Paper towel dispenser blocks lavatory clear floor space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Lavatory - Clear Floor Space 2010 ADAS 606.2 ndard: No Quantity: JOB As-built: 1 No clear floor space 30" x 48" at lavatory to allow forward approach Paper towel dispenser blocks lavatory clear floor space Relocate dispenser 1 Necessary Cost Est \$375.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 7J
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Knee Clearance
Code References:	2010 ADAS 606.2 & 306
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Lavatory bottom apron/edge not at least 27" high
Findings:	25-1/2" high knee clearance
Rec. Solution:	Provide min. 1 accessible lavatory
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 7K
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 7K Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 ndard: No Quantity: EACH As-built: 1 Hot water and drainpipes accessible under lavatory not insulated or covered
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 ndard: No Quantity: EACH As-built: 1 Hot water and drainpipes accessible under lavatory not insulated or covered No insulation provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 Indard: No Quantity: EACH As-built: 1 Hot water and drainpipes accessible under lavatory not insulated or covered No insulation provided Insulate drainpipes and hot water pipes 2 Recommended Cost Est \$220.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 7L
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Transfer - Wall-mounted
Code References:	2010 ADAS 604.8.1.1
Performance Sta	ndard: No Quantity: SF As-built : 0
Barrier Description:	Min. 60" wide x 56" deep clear floor space not provided at wall-mounted fixture
Findings:	55-1/4" from back wall to lavatory
Rec. Solution:	No remediation recommended. Front and side transfer space is provided
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
P	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 7M
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 7M Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Toilet - Rear Grab Bar 2010 ADAS 604.5.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Toilet - Rear Grab Bar 2010 ADAS 604.5.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Toilet - Rear Grab Bar 2010 ADAS 604.5.2 ndard: No Quantity: JOB As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Toilet - Rear Grab Bar 2010 ADAS 604.5.2 ndard: No Quantity: JOB As-built: 0 Rear grab bar not centered 12" from wall and 24" on the other side of WC
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Restrooms Toilet - Rear Grab Bar 2010 ADAS 604.5.2 ndard: No Quantity: JOB As-built: 0 Rear grab bar not centered 12" from wall and 24" on the other side of WC 22" on center
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A PRESTROOMS Toilet - Rear Grab Bar 2010 ADAS 604.5.2 Rear grab bar not centered 12" from wall and 24" on the other side of WC 22" on center No remediation recommended. Space constraints exist 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 7N
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Side Grab Bar
Code References:	2010 ADAS 604.5.1
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Side grab bar does not extend min. 54" from rear wall
Findings:	50" from rear wall
Rec. Solution:	No remediation recommended. Space constraints exist
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 70
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 70 Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Toilet Centerline 2010 ADAS 604.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Toilet Centerline 2010 ADAS 604.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Toilet Centerline 2010 ADAS 604.2 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Toilet Centerline 2010 ADAS 604.2 Indard: No Quantity: JOB As-built: 1 Water closet centerline not between 16" and 18" O. C.
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Toilet Centerline 2010 ADAS 604.2 mdard: No Quantity: JOB As-built: 1 Water closet centerline not between 16" and 18" O. C. 24" on center Relocate water closet
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 146 N/A Y Coordinate: N/A Restrooms Toilet Centerline 2010 ADAS 604.2 Indard: No Quantity: JOB As-built: 1 Water closet centerline not between 16" and 18" O. C. 24" on center Relocate water closet 3 Hindrance Cost Est \$850.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 7P
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Paper Dispenser
Code References:	2010 ADAS 604.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Toilet tissue dispenser not within 7" to 9" from front edge of toilet
Findings:	13-1/2" from rim
Rec. Solution:	Reposition or replace toilet paper dispenser
Barrier Severity:	3 Hindrance Cost Est \$225.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 7Q
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Wall mounted object (dispensers) protrudes more than 4" from wall
Findings:	Panel protrudes 4-7/8" at 52" high
Rec. Solution:	Relocate dispenser or provide cane-detectable warning
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 7R
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/stobe in sanitary facility
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 8A
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Vestibule V0130
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Area: Barrier Type:	Signage Permanent Room/Space - Tactile Characters
Barrier Type: Code	Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Barrier Type: Code References:	Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Barrier Type: Code References: Performance Sta Barrier	Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 2
Barrier Type: Code References: Performance Sta Barrier Description:	Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 2 No tactile characters at sign identifying permanent rooms and spaces with visual signs
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 2 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at doors within public route
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 2 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at doors within public route Provide accessible signs 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 8B
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Vestibule V0130
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 8C
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 8C Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Vestibule V0130
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Vestibule V0130 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Vestibule V0130 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Vestibule V0130 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Vestibule V0130 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Vestibule V0130 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Vestibule V0130 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Vestibule V0130 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground 47-1/2" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Vestibule V0130 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground 47-1/2" high Replace door/gate or vision panel 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 8D
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Vestibule V0130
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Kickplate
Code References:	2010 ADAS 404.2.10
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate lacks min. 10" smooth uninterrupted bottom surface
Findings:	9-1/2" high bottom panel
Rec. Solution:	Provide smooth kick plate min. 10" high at push side of door
Barrier Severity:	1 Necessary Cost Est \$225.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 8E
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 8E Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Vestibule V0130
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Vestibule V0130 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Vestibule V0130 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Vestibule V0130 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Vestibule V0130 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Vestibule V0130 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Vestibule V0130 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 1 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Vestibule V0130 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 1 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side 3-1/4" strike edge clearance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Vestibule V0130 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 1 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side 3-1/4" strike edge clearance Relocate door or gate to provide maneuvering clearance or leave door open at all times 1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 8F
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Vestibule V0130
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Corridor
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	No horn/strobes in corridor
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 9A
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Classroom 130B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 9B
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Classroom 130B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 9C
Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 9C Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Classroom 130B
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Classroom 130B N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Control or mechanism not at min. 15" or max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Control or mechanism not at min. 15" or max. 48" high Emergency phone 50" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Control or mechanism not at min. 15" or max. 48" high Emergency phone 50" high Relocate control or mechanism to min. 15" or max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 9D
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Classroom 130B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Protruding Object - Wall-mounted
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Wall mounted object protrudes more than 4" from wall
Findings:	Emergency phone protrudes 5" at 46" high
Rec. Solution:	Remove object or provide detectable warning for the visually impaired
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 9E
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Classroom 130B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Projector Screen Pull
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Screen pull not at max. 48" high for side reach
Findings:	Projector screen pull 63" high
-	Trojector screen pair 65 Tright
Rec. Solution:	Relocate to max. 48" high or provide extension
Rec. Solution: Barrier Severity:	Relocate to max. 48" high or provide extension
	Relocate to max. 48" high or provide extension 3 Hindrance Cost Est \$75.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 9F
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Classroom 130B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Podium - Surface Height
Code References:	2010 ADAS 504.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Surface height exceeds 34" high
Findings:	37" surface height but may be adjustible
Rec. Solution:	Provide min. 1 accessible podium
Barrier Severity:	4 Low Severity Cost Est \$1,275.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 9G
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 9G Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Classroom 130B
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Classroom 130B N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2 ndard: No Quantity: EACH As-built: 1 Podium knee clearance not min. 27" high, 19" deep or 30" wide
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2 ndard: No Quantity: EACH As-built: 1 Podium knee clearance not min. 27" high, 19" deep or 30" wide 29" wide knee clearance between supports. Reduced to 26" by stored item
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2 ndard: No Quantity: EACH As-built: 1 Podium knee clearance not min. 27" high, 19" deep or 30" wide 29" wide knee clearance between supports. Reduced to 26" by stored item Provide min. 1 accessible podium Provide min. 1 accessible podium A Low Severity Cost Est \$1,275.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 9H
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Classroom 130B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Electrical Outlets - Forward Reach Obstructed (10"-25")
Code References:	2010 ADAS 306.3.2
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	Outlet located over an 10" to 25" obstruction max. 34" high located above 44"
Findings:	29" deep and 34" high at accessible workstation
Rec. Solution:	Relocate control or mechanism to max. 44" high
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 9
Plda Namo	
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Classroom 130B
Location:	
Location:	Floor 1 - Classroom 130B
Location: X Coordinate:	Floor 1 - Classroom 130B N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms Alarm - No Horn/Strobe 2010 ADAS 702.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms Alarm - No Horn/Strobe 2010 ADAS 702.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms Alarm - No Horn/Strobe 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms Alarm - No Horn/Strobe 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1 Where a fire alarm is installed, no horn/strobe provided
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms Alarm - No Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 Where a fire alarm is installed, no horn/strobe provided No device provided
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 1 - Classroom 130B N/A Y Coordinate: N/A Classrooms Alarm - No Horn/Strobe 2010 ADAS 702.1 mdard: No Quantity: EACH As-built: 1 Where a fire alarm is installed, no horn/strobe provided No device provided Provide horn/stobe 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 10A
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Sign - Permanent Room/Space
Code References:	2010 ADAS 703.1
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	No sign with raised characters and Braille at permanent room or space with visual sign
Findings:	No tactile info on signs with visual information
Rec. Solution:	Provide signs at latch side of entry door, where possible
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Overhea	nd "Elevator" signage and Room 102
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 10B
Field Date: Bldg Name:	2/1/2017 Report Date 3/23/2017 Barrier #: 10B Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Lobby L0102
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Corridors Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Corridors Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Corridors Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Corridors Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Corridors Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 9 lbf and 5" strike edge clearance at corridor side of door Provide automatic door opening device
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Corridors Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 9 lbf and 5" strike edge clearance at corridor side of door Provide automatic door opening device 1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 10C
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	2 second sweep and 5" strike edge clearance at corridor side of door
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 10D
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
_	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Lobby L0102
Bldg Name: Location: X Coordinate:	
Location:	Floor 1 - Lobby L0102
Location: X Coordinate:	Floor 1 - Lobby L0102 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Doors or Gates
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 Indard: No Quantity: EACH As-built: 0
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 andard: No Quantity: EACH As-built: 0 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 Indard: No Quantity: EACH As-built: 0 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer 5" strike edge clearance Provide automatic door opening device
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 mdard: No Quantity: EACH As-built: 0 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer 5" strike edge clearance Provide automatic door opening device 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 10E
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door - Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Door knob not accessible
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 10F
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	50-3/4" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	implementation hasel



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 10G
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	51-1/4" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 10H
Field Date: Bldg Name:	2/1/2017 Report Date 3/23/2017 Barrier #: 10H Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Lobby L0102
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Corridors Clear Floor Space - Stored Items 2010 ADAS 306.3.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Corridors Clear Floor Space - Stored Items 2010 ADAS 306.3.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Corridors Clear Floor Space - Stored Items 2010 ADAS 306.3.2 Indard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Corridors Clear Floor Space - Stored Items 2010 ADAS 306.3.2 Indard: No Quantity: JOB As-built: 1 Clear floor space of min. 30" by 48" not provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Corridors Clear Floor Space - Stored Items 2010 ADAS 306.3.2 Indard: No Quantity: JOB As-built: 1 Clear floor space of min. 30" by 48" not provided Bench blocks flyer clear floor space Move stored items at side of bench where people who use wheelchairs can rest
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Corridors Clear Floor Space - Stored Items 2010 ADAS 306.3.2 Indard: No Quantity: JOB As-built: 1 Clear floor space of min. 30" by 48" not provided Bench blocks flyer clear floor space Move stored items at side of bench where people who use wheelchairs can rest 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 10I
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Flyer box 50" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 10J
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Pencil sharpener 49" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 10K
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Pencil Sharpener protrudes 5-3/4" at 47" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 10L
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
D	Corridors
Barrier Type:	Protruding Object
Code References:	
Code	Protruding Object 2010 ADAS 307
Code References:	Protruding Object 2010 ADAS 307
Code References: Performance Sta Barrier	Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1
Code References: Performance Sta Barrier Description:	Protruding Object 2010 ADAS 307 ndard: No Quantity: EACH As-built: 1 Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Code References: Performance Sta Barrier Description: Findings:	Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in in circulation path protrudes more than 4" between 27" and 80" high Panel protrudes 4-1/2" at 44-1/2" high Remove object or provide detectable warning (wing walls)
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in in circulation path protrudes more than 4" between 27" and 80" high Panel protrudes 4-1/2" at 44-1/2" high Remove object or provide detectable warning (wing walls) 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 10M
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Extinguisher - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Fire extinguisher protrudes into circulation path more than 4" between 27" and 80"
Findings:	Fire extinguisher protrudes 4-1/2" at 28" high
Rec. Solution:	Remount extinguisher with leading edge below 27" or provide detectable warning
Barrier Severity:	4 Low Severity Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 11A
Field Date: Bldg Name:	2/1/2017 Report Date 3/23/2017 Barrier #: 11A Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators Hall Call Buttons 2010 ADAS 407.4.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators Hall Call Buttons 2010 ADAS 407.4.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators Hall Call Buttons 2010 ADAS 407.4.5 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators Hall Call Buttons 2010 ADAS 407.4.5 ndard: No Quantity: EACH As-built: 1 Hall call buttons not internally illuminated with a white light over the entire button surface
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators Hall Call Buttons 2010 ADAS 407.4.5 Indard: No Quantity: EACH As-built: 1 Hall call buttons not internally illuminated with a white light over the entire button surface Hall call illuminated with a faint red light
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators Hall Call Buttons 2010 ADAS 407.4.5 Hall call buttons not internally illuminated with a white light over the entire button surface Hall call illuminated with a faint red light Replace hall call buttons 1 Necessary Cost Est \$3,500.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 11B
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Elevator E0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Doorjamb marking - Raised Star
Code References:	2010 ADAS 407.2.3.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Elevator landing door jamb signage at grade level lacks a raised five pointed star
Findings:	No raised star
Rec. Solution:	Replace door jamb signage
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 11C
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Elevator E0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Hall lanterns - Visible at Entry
Code References:	2010 ADAS 407.2.2.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Visual and audible signals not provided at each hoistway entrance to answer calls
Findings:	Hall lanterns not visible from outer side of elevator
Rec. Solution:	Provide hall lanterns visible from outer side of elevator
Barrier Severity:	1 Necessary Cost Est \$3,675.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 11D
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Elevator E0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Hall lanterns - Dimensions
Code References:	2010 ADAS 407.2.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Visual signal for each direction not min. 2-½" high by 2-½" wide
Findings:	1" high by 1" wide
Rec. Solution:	Replace hall lanterns
Barrier Severity:	3 Hindrance Cost Est \$3,675.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
-	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 11E
Field Date: Bldg Name:	2/1/2017 Report Date 3/23/2017 Barrier #: 11E
Bldg Name:	
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators Reopening Device 2010 ADAS 407.3.3.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators Reopening Device 2010 ADAS 407.3.3.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators Reopening Device 2010 ADAS 407.3.3.3 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators Reopening Device 2010 ADAS 407.3.3.3 ndard: No Quantity: JOB As-built: 1 Door-reopening devices does not remain effective for at least 20 seconds
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators Reopening Device 2010 ADAS 407.3.3.3 ndard: No Quantity: JOB As-built: 1 Door-reopening devices does not remain effective for at least 20 seconds 6 seconds
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators Reopening Device 2010 ADAS 407.3.3.3 ndard: No Quantity: JOB As-built: 1 Door-reopening devices does not remain effective for at least 20 seconds 6 seconds Repair or adjust reopening device 1 Necessary Cost Est \$3,500.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 11F
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Elevator E0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Car Control Panel - Button Order
Code References:	2010 ADAS 407.4.6.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Buttons not arranged with numbers in ascending order
Findings:	Buttons not arranged in ascending order
Rec. Solution:	Replace car controls
Barrier Severity:	2 Recommended Cost Est \$2,750.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 11G
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Elevator E0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	
	Emergency Controls - Location
Code References:	Emergency Controls - Location 2010 ADAS 407.4.6.4.1
	2010 ADAS 407.4.6.4.1
References:	2010 ADAS 407.4.6.4.1
References: Performance Sta Barrier	2010 ADAS 407.4.6.4.1 ndard: No Quantity: JOB As-built : 1
References: Performance Sta Barrier Description:	2010 ADAS 407.4.6.4.1 ndard: No Quantity: JOB As-built: 1 Emergency controls (incl. emergency stop and alarm) not grouped at the bottom of the panel
References: Performance Sta Barrier Description: Findings:	2010 ADAS 407.4.6.4.1 ndard: No Quantity: JOB As-built: 1 Emergency controls (incl. emergency stop and alarm) not grouped at the bottom of the panel Controls not grouped
References: Performance Sta Barrier Description: Findings: Rec. Solution:	ndard: No Quantity: JOB As-built: 1 Emergency controls (incl. emergency stop and alarm) not grouped at the bottom of the panel Controls not grouped Replace emergency controls 1 Necessary Cost Est \$3,500.00 Facility Function: Public Status: Open



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 11H
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Elevator E0101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Car Dimensions - Existing
Code References:	2010 ADAS 206.6
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Elevator with center-opening doors lacks clear distance between walls of min. 80" x 54"
Findings:	62" wide x 51" deep
Rec. Solution:	No remediation recommended. Existing car can accommodate people using wheelchairs
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 11I
Field Date: Bldg Name:	2/1/2017 Report Date 3/23/2017 Barrier #: 11I Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators Handrails - Height Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators Handrails - Height Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators Handrails - Height Performance Standard ndard: Yes Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators Handrails - Height Performance Standard ndard: Yes Quantity: EACH As-built: 1 Handrail not at 32" (± 1 inch) high from the floor to reduce interference with buttons
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators Handrails - Height Performance Standard ndard: Yes Quantity: EACH As-built: 1 Handrail not at 32" (± 1 inch) high from the floor to reduce interference with buttons 31" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Elevator E0101 N/A Y Coordinate: N/A Elevators Handrails - Height Performance Standard ndard: Yes Quantity: EACH As-built: 1 Handrail not at 32" (± 1 inch) high from the floor to reduce interference with buttons 31" high Replace existing handrail 2 Recommended Cost Est \$1,200.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 12A
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 126
	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 12B
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 126
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	8 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 12C
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 126
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	2 second sweep
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 12D
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 126
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Doors or Gates
Barrier Area:	Doors or Gates
Barrier Area: Barrier Type: Code	Doors or Gates Recessed Door - Min. 12" at Push Side 2010 ADAS Figure 404.2.4.3
Barrier Area: Barrier Type: Code References:	Doors or Gates Recessed Door - Min. 12" at Push Side 2010 ADAS Figure 404.2.4.3
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Doors or Gates Recessed Door - Min. 12" at Push Side 2010 ADAS Figure 404.2.4.3 Indard: No Quantity: EACH As-built: 0
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Doors or Gates Recessed Door - Min. 12" at Push Side 2010 ADAS Figure 404.2.4.3 ndard: No Quantity: EACH As-built: 0 Door in alcove deeper than 8" does not have min. 12" strike edge clearance
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Doors or Gates Recessed Door - Min. 12" at Push Side 2010 ADAS Figure 404.2.4.3 Indard: No Quantity: EACH As-built: 0 Door in alcove deeper than 8" does not have min. 12" strike edge clearance Recessed 8-1/2" Provide automatic door opening device
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Doors or Gates Recessed Door - Min. 12" at Push Side 2010 ADAS Figure 404.2.4.3 ndard: No Quantity: EACH As-built: 0 Door in alcove deeper than 8" does not have min. 12" strike edge clearance Recessed 8-1/2" Provide automatic door opening device 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 12E
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 126
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 60" - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at with min. 18" at pull side lacks min. 60" perpendicular to door
Findings:	Trash bin blocks strike edge clearance
Rec. Solution:	Remove stored item
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 12F
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 126
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 0
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Trash bin blocks electrical switch clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 12G
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 126
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	58" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 12H
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 126
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Shelves or Cabinets
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Performance Sta Barrier Description:	ndard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground
Barrier	
Barrier Description:	Shelf or cabinet not mounted max. 48" above floor or ground
Barrier Description: Findings:	Shelf or cabinet not mounted max. 48" above floor or ground Shelf or cabinet not accessible
Barrier Description: Findings: Rec. Solution:	Shelf or cabinet not mounted max. 48" above floor or ground Shelf or cabinet not accessible Provide additional shelf at accessible height or provide assistance 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 12I
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 126
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	63" high
Rec. Solution:	Provide additional hook in accessible location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 12J
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 126
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Cords in Accessible Route
Code References:	2010 ADAS 303.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Change in level greater than 1/2" in clear floor space at cords
Findings:	Cords create trip hazard
Rec. Solution:	Provide accessible cord cover or otherwise remove barrier to access
Barrier Severity:	
	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 12K
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 126
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Refrigerator and shelf clear floor space not provided
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 12L
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistance Office 126
_	
Location:	Floor 1 - Grad Teaching Assistance Office 126
Location: X Coordinate:	Floor 1 - Grad Teaching Assistance Office 126 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 1 - Grad Teaching Assistance Office 126 N/A Y Coordinate: N/A Counters and Tables
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 1 - Grad Teaching Assistance Office 126 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 1 - Grad Teaching Assistance Office 126 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 1 - Grad Teaching Assistance Office 126 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 1 - Grad Teaching Assistance Office 126 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: Knee clearance not min. 27" high, 19" deep or 30" wide
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - Grad Teaching Assistance Office 126 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide 24-7/8" high and 22" wide knee clearance
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 1 - Grad Teaching Assistance Office 126 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide 24-7/8" high and 22" wide knee clearance Provide min. 1 accessible table. Avoid pedestal base tables. 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 12M
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 126
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 13A
Field Date: Bldg Name:	2/2/2017 Report Date 3/23/2017 Barrier #: 13A Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 ndard: No Quantity: EACH As-built: 1 No sign with raised characters and Braille at permanent room or space with visual sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 ndard: No Quantity: EACH As-built: 1 No sign with raised characters and Braille at permanent room or space with visual sign No tactile info on sign with visual information
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 No sign with raised characters and Braille at permanent room or space with visual sign No tactile info on sign with visual information Provide sign at latch side of entry door, where possible 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 13B
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No strobe provided in corridor where horn is provided where fire alarm exists in building
Findings:	No strobe where horn is provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 13C
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Sign - Tactile Exit Sign at Door
Code References:	2010 ADAS 216.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Ground floor doors that exit directly to the exterior lacks tactile exit sign
Findings:	Accessible sign not provided
Rec. Solution:	Provide new sign stating "EXIT" at exiting side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 13D
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door Closer - Exterior Adjustment
Code References:	Performance Standard
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 8.5 lbf
Findings:	16 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 13E
Field Date: Bldg Name:	2/2/2017Report Date3/23/2017Barrier #:13EMoreland HallReference Dwg:2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Corridors Door Closer - Exterior Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Corridors Door Closer - Exterior Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Corridors Door Closer - Exterior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Corridors Door Closer - Exterior Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Corridors Door Closer - Exterior Sweep Period 2010 ADAS 404.2.8.1 mdard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period 3 second sweep Replace or adjust existing closer
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Corridors Door Closer - Exterior Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period 3 second sweep Replace or adjust existing closer 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 13F
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door - Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Door knob not accessible
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 13G
Field Date: Bldg Name:	2/2/2017 Report Date 3/23/2017 Barrier #: 13G Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Corridors Recessed Door - Min. 12" at Push Side 2010 ADAS Figure 404.2.4.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Corridors Recessed Door - Min. 12" at Push Side 2010 ADAS Figure 404.2.4.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Corridors Recessed Door - Min. 12" at Push Side 2010 ADAS Figure 404.2.4.3 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Corridors Recessed Door - Min. 12" at Push Side 2010 ADAS Figure 404.2.4.3 ndard: No Quantity: EACH As-built: 0 Door in alcove deeper than 8" does not have min. 12" strike edge clearance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Corridors Recessed Door - Min. 12" at Push Side 2010 ADAS Figure 404.2.4.3 ndard: No Quantity: EACH As-built: 0 Door in alcove deeper than 8" does not have min. 12" strike edge clearance Recessed 10" and no strike edge clearance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Corridors Recessed Door - Min. 12" at Push Side 2010 ADAS Figure 404.2.4.3 ndard: No Quantity: EACH As-built: 0 Door in alcove deeper than 8" does not have min. 12" strike edge clearance Recessed 10" and no strike edge clearance No remediation recommended. Door is not part of an accessible route. 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 13H
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Headroom - Existing
Code References:	2010 ADAS 404.2.3
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate clearance not min. 80" high
Findings:	79" high
Rec. Solution:	No remediation recommended. Door is not part of an accessible route.
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 13I
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door Mat
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	Recessed doormat not anchored to floor (possible trip hazard)
Findings:	Door mats not secured
Rec. Solution:	Replace door mats
Barrier Severity:	1 Necessary Cost Est \$1,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 13J
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door Threshold - >1/2"
Code References:	2010 ADAS 404.2.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate threshold exceeds 1/2" in height
Findings:	1-1/2" high
Rec. Solution:	Provide new door threshold
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 13K
Field Date: Bldg Name:	2/2/2017 Report Date 3/23/2017 Barrier #: 13K Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 Indard: No Quantity: SF As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Poors or Gates Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 Indard: No Quantity: SF As-built: 0 Door or gate lacks landing on both sides of door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 Indard: No Quantity: SF As-built: 0 Door or gate lacks landing on both sides of door Door landing is deteriorated due to water accumulation No remediation recommended. Door is not part of an accessible route.
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Hall H0102 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 Indard: No Quantity: SF As-built: 0 Door or gate lacks landing on both sides of door Door landing is deteriorated due to water accumulation No remediation recommended. Door is not part of an accessible route. 4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 13L
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Hall H0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 60" - Relocate Door
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at with min. 18" at pull side lacks min. 60" perpendicular to door
Findings:	30" perpendicular to wall
Rec. Solution:	No remediation recommended. Door is not part of an accessible route.
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 14A
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 122
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	
Notes:	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 14B
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 122
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 14C
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 122
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code	in one Appy push 12 See
References:	2010 ADAS Figure 404.2.4.1
	2010 ADAS Figure 404.2.4.1
References:	2010 ADAS Figure 404.2.4.1
References: Performance Sta Barrier	2010 ADAS Figure 404.2.4.1 Indard: No Quantity: EACH As-built: 1
References: Performance Sta Barrier Description:	2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 1 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
References: Performance Sta Barrier Description: Findings:	2010 ADAS Figure 404.2.4.1 Indard: No Quantity: EACH As-built: 1 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer 10-1/2" strike edge clearance
References: Performance Sta Barrier Description: Findings: Rec. Solution:	ndard: No Quantity: EACH As-built: 1 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer 10-1/2" strike edge clearance Relocate door or gate to provide maneuvering clearance 1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 14D
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 122
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Headroom - Existing
Code References:	2010 ADAS 404.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate clearance not min. 80" high
Findings:	79" high
Rec. Solution:	Replace door or gate
Barrier Severity:	3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 14E
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 122
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Door blocks electrical switch clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
	Treecessary Table Transfer Decir
Implementation	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 14F
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 122
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code	2010 ADAS 308.2
References:	2010 ADAS 508.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	53" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 14G
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 122
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	71" high
Rec. Solution:	Provide additional hook in accessible location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 14H
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 122
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Cabinet blocks shelf clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 14
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 122
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Carpet/Rug
Code References:	2010 ADAS 302.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Carpet/rug not anchored to floor (possible trip hazard)
Findings:	Carpet/rug creates tripping hazard
Rec. Solution:	Secure exiting carpet/rug or replace
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 14J
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 122
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Room 12	24
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 14K
Field Date: Bldg Name:	2/2/2017 Report Date 3/23/2017 Barrier #: 14K Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistance Office 122
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistance Office 122 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistance Office 122 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistance Office 122 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistance Office 122 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistance Office 122 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistance Office 122 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistance Office 122 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground Shelf not accessible
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistance Office 122 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground Shelf not accessible Provide additional shelf at accessible height or provide assistance 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 14L
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 122
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 15A
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at doors within public route
Rec. Solution:	Provide accessible signs
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Main en	try and room 120D



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 15B
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 15C
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	
	Floor 1 - Grad Teaching Assistance Office 120
	N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Doors or Gates
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Doors or Gates Headroom - Existing 2010 ADAS 404.2.3
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Doors or Gates Headroom - Existing 2010 ADAS 404.2.3
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	N/A Y Coordinate: N/A Doors or Gates Headroom - Existing 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Y Coordinate: N/A Doors or Gates Headroom - Existing 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1 Door/Gate clearance not min. 80" high
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Poors or Gates Headroom - Existing 2010 ADAS 404.2.3 Indard: No Quantity: EACH As-built: 1 Door/Gate clearance not min. 80" high 79" high
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Y Coordinate: N/A Doors or Gates Headroom - Existing 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1 Door/Gate clearance not min. 80" high 79" high Replace door or gate 3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 15D
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Relocate Door
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	14-1/2" strike edge clearance
Rec. Solution:	Relocate door or gate to provide maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 15E
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Door swing blocks electrical switch and coat hook clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 15F
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 15G
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	70" high
Rec. Solution:	Provide additional hook in accessible location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 15H
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24-1/2" high knee clearance. 3 PC stations provided and none are accessible
Rec. Solution:	Provide min. one accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 15I
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	16" deep knee clearance
Rec. Solution:	Provide min. one accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 15J
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	13" high
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 15K
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code	
References:	2010 ADAS 702.1
References: Performance Sta	
Performance Sta Barrier	ndard: No Quantity: EACH As-built : 1
Performance Sta Barrier Description: Findings:	ndard: No Quantity: EACH As-built : 1 No horn/strobes in common use areas
Performance Sta Barrier Description: Findings:	ndard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas No device provided
Performance Sta Barrier Description: Findings: Rec. Solution: Barrier Severity:	ndard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas No device provided Provide strobe in common use area



Field Date:	2/8/2017 Report Date 3/23/2017 Barrier #: 16A
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 120C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - No Braille/tactile Sign
Code References:	2010 ADAS 703.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No Braille/tactile sign at latch side of door
Findings:	No sign provided
Rec. Solution:	Provide Braille/tactile sign at latch side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/8/2017 Report Date 3/23/2017 Barrier #: 16B
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 120C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - ISA at Accessible Restroom
Code References:	2010 ADAS 216.8
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No ISA symbol on wall sign posted at accessible toilet room
Findings:	No ISA sign provided
Rec. Solution:	Provide ISA symbol on restroom wall sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/8/2017 Report Date 3/23/2017 Barrier #: 16C
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 120C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	14 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/8/2017 Report Date 3/23/2017 Barrier #: 16D
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 120C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	1 second sweep
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/8/2017 Report Date 3/23/2017 Barrier #: 16E
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 120C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Clearance - 60"
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door lacks min. 60" perpendicular to door swing
Findings:	40-1/2" perpendicular to door swing
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/8/2017 Report Date 3/23/2017 Barrier #: 16F
	2/8/2017 Report Date 3/23/2017 Barrier #: 16F Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 120C
Field Date: Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 120C N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 120C N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 120C N/A Y Coordinate: N/A Restrooms Electrical Switches 2010 ADAS 205.1 & 309.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 120C N/A Y Coordinate: N/A Restrooms Electrical Switches 2010 ADAS 205.1 & 309.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 120C N/A Y Coordinate: N/A Restrooms Electrical Switches 2010 ADAS 205.1 & 309.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 120C N/A Y Coordinate: N/A Restrooms Electrical Switches 2010 ADAS 205.1 & 309.3 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 120C N/A Y Coordinate: N/A Restrooms Electrical Switches 2010 ADAS 205.1 & 309.3 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Unisex Restroom 120C N/A Y Coordinate: N/A Restrooms Electrical Switches 2010 ADAS 205.1 & 309.3 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 50-1/2" high Relocate switch box top edge to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/8/2017 Report Date 3/23/2017 Barrier #: 16G
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 120C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Knee Clearance
Code References:	2010 ADAS 606.2 & 306
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Lavatory bottom apron/edge not at least 27" high
Findings:	Trash bin blocks knee clearance
Rec. Solution:	Remove trash bin
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/8/2017 Report Date 3/23/2017 Barrier #: 16H
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 120C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Mirror
Code References:	2010 ADAS 603.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface
Findings:	58" high
Rec. Solution:	Replace or remount mirror
Barrier Severity:	3 Hindrance Cost Est \$375.00 Facility Function: Public Status: Open
Implementation	
•	Priority: 3 Implementation Phase: Implementation Date:



Field Date:	2/8/2017 Report Date 3/23/2017 Barrier #: 16I
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 120C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Side Grab Bar
Code References:	2010 ADAS 604.5.1
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Side grab bar does not extend min. 54" from rear wall
Findings:	48" from rear wall
Rec. Solution:	Replace grab bars with reinforcement
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/8/2017 Report Date 3/23/2017 Barrier #: 16J
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	
	Floor 1 - Unisex Restroom 120C
	N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Restrooms
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Restrooms Toilet - Side Grab Bar 2010 ADAS 604.5.1
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Restrooms Toilet - Side Grab Bar 2010 ADAS 604.5.1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Y Coordinate: N/A Restrooms Toilet - Side Grab Bar 2010 ADAS 604.5.1 Indard: No Quantity: JOB As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Y Coordinate: N/A Restrooms Toilet - Side Grab Bar 2010 ADAS 604.5.1 Indard: No Quantity: JOB As-built: 1 Side grab bar not min. 42" long
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Restrooms Toilet - Side Grab Bar 2010 ADAS 604.5.1 Indard: No Quantity: JOB As-built: 1 Side grab bar not min. 42" long 36" long
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Y Coordinate: N/A Restrooms Toilet - Side Grab Bar 2010 ADAS 604.5.1 Indard: No Quantity: JOB As-built: 1 Side grab bar not min. 42" long Replace grab bars with reinforcement 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	2/8/2017 Report Date 3/23/2017 Barrier #: 16K
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 120C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Grab Bar Spacing
Code References:	2010 ADAS 609.3
Performance Sta	ndard: No Quantity: JOB As-built : 2
Barrier Description:	Space between grab bar and projecting objects above not min. 12"
Findings:	Seat cover and toilet paper dispenser blocks use of grab bar
Rec. Solution:	Relocate toilet paper and seat cover dispensers
Barrier Severity:	2 Recommended Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Toilet re	emoved for servicing at the time of the field investigation
Field Date:	2/8/2017 Report Date 3/23/2017 Barrier #: 16L
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 120C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	IN/A I Coordinate. JN/A
	Restrooms
Barrier Type:	
	Restrooms
Barrier Type: Code	Restrooms Seat Cover Dispenser 2010 ADAS 307.2
Barrier Type: Code References:	Restrooms Seat Cover Dispenser 2010 ADAS 307.2
Barrier Type: Code References: Performance Sta Barrier	Restrooms Seat Cover Dispenser 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 1
Barrier Type: Code References: Performance Sta Barrier Description:	Restrooms Seat Cover Dispenser 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 1 Seat cover dispenser not located on an accessible route. Blocked by water closet
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Restrooms Seat Cover Dispenser 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 1 Seat cover dispenser not located on an accessible route. Blocked by water closet Access to dispenser may be blocked by water closet when installed and 52" high Replace or remount dispenser on an accessible route with clear floor space
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Restrooms Seat Cover Dispenser 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 1 Seat cover dispenser not located on an accessible route. Blocked by water closet Access to dispenser may be blocked by water closet when installed and 52" high Replace or remount dispenser on an accessible route with clear floor space 2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open



Field Date:	2/8/2017 Report Date 3/23/2017 Barrier #: 16M
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Unisex Restroom 120C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/stobe in sanitary facility
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 17A
Field Date: Bldg Name:	2/2/2017 Report Date 3/23/2017 Barrier #: 17A Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Breakroom 120B
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Breakroom 120B N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Breakroom 120B N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Breakroom 120B N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Breakroom 120B N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Breakroom 120B N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Breakroom 120B N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Breakroom 120B N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Breakroom 120B N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 17B
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Breakroom 120B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	Water jugs block strike edge clearance
Rec. Solution:	Remove stored item
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 17C
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Breakroom 120B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Water jug blocks electrical switch clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 17D
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Breakroom 120B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 17E
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Breakroom 120B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 305
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	50" turning space
Rec. Solution:	Rearrange furniture to provide accessible maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
·	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 17F
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Breakroom 120B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Trash bin blocks shelves, microwave, and coffee maker clear floor space
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 17G
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Breakroom 120B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	are as
barrier Typer	Actuator/Control - Side Reach High Unobstructed
Code References:	Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3
Code	2010 ADAS 305.3
Code References:	2010 ADAS 305.3
Code References: Performance Sta Barrier	2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 0
Code References: Performance Sta Barrier Description: Findings:	2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 0 Control or mechanism not at min. 15" or max. 48" high
Code References: Performance Sta Barrier Description: Findings:	2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 0 Control or mechanism not at min. 15" or max. 48" high Coffee maker 54" high. Microwave 55" high
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	ndard: No Quantity: EACH As-built: 0 Control or mechanism not at min. 15" or max. 48" high Coffee maker 54" high. Microwave 55" high Relocate to min. 15" or max. 48" high 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 17H
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Breakroom 120B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - Wheelchair Use
Code References:	2010 ADAS 305
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	24" deep clear floor space at refrigerator
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 17I
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Breakroom 120B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Treecosory control of the control of



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 18A
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 120A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 18B
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 120A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	Trash bin blocks strike edge clearance. 15" strike edge clearance to table
Rec. Solution:	Remove stored items and move table to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 18C
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 120A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Trash bin blocks electrical switch clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 18D
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 120A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 18E
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 120A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	13" high
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 18F
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 120A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Desk blocks shelving unit and cabinet clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 18G
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 120A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 19A
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Graduate Student Office 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 19B
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Graduate Student Office 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 19C
Field Date: Bldg Name:	2/2/2017 Report Date 3/23/2017 Barrier #: 19C Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Graduate Student Office 118
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Graduate Student Office 118 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Graduate Student Office 118 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Graduate Student Office 118 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Graduate Student Office 118 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Graduate Student Office 118 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Graduate Student Office 118 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 1 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Graduate Student Office 118 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 1 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side 12" strike edge clearance to bookcase
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Graduate Student Office 118 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 1 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side 12" strike edge clearance to bookcase Remove stored item 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 19D
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Graduate Student Office 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 60" - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at with min. 18" at pull side lacks min. 60" perpendicular to door
Findings:	47" perpendicular due to placement of table
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 19E
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Graduate Student Office 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Headroom - Existing
Code References:	2010 ADAS 404.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate clearance not min. 80" high
Findings:	79-1/2" high
Rec. Solution:	Replace door or gate
Barrier Severity:	3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open
	3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open
Implementation	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 19F
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Graduate Student Office 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 19G
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Graduate Student Office 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	75" high
Rec. Solution:	Provide additional hook in accessible location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 19H
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Graduate Student Office 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	andard: No Quantity: JOB As-built: 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	28" wide circulation route between desks and wall
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 19I
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Graduate Student Office 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 305
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	48" turning space
Rec. Solution:	Rearrange furniture to provide maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 19J
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Graduate Student Office 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Table blocks bookcase clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 19K
Field Date: Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Graduate Student Office 118
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Graduate Student Office 118 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Graduate Student Office 118 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Graduate Student Office 118 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Graduate Student Office 118 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Graduate Student Office 118 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Graduate Student Office 118 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Graduate Student Office 118 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground Shelf not accessible
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Graduate Student Office 118 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground Shelf not accessible Provide additional shelf at accessible height or provide assistance 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 19L
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Graduate Student Office 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24" - 25" high knee clearance at 2 desks in room
Rec. Solution:	Provide min. 1 accessible table. Avoid pedestal base tables.
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 19M
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Graduate Student Office 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
Barrier Type:	Controls and Mechanisms
20	Controls and Mechanisms Clear Floor Space - Stored Elements
Code References:	
Code	Clear Floor Space - Stored Elements 2010 ADAS 305.3
Code References:	Clear Floor Space - Stored Elements 2010 ADAS 305.3
Code References: Performance Sta Barrier	Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1
Code References: Performance Sta Barrier Description: Findings:	Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism
Code References: Performance Sta Barrier Description: Findings:	Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Trash bin and small table blocks electrical outlet clear floor space
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Trash bin and small table blocks electrical outlet clear floor space Move stored items 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 19N
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Graduate Student Office 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	13" high
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 190
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Graduate Student Office 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Staff Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobe in staff areas
Findings:	No device provided
Rec. Solution:	Provide as an ADA Title I Accommodation
Barrier Severity:	3 Hindrance Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 20A
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 20B
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 20B Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistant Office 116
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistant Office 116 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistant Office 116 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistant Office 116 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistant Office 116 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistant Office 116 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistant Office 116 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistant Office 116 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not accessible Provide new hardware
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistant Office 116 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not accessible Provide new hardware 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 20C
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 60" - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at with min. 18" at pull side lacks min. 60" perpendicular to door
Findings:	44" perpendicular due to placement of desk
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 20D
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 116
X Coordinate:	N/A Y Coordinate: N/A
D	IN/A I Coordinate. IN/A
Barrier Area:	Doors or Gates
Barrier Area: Barrier Type:	
	Doors or Gates
Barrier Type: Code	Doors or Gates Headroom - Existing 2010 ADAS 404.2.3
Barrier Type: Code References:	Doors or Gates Headroom - Existing 2010 ADAS 404.2.3
Barrier Type: Code References: Performance Sta Barrier	Doors or Gates Headroom - Existing 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Doors or Gates Headroom - Existing 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1 Door/Gate clearance not min. 80" high
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Doors or Gates Headroom - Existing 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1 Door/Gate clearance not min. 80" high 79-1/2" high
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Doors or Gates Headroom - Existing 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1 Door/Gate clearance not min. 80" high 79-1/2" high Replace door or gate 3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 20E
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 305
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	39" turning space
Rec. Solution:	Rearrange furniture to provide accessible maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 20F
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 20F Moreland Hall Reference Dwg: 2 of 5
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistant Office 116
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistant Office 116 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistant Office 116 N/A Y Coordinate: N/A Clear Floor Space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistant Office 116 N/A Y Coordinate: N/A Clear Floor Space Cords in Accessible Route 2010 ADAS 303.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistant Office 116 N/A Y Coordinate: N/A Clear Floor Space Cords in Accessible Route 2010 ADAS 303.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistant Office 116 N/A Y Coordinate: N/A Clear Floor Space Cords in Accessible Route 2010 ADAS 303.3 Indard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistant Office 116 N/A Y Coordinate: N/A Clear Floor Space Cords in Accessible Route 2010 ADAS 303.3 Indard: No Quantity: JOB As-built: 1 Change in level greater than 1/2" in clear floor space at cords
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistant Office 116 N/A Y Coordinate: N/A Clear Floor Space Cords in Accessible Route 2010 ADAS 303.3 Indard: No Quantity: JOB As-built: 1 Change in level greater than 1/2" in clear floor space at cords Cords create trip hazard Provide accessible cord cover or otherwise remove barrier to access
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 2 of 5 Floor 1 - Grad Teaching Assistant Office 116 N/A Y Coordinate: N/A Clear Floor Space Cords in Accessible Route 2010 ADAS 303.3 Indard: No Quantity: JOB As-built: 1 Change in level greater than 1/2" in clear floor space at cords Cords create trip hazard Provide accessible cord cover or otherwise remove barrier to access 1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 20G
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 20H
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	25-3/4" high knee clearance at 5 desks in room
Rec. Solution:	Provide min. one accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 201
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Desk blocks electrical outlet clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 20J
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	
	Electrical Outlets - High Unobstructed
Code References:	Electrical Outlets - High Unobstructed 2010 ADAS 308.2.2
	2010 ADAS 308.2.2
References:	2010 ADAS 308.2.2
References: Performance Sta Barrier	2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 1
References: Performance Sta Barrier Description:	2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high
References: Performance Sta Barrier Description: Findings:	2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 12" high Relocate outlet to min. 15" or max. 48" high
References: Performance Sta Barrier Description: Findings: Rec. Solution:	2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 12" high Relocate outlet to min. 15" or max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 20K
Bldg Name:	Moreland Hall Reference Dwg: 2 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 116
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 21A
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 114
	Floor 1 - Grad Teaching Assistance Office 114 N/A Y Coordinate: N/A
X Coordinate:	
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Signage
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 21B
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 114
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 21C
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 114
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Threshold - Height exceeding 1/2"
Code References:	2010 ADAS 404.2.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate threshold exceeds 1/2" in height
Findings:	1" high
Rec. Solution:	Provide new door threshold
Barrier Severity:	
	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 21D
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 114
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	Trash bin blocks strike edge clearance
Rec. Solution:	Remove stored item
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 21E
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 114
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Headroom - Existing
Code References:	2010 ADAS 404.2.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate clearance not min. 80" high
Findings:	79" high
Rec. Solution:	Replace door or gate
Barrier Severity:	3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 21F
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 114
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Trash bin and bike tire block electrical switch and book case clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 21G
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 114
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	51" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
	primarance for the property of
Implementation	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 21H
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 114
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 305
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	56" turning space
Rec. Solution:	Rearrange furniture to provide maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 211
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 114
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Cords in Accessible Route
Code References:	2010 ADAS 303.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Change in level greater than 1/2" in clear floor space at cords
Findings:	Cords create trip hazard
Rec. Solution:	Provide accessible cord cover or otherwise remove barrier to access
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	
	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 21J
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 114
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 22A
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 22A Moreland Hall Reference Dwg: 3 of 5
Bldg Name:	
Bldg Name: Location:	Moreland Hall Reference Dwg: 3 of 5
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 22B
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 112
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 22C
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 22C Moreland Hall Reference Dwg: 3 of 5
Bldg Name:	
Bldg Name: Location:	Moreland Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Doors or Gates Headroom - Existing 2010 ADAS 404.2.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Doors or Gates Headroom - Existing 2010 ADAS 404.2.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Doors or Gates Headroom - Existing 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Doors or Gates Headroom - Existing 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1 Door/Gate clearance not min. 80" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Poors or Gates Headroom - Existing 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1 Door/Gate clearance not min. 80" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Doors or Gates Headroom - Existing 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1 Door/Gate clearance not min. 80" high Replace door or gate 3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 22D
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 112
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Hardware - Privacy Latch
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Privacy latch provided involves tight grasping, pinching or twisting
Findings:	Hardware not operable with a closed fist
Rec. Solution:	Replace door latch
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 22E
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 22E Moreland Hall Reference Dwg: 3 of 5
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Trash bin blocks electrical switch clear floor space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 112 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Trash bin blocks electrical switch clear floor space Move stored items 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 22F
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 112
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	51-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 22G
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 112
X Coordinate:	
	N/A Y Coordinate: N/A
Barrier Area:	N/A Y Coordinate: N/A Controls and Mechanisms
Barrier Area: Barrier Type:	
	Controls and Mechanisms
Barrier Type: Code	Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3
Barrier Type: Code References:	Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3
Barrier Type: Code References: Performance Sta Barrier	Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1
Barrier Type: Code References: Performance Sta Barrier Description:	Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground Shelves not accessible
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground Shelves not accessible Provide additional shelf at accessible height or provide assistance 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 22H
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 112
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 305
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	54" turning space
Rec. Solution:	Rearrange furniture to provide accessible maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 22I
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 112
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Cords in Accessible Route
Code References:	2010 ADAS 303.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Change in level greater than 1/2" in clear floor space at cords
Findings:	Cords create trip hazard
Rec. Solution:	Provide accessible cord cover or otherwise remove barrier to access
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Driegity D. Jacobson estation Dhage.
Notes:	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 22J
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 112
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Desk blocks electrical outlet clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 22K
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 112
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 23A
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 110
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 23B
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 110
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 23C
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 110
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Kickplate
Code References:	2010 ADAS 404.2.10
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate lacks min. 10" smooth uninterrupted bottom surface
Findings:	9" high indented panel at bottom of door
Rec. Solution:	Provide smooth kick plate min. 10" high at push side of door
Barrier Severity:	1 Necessary Cost Est \$225.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 23D
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 110
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Headroom - Existing
Code References:	2010 ADAS 404.2.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate clearance not min. 80" high
Findings:	79-1/2" high
Rec. Solution:	Replace door or gate
Barrier Severity:	3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 23E
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 110
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Hardware - Privacy Latch
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Privacy latch provided involves tight grasping, pinching or twisting
Findings:	Hardware not operable with a closed fist
Rec. Solution:	Replace door latch
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 23F
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 110
	1 Tool 1 - Grad Teaching Assistant Office 110
	N/A Y Coordinate: N/A
X Coordinate:	
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Controls and Mechanisms
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 50-1/2" high
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high So-1/2" high Relocate switch box top edge to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 23G
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 110
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12" high
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 23H
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 110
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 24A
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 108
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 24B
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 108
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 24C
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 108
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Kickplate
Code References:	2010 ADAS 404.2.10
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate lacks min. 10" smooth uninterrupted bottom surface
Findings:	9" high indented panel at bottom of door
Rec. Solution:	Provide smooth kick plate min. 10" high at push side of door
Barrier Severity:	1 Necessary Cost Est \$225.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 24D
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 108
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Headroom - Existing
Code References:	2010 ADAS 404.2.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate clearance not min. 80" high
Findings:	79-1/2" high
Rec. Solution:	Replace door or gate
Barrier Severity:	3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 24E
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 108
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Hardware - Privacy Latch
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Privacy latch provided involves tight grasping, pinching or twisting
Findings:	Hardware not operable with a closed fist
Rec. Solution:	Replace door latch
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 24F
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 108
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	
	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 24G
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 108
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Trash bin blocks cabinet and electrical outlet clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 24H
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 108
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12" high
	J
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Rec. Solution: Barrier Severity:	
	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 24I
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 108
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 305
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	40" turning space
Rec. Solution:	Rearrange furniture to provide accessible maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 24J
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 108
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	26" high knee clearance at 3 desks in room
Rec. Solution:	Provide min. one accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 24K
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistant Office 108
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Cords in Accessible Route
Code References:	2010 ADAS 303.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Change in level greater than 1/2" in clear floor space at cords
Findings:	Cords create trip hazard
Rec. Solution:	Provide accessible cord cover or otherwise remove barrier to access
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 24L
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 24L Moreland Hall Reference Dwg: 3 of 5
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 108
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 108 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 108 N/A Y Coordinate: N/A Alarms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 108 N/A Y Coordinate: N/A Alarms Horn/Strobe - Common Use Area 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 108 N/A Y Coordinate: N/A Alarms Horn/Strobe - Common Use Area 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 108 N/A Y Coordinate: N/A Alarms Horn/Strobe - Common Use Area 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 108 N/A Y Coordinate: N/A Alarms Horn/Strobe - Common Use Area 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 108 N/A Alarms Horn/Strobe - Common Use Area 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas No device provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistant Office 108 N/A Y Coordinate: N/A Alarms Horn/Strobe - Common Use Area 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas No device provided Provide strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 25A
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 25B
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	15 lbf and door recessed 8-1/2"
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 25C
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	2 second sweep and door recessed 8-1/2"
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 25D
ricia bate.	2/2/2017 Report Date 3/23/2017 Barrier #. 25D
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistance Office 106
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistance Office 106 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistance Office 106 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistance Office 106 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistance Office 106 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistance Office 106 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistance Office 106 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistance Office 106 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not accessible Provide new hardware
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Grad Teaching Assistance Office 106 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not accessible Provide new hardware 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 25E
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	57" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 25F
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Recessed Door - Push Side
Code References:	2010 ADAS 404.2.4.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door recessed by more than 8" lacks at least 12" clearance at push side of door
	<u> </u>
Findings:	Recessed 8-1/2"
Findings: Rec. Solution:	Recessed 8-1/2" Provide automatic door opening device
Rec. Solution:	Provide automatic door opening device
_	Provide automatic door opening device 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 25G
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Trash bin blocks electrical switch clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 25H
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-3/4" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 25I
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	70" high
Rec. Solution:	Provide additional hook in accessible location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 25J
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	
	Clear Floor Space - Stored Elements
Code References:	Clear Floor Space - Stored Elements 2010 ADAS 305.3
	2010 ADAS 305.3
References:	2010 ADAS 305.3
References: Performance Sta Barrier	2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1
References: Performance Sta Barrier Description:	2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism
References: Performance Sta Barrier Description: Findings:	2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Trash bin blocks electrical outlet clear floor space
References: Performance Sta Barrier Description: Findings: Rec. Solution:	ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Trash bin blocks electrical outlet clear floor space Move stored items 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 25K
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12-1/2" high
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 25L
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Desk blocks whiteboard clear floor space
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	
	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 25M
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Grad Teaching Assistance Office 106
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 26A
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Corridor 104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 26B
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Corridor 104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 26C
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Corridor 104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Recessed Door - Push Side
Code References:	2010 ADAS 404.2.4.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door recessed by more than 8" lacks at least 12" clearance at push side of door
Findings:	Recessed 10" at entry (push) side
Rec. Solution:	Replace door or gate and frame
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 26D
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Corridor 104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Relocate Door
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	9-1/2" strike edge clearance at exit (pull) side
Rec. Solution:	Relocate door or gate to provide maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 26E
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Corridor 104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Passage
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built: 1
Barrier Description:	Exit thru an exit enclosure/exit passageway lacks tactile exit sign
Findings:	Passageway to exterior exit with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT ROUTE" at exit side of door
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 26F
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Corridor 104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Sign - Permanent Room/Space
Code References:	2010 ADAS 703.1
Performance Sta	ndard: No Quantity: EACH As-built : 4
Barrier Description:	No sign with raised characters and Braille at permanent room or space with visual sign
Findings:	No tactile info on signs with visual information
Rec. Solution:	Provide signs at latch side of entry door, where possible
Barrier Severity:	1 Necessary Cost Est \$1,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Rooms 2	104A, 104B, 104C, 104D
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 26G
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Corridor 104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Jeon nuois
<u> </u>	Clear Floor Space - Stored Items
Code References:	
	Clear Floor Space - Stored Items 2010 ADAS 306.3.2
References:	Clear Floor Space - Stored Items 2010 ADAS 306.3.2
References: Performance Sta Barrier	Clear Floor Space - Stored Items 2010 ADAS 306.3.2 Indard: No Quantity: JOB As-built: 1
References: Performance Sta Barrier Description: Findings:	Clear Floor Space - Stored Items 2010 ADAS 306.3.2 Indard: No Quantity: JOB As-built: 1 Clear floor space of min. 30" by 48" not provided
References: Performance Sta Barrier Description: Findings:	Clear Floor Space - Stored Items 2010 ADAS 306.3.2 Indard: No Quantity: JOB As-built: 1 Clear floor space of min. 30" by 48" not provided Door swing blocks electrical switch clear floor space
References: Performance Sta Barrier Description: Findings: Rec. Solution:	Clear Floor Space - Stored Items 2010 ADAS 306.3.2 Indard: No Quantity: JOB As-built: 1 Clear floor space of min. 30" by 48" not provided Door swing blocks electrical switch clear floor space Install motion sensor actuation for lighting 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 26H
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Corridor 104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 26I
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Corridor 104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Thermostat 54" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 26J
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Corridor 104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	ADAAG 4.9.4* & 505.10.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12-1/2" high
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 26K
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Corridor 104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door - Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Door knob not accessible
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 26L
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Corridor 104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - New Construction
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	50-1/2" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	2 Recommended Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 26M
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Corridor 104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Relocate Door
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built :
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	3-1/4" strike edge clearance
Rec. Solution:	Install automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 26N
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Corridor 104
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	Desk blocks strike edge clearance
Rec. Solution:	Remove stored item
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 260
Field Date: Bldg Name:	2/2/2017 Report Date 3/23/2017 Barrier #: 260 Moreland Hall Reference Dwg: 3 of 5
Bldg Name:	Moreland Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Corridor 104
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Corridor 104 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Corridor 104 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Corridor 104 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Corridor 104 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Corridor 104 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Corridor 104 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1 No horn or strobe in corridor where fire alarm exists in building
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Corridor 104 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1 No horn or strobe in corridor where fire alarm exists in building No horn/strobe provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 3 of 5 Floor 1 - Corridor 104 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1 No horn or strobe in corridor where fire alarm exists in building No horn/strobe provided Provide horn/strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 27A
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail - Both Sides
Code References:	2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built: 30
Barrier Description:	No handrail provided at both sides of stairway
Findings:	No handrail provided at both sides
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$6,750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 27B
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Height
Code References:	2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built : 0
Barrier Description:	Handrail grip measured at center not 34"- 38" high
Findings:	29-1/2" handrail grip height
Rec. Solution:	Provide handrails at both sides of stairwav
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 27C
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Bottom
Code References:	2010 ADAS 505.10.3
Performance Sta	ndard: No Quantity: LF As-built : 0
Barrier Description:	Extension not sloped for length of one tread beyond the last riser nosing
Findings:	Extension not sloped for the length of one tread long
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 27D
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Grip
Code References:	2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built : 0
Barrier Description:	Handrail grip is not continuous
Findings:	Handrail grip is not continuous
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 27E
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Height
Code References:	2010 ADAS 505.10.2
Performance Sta	andard: No Quantity: LF As-built : 30
Barrier Description:	Handrail grip measured at center not 34"- 38" high
Findings:	31" guardrail grip height
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$6,750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 27F
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code	
References:	2010 ADAS Advisory 504.4
Performance Sta	
Performance Sta Barrier	andard: Yes Quantity: LF or TR As-built : 27
Performance Sta Barrier Description:	ndard: Yes Quantity: LF or TR As-built: 27 No contrasting color on each tread of interior stairway
Performance Sta Barrier Description: Findings:	No contrasting color on each tread of interior stairway Treads lack contrasting color defined as 70% contrast Recommended: Consider providing contrasting color on each tread
Performance Sta Barrier Description: Findings: Rec. Solution:	No contrasting color on each tread of interior stairway Treads lack contrasting color defined as 70% contrast Recommended: Consider providing contrasting color on each tread 2 Recommended Cost Est \$945.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 27G
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Surface Condition - New Construction
Code References:	2010 ADAS 504.4
Performance Sta	ndard: No Quantity: LF As-built : 27
Barrier Description:	Stairway surface is not slip resistant
Findings:	Slip resistant surface could not be verified
Rec. Solution:	Demolish and construct new stairway
Barrier Severity:	4 Low Severity Cost Est \$6,750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 27H
Field Date: Bldg Name:	2/3/2017 Report Date 3/23/2017 Barrier #: 27H Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S0202
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S0202 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S0202 N/A Y Coordinate: N/A Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S0202 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Level ICC A117.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S0202 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Level ICC A117.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S0202 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Level ICC A117.1 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S0202 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Level ICC A117.1 ndard: No Quantity: EACH As-built: 1 Tactile stairway signage not provided to indicate floor level
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S0202 N/A Stairways Sign - Enclosed Exit Stairway Level ICC A117.1 ndard: No Quantity: EACH As-built: 1 Tactile stairway signage not provided to indicate floor level No sign provided on 2nd floor
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S0202 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Level ICC A117.1 ndard: No Quantity: EACH As-built: 1 Tactile stairway signage not provided to indicate floor level No sign provided on 2nd floor Provide sign 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 27I
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Corridor
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	No horn/strobes in corridor
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28A
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in circulation path protrudes more than 4" between 27" and 80" high
	,
Findings:	Pipe protrudes 7" at 66" high
Findings: Rec. Solution:	Pipe protrudes 7" at 66" high Remove obiect or provide detectable warning (wing walls)
_	
Rec. Solution:	Remove object or provide detectable warning (wing walls) 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28B
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Sign - Permanent Room/Space
Code References:	2010 ADAS 703.1
Performance Sta	andard: No Quantity: EACH As-built: 8
Barrier Description:	No sign with raised characters and Braille at permanent room or space with visual sign
Findings:	No tactile info on signs with visual information
Rec. Solution:	Provide signs at latch side of entry door, where possible
Barrier Severity:	1 Necessary Cost Est \$2,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Rooms	242, 244, 222, 220, 224, 226, 200, 216
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28C
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn - No Strobe
Code References:	2010 ADAS 702
Performance Sta	andard: No Quantity: EACH As-built : 3
Barrier Description:	Horn provided in location where no stobe is provided
Findings:	No strobe device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$1,650.00 Facility Function: Public Status: Open
Implementation	· — · · — · · — · · — · · · · · · · · ·
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28D
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Magazine holder 10" - 44" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
	-
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28E
Field Date: Bldg Name:	2/2/2017 Report Date 3/23/2017 Barrier #: 28E Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Clear Floor Space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 ndard: No Quantity: JOB As-built: 1 Circulation route not min. 36" wide between elements
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 ndard: No Quantity: JOB As-built: 1 Circulation route not min. 36" wide between elements 28" wide circulation route between couch and magizine holder
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 ndard: No Quantity: JOB As-built: 1 Circulation route not min. 36" wide between elements 28" wide circulation route between couch and magizine holder Removed stored items 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28F
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Alcove - New Construction
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Fountain with a leading edge between 27" and 80" high protrudes more than 4" into the circulation path
Findings:	No alcove provided
Rec. Solution:	Demolish and construct new alcove as detectable warning
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28G
Field Date: Bldg Name:	2/2/2017 Report Date 3/23/2017 Barrier #: 28G Moreland Hall Reference Dwg: 4 of 5
	[5] 25] 2517 Samuel W. [250
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Counters and Tables
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Counters and Tables Table - Surface Height 2010 ADAS 902.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Counters and Tables Table - Surface Height 2010 ADAS 902.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Counters and Tables Table - Surface Height 2010 ADAS 902.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Counters and Tables Table - Surface Height 2010 ADAS 902.3 ndard: No Quantity: EACH As-built: 1 Surface height exceeds 34" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Counters and Tables Table - Surface Height 2010 ADAS 902.3 ndard: No Quantity: EACH As-built: 1 Surface height exceeds 34" high 41" surface height
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Counters and Tables Table - Surface Height 2010 ADAS 902.3 ndard: No Quantity: EACH As-built: 1 Surface height exceeds 34" high 41" surface height Provide min. 1 accessible table. Avoid pedestal base tables. 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28H
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Pedestal Base
Code References:	2010 ADAS 306.2.2 & 306.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	Pedestal base blocks knee clearance
Rec. Solution:	Provide min. 1 accessible table. Avoid pedestal base tables.
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
<u> </u>	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28I
Field Date: Bldg Name:	2/2/2017 Report Date 3/23/2017 Barrier #: 28I Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Side Reach Obstructed (10"-24") 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Side Reach Obstructed (10"-24") 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Control or mechanism over an 10" to 24" obstruction max. 34" high located above 46"
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Controls and Mechanisms Actuator/Control - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Control or mechanism over an 10" to 24" obstruction max. 34" high located above 46" ChargeAll station controls 43" high and 21" deep over an obstruction
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Control or mechanism over an 10" to 24" obstruction max. 34" high located above 46" ChargeAll station controls 43" high and 21" deep over an obstruction Relocate control or mechanism to max. 46" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28J
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28K
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0201
	7.100. E 11dil 110201
X Coordinate:	N/A Y Coordinate: N/A
	N/A Y Coordinate: N/A
Barrier Area:	N/A Y Coordinate: N/A Corridors
Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Corridors Door Mat 2010 ADAS 302.2 & Advisory 302.2
Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Corridors Door Mat 2010 ADAS 302.2 & Advisory 302.2
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Y Coordinate: N/A Corridors Door Mat 2010 ADAS 302.2 & Advisory 302.2 ndard: No Quantity: EACH As-built: 2
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Y Coordinate: N/A Corridors Door Mat 2010 ADAS 302.2 & Advisory 302.2 ndard: No Quantity: EACH As-built: 2 Recessed doormat not anchored to floor (possible trip hazard)
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Corridors Door Mat 2010 ADAS 302.2 & Advisory 302.2 ndard: No Quantity: EACH As-built: 2 Recessed doormat not anchored to floor (possible trip hazard) Door mats not secured
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Y Coordinate: N/A Corridors Door Mat 2010 ADAS 302.2 & Advisory 302.2 Indard: No Quantity: EACH As-built: 2 Recessed doormat not anchored to floor (possible trip hazard) Door mats not secured Replace door mats 1 Necessary Cost Est \$1,000.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28L
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Visual Information Provided (Exhibitions)
Code References:	ADA Title II Technical Assistance Manual 3.2000 Denial of participation
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Visual sign providing information for program, service or activity not accessible
Findings:	Accessible sign not provided
Rec. Solution:	Provide information in alternate format to provide access to people with vision impairments
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28M
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
O	interestation and interestatio
_	Floor 2 - Hall H0201
Location:	
Location: X Coordinate:	Floor 2 - Hall H0201
Location: X Coordinate:	Floor 2 - Hall H0201 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 2 - Hall H0201 N/A Y Coordinate: N/A Signage
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 2 - Hall H0201 N/A Y Coordinate: N/A Signage Lobby Info Sign Performance Standard
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 2 - Hall H0201 N/A Y Coordinate: N/A Signage Lobby Info Sign Performance Standard
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Floor 2 - Hall H0201 N/A Signage Lobby Info Sign Performance Standard ndard: Yes Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 2 - Hall H0201 N/A Y Coordinate: N/A Signage Lobby Info Sign Performance Standard ndard: Yes Quantity: EACH As-built: 1 No lobby informational sign with location of accessible elements
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 2 - Hall H0201 N/A Y Coordinate: N/A Signage Lobby Info Sign Performance Standard ndard: Yes Quantity: EACH As-built: 1 No lobby informational sign with location of accessible elements Accessible sign not provided
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 2 - Hall H0201 N/A Y Coordinate: N/A Signage Lobby Info Sign Performance Standard ndard: Yes Quantity: EACH As-built: 1 No lobby informational sign with location of accessible elements Accessible sign not provided Provide lobby informational sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28N
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	2010 ADAS 505.10.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	2-1/2" high
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 280
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Carpet/Rug
Code References:	2010 ADAS 302.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Carpet/rug not anchored to floor (possible trip hazard)
Findings:	Carpet/rug creates tripping hazard
Rec. Solution:	Secure exiting carpet/rug or replace
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28P
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Easel blocks fire extinguisher and flyer box clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28Q
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Addition
	Fire Extinguisher - Protruding Object
Code References:	
	Fire Extinguisher - Protruding Object 2010 ADAS 307.2
References:	Fire Extinguisher - Protruding Object 2010 ADAS 307.2
References: Performance Sta Barrier	Fire Extinguisher - Protruding Object 2010 ADAS 307.2 Indard: No Quantity: JOB As-built: 1
References: Performance Sta Barrier Description:	Fire Extinguisher - Protruding Object 2010 ADAS 307.2 ndard: No Quantity: JOB As-built: 1 Fire extinguisher protrudes into circulation path more than 4" between 27" and 80"
References: Performance Sta Barrier Description: Findings:	Fire Extinguisher - Protruding Object 2010 ADAS 307.2 ndard: No Quantity: JOB As-built: 1 Fire extinguisher protrudes into circulation path more than 4" between 27" and 80" Fire extinguisher protrudes 4-1/4" at 28-1/2" high
References: Performance Sta Barrier Description: Findings: Rec. Solution:	Fire Extinguisher - Protruding Object 2010 ADAS 307.2 ndard: No Quantity: JOB As-built: 1 Fire extinguisher protrudes into circulation path more than 4" between 27" and 80" Fire extinguisher protrudes 4-1/4" at 28-1/2" high Remount extinguisher with leading edge below 27" or provide detectable warning 4 Low Severity Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28R
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Metal mail box protrudes 4-1/2" at 28-1/2" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28S
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24-1/4" high knee clearance at mailbox workstation
Rec. Solution:	Provide min. 1 accessible table. Avoid pedestal base tables.
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	
Notes:	and the second s



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28T
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Mailbox - High Reach Range
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Mailbox opening is above 48" high
Findings:	42" - 73" high
Rec. Solution:	Relocate to provide opening at max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28U
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	
Location:	Moreland Hall Reference Dwg: 4 of 5
Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201
Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Corridors
Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Corridors Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in in circulation path protrudes more than 4" between 27" and 80" high Mail box protrudes 5" at 42" high
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in in circulation path protrudes more than 4" between 27" and 80" high Mail box protrudes 5" at 42" high Remove object or provide detectable warning (wing walls) I Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 28V
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Pedestal Base
Code References:	2010 ADAS 306.2.2 & 306.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	Pedestal base blocks knee clearance
Rec. Solution:	Provide min. 1 accessible table. Avoid pedestal base tables.
Barrier Severity:	2 Recommended Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 29A
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	
Location.	Floor 2 - Women's Restroom Vestibule 218
X Coordinate:	Floor 2 - Women's Restroom Vestibule 218 N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Restrooms
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Restrooms Sign - No Braille/tactile Sign 2010 ADAS 703.2.3
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Restrooms Sign - No Braille/tactile Sign 2010 ADAS 703.2.3
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Y Coordinate: N/A Restrooms Sign - No Braille/tactile Sign 2010 ADAS 703.2.3 ndard: No Quantity: EACH As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Restrooms Sign - No Braille/tactile Sign 2010 ADAS 703.2.3 ndard: No Quantity: EACH As-built: 1 No Braille/tactile sign at latch side of door
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Restrooms Sign - No Braille/tactile Sign 2010 ADAS 703.2.3 ndard: No Quantity: EACH As-built: 1 No Braille/tactile sign at latch side of door No tactile sign at vestibule entry door
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Restrooms Sign - No Braille/tactile Sign 2010 ADAS 703.2.3 ndard: No Quantity: EACH As-built: 1 No Braille/tactile sign at latch side of door No tactile sign at vestibule entry door Provide Braille/tactile sign at latch side of door 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 29B
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom Vestibule 218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - ISA at Accessible Restroom
Code References:	2010 ADAS 216.8
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	No ISA symbol on wall sign posted at accessible toilet room
Findings:	No ISA sign at vestibule entry door
Rec. Solution:	Provide ISA symbol on restroom wall sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 29C
	According to the contract of t
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	
_	Moreland Hall Reference Dwg: 4 of 5
Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom Vestibule 218
Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom Vestibule 218 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom Vestibule 218 N/A Y Coordinate: N/A Restrooms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom Vestibule 218 N/A Y Coordinate: N/A Restrooms Door Closer - Interior Adjustment 2010 ADAS 404.2.9
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom Vestibule 218 N/A Y Coordinate: N/A Restrooms Door Closer - Interior Adjustment 2010 ADAS 404.2.9
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom Vestibule 218 N/A Y Coordinate: N/A Restrooms Door Closer - Interior Adjustment 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom Vestibule 218 N/A Y Coordinate: N/A Restrooms Door Closer - Interior Adjustment 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom Vestibule 218 N/A Y Coordinate: N/A Restrooms Door Closer - Interior Adjustment 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 13 lbf at vestibule entry door Replace or adjust existing closer
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom Vestibule 218 N/A Y Coordinate: N/A Restrooms Door Closer - Interior Adjustment 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 13 lbf at vestibule entry door Replace or adjust existing closer 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 29D
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom Vestibule 218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	2 second sweep at vestibule entry door
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 29E
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	
Location.	Floor 2 - Women's Restroom Vestibule 218
X Coordinate:	Floor 2 - Women's Restroom Vestibule 218 N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Doors or Gates
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Poors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 Indard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Poors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 Indard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground 44" high at vestibule entry door
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground 44" high at vestibule entry door Replace door/gate or vision panel 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 29F
Bldg Name: Location:	
	Floor 2 - Women's Restroom Vestibule 218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Threshold (ramp)
Code References:	2010 ADAS 404.2.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate threshold height exceeds 1/2"
Findings:	3/4" high at vestibule entry door
Rec. Solution:	Provide ramp leading to new level landing at door
Barrier Severity:	1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 29G
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom Vestibule 218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	indard: No Quantity: JOB As-built : 0
Performance Sta Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Barrier	
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Barrier Description: Findings:	Clear floor space for wheelchair not provided at control or mechanism Door swing blocks electrical switch clear floor space at vestibule entry door Install motion sensor actuation for lighting
Barrier Description: Findings: Rec. Solution:	Clear floor space for wheelchair not provided at control or mechanism Door swing blocks electrical switch clear floor space at vestibule entry door Install motion sensor actuation for lighting 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 29H
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom Vestibule 218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	56" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 29I
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom Vestibule 218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Coat Hook
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	68" high
Rec. Solution:	Provide additional hook in new location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 29J
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom Vestibule 218
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Shelves
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Shelf provided not mounted between 40" and 48" above floor or ground
Findings:	73" high
Rec. Solution:	Provide additional shelf at accessible height
Barrier Severity:	2 Recommended Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 29K
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom Vestibule 218
	11001 2 Women's Restroom Vestibule 210
	N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Restrooms
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Restrooms Alarm - Horn/Strobe 2010 ADAS 702.1
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Restrooms Alarm - Horn/Strobe 2010 ADAS 702.1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Y Coordinate: N/A Restrooms Alarm - Horn/Strobe 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Y Coordinate: N/A Restrooms Alarm - Horn/Strobe 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1 Where a fire alarm is installed, no horn/strobe provided
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Restrooms Alarm - Horn/Strobe 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1 Where a fire alarm is installed, no horn/strobe provided No device provided
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Y Coordinate: N/A Restrooms Alarm - Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 Where a fire alarm is installed, no horn/strobe provided No device provided Provide horn/stobe in sanitary facility 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 30A
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - No Braille/tactile Sign
Code References:	2010 ADAS 703.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No Braille/tactile sign at latch side of door
Findings:	No tactile sign at entry door
Rec. Solution:	Provide Braille/tactile sign at latch side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 30B
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 30B Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 218A
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Restrooms Door Clear Width 2010 ADAS 404.2.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Restrooms Door Clear Width 2010 ADAS 404.2.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Restrooms Door Clear Width 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Restrooms Door Clear Width 2010 ADAS 404.2.3 Indard: No Quantity: EACH As-built: 1 Door clear width is not min. 32"
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Restrooms Door Clear Width 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1 Door clear width is not min. 32" 29" clear width at entry door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Restrooms Door Clear Width 2010 ADAS 404.2.3 Indard: No Quantity: EACH As-built: 1 Door clear width is not min. 32" 29" clear width at entry door Replace door/gate and frame 1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 30C
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Trash bin blocks sanitary dispenser and shelf clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 30D
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Sanitary Products
Code References:	2010 ADAS 603.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Sanitary product dispenser not usable with a closed fist
Findings:	Sanitary dispenser not fist operable
Rec. Solution:	Replace sanitary napkin dispenser
Barrier Severity:	1 Necessary Cost Est \$650.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 30E
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Sanitary Products
Code References:	2010 ADAS 603.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Sanitary product dispenser coin slot or control not max. 48" AFF
Findings:	56" high
Rec. Solution:	Remount no higher than 48" above floor
Barrier Severity:	2 Recommended Cost Est \$650.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 30F
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Shelves
Code References:	2010 ADAS 603.4
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Shelf provided not mounted between 40" and 48" above floor or ground
Findings:	50" high
Rec. Solution:	Provide additional shelf at accessible height
Barrier Severity:	2 Recommended Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 30G
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Clear Floor Space
Code References:	2010 ADAS 606.2
Performance Sta	ndard: No Quantity: JOB As-built : 60
Barrier Description:	No clear floor space 30" x 48" at lavatory to allow forward approach
Findings:	36" deep clear floor space to wall
Rec. Solution:	Remodel to provide access
Barrier Severity:	1 Necessary Cost Est \$34,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 30H
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 218A
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	
	N/A Y Coordinate: N/A
Barrier Area:	N/A Y Coordinate: N/A Restrooms
Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Restrooms Lavatory - Knee Clearance 2010 ADAS 606.2 & 306
Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Restrooms Lavatory - Knee Clearance 2010 ADAS 606.2 & 306
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Y Coordinate: N/A Restrooms Lavatory - Knee Clearance 2010 ADAS 606.2 & 306 Indard: No Quantity: JOB As-built: 1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Y Coordinate: N/A Restrooms Lavatory - Knee Clearance 2010 ADAS 606.2 & 306 Indard: No Quantity: JOB As-built: 1 Lavatory bottom apron/edge not at least 27" high
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Restrooms Lavatory - Knee Clearance 2010 ADAS 606.2 & 306 ndard: No Quantity: JOB As-built: 1 Lavatory bottom apron/edge not at least 27" high 24" high knee clearance Provide min. 1 accessible lavatory
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Restrooms Lavatory - Knee Clearance 2010 ADAS 606.2 & 306 Indard: No Quantity: JOB As-built: 1 Lavatory bottom apron/edge not at least 27" high 24" high knee clearance Provide min. 1 accessible lavatory 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 301
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Drainpipes
Code References:	2010 ADAS 606.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hot water and drainpipes accessible under lavatory not insulated or covered
Findings:	No insulation provided
Rec. Solution:	Insulate drainpipes and hot water pipes
Barrier Severity:	2 Recommended Cost Est \$220.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 30J
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 30J Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 218A
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Restrooms Dispensers - Height 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Restrooms Dispensers - Height 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Restrooms Dispensers - Height 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Restrooms Dispensers - Height 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 1 Dispenser control point or operating mechanism not max. 48" AFF
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Restrooms Dispensers - Height 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 1 Dispenser control point or operating mechanism not max. 48" AFF Paper towel dispenser 52" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 218A N/A N/A Y Coordinate: N/A Restrooms Dispensers - Height 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 1 Dispenser control point or operating mechanism not max. 48" AFF Paper towel dispenser 52" high Remount no higher than 48" above floor 2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 30K
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding dispenser creates protruding object in path of travel
Findings:	Paper towel dispenser protrudes 10" at 52" high
Rec. Solution:	Relocate dispenser or provide cane-detectable warning
Barrier Severity:	2 Recommended Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 30L
Dida Nama:	
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 218A
Location:	Floor 2 - Women's Restroom 218A
Location: X Coordinate:	Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Clear Floor Space
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 304.3.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 304.3.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 304.3.1 Indard: No Quantity: SF As-built: 0
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 304.3.1 ndard: No Quantity: SF As-built: Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 304.3.1 Indard: No Quantity: SF As-built: 0 Clear floor space of min. 60" in diameter not provided where 360 degree turn is made 51" turning space Remodel area to provide min. 60" turning space
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 2 - Women's Restroom 218A N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 304.3.1 ndard: No Quantity: SF As-built: 0 Clear floor space of min. 60" in diameter not provided where 360 degree turn is made 51" turning space Remodel area to provide min. 60" turning space 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 30M
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 218A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/stobe in sanitary facility
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 31A
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Toilet Room 218B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - No Braille/tactile Sign
Code References:	2010 ADAS 703.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No Braille/tactile sign at latch side of door
Findings:	No tactile sign
Rec. Solution:	Provide Braille/tactile sign at latch side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 31B
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Toilet Room 218B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Clear Width
Code References:	2010 ADAS 404.2.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door clear width is not min. 32"
Findings:	28-1/2" clear width
Rec. Solution:	Replace door/gate and frame
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 31C
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Toilet Room 218B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 304.3.1
Performance Sta	andard: No Quantity: SF As-built: 100
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	44" turning space
Rec. Solution:	Remodel area to provide min. 60" turning space
Barrier Severity:	2 Recommended Cost Est \$57,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 31D
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Toilet Room 218B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sanitary Facility not Accessible
Code References:	2010 ADAS 213.2
Performance Sta	ndard: No Quantity: SF As-built: 0
Barrier Description:	Toilet room not accessible to people with disabilities
Findings:	No wheelchair accessible stall provided in restroom
Rec. Solution:	Remodel to provide accessibility
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 31E
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Toilet Room 218B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Area:	Restrooms
Barrier Area: Barrier Type: Code	Restrooms Protruding Object 2010 ADAS 307.2
Barrier Area: Barrier Type: Code References:	Restrooms Protruding Object 2010 ADAS 307.2
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Restrooms Protruding Object 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 3
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Restrooms Protruding Object 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 3 Wall mounted object (dispensers) protrudes more than 4" from wall
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Restrooms Protruding Object 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 3 Wall mounted object (dispensers) protrudes more than 4" from wall Silver rail leading edge 77" high
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Restrooms Protruding Object 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 3 Wall mounted object (dispensers) protrudes more than 4" from wall Silver rail leading edge 77" high Relocate dispenser or provide cane-detectable warning 1 Necessary Cost Est \$1,650.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 31F
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Toilet Room 218B
X Coordinate:	
Barrier Area:	Restrooms
Barrier Type:	Stall Door Closer
Code References:	2010 ADAS 604.8.1.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Stall door not equipped with an automatic closing device
Findings:	Door does not self-close
Rec. Solution:	Replace compartment hinge with adjustible mechanism
Barrier Severity:	2 Recommended Cost Est \$1,650.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 31G
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 31G Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Toilet Room 218B
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Toilet Room 218B N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Toilet Room 218B N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Toilet Room 218B N/A Y Coordinate: N/A Restrooms Single Accommodation - In-swinging Door 2010 ADAS 603.2.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Toilet Room 218B N/A Y Coordinate: N/A Restrooms Single Accommodation - In-swinging Door 2010 ADAS 603.2.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Toilet Room 218B N/A Y Coordinate: N/A Restrooms Single Accommodation - In-swinging Door 2010 ADAS 603.2.3 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Toilet Room 218B N/A Y Coordinate: N/A Restrooms Single Accommodation - In-swinging Door 2010 ADAS 603.2.3 ndard: No Quantity: JOB As-built: 1 Space in room not adequate to allow wheelchair user to enter and close door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Toilet Room 218B N/A Y Coordinate: N/A Restrooms Single Accommodation - In-swinging Door 2010 ADAS 603.2.3 Indard: No Quantity: JOB As-built: 1 Space in room not adequate to allow wheelchair user to enter and close door Door swings into clear floor space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Toilet Room 218B N/A Y Coordinate: N/A Restrooms Single Accommodation - In-swinging Door 2010 ADAS 603.2.3 Indard: No Quantity: JOB As-built: 1 Space in room not adequate to allow wheelchair user to enter and close door Door swings into clear floor space Remodel to provide access 1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 31H
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Toilet Room 218B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Door Hardware
Code References:	2010 ADAS 604.8.1.2
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	Stall door hardware involves tight grasping/pinching to close and no U-pull provided
Findings:	No inner and outer U-pulls
Rec. Solution:	Provide U-pull hardware on outside and inside of stall door
Barrier Severity:	1 Necessary Cost Est \$600.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 31I
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Toilet Room 218B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Entry - Latch Approach - Pull/Push
Code References:	2010 ADAS 604.8.1.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Door with latch approach corridor pull/push side lacks min. 42" space perpendicular to door
Findings:	44" perpendicular to toilet
Rec. Solution:	Replace compartment
Barrier Severity:	2 Recommended Cost Est \$1,650.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 31J
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Toilet Room 218B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Clear Width
Code References:	2010 ADAS 404.2.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door clear width is not min. 32"
Findings:	Stall door 25" clear width
Rec. Solution:	Replace door/gate and frame
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 31K
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Toilet Room 218B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Transfer - Floor-mounted
Code References:	2010 ADAS 604.8.1.1
Performance Sta	andard: No Quantity: SF As-built: 80
Barrier Description:	Min. 60" wide x 59" deep clear floor space not provided at floor-mounted fixture
Findings:	37-1/2" wide x 51-1/4" deep
	Į.
Rec. Solution:	Remodel to provide access
Rec. Solution: Barrier Severity:	
	2 Recommended Cost Est \$46,000.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 31L
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Toilet Room 218B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Grab Bars
Code References:	2010 ADAS 604.5
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	No grab bars provided at water closet
Findings:	No grab bars provided
Rec. Solution:	Provide side and rear grab bars with reinforcement
Barrier Severity:	1 Necessary Cost Est \$900.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 31M
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 31M Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Toilet Room 218B
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Toilet Room 218B N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Toilet Room 218B N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Toilet Room 218B N/A Y Coordinate: N/A Restrooms Toilet - Seat Height 2010 ADAS 604.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Toilet Room 218B N/A Y Coordinate: N/A Restrooms Toilet - Seat Height 2010 ADAS 604.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Toilet Room 218B N/A Y Coordinate: N/A Restrooms Toilet - Seat Height 2010 ADAS 604.4 Indard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Toilet Room 218B N/A Y Coordinate: N/A Restrooms Toilet - Seat Height 2010 ADAS 604.4 Indard: No Quantity: JOB As-built: 1 Water closet seat not between 17" to 19" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Toilet Room 218B N/A Y Coordinate: N/A Restrooms Toilet - Seat Height 2010 ADAS 604.4 Mater closet seat not between 17" to 19" high 16-3/4" high Provide min. 1 accessible water closet
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Women's Toilet Room 218B N/A Y Coordinate: N/A Restrooms Toilet - Seat Height 2010 ADAS 604.4 Indard: No Quantity: JOB As-built: 1 Water closet seat not between 17" to 19" high 16-3/4" high Provide min. 1 accessible water closet 2 Recommended Cost Est \$850.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 31N
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Toilet Room 218B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Seat Cover Dispenser
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Seat cover dispenser not located on an accessible route. Blocked by water closet
Findings:	Access to dispenser blocked by water closet
Rec. Solution:	Replace or remount dispenser on an accessible route with clear floor space
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 310
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Toilet Room 218B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
	,
Findings:	Water closet blocks shelf clear floor space
Findings: Rec. Solution:	Water closet blocks shelf clear floor space Move stored items
_	Move stored items
Rec. Solution:	Move stored items 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 31P
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Toilet Room 218B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Shelves
Code References:	2010 ADAS 603.4
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Shelf provided not mounted between 40" and 48" above floor or ground
Findings:	68-1/4" high
Rec. Solution:	Provide additional shelf at accessible height
Barrier Severity:	2 Recommended Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 31Q
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Toilet Room 218B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: SF As-built: 1
Barrier Description:	Object protrudes more than 4" into pedestrian way
Findings:	Shelf protrudes 7-1/2" at 67-1/2" high
Rec. Solution:	Alter area to remove object
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 31R
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Toilet Room 218B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/stobe in sanitary facility
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 32A
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 214
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at doors within public route at both entry doors
Rec. Solution:	Provide accessible signs
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 32B
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 214
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	ISA - Non-Accessible Entry
Code References:	2010 ADAS 216.6
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Sign directing people to accessible entrance needed where all doors are not accessible
Findings:	Accessible sign not provided
Rec. Solution:	Provide ISA directional sign with arrow directing people to accessible entrance
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 32C
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 214
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Findings: Rec. Solution:	Hardware not accessible Provide new hardware
_	Provide new hardware
Rec. Solution:	Provide new hardware 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 32D
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 214
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Relocate Door
• • •	
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	13-1/2" strike edge clearance
Rec. Solution:	Move equipment to provide maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 32E
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 214
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 60" - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at with min. 18" at pull side lacks min. 60" perpendicular to door
Findings:	32" perpendicular due to placement of table
Rec. Solution:	
neer soration.	Rearrange furniture to provide accessible circulation path
Barrier Severity:	
	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 32F
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 214
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	ISA - Accessible Entry Door
Code References:	2010 ADAS 216.6
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No sign identifying door as accessible where all doors are not accessible
Findings:	No sign provided to indicate that entrance is accessible
Rec. Solution:	Provide ISA at accessible entrance door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 32G
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 214
	11001 2 - Classiooni 214
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	
	N/A Y Coordinate: N/A
Barrier Area:	N/A Y Coordinate: N/A Doors or Gates
Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7
Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not accessible
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Poors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not accessible Provide new hardware 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 32H
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 214
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	55-1/4" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 32I
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 214
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Protruding Object - Wall-mounted
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Wall mounted object protrudes more than 4" from wall
Findings:	Monitor protrudes 6-1/2" at 62-1/2" high
Rec. Solution:	Remove object or provide detectable warning for the visually impaired
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Tracincy random. Public Status. Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 32J
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 214
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Monitor control 51" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 32K
Field Date: Bldg Name:	2/2/2017 Report Date 3/23/2017 Barrier #: 32K Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 214
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 214 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 214 N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 214 N/A Y Coordinate: N/A Classrooms Chalkboard/Whiteboard - Area of Use Performance Standard (2010 ADAS 904.3.3)
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 214 N/A Y Coordinate: N/A Classrooms Chalkboard/Whiteboard - Area of Use Performance Standard (2010 ADAS 904.3.3)
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 214 N/A Y Coordinate: N/A Classrooms Chalkboard/Whiteboard - Area of Use Performance Standard (2010 ADAS 904.3.3) ndard: Yes Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 214 N/A Y Coordinate: N/A Classrooms Chalkboard/Whiteboard - Area of Use Performance Standard (2010 ADAS 904.3.3) ndard: Yes Quantity: EACH As-built: 1 Bottom edge of writing surface not max. 38" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 214 N/A Y Coordinate: N/A Classrooms Chalkboard/Whiteboard - Area of Use Performance Standard (2010 ADAS 904.3.3) ndard: Yes Quantity: EACH As-built: 1 Bottom edge of writing surface not max. 38" high Lower edge of writing surface 51" high from floor Remount whiteboard/chalkboard or provide alternate for use by short people
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 214 N/A Y Coordinate: N/A Classrooms Chalkboard/Whiteboard - Area of Use Performance Standard (2010 ADAS 904.3.3) ndard: Yes Quantity: EACH As-built: 1 Bottom edge of writing surface not max. 38" high Lower edge of writing surface 51" high from floor Remount whiteboard/chalkboard or provide alternate for use by short people 3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 32L
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 214
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	49" high
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 32M
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 214
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Turning Space
Barrier Type:	180 Degree Turn
Code References:	2010 ADAS 403.5.2
Performance Sta	ndard: No Quantity: SF As-built : 0
Barrier Description:	180 degree turn around obstruction not min. 42" wide
Findings:	Approach at 39-1/2" turning into 45" entering to 29"
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 32N
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 214
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Passageway is not min. 36" wide
Findings:	27" wide between chairs and wall
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 320
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 214
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Table blocks whiteboard and coat hook clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 32P
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 214
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard (2010 ADAS 904.3.3)
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 45" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 32Q
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 214
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Alarm - No Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/strobe
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 33A
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Sign - Permanent Room/Space
Code References:	2010 ADAS 703.1
Performance Sta	andard: No Quantity: EACH As-built: 3
Barrier Description:	No sign with raised characters and Braille at permanent room or space with visual sign
Findings:	No tactile info on signs with visual information
Rec. Solution:	Provide signs at latch side of entry door, where possible
Barrier Severity:	1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Rooms	208, 210, 212
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 33B
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 33C
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Landing - Existing (3.1% to 4.0%)
Code References:	2010 ADAS 404.2.4.4
Performance Sta	andard: No Quantity: SF As-built : 20
Barrier Description:	Door or gate lacks landing on both sides of door
Findings:	3.2% slope
Rec. Solution:	Demolish and reconstruct level landing
Barrier Severity:	3 Hindrance Cost Est \$2,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 33D
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Walkways
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)
Code References:	2010 ADAS 403.3
Performance Sta	andard: No Quantity: LF As-built: 13
Barrier Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)
Findings:	3.3% cross slope
Rec. Solution:	Demolish existing and construct new route
Barrier Severity:	3 Hindrance Cost Est \$1,625.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 33E
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Walkways
Barrier Type:	Change of Direction - Level Space
Code References:	2010 ADAS 304.2
Performance Sta	ndard: No Quantity: SF As-built : 25
Barrier Description:	Turning space identified with a change in level of more than 1:48 (2.0%)
Findings:	3.2% slope in landing at change of direction
Rec. Solution:	Alter floor or ground surface
Barrier Severity:	2 Recommended Cost Est \$3,125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 33F
Plda Nama:	
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Hall H0202
_	
Location:	Floor 2 - Hall H0202
Location: X Coordinate:	Floor 2 - Hall H0202 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 2 - Hall H0202 N/A Y Coordinate: N/A Alarms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 2 - Hall H0202 N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 2 - Hall H0202 N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 2 - Hall H0202 N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2 Indard: No Quantity: JOB As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 2 - Hall H0202 N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2 ndard: No Quantity: JOB As-built: 1 Fire extinguisher protrudes into circulation path more than 4" between 27" and 80"
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 2 - Hall H0202 N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2 Indard: No Quantity: JOB As-built: 1 Fire extinguisher protrudes into circulation path more than 4" between 27" and 80" Fire extinguisher protrudes 4-1/2" at 31-1/2" high
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 2 - Hall H0202 N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2 Indard: No Quantity: JOB As-built: 1 Fire extinguisher protrudes into circulation path more than 4" between 27" and 80" Fire extinguisher protrudes 4-1/2" at 31-1/2" high Remount extinguisher with leading edge below 27" or provide detectable warning 4 Low Severity Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 33G
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Mailbox - High Reach Range
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Mailbox opening is above 48" high
Findings:	50" high
Rec. Solution:	Relocate to provide opening at max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 33H
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0202
	Floor 2 - Hall H0202 N/A Y Coordinate: N/A
X Coordinate:	
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Alarms
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Alarms Horn/Strobe - Corridor 2010 ADAS 702.1
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Alarms Horn/Strobe - Corridor 2010 ADAS 702.1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	N/A Y Coordinate: N/A Alarms Horn/Strobe - Corridor 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Alarms Horn/Strobe - Corridor 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in corridor
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Alarms Horn/Strobe - Corridor 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1 No horn/strobes in corridor No device provided Provide strobe in common use area
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Y Coordinate: N/A Alarms Horn/Strobe - Corridor 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in corridor No device provided Provide strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34A
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34B
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	, , , , , , , , , , , , , , , , , , , ,
Implementation	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34C
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	43-1/2" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34D
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Doormat
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Doormat not anchored to floor (possible trip hazard)
Findings:	Doormat not secured
Rec. Solution:	Secure exiting doormat or replace
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
	Treecastry control of the states of the stat
Implementation	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34E
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Door swing and desk blocks electrical switch clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34F
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	54" high
Findings: Rec. Solution:	54" high Relocate switch box top edge to max. 48" high
_	Relocate switch box top edge to max. 48" high
Rec. Solution:	Relocate switch box top edge to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34G
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Passageway is not min. 36" wide
Findings:	Circulation route through classroom not min. 36"
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34H
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 34H Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Classrooms Desk - Ratio 2010 ADAS 902
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Classrooms Desk - Ratio 2010 ADAS 902
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Classrooms Desk - Ratio 2010 ADAS 902 ndard: No Quantity: EACH As-built: 3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Classrooms Desk - Ratio 2010 ADAS 902 ndard: No Quantity: EACH As-built: 3 At least 1 desk or 5% of all desks not accessible
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Classrooms Desk - Ratio 2010 ADAS 902 ndard: No Quantity: EACH As-built: 3 At least 1 desk or 5% of all desks not accessible 34 desks provided including 1 accessible desk
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Classrooms Desk - Ratio 2010 ADAS 902 ndard: No Quantity: EACH As-built: 3 At least 1 desk or 5% of all desks not accessible 34 desks provided including 1 accessible desk Provide min. 2 accessible desks 3 Hindrance Cost Est \$2,625.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34I
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Integration
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Desk not integrated into assembly seating
Findings:	Desk identified as accessible is not integrated into typical seating
Rec. Solution:	Move desk to integrated setting
Barrier Severity:	2 Necessary Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34J
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	30-1/2" deep clear floor space at accessible desk
	<u></u>
Rec. Solution:	Move desk to provide accessible maneuvering clearance
Rec. Solution: Barrier Severity:	
	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34K
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Passageway is not min. 36" wide
Findings:	35" wide between wall and chair
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34L
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Podium - Surface Height
Code References:	2010 ADAS 504.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Surface height exceeds 34" high
Findings:	41" surface height
Rec. Solution:	Provide min. 1 accessible podium
Barrier Severity:	4 Low Severity Cost Est \$1,275.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	implementation bate.



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34M
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Podium - Knee Clearance
Code References:	2010 ADAS 504.2
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Podium knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	Removable podium blocks podium knee clearance
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34N
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Phone 54" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 340
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Projector control 51" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34P
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 34P Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Classrooms Clear Floor Space - Stored Elements 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Classrooms Clear Floor Space - Stored Elements 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Classrooms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Classrooms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Classrooms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Floor fan blocks ceiling fan control clear floor space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Classrooms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Floor fan blocks ceiling fan control clear floor space Move stored items 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34Q
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard (2010 ADAS 904.3.3)
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 45-1/4" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34R
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 34R Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Stairway Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Stairway Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Stairway Performance Standard ndard: Yes Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Stairway Performance Standard ndard: Yes Quantity: EACH As-built: 1 Door leading directly into an exit stairway lacks tactile exit sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Stairway Performance Standard ndard: Yes Quantity: EACH As-built: 1 Door leading directly into an exit stairway lacks tactile exit sign Door to exit stair with low level illuminated sign lacks tactile exit sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Stairway Performance Standard ndard: Yes Quantity: EACH As-built: 1 Door leading directly into an exit stairway lacks tactile exit sign Door to exit stair with low level illuminated sign lacks tactile exit sign Provide sign stating "EXIT STAIR DOWN (or UP)" at latch side of door 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34S
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Exterior Adjustment
Code References:	Performance Standard
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 8.5 lbf
Findings:	13 lbf at emergency exit
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34T
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Exterior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	4 second sweep at emergency exit
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34U
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible at emergency exit
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34V
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 34V Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 1 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 1 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer 9" strike edge clearance at emergency exit
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 206 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 1 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer 9" strike edge clearance at emergency exit No remediation recommended. Door is not part of an accessible route. 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34W
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Threshold - Height exceeding 1/2"
Code References:	2010 ADAS 404.2.5
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate threshold exceeds 1/2" in height
Findings:	2" lip at emergency exit
Rec. Solution:	No remediation recommended. Door is not part of an accessible route.
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 34X
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Alarm - No Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/stobe
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 35A
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Waiting Area 204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 4
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at doors within public route
Rec. Solution:	Provide accessible signs
Barrier Severity:	1 Necessary Cost Est \$1,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Main en	try and rooms 204A, 204B, 204D
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 35B
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Waiting Area 204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
	,
Findings:	Hardware not accessible
-	Hardware not accessible Provide new hardware
-	Provide new hardware
Rec. Solution:	Provide new hardware 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 35C
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Waiting Area 204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	43-1/2" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 35D
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Waiting Area 204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	Trash bins block strike edge clearance at exit side
Rec. Solution:	Remove stored item
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 35E
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Waiting Area 204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Trash bin blocks electrical switch clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 35F
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Waiting Area 204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50-1/4" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	· — · — · — · — — ·
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 35G
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Waiting Area 204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24-1/4" high knee clearance at the only desk in the waiting area
Rec. Solution:	Provide min. 1 accessible table. Avoid pedestal base tables.
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 35H
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Waiting Area 204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Table blocks electrical outlet clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	7 2



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 351
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Waiting Area 204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	9-1/2" high
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 35J
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Waiting Area 204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - Wheelchair Use
Code References:	2010 ADAS 305
Performance Sta	andard: No Quantity: JOB As-built: 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	No wheelchair resting space provided next to seating area
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 35K
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Waiting Area 204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Horn/Strobe Device
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn or strobe in corridor where fire alarm exists in building
Findings:	No horn/strobe provided
Rec. Solution:	Provide horn/strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 36A
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 204C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 36B
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 204C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 36C
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 36C Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Doors or Gates Threshold - Height exceeding 1/2" 2010 ADAS 404.2.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Doors or Gates Threshold - Height exceeding 1/2" 2010 ADAS 404.2.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Doors or Gates Threshold - Height exceeding 1/2" 2010 ADAS 404.2.5 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Doors or Gates Threshold - Height exceeding 1/2" 2010 ADAS 404.2.5 ndard: No Quantity: EACH As-built: 1 Door/Gate threshold exceeds 1/2" in height
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Doors or Gates Threshold - Height exceeding 1/2" 2010 ADAS 404.2.5 ndard: No Quantity: EACH As-built: 1 Door/Gate threshold exceeds 1/2" in height 7/8" lip
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Doors or Gates Threshold - Height exceeding 1/2" 2010 ADAS 404.2.5 ndard: No Quantity: EACH As-built: 1 Door/Gate threshold exceeds 1/2" in height 7/8" lip Provide new door threshold 1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 36D
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 204C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	6" strike edge clearance
Rec. Solution:	Relocate door or gate to provide maneuvering clearance or install automatic door opening devi
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 36E
	2/4/2017 Report Date 3/23/2017 Barrier #: 36E Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	
Field Date: Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Electrical Switches - High Unobstructed 2010 ADAS 308.2.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Electrical Switches - High Unobstructed 2010 ADAS 308.2.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 49-1/4" high Relocate switch box top edge to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 36F
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 204C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Protruding Object - Wall-mounted
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Wall mounted object protrudes more than 4" from wall
Findings:	Monitor protrudes 5-7/8" at 61" high
Rec. Solution:	Remove object or provide detectable warning for the visually impaired
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 36G
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 36G Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Control or mechanism not at min. 15" or max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Control or mechanism not at min. 15" or max. 48" high Monitor controls 52" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Control or mechanism not at min. 15" or max. 48" high Monitor controls 52" high Relocate control or mechanism to min. 15" or max. 48" high Relocate control or mechanism to min. 15" or max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 36H
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 204C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	Cable hook 50" high
Rec. Solution:	Provide additional hook in new location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 36I
	2/4/2017 Report Date 3/23/2017 Barrier #: 36 Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5
Field Date: Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Podium - Surface Height 2010 ADAS 504.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Podium - Surface Height 2010 ADAS 504.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Podium - Surface Height 2010 ADAS 504.2 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Podium - Surface Height 2010 ADAS 504.2 ndard: No Quantity: EACH As-built: 0 Surface height exceeds 34" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Podium - Surface Height 2010 ADAS 504.2 ndard: No Quantity: EACH As-built: 0 Surface height exceeds 34" high 36" surface height of table where portable podium is placed
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Podium - Surface Height 2010 ADAS 504.2 ndard: No Quantity: EACH As-built: 0 Surface height exceeds 34" high 36" surface height of table where portable podium is placed Provide min. 1 accessible podium on table with accessible knee clearance and surface height 4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 36J
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 204C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Passageway is not min. 36" wide
Findings:	29" wide
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 36K
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 36K Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Electrical Outlets - High Unobstructed 2010 ADAS 505.10.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Electrical Outlets - High Unobstructed 2010 ADAS 505.10.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Electrical Outlets - High Unobstructed 2010 ADAS 505.10.2 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Electrical Outlets - High Unobstructed 2010 ADAS 505.10.2 Indard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Electrical Outlets - High Unobstructed 2010 ADAS 505.10.2 Indard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 12" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 204C N/A Y Coordinate: N/A Classrooms Electrical Outlets - High Unobstructed 2010 ADAS 505.10.2 Indard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 12" high Relocate outlet to min. 15" or max. 48" high 2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 36L
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 204C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Table blocks whiteboard clear floor space
Rec. Solution:	Rearrange furniture to provide accessible maneuvering space at whiteboard
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 36M
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 204C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard (2010 ADAS 904.3.3)
Performance Sta	ndard: Yes Quantity: EACH As-built: 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 48" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
	Still dailed States States Open
Implementation	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 36N
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 204C
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Alarm - No Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/stobe
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 37A
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	
	Provide accessible sign
Barrier Severity:	Provide accessible sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Barrier Severity: Implementation	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 37B
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 37C
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 37C Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 1 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Poors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 1 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side Trash bin blocks strike edge clearance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 1 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side Trash bin blocks strike edge clearance Remove stored item 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 37D
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 60" - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at with min. 18" at pull side lacks min. 60" perpendicular to door
Findings:	45" perpendicular due to placement of table
Rec. Solution:	Rearrange furniture to provide accessible maneuvering clearance at door
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 37E
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Trash bin blocks electrical switch clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	Device Both Report David Barrier H. 1975
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 37F
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	56" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 37G
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 305
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	39" turning space
Rec. Solution:	Rearrange furniture to provide accessible maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 37H
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Coat Hook - Clear Floor Space
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not located within 30" x 48" clear floor space
Findings:	Door swing blocks coat hook clear floor space
Rec. Solution:	Provide additional hook in accessible location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 37I
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	73" high
Rec. Solution:	Provide additional hook in accessible location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 37J
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24" to 24-1/4" high knee clearance at work tables in room
Rec. Solution:	Provide min. 1 accessible table. Avoid pedestal base tables.
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 37K
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Table blocks chalkboard and pencil sharpener clear floor space
Rec. Solution:	Relocate sharpener
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 37L
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard (2010 ADAS 904.3.3)
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 49" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 37M
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 37M Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Clear Floor Space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 ndard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high Pencil sharpener protrudes 5-1/2" at 46" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 ndard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high Pencil sharpener protrudes 5-1/2" at 46" high Remove object or provide detectable warning (wing walls) 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 37N
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Cords in Accessible Route
Code References:	2010 ADAS 303.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Change in level greater than 1/2" in clear floor space at cords
Findings:	Cords create trip hazard
Rec. Solution:	Provide accessible cord cover or otherwise remove barrier to access
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
r	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 370
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 370 Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - High Unobstructed 2010 ADAS 308.2.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - High Unobstructed 2010 ADAS 308.2.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - High Unobstructed 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Controls and Mechanisms Electrical Outlets - High Unobstructed 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - High Unobstructed 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 3-1/2" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - High Unobstructed 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 3-1/2" high Relocate outlet to min. 15" or max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 37P
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Printer 42-1/2" deep clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 37Q
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 37Q Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Clear Floor Space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 ndard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 ndard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high Wooden window frame protrudes 4-1/2" at 50" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Workroom 202 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 ndard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high Wooden window frame protrudes 4-1/2" at 50" high Remove object or provide detectable warning (wing walls) Remove object or provide detectable warning (wing walls) 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 37R
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 38A
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	
LOCATION.	Floor 2 - North Entrance V0201
X Coordinate:	Floor 2 - North Entrance V0201 N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Stairways
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Stairways Handrail Grip 2010 ADAS 505.7
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Stairways Handrail Grip 2010 ADAS 505.7
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Stairways Handrail Grip 2010 ADAS 505.7 ndard: No Quantity: LF As-built: 8
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Stairways Handrail Grip 2010 ADAS 505.7 ndard: No Quantity: LF As-built: 8 Handrail diameter (OD) or gripping surface not between 1-1/4" to 2" or non-circular 4"-4.8"
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Stairways Handrail Grip 2010 ADAS 505.7 ndard: No Quantity: LF As-built: 8 Handrail diameter (OD) or gripping surface not between 1-1/4" to 2" or non-circular 4"-4.8" 10" handrail grip diameter
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Stairways Handrail Grip 2010 ADAS 505.7 ndard: No Quantity: LF As-built: 8 Handrail diameter (OD) or gripping surface not between 1-1/4" to 2" or non-circular 4"-4.8" 10" handrail grip diameter Provide handrails at both sides of stairway 2 Recommended Cost Est \$1,800.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 38B
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Entrance V0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Bottom
Code References:	2010 ADAS 505.10.3
Performance Sta	ndard: No Quantity: LF As-built: 1
Barrier Description:	Extension not sloped for length of one tread beyond the last riser nosing
Findings:	Extension not sloped for the length of one tread long
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$225.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 38C
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Entrance V0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail - Opening Limitations
Code References:	Performance Standard
Performance Sta	ndard: No Quantity: LF As-built: 8
Barrier Description:	Guard or handrail have openings that allow passage of a 4" sphere
Findings:	27" openings
Rec. Solution:	Replace handrails
Barrier Severity:	Cost Est Ad 200 00 Facility Functions D. Liv. Status: O.
	1 Necessary Cost Est \$1,800.00 Facility Function: Public Status: Open
Implementation	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 38D
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Entrance V0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail - Intermediate >88" wide
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: LF As-built: 8
Barrier Description:	Stairway more than 88" in width lacks at least 1 intermediate handrail for each 88" of width
Findings:	168" wide
Rec. Solution:	Provide one intermediate handrail per 88" stairway clear width
Barrier Severity:	2 Recommended Cost Est \$1,800.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
-	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 38E
Field Date: Bldg Name:	2/2/2017 Report Date 3/23/2017 Barrier #: 38E Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - North Entrance V0201
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - North Entrance V0201 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - North Entrance V0201 N/A Y Coordinate: N/A Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - North Entrance V0201 N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - North Entrance V0201 N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - North Entrance V0201 N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 ndard: Yes Quantity: LF or TR As-built: 8
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - North Entrance V0201 N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 Indard: Yes Quantity: LF or TR As-built: 8 No contrasting color on each tread of exterior stairway
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - North Entrance V0201 N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 ndard: Yes Quantity: LF or TR As-built: 8 No contrasting color on each tread of exterior stairway Treads lack contrasting color defined as 70% contrast Recommended: Consider providing contrasting color on each tread
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - North Entrance V0201 N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 Indard: Yes Quantity: LF or TR As-built: 8 No contrasting color on each tread of exterior stairway Treads lack contrasting color defined as 70% contrast Recommended: Consider providing contrasting color on each tread 2 Recommended Cost Est \$280.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 38F
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Entrance V0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Surface Condition - New Construction
Code References:	2010 ADAS 504.4
Performance Sta	ndard: No Quantity: LF As-built : 8
Barrier Description:	Stairway surface is not slip resistant
Findings:	Slip resistant surface could not be verified
Rec. Solution:	Demolish and construct new stairway
Barrier Severity:	4 Low Severity Cost Est \$2,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 38G
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Entrance V0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull - Operation
Code References:	2010 ADAS 309.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Fire pull has no fist operable hardware
Findings:	Fire pull not fist operable
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 38H
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Entrance V0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull - Height
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Fire pulls not between 42" and 48" high
Findings:	61-1/2" high
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 38I
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Entrance V0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Trash bin blocks hand sanitizer and electrical switch clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 38J
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Entrance V0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Hi/low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of control involves low reach of less than 15" above floor or more than 48" high
Findings:	Hand sanitizer dispenser 57" high
Rec. Solution:	Relocate to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 38K
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Entrance V0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	indard: No Quantity: EACH As-built: 1
_	indard. NO Quantity. EACH As-built.
Barrier Description:	Light switch control box top edge not at max. 48" high
Description:	Light switch control box top edge not at max. 48" high
Description: Findings:	Light switch control box top edge not at max. 48" high 58" high Relocate switch box top edge to max. 48" high
Description: Findings: Rec. Solution:	Light switch control box top edge not at max. 48" high 58" high Relocate switch box top edge to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 38L
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Entrance V0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Exterior Adjustment
Code References:	Performance Standard
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 8.5 lbf
Findings:	12 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 38M
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Entrance V0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Exterior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	4 second sweep
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 38N
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Entrance V0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Door Hardware
Code References:	2010 ADAS 404.2.10
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door hardware interrupts min. 10" smooth bottom surface
Findings:	Door hardware extends into bottom 10" of door
Rec. Solution:	Remove element at bottom of door at push side
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 380
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Entrance V0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Decrease Calair
	Doors or Gates
Barrier Type:	Doormat Doormat
Barrier Type: Code References:	
Code	Doormat 2010 ADAS 302.2 & Advisory 302.2
Code References:	Doormat 2010 ADAS 302.2 & Advisory 302.2
Code References: Performance Sta Barrier	Doormat 2010 ADAS 302.2 & Advisory 302.2 Indard: No Quantity: EACH As-built: 3
Code References: Performance Sta Barrier Description: Findings:	Doormat 2010 ADAS 302.2 & Advisory 302.2 Indard: No Quantity: EACH As-built: 3 Doormat not anchored to floor (possible trip hazard)
Code References: Performance Sta Barrier Description: Findings:	Doormat 2010 ADAS 302.2 & Advisory 302.2 Indard: No Quantity: EACH As-built: 3 Doormat not anchored to floor (possible trip hazard) Doormats not secured Secure exiting doormats or replace
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Doormat 2010 ADAS 302.2 & Advisory 302.2 Indard: No Quantity: EACH As-built: 3 Doormat not anchored to floor (possible trip hazard) Doormats not secured Secure exiting doormats or replace 1 Necessary Cost Est \$1,500.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 38P
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Entrance V0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Abrupt Change in Level
Code References:	2010 ADAS 303.3
Performance Sta	ndard: No Quantity: LF As-built : 0
Barrier Description:	Change in level greater than 1/2" leading to door
Findings:	2" lip in door landing
Rec. Solution:	No remediation recommended. Door is not part of an accessible route.
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 38Q
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
· ·	interesting that
Location:	Floor 2 - North Entrance V0201
_	interesting that
Location:	Floor 2 - North Entrance V0201
Location: X Coordinate:	Floor 2 - North Entrance V0201 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 2 - North Entrance V0201 N/A Y Coordinate: N/A Signage
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 2 - North Entrance V0201 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 2 - North Entrance V0201 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 2 - North Entrance V0201 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 2 - North Entrance V0201 N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 2 - North Entrance V0201 N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 2 - North Entrance V0201 N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 38R
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Entrance V0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	ISA - Non-Accessible Entry
Code References:	2010 ADAS 216.6
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Sign directing people to accessible entrance needed where all doors are not accessible
Findings:	ISA sign provided on door but accessible route diverages and could not be seen from walkway to accessible entrance
Rec. Solution:	Provide ISA directional sign with arrow directing people to accessible entrance
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 39
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Elevator E0201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Hall lanterns - Visible at Entry
Code References:	2010 ADAS 407.2.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Visual and audible signals not provided at each hoistway entrance to answer calls
Findings:	Hall lanterns not visible from outer side of elevator
Rec. Solution:	Provide hall lanterns visible from outer side of elevator
Barrier Severity:	1 Necessary Cost Est \$3,675.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 40A
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Vestibule 240
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 3
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at doors within public route
Rec. Solution:	Provide accessible signs
Barrier Severity:	1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Rooms 2	240, 240B, 240C
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 40B
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Vestibule 240
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Findings: Rec. Solution:	Hardware not accessible Provide new hardware
J	Provide new hardware
Rec. Solution:	Provide new hardware 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 40C
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Vestibule 240
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	43-1/2" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 40D
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Vestibule 240
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	13-1/2" strike edge clearance and blocked by cabinet
Rec. Solution:	Move cabinet
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 40E
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Vestibule 240
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Cabinet blocks electrical switch clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 40F
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Vestibule 240
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	58" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 40G
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Vestibule 240
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Door swing blocks cabinet clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 40H
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Vestibule 240
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Shelves or Cabinets
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Shelf or cabinet not mounted max. 48" above floor or ground
Findings:	Shelf or cabinet not accessible
Rec. Solution:	Provide additional shelf at accessible height or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 40I
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Vestibule 240
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Cabinet blocks electrical outlet clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 40J
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Vestibule 240
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Horn/Strobe Device
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn or strobe in corridor where fire alarm exists in building
Findings:	No horn/strobe provided
Rec. Solution:	Provide horn/strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 41A
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	
Code	Permanent Room/Space - Tactile Characters
References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 41B
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 41C
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 48"
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at push side with min. 18" lacks min. 48" perpendicular to door
Findings:	29" perpendicular due to placement of trash bin
Rec. Solution:	Remove stored item
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 41D
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 60" - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at with min. 18" at pull side lacks min. 60" perpendicular to door
Findings:	14-1/2" strike edge clearance and blocked by table
Rec. Solution:	Remove stored item
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 41E
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Table blocks electrical switch clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 41F
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	51" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 41G
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	71" high
Rec. Solution:	Provide additional hook in accessible location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 41H
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Performance Sta Barrier Description:	ndard: No Quantity: JOB As-built : 1 Clear floor space for wheelchair not provided at control or mechanism
Barrier	
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Barrier Description: Findings:	Clear floor space for wheelchair not provided at control or mechanism Door swing blocks pencil sharpener clear floor space
Barrier Description: Findings: Rec. Solution:	Clear floor space for wheelchair not provided at control or mechanism Door swing blocks pencil sharpener clear floor space Move stored items 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 411
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Pencil sharpener 58" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 41J
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Pencil sharpener protrudes 4-3/4" at 55" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 41K
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 305
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	44" turning space
Rec. Solution:	Rearrange furniture to provide accessible maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 41L
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
	11001 Z Eddinge Z 10/1
	N/A Y Coordinate: N/A
X Coordinate:	
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Clear Floor Space
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 ndard: No Quantity: JOB As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 ndard: No Quantity: JOB As-built: 1 Circulation route not min. 36" wide between elements
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 ndard: No Quantity: JOB As-built: 1 Circulation route not min. 36" wide between elements 19" wide circulation route
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1 Indard: No Quantity: JOB As-built: 1 Circulation route not min. 36" wide between elements 19" wide circulation route Rearrange furniture to provide accessible maneuvering clearance 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 41M
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Carpet/Rug
Code References:	2010 ADAS 302.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Carpet/rug not anchored to floor (possible trip hazard)
Findings:	Carpet/rug creates tripping hazard
Rec. Solution:	Secure exiting carpet/rug or replace
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 41N
Field Date: Bldg Name:	2/3/2017 Report Date 3/23/2017 Barrier #: 41N Moreland Hall Reference Dwg: 4 of 5
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Lounge 240A
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Lounge 240A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Lounge 240A N/A Y Coordinate: N/A Counters and Tables
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Lounge 240A N/A Y Coordinate: N/A Counters and Tables Table - Protruding Object 2010 ADAS 902.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Lounge 240A N/A Y Coordinate: N/A Counters and Tables Table - Protruding Object 2010 ADAS 902.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Lounge 240A N/A Y Coordinate: N/A Counters and Tables Table - Protruding Object 2010 ADAS 902.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Lounge 240A N/A Y Coordinate: N/A Counters and Tables Table - Protruding Object 2010 ADAS 902.2 ndard: No Quantity: EACH As-built: 1 Table creates protruding object in accessible route
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Lounge 240A N/A Y Coordinate: N/A Counters and Tables Table - Protruding Object 2010 ADAS 902.2 ndard: No Quantity: EACH As-built: 1 Table creates protruding object in accessible route Table protrudes 9" at 28-1/2" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 4 of 5 Floor 2 - Lounge 240A N/A Y Coordinate: N/A Counters and Tables Table - Protruding Object 2010 ADAS 902.2 ndard: No Quantity: EACH As-built: 1 Table creates protruding object in accessible route Table protrudes 9" at 28-1/2" high Remove table or provide detectable warning for the visually impaired 2 Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 410
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Shelves or Cabinets
Code	2010 ADAS 305.3
References:	2010 NB/13 303.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Shelf or cabinet not mounted max. 48" above floor or ground
Findings:	Bookcase not accessible
Rec. Solution:	Provide additional shelf at accessible height or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 41P
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
	Controls and Mechanisms
Barrier Type:	Controls and Mechanisms Clear Floor Space - Stored Elements
Barrier Type: Code References:	
Code	Clear Floor Space - Stored Elements 2010 ADAS 305.3
Code References:	Clear Floor Space - Stored Elements 2010 ADAS 305.3
Code References: Performance Sta Barrier	Clear Floor Space - Stored Elements 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1
Code References: Performance Sta Barrier Description:	Clear Floor Space - Stored Elements 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism
Code References: Performance Sta Barrier Description: Findings:	Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Couch blocks electrical outlet clear floor space
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Couch blocks electrical outlet clear floor space Move stored items or provide outlet in accessible location 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 41Q
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	14" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 41R
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Surface Height
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No section at least 3 feet long between 28" and 34" provided at existing counter
Findings:	35-1/2" high
Rec. Solution:	Provide min. 3 ft long section of counter at max. 34" high
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date.	2/2/2047 Percet Data 2/22/2047 Persian H. 146
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 41S
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	No knee clearance
Rec. Solution:	Provide min. 3 ft segment of accessible counter. Flip-up counters, adiacent tables and similar de
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 41T
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Forward Reach Obstructed (10"-25")
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44"
Findings:	Suggestion box 48" high and 25-1/2" deep over 35-1/2" obstruction
Rec. Solution:	Relocate control or mechanism to max. 44" high
Barrier Severity:	
•	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	· _ · · · <u> </u>



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 41U
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Lounge 240A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 42A
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 238
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at doors within public route
Rec. Solution:	Provide accessible signs
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Rooms 2	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 42B
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 238
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Kickplate
Code References:	2010 ADAS 404.2.10
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate lacks min. 10" smooth uninterrupted bottom surface
Findings:	Bottom of door not smooth and uninterrupted
Rec. Solution:	Provide smooth kick plate min. 10" high at push side of door
Barrier Severity:	1 Necessary Cost Est \$225.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 42C
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 238
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	indard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	6-1/2" strike edge clearance measured to fixed half wall
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 42D
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 238
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 48"
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at push side with min. 18" lacks min. 48" perpendicular to door
Findings:	44" perpendicular due to placement of table
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 42E
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 238
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	
	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 42F
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 238
	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Surface Height
Code	2010 ADAS 902.3
References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	No section at least 3 feet long between 28" and 34" provided at existing counter
Findings:	42" high
Rec. Solution:	Provide min. 3 ft long section of counter at max. 34" high
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 42G
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 238
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Box blocks shelf clear floor space
Rec. Solution:	
Nec. Solution.	Move stored items
Barrier Severity:	
	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 42H
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Workroom 238
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Staff Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobe in staff areas
Findings:	No device provided
Rec. Solution:	Provide as an ADA Title I Accommodation
Barrier Severity:	3 Hindrance Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 43A
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Emergency Exit V0250
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
	Corridors
Barrier Type:	
Barrier Type: Code References:	Corridors
Code	Corridors Horn/Strobe Device 2010 ADAS 702.1
Code References:	Corridors Horn/Strobe Device 2010 ADAS 702.1
Code References: Performance Sta Barrier	Corridors Horn/Strobe Device 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1
Code References: Performance Sta Barrier Description:	Corridors Horn/Strobe Device 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1 No horn or strobe in corridor where fire alarm exists in building
Code References: Performance Sta Barrier Description: Findings:	Corridors Horn/Strobe Device 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1 No horn or strobe in corridor where fire alarm exists in building No horn/strobe provided
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Corridors Horn/Strobe Device 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1 No horn or strobe in corridor where fire alarm exists in building No horn/strobe provided Provide horn/strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 43B
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Emergency Exit V0250
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Stairway
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Door leading directly into an exit stairway lacks tactile exit sign
Findings:	Door to exit stair with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT STAIR DOWN (or UP)" at latch side of door
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 43C
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Emergency Exit V0250
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Doormat
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Doormat not anchored to floor (possible trip hazard)
Findings:	Doormat not secured
Rec. Solution:	Secure exiting doormat or replace
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 43D
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Emergency Exit V0250
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Exterior Adjustment
Code References:	Performance Standard
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 8.5 lbf
Findings:	26 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 43E
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Emergency Exit V0250
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
	<u> </u>
Findings:	Hardware not accessible
Findings: Rec. Solution:	Hardware not accessible Provide new hardware
_	Provide new hardware
Rec. Solution:	Provide new hardware 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open



Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 43F
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Emergency Exit V0250
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 60" - Relocate Door
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at with min. 18" at pull side lacks min. 60" perpendicular to door
Findings:	6-1/2" strike edge clearance
Rec. Solution:	No remediation recommended. Door is not part of an accessible route.
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Report Date 3/23/2017 Barrier #: 43G
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Emergency Exit V0250
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Threshold - Height exceeding 1/2"
Code References:	2010 ADAS 404.2.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate threshold exceeds 1/2" in height
Findings:	2" high
Rec. Solution:	No remediation recommended. Door is not part of an accessible route.
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 44A
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Sign - Permanent Room/Space
Code References:	2010 ADAS 703.1
Performance Sta	andard: No Quantity: EACH As-built : 5
Barrier Description:	No sign with raised characters and Braille at permanent room or space with visual sign
Findings:	No tactile info on signs with visual information
Rec. Solution:	Provide signs at latch side of entry door, where possible
Barrier Severity:	1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Rooms 2	228, 230, 232, 234, 236
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 44B
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Horn/Strobe Device
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn or strobe in corridor where fire alarm exists in building
Findings:	No horn/strobe provided
Rec. Solution:	Provide horn/strobe in common use area
	p
Barrier Severity:	
Barrier Severity: Implementation	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 44C
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Extinguisher - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Fire extinguisher protrudes into circulation path more than 4" between 27" and 80"
Findings:	Fire extinguisher protrudes 4-1/4" at 33" high
Rec. Solution:	Remount extinguisher with leading edge below 27" or provide detectable warning
Barrier Severity:	4 Low Severity Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 44D
Bldg Name:	Moreland Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hall H0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 304.3.1
Performance Sta	ndard: No Quantity: SF As-built : 60
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	52" turning space at waiting area in hallway
Rec. Solution:	Remodel area to provide min. 60" turning space or provide alternate waiting area
Barrier Severity:	2 Recommended Cost Est \$10,500.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 45A
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Exit Stairway S0302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Sign - Enclosed Exit Stairway Level
Code References:	ICC A117.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Tactile stairway signage not provided to indicate floor level
Findings:	No sign provided
Rec. Solution:	Provide sign
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 45B
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Exit Stairway S0302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Corridor
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in corridor
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46A
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Walkways
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)
Code References:	2010 ADAS 403.3
Performance Sta	ndard: No Quantity: LF As-built: 80
Barrier Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)
Findings:	4.9% cross slope
Rec. Solution:	Demolish existing and construct new route
Barrier Severity:	2 Recommended Cost Est \$10,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Slope th	roughout corridor H0301. Highest slope near stairway
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46B
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Electrical Switches - High Unobstructed
Code	2010 ADAS 308.2.1
References:	2010 ADAJ 300.2.1
References: Performance Sta	
Performance Sta Barrier	ndard: No Quantity: EACH As-built : 1
Performance Sta Barrier Description:	ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Performance Sta Barrier Description: Findings:	ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 50-1/2" high
Performance Sta Barrier Description: Findings: Rec. Solution:	ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 50-1/2" high Relocate switch box top edge to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46C
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Landing - Control or Mechanism
Code References:	2010 ADAS 305.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Control or mechanism not located on a level landing
Findings:	2.3% slope at electrical switch
Rec. Solution:	Install motion sensor actuation for lighting
Barrier Severity:	1 Necessary Cost Est \$400.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46D
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	14 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46E
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	3 second sweep
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46F
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door - Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Door knob not accessible
Rec. Solution:	Replace hardware
Barrier Severity:	
•	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46G
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - New Construction
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	48-1/2" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	2 Recommended Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46H
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Relocate Door
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	12" strike edge clearance to recessed wall
Rec. Solution:	Provide automatic door opening device
Rec. Solution: Barrier Severity:	Provide automatic door opening device 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46I
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Landing - Existing (3.1% to 4.0%)
Code References:	2010 ADAS 404.2.4.4
Performance Sta	ndard: No Quantity: SF As-built: 0
Barrier Description:	Door or gate lacks landing on both sides of door
Findings:	3.0% slope
Rec. Solution:	Demolish and reconstruct level landing
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46J
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - To Exit Door
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Exit door leading directly to an exit to the exterior lacks tactile exit sign
Findings:	Door leading to exit door to exterior lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT ROUTE" at exit side of door
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46K
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Landing - Control or Mechanism
Code References:	2010 ADAS 305.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Control or mechanism not located on a level landing
Findings:	2.3% slope at fire pull
Rec. Solution:	Relocate device
Barrier Severity:	1 Necessary Cost Est \$400.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
·	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46L
Field Date: Bldg Name:	2/3/2017 Report Date 3/23/2017 Barrier #: 46L Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	TAXABLE DESCRIPTION OF THE PERSON OF THE PER
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Alarms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Alarms Fire Pull - Operation 2010 ADAS 309.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Alarms Fire Pull - Operation 2010 ADAS 309.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Alarms Fire Pull - Operation 2010 ADAS 309.4 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Alarms Fire Pull - Operation 2010 ADAS 309.4 ndard: No Quantity: EACH As-built: 1 Fire pull has no fist operable hardware
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Alarms Fire Pull - Operation 2010 ADAS 309.4 Indard: No Quantity: EACH As-built: 1 Fire pull has no fist operable hardware Fire pull not fist operable
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Alarms Fire Pull - Operation 2010 ADAS 309.4 ndard: No Quantity: EACH As-built: 1 Fire pull has no fist operable hardware Fire pull not fist operable Replace fire pull when remodeling A Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46M
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull - Height
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Fire pulls not between 42" and 48" high
Findings:	67" high
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46N
Field Date: Bldg Name:	2/3/2017 Report Date 3/23/2017 Barrier #: 46N Moreland Hall Reference Dwg: 5 of 5
	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Corridors Strobe 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Corridors Strobe 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Corridors Strobe 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Corridors Strobe 2010 ADAS 702.1 No Quantity: EACH As-built: 1 No strobe provided in corridor where horn is provided where fire alarm exists in building
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Corridors Strobe 2010 ADAS 702.1 No Quantity: EACH As-built: 1 No strobe provided in corridor where horn is provided where fire alarm exists in building No strobe where horn is provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Corridors Strobe 2010 ADAS 702.1 No strobe provided in corridor where horn is provided where fire alarm exists in building No strobe where horn is provided Provide strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 460
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Panels protrude 6" - 8-1/2" at 41" - 47-1/2" high
Rec. Solution:	Remove objects or provide detectable warnings (wing walls)
Barrier Severity:	1 Necessary Cost Est \$1,100.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46P
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Pipe protrudes 9-1/4" at 67" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46Q
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Floor/Ground Space
Code References:	2010 ADAS 602.2
Performance Sta	ndard: No Quantity: SF As-built: 12
Barrier Description:	Floor/Ground Space under fountain not level
Findings:	2.6% slope
Rec. Solution:	Demolish and construct level landing or relocate fountain
Barrier Severity:	2 Recommended Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
r	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46R
Field Date: Bldg Name:	2/3/2017 Report Date 3/23/2017 Barrier #: 46R Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Drinking Fountains
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Drinking Fountains Knee Clearance 2010 ADAS 306.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Drinking Fountains Knee Clearance 2010 ADAS 306.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Drinking Fountains Knee Clearance 2010 ADAS 306.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Prinking Fountains Knee Clearance 2010 ADAS 306.3 Indard: No Quantity: EACH As-built: 1 Knee clearance under fountain not min. 27" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Prinking Fountains Knee Clearance 2010 ADAS 306.3 Indard: No Quantity: EACH As-built: 1 Knee clearance under fountain not min. 27" high No knee clearance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Drinking Fountains Knee Clearance 2010 ADAS 306.3 Indard: No Quantity: EACH As-built: 1 Knee clearance under fountain not min. 27" high No knee clearance Provide min. 1 wheelchair accessible fountain on each floor 1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46S
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12" high
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
-	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46T
Field Date: Bldg Name:	2/3/2017 Report Date 3/23/2017 Barrier #: 46T Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Controls and Mechanisms Landing - Control or Mechanism 2010 ADAS 305.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Controls and Mechanisms Landing - Control or Mechanism 2010 ADAS 305.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Controls and Mechanisms Landing - Control or Mechanism 2010 ADAS 305.2 ndard: No Quantity: JOB As-built: 2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Controls and Mechanisms Landing - Control or Mechanism 2010 ADAS 305.2 ndard: No Quantity: JOB As-built: 2 Control or mechanism not located on a level landing
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Controls and Mechanisms Landing - Control or Mechanism 2010 ADAS 305.2 ndard: No Quantity: JOB As-built: 2 Control or mechanism not located on a level landing 2.9% slope at pencil sharpener and electrical switch
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Controls and Mechanisms Landing - Control or Mechanism 2010 ADAS 305.2 ndard: No Quantity: JOB As-built: 2 Control or mechanism not located on a level landing 2.9% slope at pencil sharpener and electrical switch Relocate devices 1 Necessary Cost Est \$800.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46U
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Pencil sharpener 57" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46V
Field Date: Bldg Name:	2/3/2017 Report Date 3/23/2017 Barrier #: 46V Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 49" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 49" high Relocate switch box top edge to max. 48" high Relocate switch box top edge to max. 48" high A Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46W
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	12 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46X
Field Date: Bldg Name:	2/3/2017 Report Date 3/23/2017 Barrier #: 46X Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Corridors Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Corridors Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Corridors Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Corridors Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Corridors Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame 3 second sweep
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Corridors Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame 3 second sweep Provide automatic door opening device 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46Y
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door - Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Door knob not accessible
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46Z
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - New Construction
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	49" high
Rec. Solution:	
Nec. Joidtion.	Replace door/gate or vision panel
Barrier Severity:	
	2 Recommended Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46AA
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Relocate Door
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	11-1/4" strike edge clearance at pull side
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46AB
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	
	Front App/push 12" SEC
Code References:	Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1
	2010 ADAS Figure 404.2.4.1
References:	2010 ADAS Figure 404.2.4.1
References: Performance Sta Barrier	2010 ADAS Figure 404.2.4.1 Indard: No Quantity: EACH As-built: 0
References: Performance Sta Barrier Description:	2010 ADAS Figure 404.2.4.1 Indard: No Quantity: EACH As-built: 0 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
References: Performance Sta Barrier Description: Findings:	2010 ADAS Figure 404.2.4.1 Indard: No Quantity: EACH As-built: 0 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer 11-1/4" strike edge clearance at push side Provide automatic door opening device
References: Performance Sta Barrier Description: Findings: Rec. Solution:	2010 ADAS Figure 404.2.4.1 Indard: No Quantity: EACH As-built: 0 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer 11-1/4" strike edge clearance at push side Provide automatic door opening device 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46AC
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Landing - Existing (2.1% to 3.0%)
Code References:	2010 ADAS 404.2.4.4
Performance Sta	ndard: No Quantity: SF As-built: 40
Barrier Description:	Door or gate lacks landing on both sides of door
Findings:	2.9% slope
Rec. Solution:	Demolish and reconstruct level landing
Barrier Severity:	4 Low Severity Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Et al la Barra	Device Data Data Device H. Land
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46AD
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Signage Tactile Exit Signs - To Exit Door Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Signage Tactile Exit Signs - To Exit Door Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Signage Tactile Exit Signs - To Exit Door Performance Standard ndard: Yes Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Signage Tactile Exit Signs - To Exit Door Performance Standard ndard: Yes Quantity: EACH As-built: 1 Exit door leading directly to an exit to the exterior lacks tactile exit sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Signage Tactile Exit Signs - To Exit Door Performance Standard ndard: Yes Quantity: EACH As-built: 1 Exit door leading directly to an exit to the exterior lacks tactile exit sign Door leading to exit door to exterior lacks tactile exit sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0301 N/A Y Coordinate: N/A Signage Tactile Exit Signs - To Exit Door Performance Standard ndard: Yes Quantity: EACH As-built: 1 Exit door leading directly to an exit to the exterior lacks tactile exit sign Door leading to exit door to exterior lacks tactile exit sign Provide sign stating "EXIT ROUTE" at exit side of door 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46AE
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Corridor
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in corridor
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46AF
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Sign - Permanent Room/Space
Code References:	2010 ADAS 703.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No sign with raised characters and Braille at permanent room or space with visual sign
Findings:	No tactile info on sign with visual information
Rec. Solution:	Provide sign at latch side of entry door, where possible
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	
Notes: Room 30	p.eea.e



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 46AG
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 205.1 & 309.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 47A
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom Vestibule 366
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - No Braille/tactile Sign
Code References:	2010 ADAS 703.2.3
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	No Braille/tactile sign at latch side of door
Findings:	No tactile sign at latch side of door
Rec. Solution:	Provide Braille/tactile sign at latch side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	r r
Implementation	Priority: 3 Implementation Phase: Implementation Date:



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 47B
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom Vestibule 366
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - ISA at Accessible Restroom
Code References:	2010 ADAS 216.8
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No ISA symbol on wall sign posted at accessible toilet room
Findings:	No ISA sign
Rec. Solution:	Provide ISA symbol on restroom wall sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 47C
Field Date: Bldg Name:	2/3/2017 Report Date 3/23/2017 Barrier #: 47C Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom Vestibule 366
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom Vestibule 366 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom Vestibule 366 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom Vestibule 366 N/A Y Coordinate: N/A Restrooms Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom Vestibule 366 N/A Y Coordinate: N/A Restrooms Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom Vestibule 366 N/A Y Coordinate: N/A Restrooms Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom Vestibule 366 N/A Y Coordinate: N/A Restrooms Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom Vestibule 366 N/A Y Coordinate: N/A Restrooms Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 12 lbf and 7" strike edge clearance at exit side of door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom Vestibule 366 N/A Restrooms Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 12 lbf and 7" strike edge clearance at exit side of door Provide automatic door opening device 1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 47D
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom Vestibule 366
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	3 second sweep and 7" strike edge clearance at exit side of door
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
F: 115 .	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 47E
Field Date: Bldg Name:	2/3/2017 Report Date 3/23/2017 Barrier #: 47E Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom Vestibule 366
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom Vestibule 366 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom Vestibule 366 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom Vestibule 366 N/A Y Coordinate: N/A Restrooms Door Hardware - Operation 2010 ADAS 404.2.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom Vestibule 366 N/A Y Coordinate: N/A Restrooms Door Hardware - Operation 2010 ADAS 404.2.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom Vestibule 366 N/A Y Coordinate: N/A Restrooms Door Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom Vestibule 366 N/A Y Coordinate: N/A Restrooms Door Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1 Operating controls involve tight grasping, pinching or twisting
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom Vestibule 366 N/A Y Coordinate: N/A Restrooms Door Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1 Operating controls involve tight grasping, pinching or twisting Hardware not operable with a closed fist
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom Vestibule 366 N/A Y Coordinate: N/A Restrooms Door Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1 Operating controls involve tight grasping, pinching or twisting Hardware not operable with a closed fist Replace hardware 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 47F
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom Vestibule 366
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	43-1/2" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 47G
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom Vestibule 366
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
	Doors or Gates
Barrier Type:	Doors or Gates Landing - Existing (2.1% to 3.0%)
Barrier Type: Code References:	
Code	Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4
Code References:	Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4
Code References: Performance Sta Barrier	Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 ndard: No Quantity: SF As-built: 20
Code References: Performance Sta Barrier Description:	Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 Indard: No Quantity: SF As-built: 20 Door or gate lacks landing on both sides of door
Code References: Performance Sta Barrier Description: Findings:	Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 Indard: No Quantity: SF As-built: 20 Door or gate lacks landing on both sides of door 2.9% slope Demolish and reconstruct level landing
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 ndard: No Quantity: SF As-built: 20 Door or gate lacks landing on both sides of door 2.9% slope Demolish and reconstruct level landing 4 Low Severity Cost Est \$2,500.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 47H
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom Vestibule 366
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Relocate Door
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	7" strike edge clearance
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 47I
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom Vestibule 366
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Wall and door swing block electrical switch clear floor space
Rec. Solution:	Install motion sensor actuation for lighting
Barrier Severity:	1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 47J
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom Vestibule 366
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Electrical Switches
Code References:	2010 ADAS 205.1 & 309.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	56" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 47K
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom Vestibule 366
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
Dairiei Area.	Signage
Barrier Type:	Signage Permanent Room/Space - Tactile Characters
Barrier Type: Code	Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Barrier Type: Code References:	Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Barrier Type: Code References: Performance Sta Barrier	Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route to restroom fixtures Provide accessible sign
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route to restroom fixtures Provide accessible sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 47L
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom Vestibule 366
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/stobe in sanitary facility
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 48A
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A
Location:	
Location:	Floor 3 - Men's Restroom 366A
Location: X Coordinate:	Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Restrooms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Restrooms Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Restrooms Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Floor 3 - Men's Restroom 366A N/A Restrooms Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 3 - Men's Restroom 366A N/A Restrooms Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Restrooms Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 15 lbf and 6-1/2" strike edge clearance at entry side Provide automatic door opening device
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Restrooms Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 15 lbf and 6-1/2" strike edge clearance at entry side Provide automatic door opening device I Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 48B
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 366A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	1 second sweep and 6-1/2" strike edge clearance at entry side
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 48C
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 366A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Operating controls involve tight grasping, pinching or twisting
Findings:	Hardware not operable with a closed fist
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 48D
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 366A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	46-1/2" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 48E
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 366A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Threshold (replacement)
Code References:	2010 ADAS 404.2.5
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate threshold height exceeds 1/2"
Findings:	1-1/2" lip
Rec. Solution:	
	Provide new door threshold
Barrier Severity:	
	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 48F
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 366A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Clearance - Push Side
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door lacks min. 12" strike edge clearance at push side
Findings:	6-1/2" strike edge clearance
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
· · · · · · · · · · · · · · · · · · ·	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 48G
Field Date: Bldg Name:	2/3/2017 Report Date 3/23/2017 Barrier #: 48G Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Restrooms Urinal - Flush Controls 2010 ADAS 309
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Restrooms Urinal - Flush Controls 2010 ADAS 309
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Restrooms Urinal - Flush Controls 2010 ADAS 309 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Restrooms Urinal - Flush Controls 2010 ADAS 309 Indard: No Quantity: JOB As-built: 1 Urinal flush controls mounted higher than 48" above the floor
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Restrooms Urinal - Flush Controls 2010 ADAS 309 ndard: No Quantity: JOB As-built: 1 Urinal flush controls mounted higher than 48" above the floor 54" high Replace urinal controls where possible or entire urinal
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Restrooms Urinal - Flush Controls 2010 ADAS 309 Indard: No Quantity: JOB As-built: 1 Urinal flush controls mounted higher than 48" above the floor 54" high Replace urinal controls where possible or entire urinal 2 Recommended Cost Est \$800.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 48H
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 366A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Rim
Code References:	2010 ADAS 605.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Urinal not max. 17" above the floor
Findings:	26" high rim at both fixtures provided
Rec. Solution:	Provide min. 1 accessible urinal
Barrier Severity:	2 Recommended Cost Est \$800.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 48I
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 366A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Faucet
Code References:	2010 ADAS 606.4 & 309
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Lavatory faucet not operable with one hand (fist)
Findings:	Faucet not fist operable
Rec. Solution:	Replace faucet
Barrier Severity:	1 Necessary Cost Est \$375.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 48J
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 366A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Knee Clearance
Code References:	2010 ADAS 606.2 & 306
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Lavatory bottom apron/edge not at least 27" high
Findings:	23" high knee clearance at both fixtures
Rec. Solution:	Provide min. 1 accessible lavatory
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 48K
Field Date: Bldg Name:	2/3/2017 Report Date 3/23/2017 Barrier #: 48K Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 ndard: No Quantity: EACH As-built: 1 Hot water and drainpipes accessible under lavatory not insulated or covered
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 ndard: No Quantity: EACH As-built: 1 Hot water and drainpipes accessible under lavatory not insulated or covered No insulation provided Insulate drainpipes and hot water pipes
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 Indard: No Quantity: EACH As-built: 1 Hot water and drainpipes accessible under lavatory not insulated or covered No insulation provided Insulate drainpipes and hot water pipes 2 Recommended Cost Est \$220.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 48L
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 366A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Mirror
Code References:	2010 ADAS 603.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface
Findings:	55" high
Rec. Solution:	Replace or remount mirror
Barrier Severity:	3 Hindrance Cost Est \$375.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 48M
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 366A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Height
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Dispenser control point or operating mechanism not max. 48" AFF
Findings:	Paper towel dispenser 47" high
Rec. Solution:	Remount no higher than 48" above floor
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority 2 Implementation Phases Implementation Potas
Notes:	Priority: 3 Implementation Phase: Implementation Date:



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 48N
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 366A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding dispenser creates protruding object in path of travel
Findings:	Paper towel dispenser protrudes 10" at 47" high
Rec. Solution:	Relocate dispenser or provide cane-detectable warning
Barrier Severity:	2 Recommended Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 480
Field Date: Bldg Name:	2/3/2017 Report Date 3/23/2017 Barrier #: 480 Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Counters and Tables
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide 24" high knee clearance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 366A N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide 24" high knee clearance Provide min. 1 accessible table. Avoid pedestal base tables. 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 48P
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 366A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/stobe in sanitary facility
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 49A
Field Date: Bldg Name:	2/3/2017 Report Date 3/23/2017 Barrier #: 49A Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Toilet Room 366B
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Toilet Room 366B N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Toilet Room 366B N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Toilet Room 366B N/A Y Coordinate: N/A Restrooms Door Clear Width 2010 ADAS 404.2.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Toilet Room 366B N/A Y Coordinate: N/A Restrooms Door Clear Width 2010 ADAS 404.2.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Toilet Room 366B N/A Y Coordinate: N/A Restrooms Door Clear Width 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Toilet Room 366B N/A Y Coordinate: N/A Restrooms Door Clear Width 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1 Door clear width is not min. 32"
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Toilet Room 366B N/A Y Coordinate: N/A Restrooms Door Clear Width 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1 Door clear width is not min. 32" 30-1/2" clear width
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Men's Toilet Room 366B N/A Y Coordinate: N/A Restrooms Door Clear Width 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1 Door clear width is not min. 32" 30-1/2" clear width Replace door/gate and frame 1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 49B
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Toilet Room 366B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Maneuvering Clearance
Code References:	2010 ADAS 603.2.1
Performance Sta	ndard: No Quantity: SF As-built: 100
Barrier Description:	T-shaped turning space not 36" wide turning into 36" space
Findings:	41" wide between privacy wall and stalls
Rec. Solution:	Remodel toilet room
Barrier Severity:	2 Recommended Cost Est \$57,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 49C
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Toilet Room 366B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Protruding Object
Code	
References:	2010 ADAS 307.2
References: Performance Sta	
Performance Sta Barrier	ndard: No Quantity: JOB As-built : 3
Performance Sta Barrier Description:	ondard: No Quantity: JOB As-built: 3 Object protrudes more than 4" into pedestrian way
Performance Sta Barrier Description: Findings:	Object protrudes more than 4" into pedestrian way Silver rail leading edge 77" high Relocate protruding elements out of pedestrian way or provide cane-detectable warning
Performance Sta Barrier Description: Findings: Rec. Solution:	Object protrudes more than 4" into pedestrian way Silver rail leading edge 77" high Relocate protruding elements out of pedestrian way or provide cane-detectable warning 1 Necessary Cost Est \$1,650.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 49D
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Toilet Room 366B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Door Closer
Code References:	2010 ADAS 604.8.1.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Stall door not equipped with an automatic closing device
Findings:	Door does not self-close
Rec. Solution:	Replace compartment hinge with adjustible mechanism
Barrier Severity:	2 Recommended Cost Est \$1,650.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 49E
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Toilet Room 366B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Single Accommodation - In-swinging Door
Code References:	2010 ADAS 603.2.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Space in room not adequate to allow wheelchair user to enter and close door
Findings:	Door swings into clear floor space
Rec. Solution:	Change door swing
	Change door swing
Barrier Severity:	
Implementation	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 49F
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Toilet Room 366B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Door Hardware
Code References:	2010 ADAS 604.8.1.2
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	Stall door hardware involves tight grasping/pinching to close and no U-pull provided
Findings:	No inner and outer U-pulls
Rec. Solution:	Provide U-pull hardware on outside and inside of stall door
Barrier Severity:	1 Necessary Cost Est \$600.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 49G
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Toilet Room 366B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Clear Width
Code References:	2010 ADAS 404.2.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door clear width is not min. 32"
Findings:	25" clear width at stall door
Rec. Solution:	Replace door/gate and frame
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 49H
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Toilet Room 366B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Entry - Front App/push 48"
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: SF As-built : 0
Barrier Description:	Stall door at push side min. 12" lacks strike edge clearance
Findings:	5" strike edge clearance
Rec. Solution:	Redesign toilet room to provide maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 49
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Toilet Room 366B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Coat Hook
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	64" high
Rec. Solution:	Provide additional hook in new location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	
Implementation	Priority: 3 Implementation Phase: Implementation Date:



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 49J
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Toilet Room 366B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Transfer - Floor-mounted
Code References:	2010 ADAS 604.8.1.1
Performance Sta	andard: No Quantity: SF As-built: 0
Barrier Description:	Min. 60" wide x 59" deep clear floor space not provided at floor-mounted fixture
Findings:	36-1/2" wide x 51-1/4" deep
Rec. Solution:	Remodel to provide front transfer space
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 49K
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Toilet Room 366B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Grab Bars
Code References:	2010 ADAS 604.5
Performance Sta	andard: No Quantity: JOB As-built: 1
Barrier Description:	No grab bars provided at water closet
Findings:	No grab bars provided
Rec. Solution:	Provide side and rear grab bars with reinforcement
Barrier Severity:	1 Necessary Cost Est \$900.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 49L
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Toilet Room 366B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Seat Height
Code References:	2010 ADAS 604.4
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Water closet seat not between 17" to 19" high
Findings:	16-3/4" high
Rec. Solution:	Provide min. 1 accessible water closet
Barrier Severity:	2 Recommended Cost Est \$850.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 49M
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Toilet Room 366B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Seat Cover Dispenser
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Seat cover dispenser not located on an accessible route. Blocked by water closet
Findings:	Access to dispenser blocked by water closet
Rec. Solution:	,
Nec. Joidtion.	Replace or remount dispenser on an accessible route with clear floor space
Barrier Severity:	
	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 49N
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Toilet Room 366B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Water closet blocks shelf clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 490
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 2. Mon's Toilet Boom 266B
	Floor 3 - Men's Toilet Room 366B
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	Plate 1
	N/A Y Coordinate: N/A
Barrier Area:	N/A Y Coordinate: N/A Restrooms
Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Restrooms Shelves 2010 ADAS 603.4
Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Restrooms Shelves 2010 ADAS 603.4
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Y Coordinate: N/A Restrooms Shelves 2010 ADAS 603.4 ndard: No Quantity: EACH As-built: 1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Y Coordinate: N/A Restrooms Shelves 2010 ADAS 603.4 ndard: No Quantity: EACH As-built: 1 Shelf provided not mounted between 40" and 48" above floor or ground
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Y Coordinate: N/A Restrooms Shelves 2010 ADAS 603.4 ndard: No Quantity: EACH As-built: 1 Shelf provided not mounted between 40" and 48" above floor or ground 68-1/4" high
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Y Coordinate: N/A Restrooms Shelves 2010 ADAS 603.4 ndard: No Quantity: EACH As-built: 1 Shelf provided not mounted between 40" and 48" above floor or ground 68-1/4" high Provide additional shelf at accessible height 2 Recommended Cost Est \$75.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 49P
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Toilet Room 366B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Object protrudes more than 4" into pedestrian way
Findings:	Shelf protrudes 7-1/2" at 67-1/2" high
Rec. Solution:	Relocate protruding elements out of pedestrian way or provide cane-detectable warning
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 49Q
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Toilet Room 366B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/stobe in sanitary facility
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 50A
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Break Room 364
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 50B
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
· ·	Involved and Hall
_	Floor 3 - Break Room 364
Location:	
Location:	Floor 3 - Break Room 364
Location: X Coordinate:	Floor 3 - Break Room 364 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 3 - Break Room 364 N/A Y Coordinate: N/A Doors or Gates
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 3 - Break Room 364 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 3 - Break Room 364 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Floor 3 - Break Room 364 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 3 - Break Room 364 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 3 - Break Room 364 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not accessible
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 3 - Break Room 364 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not accessible Provide new hardware 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 50C
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Break Room 364
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Landing - Existing (3.1% to 4.0%)
Code References:	2010 ADAS 404.2.4.4
Performance Sta	ndard: No Quantity: SF As-built: 20
Barrier Description:	Door or gate lacks landing on both sides of door
Findings:	3.9% slope
Rec. Solution:	Demolish and reconstruct level landing
Barrier Severity:	3 Hindrance Cost Est \$2,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 50D
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Break Room 364
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
	Light switch control box top eage not at max. 46 mgn
Findings:	56" high
Findings:	
J	56" high Relocate switch box top edge to max. 48" high
Rec. Solution:	Se" high Relocate switch box top edge to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 50E
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Break Room 364
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 305
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	57" turning space
Rec. Solution:	Rearrange furniture to provide accessible maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 50F
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Break Room 364
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24-1/4" to 26" high knee clearance at work table
Rec. Solution:	Provide min. 1 accessible table. Avoid pedestal base tables.
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	, , , , , , , , , , , , , , , , , , , ,
implementation	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 50G
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Break Room 364
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Forward Reach Obstructed (10"-25")
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44"
Findings:	Mechanical switch 53" high and 29" deep on wall behind water bottles and boxes
Rec. Solution:	Relocate control or mechanism to max. 44" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 50H
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Break Room 364
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	
	Clear Floor Space - Stored Elements
Code References:	
	Clear Floor Space - Stored Elements 2010 ADAS 305.3
References:	Clear Floor Space - Stored Elements 2010 ADAS 305.3
References: Performance Sta Barrier	Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1
References: Performance Sta Barrier Description: Findings:	Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism
References: Performance Sta Barrier Description: Findings:	Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Clear floor space not provided at water dispenser and refrigerator
References: Performance Sta Barrier Description: Findings: Rec. Solution:	Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Clear floor space not provided at water dispenser and refrigerator Move stored items 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 50
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Break Room 364
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - 30" x 48" Clearance
Code References:	2010 ADAS 305
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Sink lacks 30" x 48" clear floor space
Findings:	Clear space not provided to approach sink due to door swing
Rec. Solution:	Replace sink and remodel area
Barrier Severity:	2 Recommended Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 50J
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Break Room 364
X Coordinate:	
	N/A Y Coordinate: N/A
Barrier Area:	N/A Y Coordinate: N/A Classrooms
Barrier Area: Barrier Type:	
	Classrooms
Barrier Type: Code	Classrooms Sink Faucet - Operation 2010 ADAS 606.4 & 309
Barrier Type: Code References:	Classrooms Sink Faucet - Operation 2010 ADAS 606.4 & 309
Barrier Type: Code References: Performance Sta Barrier	Classrooms Sink Faucet - Operation 2010 ADAS 606.4 & 309 ndard: No Quantity: EACH As-built: 1 Faucets lack controls and operating mechanisms involve tight grasping, pinching or twisting of
Barrier Type: Code References: Performance Sta Barrier Description:	Classrooms Sink Faucet - Operation 2010 ADAS 606.4 & 309 ndard: No Quantity: EACH As-built: 1 Faucets lack controls and operating mechanisms involve tight grasping, pinching or twisting of the wrist
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Classrooms Sink Faucet - Operation 2010 ADAS 606.4 & 309 ndard: No Quantity: EACH As-built: 1 Faucets lack controls and operating mechanisms involve tight grasping, pinching or twisting of the wrist Faucet not fist operable
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Classrooms Sink Faucet - Operation 2010 ADAS 606.4 & 309 ndard: No Quantity: EACH As-built: 1 Faucets lack controls and operating mechanisms involve tight grasping, pinching or twisting of the wrist Faucet not fist operable Replace faucet 1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 50K
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Break Room 364
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Rim or Countertop
Code References:	2010 ADAS 606.3
Performance Sta	andard: No Quantity: LF As-built: 3
Barrier Description:	No accessible section of counter at max 34" high provided
Findings:	34-1/2" high
Rec. Solution:	Reposition existing sink or provide additional sink for use in area
Barrier Severity:	1 Necessary Cost Est \$1,110.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 50L
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Break Room 364
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Knee Clearance
Code References:	2010 ADAS 606.2 & 306
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	No knee clearance
Rec. Solution:	Replace cabinet and remount sink
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 50M
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Break Room 364
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Forward Reach Obstructed (10"-25")
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44"
Findings:	Paper towel dispenser 59" high and 17" deep
Rec. Solution:	Relocate control or mechanism to max. 44" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 50N
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Break Room 364
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Surface Height
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No section at least 3 feet long between 28" and 34" provided at existing counter
Findings:	34-1/2" high
Rec. Solution:	Provide min. 3 ft long section of counter at max. 34" high
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 500
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Break Room 364
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	No knee clearance and "flip-up" type counter protrudes 14" at 27" high
Rec. Solution:	Provide min. 3 ft segment of accessible counter. Flip-up counters, adiacent tables and similar de
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 50P
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Break Room 364
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 51A
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 362
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 51B
Field Date: Bldg Name:	2/5/2017 Report Date 3/23/2017 Barrier #: 51B Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not accessible
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not accessible Provide new hardware 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 51C
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 362
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	43-1/2" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 51D
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 362
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Landing - Existing (2.1% to 3.0%)
Code References:	2010 ADAS 404.2.4.4
Performance Sta	andard: No Quantity: SF As-built : 40
Barrier Description:	Door or gate lacks landing on both sides of door
Findings:	2.5% slope on both sides of door
Rec. Solution:	Demolish and reconstruct level landing
Barrier Severity:	4 Low Severity Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 51E
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 362
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Walkways
Barrier Type:	Cross Slope - Existing (3.1% to 4.0%)
Code References:	2010 ADAS 403.3
Performance Sta	ndard: No Quantity: LF As-built : 23
Barrier Description:	Cross slope exceeds 2.0% (3.1% to 4.0%)
Findings:	3.7% cross slope
Rec. Solution:	Demolish existing and construct new route
Barrier Severity:	3 Hindrance Cost Est \$2,875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 51F
Field Date: Bldg Name:	2/5/2017 Report Date 3/23/2017 Barrier #: 51F Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Controls and Mechanisms Landing - Control or Mechanism 2010 ADAS 305.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Controls and Mechanisms Landing - Control or Mechanism 2010 ADAS 305.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Controls and Mechanisms Landing - Control or Mechanism 2010 ADAS 305.2 ndard: No Quantity: JOB As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Controls and Mechanisms Landing - Control or Mechanism 2010 ADAS 305.2 ndard: No Quantity: JOB As-built: 0 Control or mechanism not located on a level landing
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Controls and Mechanisms Landing - Control or Mechanism 2010 ADAS 305.2 ndard: No Quantity: JOB As-built: 0 Control or mechanism not located on a level landing 3.5% slope at electrical switch and pencil sharpener
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Controls and Mechanisms Landing - Control or Mechanism 2010 ADAS 305.2 ndard: No Quantity: JOB As-built: 0 Control or mechanism not located on a level landing 3.5% slope at electrical switch and pencil sharpener Relocate device 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 51G
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 362
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	51-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 51H
Field Date: Bldg Name:	2/5/2017 Report Date 3/23/2017 Barrier #: 51H Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Protruding Object - Wall-mounted 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Protruding Object - Wall-mounted 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Protruding Object - Wall-mounted 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Protruding Object - Wall-mounted 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 1 Wall mounted object protrudes more than 4" from wall
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Protruding Object - Wall-mounted 2010 ADAS 307.2 mdard: No Quantity: EACH As-built: 1 Wall mounted object protrudes more than 4" from wall Pencil sharpener protrudes 5-1/2" at 42" high Remove object or provide detectable warning for the visually impaired
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Protruding Object - Wall-mounted 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 1 Wall mounted object protrudes more than 4" from wall Pencil sharpener protrudes 5-1/2" at 42" high Remove object or provide detectable warning for the visually impaired 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 511
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 362
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Landing - Control or Mechanism
Code References:	2010 ADAS 305.2
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Control or mechanism not located on a level landing
Findings:	3.7% slope at chalkboard and projector screen pull
Rec. Solution:	Relocate device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	o /s /sour Ports To /so /sour Portion #1 Fall
ricia bate.	2/5/2017 Report Date 3/23/2017 Barrier #: 51J
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Chalkboard/Whiteboard - Area of Use Performance Standard (2010 ADAS 904.3.3)
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Chalkboard/Whiteboard - Area of Use Performance Standard (2010 ADAS 904.3.3)
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Chalkboard/Whiteboard - Area of Use Performance Standard (2010 ADAS 904.3.3) ndard: Yes Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Chalkboard/Whiteboard - Area of Use Performance Standard (2010 ADAS 904.3.3) ndard: Yes Quantity: EACH As-built: 1 Bottom edge of writing surface not max. 38" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Chalkboard/Whiteboard - Area of Use Performance Standard (2010 ADAS 904.3.3) ndard: Yes Quantity: EACH As-built: 1 Bottom edge of writing surface not max. 38" high Lower edge of writing surface 48" high from floor
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Chalkboard/Whiteboard - Area of Use Performance Standard (2010 ADAS 904.3.3) ndard: Yes Quantity: EACH As-built: 1 Bottom edge of writing surface not max. 38" high Lower edge of writing surface 48" high from floor Remount whiteboard/chalkboard or provide alternate for use by short people 3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 51K
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 362
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Projector Screen Pull
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Screen pull not at max. 48" high for side reach
Findings:	Projector screen pull 68" high
Rec. Solution:	Relocate to max. 48" high or provide extension
Barrier Severity:	3 Hindrance Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 51L
Field Date: Bldg Name:	2/5/2017 Report Date 3/23/2017 Barrier #: 51L Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Counters and Tables
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide 25-7/8" high knee clearance at instructors desk where students may give presentations
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide 25-7/8" high knee clearance at instructors desk where students may give presentations Provide min. 1 accessible table. Avoid pedestal base tables. 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 51M
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 362
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Podium - Surface Height
Code References:	2010 ADAS 504.2
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Surface height exceeds 34" high
Findings:	39" surface height at portable podium
Rec. Solution:	Provide min. 1 accessible podium
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 51N
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 362
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Podium - Knee Clearance
Code References:	2010 ADAS 504.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Podium knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	14-1/2" deep knee clearance at adjustible podium
Rec. Solution:	Provide min. 1 accessible podium
Barrier Severity:	4 Low Severity Cost Est \$1,275.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 510
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 362
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Keyboard shelf protrudes 9-1/2" at 38" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 51P
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 362
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Passageway is not min. 36" wide
Findings:	Circulation route through classroom not min. 36"
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 51Q
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 362
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Ratio
Code References:	2010 ADAS 902
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	At least 1 desk or 5% of all desks not accessible
Findings:	28 desks provided and no accessible desks are provided
Rec. Solution:	Provide min. 2 accessible desks
Barrier Severity:	3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 51R
Field Date: Bldg Name:	2/5/2017 Report Date 3/23/2017 Barrier #: 51R Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Desk - Knee Clearance 2010 ADAS 902
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Desk - Knee Clearance 2010 ADAS 902
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Desk - Knee Clearance 2010 ADAS 902 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Desk - Knee Clearance 2010 ADAS 902 ndard: No Quantity: EACH As-built: 0 Knee clearance not min. 27" high, 19" deep or 30" wide
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Desk - Knee Clearance 2010 ADAS 902 ndard: No Quantity: EACH As-built: 0 Knee clearance not min. 27" high, 19" deep or 30" wide 26-3/4" knee clearance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Desk - Knee Clearance 2010 ADAS 902 Mard: No Quantity: EACH As-built: 0 Knee clearance not min. 27" high, 19" deep or 30" wide 26-3/4" knee clearance Reposition desk to provide knee clearance 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 51S
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 362
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Integration
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Desk not integrated into assembly seating
Findings:	Desk identified as accessible is not integrated into typical seating
Rec. Solution:	Move desk to integrated setting
Barrier Severity:	2 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 51T
Field Date: Bldg Name:	2/5/2017 Report Date 3/23/2017 Barrier #: 51T Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Electrical Outlets - High Unobstructed 2010 ADAS 505.10.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Electrical Outlets - High Unobstructed 2010 ADAS 505.10.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Electrical Outlets - High Unobstructed 2010 ADAS 505.10.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Electrical Outlets - High Unobstructed 2010 ADAS 505.10.2 ndard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Electrical Outlets - High Unobstructed 2010 ADAS 505.10.2 ndard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 12" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 362 N/A Y Coordinate: N/A Classrooms Electrical Outlets - High Unobstructed 2010 ADAS 505.10.2 Indard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 12" high Relocate outlet to min. 15" or max. 48" high 2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 51U
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 362
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Alarm - No Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/stobe
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 52A
Field Date: Bldg Name:	2/3/2017 Report Date 3/23/2017 Barrier #: 52A
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0302
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0302 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0302 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0302 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0302 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0302 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 Indard: No Quantity: EACH As-built: 10
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0302 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 Indard: No Quantity: EACH As-built: 10 No sign with raised characters and Braille at permanent room or space with visual sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0302 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 Mo Quantity: EACH As-built: 10 No sign with raised characters and Braille at permanent room or space with visual sign No tactile info on signs with visual information Provide signs at latch side of entry door, where possible
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0302 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 Indard: No Quantity: EACH As-built: 10 No sign with raised characters and Braille at permanent room or space with visual sign No tactile info on signs with visual information Provide signs at latch side of entry door, where possible 1 Necessary Cost Est \$2,500.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 52B
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Extinguisher - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: JOB As-built: 1
Barrier Description:	Fire extinguisher protrudes into circulation path more than 4" between 27" and 80"
Findings:	Fire extinguisher protrudes 4-1/4" at 31-1/2" high
Rec. Solution:	Remount extinguisher with leading edge below 27" or provide detectable warning
Barrier Severity:	4 Low Severity Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 52C
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	ADAAG 4.9.4* & 505.10.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12-1/2" high
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 52D
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Horn/Strobe Device
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn or strobe in corridor where fire alarm exists in building
Findings:	No horn/strobe provided
Rec. Solution:	Provide horn/strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 53A
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Emergency Exit V0302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Horn/Strobe Device
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn or strobe in corridor where fire alarm exists in building
Findings:	No horn/strobe provided
Rec. Solution:	Provide horn/strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	Thorty. S imperientation hase.



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 53B
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Emergency Exit V0302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	ADAAG 4.9.4* & 505.10.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12-1/2" high
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 53C
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Emergency Exit V0302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Sign - Tactile Exit Sign at Door
Code References:	2010 ADAS 216.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Ground floor doors that exit directly to the exterior lacks tactile exit sign
Findings:	Accessible sign not provided
Rec. Solution:	Provide new sign stating "EXIT" at exiting side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 53D
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Emergency Exit V0302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door Closer - Exterior Adjustment
Code References:	Performance Standard
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 8.5 lbf
Findings:	12 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 53E
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Emergency Exit V0302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door - Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Door knob not accessible
Rec. Solution:	Replace hardware
Barrier Severity:	
	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 53F
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Emergency Exit V0302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	8" strike edge clearance
Rec. Solution:	No remediation recommended. Door is not part of an accessible route.
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 53G
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Emergency Exit V0302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Threshold - Height exceeding 1/2"
Code References:	2010 ADAS 404.2.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate threshold exceeds 1/2" in height
Findings:	1" lip at door leading to fire escape
Dog Colutions	
Rec. Solution:	No remediation recommended. Door is not part of an accessible route.
Barrier Severity:	
	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 54A
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Lounge 336
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 54B
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Lounge 336
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 54C
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Lounge 336
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - New Construction
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	43-1/2" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	2 Recommended Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 54D
Dida Nama	
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336
_	
Location:	Floor 3 - Lounge 336
Location: X Coordinate:	Floor 3 - Lounge 336 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 3 - Lounge 336 N/A Y Coordinate: N/A Doors or Gates
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 3 - Lounge 336 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 3 - Lounge 336 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 3 - Lounge 336 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 Indard: No Quantity: SF As-built: 20
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 3 - Lounge 336 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 ndard: No Quantity: SF As-built: 20 Door or gate lacks landing on both sides of door
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 3 - Lounge 336 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 Indard: No Quantity: SF As-built: 20 Door or gate lacks landing on both sides of door 2.3% slope Demolish and reconstruct level landing
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 3 - Lounge 336 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 ndard: No Quantity: SF As-built: 20 Door or gate lacks landing on both sides of door 2.3% slope Demolish and reconstruct level landing 4 Low Severity Cost Est \$2,500.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 54E
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Lounge 336
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	3" strike edge clearance
Rec. Solution:	Rearrange furniture to provide accessible maneuvering clearance at door
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 54F
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Lounge 336
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 60" - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at with min. 18" at pull side lacks min. 60" perpendicular to door
Findings:	41" perpendicular due to placement of table
Rec. Solution:	Rearrange furniture to provide accessible maneuvering clearance at door
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 54G
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Lounge 336
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Headroom - Existing
Code References:	2010 ADAS 404.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate clearance not min. 80" high
Findings:	79" high
Rec. Solution:	Replace door or gate
Barrier Severity:	3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 54H
Field Date: Bldg Name:	2/3/2017 Report Date 3/23/2017 Barrier #: 54H Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Table blocks electrical switch clear floor space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Table blocks electrical switch clear floor space Move stored items 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 54I
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Lounge 336
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	51" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 54J
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Lounge 336
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	25" high and 27-1/2" wide knee clearance at 2 PC workstations provided
Rec. Solution:	Provide min. one accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
	S Hillurance Cost Est 5875.00 Tacinty Function. Public Status. Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 54K
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Lounge 336
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	Circulation route not 36" wide in multiple locations
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 54L
Field Date: Bldg Name:	2/3/2017 Report Date 3/23/2017 Barrier #: 54L Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Couch blocks electrical outlet clear floor space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Couch blocks electrical outlet clear floor space Move stored items or provide outlet in accessible location 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 54M
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Lounge 336
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12-1/2" high
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/2/2017 Penert Date 2/22/2017 Perrier #4 F444
ricia bate.	2/3/2017 Report Date 3/23/2017 Barrier #: 54N
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground Bookcases not accessible
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Lounge 336 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground Bookcases not accessible Provide additional shelf at accessible height or provide assistance 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/3/2017 Report Date 3/23/2017 Barrier #: 540
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Lounge 336
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 55A
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 55A Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 55B
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 334
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 55C
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 55C Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Doors or Gates Vision Lights - New Construction 2010 ADAS 404.2.11
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Doors or Gates Vision Lights - New Construction 2010 ADAS 404.2.11
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Doors or Gates Vision Lights - New Construction 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Doors or Gates Vision Lights - New Construction 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Doors or Gates Vision Lights - New Construction 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground 48-1/2" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Doors or Gates Vision Lights - New Construction 2010 ADAS 404.2.11 view panels in or adjacent to doors or gates not max. 43" above floor or ground 48-1/2" high Replace door/gate or vision panel 2 Recommended Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 55D
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 334
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Landing - Existing (2.1% to 3.0%)
Code References:	2010 ADAS 404.2.4.4
Performance Sta	ndard: No Quantity: SF As-built : 25
Barrier Description:	Door or gate lacks landing on both sides of door
Findings:	2.3% slope
Rec. Solution:	Demolish and reconstruct level landing
Barrier Severity:	4 Low Severity Cost Est \$3,125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 55E
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 55E Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Doors or Gates Headroom - Existing 2010 ADAS 404.2.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Doors or Gates Headroom - Existing 2010 ADAS 404.2.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Doors or Gates Headroom - Existing 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Doors or Gates Headroom - Existing 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1 Door/Gate clearance not min. 80" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Doors or Gates Headroom - Existing 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1 Door/Gate clearance not min. 80" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Doors or Gates Headroom - Existing 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1 Door/Gate clearance not min. 80" high Replace door or gate 3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 55F
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 334
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 55G
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 334
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
	Classrooms
Barrier Type:	Classrooms Chalkboard/Whiteboard - Area of Use
Barrier Type: Code References:	
Code	Chalkboard/Whiteboard - Area of Use Performance Standard (2010 ADAS 904.3.3)
Code References:	Chalkboard/Whiteboard - Area of Use Performance Standard (2010 ADAS 904.3.3)
Code References: Performance Sta Barrier	Chalkboard/Whiteboard - Area of Use Performance Standard (2010 ADAS 904.3.3) ndard: Yes Quantity: EACH As-built: 1
Code References: Performance Sta Barrier Description: Findings:	Chalkboard/Whiteboard - Area of Use Performance Standard (2010 ADAS 904.3.3) ndard: Yes Quantity: EACH As-built: 1 Bottom edge of writing surface not max. 38" high
Code References: Performance Sta Barrier Description: Findings:	Chalkboard/Whiteboard - Area of Use Performance Standard (2010 ADAS 904.3.3) ndard: Yes Quantity: EACH As-built: 1 Bottom edge of writing surface not max. 38" high Lower edge of writing surface 42" high from floor
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Chalkboard/Whiteboard - Area of Use Performance Standard (2010 ADAS 904.3.3) ndard: Yes Quantity: EACH As-built: 1 Bottom edge of writing surface not max. 38" high Lower edge of writing surface 42" high from floor Remount whiteboard/chalkboard or provide alternate for use by short people 3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 55H
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 334
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Projector Screen Pull
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Screen pull not at max. 48" high for side reach
Findings:	Projector screen pull 55" high
Rec. Solution:	Relocate to max. 48" high or provide extension
Barrier Severity:	3 Hindrance Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 55I
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 334
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
	<u></u>
Findings:	25-1/2" high knee clearance at instructors desk where students may give presentations
Findings: Rec. Solution:	25-1/2" high knee clearance at instructors desk where students may give presentations Provide min. 1 accessible table. Avoid pedestal base tables.
_	Provide min. 1 accessible table. Avoid pedestal base tables.
Rec. Solution:	Provide min. 1 accessible table. Avoid pedestal base tables. 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 55J
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 334
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Podium - Knee Clearance
Code References:	2010 ADAS 504.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Podium knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	14-1/2" deep knee clearance
Rec. Solution:	Provide min. 1 accessible podium
Barrier Severity:	4 Low Severity Cost Est \$1,275.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
-	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 55K
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #:
Bldg Name:	
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2 ndard: No Quantity: EACH As-built: 0 Podium knee clearance not min. 27" high, 19" deep or 30" wide
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2 ndard: No Quantity: EACH As-built: 0 Podium knee clearance not min. 27" high, 19" deep or 30" wide No knee clearance provided at portable podium
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 334 N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2 ndard: No Quantity: EACH As-built: 0 Podium knee clearance not min. 27" high, 19" deep or 30" wide No knee clearance provided at portable podium Provide min. 1 accessible podium A Low Severity Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 55L
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 334
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Passageway is not min. 36" wide
Findings:	Circulation route through classroom not min. 36"
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 55M
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 334
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Ratio
Code References:	2010 ADAS 902
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	At least 1 desk or 5% of all desks not accessible
Findings:	38 desks provided and 1 desk identified as accessible
Rec. Solution:	Provide min. 2 accessible desks in classroom
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 55N
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 334
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Integration
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Desk not integrated into assembly seating
Findings:	Desk identified as accessible is not integrated into typical seating
Rec. Solution:	Move desk to integrated setting
Barrier Severity:	2 Necessary Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 550
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 334
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Desk blocks electrical outlet clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 55P
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 334
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12" high
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 55Q
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 334
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Floor Surface - Slope
Code References:	2010 ADAS 302 & 303
Performance Sta	ndard: No Quantity: SF As-built : 60
Barrier Description:	Floor surface slope exceeds 2.0%
Findings:	4.3% slope for 20 feet in floor
Rec. Solution:	No remediation recommended. Entire floor in classroom is not part of an accessible route.
Barrier Severity:	2 Necessary Cost Est \$34,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 55R
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 334
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Alarm - No Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/stobe
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 56A
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 332
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 56B
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 332
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 56C
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 56C Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 332
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 332 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 332 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 332 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 332 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 332 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 ndard: No Quantity: SF As-built: 20
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 332 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 ndard: No Quantity: SF As-built: 20 Door or gate lacks landing on both sides of door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 332 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 ndard: No Quantity: SF As-built: 20 Door or gate lacks landing on both sides of door 2.9 % slope
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 332 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 ndard: No Quantity: SF As-built: 20 Door or gate lacks landing on both sides of door 2.9 % slope Demolish and reconstruct level landing A Low Severity Cost Est \$2,500.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 56D
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 332
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	51" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 56E
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 332
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier	
Description:	Passageway is not min. 36" wide
Description: Findings:	
Findings:	Passageway is not min. 36" wide
Findings:	Passageway is not min. 36" wide Circulation route through classroom not min. 36"
Findings: Rec. Solution:	Passageway is not min. 36" wide Circulation route through classroom not min. 36" Rearrange furniture to provide accessible circulation path 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 56F
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 332
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Ratio
Code References:	2010 ADAS 902
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	At least 1 desk or 5% of all desks not accessible
Findings:	42 desks provided and no accessible desks are provided
Rec. Solution:	Provide min. 2 accessible desks
Barrier Severity:	3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 56G
	2/4/2017 Report Date 3/23/2017 Barrier #: 56G Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	「
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 332
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 332 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 332 N/A Y Coordinate: N/A Counters and Tables
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 332 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 332 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 332 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 332 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide 25-1/2" high knee clearance at desk next to instructors desk where students may give
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 332 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide 25-1/2" high knee clearance at desk next to instructors desk where students may give presentations
Field Date: Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: Barrier Severity: Implementation	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 332 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 March Mo Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide 25-1/2" high knee clearance at desk next to instructors desk where students may give presentations Provide min. 1 accessible table. Avoid pedestal base tables. 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 56H
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 332
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Floor Surface - Slope
Code References:	2010 ADAS 302 & 303
Performance Sta	andard: No Quantity: SF As-built: 115
Barrier Description:	Floor surface slope exceeds 2.0%
Findings:	5.2% slope for 23 feet at front of classroom at chalkboard
Rec. Solution:	Remodel to provide level clear floor space at chalkboarde or reorient blackboard and seating to
Barrier Severity:	2 Necessary Cost Est \$66,125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 56I
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 332
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard (2010 ADAS 904.3.3)
Performance Sta	andard: Yes Quantity: EACH As-built: 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 43-1/2" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	
barrier severity.	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 56J
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 332
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Projector Screen Pull
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Screen pull not at max. 48" high for side reach
Findings:	Projector screen pull 74" high
Rec. Solution:	Relocate to max. 48" high or provide extension
Barrier Severity:	3 Hindrance Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 56K
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 332
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Podium - Knee Clearance
Code References:	2010 ADAS 504.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Podium knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	14-1/2" deep knee clearance
Rec. Solution:	Provide min. 1 accessible podium
Barrier Severity:	4 Low Severity Cost Est \$1,275.00 Facility Function: Public Status: Open
Implementation	· — · — · — · — — ·
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 56L
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 332
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Keyboard shelf protrudes 11" at 35" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 56M
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 332
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Podium - Surface Height
Code References:	2010 ADAS 504.2
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Surface height exceeds 34" high
Findings:	40" surface height
Rec. Solution:	Provide min. 1 accessible podium
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 56N
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 332
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	11" high
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 560
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 332
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Alarm - No Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/stobe
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Trecessary established the period of the per
implementation	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	2/1/2017 Report Date 3/23/2017 Barrier #: 57
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Elevator E0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Hall lanterns - Visible at Entry
Code References:	2010 ADAS 407.2.2.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Visual and audible signals not provided at each hoistway entrance to answer calls
Findings:	Hall lanterns not visible from outer side of elevator
Rec. Solution:	Provide hall lanterns visible from outer side of elevator
Barrier Severity:	1 Necessary Cost Est \$3,675.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58A
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at both doors within public route
Rec. Solution:	Provide accessible signs
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58B
Bldg Name:	
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	ISA - Accessible Entry Door
Code References:	2010 ADAS 216.6
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No sign identifying door as accessible where all doors are not accessible
Findings:	No sign provided to indicate that entrance is accessible
Rec. Solution:	Provide ISA at accessible entrance door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58C
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	10 lbf
Rec. Solution:	Provide automatic door opening device at one door and ISA directional sign at other
	Provide automatic door opening device at one door and is a directional sign at other
Barrier Severity:	
Barrier Severity: Implementation	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58D
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	3 second sweep
Rec. Solution:	Provide automatic door opening device at one door and ISA directional sign at other
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58E
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	49" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	
•	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	· _ · _ · _ · _ · · _ · · · · · · · · ·



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58F
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Door Stop
Code References:	2010 ADAS 404.2.10
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door stop interrupts min.10" smooth bottom surface
Findings:	Door stop at bottom of door can create trapping condition
Rec. Solution:	Remove door stop or other element at bottom of door at push side
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58G
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Doors or Gates
Barrier Area:	Doors or Gates
Barrier Area: Barrier Type: Code	Doors or Gates Headroom - Existing 2010 ADAS 404.2.3
Barrier Area: Barrier Type: Code References:	Doors or Gates Headroom - Existing 2010 ADAS 404.2.3
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Doors or Gates Headroom - Existing 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Doors or Gates Headroom - Existing 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1 Door/Gate clearance not min. 80" high
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Doors or Gates Headroom - Existing 2010 ADAS 404.2.3 ndard: No Quantity: EACH As-built: 1 Door/Gate clearance not min. 80" high 79" high
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Doors or Gates Headroom - Existing 2010 ADAS 404.2.3 Indard: No Quantity: EACH As-built: 1 Door/Gate clearance not min. 80" high 79" high Replace door or gate 3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58H
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Passage
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Exit thru an exit enclosure/exit passageway lacks tactile exit sign
Findings:	Passageway to exterior exit with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT ROUTE" at exit side of door
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 581
Field Date: Bldg Name:	2/4/2017 Report Date 3/23/2017 Barrier #: 58I Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 330
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 330 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 330 N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 330 N/A Y Coordinate: N/A Signage ISA - Non-Accessible Entry 2010 ADAS 216.6
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 330 N/A Y Coordinate: N/A Signage ISA - Non-Accessible Entry 2010 ADAS 216.6
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 330 N/A Y Coordinate: N/A Signage ISA - Non-Accessible Entry 2010 ADAS 216.6 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 330 N/A Y Coordinate: N/A Signage ISA - Non-Accessible Entry 2010 ADAS 216.6 ndard: No Quantity: EACH As-built: 1 Sign directing people to accessible entrance needed where all doors are not accessible
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 330 N/A Y Coordinate: N/A Signage ISA - Non-Accessible Entry 2010 ADAS 216.6 Indard: No Quantity: EACH As-built: 1 Sign directing people to accessible entrance needed where all doors are not accessible Accessible sign not provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 330 N/A Y Coordinate: N/A Signage ISA - Non-Accessible Entry 2010 ADAS 216.6 Marcing people to accessible entrance needed where all doors are not accessible Accessible sign not provided Provide ISA directional sign indicating location of and route to accessible entrance 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58J
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	11 lbf
Rec. Solution:	Provide ISA directional sign indicating location of and route to accessible entrance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58K
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	4 second sweep
Rec. Solution:	Provide ISA directional sign indicating location of and route to accessible entrance
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58L
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - New Construction
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	48" high
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	2 Recommended Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58M
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Door Stop
Code References:	2010 ADAS 404.2.10
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door stop interrupts min.10" smooth bottom surface
Findings:	Door stop at bottom of door can create trapping condition
Rec. Solution:	Remove door stop or other element at bottom of door at push side in the case of an emergency
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58N
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Landing - Existing (2.1% to 3.0%)
Code References:	2010 ADAS 404.2.4.4
Performance Sta	andard: No Quantity: SF As-built: 0
Barrier Description:	Door or gate lacks landing on both sides of door
Findings:	2.7% slope
Rec. Solution:	Provide ISA directional sign indicating location of and route to accessible entrance
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 580
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: EACH As-built: 0
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	6" strike edge clearance
Rec. Solution:	Provide ISA directional sign indicating location of and route to accessible entrance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58P
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Headroom - Existing
Code References:	2010 ADAS 404.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate clearance not min. 80" high
Findings:	79" high
Rec. Solution:	Provide ISA directional sign indicating location of and route to accessible entrance
Barrier Severity:	3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58Q
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Passage
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Exit thru an exit enclosure/exit passageway lacks tactile exit sign
Findings:	Passageway to exterior exit with low level illuminated sign lacks tactile exit sign
Findings: Rec. Solution:	Passageway to exterior exit with low level illuminated sign lacks tactile exit sign Provide sign stating "EXIT ROUTE" at exit side of door
J	Provide sign stating "EXIT ROUTE" at exit side of door
Rec. Solution:	Provide sign stating "EXIT ROUTE" at exit side of door 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58R
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58S
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Touch screen 49" high. Emergency phone 50" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	
Implomentation	3 Hindrance Cost Est \$1,500.00 Facility Function: Public Status: Open
implementation	3 Hindrance Cost Est \$1,500.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58T
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Protruding Object - Wall-mounted
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Wall mounted object protrudes more than 4" from wall
Findings:	Emergency phone protrudes 7" at 48" high
Rec. Solution:	Remove object or provide detectable warning for the visually impaired
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58U
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
	Classrooms
Barrier Type:	Classrooms Passageway - Min. 36" (Stored Item)
Barrier Type: Code References:	
Code	Passageway - Min. 36" (Stored Item) 2010 ADAS 404.2.9
Code References:	Passageway - Min. 36" (Stored Item) 2010 ADAS 404.2.9
Code References: Performance Sta Barrier	Passageway - Min. 36" (Stored Item) 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1
Code References: Performance Sta Barrier Description: Findings:	Passageway - Min. 36" (Stored Item) 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Passageway is not min. 36" wide
Code References: Performance Sta Barrier Description: Findings:	Passageway - Min. 36" (Stored Item) 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Passageway is not min. 36" wide Circulation route through classroom not min. 36"
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Passageway - Min. 36" (Stored Item) 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Passageway is not min. 36" wide Circulation route through classroom not min. 36" Rearrange furniture to provide accessible circulation path 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58V
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Ratio
Code References:	2010 ADAS 902
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	At least 1 desk or 5% of all desks not accessible
Findings:	56 desks provided and 1 desk identified as accessible
Rec. Solution:	Provide min. 2 additional accessible desks
Barrier Severity:	3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58W
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Integration
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Desk not integrated into assembly seating
Findings:	Existing accessible desk identified as accessible is not integrated into typical seating
Rec. Solution:	Move desk to integrated setting
Barrier Severity:	2 Necessary Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58X
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Floor Surface - Slope
Code References:	2010 ADAS 302 & 303
Performance Sta	ndard: No Quantity: SF As-built : 0
Barrier Description:	Floor surface slope exceeds 2.0%
Findings:	3.0% slope 5' wide x 32' long stretching the entire width of classroom
Rec. Solution:	No remediation recommended. Entire classroom floor is not part of an accessible route.
Barrier Severity:	2 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58Y
ricia Date.	2/4/2017 Report Date 3/23/2017 Darrier #. 381
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 330
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 330 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 330 N/A Y Coordinate: N/A Counters and Tables
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 330 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 330 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 330 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 330 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 330 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide 25-1/2" high knee clearance at instructors desk where students may give presentations
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Classroom 330 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide 25-1/2" high knee clearance at instructors desk where students may give presentations Provide min. 1 accessible table. Avoid pedestal base tables. 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58Z
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Podium - Surface Height
Code References:	2010 ADAS 504.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Surface height exceeds 34" high
Findings:	36" surface height at portable podium
Rec. Solution:	Provide min. 1 accessible podium
Barrier Severity:	4 Low Severity Cost Est \$1,275.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58AA
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	
	N/A Y Coordinate: N/A
Barrier Area:	N/A Y Coordinate: N/A Classrooms
Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Classrooms Electrical Outlets - High Unobstructed 2010 ADAS 505.10.2
Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Classrooms Electrical Outlets - High Unobstructed 2010 ADAS 505.10.2
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Y Coordinate: N/A Classrooms Electrical Outlets - High Unobstructed 2010 ADAS 505.10.2 ndard: No Quantity: EACH As-built: 1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Y Coordinate: N/A Classrooms Electrical Outlets - High Unobstructed 2010 ADAS 505.10.2 ndard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Classrooms Electrical Outlets - High Unobstructed 2010 ADAS 505.10.2 ndard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 12" high
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Y Coordinate: N/A Classrooms Electrical Outlets - High Unobstructed 2010 ADAS 505.10.2 Indard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 12" high Relocate outlet to min. 15" or max. 48" high 2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58AB
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Podium - Knee Clearance
Code References:	2010 ADAS 504.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Podium knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	14-1/2" deep knee clearance
Rec. Solution:	Provide min. 1 accessible podium
Barrier Severity:	4 Low Severity Cost Est \$1,275.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58AC
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Keyboard shelf protrudes 11" at 35" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/4/2017 Report Date 3/23/2017 Barrier #: 58AD
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Classroom 330
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Alarm - No Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/stobe
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
-	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 59A
Field Date: Bldg Name:	2/5/2017 Report Date 3/23/2017 Barrier #: 59A Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0303
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0303 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0303 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0303 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0303 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0303 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 ndard: No Quantity: EACH As-built: 12
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0303 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 ndard: No Quantity: EACH As-built: 12 No sign with raised characters and Braille at permanent room or space with visual sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0303 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 ndard: No Quantity: EACH As-built: 12 No sign with raised characters and Braille at permanent room or space with visual sign No tactile info on signs with visual information
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0303 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 ndard: No Quantity: EACH As-built: 12 No sign with raised characters and Braille at permanent room or space with visual sign No tactile info on signs with visual information Provide signs at latch side of entry door, where possible 1 Necessary Cost Est \$3,000.00 Facility Function: Public Status: Open



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 59B
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0303
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Horn/Strobe Device
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn or strobe in corridor where fire alarm exists in building
Findings:	No horn/strobe provided
Rec. Solution:	Provide horn/strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 59C
Field Date: Bldg Name:	2/5/2017 Report Date 3/23/2017 Barrier #: 59C Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0303
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0303 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0303 N/A Y Coordinate: N/A Alarms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0303 N/A Y Coordinate: N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0303 N/A Y Coordinate: N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0303 N/A Y Coordinate: N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0303 N/A Y Coordinate: N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2 ndard: No Quantity: JOB As-built: 1 Fire extinguisher protrudes into circulation path more than 4" between 27" and 80"
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0303 N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2 Indard: No Quantity: JOB As-built: 1 Fire extinguisher protrudes into circulation path more than 4" between 27" and 80" Fire extinguisher protrudes 4-1/2" at 37" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Hall H0303 N/A Y Coordinate: N/A Alarms Fire Extinguisher - Protruding Object 2010 ADAS 307.2 Index No Quantity: JOB As-built: 1 Fire extinguisher protrudes into circulation path more than 4" between 27" and 80" Fire extinguisher protrudes 4-1/2" at 37" high Remount extinguisher with leading edge below 27" or provide detectable warning 4 Low Severity Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 59D
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0303
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	2010 ADAS 505.10.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12" high
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 59E
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0303
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Floor Surface - Slope
Code References:	2010 ADAS 302 & 303
Performance Sta	andard: No Quantity: SF As-built: 15
Barrier Description:	Floor surface slope exceeds 2.0%
Findings:	4.1% slope
Rec. Solution:	Remodel to provide level clear floor space at controls/mechanisms
Barrier Severity:	2 Necessary Cost Est \$8,625.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 59F
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hall H0303
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Floor Surface - Slope
Code References:	2010 ADAS 302 & 303
Performance Sta	ndard: No Quantity: SF As-built: 15
Barrier Description:	Floor surface slope exceeds 2.0%
Findings:	6.2% slope
Rec. Solution:	Remodel to provide level clear floor space at controls/mechanisms
Barrier Severity:	2 Necessary Cost Est \$8,625.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 60A
Field Date: Bldg Name:	2/5/2017 Report Date 3/23/2017 Barrier #: 60A Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1 No horn or strobe in corridor where fire alarm exists in building
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1 No horn or strobe in corridor where fire alarm exists in building No horn/strobe provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1 No horn or strobe in corridor where fire alarm exists in building No horn/strobe provided Provide horn/strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 60B
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Vestibule V0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	2010 ADAS 505.10.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12" high
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 60C
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Vestibule V0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Stairway
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built : 1
Barrier Description:	Door leading directly into an exit stairway lacks tactile exit sign
Findings:	Door to exit stair with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT STAIR DOWN (or UP)" at latch side of door
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 60D
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Vestibule V0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door Closer - Exterior Adjustment
Code References:	Performance Standard
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 8.5 lbf
Findings:	16 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 60E
Field Date: Bldg Name:	2/5/2017 Report Date 3/23/2017 Barrier #: 60E Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Corridors Door Closer - Exterior Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Corridors Door Closer - Exterior Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Corridors Door Closer - Exterior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Corridors Door Closer - Exterior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Corridors Door Closer - Exterior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period 1 second sweep
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Corridors Door Closer - Exterior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period 1 second sweep Replace or adjust existing closer 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 60F
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Vestibule V0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door - Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Door knob not accessible
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 60G
Field Date: Bldg Name:	2/5/2017 Report Date 3/23/2017 Barrier #: 60G Moreland Hall Reference Dwg: 5 of 5
	The state of the s
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer 8" strike edge clearance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Vestibule V0301 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer 8" strike edge clearance No remediation recommended. Door is not part of an accessible route. 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 60H
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Vestibule V0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Threshold - Height exceeding 1/2"
Code References:	2010 ADAS 404.2.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate threshold exceeds 1/2" in height
Findings:	2" lip at fire escape
Rec. Solution:	No remediation recommended. Door is not part of an accessible route.
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 61A
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Graduate Student Office 304
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 61B
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Graduate Student Office 304
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 61C
Field Date: Bldg Name:	2/5/2017 Report Date 3/23/2017 Barrier #: 61C Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 304
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 304 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (3.1% to 4.0%)
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 304 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 304 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (3.1% to 4.0%) 2010 ADAS 404.2.4.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 304 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (3.1% to 4.0%) 2010 ADAS 404.2.4.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 304 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (3.1% to 4.0%) 2010 ADAS 404.2.4.4 ndard: No Quantity: SF As-built: 40
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 304 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (3.1% to 4.0%) 2010 ADAS 404.2.4.4 ndard: No Quantity: SF As-built: 40 Door or gate lacks landing on both sides of door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 304 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (3.1% to 4.0%) 2010 ADAS 404.2.4.4 ndard: No Quantity: SF As-built: 40 Door or gate lacks landing on both sides of door 3.7% slope at both sides of door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 304 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (3.1% to 4.0%) 2010 ADAS 404.2.4.4 ndard: No Quantity: SF As-built: 40 Door or gate lacks landing on both sides of door 3.7% slope at both sides of door Demolish and reconstruct level landing 3 Hindrance Cost Est \$5,000.00 Facility Function: Public Status: Open



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 61D
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Graduate Student Office 304
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 60" - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at with min. 18" at pull side lacks min. 60" perpendicular to door
Findings:	51-1/2" perpendicular due to placement of table
Rec. Solution:	Rearrange furniture to provide accessible maneuvering clearance at door
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 61E
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Graduate Student Office 304
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Walkways
Barrier Type:	Cross Slope - Existing (4.1% to 4.9%)
Code References:	2010 ADAS 403.3
Performance Sta	andard: No Quantity: LF As-built: 23
Barrier Description:	Cross slope exceeds 2.0% (4.1% to 4.9%)
Findings:	4.6% cross slope
Rec. Solution:	Demolish existing and construct new route
Barrier Severity:	2 Recommended Cost Est \$2,875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 61F
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Graduate Student Office 304
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Landing - Control or Mechanism
Code References:	2010 ADAS 305.2
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Control or mechanism not located on a level landing
Findings:	4.6% slope at electrical switch
Rec. Solution:	Relocate device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 61G
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Graduate Student Office 304
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	Cost Est ATE OD Facility Functions D. Liv. Status: O.
	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 61H
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Graduate Student Office 304
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 305
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	36" turning space
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 611
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Graduate Student Office 304
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	andard: No Quantity: JOB As-built: 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	Circulation route through room not min. 36"
Rec. Solution:	Rearrange furniture to provide accessible circulation path
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 61J
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Graduate Student Office 304
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Chair and table blocks whiteboard and electrical outlet clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 61K
Field Date: Bldg Name:	2/5/2017 Report Date 3/23/2017 Barrier #: 61K Moreland Hall Reference Dwg: 5 of 5
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 304
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 304 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 304 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 304 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - High Unobstructed 2010 ADAS 308.2.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 304 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - High Unobstructed 2010 ADAS 308.2.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 304 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - High Unobstructed 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 304 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - High Unobstructed 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 304 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - High Unobstructed 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 10" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 304 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - High Unobstructed 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 10" high Relocate outlet to min. 15" or max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 61L				
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5				
Location:	Floor 3 - Graduate Student Office 304				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Counters and Tables				
Barrier Type:	Table - Pedestal Base				
Code References:	2010 ADAS 306.2.2 & 306.2.3				
Performance Sta	ndard: No Quantity: EACH As-built : 1				
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide				
Findings:	Pedestal base blocks knee clearance				
Rec. Solution:	Provide min. 1 accessible table. Avoid pedestal base tables.				
Barrier Severity:	2 Recommended Cost Est \$450.00 Facility Function: Public Status: Open				
Implementation	Priority: 2 Implementation Phase: Implementation Date:				
Notes:					
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 61M				
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5				
Location:	Floor 3 - Graduate Student Office 304				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Clear Floor Space				
Barrier Type:	Jereal Floor Space				
	Cords in Accessible Route				
Code References:					
	Cords in Accessible Route 2010 ADAS 303.3				
References:	Cords in Accessible Route 2010 ADAS 303.3				
References: Performance Sta Barrier	Cords in Accessible Route 2010 ADAS 303.3 Indard: No Quantity: JOB As-built: 1				
References: Performance Sta Barrier Description:	Cords in Accessible Route 2010 ADAS 303.3 Indard: No Quantity: JOB As-built: 1 Change in level greater than 1/2" in clear floor space at cords				
References: Performance Sta Barrier Description: Findings:	Cords in Accessible Route 2010 ADAS 303.3 Indard: No Quantity: JOB As-built: 1 Change in level greater than 1/2" in clear floor space at cords Cords create trip hazard Provide accessible cord cover or otherwise remove barrier to access				
References: Performance Sta Barrier Description: Findings: Rec. Solution:	Cords in Accessible Route 2010 ADAS 303.3 ndard: No Quantity: JOB As-built: 1 Change in level greater than 1/2" in clear floor space at cords Cords create trip hazard Provide accessible cord cover or otherwise remove barrier to access 1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open				



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 61N				
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5				
Location:	Floor 3 - Graduate Student Office 304				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Alarms				
Barrier Type:	Horn/Strobe - Common Use Area				
Code References:	2010 ADAS 702.1				
Performance Sta	ndard: No Quantity: EACH As-built : 1				
Barrier Description:	No horn/strobes in common use areas				
Findings:	No device provided				
Rec. Solution:	Provide strobe in common use area				
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open				
Implementation	Priority: 2 Implementation Phase: Implementation Date:				
Notes:					
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 62A				
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5				
Diag Name.	INFORMATION INCIDENCE SWIG. 5 01 5				
Location:	Floor 3 - Graduate Student Office 300				
_					
Location:	Floor 3 - Graduate Student Office 300				
Location: X Coordinate:	Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A				
Location: X Coordinate: Barrier Area:	Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Signage				
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2				
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2				
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 1				
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs				
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route				
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open				



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 62B				
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5				
Location:	Floor 3 - Graduate Student Office 300				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Doors or Gates				
Barrier Type:	Hardware - Operation				
Code References:	2010 ADAS 404.2.7				
Performance Sta	ndard: No Quantity: EACH As-built : 1				
Barrier Description:	Hardware not operable with a closed fist				
Findings:	Hardware not accessible				
Rec. Solution:	Provide new hardware				
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open				
Implementation	Priority: 2 Implementation Phase: Implementation Date:				
Notes:					
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 62C				
Field Date: Bldg Name:	2/5/2017 Report Date 3/23/2017 Barrier #: 62C Moreland Hall Reference Dwg: 5 of 5				
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5				
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300				
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A				
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Doors or Gates				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 Indard: No Quantity: EACH As-built: 1				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 Indard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground 44" high				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 Indard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground 44" high Replace door/gate or vision panel 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open				



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 62D				
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5				
Location:	Floor 3 - Graduate Student Office 300				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Doors or Gates				
Barrier Type:	Threshold - Height exceeding 1/2"				
Code References:	2010 ADAS 404.2.5				
Performance Sta	ndard: No Quantity: EACH As-built : 1				
Barrier Description:	Door/Gate threshold exceeds 1/2" in height				
Findings:	7/8" lip				
Rec. Solution:	Provide new door threshold				
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open				
Implementation	Priority: 2 Implementation Phase: Implementation Date:				
Notes:					
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 62E				
Field Date: Bldg Name:	2/5/2017 Report Date 3/23/2017 Barrier #: 62E Moreland Hall Reference Dwg: 5 of 5				
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5				
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300				
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A				
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Doors or Gates				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (4.1% to 4.9%) 2010 ADAS 404.2.4.4				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (4.1% to 4.9%) 2010 ADAS 404.2.4.4				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (4.1% to 4.9%) 2010 ADAS 404.2.4.4 ndard: No Quantity: SF As-built: 20				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (4.1% to 4.9%) 2010 ADAS 404.2.4.4 ndard: No Quantity: SF As-built: 20 Door or gate lacks landing on both sides of door				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (4.1% to 4.9%) 2010 ADAS 404.2.4.4 ndard: No Quantity: SF As-built: 20 Door or gate lacks landing on both sides of door 4.1% slope				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Doors or Gates Landing - Existing (4.1% to 4.9%) 2010 ADAS 404.2.4.4 ndard: No Quantity: SF As-built: 20 Door or gate lacks landing on both sides of door 4.1% slope Demolish and reconstruct level landing 2 Recommended Cost Est \$2,500.00 Facility Function: Public Status: Open				



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 62F				
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5				
Location:	Floor 3 - Graduate Student Office 300				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Doors or Gates				
Barrier Type:	Front App/pull 18" SEC - Blocked				
Code References:	2010 ADAS Figure 404.2.4.1				
Performance Sta	ndard: No Quantity: ADMINI As-built : 1				
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side				
Findings:	9-1/2" strike edge clearance				
Rec. Solution:	Rearrange furniture to provide accessible maneuvering clearance at door				
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open				
Implementation	Priority: 2 Implementation Phase: Implementation Date:				
Notes:					
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 62G				
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5				
Location:					
	Floor 3 - Graduate Student Office 300				
X Coordinate:	Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A				
X Coordinate: Barrier Area:					
	N/A Y Coordinate: N/A				
Barrier Area:	N/A Y Coordinate: N/A Controls and Mechanisms				
Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2				
Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2				
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1				
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high				
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 56-1/2" high				
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high Relocate switch box top edge to max. 48" high Relocate switch box top edge to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open				



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 62H				
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5				
Location:	Floor 3 - Graduate Student Office 300				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Controls and Mechanisms				
Barrier Type:	Coat Hook - Clear Floor Space				
Code References:	2010 ADAS 603.4				
Performance Sta	ndard: No Quantity: EACH As-built : 0				
Barrier Description:	Clothing hooks not located within 30" x 48" clear floor space				
Findings:	Chair blocks coat hook clear floor space				
Rec. Solution:	Move chair as needed				
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open				
Implementation	Priority: 2 Implementation Phase: Implementation Date:				
Notes:					
Field Date:	A CONTRACT OF THE CONTRACT OF				
i leiu Date.	2/5/2017 Report Date 3/23/2017 Barrier #: 621				
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5				
	20, 188				
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5				
Bldg Name: Location:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300				
Bldg Name: Location: X Coordinate:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A				
Bldg Name: Location: X Coordinate: Barrier Area:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Clear Floor Space				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 305				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 305				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 305 ndard: No Quantity: JOB As-built: 1				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 305 ndard: No Quantity: JOB As-built: 1 Clear floor space of min. 60" in diameter not provided where 360 degree turn is made				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 305 ndard: No Quantity: JOB As-built: 1 Clear floor space of min. 60" in diameter not provided where 360 degree turn is made 57-1/2" turning space				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Moreland Hall Reference Dwg: 5 of 5 Floor 3 - Graduate Student Office 300 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 305 ndard: No Quantity: JOB As-built: 1 Clear floor space of min. 60" in diameter not provided where 360 degree turn is made 57-1/2" turning space Move stored items blocking maneuvering clearance 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open				



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 62J				
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5				
Location:	Floor 3 - Graduate Student Office 300				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Controls and Mechanisms				
Barrier Type:	Clear Floor Space - Stored Elements				
Code References:	2010 ADAS 305.3				
Performance Sta	andard: No Quantity: JOB As-built: 1				
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism				
Findings:	Desk blocks electrical outlet clear floor space				
Rec. Solution:	Move stored items or provide outlet in accessible location				
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open				
Implementation	Priority: 2 Implementation Phase: Implementation Date:				
Notes:					
Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 62K				
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5				
Location:	Floor 3 - Graduate Student Office 300				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Controls and Mechanisms				
Barrier Type:	Electrical Outlets - High Unobstructed				
Code References:	2010 ADAS 308.2.2				
Performance Sta	andard: No Quantity: EACH As-built : 1				
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high				
Findings:	11-1/2" high				
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high				
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open				
Implementation Priority: 2 Implementation Phase: Implementation Date:					
Notes:					



Field Date:	2/5/2017 Report Date 3/23/2017 Barrier #: 62L				
Bldg Name:	Moreland Hall Reference Dwg: 5 of 5				
Location:	Floor 3 - Graduate Student Office 300				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Alarms				
Barrier Type:	Horn/Strobe - Staff Area				
Code References:	2010 ADAS 702.1				
Performance Sta	ndard: No Quantity: EACH As-built : 1				
Barrier Description:	No horn/strobe in staff areas				
Findings:	No device provided				
Rec. Solution:	Provide as an ADA Title I Accommodation				
Barrier Severity:	3 Hindrance Cost Est \$5,500.00 Facility Function: Public Status: Open				
Implementation	Priority: 2 Implementation Phase: Implementation Date:				
Notes:					





SUMMARY REPORT

Cost Estimate Total	\$1,257,975.00		
Cost Estimate - Priority 1:	\$22,050.00	% of Total Cost Estimate:	1.75%
Cost Estimate - Priority 2:	\$754,190.00	% of Total Cost Estimate:	59.95%
Cost Estimate - Priority 3:	\$476,235.00	% of Total Cost Estimate:	37.86%