SZS CONSULTING GROUP

ARNOLD DINING CENTER

ADA ASSESSMENT & SURVEY



Sacramento Office 770 L Street, Suite 950 Sacramento, CA 95814 Tel: 916.669.8750 Fax: 888.211.7441

Silicon Valley Office 2225 E. Bayshore Road, Suite 200

Palo Alto CA 94303 Tel: 866.694.7637 www.szs-consulting.com

January 9, 2015



Angelo Gomez Executive Director Office of Equity and Inclusion Oregon State University 330 Snell Hall Corvallis, OR 97331-2128

Re: ADA Accessibility Survey and Assessment - Arnold Dining Center

Dear Angelo,

We are pleased to submit this report for the Arnold Dining Center. This report is part of our project to provide a Campus Accessibility Survey and Assessment for Oregon State University. It is our hope that this report will assist OSU in improving access to people with disabilities to campus facilities.

SZS has been pleased to be a part of this effort to evaluate campus buildings using federal and state statutes and regulations, as well as universal design principles in order to create performance standards that will guide design, construction and maintenance on campus.

We look forward to discussing our findings with your team.

Regards,

Syroun Z. Sanossian, Principal

Syn 2. 8m.

SZS Consulting Group LLC

TABLE OF CONTENTS

Ι.	EXECUTIV	VE SUMMARY OF FINDINGS	p. 1
	a.	Pedestrian Facilities and Exterior Spaces Analyzed	p. 2
	b.	Building Entrances	p. 3
2.	INTERIOR	SPACES	p. 3
3.	BARRIER	R DATA RECORDS	
		Exterior Area Barriers	p. 5
		Interior Area Barriers	p. 11
		Cost Estimate	p. 54

1. EXECUTIVE SUMMARY OF FINDINGS

The field investigation for the interior spaces began on February 19, 2014. The exterior site elements were assessed originally as part of the pedestrian facilities assessment in June-September 2011 and are included as an essential part of this report. Images of each physical element identified in this report were captured in HD digital photos while manual measurements were taken to establish as-built conditions to facilitate the process of cost estimating. Digital photographs are provided within the report for each barrier to access, to facilitate the review of the data collected. We have found that technical data can be difficult to interpret without a visual component; the photos provide a clear connection between the technical data and each barrier to access.

The Arnold Dining Center is considered a pre-ADA structure and many barriers to access were identified in the building. That is quite typical, as barriers to access exist in virtually every building, whether new or existing.

No "perfect" building exists in the real world.

This ADA Assessment and Survey report is intended to not only identify barriers to access, but to provide solutions. The basis for this ADA Assessment and Survey process is the underlying desire on the part of OSU to improve access by relying on higher standards than the minimum requirements in state and federal building codes. SZS intends to provide the information in this report in a clear and easy to understand format. The information in this report is compiled for use by designated OSU staff and other interested persons, so the content is designed to be understood by professionals and laymen alike.

The findings presented are both narrative and technical in nature; barriers to access identified during the field investigation process are documented in two ways;

Narrative Analysis: The analysis of findings is contained in an executive summary in a
narrative form that not only describes each type of barrier identified but also provides a
discussion that analyses the functionality of physical elements. We also provide the
reasoning and research behind the identification of barriers that conflict with universal
design principles. This analysis may be accompanied by digital photographs or
diagrams, where applicable.

NOTE: Understanding building function and usage is essential when interpreting the findings held in this report. The narrative is intended to facilitate this process.

2. <u>Barrier Data Records:</u> Individual barriers to access are entered into the SZS database so that technical information on the barriers can be provided as barrier data records. These barrier data records include digital photographs of each barrier identified, code references that determine the barrier to access, as-built measurements, barrier severity ratings, budgetary cost estimates, recommended solutions for barrier removal and a priority for barrier removal. The information is formatted with two barriers on each report page.

In order to consolidate the report data, some of the more typical barriers found in multiple locations have been grouped within the barrier data records with a description of the locations in which they were found.

A. Pedestrian Facilities and Exterior Spaces Analyzed

This report provides information on campus pedestrian facilities that serve the Arnold Dining Center. Many physical elements are part of the comprehensive whole that creates a pedestrian facility. The fundamental elements evaluated as to whether they provide accessible pedestrian facilities include the following:

- Sidew alks
- Walkw ays
- Ramps
- Curb Ramps
- **Blended Transitions**
- Signalized Intersections
- Stairw ays (94% of people with disabilities are not mobility impaired)
- Benches and other Seating Elements
- Picnic Facilities

The descriptions provided for physical elements in this report are intended to clearly describe the differences between each physical element, such as when a pedestrian route is a sidewalk, rather than a walkway. The descriptions are intended to explain how the elements interact to form a cohesive pedestrian facility. Other more specific information described within this section intends to provide guidance on determinations made in this report.

The key to providing accessible pedestrian facilities is in recognizing that different people with disabilities have different needs. Setting policies that speak to the entire group is essential, rather than focusing one particular subset of the overall group. Universal design principles govern here - physical elements should be usable to everyone that visits campus without having to resort to any adaptation or specialized design.

In summary, an accessible route exists within a building, property boundary or interior space and is separate from the PROW. Pedestrian walkways are similar to sidewalks as paved surfaces improved for use by pedestrians but walkways are not located along or adjacent to the curb line, gutter or roadway and walkways are generally not considered part of the PROW. The pedestrian facility is the combination of the PROW and the accessible route, which functions as a whole to provide pedestrian access to facility entrances.

As a public building governed by the ADA Standards, the Arnold Dining Center should have at least one accessible entrance. Two accessible entrances are provided on the east side of this building which faces the INTO building and other residence halls. Both entry door vestibules are provided with automatic door opening devices. The Arnold Dining Center has an accessible route provided within the site from accessible parking spaces located in a nearby parking lot and accessible passenger loading zones; public streets and sidewalks;

and public transportation stops to the accessible building or facility entrance they serve as compared to the 2010 ADA Standard for Accessible Design. Details on barriers identified in that route are provided within the ADA Assessment and Survey of the pedestrian facilities provided as a separate report, as well as in the following records. Please see the barrier data records for details.

B. Building Entrances

The building is located in the center of several residence halls southeast of parking structure 1. Pedestrian entrances to the building are provided on the east side of the building in two locations and multiple staff entrances are located on all of the other sides of the building. Both public entry doors are equipped with an automatic door opening device. It is recommended to install ISA directional signs at the other non-accessible doors.

INTERIOR SPACES

The Arnold Dining Center is a single story structure. The building is a pre-ADA structure and much of the building is used for food preparation or storage and accessed only by staff members. The dining staff also has offices and a catering service located in the dining center. The building contains two lobbies, a mailroom, one large open dining area, one large open food service area with multiple counters and men and women's multi-accommodation restrooms. Meeting and conference rooms are also located in the building.

As described above, the east side of the building has two sets of entry door vestibules and both doors are provided with automatic door opening devices and ISA signage. A number of other entrance doors exist around the perimeter of the building and those doors should be provided with ISA directional signs. The exterior entrance to the Marketplace department office was equipped with an automatic door opening device but the device is not functional. The exterior entry door was also equipped with a BHMA sign but no ISA sign was posted at the entrance. The interior space is used for meetings and was identified with pedestal based tables that were not accessible to people with mobility impairments.

Other barriers identified at the east entrances include non-secured door mats, and no tactile exit signs were provided. The lobby/entry area at both doors lacked lobby informational signs, the mail room lacked accessible mailboxes and the PC workstation in the lobby was not accessible. As a performance standard, it is recommended that lobby identification signage be provided that indicates the floor plan, the location of the person viewing the sign and the location of accessible features such as restrooms in proximity to the location of the person reading the sign. The accessible restrooms provided in the building are located in an alcove that could be difficult to locate without directions.

The service counter at the information desk was constructed with a lower section of counter space but the lower counter was blocked by a horizontal door that remains closed during business hours. Staff members working at the information counter have a key for the lock on the door but the counter remains closed otherwise. The concern with that counter is that it is not usable when people approach for assistance. Past that, the low section of counter is not at least 3 feet long.


¹ 2010 ADA Standards for Accessible Design, Section 206.2.1 Site Arrival Points

The men and women's multi-accommodation restrooms are located in the southeast lobby area and a unisex accessible restroom is located in the main dining area. The unisex restroom was identified with barriers to access including protruding dispensers and a lack of an ISA symbol at the actuator for the automatic door opening device. This is an issue at all automatic door opening actuators in the building. The entry vestibule to the multi-accommodation restrooms was identified with an AED device and PRIDE drop box, which both created protruding hazards in the pathway to the men's restroom.

The multi-accommodation restrooms were identified with signage that was not accessible, automatic door opening devices that did not remain open for at least 6 seconds, non-accessible dispensers were identified that protruded into the circulation route, and lavatory counters and rims were not accessible, which is problematic for both short people and people who use wheelchairs. The toilet stalls were also identified as lacking accessible door hardware and dispensers.

No drinking fountain was identified in the building, although water dispensers were provided in the food service area. This fact makes it important to ensure that the water dispensers are located in accessible locations (accessible counters) and the controls should be located within accessible

reach ranges. The food service area provided a number of separate food service areas with separate order and pickup counters. The cashiers counters were all measured at a height exceeding 34" above the floor. Maneuvering clearance between the food service counters is accessible but none of the counters in the food service area were accessible in terms of counter height, reach range to soda fountains, refrigerated food displays, shelves or pickup counters above 48" high (see figure at right). Recycling center counters and tray drop off counters were also not accessible. Remodeling will be necessary to provide w heelchair access at each café and restaurant.



The open dining area was identified with a number of different types and sizes of dining tables in addition to a lengthy high dining counter with chairs. Not all tables need to be accessible, but at least one of each type of table (4-person, 6-person etc.) should be accessible or where more than 20 of one type exists, at least 5% overall should be accessible and dispersed within the dining area. Each type of food service area (Nomi Sushi, Pizzeria, International Faire, salad/dessert bar, etc.) should also be accessible including the tray slide where food can be viewed, chosen and served and condiment tables where utensils, napkins, water coolers, etc. are provided. Reach range at these elements was not accessible throughout the dining area to include fruit stands, deli counters with viewing and serving height above accessible ranges. No accessible dining tables, booths or counters were provided in this building.

Conference or meeting rooms in this building were also identified as lacking accessible signage, entry doors and tables or counters. Many staff use only areas were identified in the building. These spaces include preparation areas, workrooms, offices and associated spaces. Signage at the door/doorway to these spaces was included in this report as it is located along the public circulation route of travel, but these interior spaces were not investigated as part of this assessment process. In general, institutions and organizations make staff-use-only areas accessible as needed through the reasonable accommodation process between the employer and employee. The following barrier data records provide more detailed information on the barriers described above.





Field Date:	8/10/2011 Report Date 8/10/2011 Barrier #: 1499A
Bldg Name:	Arnold Dining Center Reference Dwg: 1 of 2
Location:	Exterior - South East Entrance
X Coordinate:	7478286.889 Y Coordinate: 338266.039
Barrier Area:	Signage
Barrier Type:	ISA - Non-Accessible Entry
Code References:	2010 ADAS 404.2.4.4
Performance S	Standard: No Quantity: EACH As-built: 1
Barrier Description:	Sign directing people to accessible entrance needed where all doors are not accessible
Findings:	Accessible sign not provided
Rec. Solution:	Provide ISA directional sign with arrow directing people to accessible entrance
Barrier Severit	y: 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	on Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	8/10/2011 Report Date 8/10/2011 Barrier #: 1499B
Field Date: Bldg Name:	8/10/2011 Report Date 8/10/2011 Barrier #: 1499B Arnold Dining Center Reference Dwg: 1 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South East Entrance
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South East Entrance
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South East Entrance 7478286.889 Y Coordinate: 338266.039
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South East Entrance 7478286.889 Y Coordinate: 338266.039 Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South East Entrance 7478286.889 Y Coordinate: 338266.039 Doors or Gates Door/Gate Landing - Existing (3.1% to 4.0%) 2010 ADAS 404.2.4.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South East Entrance 7478286.889 Y Coordinate: 338266.039 Doors or Gates Door/Gate Landing - Existing (3.1% to 4.0%) 2010 ADAS 404.2.4.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South East Entrance 7478286.889 Y Coordinate: 338266.039 Doors or Gates Door/Gate Landing - Existing (3.1% to 4.0%) 2010 ADAS 404.2.4.4 Standard: No Quantity: SF As-built: 125
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South East Entrance 7478286.889 Y Coordinate: 338266.039 Doors or Gates Door/Gate Landing - Existing (3.1% to 4.0%) 2010 ADAS 404.2.4.4 Standard: No Quantity: SF As-built: 125 Door or gate lacks landing on both sides of door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South East Entrance 7478286.889 Y Coordinate: 338266.039 Doors or Gates Door/Gate Landing - Existing (3.1% to 4.0%) 2010 ADAS 404.2.4.4 Standard: No Quantity: SF As-built: 125 Door or gate lacks landing on both sides of door 3.1%
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South East Entrance 7478286.889 Y Coordinate: 338266.039 Doors or Gates Door/Gate Landing - Existing (3.1% to 4.0%) 2010 ADAS 404.2.4.4 Standard: No Quantity: SF As-built: 125 Door or gate lacks landing on both sides of door 3.1% Demolish and reconstruct level landing y: 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	8/10/2011 Report Date 8/10/2011 Barrier #: 1500A
Bldg Name:	Arnold Dining Center Reference Dwg: 1 of 2
Location:	Exterior - South West Entrance
X Coordinate:	7478252.012 Y Coordinate: 338265.422
Barrier Area:	Signage
Barrier Type:	ISA - Non-Accessible Entry
Code References:	2010 ADAS 404.2.4.4
Performance S	tandard: No Quantity: EACH As-built : 1
Barrier Description:	Sign directing people to accessible entrance needed where all doors are not accessible
Findings:	Accessible sign not provided
Rec. Solution:	Provide ISA directional sign with arrow directing people to accessible entrance
Barrier Severit	y: 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	on Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	8/10/2011 Report Date 8/10/2011 Barrier #: 1500B
Field Date: Bldg Name:	8/10/2011 Report Date 8/10/2011 Barrier #: 1500B Arnold Dining Center Reference Dwg: 1 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South West Entrance
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South West Entrance
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South West Entrance 7478252.012 Y Coordinate: 338265.422
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South West Entrance 7478252.012 Y Coordinate: 338265.422 Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South West Entrance 7478252.012 Y Coordinate: 338265.422 Doors or Gates Door/Gate Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South West Entrance 7478252.012 Y Coordinate: 338265.422 Doors or Gates Door/Gate Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South West Entrance 7478252.012 Y Coordinate: 338265.422 Doors or Gates Door/Gate Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 tandard: No Quantity: SF As-built: 125
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South West Entrance 7478252.012 Y Coordinate: 338265.422 Doors or Gates Door/Gate Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 tandard: No Quantity: SF As-built: 125 Door or gate lacks landing on both sides of door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South West Entrance 7478252.012 Y Coordinate: 338265.422 Doors or Gates Door/Gate Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 tandard: No Quantity: SF As-built: 125 Door or gate lacks landing on both sides of door 2.8%
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - South West Entrance 7478252.012 Y Coordinate: 338265.422 Doors or Gates Door/Gate Landing - Existing (2.1% to 3.0%) 2010 ADAS 404.2.4.4 tandard: No Quantity: SF As-built: 125 Door or gate lacks landing on both sides of door 2.8% Demolish and reconstruct level landing y: 4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	8/10/2011 Report Date 8/10/2011 Barrier #: 1494A
Bldg Name:	Arnold Dining Center Reference Dwg: 1 of 2
Location:	Exterior - West Staff Entrance
X Coordinate:	7478152.485 Y Coordinate: 338352.84
Barrier Area:	Signage
Barrier Type:	ISA - Non-Accessible Entry
Code References:	2010 ADAS 404.2.4.4
Performance S	tandard: No Quantity: EACH As-built: 1
Barrier Description:	Sign directing people to accessible entrance needed where all doors are not accessible
Findings:	Accessible sign not provided
Rec. Solution:	Provide ISA directional sign with arrow directing people to accessible entrance
Barrier Severit	y: 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementatio	on Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	8/10/2011 Report Date 8/10/2011 Barrier #: 1494B
Field Date: Bldg Name:	8/10/2011 Report Date 8/10/2011 Barrier #: 1494B Arnold Dining Center Reference Dwg: 1 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Staff Entrance
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Staff Entrance
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Staff Entrance 7478152.485 Y Coordinate: 338352.84
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Staff Entrance 7478152.485 Y Coordinate: 338352.84 Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Staff Entrance 7478152.485 Y Coordinate: 338352.84 Doors or Gates Door/Gate Landing - Existing (≥ 5.0%) 2010 ADAS 404.2.4.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Staff Entrance 7478152.485 Y Coordinate: 338352.84 Doors or Gates Door/Gate Landing - Existing (≥ 5.0%) 2010 ADAS 404.2.4.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Staff Entrance 7478152.485 Y Coordinate: 338352.84 Doors or Gates Door/Gate Landing - Existing (≥ 5.0%) 2010 ADAS 404.2.4.4 standard: No Quantity: SF As-built: 125
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Staff Entrance 7478152.485 Y Coordinate: 338352.84 Doors or Gates Door/Gate Landing - Existing (≥ 5.0%) 2010 ADAS 404.2.4.4 Standard: No Quantity: SF As-built: 125 Door or gate lacks landing on both sides of door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Staff Entrance 7478152.485 Y Coordinate: 338352.84 Doors or Gates Door/Gate Landing - Existing (≥ 5.0%) 2010 ADAS 404.2.4.4 Standard: No Quantity: SF As-built: 125 Door or gate lacks landing on both sides of door 13.4% slope at staff entry
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Staff Entrance 7478152.485 Y Coordinate: 338352.84 Doors or Gates Door/Gate Landing - Existing (≥ 5.0%) 2010 ADAS 404.2.4.4 Extandard: No Quantity: SF As-built: 125 Door or gate lacks landing on both sides of door 13.4% slope at staff entry Demolish and reconstruct level landing y: 4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open




Field Date:	8/10/2011 Report Date 8/10/2011 Barrier #: 1493A
Bldg Name:	Arnold Dining Center Reference Dwg: 1 of 2
Location:	Exterior - West Ramp
X Coordinate:	7478162.286 Y Coordinate: 338387.95
Barrier Area:	Signage
Barrier Type:	ISA - Non-Accessible Entry
Code References:	2010 ADAS 505.2
Performance S	tandard: No Quantity: EACH As-built: 1
Barrier Description:	Sign directing people to accessible entrance needed where all doors are not accessible
Findings:	Accessible sign not provided
Rec. Solution:	Provide ISA directional sign with arrow directing people to accessible entrance
Barrier Severit	y: 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementatio	n Priority: 1 Implementation Phase: Implementation Date:
Notes:	
-	
Field Date:	8/10/2011 Report Date 8/10/2011 Barrier #: 1493B
Field Date: Bldg Name:	8/10/2011 Report Date 8/10/2011 Barrier #: 1493B Arnold Dining Center Reference Dwg: 1 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Ramp
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Ramp
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Ramp 7478162.286 Y Coordinate: 338387.95
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Ramp 7478162.286 Y Coordinate: 338387.95 Ramps
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Ramp 7478162.286 Y Coordinate: 338387.95 Ramps Handrail 2010 ADAS 505.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Ramp 7478162.286 Y Coordinate: 338387.95 Ramps Handrail 2010 ADAS 505.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Ramp 7478162.286 Y Coordinate: 338387.95 Ramps Handrail 2010 ADAS 505.2 tandard: No Quantity: LF As-built: 225
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Ramp 7478162.286 Y Coordinate: 338387.95 Ramps Handrail 2010 ADAS 505.2 tandard: No Quantity: LF As-built: 225 No handrail provided at both sides
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Ramp 7478162.286 Y Coordinate: 338387.95 Ramps Handrail 2010 ADAS 505.2 tandard: No Quantity: LF As-built: 225 No handrail provided at both sides No handrail provided at both sides
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Ramp 7478162.286 Y Coordinate: 338387.95 Ramps Handrail 2010 ADAS 505.2 tandard: No Quantity: LF As-built: 225 No handrail provided at both sides No handrail provided at both sides Provide handrails at both sides of ramp y: 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	8/10/2011 Report Date 8/10/2011 Barrier #: 1493C
Bldg Name:	Arnold Dining Center Reference Dwg: 1 of 2
Location:	Exterior - West Ramp
X Coordinate:	7478162.286 Y Coordinate: 338387.95
Barrier Area:	Ramps
Barrier Type:	Handrail Grip
Code References:	2010 ADAS 505.10
Performance S	tandard: No Quantity: LF As-built: 225
Barrier Description:	Handrail grip is not 1/4" - 1/2" in diameter
Findings:	2-1/4" handrail grip diameter
Rec. Solution:	Provide handrails at both sides of ramp
Barrier Severit	y: 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementatio	n Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	8/10/2011 Report Date 8/10/2011 Barrier #: 1493D
Field Date: Bldg Name:	8/10/2011 Report Date 8/10/2011 Barrier #: 1493D Arnold Dining Center Reference Dwg: 1 of 2
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 1 of 2
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Ramp
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Ramp 7478162.286 Y Coordinate: 338387.95
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Ramp 7478162.286 Y Coordinate: 338387.95 Ramps
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Ramp 7478162.286 Y Coordinate: 338387.95 Ramps Handrail Extension - 12" 2010 ADAS 505.10
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Ramp 7478162.286 Y Coordinate: 338387.95 Ramps Handrail Extension - 12" 2010 ADAS 505.10
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Ramp 7478162.286 Y Coordinate: 338387.95 Ramps Handrail Extension - 12" 2010 ADAS 505.10 tandard: No Quantity: LF As-built: 225
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Ramp 7478162.286 Y Coordinate: 338387.95 Ramps Handrail Extension - 12" 2010 ADAS 505.10 tandard: No Quantity: LF As-built: 225 Handrail extension does not extend min. 12" from ramp run
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Ramp 7478162.286 Y Coordinate: 338387.95 Ramps Handrail Extension - 12" 2010 ADAS 505.10 tandard: No Quantity: LF As-built: 225 Handrail extension does not extend min. 12" from ramp run No bottom handrail extension provided Provide handrails at both sides of ramp
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 1 of 2 Exterior - West Ramp 7478162.286 Y Coordinate: 338387.95 Ramps Handrail Extension - 12" 2010 ADAS 505.10 tandard: No Quantity: LF As-built: 225 Handrail extension does not extend min. 12" from ramp run No bottom handrail extension provided Provide handrails at both sides of ramp y: 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	8/10/2011 Report Date 8/10/2011 Barrier #: 1493E
Bldg Name:	Arnold Dining Center Reference Dwg: 1 of 2
Location:	Exterior - West Ramp
X Coordinate:	7478162.286 Y Coordinate: 338387.95
Barrier Area:	Ramps
Barrier Type:	Handrail Extension - Length
Code References:	2010 ADAS 505.10
Performance S	Standard: No Quantity: LF As-built: 225
Barrier Description:	Handrail extension not min. 12" long
Findings:	No top handrail extension provided
Rec. Solution:	Provide handrails at both sides of ramp
Barrier Severit	y: 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	on Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	Report Date Barrier #:
Bldg Name:	Arnold Dining Center Reference Dwg:
	Arnold Dining Center Reference Dwg:
Location:	Arnold Dining Center Reference Dwg.
_	
Location:	
Location: X Coordinate:	
Location: X Coordinate: Barrier Area:	
Location: X Coordinate: Barrier Area: Barrier Type: Code	Y Coordinate:
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Y Coordinate:
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Y Coordinate:
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description:	Y Coordinate: Coordinate:
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Y Coordinate: Standard: Quantity: As-built:
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Y Coordinate:





Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 1A
Bldg Name:	Arnold Dining Center Reference Dwg: 1 of 2
Location:	Marketplace Office Exterior Entrance
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Landing - Existing (3.1% to 4.0%)
Code References:	2010 ADAS 404.2.4.4
Performance S	standard: No Quantity: SF As-built: 0
Barrier Description:	Door or gate lacks landing on both sides of door
Findings:	3.2% slope
Rec. Solution:	Demolish and reconstruct level landing
Barrier Severit	y: 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	on Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 1B
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 1B Arnold Dining Center Reference Dwg: 1 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance N/A Y Coordinate: N/A Doors or Gates Automatic Doors - Actuation Clear Floor Space 2010 ADAS 404.3.5 & 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance N/A Y Coordinate: N/A Doors or Gates Automatic Doors - Actuation Clear Floor Space 2010 ADAS 404.3.5 & 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance N/A Y Coordinate: N/A Doors or Gates Automatic Doors - Actuation Clear Floor Space 2010 ADAS 404.3.5 & 305.3 Standard: No Quantity: JOB As-built: 1 Actuation control lacks clear floor space min. 30" x 48" at device beyond the arc of the door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance N/A Y Coordinate: N/A Doors or Gates Automatic Doors - Actuation Clear Floor Space 2010 ADAS 404.3.5 & 305.3 Standard: No Quantity: JOB As-built: 1 Actuation control lacks clear floor space min. 30" x 48" at device beyond the arc of the door swing
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance N/A Doors or Gates Automatic Doors - Actuation Clear Floor Space 2010 ADAS 404.3.5 & 305.3 Standard: No Quantity: JOB As-built: 1 Actuation control lacks clear floor space min. 30" x 48" at device beyond the arc of the door swing No actuation device exists at door with BHMA sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance N/A Y Coordinate: N/A Doors or Gates Automatic Doors - Actuation Clear Floor Space 2010 ADAS 404.3.5 & 305.3 Standard: No Quantity: JOB As-built: 1 Actuation control lacks clear floor space min. 30" x 48" at device beyond the arc of the door swing No actuation device exists at door with BHMA sign Reinstall actuation device y: 1 Necessary Cost Est \$400.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 1C
Bldg Name:	Arnold Dining Center Reference Dwg: 1 of 2
Location:	Marketplace Office Exterior Entrance
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Sign
Code References:	Performance Standard
Performance S	Standard: Yes Quantity: JOB As-built: 1
Barrier Description:	ISA symbol at automatic door opening device not min. 4" x 4" in size
Findings:	No ISA symbol on door with automatic door opening device
Rec. Solution:	Recommended: Provide ISA symbol min. 4" x 4" in size
Barrier Severit	y: 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	on Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 2
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 2 Arnold Dining Center Reference Dwg: 1 of 2
	NAME OF TAXABLE PARTY O
Bldg Name:	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance N/A Y Coordinate: N/A Signage ISA - Non-Accessible Entry 2010 ADAS 216.6
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance N/A Y Coordinate: N/A Signage ISA - Non-Accessible Entry 2010 ADAS 216.6
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance N/A Y Coordinate: N/A Signage ISA - Non-Accessible Entry 2010 ADAS 216.6 Standard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance N/A Y Coordinate: N/A Signage ISA - Non-Accessible Entry 2010 ADAS 216.6 Standard: No Quantity: EACH As-built: 1 Sign directing people to accessible entrance needed where all doors are not accessible
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance N/A Signage ISA - Non-Accessible Entry 2010 ADAS 216.6 Standard: No Quantity: EACH As-built: 1 Sign directing people to accessible entrance needed where all doors are not accessible Accessible sign not provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 1 of 2 Marketplace Office Exterior Entrance N/A Y Coordinate: N/A Signage ISA - Non-Accessible Entry 2010 ADAS 216.6 Standard: No Quantity: EACH As-built: 1 Sign directing people to accessible entrance needed where all doors are not accessible Accessible sign not provided Provide ISA directional sign with arrow directing people to accessible entrance y: 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 3A
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Southeast Entry Vestibule
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Sign
Code References:	Performance Standard
Performance S	Standard: Yes Quantity: JOB As-built: 2
Barrier Description:	ISA symbol at automatic door opening device not min. 4" x 4" in size
Findings:	Existing symbol 1-3/4" high. Nor visible from a distance
Rec. Solution:	Recommended: Provide ISA symbol min. 4" x 4" in size on exterior and interior actuators
Barrier Severit	ty: 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	on Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 3B
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Southeast Entry Vestibule
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Location - 48" to 60" high
Code References:	2010 ADAS 703.4.1
Performance S	
	Standard: No Quantity: EACH As-built : 1
Barrier Description:	Standard: No Quantity: EACH As-built: 1 Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor
Description: Findings:	Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor
Description: Findings:	Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor 63-1/2" high Provide accessible sign and mount at proper height
Description: Findings: Rec. Solution:	Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor 63-1/2" high Provide accessible sign and mount at proper height ty: 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 3C
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Southeast Entry Vestibule
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Doormat
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance S	Standard: No Quantity: EACH As-built : 3
Barrier Description:	Doormat not anchored to floor (possible trip hazard)
Findings:	Door mats not secured
Rec. Solution:	Secure exiting doormats or replace
Barrier Severit	cy: 1 Necessary Cost Est \$1,500.00 Facility Function: Public Status: Open
Implementatio	on Priority: 2 Implementation Phase: Implementation Date:
Notes: Door i	mats at interior and exterior side of doors
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 3D
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Southeast Entry Vestibule
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Door
Code References:	2010 ADAS 216.4.1
Performance S	Standard: No Quantity: EACH As-built : 1
Barrier Description:	Ground floor doors that exit to exterior lacks tactile exit sign
Findings:	Exit door with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT" at exit side of door
	provide sign stating Exit at exit side of door
Barrier Severit	
Barrier Severit Implementatio	cy: 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 4A
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Northeast Entry Vestibule
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Sign
Code References:	Performance Standard
Performance S	Standard: Yes Quantity: JOB As-built : 2
Barrier Description:	ISA symbol at automatic door opening device not min. 4" x 4" in size
Findings:	Existing symbol 1-3/4" high. Nor visible from a distance
Rec. Solution:	Recommended: Provide ISA symbol min. 4" x 4" in size at exterior and interior actuators
Barrier Severit	cy: 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	on Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 4B
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Northeast Entry Vestibule
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
	Signage
Barrier Type:	Signage Location - 48" to 60" high
Barrier Type: Code	Location - 48" to 60" high 2010 ADAS 703.4.1
Barrier Type: Code References:	Location - 48" to 60" high 2010 ADAS 703.4.1
Barrier Type: Code References: Performance S Barrier	Location - 48" to 60" high 2010 ADAS 703.4.1 Standard: No Quantity: EACH As-built: 1
Barrier Type: Code References: Performance S Barrier Description: Findings:	Location - 48" to 60" high 2010 ADAS 703.4.1 Standard: No Quantity: EACH As-built: 1 Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor
Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Location - 48" to 60" high 2010 ADAS 703.4.1 Standard: No Quantity: EACH As-built: 1 Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor 63-1/2" high
Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Location - 48" to 60" high 2010 ADAS 703.4.1 Standard: No Quantity: EACH As-built: 1 Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor 63-1/2" high Provide accessible sign and mount at proper height Ey: 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 4C
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Northeast Entry Vestibule
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Doormat
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance S	Standard: No Quantity: EACH As-built : 2
Barrier Description:	Doormat not anchored to floor (possible trip hazard)
Findings:	Door mats not secured
Rec. Solution:	Secure exiting doormats or replace
Barrier Severit	y: 1 Necessary Cost Est \$1,000.00 Facility Function: Public Status: Open
Implementation	on Priority: 2 Implementation Phase: Implementation Date:
Notes: Door	mats at exterior doors
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 4D
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 4D Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Northeast Entry Vestibule
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Northeast Entry Vestibule
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Northeast Entry Vestibule N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Northeast Entry Vestibule N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Northeast Entry Vestibule N/A Y Coordinate: N/A Signage Tactile Exit Signs - Door 2010 ADAS 216.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Northeast Entry Vestibule N/A Y Coordinate: N/A Signage Tactile Exit Signs - Door 2010 ADAS 216.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Northeast Entry Vestibule N/A Y Coordinate: N/A Signage Tactile Exit Signs - Door 2010 ADAS 216.4.1 Standard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Northeast Entry Vestibule N/A Y Coordinate: N/A Signage Tactile Exit Signs - Door 2010 ADAS 216.4.1 Standard: No Quantity: EACH As-built: 1 Ground floor doors that exit to exterior lacks tactile exit sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Northeast Entry Vestibule N/A Y Coordinate: N/A Signage Tactile Exit Signs - Door 2010 ADAS 216.4.1 Standard: No Quantity: EACH As-built: 1 Ground floor doors that exit to exterior lacks tactile exit sign Exit door with low level illuminated sign lacks tactile exit sign Provide sign stating "EXIT" at exit side of door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Northeast Entry Vestibule N/A Y Coordinate: N/A Signage Tactile Exit Signs - Door 2010 ADAS 216.4.1 Ground floor doors that exit to exterior lacks tactile exit sign Exit door with low level illuminated sign lacks tactile exit sign Provide sign stating "EXIT" at exit side of door cy: 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 5A
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Dining Area
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Dining Facilities
Barrier Type:	Table Seating - Knee Clearance
Code References:	2010 ADAS 902.2
Performance S	Standard: No Quantity: EACH As-built: 1
Barrier Description:	Table knee clearance not min. 27" high, 30" wide or 19" deep
Findings:	Pedestal base blocks knee clearance
Rec. Solution:	Provide accessible table. Avoid pedestal base tables
Barrier Severit	y: 2 Recommended Cost Est \$450.00 Facility Function: Public Status: Open
Implementatio	on Priority: 2 Implementation Phase: Implementation Date:
Notes: PC coi	mputer workstation on pedestal table with knee clearance 14" deep in 2 locations
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 5B
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Dining Area
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance S	Standard: No Quantity: EACH As-built: 5
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severit	y: 3 Hindrance Cost Est \$3,750.00 Facility Function: Public Status: Open
Implementatio	on Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 5C
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Dining Area
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Dining Facilities
Barrier Type:	Table Seating - Knee Clearance
Code References:	2010 ADAS 902.2
Performance S	tandard: No Quantity: EACH As-built : 1
Barrier Description:	Table knee clearance not min. 27" high, 30" wide or 19" deep
Findings:	Pedestal base blocks knee clearance
Rec. Solution:	Provide min. 1 accessible PC station. Avoid pedestal base tables
Barrier Severit	y: 2 Recommended Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	on Priority: 2 Implementation Phase: Implementation Date:
Notes: PC co	mputer workstation on pedestal table with knee clearance 14" deep in 2 locations
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 5D
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 5D Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Dining Area
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Dining Area
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Dining Area N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Dining Area N/A Y Coordinate: N/A Dining Facilities
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Dining Area N/A Y Coordinate: N/A Dining Facilities Bar - >20 ft Long Bar (5% Accessible) 2010 ADAS 902.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Dining Area N/A Y Coordinate: N/A Dining Facilities Bar - >20 ft Long Bar (5% Accessible) 2010 ADAS 902.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Dining Area N/A Y Coordinate: N/A Dining Facilities Bar - >20 ft Long Bar (5% Accessible) 2010 ADAS 902.2 standard: No Quantity: EACH As-built: 2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Dining Area N/A Y Coordinate: N/A Dining Facilities Bar - >20 ft Long Bar (5% Accessible) 2010 ADAS 902.2 Standard: No Quantity: EACH As-built: 2 Min. 5% of bar for dining/drinking lacks knee clearance 28" to 34" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Dining Area N/A V Coordinate: N/A Dining Facilities Bar - >20 ft Long Bar (5% Accessible) 2010 ADAS 902.2 Atandard: No Quantity: EACH As-built: 2 Min. 5% of bar for dining/drinking lacks knee clearance 28" to 34" high 20 chairs at bar 40 LF long. No accessible section provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Dining Area N/A Y Coordinate: N/A Dining Facilities Bar - >20 ft Long Bar (5% Accessible) 2010 ADAS 902.2 Standard: No Quantity: EACH As-built: 2 Min. 5% of bar for dining/drinking lacks knee clearance 28" to 34" high 20 chairs at bar 40 LF long. No accessible section provided Alter to ensure that min. 5% of bar has a surface at max. 34" above floor or ground y: 2 Recommended Cost Est \$3,200.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 6
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Cashiers
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Dining Facilities
Barrier Type:	Service Counter - Surface Height
Code References:	2010 ADAS 902.2
Performance S	tandard: No Quantity: EACH As-built: 1
Barrier Description:	Counter surface not between 28" and 34" above floor or ground
Findings:	34-1/3" high surface
Rec. Solution:	Provide min. 1 cashiers counter with 3 ft segment with surface at max. 34" above floor or ground
Barrier Severit	y: 2 Recommended Cost Est \$1,250.00 Facility Function: Public Status: Open
Implementatio	n Priority: 2 Implementation Phase: Implementation Date:
Notes: Cashie	er counter
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 7
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 7 Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name:	
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Nori Grill
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Nori Grill N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Nori Grill N/A Y Coordinate: N/A Dining Facilities
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Nori Grill N/A Y Coordinate: N/A Dining Facilities Lunch Counter - Surface Height 2010 ADAS 902.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Nori Grill N/A Y Coordinate: N/A Dining Facilities Lunch Counter - Surface Height 2010 ADAS 902.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Nori Grill N/A Y Coordinate: N/A Dining Facilities Lunch Counter - Surface Height 2010 ADAS 902.2 tandard: No Quantity: EACH As-built: 2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Nori Grill N/A Y Coordinate: N/A Dining Facilities Lunch Counter - Surface Height 2010 ADAS 902.2 tandard: No Quantity: EACH As-built: 2 Top of counter not max. 34" above floor or ground with min. 27" knee clearance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Nori Grill N/A V Coordinate: N/A Dining Facilities Lunch Counter - Surface Height 2010 ADAS 902.2 tandard: No Quantity: EACH As-built: 2 Top of counter not max. 34" above floor or ground with min. 27" knee clearance Sushi order and pickup counter 35-1/2" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Nori Grill N/A Y Coordinate: N/A Dining Facilities Lunch Counter - Surface Height 2010 ADAS 902.2 tandard: No Quantity: EACH As-built: 2 Top of counter not max. 34" above floor or ground with min. 27" knee clearance Sushi order and pickup counter 35-1/2" high Provide min. 1 accessible section of counter at order and pickup areas at max. 34" above floor y: 2 Recommended Cost Est \$2,500.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 8A
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Central Salad Bar
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Dining Facilities
Barrier Type:	Bar - Accessible Height
Code References:	2010 ADAS 902.4
Performance S	Standard: No Quantity: LF As-built: 1
Barrier Description:	Min. 60" long bar surface not min. 28" to 34" high
Findings:	34-1/4" - 34-1/2" high surface surrounding bar.
Rec. Solution:	Provide accessible dining area counter min. 60" long or 5% of total counter length
Barrier Severit	y: 2 Recommended Cost Est \$2,400.00 Facility Function: Public Status: Open
Implementation	on Priority: 2 Implementation Phase: Implementation Date:
Notes: Centr	al salad bar
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 8B
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 8B Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Central Salad Bar
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Central Salad Bar
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Central Salad Bar N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Central Salad Bar N/A Y Coordinate: N/A Dining Facilities
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Central Salad Bar N/A Y Coordinate: N/A Dining Facilities Actuator/Control - Forward Reach Obstructed (10"-25") 2010 ADAS 308.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Central Salad Bar N/A Y Coordinate: N/A Dining Facilities Actuator/Control - Forward Reach Obstructed (10"-25") 2010 ADAS 308.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Central Salad Bar N/A Y Coordinate: N/A Dining Facilities Actuator/Control - Forward Reach Obstructed (10"-25") 2010 ADAS 308.2 Standard: No Quantity: EACH As-built: 4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Central Salad Bar N/A Y Coordinate: N/A Dining Facilities Actuator/Control - Forward Reach Obstructed (10"-25") 2010 ADAS 308.2 Standard: No Quantity: EACH As-built: 4 Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44"
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Central Salad Bar N/A V Coordinate: N/A Dining Facilities Actuator/Control - Forward Reach Obstructed (10"-25") 2010 ADAS 308.2 Standard: No Quantity: EACH As-built: 4 Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44" Reach to food items in recessed areas more than 25" deep over 36-1/2" high counter
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Central Salad Bar N/A Y Coordinate: N/A Dining Facilities Actuator/Control - Forward Reach Obstructed (10"-25") 2010 ADAS 308.2 Standard: No Quantity: EACH As-built: 4 Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44" Reach to food items in recessed areas more than 25" deep over 36-1/2" high counter Relocate all food items to max. 44" high and max. 25" deep cy: 3 Hindrance Cost Est \$3,000.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 9A
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Deli and Pizzeria
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Dining Facilities
Barrier Type:	Lunch Counter - Surface Height
Code References:	2010 ADAS 902.2
Performance S	Standard: No Quantity: EACH As-built : 1
Barrier Description:	Top of counter not max. 34" above floor or ground with min. 27" knee clearance
Findings:	35" - 35-1/4" high
Rec. Solution:	Provide lunch counter with surface at max. 34" above floor or ground
Barrier Severit	ty: 2 Recommended Cost Est \$1,250.00 Facility Function: Public Status: Open
Implementation	on Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 9B
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Deli and Pizzeria
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Dining Facilities
Barrier Type:	Service Counter - Surface Height
	Service Counter - Surface freight
Code References:	2010 ADAS 902.2
	2010 ADAS 902.2
References:	2010 ADAS 902.2
References: Performance S Barrier	2010 ADAS 902.2 Standard: No Quantity: EACH As-built: 1
References: Performance S Barrier Description: Findings:	2010 ADAS 902.2 Standard: No Quantity: EACH As-built: 1 Counter surface not between 28" and 34" above floor or ground
References: Performance S Barrier Description: Findings: Rec. Solution:	2010 ADAS 902.2 Standard: No Quantity: EACH As-built: 1 Counter surface not between 28" and 34" above floor or ground Deli case shelves at 56" high
References: Performance S Barrier Description: Findings: Rec. Solution:	2010 ADAS 902.2 Standard: No Quantity: EACH As-built: 1 Counter surface not between 28" and 34" above floor or ground Deli case shelves at 56" high Provide service counter with 3 ft segment with surface at max. 34" above floor or ground Ey: 2 Recommended Cost Est \$1,250.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 10
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Drink Fridge
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Operation
Code References:	2010 ADAS 305.3
Performance S	Standard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism needs more than 5 lbf to operate
Findings:	Drink fridge doors exceed 5 lbf to operate
Rec. Solution:	Replace operating control
Barrier Severit	y: 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	on Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 11A
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Self-Serve Drink Counter
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Carpet/Rug
Code References:	2010 ADAS 302.2
Performance S	Standard: No Quantity: EACH As-built : 1
Barrier Description:	Carpet/rug not anchored to floor (possible trip hazard)
Findings:	Mat at soda machine has rolled edges and creates tripping hazard
Rec. Solution:	Secure exiting carpet/rug or replace
Barrier Severit	y: 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementatio	on Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 11B
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Self-Serve Drink Counter
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Dining Facilities
Barrier Type:	Service Counter - Surface Height
Code References:	2010 ADAS 902.2
Performance S	Standard: No Quantity: EACH As-built: 1
Barrier Description:	Counter surface not between 28" and 34" above floor or ground
Findings:	Self-service counter at 34-1/2" high
Rec. Solution:	Provide service counter with 3 ft segment with surface at max. 34" above floor or ground
Barrier Severit	y: 2 Recommended Cost Est \$1,250.00 Facility Function: Public Status: Open
Implementation	on Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 11C
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 11C Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Self-Serve Drink Counter
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Self-Serve Drink Counter
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Self-Serve Drink Counter N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Self-Serve Drink Counter N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Self-Serve Drink Counter N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Side Reach Obstructed (10"-24") 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Self-Serve Drink Counter N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Side Reach Obstructed (10"-24") 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Self-Serve Drink Counter N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 Standard: No Quantity: EACH As-built: 4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Self-Serve Drink Counter N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 Standard: No Quantity: EACH As-built: 4 Control or mechanism over an 10" to 24" obstruction max. 34" high located above 46"
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Self-Serve Drink Counter N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 Standard: No Quantity: EACH As-built: 4 Control or mechanism over an 10" to 24" obstruction max. 34" high located above 46" Multiple dispensers 46" high and over an obstruction 34-1/2" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Self-Serve Drink Counter N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 Standard: No Quantity: EACH As-built: 4 Control or mechanism over an 10" to 24" obstruction max. 34" high located above 46" Multiple dispensers 46" high and over an obstruction 34-1/2" high Relocate controls or mechanisms to max. 46" high y: 3 Hindrance Cost Est \$3,000.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 12
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Exit Door
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Door
Code References:	2010 ADAS 216.4.1
Performance S	tandard: No Quantity: EACH As-built : 1
Barrier Description:	Ground floor doors that exit to exterior lacks tactile exit sign
Findings:	Exit door with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT" at exit side of door
Barrier Severity	y: 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementatio	n Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 13A
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Servery
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Location - 48" to 60" high
Code References:	2010 ADAS 703.4.1
Performance S	tandard: No Quantity: EACH As-built : 4
Barrier Description:	Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor
Findings:	63-1/2" high in 4 locations within the public pedestrian path
Rec. Solution:	Provide accessible signs and mount at proper height
Barrier Severity	y: 1 Necessary Cost Est \$1,000.00 Facility Function: Public Status: Open
Implementatio	on Priority: 3 Implementation Phase: Implementation Date:
Notes: Also, b	oraille not 3/8" and max. 1/2" directly below the tactile characters



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 13B
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Servery
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Dining Facilities
Barrier Type:	Condiment Stand - Surface Height
Code References:	2010 ADAS 902.2
Performance S	standard: No Quantity: EACH As-built : 1
Barrier Description:	Surface not max. 34" above floor or ground
Findings:	Condiment counter 34-1/2" high surface
Rec. Solution:	Replace condiment stand
Barrier Severit	y: 2 Recommended Cost Est \$1,250.00 Facility Function: Public Status: Open
Implementation	on Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 13C
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 13C Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Servery
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Servery
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Servery N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Servery N/A Y Coordinate: N/A Dining Facilities
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Servery N/A Y Coordinate: N/A Dining Facilities Condiment Stand - Side Reach Obstructed (10"-24") 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Servery N/A Y Coordinate: N/A Dining Facilities Condiment Stand - Side Reach Obstructed (10"-24") 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Servery N/A Y Coordinate: N/A Dining Facilities Condiment Stand - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 Standard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Servery N/A V Coordinate: N/A Dining Facilities Condiment Stand - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 Standard: No Quantity: EACH As-built: 1 Control or mechanism over an 10" to 24" obstruction max. 34" high located above 46"
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Servery N/A Dining Facilities Condiment Stand - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 Standard: No Quantity: EACH As-built: 1 Control or mechanism over an 10" to 24" obstruction max. 34" high located above 46" Condiments 51" high and 20" deep over an obstruction 34-1/2" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Servery N/A V Coordinate: N/A Dining Facilities Condiment Stand - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 Standard: No Quantity: EACH As-built: 1 Control or mechanism over an 10" to 24" obstruction max. 34" high located above 46" Condiments 51" high and 20" deep over an obstruction 34-1/2" high Relocate controls or mechanisms to max. 46" high y: 3 Hindrance Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 14A
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Global Fare Counter
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Dining Facilities
Barrier Type:	Lunch Counter - Surface Height
Code References:	2010 ADAS 902.2
Performance S	itandard: No Quantity: EACH As-built : 1
Barrier Description:	Top of counter not max. 34" above floor or ground with min. 27" knee clearance
Findings:	35-1/4" - 35-1/2" high at order counter
Rec. Solution:	Provide lunch counter with surface at max. 34" above floor or ground
Barrier Severit	y: 2 Recommended Cost Est \$1,250.00 Facility Function: Public Status: Open
Implementation	on Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 14B
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 14B Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Global Fare Counter
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Global Fare Counter
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Global Fare Counter N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Global Fare Counter N/A Y Coordinate: N/A Dining Facilities
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Global Fare Counter N/A Y Coordinate: N/A Dining Facilities Lunch Counter - Surface Height 2010 ADAS 902.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Global Fare Counter N/A Y Coordinate: N/A Dining Facilities Lunch Counter - Surface Height 2010 ADAS 902.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Global Fare Counter N/A Y Coordinate: N/A Dining Facilities Lunch Counter - Surface Height 2010 ADAS 902.2 standard: No Quantity: EACH As-built: 3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Global Fare Counter N/A Y Coordinate: N/A Dining Facilities Lunch Counter - Surface Height 2010 ADAS 902.2 Standard: No Quantity: EACH As-built: 3 Top of counter not max. 34" above floor or ground with min. 27" knee clearance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Global Fare Counter N/A V Coordinate: N/A Dining Facilities Lunch Counter - Surface Height 2010 ADAS 902.2 Standard: No Quantity: EACH As-built: 3 Top of counter not max. 34" above floor or ground with min. 27" knee clearance Deli counter for ordering 52" high in 3 ordering locations
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Global Fare Counter N/A Y Coordinate: N/A Dining Facilities Lunch Counter - Surface Height 2010 ADAS 902.2 Standard: No Quantity: EACH As-built: 3 Top of counter not max. 34" above floor or ground with min. 27" knee clearance Deli counter for ordering 52" high in 3 ordering locations Provide accessible deli counter with surface at max. 34" above floor or ground y: 2 Recommended Cost Est \$6,750.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 15A
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Recycling Area/Dish Drop-off
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Carpet/Rug
Code References:	2010 ADAS 302.2
Performance S	Standard: No Quantity: EACH As-built : 1
Barrier Description:	Carpet/rug not anchored to floor (possible trip hazard)
Findings:	Carpet/rug creates tripping hazard at water cooler counter
Rec. Solution:	Secure exiting carpet/rug or replace
Barrier Severit	y: 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	on Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 15B
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 15B Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Recycling Area/Dish Drop-off
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Recycling Area/Dish Drop-off
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Recycling Area/Dish Drop-off N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Recycling Area/Dish Drop-off N/A Y Coordinate: N/A Dining Facilities
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Recycling Area/Dish Drop-off N/A Y Coordinate: N/A Dining Facilities Service Counter - Surface Height 2010 ADAS 902.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Recycling Area/Dish Drop-off N/A Y Coordinate: N/A Dining Facilities Service Counter - Surface Height 2010 ADAS 902.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Recycling Area/Dish Drop-off N/A Y Coordinate: N/A Dining Facilities Service Counter - Surface Height 2010 ADAS 902.2 Standard: No Quantity: EACH As-built: 5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Recycling Area/Dish Drop-off N/A Y Coordinate: N/A Dining Facilities Service Counter - Surface Height 2010 ADAS 902.2 Standard: No Quantity: EACH As-built: 5 Counter surface not between 28" and 34" above floor or ground
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Recycling Area/Dish Drop-off N/A Y Coordinate: N/A Dining Facilities Service Counter - Surface Height 2010 ADAS 902.2 Standard: No Quantity: EACH As-built: 5 Counter surface not between 28" and 34" above floor or ground Recycle counter 36-1/3" high surface with a 10" reach at multiple sorting bins
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Recycling Area/Dish Drop-off N/A Y Coordinate: N/A Dining Facilities Service Counter - Surface Height 2010 ADAS 902.2 Standard: No Quantity: EACH As-built: 5 Counter surface not between 28" and 34" above floor or ground Recycle counter 36-1/3" high surface with a 10" reach at multiple sorting bins Provide service counter with 3 ft segment with surface at max. 34" above each type of bin cy: 2 Recommended Cost Est \$6,250.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 15C
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Recycling Area/Dish Drop-off
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Carpet/Rug
Code References:	2010 ADAS 302.2
Performance S	Standard: No Quantity: EACH As-built : 1
Barrier Description:	Carpet/rug not anchored to floor (possible trip hazard)
Findings:	Dish return counter has mat that creates tripping hazard
Rec. Solution:	Secure exiting carpet/rug or replace
Barrier Severit	y: 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	on Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 16A
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Conference Room 108
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Location - 48" to 60" high
Code References:	2010 ADAS 703.4.1
Performance S	Standard: No Quantity: EACH As-built : 2
Barrier Description:	Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor
Findings:	63-1/2" high
Rec. Solution:	Provide accessible signs and mount at proper height
	y: 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementatio	
Notes: Also, I	braille not 3/8" and max. 1/2" directly below the tactile characters



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 16B
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Conference Room 108
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Surface Height
Code References:	2010 ADAS 902.3
Performance S	standard: No Quantity: EACH As-built: 1
Barrier Description:	No section at least 3 feet long between 28" and 34" provided at existing counter
Findings:	35" high
Rec. Solution:	Provide min. 3 ft long section of counter at max. 34" high
Barrier Severit	y: 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	on Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 16C
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 16C Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Conference Room 108
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Conference Room 108
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Conference Room 108 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Conference Room 108 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Conference Room 108 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Side Reach Obstructed (10"-24") 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Conference Room 108 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Side Reach Obstructed (10"-24") 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Conference Room 108 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 standard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Conference Room 108 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 Standard: No Quantity: EACH As-built: 1 Outlet located over an 10" to 24" obstruction max. 34" high located above 46"
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Conference Room 108 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 Standard: No Quantity: EACH As-built: 1 Outlet located over an 10" to 24" obstruction max. 34" high located above 46" 43" high and 26" deep over an obstruction 35" high counter for outlet
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Conference Room 108 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 Standard: No Quantity: EACH As-built: 1 Outlet located over an 10" to 24" obstruction max. 34" high located above 46" 43" high and 26" deep over an obstruction 35" high counter for outlet Relocate control or mechanism to max. 46" high y: 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date: 2/19/2014 Report Date 3/18/2014 Barrier #: 17A	\mathscr{H}
Bldg Name: Arnold Dining Center Reference Dwg: 2 of 2	
Location: Floor 1 - ATM Area	
X Coordinate: N/A Y Coordinate: N/A	
Barrier Area: Controls and Mechanisms	
Barrier Type: Clear Floor Space	
Code 2010 ADAS 305.3 References:	
Performance Standard: No Quantity: SF As-built: 0	
Barrier Clear floor space for wheelchair not provided at control or mechanism Description:	
42" clear floor space between ATM and tables Findings:	
Rec. Solution: Move tables to provide wheelchair space at ATM	
Barrier Severity: 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open	
Implementation Priority: 2 Implementation Phase: Implementation Date:	
Notes:	
Field Date: 2/19/2014 Report Date 3/18/2014 Barrier #: 17B	
Bldg Name: Arnold Dining Center Reference Dwg: 2 of 2	
Location: Floor 1 - ATM Area	
X Coordinate: N/A Y Coordinate: N/A	
Parrier Arrest	
Barrier Area: Controls and Mechanisms	
Barrier Type: ATM Machine - Tactile Signage	
Barrier Type: ATM Machine - Tactile Signage Code 2010 ADAS 308 and 702	
Barrier Type: ATM Machine - Tactile Signage Code	
Barrier Type: ATM Machine - Tactile Signage Code	
Barrier Type: ATM Machine - Tactile Signage Code References: Performance Standard: No Quantity: JOB As-built: 1 Barrier Description: ATM lacks raised characters or Braille for the visually impaired ATM keypad has no braille information	
Barrier Type: ATM Machine - Tactile Signage Code	
Barrier Type: ATM Machine - Tactile Signage Code	



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 18A
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Unisex Restroom
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Location - 48" to 60" high
Code References:	2010 ADAS 703.4.1
Performance S	Standard: No Quantity: EACH As-built : 1
Barrier Description:	Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor
Findings:	63" high
Rec. Solution:	Provide accessible sign and mount at proper height
Barrier Severit	cy: 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	on Priority: 3 Implementation Phase: Implementation Date:
	sign containing Braille/tactile info located on a door, braille not 3/8" and max. 1/2" directly below actile characters and contracted (Grade 2) Braille not used on sign
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 18B
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 18B Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms Door Closer - Automatic Opening Device 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms Door Closer - Automatic Opening Device 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms Door Closer - Automatic Opening Device 2010 ADAS 404.2.9 Standard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms Door Closer - Automatic Opening Device 2010 ADAS 404.2.9 Standard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms Door Closer - Automatic Opening Device 2010 ADAS 404.2.9 Standard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf Door to toilet room does not self-close. No door closer present Provide automatic door opener
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms Door Closer - Automatic Opening Device 2010 ADAS 404.2.9 Standard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf Door to toilet room does not self-close. No door closer present Provide automatic door opener cy: 1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 18C
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Unisex Restroom
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Protruding Object
Code References:	2010 ADAS 307.2
Performance S	standard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding dispenser creates protruding hazard in path of travel
Findings:	Paper towel dispenser protrudes 10"
Rec. Solution:	Remove dispenser or provide detectable warning for the visually impaired
Barrier Severit	y: 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	on Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 18D
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 18D Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Clear Floor Space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - Wheelchair Use 2010 ADAS 305
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - Wheelchair Use 2010 ADAS 305
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - Wheelchair Use 2010 ADAS 305 standard: No Quantity: JOB As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - Wheelchair Use 2010 ADAS 305 Standard: No Quantity: JOB As-built: 0 Clear floor space of min. 30" by 48" not provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - Wheelchair Use 2010 ADAS 305 Standard: No Quantity: JOB As-built: 0 Clear floor space of min. 30" by 48" not provided Trash bin blocks paper towel dispenser clear floor space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - Wheelchair Use 2010 ADAS 305 Clear floor space of min. 30" by 48" not provided Trash bin blocks paper towel dispenser clear floor space Move stored items at control or mechanism y: 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 18E
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Unisex Restroom
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Centerline
Code References:	2010 ADAS 606
Performance S	tandard: No Quantity: JOB As-built: 1
Barrier Description:	Lavatory adjacent to wall not min. 15" to the centerline of fixture
Findings:	14-1/2" to centerline of fixture
Rec. Solution:	Relocate lavatory
Barrier Severit	y: 2 Recommended Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	on Priority: 3 Implementation Phase: Implementation Date:
Notes:	
-	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 18F
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 18F Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms Doormat 2010 ADAS 302.2 & Advisory 302.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms Doormat 2010 ADAS 302.2 & Advisory 302.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms Doormat 2010 ADAS 302.2 & Advisory 302.2 standard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms Doormat 2010 ADAS 302.2 & Advisory 302.2 standard: No Quantity: EACH As-built: 1 Doormat not anchored to floor (trip hazard)
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms Doormat 2010 ADAS 302.2 & Advisory 302.2 standard: No Quantity: EACH As-built: 1 Doormat not anchored to floor (trip hazard) Door mat under lavatory not secured
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms Doormat 2010 ADAS 302.2 & Advisory 302.2 Standard: No Quantity: EACH As-built: 1 Doormat not anchored to floor (trip hazard) Door mat under lavatory not secured Replace doormat or anchor existing Y: 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 18G
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Unisex Restroom
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Mirror
Code References:	2010 ADAS 603.3
Performance S	standard: No Quantity: EACH As-built: 1
Barrier Description:	Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface
Findings:	49-1/2" high
Rec. Solution:	Replace or remount mirror
Barrier Severit	y: 3 Hindrance Cost Est \$375.00 Facility Function: Public Status: Open
Implementation	on Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 18H
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 18H Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms Coat Hook 2010 ADAS 603.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms Coat Hook 2010 ADAS 603.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms Coat Hook 2010 ADAS 603.4 Standard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms Coat Hook 2010 ADAS 603.4 Standard: No Quantity: EACH As-built: 1 Clothing hooks not max. 48" high AFF
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms Coat Hook 2010 ADAS 603.4 Standard: No Quantity: EACH As-built: 1 Clothing hooks not max. 48" high AFF
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Unisex Restroom N/A Y Coordinate: N/A Restrooms Coat Hook 2010 ADAS 603.4 Clothing hooks not max. 48" high AFF Frovide additional hook Y: 2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 18I
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Unisex Restroom
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Changing Station - Accessible Route
Code References:	2010 ADAS 402 & 403
Performance S	Standard: No Quantity: JOB As-built : 1
Barrier Description:	Accessible route not provided to changing station in stall (min. 36" clear width)
Findings:	34-1/2" high surface
Rec. Solution:	Remount changing station at accessible height
Barrier Severit	cy: 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	on Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 19
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Service Center
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Clear Floor Space
Code References:	2010 ADAS 305.3
Performance S	Standard: No Quantity: EACH As-built : 1
Barrier Description:	Clear floor space 30" x 48" not provided at counter
Findings:	35" long section of accessible counter installed, but remains blocked by a horizontal door
Rec. Solution:	Replace counter to provide min. 36" long accessible counter and remove horizontal door
Barrier Severit	y: 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	on Priority: 2 Implementation Phase: Implementation Date:
	eaves door closed which blocks use of the counter. A key must be used to unlock the door. 42" at standard counter



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 20A
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Mailbox Area
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Location - 48" to 60" high
Code References:	2010 ADAS 703.4.1
Performance S	Standard: No Quantity: EACH As-built : 1
Barrier Description:	Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor
Findings:	63-1/2" high at catering office door
Rec. Solution:	Provide accessible sign and mount at proper height
Barrier Severit	y: 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	on Priority: 3 Implementation Phase: Implementation Date:
Notes: Also,	braille not 3/8" and max. 1/2" directly below the tactile characters
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 20B
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 20B Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Mailbox Area
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Mailbox Area
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Mailbox Area N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Mailbox Area N/A Y Coordinate: N/A Clear Floor Space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Mailbox Area N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Mailbox Area N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Mailbox Area N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Standard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Mailbox Area N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Standard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Mailbox Area N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Standard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high Drop box for mail protrudes 7" at 41" high Remove object or provide detectable warning for the visually impaired
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Mailbox Area N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Standard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high Drop box for mail protrudes 7" at 41" high Remove object or provide detectable warning for the visually impaired by: 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 20C
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Mailbox Area
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Mailbox - High Reach Range
Code References:	2010 ADAS 308.2.2
Performance S	Standard: No Quantity: EACH As-built: 10
Barrier Description:	Mailbox opening is above 48" high
Findings:	20% of mailboxes higher than 48" high
Rec. Solution:	Relocate to provide opening at max. 48" high or provide assistance
Barrier Severit	y: 3 Hindrance Cost Est \$7,500.00 Facility Function: Public Status: Open
Implementation	on Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 21A
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 21A
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Vestibule
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Vestibule
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Vestibule N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Vestibule N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Vestibule N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Vestibule N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Vestibule N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307 Standard: No Quantity: EACH As-built: 2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Vestibule N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307 Standard: No Quantity: EACH As-built: 2 Protruding object in in circulation path protrudes more than 4" between 27" and 80" high PRIDE drop box protrudes 6" at 53-1/2" high. AED cabinet protrudes 6" at 42" high in route to
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Vestibule N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307 Standard: No Quantity: EACH As-built: 2 Protruding object in in circulation path protrudes more than 4" between 27" and 80" high PRIDE drop box protrudes 6" at 53-1/2" high. AED cabinet protrudes 6" at 42" high in route to restrooms Remove objects or provide detectable warning (wing walls)
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Vestibule N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307 Standard: No Quantity: EACH As-built: 2 Protruding object in in circulation path protrudes more than 4" between 27" and 80" high PRIDE drop box protrudes 6" at 53-1/2" high. AED cabinet protrudes 6" at 42" high in route to restrooms Remove objects or provide detectable warning (wing walls) y: 1 Necessary Cost Est \$1,100.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 21B
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Vestibule
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance S	standard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	PRIDE drop box 58-1/2" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severit	y: 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	on Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 22A
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 22A Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Signage Location - 48" to 60" high 2010 ADAS 703.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Signage Location - 48" to 60" high 2010 ADAS 703.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Signage Location - 48" to 60" high 2010 ADAS 703.4.1 standard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Signage Location - 48" to 60" high 2010 ADAS 703.4.1 Standard: No Quantity: EACH As-built: 1 Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Signage Location - 48" to 60" high 2010 ADAS 703.4.1 Standard: No Quantity: EACH As-built: 1 Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor 63" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Signage Location - 48" to 60" high 2010 ADAS 703.4.1 Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor 63" high Provide accessible sign and mount at proper height y: 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 22B
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Men's Restroom
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Location - Within 18" of Door
Code References:	2010 ADAS 703.4.2
Performance S	Standard: No Quantity: EACH As-built: 1
Barrier Description:	Approach to tactile characters on sign not centered at 18" minimum from door swing
Findings:	AED cabinet prevents the visually impaired from approaching the sign to read by touch
Rec. Solution:	Move AED cabinet
Barrier Severit	y: 1 Necessary Cost Est \$150.00 Facility Function: Public Status: Open
Implementation	on Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 22C
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 22C Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Doors or Gates Automatic Doors - Timing 2010 ADAS 404.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Doors or Gates Automatic Doors - Timing 2010 ADAS 404.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Doors or Gates Automatic Doors - Timing 2010 ADAS 404.3 Standard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Doors or Gates Automatic Doors - Timing 2010 ADAS 404.3 Standard: No Quantity: JOB As-built: 1 Door does not remain open for at least 6 seconds
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Doors or Gates Automatic Doors - Timing 2010 ADAS 404.3 Standard: No Quantity: JOB As-built: 1 Door does not remain open for at least 6 seconds Door closes after 3 seconds
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Doors or Gates Automatic Doors - Timing 2010 ADAS 404.3 Standard: No Quantity: JOB As-built: 1 Door does not remain open for at least 6 seconds Door closes after 3 seconds Repair actuation device y: 1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 22D
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Men's Restroom
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Sign
Code References:	Performance Standard
Performance S	Standard: Yes Quantity: JOB As-built: 2
Barrier Description:	ISA symbol at automatic door opening device not min. 4" x 4" in size
Findings:	No ISA symbol on actuator at entry or exit actuator devices
Rec. Solution:	Recommended: Provide ISA symbol min. 4" x 4" in size
Barrier Severit	cy: 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementatio	on Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 22E
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Men's Restroom
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Height
Code References:	2010 ADAS 307.2
Performance S	Standard: No Quantity: EACH As-built : 1
Barrier	
Description:	Dispenser control point or operating mechanism not max. 48" AFF
Description: Findings:	Dispenser control point or operating mechanism not max. 48" AFF Paper towel dispenser at 57" high
Findings:	
Findings:	Paper towel dispenser at 57" high Remount no higher than 48" above floor
Findings:	Paper towel dispenser at 57" high Remount no higher than 48" above floor Ey: 2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 22F
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Men's Restroom
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Rim Height
Code References:	2010 ADAS 606.3
Performance S	Standard: No Quantity: JOB As-built: 1
Barrier Description:	Lavatory rim or counter edge is higher than 34" AFF
Findings:	34-1/3" high rims
Rec. Solution:	Provide min. 1 accessible lavatory
Barrier Severit	y: 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	on Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 22G
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 22G Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms Doormat 2010 ADAS 302.2 & Advisory 302.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms Doormat 2010 ADAS 302.2 & Advisory 302.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms Doormat 2010 ADAS 302.2 & Advisory 302.2 Standard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms Doormat 2010 ADAS 302.2 & Advisory 302.2 Standard: No Quantity: EACH As-built: 1 Doormat not anchored to floor (trip hazard)
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms Doormat 2010 ADAS 302.2 & Advisory 302.2 Standard: No Quantity: EACH As-built: 1 Doormat not anchored to floor (trip hazard) Door mat under lavatory not secured
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms Doormat 2010 ADAS 302.2 & Advisory 302.2 Standard: No Quantity: EACH As-built: 1 Doormat not anchored to floor (trip hazard) Door mat under lavatory not secured Replace doormat or anchor existing y: 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 22H
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Men's Restroom
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Mirror
Code References:	2010 ADAS 603.3
Performance S	tandard: No Quantity: EACH As-built : 1
Barrier Description:	Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface
Findings:	49-1/2" high
Rec. Solution:	Replace or remount mirror
Barrier Severit	y: 3 Hindrance Cost Est \$375.00 Facility Function: Public Status: Open
Implementatio	on Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 22I
ricia batc.	2/19/2014 Report Date 3/18/2014 Barrier #. 221
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms Urinal - Alcove 2010 ADAS 305.7.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms Urinal - Alcove 2010 ADAS 305.7.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms Urinal - Alcove 2010 ADAS 305.7.1 standard: No Quantity: SF As-built: 100
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms Urinal - Alcove 2010 ADAS 305.7.1 standard: No Quantity: SF As-built: 100 Urinal located in alcove lacks at least 36" clear width in alcove more than 24" deep
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms Urinal - Alcove 2010 ADAS 305.7.1 Itandard: No Quantity: SF As-built: 100 Urinal located in alcove lacks at least 36" clear width in alcove more than 24" deep Urinal in alcove 30" wide x 24-1/2" deep Remodel sanitary facility to provide access
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms Urinal - Alcove 2010 ADAS 305.7.1 Urinal located in alcove lacks at least 36" clear width in alcove more than 24" deep Urinal in alcove 30" wide x 24-1/2" deep Remodel sanitary facility to provide access y: 2 Recommended Cost Est \$57,500.00 Facility Function: Public Status: Open



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 22J
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2
Location:	Floor 1 - Men's Restroom
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Door Closer
Code References:	2010 ADAS 604.8.1.2
Performance S	Standard: No Quantity: JOB As-built : 1
Barrier Description:	Stall door not equipped with an automatic closing device
Findings:	Stall door not self-closing
Rec. Solution:	Replace compartment hinge with adjustible mechanism
Barrier Severit	y: 2 Recommended Cost Est \$1,650.00 Facility Function: Public Status: Open
Implementation	on Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 22K
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 22K Arnold Dining Center Reference Dwg: 2 of 2
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 Standard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 Standard: No Quantity: EACH As-built: 1 Outside of compartment door lacks a loop or U-pull below latch
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 Standard: No Quantity: EACH As-built: 1 Outside of compartment door lacks a loop or U-pull below latch No U-pull provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Men's Restroom N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 Standard: No Quantity: EACH As-built: 1 Outside of compartment door lacks a loop or U-pull below latch No U-pull provided Provide hardware y: 1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open



Field Date: 2/19/2014 Report Date 3/18/2014 Barrier #: 22L	1				
Bldg Name: Arnold Dining Center Reference Dwg: 2 of 2					
Location: Floor 1 - Men's Restroom					
ordinate: N/A Y Coordinate: N/A					
Barrier Area: Restrooms					
Barrier Type: Toilet Stall - Door Hardware					
Code 2010 ADAS 604.8.1.2 References:					
Performance Standard: No Quantity: EACH As-built : 1					
Barrier Inside of compartment door lacks a loop or U-pull below latch Description:					
No U-pull provided Findings:					
Rec. Solution: Provide hardware					
Barrier Severity: 1 Necessary Cost Est \$75.00 Facility Function: Public Status: Oper	1				
Implementation Priority: 3 Implementation Phase: Implementation Date:					
Notes:					
Field Date: 2/19/2014 Report Date 3/18/2014 Barrier #: 22M					
Bldg Name: Arnold Dining Center Reference Dwg: 2 of 2					
Location: Floor 1 - Men's Restroom					
X Coordinate: N/A Y Coordinate: N/A					
Barrier Area: Restrooms					
Barrier Type: Coat Hook					
Code References: 2010 ADAS 603.4					
Performance Standard: No Quantity: EACH As-built : 1					
Barrier Clothing hooks not max. 48" high AFF Description:					
68" high					
Findings:					
Rec. Solution: Provide additional hook					
Barrier Severity: 2 Recommended Cost Est \$125.00 Facility Function: Public Status: Oper	1				
Implementation Priority: 3 Implementation Phase: Implementation Date:					
Notes:	$\overline{}$				



Field Date: 2/19/2014 Report Date 3/18/2014 Barrier #: 22N					
Bldg Name: Arnold Dining Center Reference Dwg: 2 of 2	Arnold Dining Center Reference Dwg: 2 of 2				
Location: Floor 1 - Men's Restroom	Floor 1 - Men's Restroom				
X Coordinate: N/A Y Coordinate: N/A	7				
Barrier Area: Restrooms					
Barrier Type: Toilet Paper Dispenser					
Code 2010 ADAS 604.7 References:					
Performance Standard: No Quantity: EACH As-built : 1					
Barrier Toilet tissue dispenser not within 7" to 9" from front edge of toilet Description:					
Toilet paper dispenser not within 7" to 9" from front edge of toilet Findings:					
Rec. Solution: Reposition or replace toilet paper dispenser					
Barrier Severity: 3 Hindrance Cost Est \$225.00 Facility Function: Public Status: Open					
Implementation Priority: 3 Implementation Phase: Implementation Date:	\Box				
Notes:					
Field Date: 2/19/2014 Report Date 3/18/2014 Barrier #: 23A					
Bldg Name: Arnold Dining Center Reference Dwg: 2 of 2					
Location: Floor 1 - Women's Restroom					
X Coordinate: N/A Y Coordinate: N/A					
Barrier Area: Signage					
Barrier Type: Location - 48" to 60" high					
Code 2010 ADAS 703.4.1 References:					
Performance Standard: No Quantity: EACH As-built : 2					
Barrier Description: Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor					
63" high					
Findings:					
Rec. Solution: Provide accessible signs and mount at proper height					
Barrier Severity: 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open					
Implementation Priority: 3 Implementation Phase: Implementation Date:					
Notes: Also, tactile sign located on a door, Braille not placed below all multi-lined tactile characters in one lin together	e				



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 23B					
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2					
Location:	Floor 1 - Women's Restroom					
X Coordinate:						
Barrier Area:	Doors or Gates					
Barrier Type:	Automatic Doors - Timing					
Code References:	2010 ADAS 404.3					
Performance S	tandard: No Quantity: JOB As-built : 1					
Barrier Description:	Door does not remain open for at least 6 seconds					
Findings:	Door closes after 2 seconds					
Rec. Solution:	Repair actuation device					
Barrier Severit	y: 1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open					
Implementation	on Priority: 3 Implementation Phase: Implementation Date:					
Notes:						
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 23C					
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 23C Arnold Dining Center Reference Dwg: 2 of 2					
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom					
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom					
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A					
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Doors or Gates					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Doors or Gates Automatic Doors - Sign Performance Standard					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Doors or Gates Automatic Doors - Sign Performance Standard					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Doors or Gates Automatic Doors - Sign Performance Standard Standard: Yes Quantity: JOB As-built: 2					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Doors or Gates Automatic Doors - Sign Performance Standard Standard: Yes Quantity: JOB As-built: 2 ISA symbol at automatic door opening device not min. 4" x 4" in size					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Doors or Gates Automatic Doors - Sign Performance Standard Standard: Yes Quantity: JOB As-built: 2 ISA symbol at automatic door opening device not min. 4" x 4" in size No ISA symbol on door actuating devices at entry or exit side of door					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Doors or Gates Automatic Doors - Sign Performance Standard Standard: Yes Quantity: JOB As-built: 2 ISA symbol at automatic door opening device not min. 4" x 4" in size No ISA symbol on door actuating devices at entry or exit side of door Recommended: Provide ISA symbol min. 4" x 4" in size y: 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open					



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 23D				
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2				
Location:	Floor 1 - Women's Restroom				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Restrooms				
Barrier Type:	Dispensers - Protruding Object				
Code References:	2010 ADAS 307.2				
Performance S	Standard: No Quantity: EACH As-built : 1				
Barrier Description:	Protruding dispenser creates protruding hazard in path of travel				
Findings:	Paper towel dispenser protrudes 10" at height over 27" high				
Rec. Solution:	Remove dispenser or provide detectable warning for the visually impaired				
Barrier Severit	y: 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open				
Implementation	on Priority: 3 Implementation Phase: Implementation Date:				
Notes:					
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 23E				
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 23E Arnold Dining Center Reference Dwg: 2 of 2				
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom				
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom				
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A				
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Lavatory - Rim Height 2010 ADAS 606.3				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Lavatory - Rim Height 2010 ADAS 606.3				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Lavatory - Rim Height 2010 ADAS 606.3 Standard: No Quantity: JOB As-built: 1				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Lavatory - Rim Height 2010 ADAS 606.3 Standard: No Quantity: JOB As-built: 1 Lavatory rim or counter edge is higher than 34" AFF				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Lavatory - Rim Height 2010 ADAS 606.3 Standard: No Quantity: JOB As-built: 1 Lavatory rim or counter edge is higher than 34" AFF 34-1/2" high rim				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Lavatory - Rim Height 2010 ADAS 606.3 Standard: No Quantity: JOB As-built: 1 Lavatory rim or counter edge is higher than 34" AFF 34-1/2" high rim Provide min. 1 accessible lavatory y: 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open				



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 23F					
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2					
Location:	Floor 1 - Women's Restroom					
X Coordinate:	N/A Y Coordinate: N/A					
Barrier Area:	Restrooms					
Barrier Type:	Doormat					
Code References:	2010 ADAS 302.2 & Advisory 302.2					
Performance S	standard: No Quantity: EACH As-built: 1					
Barrier Description:	Doormat not anchored to floor (trip hazard)					
Findings:	Door mat under lavatory not secured					
Rec. Solution:	Replace doormat or anchor existing					
Barrier Severit	y: 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open					
Implementation	on Priority: 3 Implementation Phase: Implementation Date:					
Notes:						
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 23G					
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 23G Arnold Dining Center Reference Dwg: 2 of 2					
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom					
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom					
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A					
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Door Clearance - Push Side 2010 ADAS Figure 404.2.4.1					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Door Clearance - Push Side 2010 ADAS Figure 404.2.4.1					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Door Clearance - Push Side 2010 ADAS Figure 404.2.4.1 standard: No Quantity: EACH As-built: 100					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Door Clearance - Push Side 2010 ADAS Figure 404.2.4.1 Standard: No Quantity: EACH As-built: 100 Door lacks min. 12" strike edge clearance at push side					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Door Clearance - Push Side 2010 ADAS Figure 404.2.4.1 Standard: No Quantity: EACH As-built: 100 Door lacks min. 12" strike edge clearance at push side 41" wide x 105" deep corridor leading to accessible toilet stall					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Door Clearance - Push Side 2010 ADAS Figure 404.2.4.1 Standard: No Quantity: EACH As-built: 100 Door lacks min. 12" strike edge clearance at push side 41" wide x 105" deep corridor leading to accessible toilet stall Remodel to provide accessible maneuvering clearance at stall entry door y: 1 Necessary Cost Est \$57,500.00 Facility Function: Public Status: Open					



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 23H				
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2				
Location:	Floor 1 - Women's Restroom				
X Coordinate:					
Barrier Area:	ea: Restrooms				
Barrier Type:	Toilet Stall - Door Hardware				
Code References:	2010 ADAS 604.8.1.2				
Performance S	standard: No Quantity: EACH As-built : 1				
Barrier Description:	Outside of compartment door lacks a loop or U-pull below latch				
Findings:	No U-pull provided				
Rec. Solution:	Provide hardware				
Barrier Severit	y: 1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open				
Implementation	on Priority: 3 Implementation Phase: Implementation Date:				
Notes:					
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 23I				
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 23 Arnold Dining Center Reference Dwg: 2 of 2				
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom				
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom				
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A				
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 Standard: No Quantity: EACH As-built: 1				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 Standard: No Quantity: EACH As-built: 1 Inside of compartment door lacks a loop or U-pull below latch				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 Standard: No Quantity: EACH As-built: 1 Inside of compartment door lacks a loop or U-pull below latch No U-pull provided				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Toilet Stall - Door Hardware 2010 ADAS 604.8.1.2 Standard: No Quantity: EACH As-built: 1 Inside of compartment door lacks a loop or U-pull below latch No U-pull provided Provide hardware y: 1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open				



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 23J					
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2					
Location:	Floor 1 - Women's Restroom					
X Coordinate:						
Barrier Area:						
Barrier Type:	Coat Hook					
Code References:	2010 ADAS 603.4					
Performance S	Standard: No Quantity: EACH As-built : 1					
Barrier Description:	Clothing hooks not max. 48" high AFF					
Findings:	68" high					
Rec. Solution:	Provide additional hook					
Barrier Severit	y: 2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open					
Implementation	on Priority: 3 Implementation Phase: Implementation Date:					
Notes:						
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 23K					
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 23K Arnold Dining Center Reference Dwg: 2 of 2					
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom					
Bldg Name: Location:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom					
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A					
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Toilet Paper Dispenser 2010 ADAS 604.7					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Toilet Paper Dispenser 2010 ADAS 604.7					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Toilet Paper Dispenser 2010 ADAS 604.7 Standard: No Quantity: EACH As-built: 1					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Toilet Paper Dispenser 2010 ADAS 604.7 Standard: No Quantity: EACH As-built: 1 Toilet tissue dispenser not within 7" to 9" from front edge of toilet					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Toilet Paper Dispenser 2010 ADAS 604.7 Standard: No Quantity: EACH As-built: 1 Toilet tissue dispenser not within 7" to 9" from front edge of toilet Toilet paper dispenser not within 7" to 9" from front edge of toilet					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Women's Restroom N/A Y Coordinate: N/A Restrooms Toilet Paper Dispenser 2010 ADAS 604.7 Standard: No Quantity: EACH As-built: 1 Toilet tissue dispenser not within 7" to 9" from front edge of toilet Toilet paper dispenser not within 7" to 9" from front edge of toilet Reposition or replace toilet paper dispenser y: 3 Hindrance Cost Est \$225.00 Facility Function: Public Status: Open					



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 24A					
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2					
Location:	Floor 1 - Market-Office Area 0134					
X Coordinate:	N/A Y Coordinate: N/A					
Barrier Area:	Signage					
Barrier Type:	Location - 48" to 60" high					
Code References:	2010 ADAS 703.4.1					
Performance S	Standard: No Quantity: EACH As-built : 3					
Barrier Description:	Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor					
Findings:	64" high					
Rec. Solution:	Provide accessible signs and mount at proper height					
Barrier Severit	y: 1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open					
Implementatio	on Priority: 3 Implementation Phase: Implementation Date:					
	et 0134, Dining Office 0131 and dining 0101. Also, Braille not 3/8" and max. 1/2" directly below ctile characters					
Field Date:	2/40/2044 Papart Data 2/40/2044 Parrier # 24D					
rieiu Date.	2/19/2014 Report Date 3/18/2014 Barrier #: 24B					
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2					
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134					
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134					
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134 N/A Y Coordinate: N/A					
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134 N/A Y Coordinate: N/A Clear Floor Space					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - Wheelchair Use 2010 ADAS 305					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - Wheelchair Use 2010 ADAS 305					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - Wheelchair Use 2010 ADAS 305 Standard: No Quantity: SF As-built: 0					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - Wheelchair Use 2010 ADAS 305 Standard: No Quantity: SF As-built: 0 Clear floor space of min. 30" by 48" not provided					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - Wheelchair Use 2010 ADAS 305 Standard: No Quantity: SF As-built: 0 Clear floor space of min. 30" by 48" not provided Table blocks signs clear floor space					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - Wheelchair Use 2010 ADAS 305 Standard: No Quantity: SF As-built: 0 Clear floor space of min. 30" by 48" not provided Table blocks signs clear floor space Remove table at entry door blocking tactile sign read by touch cy: 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open					



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 24C					
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2					
Location:	Floor 1 - Market-Office Area 0134					
X Coordinate:						
Barrier Area:	Dining Facilities					
Barrier Type:	Fire Extinguisher - Protruding Hazard					
Code References:	2010 ADAS 307.2					
Performance S	standard: No Quantity: JOB As-built: 1					
Barrier Description:	Fire extinguisher protrudes into circulation path more than 4" between 27" and 80"					
Findings:	Fire extinguisher protrudes 4-1/2" at 35" high					
Rec. Solution:	Move extinguisher to another area and remount with leading edge below 27" or provide detecta					
Barrier Severit	y: 4 Low Severity Cost Est \$1,500.00 Facility Function: Public Status: Open					
Implementation	on Priority: 2 Implementation Phase: Implementation Date:					
Notes:						
Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 24D					
Field Date: Bldg Name:	2/19/2014 Report Date 3/18/2014 Barrier #: 24D Arnold Dining Center Reference Dwg: 2 of 2					
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134					
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134					
Bldg Name: Location: X Coordinate:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134 N/A Y Coordinate: N/A					
Bldg Name: Location: X Coordinate: Barrier Area:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134 N/A Y Coordinate: N/A Dining Facilities					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134 N/A Y Coordinate: N/A Dining Facilities Fire Extinguisher - Clear Floor Space 2010 ADAS 308.2.2					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134 N/A Y Coordinate: N/A Dining Facilities Fire Extinguisher - Clear Floor Space 2010 ADAS 308.2.2					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134 N/A Y Coordinate: N/A Dining Facilities Fire Extinguisher - Clear Floor Space 2010 ADAS 308.2.2 standard: No Quantity: JOB As-built: 1					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134 N/A Y Coordinate: N/A Dining Facilities Fire Extinguisher - Clear Floor Space 2010 ADAS 308.2.2 Standard: No Quantity: JOB As-built: 1 Fire extinguisher or cabinet lacks clear floor space					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134 N/A Y Coordinate: N/A Dining Facilities Fire Extinguisher - Clear Floor Space 2010 ADAS 308.2.2 Standard: No Quantity: JOB As-built: 1 Fire extinguisher or cabinet lacks clear floor space Table and chair block fire extinguisher clear floor space near exit door					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance S Barrier Description: Findings: Rec. Solution:	Arnold Dining Center Reference Dwg: 2 of 2 Floor 1 - Market-Office Area 0134 N/A Y Coordinate: N/A Dining Facilities Fire Extinguisher - Clear Floor Space 2010 ADAS 308.2.2 Standard: No Quantity: JOB As-built: 1 Fire extinguisher or cabinet lacks clear floor space Table and chair block fire extinguisher clear floor space near exit door Remove stored objects or relocate y: 4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open					



Field Date:	2/19/2014 Report Date 3/18/2014 Barrier #: 24E					
Bldg Name:	Arnold Dining Center Reference Dwg: 2 of 2					
Location:	ation: Floor 1 - Market-Office Area 0134					
X Coordinate:	N/A Y Coordinate: N/A	1				
Barrier Area:	Dining Facilities					
Barrier Type:	Table Seating - Knee Clearance					
Code References:	2010 ADAS 902.2					
Performance S	Standard: No Quantity: EACH As-built : 1					
Barrier Description:	Table knee clearance not min. 27" high, 30" wide or 19" deep					
Findings:	8 pedestal tables identified. None are accessible					
Rec. Solution:	Provide min. 1 accessible table. Avoid pedestal base tables					
Barrier Severit	y: 2 Recommended Cost Est \$450.00 Facility Function: Public Status: Open					
Implementatio	on Priority: 2 Implementation Phase: Implementation Date:					
Notes:						





SUMMARY REPORT

Cost Estimate Total	\$196,750.00		
Cost Estimate - Priority 1:	\$3,300.00	% of Total Cost Estimate:	1.68%
Cost Estimate - Priority 2:	\$56,950.00	% of Total Cost Estimate:	28.95%
Cost Estimate - Priority 3:	\$136,500.00	% of Total Cost Estimate:	69.38%