SZS CONSULTING GROUP

OREGON STATE UNIVERSITY (OSU)

BATCHELLER HALL

ADA ASSESSMENT & SURVEY



Sacramento Office 770 L Street, Suite 950 Sacramento, CA 95814 Tel: 916.669.8750 Fax: 888.211.7441

Silicon Valley Office 2225 E. Bayshore Road, Suite 200 Pale Alto CA 24202

Palo Alto CA 94303 Tel: 866.694.7637 www.szs-consulting.com

January 9, 2015



Angelo Gomez Executive Director Office of Equity and Inclusion Oregon State University 330 Snell Hall Corvallis, OR 97331-2128

Re: ADA Accessibility Survey and Assessment - Batcheller Hall

Dear Angelo,

We are pleased to submit this report for the Batcheller Hall. This report is part of our project to provide a Campus Accessibility Survey and Assessment for Oregon State University. It is our hope that this report will assist OSU in improving access to people with disabilities to campus facilities.

SZS has been pleased to be a part of this effort to evaluate campus buildings using federal and state statutes and regulations, as well as universal design principles in order to create performance standards that will guide design, construction and maintenance on campus.

We look forward to discussing our findings with your team.

Regards,

Syroun Z. Sanossian, Principal SZS Consulting Group LLC

Syn 2. 8m.

TABLE OF CONTENTS

1.	EXECUTIV	VE SUMMARY OF FINDINGS	p. 1	
	a.	Pedestrian Facilities and Exterior Spaces Analyzed	p. 2	
	b.	Building Entrances	p. 3	
2.	INTERIOR	? SPACES		
		Basement	p. 4	
		First Floor	p. 5	
		Second Floor	p. 6	
		Third Floor	p. 6	
3.	BARRIEF	R DATA RECORDS		
		Exterior Area Barriers	p. 7	
		Interior Area Barriers	p. 14	
		Cost Estimate	p. 198	3

1. EXECUTIVE SUMMARY OF FINDINGS

The field investigation for the interior spaces began on March 4, 2014. The exterior site elements were assessed originally as part of the pedestrian facilities assessment in June-September 2011 and are included as an essential part of this report. Images of each physical element identified in this report were captured in HD digital photos while manual measurements were taken to establish as-built conditions to facilitate the process of cost estimating. Digital photographs are provided within the report for each barrier to access, to facilitate the review of the data collected. We have found that technical data can be difficult to interpret without a visual component; the photos provide a clear connection between the technical data and each barrier to access.

The Batcheller Hall is a historic structure and many barriers to access were identified in the building. That is quite typical, as barriers to access exist in virtually every building, whether new or existing.

No "perfect" building exists in the real world.

This ADA Assessment and Survey report is intended to not only identify barriers to access, but to provide solutions. The basis for this ADA Assessment and Survey process is the underlying desire on the part of OSU to improve access by relying on higher standards than the minimum requirements in state and federal building codes. SZS intends to provide the information in this report in a clear and easy to understand format. The information in this report is compiled for use by designated OSU staff and other interested persons, so the content is designed to be understood by professionals and laymen alike.

The findings presented are both narrative and technical in nature; barriers to access identified during the field investigation process are documented in two ways;

1. Narrative Analysis: The analysis of findings is contained in an executive summary in a narrative form that not only describes each type of barrier identified but also provides a discussion that analyses the functionality of physical elements. We also provide the reasoning and research behind the identification of barriers that conflict with universal design principles. This analysis may be accompanied by digital photographs or diagrams, where applicable.

NOTE: Understanding building function and usage is essential when interpreting the findings held in this report. The narrative is intended to facilitate this process.

2. Barrier Data Records: Individual barriers to access are entered into the SZS database so that technical information on the barriers can be provided as barrier data records. These barrier data records include digital photographs of each barrier identified, code references that determine the barrier to access, as-built measurements, barrier severity ratings, budgetary cost estimates, recommended solutions for barrier removal and a priority for barrier removal. The information is formatted with two barriers on each report page.

In order to consolidate the report data, some of the more typical barriers found in multiple locations have been grouped within the barrier data records with a description of the locations in which they were found.

A. Pedestrian Facilities and Exterior Spaces Analyzed

This report provides information on campus pedestrian facilities that serve Batcheller Hall. Many physical elements are part of the comprehensive whole that creates a pedestrian facility. The fundamental elements evaluated as to whether they provide accessible pedestrian facilities include the following:

- Sidew alks
- Walkw ays
- Ramps
- Curb Ramps
- **Blended Transitions**
- Signalized Intersections
- Stairw ays (94% of people with disabilities are not mobility impaired)
- Benches and other Seating Elements
- Picnic Facilities

The descriptions provided for physical elements in this report are intended to clearly describe the differences between each physical element, such as when a pedestrian route is a sidewalk, rather than a walkway. The descriptions are intended to explain how the elements interact to form a cohesive pedestrian facility. Other more specific information described within this section intends to provide guidance on determinations made in this report.

The key to providing accessible pedestrian facilities is in recognizing that different people with disabilities have different needs. Setting policies that speak to the entire group is essential, rather than focusing one particular subset of the overall group. Universal design principles govern here - physical elements should be usable to everyone that visits campus without having to resort to any adaptation or specialized design.

In summary, an accessible route exists within a building, property boundary or interior space and is separate from the PROW. Pedestrian walkways are similar to sidewalks as paved surfaces improved for use by pedestrians but walkways are not located along or adjacent to the curb line, gutter or roadway and walkways are generally not considered part of the PROW. The pedestrian facility is the combination of the PROW and the accessible route, which functions as a whole to provide pedestrian access to facility entrances.

Batcheller Hall is considered a historic structure. As a public building governed by the ADA Standards, Batcheller Hall should have at least one accessible entrance, but all physical entrances at the building are by way of stairs. The building is located on the north side of SW Campus Way between Covell Hall and Dearborn Hall. Although the only direct vertical access provided to the building is in the form of stairways, an interior corridor connection to Covell Hall provides a way for people with mobility impairments to enter Covell Hall, travel through that building and reach Batcheller Hall although the pedestrian route is in excess of

200 linear feet. According to the ADA Standards Advisory Section 405.2, to accommodate the widest range of users, the length of pedestrian routes can be a concern for those individuals for whom distance presents a greater barrier than steps, e.g., people with heart disease or limited stamina. Also, according to the ADA Standards Section 403.5.3 Passing Spaces, an accessible route with a clear width less than 60 inches shall be provided to allow passing spaces at intervals of 200 feet maximum. Passing spaces shall be either: a space 60 inches minimum by 60 inches minimum; or, an intersection of two walking surfaces providing a T-shaped space where the base and arms of the T-shaped space extend 48 inches minimum beyond the intersection. The provision of a passing space throughout this lengthy path of travel between the accessible entrance of Covell Hall and Batcheller Hall may be difficult to maintain over time. It is important to ensure that maintenance staff understands that the corridors used for this path of travel are kept clear.

Where this connection route remains accessible, Batcheller Hall can be considered to have an accessible route provided within the site from accessible parking spaces and accessible passenger loading zones; public streets and sidewalks; and public transportation stops to the accessible building or facility entrance they serve as compared to the 2010 ADA Standard for Accessible Design. Details on barriers identified in that route are provided within the ADA Assessment and Survey of the pedestrian facilities provided as a separate report, as well as in the following records. Please see the barrier data records for details.

B. Building Entrances

The building is located along SW Campus Way. No parking is provided on-site. Pedestrian entrances are provided at the north and south sides of the building, as described above. No International Symbol of Accessibility (ISA) directional sign is provided at these locations or ground floor entrance doors leading to stairways indicating that the accessible route to this building is provided through Covell Hall. This signage is essential.

¹ 2010 ADA Standards for Accessible Design, Section 206.2.1 Site Arrival Points

INTERIOR SPACES

BASEMENT

Batcheller Hall is a three-story building including a basement. The building is pre-ADA building and entrance to the building is provided through Covell Hall, as discussed above. The basement houses an ergonomics laboratory, classroom, computer lab and a men's restroom. Barriers identified in the basement include entrance doors to classrooms or laboratories that lacked accessible signage, door hardware, door closer operating force/sweep period where door closers were installed and where doors were identified with view panels, the panels were not accessible to short people or wheelchair users.

In many instances, entry doors lacked accessible maneuvering clearance as either a result of the original design or due to the location of cabinets or other items that encroached into the space needed by wheelchair users to maneuver. The lack of accessible maneuvering clearance may necessitate the installation of automatic door opening devices at entrance doors to classrooms and laboratories in many locations. Light switches and outlets were identified as non-accessible throughout the floor. Accessible desks were not provided and strobe devices used to notify people with hearing impairments of an alarm actuation were not identified in these spaces.

A computer lab on this floor lacked accessible workstations and a classroom with fixed seats also lacked accessible desks where at least 5% should be accessible. The ergonomics lab was identified with no accessible desks, protruding hazards and an exit door from the lab lacked accessible hardware and maneuvering clearance.

Tactile signage was not identified in any location on this floor. No drinking fountains were identified in the basement and the central corridor was identified with non-accessible signage, protruding objects and exit doors in the corridor lacked tactile exit signs or accessible operating force, door hardware or clear width adequate to allow a person using a mobility assist device to enter the building on this level. A drainage grate located in the center of the corridor created a trip hazard and uneven walking surface in the corridor. Fire pulls in the basement were not fist operable and the actuating devices were not located within accessible reach ranges.

The north entry and lobby were identified as lacking accessible signage including lobby informational signage and protruding objects were identified in those spaces. Doors were

identified with non-accessible operating force, view panels to high for use by short people, door stops and an uneven surface within the bottom 10" of each door could create trap conditions for people who use wheelchairs. Signage indicating the location of the emergency exit was also not provided.

The north exit stairway exit passage lacks accessible doors, door operating force and doormats in the pathway are also not secured. The stairway handrails appeared to be original to the building and were not accessible. The stairway tread surface appeared to be slick and may lack slip resistance although the surface was not rigorously tested.



A men's restroom was located within the central corridor. The sanitary facility was a multiaccommodation restroom. The entry door lacked accessible signage, the door operating force was excessive, and the door hardware was not accessible. Signage posted above the entry door lacked characters that could be viewed from a distance. The restroom lacked an accessible lavatory, urinal or toilet. Maneuvering clearance in the room was not adequate to allow a person using a wheelchair to pull in front of a lavatory or enter a toilet stall. Dispensers created protruding objects within the circulation route in the room, which presents a barrier to the visually impaired and strobe devices used to notify people with hearing impairments of an alarm actuation were not identified in these spaces.

The central corridor was identified with non-accessible signage, protruding objects and exit doors in the corridor lacked tactile exit signs or accessible operating force and door hardware. A phone and fire pull were not located within accessible reach ranges.

The Hub study area lacked accessible entry doors, signage and clear floor space in the waiting area. The advising areas were identified with accessible desks and maneuvering clearance in the public areas, but tables and study carrels within the Hub were not accessible.

FIRST FLOOR


A women's single accommodation toilet room is located on the intermediate stairway landing in the north stairway. The door signage was not accessible, the entry door was too narrow for someone using a mobility assist device to enter and the existing square footage of the room is not adequate for accessibility. More importantly, the restroom is not located on an accessible route, although it is the only restroom on the first floor. The stairway serves as the north entry point for the building. Fire pulls in the stairwell and central corridor were not fist operable and the actuating devices including light switches were not located within accessible reach ranges. An electrical panel located directly in the emergency exit path lacked detectable warnings, and the stairway clear width may not be adequate for emergency exiting considering the occupancy load in classrooms and laboratories on upper floors.

The entry doors at the north and south stairways were identified with ISA signs (stickers) within the door view panels, but people would have to travel up the stairs to view the sign and find that the accessible entrance is located elsewhere. It is recommended to provide ISA directional sign in a location where people approaching the building can make use of information without having to retrace their steps.

A public phone in the central lobby was not located within accessible reach range. Electrical outlets were identified along the baseboard a few inches from the floor where people using wheelchairs could not reach them. A drinking fountain intended for wheelchair access was located in the lobby but it was not located within an alcove. It was also mounted with knee clearance that could prevent people using wheelchairs from pulling under the fountain. A shelf mounted next to the fountain also has a sharp metal edge that protrudes into the circulation route in the lobby and no detectable warning is provided.

No elevator is provided in the building. Barriers identified in the first floor were commonly identified throughout the building in common use areas. Classrooms and laboratory space in the building lacked entry doors that operated with accessible opening force and lacked accessible door view panels and strike edge clearance necessary for people using

wheelchairs to maneuver close enough to the door to operate the door hardware. Controls and mechanisms such as pencil sharpeners were also not located within accessible reach ranges. Carpet in classroom 150 was deteriorating and could create trip hazards or hinder wheelchair travel as shown in the figure to the right.



SECOND FLOOR

Barriers noted above in public use spaces were similar to those identified in the lower floors of the building. Many staff and faculty offices are located on floor 2. Staff only areas were not part of the scope of work for this assessment report.

A women's single accommodation toilet room is located on the west side of floor 2. No drinking fountain was located on floor 2. The door signage was not accessible, the entry door was too narrow for someone using a mobility assist device to enter and the entry door was heavy. The room could be remodeled to provide wheelchair access with the relocation or replacement of dispensers, the toilet and lavatory. Fire pulls in the stairwell and central corridor were not fist operable and the actuating devices including light switches were not located within accessible reach ranges.

Corridors, a computer lab and the Precollege Program workroom were identified with barriers described above including a lack of maneuvering clearance due to both the number of desks or workspaces in rooms and the limited square footage.

THIRD FLOOR

Restrooms or drinking fountains were not provided on the third floor. A number of staff-use only spaces and work areas were located on the floor. Public areas on floor 3 include corridors, a north stairway, conference room and waiting room for academic advising. The entry doors and signage at the waiting room and conference room were not accessible. some controls and mechanisms were not at accessible locations and the table used for meetings lacked accessible knee clearance and no portable assistive listening system was identified as available for use in the room, on an as needed basis.

A workroom was located on the east side of the floor. The space was not provided with accessible fixtures, counter, sink or maneuvering clearance but the room also served as an emergency exit by way of stairs where no accessible route was provided for people with mobility impairments and no accessible bridge connection was provided on floor 3 which prevents access to the floor for people with mobility impairments.

The following barrier data records provide more detailed information on the barriers described above.





Field Date:	6/28/2011 Report Date 6/28/2011 Barrier #: 255A
Bldg Name:	Batcheller Hall Reference Dwg: 1 of 5
Location:	Exterior - North Stairway Entrance
X Coordinate:	7478982.85 Y Coordinate: 340709.422
Barrier Area:	Signage
Barrier Type:	ISA - Non-Accessible Entry
Code References:	2010 ADAS 216.6
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Sign directing people to accessible entrance needed where all doors are not accessible
Findings:	Accessible sign not provided
Rec. Solution:	Provide ISA directional sign with arrow directing people to accessible entrance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/28/2011 Report Date 6/28/2011 Barrier #: 255B
Field Date: Bldg Name:	6/28/2011 Report Date 6/28/2011 Barrier #: 255B Batcheller Hall Reference Dwg: 1 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 1 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - North Stairway Entrance
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - North Stairway Entrance 7478982.85 Y Coordinate: 340709.422
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - North Stairway Entrance 7478982.85 Y Coordinate: 340709.422 Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 1 of 5 Exterior - North Stairway Entrance 7478982.85 Y Coordinate: 340709.422 Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - North Stairway Entrance 7478982.85 Y Coordinate: 340709.422 Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 1 of 5 Exterior - North Stairway Entrance 7478982.85 Y Coordinate: 340709.422 Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3 ndard: No Quantity: LF As-built: 225
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - North Stairway Entrance 7478982.85 Y Coordinate: 340709.422 Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3 ndard: No Quantity: LF As-built: 225 Bottom handrail extension not sloped for length of one tread beyond the last riser nosing
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - North Stairway Entrance 7478982.85 Y Coordinate: 340709.422 Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3 ndard: No Quantity: LF As-built: 225 Bottom handrail extension not sloped for length of one tread beyond the last riser nosing Bottom handrail extension not min. 12" Provide handrails at both sides of stairway
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - North Stairway Entrance 7478982.85 Y Coordinate: 340709.422 Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3 ndard: No Quantity: LF As-built: 225 Bottom handrail extension not sloped for length of one tread beyond the last riser nosing Bottom handrail extension not min. 12" Provide handrails at both sides of stairway 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	6/28/2011 Report Date 6/28/2011 Barrier #: 255C
Bldg Name:	Batcheller Hall Reference Dwg: 1 of 5
Location:	Exterior - North Stairway Entrance
X Coordinate:	7478982.85 Y Coordinate: 340709.422
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code References:	2010 ADAS Advisory 504.4
Performance Sta	ndard: Yes Quantity: LF or TR As-built : 35
Barrier Description:	No contrasting color on each tread of exterior stairway
Findings:	No contrasting color provided
Rec. Solution:	Consider providing contrasting color on each tread
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/28/2011 Report Date 6/28/2011 Barrier #: 255D
Field Date: Bldg Name:	6/28/2011 Report Date 6/28/2011 Barrier #: 255D Batcheller Hall Reference Dwg: 1 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 1 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - North Stairway Entrance
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - North Stairway Entrance 7478982.85 Y Coordinate: 340709.422
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - North Stairway Entrance 7478982.85 Y Coordinate: 340709.422 Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 1 of 5 Exterior - North Stairway Entrance 7478982.85 Y Coordinate: 340709.422 Stairways Vertical Access - Lift 2010 ADAS 403.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - North Stairway Entrance 7478982.85 Y Coordinate: 340709.422 Stairways Vertical Access - Lift 2010 ADAS 403.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 1 of 5 Exterior - North Stairway Entrance 7478982.85 Y Coordinate: 340709.422 Stairways Vertical Access - Lift 2010 ADAS 403.1 Indard: No Quantity: JOB As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - North Stairway Entrance 7478982.85 Y Coordinate: 340709.422 Stairways Vertical Access - Lift 2010 ADAS 403.1 Indard: No Quantity: JOB As-built: 0 No form of vertical access provided at stairway to reach upper floors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - North Stairway Entrance 7478982.85 Y Coordinate: 340709.422 Stairways Vertical Access - Lift 2010 ADAS 403.1 Indard: No Quantity: JOB As-built: 0 No form of vertical access provided at stairway to reach upper floors Stairway is the only pedestrian route into building
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - North Stairway Entrance 7478982.85 Y Coordinate: 340709.422 Stairways Vertical Access - Lift 2010 ADAS 403.1 No Quantity: JOB As-built: 0 No form of vertical access provided at stairway to reach upper floors Stairway is the only pedestrian route into building Provide ISA directional sign indicating location of and route to accessible entry at Covell Hall 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	6/28/2011 Report Date 6/28/2011 Barrier #: 257A
Bldg Name:	Batcheller Hall Reference Dwg: 1 of 5
Location:	Exterior - North Stairway Entrance Landing
X Coordinate:	7478986.92 Y Coordinate: 340704.456
Barrier Area:	Signage
Barrier Type:	ISA - Non-Accessible Entry
Code References:	2010 ADAS 404.2.4.4
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Sign directing people to accessible entrance needed where all doors are not accessible
Findings:	Accessible sign not provided
Rec. Solution:	Provide ISA directional sign with arrow directing people to accessible entrance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	6/28/2011 Report Date 6/28/2011 Barrier #: 257B
Bldg Name:	Batcheller Hall Reference Dwg: 1 of 5
Location:	Exterior - North Stairway Entrance Landing
X Coordinate:	7478986.92 Y Coordinate: 340704.456
Barrier Area:	
	Doors or Gates
Barrier Type:	Doors or Gates Door/Gate Landing - Existing (≥ 5.0%)
Barrier Type: Code References:	
Code	Door/Gate Landing - Existing (≥ 5.0%) 2010 ADAS 404.2.4.4
Code References:	Door/Gate Landing - Existing (≥ 5.0%) 2010 ADAS 404.2.4.4
Code References: Performance Sta Barrier	Door/Gate Landing - Existing (≥ 5.0%) 2010 ADAS 404.2.4.4 Indard: No Quantity: SF As-built: 125
Code References: Performance Sta Barrier Description:	Door/Gate Landing - Existing (≥ 5.0%) 2010 ADAS 404.2.4.4 Indard: No Quantity: SF As-built: 125 Door or gate lacks landing on both sides of door
Code References: Performance Sta Barrier Description: Findings:	Door/Gate Landing - Existing (≥ 5.0%) 2010 ADAS 404.2.4.4 Indard: No Quantity: SF As-built: 125 Door or gate lacks landing on both sides of door 9.5% slope Demolish and reconstruct level landing
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Door/Gate Landing - Existing (≥ 5.0%) 2010 ADAS 404.2.4.4 Indard: No Quantity: SF As-built: 125 Door or gate lacks landing on both sides of door 9.5% slope Demolish and reconstruct level landing 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	7/7/2011 Report Date 7/7/2011 Barrier #: 498A
Bldg Name:	Batcheller Hall Reference Dwg: 1 of 5
Location:	Exterior - South Stairway Entrance
X Coordinate:	7478982.473 Y Coordinate: 340625.542
Barrier Area:	Signage
Barrier Type:	ISA - Non-Accessible Entry
Code References:	2010 ADAS 216.6
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Sign directing people to accessible entrance needed where all doors are not accessible
Findings:	Accessible sign not provided
Rec. Solution:	Provide ISA directional sign indicating location of and route to accessible entry at Covell Hall
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/7/2011 Report Date 7/7/2011 Barrier #: 498B
Bldg Name:	Batcheller Hall Reference Dwg: 1 of 5
Location:	Exterior - South Stairway Entrance
X Coordinate:	7478982.473 Y Coordinate: 340625.542
Barrier Area:	Stairways
Barrier Type:	Riser Height - Existing
Code References:	2010 ADAS 504.2
Performance Sta	andard: No Quantity: SF As-built : 250
Barrier Description:	Stair riser height or tread width is not consistent
Findings:	Consistent stair riser height or tread width provided
Rec. Solution:	Demolish and construct new stairway
Rec. Solution: Barrier Severity:	
	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open




Field Date:	7/7/2011 Report Date 7/7/2011 Barrier #: 498C
Bldg Name:	Batcheller Hall Reference Dwg: 1 of 5
Location:	Exterior - South Stairway Entrance
X Coordinate:	7478982.473 Y Coordinate: 340625.542
Barrier Area:	Stairways
Barrier Type:	Handrail Height
Code References:	2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built: 225
Barrier Description:	Handrail grip measured at center not 34"- 38" high
Findings:	32" handrail grip height
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/7/2011 Report Date 7/7/2011 Barrier #: 498D
Field Date: Bldg Name:	7/7/2011 Report Date 7/7/2011 Barrier #: 498D Batcheller Hall Reference Dwg: 1 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 1 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - South Stairway Entrance
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - South Stairway Entrance 7478982.473 Y Coordinate: 340625.542
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - South Stairway Entrance 7478982.473 Y Coordinate: 340625.542 Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 1 of 5 Exterior - South Stairway Entrance 7478982.473 Y Coordinate: 340625.542 Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - South Stairway Entrance 7478982.473 Y Coordinate: 340625.542 Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 1 of 5 Exterior - South Stairway Entrance 7478982.473 Y Coordinate: 340625.542 Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 ndard: Yes Quantity: LF or TR As-built: 35
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - South Stairway Entrance 7478982.473 Y Coordinate: 340625.542 Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 ndard: Yes Quantity: LF or TR As-built: 35 No contrasting color on each tread of exterior stairway
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - South Stairway Entrance 7478982.473 Y Coordinate: 340625.542 Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 ndard: Yes Quantity: LF or TR As-built: 35 No contrasting color on each tread of exterior stairway No contrasting color provided Consider providing contrasting color on each tread
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 1 of 5 Exterior - South Stairway Entrance 7478982.473 Y Coordinate: 340625.542 Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 Indard: Yes Quantity: LF or TR As-built: 35 No contrasting color on each tread of exterior stairway No contrasting color provided Consider providing contrasting color on each tread 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	7/7/2011 Report Date 7/7/2011 Barrier #: 498E
Bldg Name:	Batcheller Hall Reference Dwg: 1 of 5
Location:	Exterior - South Stairway Entrance
X Coordinate:	7478982.473 Y Coordinate: 340625.542
Barrier Area:	Stairways
Barrier Type:	Vertical Access - Lift
Code References:	2010 ADAS 403.1
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	No form of vertical access provided at stairway to reach upper floors
Findings:	Stairway is the only pedestrian route into building
Rec. Solution:	Provide a wheelchair lift to reach upper floors in at least one location
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/7/2011 Report Date 7/7/2011 Barrier #: 499A
Bldg Name:	Batcheller Hall Reference Dwg: 1 of 5
Location:	Exterior Court Stainway Entranga Landing
	Exterior - South Stairway Entrance Landing
X Coordinate:	7478997.92 Y Coordinate: 340636.491
X Coordinate: Barrier Area:	
	7478997.92 Y Coordinate: 340636.491
Barrier Area:	7478997.92 Y Coordinate: 340636.491 Signage
Barrier Area: Barrier Type: Code	7478997.92 Y Coordinate: 340636.491 Signage ISA - Non-Accessible Entry 2010 ADAS 404.2.4.4
Barrier Area: Barrier Type: Code References:	7478997.92 Y Coordinate: 340636.491 Signage ISA - Non-Accessible Entry 2010 ADAS 404.2.4.4
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	7478997.92 Y Coordinate: 340636.491 Signage ISA - Non-Accessible Entry 2010 ADAS 404.2.4.4 Indard: No Quantity: EACH As-built: 1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	7478997.92 Y Coordinate: 340636.491 Signage ISA - Non-Accessible Entry 2010 ADAS 404.2.4.4 Indard: No Quantity: EACH As-built: 1 Sign directing people to accessible entrance needed where all doors are not accessible
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Taylor T
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Tayson T



Field Date:	7/7/2011 Report Date 7/7/2011 Barrier #: 499B
Bldg Name:	Batcheller Hall Reference Dwg: 1 of 5
Location:	Exterior - South Stairway Entrance Landing
X Coordinate:	7478997.92 Y Coordinate: 340636.491
Barrier Area:	Doors or Gates
Barrier Type:	Door/Gate Landing - Existing (≥ 5.0%)
Code References:	2010 ADAS 404.2.4.4
Performance Sta	ndard: No Quantity: SF As-built: 125
Barrier Description:	Door or gate lacks landing on both sides of door
Findings:	9.8% slope
Rec. Solution:	Demolish and reconstruct level landing
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	7/7/2011 Report Date 7/7/2011 Barrier #:
Bldg Name:	Batcheller Hall Reference Dwg:
Location:	
X Coordinate:	Y Coordinate:
Barrier Area:	
Barrier Type:	
Code References:	
Performance Sta	ndard: Quantity: As-built :
Barrier Description:	
Findings:	
Rec. Solution:	
Barrier Severity:	Cost Est Facility Function: Status:
Implementation	Priority: Implementation Phase: Implementation Date:
Notes: Barrier o	data record left blank intentionally to facilitate printing





Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 1A
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - East Corridor H0002
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Abrupt Change in Level
Code References:	2010 ADAS 303.3
Performance Sta	ndard: No Quantity: LF As-built : 1
Barrier Description:	Change in level greater than 1/2" leading in circulation path
Findings:	Grate in route is deteriorating and may potential cause a trip hazard in circulation route
Rec. Solution:	Repair or replace to remove trip hazard
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes: Accessik	ole entry to Batcheller Hall is currently provided through Covell Hall's accessible entry
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 1B
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 1B Batcheller Hall Reference Dwg: 2 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 2 of 5 Basement - East Corridor H0002
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 2 of 5 Basement - East Corridor H0002 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 2 of 5 Basement - East Corridor H0002 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 2 of 5 Basement - East Corridor H0002 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 2 of 5 Basement - East Corridor H0002 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 2 of 5 Basement - East Corridor H0002 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 2 of 5 Basement - East Corridor H0002 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 ndard: No Quantity: EACH As-built: 1 No sign with raised characters and Braille at permanent room or space with visual sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 2 of 5 Basement - East Corridor H0002 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 No Quantity: EACH As-built: 1 No sign with raised characters and Braille at permanent room or space with visual sign No tactile info on signs with visual information Provide sign at latch side of entry door, where possible
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 2 of 5 Basement - East Corridor H0002 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 No sign with raised characters and Braille at permanent room or space with visual sign No tactile info on signs with visual information Provide sign at latch side of entry door, where possible 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 1C
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - East Corridor H0002
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Fire extinguisher protrudes 5" at 27-1/2" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 1D
	3/4/2014 Nepare Batte 3/0/2014 Battle 11 11
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 2 of 5 Basement - East Corridor H0002
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 2 of 5 Basement - East Corridor H0002 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 2 of 5 Basement - East Corridor H0002 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 2 of 5 Basement - East Corridor H0002 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 2 of 5 Basement - East Corridor H0002 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 2 of 5 Basement - East Corridor H0002 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 2 of 5 Basement - East Corridor H0002 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn or strobe in corridor where fire alarm exists in building
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 2 of 5 Basement - East Corridor H0002 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1 No horn or strobe in corridor where fire alarm exists in building No device provided Provide horn/strobe in common use area
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 2 of 5 Basement - East Corridor H0002 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1 No horn or strobe in corridor where fire alarm exists in building No device provided Provide horn/strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 2A
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Grad Student Lab 0042A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Room 0	042A
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 2B
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 2B Batcheller Hall Reference Dwg: 2 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 15 lbf Provide automatic door opening device at one door and ISA directional sign at other
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 15 lbf Provide automatic door opening device at one door and ISA directional sign at other 1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 2C
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Grad Student Lab 0042A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	Door does not stop 5" from door frame
Rec. Solution:	Provide automatic door opening device at one door and ISA directional sign at other
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 2D
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 2D Batcheller Hall Reference Dwg: 2 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 Indard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 windard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel located higher than 43" above the floor Replace door/gate or vision panel
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 view panels in or adjacent to doors or gates not max. 43" above floor or ground View panel located higher than 43" above the floor Replace door/gate or vision panel 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 2E
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Grad Student Lab 0042A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: ADMINI As-built : 0
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	17" strike edge clearance
Rec. Solution:	Provide automatic door opening device and remove stored item
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Blocked	by trash can and desk. 4" to trash can and 17" to desk
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 2F
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Grad Student Lab 0042A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	Switches in room 49-1/2" - 57" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$1,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 2 light s	, <u> </u>



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 2G
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Grad Student Lab 0042A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24-3/4" high knee clearance
Rec. Solution:	Provide accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 6 desks.	None are accessible
<u> </u>	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 2H
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 2H Batcheller Hall Reference Dwg: 2 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Hi/Low Reach 2010 ADAS 308.2.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Hi/Low Reach 2010 ADAS 308.2.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Hi/Low Reach 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Hi/Low Reach 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Hi/Low Reach 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 37" high and 37" deep
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Hi/Low Reach 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 37" high and 37" deep Relocate outlet to area at min. 15" or max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 21
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Grad Student Lab 0042A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Shelves or Cabinets
Code References:	2010 ADAS 305.3
Performance Sta	indard: No Quantity: JOB As-built : 1
Barrier Description:	Shelf or cabinet not mounted max. 48" above floor or ground
Findings:	Shelf or cabinet not accessible
Rec. Solution:	Provide additional shelf at accessible height or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 2J
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Grad Student Lab 0042A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator or Control - Height
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at max. 48" high for side reach
Findings:	Desks block refrigerator and microwave clear floor space
Rec. Solution:	Relocate within accessible reach range
Barrier Severity:	
	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 2K
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Grad Student Lab 0042A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator or Control - Operation
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not usable with a closed fist
Findings:	Ventilator dial not fist operable
Rec. Solution:	Replace operating control
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 2L
DL-L- N	
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Basement - Grad Student Lab 0042A Reference Dwg: 2 of 5
Location:	Basement - Grad Student Lab 0042A
Location: X Coordinate:	Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Clear Floor Space
Location: X Coordinate: Barrier Area: Barrier Type: Code	Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in in circulation path protrudes more than 4" between 27" and 80" high Fire alarm/electrical panel protrudes 6" at 59" high Object does not appear to be in circulation route. If desk is moved, provide detectable warning
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Basement - Grad Student Lab 0042A N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in in circulation path protrudes more than 4" between 27" and 80" high Fire alarm/electrical panel protrudes 6" at 59" high Object does not appear to be in circulation route. If desk is moved, provide detectable warning 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 2M
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Grad Student Lab 0042A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobes in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 3A
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Computer Room 0041
X Coordinate:	N/A Y Coordinate: N/A Signage
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at doors within public route
Rec. Solution:	Provide accessible signs
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: 2 entry	doors



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 3B
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Computer Room 0041
X Coordinate:	N/A Y Coordinate: N/A Doors or Gates
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	8 - 11 lbf
Rec. Solution:	Provide automatic door opening device at one door and ISA directional sign at other
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Single d	oor and double door entry from corridor
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 3C
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Computer Room 0041
X Coordinate:	N/A Y Coordinate: N/A Doors or Gates
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	3 - 4 second sweep
Rec. Solution:	Provide automatic door opening device at one door and ISA directional sign at other
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Single d	oor and double door entry from corridor



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 3D
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Computer Room 0041
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	N/A Y Coordinate: N/A Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 3
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	View panel located higher than 43" above the floor
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$6,750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
	oor and double door entry from corridor. Door hardware accessible at single entry door, but ouble doors
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 3E
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Computer Room 0041
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Side Reach Obstructed (≤10")
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge over an obstruction max. 34" high located above 48"
Findings:	50-1/4" high
Rec. Solution:	Relocate control or mechanism to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
implementation	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 3F
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Computer Room 0041
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Electrical panel protrudes 7" at 54-3/4" high
Rec. Solution:	Remove obiect or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
-	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 3G
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 3G Batcheller Hall Reference Dwg: 2 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Computer Room 0041
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Computer Room 0041 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Computer Room 0041 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 2 of 5 Basement - Computer Room 0041 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Hi/low Reach 2010 ADAS 308.2.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Computer Room 0041 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Hi/low Reach 2010 ADAS 308.2.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 2 of 5 Basement - Computer Room 0041 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Hi/low Reach 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Computer Room 0041 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Hi/low Reach 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 1 Use of control involves low reach of less than 15" above floor or more than 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Computer Room 0041 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Hi/low Reach 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 1 Use of control involves low reach of less than 15" above floor or more than 48" high A/C unit 66" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Computer Room 0041 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Hi/low Reach 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 1 Use of control involves low reach of less than 15" above floor or more than 48" high A/C unit 66" high Relocate to area at min. 15" or max. 48" high Relocate to area at min. 15" or max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 3H
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Computer Room 0041
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Ratio
Code References:	2010 ADAS 902
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	At least 1 desk or 5% of all desks not accessible
Findings:	At least 2 accessible desks not provided
Rec. Solution:	Provide at least 2 accessible desks
Barrier Severity:	3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 26 comp	outer workstations. None are accessible
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 3I
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Computer Room 0041
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	14" knee clearance at computer stations
Rec. Solution:	Provide min. one accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 3J
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Computer Room 0041
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobes in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 4A
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 4A Batcheller Hall Reference Dwg: 2 of 5
	3/4/2014 Report Date 3/6/2014 Barrier #: 44
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 2 of 5 Basement - West Corridor H0003
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 2 of 5 Basement - West Corridor H0003 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 2 of 5 Basement - West Corridor H0003 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 2 of 5 Basement - West Corridor H0003 N/A Y Coordinate: N/A Corridors Sign - Tactile Exit Sign at Door 2010 ADAS 216.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 2 of 5 Basement - West Corridor H0003 N/A Y Coordinate: N/A Corridors Sign - Tactile Exit Sign at Door 2010 ADAS 216.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 2 of 5 Basement - West Corridor H0003 N/A Y Coordinate: N/A Corridors Sign - Tactile Exit Sign at Door 2010 ADAS 216.4.1 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 2 of 5 Basement - West Corridor H0003 N/A Y Coordinate: N/A Corridors Sign - Tactile Exit Sign at Door 2010 ADAS 216.4.1 Indard: No Quantity: EACH As-built: 1 Ground floor doors that exit directly to the exterior lacks tactile exit sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 2 of 5 Basement - West Corridor H0003 N/A Y Coordinate: N/A Corridors Sign - Tactile Exit Sign at Door 2010 ADAS 216.4.1 Indard: No Quantity: EACH As-built: 1 Ground floor doors that exit directly to the exterior lacks tactile exit sign Accessible sign not provided Provide new sign stating "EXIT" at exiting side of door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 2 of 5 Basement - West Corridor H0003 N/A Y Coordinate: N/A Corridors Sign - Tactile Exit Sign at Door 2010 ADAS 216.4.1 Ground floor doors that exit directly to the exterior lacks tactile exit sign Accessible sign not provided Provide new sign stating "EXIT" at exiting side of door 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 4B
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - West Corridor H0003
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code	2010 ADAS 308.2.1
References:	2010 ADAS 308.2.1
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	Electrical switch above 48" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 4C
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - West Corridor H0003
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull
Code References:	2010 ADAS 309.4
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Fire pull has no usable hardware
Findings:	Fire pull not fist operable
Rec. Solution:	Replace fire pull when remodeling
	replace the pair when remodeling
Barrier Severity:	
Barrier Severity: Implementation	4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 4D
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - West Corridor H0003
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Fire pulls not between 42" and 48" high
Findings:	64" high
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 4E
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - West Corridor H0003
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No strobe provided in corridor where horn is provided where fire alarm exists in building
Findings:	No strobe where horn is provided
Rec. Solution:	Provide strobe in common use area
	ir tovide strobe in common use area
Barrier Severity:	
Barrier Severity: Implementation	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 5A
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Computer Room 45
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at doors within public route
Rec. Solution:	Provide accessible signs
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Rooms	45 and 45A
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 5B
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Computer Room 45
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	Door closers provided but disconnected. Force to operate exceed 5 lbf
Rec. Solution:	Provide automatic door opening device at one door and ISA directional sign at other
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 5C
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Computer Room 45
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Double	door between 041 and 045
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 5D
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Computer Room 45
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
Dairiei Alea.	Doors or Gates
Barrier Type:	Doors or Gates Vision Lights - Existing
Barrier Type: Code	Vision Lights - Existing 2010 ADAS 404.2.11
Barrier Type: Code References:	Vision Lights - Existing 2010 ADAS 404.2.11
Barrier Type: Code References: Performance Sta Barrier	Vision Lights - Existing 2010 ADAS 404.2.11 Indard: No Quantity: EACH As-built: 2
Barrier Type: Code References: Performance Sta Barrier Description:	Vision Lights - Existing 2010 ADAS 404.2.11 Indard: No Quantity: EACH As-built: 2 View panels in or adjacent to doors or gates not max. 43" above floor or ground
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Vision Lights - Existing 2010 ADAS 404.2.11 Indard: No Quantity: EACH As-built: 2 View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel located higher than 43" above the floor Replace door/gate or vision panel
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Vision Lights - Existing 2010 ADAS 404.2.11 Indard: No Quantity: EACH As-built: 2 View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel located higher than 43" above the floor Replace door/gate or vision panel 3 Hindrance Cost Est \$4,500.00 Facility Function: Public Status: Open



Et al la Davis	December 19 to 19
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 5E
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Computer Room 45
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	5-1/2" strike edge clearance
Rec. Solution:	Provide automatic door opening device at one door and ISA directional sign at other or remode
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 5F
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Computer Room 45
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50-1/4" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 5G
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Computer Room 45
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Hi/low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of control involves low reach of less than 15" above floor or more than 48" high
Findings:	A/C controls 65" high and obstructed by workstations
Rec. Solution:	Relocate to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 2 units	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 5H
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Computer Room 45
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Ratio
Code References:	2010 ADAS 902
Performance Sta	ndard: No Quantity: EACH As-built: 2
Barrier Description:	At least 1 desk or 5% of all desks not accessible
Findings:	At least 2 accessible desks not provided
Rec. Solution:	Provide at least 2 accessible desks
Barrier Severity:	3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 28 work	stations. None are accessible



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 5I
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Computer Room 45
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	16-3/4" deep knee clearance
Rec. Solution:	Provide accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 5J
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Computer Room 45
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
	I.
Findings:	No device provided
Findings: Rec. Solution:	No device provided Provide strobes in common use area
_	Provide strobes in common use area
Rec. Solution:	Provide strobes in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6A
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6B
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Minutes From Bistones, 270% bish
	Viewing From Distance - >70" high
Code References:	2010 ADAS 703.5.5 and Table 703.5.5
	2010 ADAS 703.5.5 and Table 703.5.5
References:	2010 ADAS 703.5.5 and Table 703.5.5
References: Performance Sta Barrier	2010 ADAS 703.5.5 and Table 703.5.5 andard: No Quantity: EACH As-built: 1
References: Performance Sta Barrier Description:	2010 ADAS 703.5.5 and Table 703.5.5 Indard: No Quantity: EACH As-built: 1 Signs between 70" and 120" high lack characters at least 2" high
References: Performance Sta Barrier Description: Findings:	2010 ADAS 703.5.5 and Table 703.5.5 andard: No Quantity: EACH As-built: 1 Signs between 70" and 120" high lack characters at least 2" high Characters on overhead sign not large enough to view from a distance Replace sign with characters min. 2" in height for viewing at a distance
References: Performance Sta Barrier Description: Findings: Rec. Solution:	2010 ADAS 703.5.5 and Table 703.5.5 andard: No Quantity: EACH As-built: 1 Signs between 70" and 120" high lack characters at least 2" high Characters on overhead sign not large enough to view from a distance Replace sign with characters min. 2" in height for viewing at a distance 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6C
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	12 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6D
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 6D Batcheller Hall Reference Dwg: 2 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Men's Restroom 0052
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Men's Restroom 0052 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Men's Restroom 0052 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 2 of 5 Basement - Men's Restroom 0052 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Men's Restroom 0052 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Batcheller Hall Reference Dwg: 2 of 5 Basement - Men's Restroom 0052 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Men's Restroom 0052 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Men's Restroom 0052 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame Door does not stop 5" from door frame
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Men's Restroom 0052 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame Door does not stop 5" from door frame Provide automatic door opening device 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6E
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6F
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 6F Batcheller Hall Reference Dwg: 2 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Men's Restroom 0052
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Men's Restroom 0052 N/A Y Coordinate: N/A Restrooms Dispensers - Protruding Object
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Men's Restroom 0052 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 2 of 5 Basement - Men's Restroom 0052 N/A Y Coordinate: N/A Restrooms Dispensers - Protruding Object 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Men's Restroom 0052 N/A Y Coordinate: N/A Restrooms Dispensers - Protruding Object 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 2 of 5 Basement - Men's Restroom 0052 N/A Y Coordinate: N/A Restrooms Dispensers - Protruding Object 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Men's Restroom 0052 N/A Y Coordinate: N/A Restrooms Dispensers - Protruding Object 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 1 Protruding dispenser creates protruding hazard in path of travel
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Men's Restroom 0052 N/A Y Coordinate: N/A Restrooms Dispensers - Protruding Object 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 1 Protruding dispenser creates protruding hazard in path of travel Paper towel dispenser protrudes 10" at 59" high Relocate dispenser or provide cane-detectable warning
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Men's Restroom 0052 N/A Y Coordinate: N/A Restrooms Dispensers - Protruding Object 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 1 Protruding dispenser creates protruding hazard in path of travel Paper towel dispenser protrudes 10" at 59" high Relocate dispenser or provide cane-detectable warning 2 Recommended Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6G
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers 2010/2014 12:57
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Dispenser operating mechanism not operable with a fist or less than 5 lbf
Findings:	Paper towel dispensing mechanism does not function
Rec. Solution:	Replace dispenser
Barrier Severity:	1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6H
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers Sales/2014 12:57
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Dispenser control point or operating mechanism not max. 48" AFF
Findings:	Paper towel dispenser 59" high
Rec. Solution:	Remount no higher than 48" above floor
Barrier Severity:	Remount no higher than 48 above floor
barrier severity.	
Implementation	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 61
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Knee Cl
Code References:	2010 ADAS 606.2 & 306
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Lavatory bottom apron/edge not max 29" reducing to 27" at 8" back from edge
Findings:	23" high
Rec. Solution:	Replace lavatory
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6J
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Mirror 03/05/2014 12-57
Code References:	2010 ADAS 603.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface
Findings:	45" high
Rec. Solution:	Replace or remount mirror
Barrier Severity:	3 Hindrance Cost Est \$375.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6K
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Flush Controls
Code References:	2010 ADAS 309
Performance Sta	indard: No Quantity: JOB As-built : 1
Barrier Description:	Urinal flush controls involve more than 5 lbf (22.2 N) to activate
Findings:	6 lbf. Lavatory and stall block urinal clear floor space
Rec. Solution:	Replace urinal controls where possible or entire urinal
Barrier Severity:	2 Recommended Cost Est \$800.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: 33" dee	p clear floor space. No clear floor space for people using wheelchairs
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6L
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Flush Controls
Code References:	2010 ADAS 309
Performance Sta	indard: No Quantity: JOB As-built : 0
Barrier Description:	Urinal flush controls mounted higher than 48" above the floor
Findings:	51" high
Rec. Solution:	Replace urinal controls where possible or entire urinal
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6M
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Rim
Code References:	2010 ADAS 605.2
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Min. 1 urinal has no elongated rim projecting 14" to 17" from wall
Findings:	13" projection from wall
Rec. Solution:	Replace urinal
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6N
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Rim
Code References:	2010 ADAS 605.2
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Urinal not max. 17" above the floor
Findings:	24" high
Rec. Solution:	Replace urinal
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
Notes:	Priority: 3 Implementation Phase: Implementation Date:



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 60
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Maneuvering Clearance
Code References:	2010 ADAS 603.2.1
Performance Sta	indard: No Quantity: SF As-built: 140
Barrier Description:	No 60" turning circle provided in toilet facility (min. 27" high above floor)
Findings:	45" between toilet stall door to lavatories
Rec. Solution:	Remodel toilet room
Barrier Severity:	2 Recommended Cost Est \$80,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6P
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	
	N/A Y Coordinate: N/A
Barrier Area:	N/A Y Coordinate: N/A Restrooms
	Restrooms Door Headroom
Barrier Area:	Restrooms
Barrier Area: Barrier Type: Code	Restrooms Door Headroom 2010 ADAS 404.2.3
Barrier Area: Barrier Type: Code References:	Restrooms Door Headroom 2010 ADAS 404.2.3
Barrier Area: Barrier Type: Code References: Performance Sta	Restrooms Door Headroom 2010 ADAS 404.2.3 Indard: No Quantity: EACH As-built: 1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Restrooms Door Headroom 2010 ADAS 404.2.3 Indard: No Quantity: EACH As-built: 1 Door clearance not min. 80" high
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Restrooms Door Headroom 2010 ADAS 404.2.3 Indard: No Quantity: EACH As-built: 1 Door clearance not min. 80" high 74-1/2" high Remodel room to provide access
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Restrooms Door Headroom 2010 ADAS 404.2.3 Indard: No Quantity: EACH As-built: 1 Door clearance not min. 80" high 74-1/2" high Remodel room to provide access 2 Recommended Cost Est \$1,750.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6Q
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Transfer - Floor-mounted
Code References:	2010 ADAS 604.8.1.1
Performance Sta	andard: No Quantity: SF As-built : 0
Barrier Description:	Min. 60" wide x 59" deep clear floor space not provided at floor-mounted fixture
Findings:	34" wide x 54-1/2" deep
Rec. Solution:	Remodel to provide front transfer space
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: 4 stalls	with the same dimensions
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6R
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Stall - Coat Hook
Code References:	2010 ADAS 603.4
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	67-1/2" high
Rec. Solution:	Provide additional hook
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6S
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Grab Bars
Code References:	2010 ADAS 604.5
Performance Sta	andard: No Quantity: JOB As-built: 1
Barrier Description:	No grab bars provided at water closet
Findings:	No grab bars provided
Rec. Solution:	Provide side and rear grab bars with reinforcement
Barrier Severity:	1 Necessary Cost Est \$900.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6T
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Seat Height
Code References:	2010 ADAS 604.4
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Water closet seat not between 17" to 19" high
Findings:	16" high
Rec. Solution:	Desile de la contraction de la
	Replace water closet
Barrier Severity:	
Barrier Severity: Implementation	2 Recommended Cost Est \$850.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6U
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Parallel Approach
Code References:	2010 ADAS 308.3.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Where the high side reach is over an obstruction, the height of the obstruction exceeds 34" maximum
Findings:	54 " - 60" high. Water closet blocks seat cover dispenser clear floor space
Rec. Solution:	Relocate dispenser to location within reach range or provide additional dispenser
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: 54 " - 60	" high. Water closet blocks seat cover dispenser clear floor space
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6V
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Shelves
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Shelf provided not mounted between 40" and 48" above floor or ground
Findings:	Shelf or cabinet not accessible
Rec. Solution:	Provide additional shelf at accessible height
Barrier Severity:	2 Recommended Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	· — · — — · ——
Notes: Four she	elves in water closets at 66" high



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 6W
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 0052
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobes in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
<u> </u>	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 7A
	3/4/2014 Report Date 3/6/2014 Barrier #: 7A Batcheller Hall Reference Dwg: 2 of 5
Bldg Name:	
Bldg Name: Location:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50
Field Date: Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 At interior or exterior location, no tactile characters at sign identifying permanent rooms and
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces No tactile signage provided at door within public route
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces No tactile signage provided at door within public route Provide accessible sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 7B
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Human Factors/Ergonomics Lab 50
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	16 lbf
Rec. Solution:	Provide automatic door opening device at main entry and ISA directional sign at other door
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Sweep p	period okay
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 7C
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Human Factors/Ergonomics Lab 50
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	
barrier Type:	Vision Lights - Existing
Code References:	
Code	Vision Lights - Existing 2010 ADAS 404.2.11
Code References:	Vision Lights - Existing 2010 ADAS 404.2.11
Code References: Performance Sta Barrier	Vision Lights - Existing 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1
Code References: Performance Sta Barrier Description:	Vision Lights - Existing 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground
Code References: Performance Sta Barrier Description: Findings:	Vision Lights - Existing 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel located higher than 43" above the floor Replace door/gate or vision panel
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Vision Lights - Existing 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel located higher than 43" above the floor Replace door/gate or vision panel 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 7D
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Human Factors/Ergonomics Lab 50
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Threshold - Height 1/2" with Ramp
Code References:	2010 ADAS 404.2.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate threshold bevel at max 1/2" lip exceeds 1:2 or 50% slope
Findings:	3/4" high
Rec. Solution:	Provide accessible threshold leading to new level landing at door
Barrier Severity:	1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 7E
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 7E Batcheller Hall Reference Dwg: 2 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 0 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 0 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side 2" strike edge clearance Remove trash bin
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 0 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side 2" strike edge clearance Remove trash bin 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 7F
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Human Factors/Ergonomics Lab 50
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	48-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 7G
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Human Factors/Ergonomics Lab 50
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 603.4
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier	Clothing hooks not max. 48" high AFF
Description:	Clothing Hooks Hot max. 46 High All
Findings:	70" high. Desk and stored items block coat hook clear floor space
·	
Findings:	70" high. Desk and stored items block coat hook clear floor space Provide additional hook in new location
Findings: Rec. Solution:	70" high. Desk and stored items block coat hook clear floor space Provide additional hook in new location 2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 7H
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Human Factors/Ergonomics Lab 50
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard & 2010 ADAS 904.3.3
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 44" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 71
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Human Factors/Ergonomics Lab 50
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Projector Screen Pull
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Screen pull not at max. 48" high for side reach
	'
Findings:	Projector screen pull 82" high. Table blocks whiteboard and projector screen clear floor space
Findings: Rec. Solution:	Projector screen pull 82" high. Table blocks whiteboard and projector screen clear floor space Relocate to max. 48" high or provide extension
-	Relocate to max. 48" high or provide extension
Rec. Solution:	Relocate to max. 48" high or provide extension 3 Hindrance Cost Est \$75.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 7J
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Human Factors/Ergonomics Lab 50
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	Passageway less than 36" in multiple locations around group table
Rec. Solution:	Rearrange furniture to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Circulati	ion route around table
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 7K
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Human Factors/Ergonomics Lab 50
X Coordinate:	
7. 555	N/A Y Coordinate: N/A
Barrier Area:	N/A
Barrier Area:	Counters and Tables Table - Knee Clearance
Barrier Area: Barrier Type: Code	Counters and Tables Table - Knee Clearance 2010 ADAS 305.3
Barrier Area: Barrier Type: Code References:	Counters and Tables Table - Knee Clearance 2010 ADAS 305.3
Barrier Area: Barrier Type: Code References: Performance Sta	Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide 25-1/2" high knee clearance Provide min. 1 accessible table
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide 25-1/2" high knee clearance Provide min. 1 accessible table 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 7L
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Human Factors/Ergonomics Lab 50
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24" - 24-1/2" high knee clearance
Rec. Solution:	Provide accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 6 PC wo	orkstations and one work bench. None are accessible
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 7M
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Human Factors/Ergonomics Lab 50
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	Passageway less than 36" in multiple locations
Rec. Solution:	Rearrange furniture to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 28" wid	e circulation route to flight simulator



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 7N
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Human Factors/Ergonomics Lab 50
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Turning Space
Barrier Type:	Circular Turning Space - Min. 60"
Code References:	2010 ADAS 304.3.1
Performance Sta	ndard: No Quantity: SF As-built: 80
Barrier Description:	Circular turning space not minimum of 60" in diameter (including toe/knee space)
Findings:	60" turning diameter not provided at flight simulator
Rec. Solution:	Remodel to provide access
Barrier Severity:	2 Recommended Cost Est \$6,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 70
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 70
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance State Barrier Description:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground Shelf or cabinet not accessible Provide additional shelf at accessible height or provide assistance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Human Factors/Ergonomics Lab 50 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground Shelf or cabinet not accessible Provide additional shelf at accessible height or provide assistance 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 7P
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Human Factors/Ergonomics Lab 50
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobes in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 7Q
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Human Factors/Ergonomics Lab 50
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware. Door may be used in the case of an emergency to exit lab
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
Notes: Door to	lobby L0001



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 7R
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Human Factors/Ergonomics Lab 50
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Recessed Door - Push Side
Code References:	2010 ADAS 404.2.4.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door recessed by more than 8" lacks at least 12" clearance at push side of door
Findings:	Recessed 9" and no strike edge clearance
Rec. Solution:	Provide automatic door opening device at main entry and ISA directional sign at other door
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Door to	lobby L0001
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 8A
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L0001
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	indard: No Quantity: EACH As-built: 1
Barrier Description:	At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Rec. Solution: Barrier Severity:	
	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 8B
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L0001
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	13 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 8C
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L0001
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Doors or Gates
	Doors or Gates Door Closer - Interior Sweep Period
Barrier Area:	Doors or Gates
Barrier Area: Barrier Type: Code	Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Barrier Area: Barrier Type: Code References:	Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Barrier Area: Barrier Type: Code References: Performance Sta	Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame 4 second sweep Provide automatic door opening device
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame 4 second sweep Provide automatic door opening device 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 8D
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L0001
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	58-1/2" high. Stairs block electrical switch clear floor space
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 8E
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 8E Batcheller Hall Reference Dwg: 2 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Clear Floor Space Protruding Object
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Clear Floor Space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in in circulation path protrudes more than 4" between 27" and 80" high Piping protrudes 6" at 43 1/2" high and electrical box creates protruding hazard Remove object or provide detectable warning (wing walls)
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in in circulation path protrudes more than 4" between 27" and 80" high Piping protrudes 6" at 43 1/2" high and electrical box creates protruding hazard Remove object or provide detectable warning (wing walls) 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 8F
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L0001
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	59-1/2" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 8G
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 8G Batcheller Hall Reference Dwg: 2 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Signage Lobby Info Sign Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Signage Lobby Info Sign Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Signage Lobby Info Sign Performance Standard ndard: Yes Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Signage Lobby Info Sign Performance Standard Indard: Yes Quantity: EACH As-built: 1 No lobby informational sign with location of accessible elements
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Signage Lobby Info Sign Performance Standard Indard: Yes Quantity: EACH As-built: 1 No lobby informational sign with location of accessible elements Accessible sign not provided Provide lobby informational sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Signage Lobby Info Sign Performance Standard Indard: Yes Quantity: EACH As-built: 1 No lobby informational sign with location of accessible elements Accessible sign not provided Provide lobby informational sign I Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 8H
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L0001
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobes in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
<u> </u>	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 8I
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 8I Batcheller Hall Reference Dwg: 2 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Stairways Vertical Access - Elevator
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Stairways Vertical Access - Elevator 2010 ADAS 403.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Stairways Vertical Access - Elevator 2010 ADAS 403.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Stairways Vertical Access - Elevator 2010 ADAS 403.1 Indard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Stairways Vertical Access - Elevator 2010 ADAS 403.1 Indard: No Quantity: JOB As-built: 1 No form of vertical access provided at stairway to reach upper floors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Stairways Vertical Access - Elevator 2010 ADAS 403.1 No form of vertical access provided at stairway to reach upper floors Stairway in lobby does not provide an accessible route through building Provide a passenger elevator to reach upper floors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Lobby L0001 N/A Y Coordinate: N/A Stairways Vertical Access - Elevator 2010 ADAS 403.1 No form of vertical access provided at stairway to reach upper floors Stairway in lobby does not provide an accessible route through building Provide a passenger elevator to reach upper floors 1 Necessary Cost Est \$1,250,000.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 9A
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway S0002
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Sign - Enclosed Exit Stairway Level
Code References:	ICC A117.1
Performance Sta	ndard: Yes Quantity: EACH As-built: 1
Barrier Description:	Tactile stairway signage not provided to indicate floor level
Findings:	No sign provided
Rec. Solution:	Provide accessible sign
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Stairwa discharg	y is not enclosed. Recommended: provide accessible tactile stairway signage to indicate ge level.
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 9B
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 9B Batcheller Hall Reference Dwg: 2 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Stairway S0002
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Stairway S0002 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Stairway S0002 N/A Y Coordinate: N/A Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 2 of 5 Basement - Stairway S0002 N/A Y Coordinate: N/A Stairways Handrail Grip 2010 ADAS 505.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Stairway S0002 N/A Y Coordinate: N/A Stairways Handrail Grip 2010 ADAS 505.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 2 of 5 Basement - Stairway S0002 N/A Y Coordinate: N/A Stairways Handrail Grip 2010 ADAS 505.7 Indard: No Quantity: LF As-built: 34
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Stairway S0002 N/A Y Coordinate: N/A Stairways Handrail Grip 2010 ADAS 505.7 Indard: No Quantity: LF As-built: 34 Handrail grip is not 1-1/4" - 2" in diameter
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Stairway S0002 N/A Y Coordinate: N/A Stairways Handrail Grip 2010 ADAS 505.7 Indard: No Quantity: LF As-built: 34 Handrail grip is not 1-1/4" - 2" in diameter 3-1/4" inner handrail grip diameter
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Stairway S0002 N/A Y Coordinate: N/A Stairways Handrail Grip 2010 ADAS 505.7 Indard: No Quantity: LF As-built: 34 Handrail grip is not 1-1/4" - 2" in diameter 3-1/4" inner handrail grip diameter Provide handrails at both sides of stairway 2 Recommended Cost Est \$7,650.00 Facility Function: Public Status: Open
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: Barrier Severity:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Stairway S0002 N/A Y Coordinate: N/A Stairways Handrail Grip 2010 ADAS 505.7 Indard: No Quantity: LF As-built: 34 Handrail grip is not 1-1/4" - 2" in diameter 3-1/4" inner handrail grip diameter Provide handrails at both sides of stairway 2 Recommended Cost Est \$7,650.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 9C
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway S0002
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Bottom
Code References:	2010 ADAS 505.10.3
Performance Sta	ndard: No Quantity: LF As-built : 2
Barrier Description:	Bottom handrail extension not sloped for length of one tread beyond the last riser nosing
Findings:	No extensions on either side
Rec. Solution:	Provide handrails at both sides of stairwav
Barrier Severity:	2 Recommended Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 9D
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway S0002
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code References:	2010 ADAS Advisory 504.4
Performance Sta	ndard: Yes Quantity: LF or TR As-built : 24
Barrier Description:	No contrasting color on each tread of interior stairway
Findings:	Treads lack contrasting color defined as 70% contrast
Rec. Solution:	Recommended: Consider providing contrasting color on each tread
Barrier Severity:	2 Recommended Cost Est \$840.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 9E
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway S0002
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Surface Condition - Existing
Code References:	2010 ADAS 504.4
Performance Sta	ndard: No Quantity: SF As-built : 240
Barrier Description:	Stairway surface is not slip resistant
Findings:	Slip resistant surface could not be verified
Rec. Solution:	Provide slip resistant surface
Barrier Severity:	4 Low Severity Cost Est \$60,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 10A
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Entry V0002
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Findings:	No tactile signage provided at doors within public route
Rec. Solution:	Provide accessible signs
Barrier Severity:	
barrier beveriey.	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 10B
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Entry V0002
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 10C
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 10C Batcheller Hall Reference Dwg: 2 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Entry V0002
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Entry V0002 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 2 of 5 Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 2 of 5 Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 view panels in or adjacent to doors or gates not max. 43" above floor or ground View panel located higher than 43" above the floor
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel located higher than 43" above the floor Replace door/gate or vision panel 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 10D
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Entry V0002
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Passage
Code References:	Performance Standard
Performance Sta	indard: Yes Quantity: EACH As-built : 1
Barrier Description:	Exit thru an exit enclosure/exit passageway lacks tactile exit sign
Findings:	Passageway to exterior exit with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT ROUTE" at exit side of door
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Double	doors view panel located higher than 43" above the floor
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 10E
Bldg Name:	
2.00.10	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Entry V0002
Location:	
Location:	Basement - Entry V0002
Location: X Coordinate:	Basement - Entry V0002 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates
Location: X Coordinate: Barrier Area: Barrier Type: Code	Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Basement - Entry V0002 N/A Y Coordinate: Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10 Indard: No Quantity: EACH As-built: 2
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10 andard: No Quantity: EACH As-built: Door/Gate lacks min. 10" smooth uninterrupted bottom surface
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10 andard: No Quantity: EACH As-built: 2 Door/Gate lacks min. 10" smooth uninterrupted bottom surface Bottom of door not smooth and uninterrupted Provide kick plate at push side of door and remove door stop
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10 Indard: No Quantity: EACH As-built: 2 Door/Gate lacks min. 10" smooth uninterrupted bottom surface Bottom of door not smooth and uninterrupted Provide kick plate at push side of door and remove door stop 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 10F
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Entry V0002
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Shelving protrudes 9" at 48" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 10G
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 10G Batcheller Hall Reference Dwg: 2 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Entry V0002
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Entry V0002 N/A Y Coordinate: N/A Clear Floor Space Protruding Object
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Entry V0002 N/A Y Coordinate: N/A Clear Floor Space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 2 of 5 Basement - Entry V0002 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Entry V0002 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 2 of 5 Basement - Entry V0002 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Entry V0002 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Entry V0002 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in in circulation path protrudes more than 4" between 27" and 80" high Piping across doorway protrudes at 78" high for 89" long Remove object or provide detectable warning (wing walls)
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 2 of 5 Basement - Entry V0002 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in in circulation path protrudes more than 4" between 27" and 80" high Piping across doorway protrudes at 78" high for 89" long Remove object or provide detectable warning (wing walls) I Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 10H
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Entry V0002
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Piping protrudes 15" at 68" high. Multiple instances where the piping protrudes into path of travel
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 10I
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Entry V0002
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - To Exit Door
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Exit door leading directly to an door to the exterior lacks tactile exit sign
Findings:	Exit door leading to a door to the exterior lacks tactile exit sign
Rec. Solution:	Provide sign stating "TO EXIT" at exit side of door leading to an exit passage with a door to the
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
implementation	Priority: 3 Implementation Phase: Implementation Date:



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 10J
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Entry V0002
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Ramps
Barrier Type:	Running Slope - Existing (8.34% - 8.5%)
Code References:	2010 ADAS 405.3
Performance Sta	ndard: No Quantity: LF As-built : 20
Barrier Description:	Running slope exceeds 8.33% (8.34% to 8.5%)
Findings:	8.5% running slope
Rec. Solution:	Demolish existing and construct new ramp
Barrier Severity:	4 Low Severity Cost Est \$4,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Floor slo	opes towards the exit.
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 10K
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Entry V0002
V Caardinata.	
x coordinate:	N/A Y Coordinate: N/A
	N/A Y Coordinate: N/A Doors or Gates
X Coordinate: Barrier Area: Barrier Type:	
Barrier Area: Barrier Type: Code	Doors or Gates
Barrier Area:	Doors or Gates Doormat 2010 ADAS 302.2 & Advisory 302.2
Barrier Area: Barrier Type: Code References: Performance Sta	Doors or Gates Doormat 2010 ADAS 302.2 & Advisory 302.2
Barrier Area: Barrier Type: Code References: Performance Sta	Doors or Gates Doormat 2010 ADAS 302.2 & Advisory 302.2 Indard: No Quantity: EACH As-built: 1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Doors or Gates Doormat 2010 ADAS 302.2 & Advisory 302.2 Indard: No Quantity: EACH As-built: 1 Doormat not anchored to floor (possible trip hazard)
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Doors or Gates Doormat 2010 ADAS 302.2 & Advisory 302.2 Indard: No Quantity: EACH As-built: 1 Doormat not anchored to floor (possible trip hazard) Doormat not secured Secure exiting doormat or replace
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Doormat 2010 ADAS 302.2 & Advisory 302.2 Indard: No Quantity: EACH As-built: 1 Doormat not anchored to floor (possible trip hazard) Doormat not secured Secure exiting doormat or replace 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 10L
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Entry V0002
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Exterior Adjustment
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 8.5 lbf
Findings:	17 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 10M
51.1.4.	Batcheller Hall Reference Dwg: 2 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Entry V0002
_	
Location:	Basement - Entry V0002
Location: X Coordinate:	Basement - Entry V0002 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates
Location: X Coordinate: Barrier Area: Barrier Type: Code	Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates Door Closer - Sweep Period 2010 ADAS 404.2.8.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates Door Closer - Sweep Period 2010 ADAS 404.2.8.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates Door Closer - Sweep Period 2010 ADAS 404.2.8.1 andard: NO Quantity: EACH As-built: O
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates Door Closer - Sweep Period 2010 ADAS 404.2.8.1 andard: No Quantity: EACH As-built: Door closer lacks min. 5 second sweep period
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates Door Closer - Sweep Period 2010 ADAS 404.2.8.1 andard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period 4 second sweep
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Basement - Entry V0002 N/A Y Coordinate: N/A Doors or Gates Door Closer - Sweep Period 2010 ADAS 404.2.8.1 andard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period 4 second sweep Replace or adjust existing closer 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 10N
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Entry V0002
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Clear Width
Code References:	2010 ADAS 404.2.3
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Door, sliding/folding door or gate clear width is not min. 32"
Findings:	28" clear width
Rec. Solution:	Replace door or gate and frame to provide min. one accessible door leaf
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 100
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Entry V0002
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Smooth Surface at Bottom
Code References:	2010 ADAS 404.2.10
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate lacks min. 10" smooth uninterrupted bottom surface
Description	Doory Gate lacks Hill. 10 Shlooth uninterrupted bottom surface
Findings:	Door hardware prevents 10" smooth uninterrupted surface
Findings:	
Findings:	Door hardware prevents 10" smooth uninterrupted surface Change door hardware to provide smooth, uninterrupted surface
Findings: Rec. Solution:	Door hardware prevents 10" smooth uninterrupted surface Change door hardware to provide smooth, uninterrupted surface 1 Necessary Cost Est \$225.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 10P
Bldg Name:	Batcheller Hall Reference Dwg: 2 of 5
Location:	Basement - Entry V0002
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible on exterior side
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Simultai	neous thumb activation needed while pulling
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 11A
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Entry V0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	ISA - Non-Accessible Entry
Code References:	2010 ADAS 216.6
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Sign directing people to accessible entrance needed where all doors are not accessible
Findings:	Sign located at top of stairs at entry door
Rec. Solution:	Provide ISA directional sign in location where people approaching building can make use of info
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 11B
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Entry V0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Exterior Adjustment
Code References:	Performance Standard
Performance Sta	indard: Yes Quantity: EACH As-built: 1
Barrier Description:	Door opening force exceeds 8.5 lbf
Findings:	14 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Sweep p	period okay
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 11C
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Entry V0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Doormat One 1916 12:30
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance Sta	indard: No Quantity: EACH As-built: 1
Barrier Description:	Doormat not anchored to floor (possible trip hazard)
•	<u> </u>
Findings:	Doormat not secured
·	Doormat not secured Secure exiting doormat or replace
Findings:	Secure exiting doormat or replace
Findings: Rec. Solution:	Secure exiting doormat or replace 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 11D
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Entry V0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull
Code References:	2010 ADAS 309.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Fire pull has no usable hardware
Findings:	Fire pull not fist operable
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 11E
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 11E Batcheller Hall Reference Dwg: 3 of 5
Bldg Name:	
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5
	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Entry V0102
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Entry V0102 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Entry V0102 N/A Y Coordinate: N/A Alarms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Entry V0102 N/A Y Coordinate: N/A Alarms Fire Pull 2010 ADAS 308.2.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Entry V0102 N/A Y Coordinate: N/A Alarms Fire Pull 2010 ADAS 308.2.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Entry V0102 N/A Alarms Fire Pull 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Entry V0102 N/A Alarms Fire Pull 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 0 Fire pulls not between 42" and 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Entry V0102 N/A Alarms Fire Pull 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 0 Fire pulls not between 42" and 48" high 63-1/2" high Replace fire pull when remodeling
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Entry V0102 N/A Alarms Fire Pull 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 0 Fire pulls not between 42" and 48" high 63-1/2" high Replace fire pull when remodeling A Low Severity Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12A
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 0146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12B
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	
	Floor 1 - Women's Restroom 0146
X Coordinate:	Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	
	N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high
Barrier Area:	N/A Y Coordinate: N/A Signage
Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5
Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5 Indard: No Quantity: EACH As-built: 1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5 Indard: No Quantity: EACH As-built: 1 Signs between 70" and 120" high lack characters at least 2" high
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5 Indard: No Quantity: EACH As-built: 1 Signs between 70" and 120" high lack characters at least 2" high Characters on sign not large enough to view from a distance at 1-1/2" high Replace sign with characters min. 2" in height for viewing at a distance
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5 Indard: No Quantity: EACH As-built: 1 Signs between 70" and 120" high lack characters at least 2" high Characters on sign not large enough to view from a distance at 1-1/2" high Replace sign with characters min. 2" in height for viewing at a distance 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12C
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 0146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - Non-Accessible Restroom
Code References:	2010 ADAS 216.6
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No directional ISA sign identifying location of accessible restroom where all are not accessible
Findings:	No directional ISA sign provided to an accessible restroom
Rec. Solution:	Provide ISA directional sign indicating location of and route to accessible restroom
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12D
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 12D Batcheller Hall Reference Dwg: 3 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Door Closer
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Door Closer 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Door Closer 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Door Closer 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Door Closer 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Door Closer 2010 ADAS 404.2.9 mdard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf Replace or adjust existing closer
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Door Closer 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf Replace or adjust existing closer I Necessary Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12E
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 0146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Sweep
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	3 second sweep
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12F
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
blug Name.	Datcheller Hall
Location:	Floor 1 - Women's Restroom 0146
Location:	Floor 1 - Women's Restroom 0146
Location: X Coordinate:	Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Door Hardware
Location: X Coordinate: Barrier Area:	Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Door Hardware 2010 ADAS 404.2.7
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Door Hardware 2010 ADAS 404.2.7
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 1 - Women's Restroom 0146 N/A Restrooms Door Hardware 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 1 - Women's Restroom 0146 N/A Restrooms Door Hardware 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Operating controls involve tight grasping, pinching or twisting
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Door Hardware 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Operating controls involve tight grasping, pinching or twisting Hardware not accessible Replace hardware
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Door Hardware 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Operating controls involve tight grasping, pinching or twisting Hardware not accessible Replace hardware 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12G
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 0146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Clearance - Pull Side
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door lacks min. 18" strike edge clearance at pull side
Findings:	5" strike edge clearance
Rec. Solution:	Relocate door or gate to provide maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12H
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 12H Batcheller Hall Reference Dwg: 3 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Door Clearance - Push Side
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Door Clearance - Push Side 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Door Clearance - Push Side 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Door Clearance - Push Side 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Door Clearance - Push Side 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0 Door lacks min. 12" strike edge clearance at push side
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Door Clearance - Push Side 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0 Door lacks min. 12" strike edge clearance at push side 6" strike edge clearance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Door Clearance - Push Side 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0 Door lacks min. 12" strike edge clearance at push side 6" strike edge clearance Relocate door or gate to provide maneuvering clearance 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12I
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 0146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Clear Width
Code References:	2010 ADAS 404.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door clear width is not min. 32"
Findings:	31" clear width
Rec. Solution:	Replace door/gate and frame
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12J
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 12J Batcheller Hall Reference Dwg: 3 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Maneuvering Clearance
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Maneuvering Clearance 2010 ADAS 603.2.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Maneuvering Clearance 2010 ADAS 603.2.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Maneuvering Clearance 2010 ADAS 603.2.1 ndard: No Quantity: SF As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Maneuvering Clearance 2010 ADAS 603.2.1 Indard: No Quantity: SF As-built: 1 Entry door encroaches into min. 60" turning space by more than 12"
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Maneuvering Clearance 2010 ADAS 603.2.1 Entry door encroaches into min. 60" turning space by more than 12" Dimensions of bathroom are 41-3/4" wide x 71-1/2" long, wall to wall Remodel toilet room
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Maneuvering Clearance 2010 ADAS 603.2.1 Entry door encroaches into min. 60" turning space by more than 12" Dimensions of bathroom are 41-3/4" wide x 71-1/2" long, wall to wall Remodel toilet room 2 Recommended Cost Est \$575.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12K
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 0146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Electrical Switches
Code References:	2010 ADAS 205.1 & 309.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	59-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12L
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146
Location:	Floor 1 - Women's Restroom 0146
Location: X Coordinate:	Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Dispensers - Protruding Object
Location: X Coordinate: Barrier Area:	Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 1 - Women's Restroom 0146 N/A Restrooms Dispensers - Protruding Object 2010 ADAS 307.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 1 - Women's Restroom 0146 N/A Restrooms Dispensers - Protruding Object 2010 ADAS 307.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 1 - Women's Restroom 0146 N/A Restrooms Dispensers - Protruding Object 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 1 - Women's Restroom 0146 N/A Restrooms Dispensers - Protruding Object 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 1 Protruding dispenser creates protruding hazard in path of travel
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - Women's Restroom 0146 N/A Restrooms Dispensers - Protruding Object 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 1 Protruding dispenser creates protruding hazard in path of travel Paper towel dispenser protrudes 10" at 59" high Relocate dispenser or provide cane-detectable warning
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Dispensers - Protruding Object 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 1 Protruding dispenser creates protruding hazard in path of travel Paper towel dispenser protrudes 10" at 59" high Relocate dispenser or provide cane-detectable warning 2 Recommended Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12M
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 0146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers 03/10/2014 16/50
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Dispenser control point or operating mechanism not max. 48" AFF
Findings:	Paper towel dispenser 53" high
Rec. Solution:	Remount no higher than 48" above floor
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12N
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 0146
X Coordinate:	V Coordinate: N/A
	N/A Y Coordinate: N/A
Barrier Area:	Restrooms Y Coordinate: JN/A
Barrier Area: Barrier Type:	Restrooms Dispensers - Protruding Object
	Restrooms
Barrier Type: Code	Restrooms Dispensers - Protruding Object 2010 ADAS 307.2
Barrier Type: Code References:	Restrooms Dispensers - Protruding Object 2010 ADAS 307.2
Barrier Type: Code References: Performance Sta Barrier	Restrooms Dispensers - Protruding Object 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 1
Barrier Type: Code References: Performance Sta Barrier Description:	Restrooms Dispensers - Protruding Object 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 1 Protruding dispenser creates protruding hazard in path of travel
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Restrooms Dispensers - Protruding Object 2010 ADAS 307.2 ndard: No Quantity: EACH As-built: 1 Protruding dispenser creates protruding hazard in path of travel Dispenser protrudes 6-1/4" at 54-1/2" high
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Restrooms Dispensers - Protruding Object 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 1 Protruding dispenser creates protruding hazard in path of travel Dispenser protrudes 6-1/4" at 54-1/2" high Relocate dispenser or provide cane-detectable warning 2 Recommended Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 120
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 0146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Dispenser control point or operating mechanism not max. 48" AFF
Findings:	Dispenser 66" high. Toilet, sink and wall block dispensers clear floor space
Rec. Solution:	Remount no higher than 48" above floor
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/4/2044 Papert Data 2/5/2044 Pagging #1 42D
i icia Date.	3/4/2014 Report Date 3/6/2014 Barrier #: 12P
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Lavatory - Centerline 2010 ADAS 606
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Lavatory - Centerline 2010 ADAS 606
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Lavatory - Centerline 2010 ADAS 606 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Lavatory - Centerline 2010 ADAS 606 ndard: No Quantity: JOB As-built: 1 Lavatory adjacent to wall not min. 15" to the centerline of fixture
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Lavatory - Centerline 2010 ADAS 606 ndard: No Quantity: JOB As-built: 1 Lavatory adjacent to wall not min. 15" to the centerline of fixture 12" centerline at lavatory in corner Relocate or replace lavatory
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Lavatory - Centerline 2010 ADAS 606 ndard: No Quantity: JOB As-built: 1 Lavatory adjacent to wall not min. 15" to the centerline of fixture 12" centerline at lavatory in corner Relocate or replace lavatory 2 Recommended Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12Q
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 0146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Depth
Code References:	2010 ADAS 606.2 & 306
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Lavatory lacks min. 17" in horizontal depth measured from back wall
Findings:	10-1/2" deep
Rec. Solution:	Replace lavatory
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	Daylor Barrett Data Data Daylor H. Lon
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12R
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 ndard: No Quantity: EACH As-built: 1 Hot water and drainpipes accessible under lavatory not insulated or covered
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 ndard: No Quantity: EACH As-built: 1 Hot water and drainpipes accessible under lavatory not insulated or covered No insulation provided. Radiator, trash can and walls block sink clear floor space Insulate drainpipes and hot water pipes
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Lavatory - Drainpipes 2010 ADAS 606.5 Indard: No Quantity: EACH As-built: 1 Hot water and drainpipes accessible under lavatory not insulated or covered No insulation provided. Radiator, trash can and walls block sink clear floor space Insulate drainpipes and hot water pipes 2 Recommended Cost Est \$220.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12S
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 0146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Mirror 16:45
Code References:	2010 ADAS 603.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface
Findings:	55-1/4" high
Rec. Solution:	Replace or remount mirror
Barrier Severity:	3 Hindrance Cost Est \$375.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12T
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 0146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Shelves OSPIGIZZNA 10-50
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Shelf provided not mounted between 40" and 48" above floor or ground
Findings:	Shelf or cabinet not accessible
Rec. Solution:	Provide additional shelf at accessible height
Barrier Severity:	2 Recommended Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: 65-1/4"	high



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12U
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 0146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Grab Bars
Code References:	2010 ADAS 604.5
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	No grab bars provided at water closet
Findings:	No grab bars provided
Rec. Solution:	Provide side and rear grab bars with reinforcement
Barrier Severity:	1 Necessary Cost Est \$900.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12V
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 0146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Seat Height
Code References:	2010 ADAS 604.4
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Water closet seat not between 17" to 19" high
Findings:	15" high
Rec. Solution:	Replace water closet
Barrier Severity:	2 Recommended Cost Est \$850.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12W
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 0146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Centerline
Code References:	2010 ADAS 604.2
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Water closet centerline not between 16" and 18" O. C.
Findings:	21-3/4" OC
Rec. Solution:	Relocate water closet
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12X
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 12X Batcheller Hall Reference Dwg: 3 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Dispensers - Parallel Approach
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Dispensers - Parallel Approach 2010 ADAS 308.3.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Dispensers - Parallel Approach 2010 ADAS 308.3.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Dispensers - Parallel Approach 2010 ADAS 308.3.2 Indard: No Quantity: JOB As-built: 1 Where the high side reach is over an obstruction, the height of the obstruction exceeds 34"
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Dispensers - Parallel Approach 2010 ADAS 308.3.2 Indard: No Quantity: JOB As-built: 1 Where the high side reach is over an obstruction, the height of the obstruction exceeds 34" maximum
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A Y Coordinate: N/A Restrooms Dispensers - Parallel Approach 2010 ADAS 308.3.2 Where the high side reach is over an obstruction, the height of the obstruction exceeds 34" maximum Seat cover dispenser 52" high. Water closet blocks dispenser clear floor space Relocate dispenser to location within reach range or provide additional dispenser
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 0146 N/A P Coordinate: N/A Restrooms Dispensers - Parallel Approach 2010 ADAS 308.3.2 Where the high side reach is over an obstruction, the height of the obstruction exceeds 34" maximum Seat cover dispenser 52" high. Water closet blocks dispenser clear floor space Relocate dispenser to location within reach range or provide additional dispenser 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12Y
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 0146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Coat Hook
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	71-3/4" high
Rec. Solution:	Provide additional hook in new location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 12Z
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 0146
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/strobe in sanitary facility
Darriar Cavarity	i rovide norm, strobe in sameary racinty
Barrier Severity:	
Implementation	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 13A
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Stairway S0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Egress Stairway - Clear Width
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: LF As-built : 1
Barrier Description:	Exit stairway does not provide min. 48" clear width between handrails
Findings:	36-1/4" clear width between handrails
Rec. Solution:	Reconfigure handrail to provide min. 48" clear width
Barrier Severity:	1 Necessary Cost Est \$225.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 13B
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Stairway S0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Doormat 03/05/2014-17-52
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Doormat not anchored to floor (possible trip hazard)
Findings:	Doormat not secured
Rec. Solution:	Secure exiting doormat or replace
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 13C
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Stairway S0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Protruding Hazard
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: SF As-built : 1
Barrier Description:	Object protrudes more than 4" into pedestrian way
Findings:	Electrical panel protrudes 6-1/2" at 35-1/2" high
Rec. Solution:	Remove object or provide detectable warning
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 13D
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 13D Batcheller Hall Reference Dwg: 3 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Y Coordinate: N/A Alarms Horn/Strobe
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Y Coordinate: N/A Alarms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in stairwell
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Alarms Horn/Strobe 2010 ADAS 702.1 No horn/strobes in stairwell No device provided Provide strobes in common use area
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Alarms Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in stairwell No device provided Provide strobes in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 13E
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Stairway S0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Sign - Enclosed Exit Stairway Level
Code References:	ICC A117.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Tactile stairway signage not provided to indicate floor level
Findings:	No sign provided
Rec. Solution:	Provide accessible sign
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Also, tao	ctile stairway signage not provided to indicate stair level or discharge level
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 13F
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 13F Batcheller Hall Reference Dwg: 3 of 5
	HAPPY 100TH BIRTHDAY
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Y Coordinate: N/A Stairways Sign - Exit Door
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Y Coordinate: N/A Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Y Coordinate: N/A Stairways Sign - Exit Door Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Y Coordinate: N/A Stairways Sign - Exit Door Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Y Coordinate: N/A Stairways Sign - Exit Door Performance Standard ndard: Yes Quantity: EACH As-built: 2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Stairways Sign - Exit Door Performance Standard ndard: Yes Quantity: EACH As-built: 2 Door leading directly into an exit stairway lacks tactile exit sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Stairways Sign - Exit Door Performance Standard ndard: Yes Quantity: EACH As-built: 2 Door leading directly into an exit stairway lacks tactile exit sign Door to exit stair with low level illuminated sign lacks tactile exit sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Y Coordinate: N/A Stairways Sign - Exit Door Performance Standard Door leading directly into an exit stairway lacks tactile exit sign Door to exit stair with low level illuminated sign lacks tactile exit sign Provide sign stating "EXIT STAIR DOWN" at latch side of each exit door 2 Recommended Cost Est \$500.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 13G
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Stairway S0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	13 - 16 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$900.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Sweep p	period okay
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 13H
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 13H Batcheller Hall Reference Dwg: 3 of 5
	HAPPY 100TH BIRTHDAY
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Y Coordinate: N/A Stairways Door Hardware - Operation
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Y Coordinate: N/A Stairways Door Hardware - Operation 2010 ADAS 404.2.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Y Coordinate: N/A Stairways Door Hardware - Operation 2010 ADAS 404.2.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Y Coordinate: N/A Stairways Door Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Y Coordinate: N/A Stairways Door Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 0 Hardware not operable with a closed fist
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Stairways Door Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 0 Hardware not operable with a closed fist Hardware not accessible
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Stairway S0102 N/A Y Coordinate: N/A Stairways Door Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 0 Hardware not operable with a closed fist Hardware not accessible Replace hardware 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 13I
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Stairway S0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	View panel located higher than 43" above the floor
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$4,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: At 54-1/	⁷ 4" high
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 14A
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Lobby Info Sign
Code References:	Performance Standard
Performance Sta	indard: Yes Quantity: EACH As-built : 1
Barrier Description:	No lobby informational sign with location of accessible elements
Findings:	Accessible sign not provided
	Accessible sign not provided
Rec. Solution:	Provide lobby informational sign
-	Provide lobby informational sign
Rec. Solution:	Provide lobby informational sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 14B
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Findings:	No tactile signage provided at doors within public route
Rec. Solution:	Provide accessible signs
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Rooms 2	147, 152
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 14C
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull
Code References:	2010 ADAS 309.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Fire pull has no usable hardware
Findings:	Fire pull not fist operable
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 14D
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Fire pulls not between 42" and 48" high
Findings:	64-1/2" high
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 14E
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2.1
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	64-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 14F
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Telephone 56" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 14G
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	5" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 14H
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Shelf protrudes 12" at 35-1/4" high
Rec. Solution:	Provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 141
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Alcove - New Construction
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: SF As-built : 20
Barrier Description:	Fountain with a leading edge between 27" and 80" high protrudes more than 4" into the circulation path
Findings:	No alcove provided
Rec. Solution:	Construct new alcove as detectable warning
Barrier Severity:	
-	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 14J
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Bubbler water flow
Code References:	2010 ADAS 602.6
Performance Sta	indard: No Quantity: JOB As-built : 2
Barrier Description:	Water flow from bubbler not min. 4" high
Findings:	2" - 2-1/2" high water flow from bubbler
Rec. Solution:	Adiust drinking fountain to provide min. 4" high water flow
Barrier Severity:	2 Recommended Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: High and	d Low Fountains
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 14K
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 14K Batcheller Hall Reference Dwg: 3 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Lobby L0102
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Drinking Fountains Knee Clearance
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Drinking Fountains
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Drinking Fountains Knee Clearance 2010 ADAS 306.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Drinking Fountains Knee Clearance 2010 ADAS 306.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Drinking Fountains Knee Clearance 2010 ADAS 306.3 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Lobby L0102 N/A V Coordinate: N/A Drinking Fountains Knee Clearance 2010 ADAS 306.3 Indard: No Quantity: EACH As-built: 1 Knee clearance under fountain not min. 27" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Drinking Fountains Knee Clearance 2010 ADAS 306.3 Indard: No Quantity: EACH As-built: 1 Knee clearance under fountain not min. 27" high 26-1/2" high knee clearance Replace drinking fountain with accessible unit or remount existing
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Lobby L0102 N/A Y Coordinate: N/A Drinking Fountains Knee Clearance 2010 ADAS 306.3 Indard: No Quantity: EACH As-built: 1 Knee clearance under fountain not min. 27" high 26-1/2" high knee clearance Replace drinking fountain with accessible unit or remount existing 1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 14L
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Lobby L0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobes in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 15A
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Classroom 0150
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	
	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 15B
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Classroom 0150
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	10 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 15C
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Classroom 0150
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	3 second sweep
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 15D
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Classroom 0150
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Door Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Operating controls involve tight grasping, pinching or twisting
Findings:	Hardware not accessible
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 15E
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Classroom 0150
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Door Vision Lights
Code References:	2010 ADAS 404.2.11
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	View panel located higher than 43" above the floor
Rec. Solution:	Replace door/gate or vision panel
Rec. Solution: Barrier Severity:	
	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 15F
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Classroom 0150
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Door Clearance - Min. 12" at Push Side
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door lacks min. 12" strike edge clearance at push side
Findings:	7-3/4" strike edge clearance
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 15G
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 15G Batcheller Hall Reference Dwg: 3 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Classroom 0150
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Classroom 0150 N/A Y Coordinate: N/A Classrooms Electrical Switches
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Classroom 0150 N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Classroom 0150 N/A Y Coordinate: N/A Classrooms Electrical Switches 2010 ADAS 205.1 & 309.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Classroom 0150 N/A Y Coordinate: N/A Classrooms Electrical Switches 2010 ADAS 205.1 & 309.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Classroom 0150 N/A Y Coordinate: N/A Classrooms Electrical Switches 2010 ADAS 205.1 & 309.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Classroom 0150 N/A Y Coordinate: N/A Classrooms Electrical Switches 2010 ADAS 205.1 & 309.3 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Classroom 0150 N/A Y Coordinate: N/A Classrooms Electrical Switches 2010 ADAS 205.1 & 309.3 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Classroom 0150 N/A Y Coordinate: N/A Classrooms Electrical Switches 2010 ADAS 205.1 & 309.3 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high S4" high Relocate switch box top edge to max. 48" high Relocate switch box top edge to max. 48" high Relocate switch box top edge to max. 48" high Relocate switch box top edge to max. 48" high Relocate switch box top edge to max. 48" high



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 15H
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Classroom 0150
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Pencil sharpener 54" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 15I
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Classroom 0150
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	indard: No Quantity: LF As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	13-1/4" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Rec. Solution: Barrier Severity:	
	2 Recommended Cost Est \$225.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 15J
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Classroom 0150
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Abrupt Change in Level
Code References:	2010 ADAS 303.3
Performance Sta	ndard: No Quantity: LF As-built : 1
Barrier Description:	Change in level greater than 1/2" leading in circulation path
Findings:	Carpet is deteriorating and may create a tripping hazard
Rec. Solution:	Repair to remove trip hazard
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 15K
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Classroom 0150
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Ratio
Code References:	2010 ADAS 902
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	At least 1 desk or 5% of all desks not accessible
Findings:	At least 3 accessible desks not provided
Rec. Solution:	Provide at least 3 accessible desks
Barrier Severity:	3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open
Implementation	· · · · · · · · _
Notes: 48 desks	s. 1 accessible desk provided



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 15L
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Classroom 0150
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	Passageway less than 36" in multiple locations
Rec. Solution:	Rearrange furniture to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 15M
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Classroom 0150
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Integration
Code References:	2010 ADAS 307.2
Performance Sta	indard: No Quantity: EACH As-built : 0
Barrier Description:	Desk not integrated into assembly seating
Findings:	Desk identified as accessible is not integrated into typical seating
Rec. Solution:	Move desk to integrated setting
Barrier Severity:	2 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Desk is a	accessible



Field Date.	Daylord Data Data Daylord Devices H. 451
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 15N
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Classroom 0150
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Projector Screen Pull
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Screen pull not at max. 48" high for side reach
Findings:	Projector screen pull 67-1/2" high
Rec. Solution:	Relocate to max. 48" high or provide extension
Barrier Severity:	3 Hindrance Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 150
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Classroom 0150
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
	Control or mechanism not at min. 15" or max. 48" high Telephones 49" high. Stored elements block telephone clear floor space
Description:	
Description: Findings:	Telephones 49" high. Stored elements block telephone clear floor space Relocate control or mechanism to min. 15" or max. 48" high
Description: Findings: Rec. Solution:	Telephones 49" high. Stored elements block telephone clear floor space Relocate control or mechanism to min. 15" or max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 15P
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Classroom 0150
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Podium - Surface Height
Code References:	2010 ADAS 504.2
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Surface height exceeds 34" high
Findings:	Keyboard and monitor 35-1/4" high - 43" high at the workstation
Rec. Solution:	Provide min. 1 accessible podium
Barrier Severity:	4 Low Severity Cost Est \$1,275.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 15Q
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Classroom 0150
Location: X Coordinate:	Floor 1 - Classroom 0150 N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Classrooms
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Classrooms Alarm - Horn/Strobe 2010 ADAS 702.1
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Classrooms Alarm - Horn/Strobe 2010 ADAS 702.1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	N/A Y Coordinate: N/A Classrooms Alarm - Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Y Coordinate: N/A Classrooms Alarm - Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 Where a fire alarm is installed, no horn/strobe provided
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Classrooms Alarm - Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 Where a fire alarm is installed, no horn/strobe provided No device provided Provide horn/strobe in sanitary facility
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Classrooms Alarm - Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 Where a fire alarm is installed, no horn/strobe provided No device provided Provide horn/strobe in sanitary facility 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 16A
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Undergraduate Programs Office 0151
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 4
Barrier Description:	At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Findings:	No tactile signage provided at doors within public route
Rec. Solution:	Provide accessible signs
Barrier Severity:	1 Necessary Cost Est \$1,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Rooms	151, 151B, 151D, 151E
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 16B
	3/4/2014 Report Date 3/6/2014 Barrier #: 16B Batcheller Hall Reference Dwg: 3 of 5
Bldg Name:	
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5
Field Date: Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Undergraduate Programs Office 0151
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Undergraduate Programs Office 0151 N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Undergraduate Programs Office 0151 N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Undergraduate Programs Office 0151 N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Undergraduate Programs Office 0151 N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Undergraduate Programs Office 0151 N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Undergraduate Programs Office 0151 N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5 Indard: No Quantity: EACH As-built: 1 Signs between 70" and 120" high lack characters at least 2" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Undergraduate Programs Office 0151 N/A Y Coordinate: N/A Signage Viewing From Distance - > 70" high 2010 ADAS 703.5.5 and Table 703.5.5 Indard: No Quantity: EACH As-built: 1 Signs between 70" and 120" high lack characters at least 2" high Characters on sign not large enough to view from a distance at 1/2" high Replace sign with characters min. 2" in height for viewing at a distance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Undergraduate Programs Office 0151 N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5 Indard: No Quantity: EACH As-built: 1 Signs between 70" and 120" high lack characters at least 2" high Characters on sign not large enough to view from a distance at 1/2" high Replace sign with characters min. 2" in height for viewing at a distance 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 16C
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Undergraduate Programs Office 0151
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	14 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 16D
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 16D Batcheller Hall Reference Dwg: 3 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Undergraduate Programs Office 0151
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Undergraduate Programs Office 0151 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Undergraduate Programs Office 0151 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Undergraduate Programs Office 0151 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Undergraduate Programs Office 0151 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Undergraduate Programs Office 0151 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Undergraduate Programs Office 0151 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Undergraduate Programs Office 0151 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame 3 second sweep
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Undergraduate Programs Office 0151 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame 3 second sweep Provide automatic door opening device 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 16E
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Undergraduate Programs Office 0151
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 16F
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Undergraduate Programs Office 0151
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code	
References:	2010 ADAS 404.2.11
References:	
References: Performance Sta Barrier	andard: No Quantity: EACH As-built : 1
References: Performance Sta Barrier Description: Findings:	andard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground
References: Performance Sta Barrier Description: Findings: Rec. Solution:	Andard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel located higher than 43" above the floor Replace door/gate or vision panel
References: Performance Sta Barrier Description: Findings: Rec. Solution: Barrier Severity:	As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel located higher than 43" above the floor Replace door/gate or vision panel 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
References: Performance Sta Barrier Description:	Andard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel located higher than 43" above the floor Replace door/gate or vision panel 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open Priority: 2 Implementation Phase: Implementation Date:



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 16G
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Undergraduate Programs Office 0151
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Surface Height
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	No section at least 3 feet long between 28" and 34" provided at existing counter
Findings:	42-1/4" high
Rec. Solution:	Provide min. 3 ft long section of counter at max. 34" high
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 16H
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Undergraduate Programs Office 0151
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - Wheelchair Use
Code References:	2010 ADAS 306.3.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	No wheelchair space provided in waiting area
Rec. Solution:	Rearrange furniture to provide wheelchair space
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 16I
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Undergraduate Programs Office 0151
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Printer 54" high
Rec. Solution:	Relocate within accessible reach range
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 16J
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Undergraduate Programs Office 0151
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36"
Code References:	2010 ADAS 403.5.1
Performance Sta	ndard: No Quantity: LF As-built : 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	Passageway less than 36" in multiple locations
Rec. Solution:	Remodel to provide access
Barrier Severity:	1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 34-1/2"	wide circulation between desk and wall



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 16K
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Undergraduate Programs Office 0151
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobes in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 17A
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - South Entry Vestibule V0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Door
Code References:	2010 ADAS 216.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Ground floor doors that exit to exterior lacks tactile exit sign
Findings:	Exit door with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT" at exit side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 17B
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - South Entry Vestibule V0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	indard: No Quantity: EACH As-built: 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Dispenser 53" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 17C
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - South Entry Vestibule V0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	64-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 17D
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - South Entry Vestibule V0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Doormat
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Doormat not anchored to floor (possible trip hazard)
Findings:	Doormat not secured
Rec. Solution:	Secure exiting doormat or replace
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 17E
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 17E Batcheller Hall Reference Dwg: 3 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - South Entry Vestibule V0102
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - South Entry Vestibule V0102 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - South Entry Vestibule V0102 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - South Entry Vestibule V0102 N/A Y Coordinate: N/A Doors or Gates Door Closer - Exterior Adjustment Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - South Entry Vestibule V0102 N/A Y Coordinate: N/A Doors or Gates Door Closer - Exterior Adjustment Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - South Entry Vestibule V0102 N/A Y Coordinate: N/A Doors or Gates Door Closer - Exterior Adjustment Performance Standard andard: Yes Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - South Entry Vestibule V0102 N/A Y Coordinate: N/A Doors or Gates Door Closer - Exterior Adjustment Performance Standard andard: Yes Quantity: EACH As-built: 1 Door opening force exceeds 8.5 lbf
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - South Entry Vestibule V0102 N/A Y Coordinate: N/A Doors or Gates Door Closer - Exterior Adjustment Performance Standard andard: Yes Quantity: EACH As-built: 1 Door opening force exceeds 8.5 lbf 14 lbf Replace or adjust existing closer
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - South Entry Vestibule V0102 N/A Y Coordinate: N/A Doors or Gates Door Closer - Exterior Adjustment Performance Standard andard: Yes Quantity: EACH As-built: 1 Door opening force exceeds 8.5 lbf 14 lbf Replace or adjust existing closer 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 17F
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - South Entry Vestibule V0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Exterior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	4 second sweep
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 17G
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - South Entry Vestibule V0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	
barrier Type.	ISA - Non-Accessible Entry
Code References:	ISA - Non-Accessible Entry 2010 ADAS 216.6
Code	2010 ADAS 216.6
Code References:	2010 ADAS 216.6
Code References: Performance Sta Barrier	2010 ADAS 216.6 andard: No Quantity: EACH As-built: 1
Code References: Performance Sta Barrier Description:	2010 ADAS 216.6 andard: No Quantity: EACH As-built: 1 Sign directing people to accessible entrance needed where all doors are not accessible
Code References: Performance Sta Barrier Description: Findings:	2010 ADAS 216.6 andard: No Quantity: EACH As-built: 1 Sign directing people to accessible entrance needed where all doors are not accessible Sign posted at top of stairway on view panel Provide ISA directional sign in location where people approaching building can make use of info
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	2010 ADAS 216.6 andard: No Quantity: EACH As-built: 1 Sign directing people to accessible entrance needed where all doors are not accessible Sign posted at top of stairway on view panel Provide ISA directional sign in location where people approaching building can make use of info 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 18A
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - East Corridor H0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	10 - 13 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Double	Doors
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 18B
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - East Corridor H0102
_	
Location:	Floor 1 - East Corridor H0102
Location: X Coordinate:	Floor 1 - East Corridor H0102 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period
Location: X Coordinate: Barrier Area:	Floor 1 - East Corridor H0102 N/A Y Coordinate: N/A Doors or Gates
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 1 - East Corridor H0102 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 1 - East Corridor H0102 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 1 - East Corridor H0102 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 1 - East Corridor H0102 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 andard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - East Corridor H0102 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame Door does not stop 5" from door frame Provide automatic door opening device
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 1 - East Corridor H0102 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 mdard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame Door does not stop 5" from door frame Provide automatic door opening device 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 18C
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - East Corridor H0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Threshold - Height exceeding 1/4" without bevel
Code References:	2010 ADAS 404.2.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate threshold exceeds 1/4" in height without a bevel
Findings:	Threshold surface deteriorating, not firm and stable
Rec. Solution:	Provide new door threshold
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 18D
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 18D Batcheller Hall Reference Dwg: 3 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - East Corridor H0102
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - East Corridor H0102 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - East Corridor H0102 N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - East Corridor H0102 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Passage Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - East Corridor H0102 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Passage Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - East Corridor H0102 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Passage Performance Standard ndard: Yes Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - East Corridor H0102 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Passage Performance Standard Indard: Yes Quantity: EACH As-built: 1 Exit thru an exit enclosure/exit passageway lacks tactile exit sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - East Corridor H0102 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Passage Performance Standard mdard: Yes Quantity: EACH As-built: 1 Exit thru an exit enclosure/exit passageway lacks tactile exit sign Passageway to exterior exit with low level illuminated sign lacks tactile exit sign Provide sign stating "EXIT ROUTE" at exit side of door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - East Corridor H0102 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Passage Performance Standard Indard: Yes Quantity: EACH As-built: 1 Exit thru an exit enclosure/exit passageway lacks tactile exit sign Passageway to exterior exit with low level illuminated sign lacks tactile exit sign Provide sign stating "EXIT ROUTE" at exit side of door 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 18E
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - East Corridor H0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Room 1	45
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 18F
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - East Corridor H0102
X Coordinate:	
A coordinate.	N/A Y Coordinate: N/A
Barrier Area:	N/A
	Signage Viewing From Distance - >70" high
Barrier Area:	Signage
Barrier Area: Barrier Type: Code	Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5
Barrier Area: Barrier Type: Code References:	Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5
Barrier Area: Barrier Type: Code References: Performance Sta	Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5 Indard: No Quantity: EACH As-built : 1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5 Indard: No Quantity: EACH As-built: 1 Signs between 70" and 120" high lack characters at least 2" high
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5 Indard: No Quantity: EACH As-built : 1 Signs between 70" and 120" high lack characters at least 2" high Characters on sign not large enough to view from a distance at 3/8" high Replace sign with characters min. 2" in height for viewing at a distance
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5 Indard: No Quantity: EACH As-built: 1 Signs between 70" and 120" high lack characters at least 2" high



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 18G
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - East Corridor H0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	58" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 18H
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - East Corridor H0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Mailbox - High Reach Range
Code References:	2010 ADAS 308.2.2
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Mailbox opening is above 48" high
Findings:	Mail slots 61-1/2" - 71" high
Rec. Solution:	Relocate to provide opening at max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 18I
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - East Corridor H0102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in corridor
Findings:	No device provided
Rec. Solution:	Provide strobes in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 19A
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 19A Batcheller Hall Reference Dwg: 3 of 5
	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - The HUB 0144
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - The HUB 0144 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - The HUB 0144 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - The HUB 0144 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - The HUB 0144 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - The HUB 0144 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 1 At interior or exterior location, no tactile characters at sign identifying permanent rooms and
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - The HUB 0144 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 1 At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - The HUB 0144 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces No tactile signage provided at door within public route Provide accessible sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - The HUB 0144 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces No tactile signage provided at door within public route Provide accessible sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 19B
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - The HUB 0144
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Visual Information Provided (Exhibitions)
Code References:	ADA Title II Technical Assistance Manual 3.2000 Denial of participation
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Visual sign providing information for program, service or activity not accessible
Findings:	Accessible sign not provided
Rec. Solution:	Provide information in alternate format to provide access to people with vision impairments
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 19C
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - The HUB 0144
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	13 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 19D
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - The HUB 0144
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	Door does not stop 5" from door frame
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 5 second	d sweep
E: 115 ·	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 19E
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - The HUB 0144
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - The HUB 0144 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - The HUB 0144 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - The HUB 0144 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - The HUB 0144 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - The HUB 0144 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - The HUB 0144 N/A V Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - The HUB 0144 N/A Poors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel located higher than 43" above the floor Replace door/gate or vision panel
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - The HUB 0144 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel located higher than 43" above the floor Replace door/gate or vision panel 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 19F
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - The HUB 0144
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Desks a	re pedestal base desks but they provide enough knee clearance at the visitor's side of the desk
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 19G
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - The HUB 0144
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
	Classrooms
Barrier Type:	Classrooms Protruding Object
Barrier Type: Code References:	
Code	Protruding Object 2010 ADAS 307.2
Code References:	Protruding Object 2010 ADAS 307.2
Code References: Performance Sta Barrier	Protruding Object 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 1
Code References: Performance Sta Barrier Description:	Protruding Object 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 1 Wall mounted object (dispensers) protrudes more than 4" from wall
Code References: Performance Sta Barrier Description: Findings:	Protruding Object 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 1 Wall mounted object (dispensers) protrudes more than 4" from wall Coat hook rack protrudes more than 4" at 64-1/4" high Relocate or remove object or provide detectable warning
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Protruding Object 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 1 Wall mounted object (dispensers) protrudes more than 4" from wall Coat hook rack protrudes more than 4" at 64-1/4" high Relocate or remove object or provide detectable warning 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 19H
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - The HUB 0144
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	64-1/4" high
Rec. Solution:	Provide additional hook in new location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 19
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - The HUB 0144
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - Wheelchair Use
Code References:	2010 ADAS 305
Performance Sta	ndard: No Quantity: SF As-built : 0
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	No space provided for wheelchair users
Rec. Solution:	Rearrange furniture to provide wheelchair space
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 19J
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - The HUB 0144
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	12-1/2" deep knee clearance. Cubicles are 37" wide from entrance to the wall
Rec. Solution:	Provide min. 1 accessible table
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 3 cubica	ll study spaces
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 19K
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - The HUB 0144
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard & 2010 ADAS 904.3.3
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 40-3/4" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	
	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 19L
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - The HUB 0144
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	12-1/2" deep knee clearance
Rec. Solution:	Provide min. 1 accessible table
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 4 tables	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 19M
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - The HUB 0144
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobes in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 20A
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women in Engineering Lounge 141
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 20B
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 20B Batcheller Hall Reference Dwg: 3 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women in Engineering Lounge 141
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5 ndard: No Quantity: EACH As-built: 1 Signs between 70" and 120" high lack characters at least 2" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5 ndard: No Quantity: EACH As-built: 1 Signs between 70" and 120" high lack characters at least 2" high Characters on sign not large enough to view from a distance at 3/8" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5 ndard: No Quantity: EACH As-built: 1 Signs between 70" and 120" high lack characters at least 2" high Characters on sign not large enough to view from a distance at 3/8" high Replace sign with characters min. 2" in height for viewing at a distance 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 20C
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women in Engineering Lounge 141
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 20D
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 20D Batcheller Hall Reference Dwg: 3 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women in Engineering Lounge 141
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 ndard: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 view panels in or adjacent to doors or gates not max. 43" above floor or ground View panel located higher than 43" above the floor
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 3 of 5 Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Doors or Gates Vision Lights - Existing 2010 ADAS 404.2.11 Indiand: No Quantity: EACH As-built: 1 View panels in or adjacent to doors or gates not max. 43" above floor or ground View panel located higher than 43" above the floor Replace door/gate or vision panel 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 20E
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women in Engineering Lounge 141
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-1/2" - 50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 20F
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women in Engineering Lounge 141
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	56-1/2" high. Bookcase blocks clear floor space at coat hook and electrical switch
Rec. Solution:	Provide additional hook in new location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	
	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 20G
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women in Engineering Lounge 141
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12-3/4" high. Stored items block outlet clear floor space
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Tables h	nave accessible knee clearance
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 20H
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women in Engineering Lounge 141
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36"
Code References:	2010 ADAS 403.5.1
Performance Sta	ndard: No Quantity: LF As-built : 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	12" - 14-1/4" wide circulation route to whiteboard, and advising desk
Rec. Solution:	Demolish existing and construct new passageway
Barrier Severity:	1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	
•	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 201
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women in Engineering Lounge 141
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Protruding Hazard
Code References:	2010 ADAS 902.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Desk creates protruding hazard in accessible route
Findings:	Desk protrudes more than 4" above 27" high
Rec. Solution:	Provide detectable warning, as needed
Barrier Severity:	2 Necessary Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes: Desk do	es have accessible knee clearance
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 20J
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women in Engineering Lounge 141
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Carpet/Rug
Code References:	2010 ADAS 302.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Carpet/rug not anchored to floor (possible trip hazard)
Description.	Carpety rag not anononed to noon (possible trip nazara)
Findings:	Carpet/rug creates tripping hazard
·	
Findings:	Carpet/rug creates tripping hazard Secure exiting carpet/rug or replace
Findings: Rec. Solution:	Carpet/rug creates tripping hazard Secure exiting carpet/rug or replace 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 20L
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women in Engineering Lounge 141
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard & 2010 ADAS 904.3.3
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 49-1/2" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Whitebo	oard on door 49-1/2" high
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 20M
Bldg Name:	Batcheller Hall Reference Dwg: 3 of 5
	jactereller Hall
Location:	Floor 1 - Women in Engineering Lounge 141
Location: X Coordinate:	
	Floor 1 - Women in Engineering Lounge 141
X Coordinate:	Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Alarms
X Coordinate: Barrier Area: Barrier Type: Code	Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1
X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas No device provided Provide strobes in common use area
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 1 - Women in Engineering Lounge 141 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1 mdard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas No device provided Provide strobes in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 21A
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Extension
Code References:	2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built : 2
Barrier Description:	Handrail extension does not return to wall, guard or landing surface
Findings:	Electrical box blocks top handrail extension
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 21B
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Sign - Enclosed Exit Stairway Level
Code References:	ICC A117.1
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	Tactile stairway signage not provided to indicate floor level
Findings:	No sign provided
Rec. Solution:	Provide accessible sign
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 21C
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Sign - Exit Door
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Door leading directly into an exit stairway lacks tactile exit sign
Findings:	Door to exit stair with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT STAIR DOWN" at latch side of door
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
-	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 21D
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 21D Batcheller Hall Reference Dwg: 4 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S0202
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S0202 N/A Y Coordinate: N/A Stairways Door Closer - Interior Adjustment
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S0202 N/A Y Coordinate: N/A Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S0202 N/A Y Coordinate: N/A Stairways Door Closer - Interior Adjustment 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S0202 N/A Y Coordinate: N/A Stairways Door Closer - Interior Adjustment 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S0202 N/A Y Coordinate: N/A Stairways Door Closer - Interior Adjustment 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S0202 N/A Y Coordinate: N/A Stairways Door Closer - Interior Adjustment 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S0202 N/A Y Coordinate: N/A Stairways Door Closer - Interior Adjustment 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 14 lbf Replace or adjust existing closer
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S0202 N/A Y Coordinate: N/A Stairways Door Closer - Interior Adjustment 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 14 lbf Replace or adjust existing closer 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 21E
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Door Closer - Interior Sweep ADA
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	4 second sweep
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: West sta	air door sweep is okay at 7 sec - East stairway door 4 sec
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 21F
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Door Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not accessible
Rec. Solution:	
	Replace hardware
Barrier Severity:	
Barrier Severity: Implementation	1 Necessary Cost Est \$600.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 21G
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobes in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 22A
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Main Corridor H0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built: 3
Barrier Description:	At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Findings:	No tactile signage provided at doors within public route
Rec. Solution:	
Barrier Severity:	Provide accessible signs
barrier severity.	
Implementation	1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 22B
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Main Corridor H0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Carpet - Firmly Attached
Code References:	2010 ADAS 302.2
Performance Sta	ndard: No Quantity: SF As-built : 200
Barrier Description:	Carpet, carpet tile or exposed edges of carpet not securely attached or fastened to floor
Findings:	Carpet not firmly attached to floor. Surface deteriorating, not firm and stable
Rec. Solution:	Fasten carpet or tiles firmly to floor, remove or replace
Barrier Severity:	2 Recommended Cost Est \$2,400.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 22C
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Main Corridor H0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	54-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 22D
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Main Corridor H0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12-1/2" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 22E
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Main Corridor H0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Passage
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built : 2
Barrier Description:	Exit thru an exit enclosure/exit passageway lacks tactile exit sign
Findings:	Passageway to exterior exit with low level illuminated sign lacks tactile exit sign
Findings: Rec. Solution:	Passageway to exterior exit with low level illuminated sign lacks tactile exit sign Provide sign stating "EXIT ROUTE" at exit side of door
-	Provide sign stating "EXIT ROUTE" at exit side of door
Rec. Solution:	Provide sign stating "EXIT ROUTE" at exit side of door 2 Recommended Cost Est \$500.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 22F
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Main Corridor H0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull
Code References:	2010 ADAS 309.4
Performance Sta	indard: No Quantity: EACH As-built: 1
Barrier Description:	Fire pull has no usable hardware
Findings:	Fire pull not fist operable
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 22G
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Main Corridor H0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Fire pulls not between 42" and 48" high
Findings:	58" high
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Barrier Severity: Implementation	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 22H
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Main Corridor H0202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn provided with strobe
Findings:	Horn provided without a strobe
Rec. Solution:	Provide horn device with strobe device
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes: Door at	the end of the hall leads to Dearborn - Door barriers noted in Dearborn's Database
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 23A
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 0250
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 23B
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 0250
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Door Clearance - Min. 12" at Push Side
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door lacks min. 12" strike edge clearance at push side
Findings:	No strike edge clearance
Rec. Solution:	Relocate door or gate to provide maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Blocked	by trash cans
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 23C
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 0250
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Electrical Switches - High Unobstructed
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-3/4" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Rec. Solution: Barrier Severity:	
	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 23D
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 0250
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Projector Screen Pull
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Screen pull not at max. 48" high for side reach
Findings:	Projector screen pull 59-1/2" high
Rec. Solution:	Relocate to max. 48" high or provide extension
Barrier Severity:	3 Hindrance Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 23E
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 0250
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Workstation - Knee Clearance
Code References:	2010 ADAS 902
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance of at least 27" high, 30" wide and 8" deep not provided
Findings:	14-1/2" deep knee clearance
Rec. Solution:	Reposition workstation to provide knee clearance
Barrier Severity:	1 Necessary Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	
	ors workstation



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 23F
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 0250
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24-1/2" high knee clearance
Rec. Solution:	Provide min. 1 accessible table
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Instruct	ors table
-	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 23G
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 23G Batcheller Hall Reference Dwg: 4 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 0250
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 0250 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 0250 N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 0250 N/A Y Coordinate: N/A Classrooms Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 0250 N/A Y Coordinate: N/A Classrooms Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 0250 N/A Y Coordinate: N/A Classrooms Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 0250 N/A Y Coordinate: N/A Classrooms Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Control or mechanism not at min. 15" or max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 0250 N/A Y Coordinate: N/A Classrooms Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Control or mechanism not at min. 15" or max. 48" high Telephone 53" high. Stored elements block telephone clear floor space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Classroom 0250 N/A Y Coordinate: N/A Classrooms Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Control or mechanism not at min. 15" or max. 48" high Telephone 53" high. Stored elements block telephone clear floor space Relocate control or mechanism to min. 15" or max. 48" high Relocate control or mechanism to min. 15" or max. 48" high Alindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 23H
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 0250
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: LF As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	10-1/4" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	2 Recommended Cost Est \$225.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 23I
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 0250
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Ratio
Code References:	2010 ADAS 902
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	At least 1 desk or 5% of all desks not accessible
Findings:	At least 3 accessible desks not provided
Rec. Solution:	Provide at least 3 accessible desks
Barrier Severity:	
	3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open
Implementation	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 23J
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 0250
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	Passageway less than 36" in multiple locations
Rec. Solution:	Rearrange furniture to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 23K
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 0250
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Integration
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Desk not integrated into assembly seating
Findings:	Desk identified as accessible is not integrated into typical seating
Rec. Solution:	Move accessible desk to integrated setting
Barrier Severity:	2 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 23L
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 0250
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Knee clearance of at least 27" high, 30" wide and 8" deep not provided underneath desk
Findings:	26-1/4" high, 16-1/4" deep knee clearance
Rec. Solution:	Reposition desk to provide knee clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Adjusta	ble Desk
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 23M
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
-	Date letter Trail
Location:	Floor 2 - Classroom 0250
Location:	Floor 2 - Classroom 0250
Location: X Coordinate:	Floor 2 - Classroom 0250 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 2 - Classroom 0250 N/A Y Coordinate: N/A Controls and Mechanisms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 2 - Classroom 0250 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 2 - Classroom 0250 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 2 - Classroom 0250 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 andard: No Quantity: JOB As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 2 - Classroom 0250 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 andard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 2 - Classroom 0250 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 andard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground Shelf or cabinet not accessible Provide additional shelf at accessible height or provide assistance
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 2 - Classroom 0250 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 Andard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground Shelf or cabinet not accessible Provide additional shelf at accessible height or provide assistance 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 23N
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Classroom 0250
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in classroom
Findings:	No device provided
Rec. Solution:	Provide strobes in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
<u> </u>	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 24A
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 24A Batcheller Hall Reference Dwg: 4 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - West Corridor H0205
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - West Corridor H0205 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - West Corridor H0205 N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - West Corridor H0205 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - West Corridor H0205 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - West Corridor H0205 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 At interior or exterior location, no tactile characters at sign identifying permanent rooms and
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - West Corridor H0205 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 3 At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - West Corridor H0205 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces No tactile signage provided at doors within public route Provide accessible signs
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - West Corridor H0205 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces No tactile signage provided at doors within public route Provide accessible signs 1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 24B
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - West Corridor H0205
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 24C
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - West Corridor H0205
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Pamphlet holder 50-1/2" - 75-1/2" high
Rec. Solution:	Relocate control or mechanisms to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25A
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 0259
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25B
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 0259
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	16 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	· ·
implementation	Priority: 3 Implementation Phase: Implementation Date:



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25C
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 0259
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	2 second sweep
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25D
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 25D Batcheller Hall Reference Dwg: 4 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Doors or Gates Clear Width
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Doors or Gates Clear Width 2010 ADAS 404.2.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Doors or Gates Clear Width 2010 ADAS 404.2.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Doors or Gates Clear Width 2010 ADAS 404.2.3 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Doors or Gates Clear Width 2010 ADAS 404.2.3 Indard: No Quantity: EACH As-built: 1 Door, sliding/folding door or gate clear width is not min. 32"
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Poors or Gates Clear Width 2010 ADAS 404.2.3 Indard: No Quantity: EACH As-built: 1 Door, sliding/folding door or gate clear width is not min. 32" 28-1/2" clear width Replace door or gate and frame
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Doors or Gates Clear Width 2010 ADAS 404.2.3 Indard: No Quantity: EACH As-built: 1 Door, sliding/folding door or gate clear width is not min. 32" 28-1/2" clear width Replace door or gate and frame I Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25E
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 0259
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Relocate Door
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	4" strike edge clearance
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25F
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 0259
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-3/4" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25G
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 0259
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Wall mounted object (dispensers) protrudes more than 4" from wall
Findings:	Paper towel dispenser protrudes 10" at 55" high
Rec. Solution:	Relocate dispenser or provide cane-detectable warning
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25H
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 25H Batcheller Hall Reference Dwg: 4 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Restrooms Dispensers - Height 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Restrooms Dispensers - Height 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Restrooms Dispensers - Height 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Restrooms Dispensers - Height 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 0 Dispenser control point or operating mechanism not max. 48" AFF
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Restrooms Dispensers - Height 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 0 Dispenser control point or operating mechanism not max. 48" AFF Paper towel dispenser 55" high Remount no higher than 48" above floor
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Restrooms Dispensers - Height 2010 ADAS 307.2 Indard: No Quantity: EACH As-built: 0 Dispenser control point or operating mechanism not max. 48" AFF Paper towel dispenser 55" high Remount no higher than 48" above floor 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 251
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 0259
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	57-1/2" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
<u> </u>	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25J
	3/4/2014 Report Date 3/6/2014 Barrier #: 25J Batcheller Hall Reference Dwg: 4 of 5
Bldg Name:	
Bldg Name: Location:	Batcheller Hall Reference Dwg: 4 of 5
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259
Field Date: Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Restrooms Mirror 2010 ADAS 603.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Restrooms Mirror 2010 ADAS 603.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Restrooms Mirror 2010 ADAS 603.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Restrooms Mirror 2010 ADAS 603.3 ndard: No Quantity: EACH As-built: 1 Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Y Coordinate: N/A Restrooms Mirror 2010 ADAS 603.3 ndard: No Quantity: EACH As-built: 1 Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface 41-1/2" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 0259 N/A Proordinate: N/A Restrooms Mirror 2010 ADAS 603.3 Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface 41-1/2" high Replace or remount mirror 3 Hindrance Cost Est \$375.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25K
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 0259
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Knee Cl
Code References:	2010 ADAS 606.2 & 306
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Lavatory bottom apron/edge not max 29" reducing to 27" at 8" back from edge
Findings:	24" high knee clearance
Rec. Solution:	Replace lavatory
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Only lav	atory
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25L
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 0259
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Drainpipes
Code References:	2010 ADAS 606.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hot water and drainpipes accessible under lavatory not insulated or covered
Findings:	No insulation provided
Rec. Solution:	Insulate drainpipes and hot water pipes
Barrier Severity:	2 Recommended Cost Est \$220.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25M
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 0259
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Coat Hook
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	68-1/2" high. Wall blocks coat hook clear floor space
Rec. Solution:	Provide additional hook in new location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25N
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 0259
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Transfer - Floor-mounted
Code References:	2010 ADAS 604.8.1.1
Performance Sta	ndard: No Quantity: SF As-built : 80
Barrier Description:	Min. 60" wide x 59" deep clear floor space not provided at floor-mounted fixture
Findings:	53-3/4" wide to lavatory
Rec. Solution:	Remodel to provide front transfer space
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 250
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 0259
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Grab Bars
Code References:	2010 ADAS 604.5
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	No grab bars provided at water closet
Findings:	No grab bars provided
Rec. Solution:	Provide side and rear grab bars with reinforcement
Barrier Severity:	1 Necessary Cost Est \$900.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25P
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 0259
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Flush Handle
Code References:	2010 ADAS 604.6
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Handle does not point to wide side of stall or compartment
Findings:	Handle positioned on wall side
Rec. Solution:	Replace water closet
Barrier Severity:	
	1 Necessary Cost Est \$850.00 Facility Function: Public Status: Open
Implementation	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25Q
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 0259
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Seat Height
Code References:	2010 ADAS 604.4
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Water closet seat not between 17" to 19" high
Findings:	15-1/2" high
Rec. Solution:	Replace water closet
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25R
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 0259
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Centerline
Code References:	2010 ADAS 604.2
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Water closet centerline not between 16" and 18" O. C.
Findings:	19-1/2" OC
Rec. Solution:	Relocate water closet
Barrier Severity:	
Implementation	
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25S
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 0259
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Paper Dispenser
Code References:	2010 ADAS 604.7
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Toilet tissue dispenser not within 7" to 9" from front edge of toilet
Findings:	Mounted behind front of toilet
Rec. Solution:	Reposition or replace toilet paper dispenser
Barrier Severity:	3 Hindrance Cost Est \$225.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25T
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 0259
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Dispenser not located on an accessible route
Findings:	Sanitary product dispenser located behind toilet seat rim
Rec. Solution:	Replace or remount dispenser
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25U
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 0259
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Seat Cover Dispenser
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Seat cover dispenser not located on an accessible route. Blocked by water closet
Findings:	Access to dispenser blocked by water closet
Rec. Solution:	Replace or remount dispenser on an accessible route with clear floor space
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 25V
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 0259
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobes in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 26A
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Central Corridor H0204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Room 2	51
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 26B
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Central Corridor H0204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2.1
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Dala sata susitah harutan adas ta sasu 400 bish
	Relocate switch box top edge to max. 48" high
Barrier Severity:	
Barrier Severity: Implementation	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 27A
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Precollege Programs Workroom 249
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 27B
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 27B Batcheller Hall Reference Dwg: 4 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Precollege Programs Workroom 249
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Precollege Programs Workroom 249 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Precollege Programs Workroom 249 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Precollege Programs Workroom 249 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Precollege Programs Workroom 249 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Precollege Programs Workroom 249 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Precollege Programs Workroom 249 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Precollege Programs Workroom 249 N/A V Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 17 lbf Provide automatic door opening device
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Precollege Programs Workroom 249 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 17 lbf Provide automatic door opening device I Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 27C
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Precollege Programs Workroom 249
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	3 second sweep
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 27D
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Precollege Programs Workroom 249
X Coordinate:	N/A Y Coordinate: N/A
	1.47.1
Barrier Area:	Doors or Gates
Barrier Area: Barrier Type:	Doors or Gates Hardware - Operation
	Doors or Gates
Barrier Type: Code	Doors or Gates Hardware - Operation 2010 ADAS 404.2.7
Barrier Type: Code References:	Doors or Gates Hardware - Operation 2010 ADAS 404.2.7
Barrier Type: Code References: Performance Sta Barrier	Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1
Barrier Type: Code References: Performance Sta Barrier Description:	Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not accessible Provide new hardware
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not accessible Provide new hardware 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 27E
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Precollege Programs Workroom 249
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	View panel located higher than 43" above the floor
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 48-1/2"	high
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 27F
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Precollege Programs Workroom 249
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built: 0
	, , , , , , , , , , , , , , , , , , , ,
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Description: Findings:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side 4-1/4" strike edge clearance Provide automatic door opening device and move table/items to provide access
Description: Findings: Rec. Solution:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side 4-1/4" strike edge clearance Provide automatic door opening device and move table/items to provide access 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 27G
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Precollege Programs Workroom 249
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 27H
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Precollege Programs Workroom 249
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Circulation route through corridor not min. 36"
Findings:	Passageway less than 36" in multiple locations
Rec. Solution:	Rearrange or remove equipment/furniture to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 26" wide	e circulation route between table and copier



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 27
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Precollege Programs Workroom 249
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Turning Space
Barrier Type:	Circular Turning Space - Min. 60"
Code References:	2010 ADAS 304.3.1
Performance Sta	andard: No Quantity: SF As-built : 40
Barrier Description:	Circular turning space not minimum of 60" in diameter (including toe/knee space)
Findings:	60" turning diameter not provided in room
Rec. Solution:	Rework floor or ground surface
Barrier Severity:	2 Recommended Cost Est \$3,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: AC unit,	boxes under table and copier encroach into turning circle
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 27J
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Precollege Programs Workroom 249
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built: 1
Dannian	
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
	Use of outlet involves low reach of less than 15" above floor or more than 48" high 12-1/2" high
Description: Findings:	
Description: Findings: Rec. Solution:	12-1/2" high Relocate outlet to area at min. 15" or max. 48" high
Description:	12-1/2" high Relocate outlet to area at min. 15" or max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 27K
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Precollege Programs Workroom 249
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	No knee clearance at work desk
Rec. Solution:	Move stored objects
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Paper b	oxes, vacuum, AC unit block knee clearance under large desk
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 27L
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Precollege Programs Workroom 249
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Printer 50-1/2" high
Rec. Solution:	Relocate within accessible reach range
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Room o	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 27M
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Precollege Programs Workroom 249
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	indard: No Quantity: EACH As-built: 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobes in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 28A
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - West Corridor H0203
Location:	Floor 2 - West Corridor H0203
Location: X Coordinate:	Floor 2 - West Corridor H0203 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 2 - West Corridor H0203 N/A Y Coordinate: N/A Signage
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 2 - West Corridor H0203 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 2 - West Corridor H0203 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 2 - West Corridor H0203 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 At interior or exterior location, no tactile characters at sign identifying permanent rooms and
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 2 - West Corridor H0203 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 2 - West Corridor H0203 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces No tactile signage provided at doors within public route Provide accessible signs
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 2 - West Corridor H0203 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces No tactile signage provided at doors within public route Provide accessible signs 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 28B
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - West Corridor H0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-3/4" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 28C
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - West Corridor H0203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Pamphlet holder 51-1/2" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	Daylord Data Data Data Deminuth Day
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 29A
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Computer Graphics Education Lab 244
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	At interior or exterior location, no tactile characters at sign identifying permanent rooms and spaces
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	
Notes: Lab 024	4
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 29B
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Computer Graphics Education Lab 244
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	14 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 29C
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Computer Graphics Education Lab 244
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Door Closer - Sweep
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	3 second sweep
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 29D
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Computer Graphics Education Lab 244
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Door Threshold (Replace)
Code References:	2010 ADAS 404.2.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate threshold height exceeds 1/2"
Findings:	3/4" high. Threshold not firm and stable
Rec. Solution:	Provide new door threshold
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 29E
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Computer Graphics Education Lab 244
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Door Clearance - Min. 60" Perpendicular
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door lacks min. 60" perpendicular to door swing at pull side
Findings:	Desk and stored items block clear space perpendicular to door
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Remove	stored items to provide clearance
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 29F
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 29F Batcheller Hall Reference Dwg: 4 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Computer Graphics Education Lab 244
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Computer Graphics Education Lab 244 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Computer Graphics Education Lab 244 N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Computer Graphics Education Lab 244 N/A Y Coordinate: N/A Classrooms Electrical Switches - High Unobstructed 2010 ADAS 308.2.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Computer Graphics Education Lab 244 N/A Y Coordinate: N/A Classrooms Electrical Switches - High Unobstructed 2010 ADAS 308.2.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Computer Graphics Education Lab 244 N/A Y Coordinate: N/A Classrooms Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Computer Graphics Education Lab 244 N/A Y Coordinate: N/A Classrooms Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Computer Graphics Education Lab 244 N/A Y Coordinate: N/A Classrooms Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 54-3/4" high. Stored elements block electrical switch clear floor space Relocate switch box top edge to max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Computer Graphics Education Lab 244 N/A Y Coordinate: N/A Classrooms Electrical Switches - High Unobstructed 2010 ADAS 308.2.1 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 54-3/4" high. Stored elements block electrical switch clear floor space Relocate switch box top edge to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 29G
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Computer Graphics Education Lab 244
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance of at least 27" high, 30" wide and 8" deep not provided underneath desk
Findings:	25-1/2" knee clearance. Wall blocks instructors desk clear floor space
Rec. Solution:	Reposition desk to provide knee clearance
Barrier Severity:	1 Necessary Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Instruct	ors desk
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 29H
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Computer Graphics Education Lab 244
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
	•
Performance Sta	ndard: No Quantity: EACH As-built : 1
Performance Sta Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Barrier	
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Barrier Description: Findings:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high Television protrudes 6" at 54" high Remove object or provide detectable warning (wing walls)
Barrier Description: Findings: Rec. Solution:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high Television protrudes 6" at 54" high Remove object or provide detectable warning (wing walls) 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 291
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Computer Graphics Education Lab 244
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Projector Screen Pull
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Screen pull not at max. 48" high for side reach
Findings:	Projector screen pull 101" high
Rec. Solution:	Relocate to max. 48" high or provide extension
Barrier Severity:	3 Hindrance Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 29J
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 29J Batcheller Hall Reference Dwg: 4 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Computer Graphics Education Lab 244
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Computer Graphics Education Lab 244 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Computer Graphics Education Lab 244 N/A Y Coordinate: N/A Clear Floor Space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Computer Graphics Education Lab 244 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" 2010 ADAS 403.5.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Computer Graphics Education Lab 244 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" 2010 ADAS 403.5.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Computer Graphics Education Lab 244 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" 2010 ADAS 403.5.1 Indard: No Quantity: LF As-built: 100
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Computer Graphics Education Lab 244 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" 2010 ADAS 403.5.1 Indard: No Quantity: LF As-built: 100 Circulation route not min. 36" wide between elements
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Computer Graphics Education Lab 244 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" 2010 ADAS 403.5.1 andard: No Quantity: LF As-built: 100 Circulation route not min. 36" wide between elements Passageway less than 36" in multiple locations Remodel to provide access
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 4 of 5 Floor 2 - Computer Graphics Education Lab 244 N/A Y Coordinate: N/A Clear Floor Space Passageway - Min. 36" 2010 ADAS 403.5.1 Indard: No Quantity: LF As-built: 100 Circulation route not min. 36" wide between elements Passageway less than 36" in multiple locations Remodel to provide access 1 Necessary Cost Est \$12,500.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 29K
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Computer Graphics Education Lab 244
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Actuator/Control - Side Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Printer 56-3/4 " high
Rec. Solution:	Relocate within accessible reach range
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 29L
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Computer Graphics Education Lab 244
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Ratio
Code References:	2010 ADAS 902
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	At least 1 desk or 5% of all desks not accessible
Findings:	Min. 1 accessible desk not provided
Rec. Solution:	Provide min. 2 accessible desks
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 24 com	·



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 29M
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Computer Graphics Education Lab 244
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Knee clearance of at least 27" high, 30" wide and 8" deep not provided underneath desk
Findings:	25-1/2" high knee clearance
Rec. Solution:	Provide min. 2 accessible desks
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 24 comp	outer workstations. None are accessible
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 29N
Bldg Name:	Batcheller Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Computer Graphics Education Lab 244
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Classrooms
	Classrooms Alarm - Horn/Strobe
Barrier Area:	Classrooms
Barrier Area: Barrier Type: Code	Classrooms Alarm - Horn/Strobe 2010 ADAS 702.1
Barrier Area: Barrier Type: Code References:	Classrooms Alarm - Horn/Strobe 2010 ADAS 702.1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Classrooms Alarm - Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Classrooms Alarm - Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 Where a fire alarm is installed, no horn/strobe provided
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Classrooms Alarm - Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 Where a fire alarm is installed, no horn/strobe provided No device provided Provide horn/strobe in sanitary facility
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Classrooms Alarm - Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 Where a fire alarm is installed, no horn/strobe provided No device provided Provide horn/strobe in sanitary facility 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 30A
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Stairway S0302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Protruding Hazard
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in route of travel between 27" and 80" high
Findings:	Electrical box has sharp edges at the top of the handrail
Rec. Solution:	Remove object or provide detectable warning
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 30B
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S0302
_	
Location:	Floor 3 - Stairway S0302
Location: X Coordinate:	Floor 3 - Stairway S0302 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 3 - Stairway S0302 N/A Y Coordinate: N/A Stairways
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 3 - Stairway S0302 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Level ICC A117.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 3 - Stairway S0302 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Level ICC A117.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 3 - Stairway S0302 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Level ICC A117.1 Indard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 3 - Stairway S0302 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Level ICC A117.1 Indard: No Quantity: EACH As-built: 1 Tactile stairway signage not provided to indicate floor level
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 3 - Stairway S0302 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Level ICC A117.1 Indard: No Quantity: EACH As-built: 1 Tactile stairway signage not provided to indicate floor level No sign provided Provide accessible sign
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 3 - Stairway S0302 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Level ICC A117.1 Indard: No Quantity: EACH As-built: 1 Tactile stairway signage not provided to indicate floor level No sign provided Provide accessible sign 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 30C
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Stairway S0302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Sign - Exit Door
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built : 1
Barrier Description:	Door leading directly into an exit stairway lacks tactile exit sign
Findings:	Door to exit stair with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT STAIR DOWN (or UP)" at latch side of door
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 30D
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Stairway S0302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Door Closer - Interior Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	14 lbf
Rec. Solution:	
Barrier Severity:	Replace or adjust existing closer
Implementation	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 30E
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Stairway S0302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Door Closer - Interior Sweep ADA
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	3 second sweep
Rec. Solution:	Replace closer or provide automatic door opener
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: 2 entry	doors
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 30F
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 30F Batcheller Hall Reference Dwg: 5 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S0302
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S0302 N/A Y Coordinate: N/A Stairways Door Hardware - Operation
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S0302 N/A Y Coordinate: N/A Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S0302 N/A Y Coordinate: N/A Stairways Door Hardware - Operation 2010 ADAS 404.2.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S0302 N/A Y Coordinate: N/A Stairways Door Hardware - Operation 2010 ADAS 404.2.7
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S0302 N/A Y Coordinate: N/A Stairways Door Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S0302 N/A Y Coordinate: N/A Stairways Door Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 2 Hardware not operable with a closed fist
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S0302 N/A Y Coordinate: N/A Stairways Door Hardware - Operation 2010 ADAS 404.2.7 ndard: No Quantity: EACH As-built: 2 Hardware not operable with a closed fist Hardware not accessible
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S0302 N/A Y Coordinate: N/A Stairways Door Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 2 Hardware not operable with a closed fist Hardware not accessible Replace hardware 1 Necessary Cost Est \$600.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 30G
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Stairway S0302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobes in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 31A
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 31A Batcheller Hall Reference Dwg: 5 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Waiting Room L0350
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Waiting Room L0350 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Waiting Room L0350 N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Waiting Room L0350 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Waiting Room L0350 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Waiting Room L0350 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Waiting Room L0350 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 4 No tactile characters at sign identifying permanent rooms and spaces with visual signs
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Waiting Room L0350 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 4 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at doors within public route Provide accessible signs
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Waiting Room L0350 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 4 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at doors within public route Provide accessible signs 1 Necessary Cost Est \$1,000.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 31B
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Waiting Room L0350
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	19 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 31C
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Waiting Room L0350
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	4 second sweep
Findings: Rec. Solution:	4 second sweep Provide automatic door opening device
Rec. Solution:	
Rec. Solution:	Provide automatic door opening device 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 31D
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Waiting Room L0350
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Door Stop
Code References:	2010 ADAS 404.2.10
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door stop interrupts min. 10" smooth bottom surface
Findings:	Door stop at bottom of door can create trapping condition
Rec. Solution:	Remove door stop or other element at bottom of door at push side
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 31E
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Waiting Room L0350
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 31F
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Waiting Room L0350
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 603.4
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	65-1/2" high
Rec. Solution:	Provide additional hook in new location
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 31G
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Waiting Room L0350
Location:	Floor 3 - Waiting Room L0350
Location: X Coordinate:	Floor 3 - Waiting Room L0350 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 3 - Waiting Room L0350 N/A Y Coordinate: N/A Alarms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 3 - Waiting Room L0350 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 3 - Waiting Room L0350 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 3 - Waiting Room L0350 N/A Alarms Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 3 - Waiting Room L0350 N/A Alarms Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in corridor
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 3 - Waiting Room L0350 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in corridor No device provided Provide strobes in common use area
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 3 - Waiting Room L0350 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in corridor No device provided Provide strobes in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 32A
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Corridor H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 4
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at doors within public route
Rec. Solution:	Provide accessible signs
Barrier Severity:	1 Necessary Cost Est \$1,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Rooms 3	352, 349, 345, 344
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 32B
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 32B Batcheller Hall Reference Dwg: 5 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Corridor H0301
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Corridor H0301 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Corridor H0301 N/A Y Coordinate: N/A Counters and Tables
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Corridor H0301 N/A Y Coordinate: N/A Counters and Tables Table - Pedestal Base 2010 ADAS 306.2.2 and 306.2.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Corridor H0301 N/A Y Coordinate: N/A Counters and Tables Table - Pedestal Base 2010 ADAS 306.2.2 and 306.2.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Corridor H0301 N/A Y Coordinate: N/A Counters and Tables Table - Pedestal Base 2010 ADAS 306.2.2 and 306.2.3 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Corridor H0301 N/A Y Coordinate: N/A Counters and Tables Table - Pedestal Base 2010 ADAS 306.2.2 and 306.2.3 Indard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Corridor H0301 N/A Y Coordinate: N/A Counters and Tables Table - Pedestal Base 2010 ADAS 306.2.2 and 306.2.3 Indard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide Pedestal base at table blocks knee clearance Provide min. 1 accessible table. Avoid pedestal base tables.
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Corridor H0301 N/A Y Coordinate: N/A Counters and Tables Table - Pedestal Base 2010 ADAS 306.2.2 and 306.2.3 Indard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide Pedestal base at table blocks knee clearance Provide min. 1 accessible table. Avoid pedestal base tables. 2 Recommended Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 32C
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Corridor H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Fire riser protrudes 8" at 57-1/4" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 32D
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Corridor H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Electrical box protrudes 6-1/4" at 48" high
Rec. Solution:	
	Remove object or provide detectable warning (wing walls)
Barrier Severity:	
Barrier Severity: Implementation	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 32F
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Corridor H0301
X Coordinate:	N/A Y Coordinate: N/A Energy/Efficiency Center
Barrier Area:	Signage
Barrier Type:	Viewing From Distance - >70" high
Code References:	2010 ADAS 703.5.5 and Table 703.5.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Signs between 70" and 120" high lack characters at least 2" high
Findings:	Characters on sign not large enough to view from a distance at 3/4" high
Rec. Solution:	Replace sign with characters min. 2" in height for viewing at a distance
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Room 3	44 Not a protrusion
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 32G
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Corridor H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull 03/07/2014 11:41
Code References:	2010 ADAS 309.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Fire pull has no usable hardware
Findings:	Fire pull not fist operable
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 32H
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Corridor H0301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull 03/07/2014 11:41
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Fire pulls not between 42" and 48" high
Findings:	66-1/4" high
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 321
Dida Nasa.	
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Reference Dwg: 5 of 5 Floor 3 - Corridor H0301
Location:	Floor 3 - Corridor H0301
Location: X Coordinate:	Floor 3 - Corridor H0301 N/A Y Coordinate: N/A Alarms Horn/Strobe
Location: X Coordinate: Barrier Area:	Floor 3 - Corridor H0301 N/A Y Coordinate: N/A Alarms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 3 - Corridor H0301 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 3 - Corridor H0301 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 3 - Corridor H0301 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1 andard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 3 - Corridor H0301 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1 andard: No Quantity: EACH As-built: 1 No horn/strobes in corridor
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 3 - Corridor H0301 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1 andard: No Quantity: EACH As-built: 1 No horn/strobes in corridor No strobe provided Provide strobes in common use area
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 3 - Corridor H0301 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1 Andard: No Quantity: EACH As-built: 1 No horn/strobes in corridor No strobe provided Provide strobes in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 33A
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Workroom 342
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: This roo	m also serves as an emergency exit by way of stairs
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 33B
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 33B Batcheller Hall Reference Dwg: 5 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Clear Floor Space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 304.3.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 304.3.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 304.3.1 ndard: No Quantity: SF As-built: 80
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 304.3.1 ndard: No Quantity: SF As-built: 80 Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 304.3.1 ndard: No Quantity: SF As-built: 80 Clear floor space of min. 60" in diameter not provided where 360 degree turn is made Stairway blocks 60" turning circle Remodel area to provide min. 60" turning space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 304.3.1 ndard: No Quantity: SF As-built: 80 Clear floor space of min. 60" in diameter not provided where 360 degree turn is made Stairway blocks 60" turning circle Remodel area to provide min. 60" turning space 2 Recommended Cost Est \$14,000.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 33C
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Workroom 342
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	14-3/4" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 33D
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 33D Batcheller Hall Reference Dwg: 5 of 5
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Door Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Door Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Door Performance Standard Indard: Yes Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Door Performance Standard Indard: Yes Quantity: EACH As-built: 1 Door leading directly into an exit stairway lacks tactile exit sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Door Performance Standard mdard: Yes Quantity: EACH As-built: 1 Door leading directly into an exit stairway lacks tactile exit sign Door to exit stair with low level illuminated sign lacks tactile exit sign Provide sign stating "EXIT STAIR UP" at latch side of door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Door Performance Standard ndard: Yes Quantity: EACH As-built: 1 Door leading directly into an exit stairway lacks tactile exit sign Door to exit stair with low level illuminated sign lacks tactile exit sign Provide sign stating "EXIT STAIR UP" at latch side of door 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 33E
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Workroom 342
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail - Both Sides
Code References:	ADAAG 4.9.4* & 2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built : 8
Barrier Description:	No handrail provided at both sides of stairway
Findings:	No handrail provided at both sides
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$1,800.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 33F
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342
Location:	Floor 3 - Workroom 342
Location: X Coordinate:	Floor 3 - Workroom 342 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 3 - Workroom 342 N/A Y Coordinate: N/A Stairways
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 3 - Workroom 342 N/A Y Coordinate: N/A Stairways Riser Height - Existing 2010 ADAS 504.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 3 - Workroom 342 N/A Y Coordinate: N/A Stairways Riser Height - Existing 2010 ADAS 504.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 3 - Workroom 342 N/A Stairways Riser Height - Existing 2010 ADAS 504.2 Indard: No Quantity: SF As-built: 30
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 3 - Workroom 342 N/A Stairways Riser Height - Existing 2010 ADAS 504.2 Indard: No Quantity: SF As-built: 30 Stair riser height is not between 4" and 7"
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 3 - Workroom 342 N/A Y Coordinate: N/A Stairways Riser Height - Existing 2010 ADAS 504.2 Indard: No Quantity: SF As-built: 30 Stair riser height is not between 4" and 7" 8-1/2" stair riser height Demolish and construct new stairway
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 3 - Workroom 342 N/A Y Coordinate: N/A Stairways Riser Height - Existing 2010 ADAS 504.2 Indard: No Quantity: SF As-built: 30 Stair riser height is not between 4" and 7" 8-1/2" stair riser height Demolish and construct new stairway 4 Low Severity Cost Est \$7,500.00 Facility Function: Public Status: Open



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 33G				
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5				
Location:	Floor 3 - Workroom 342				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Stairways				
Barrier Type:	Tread Depth - Existing				
Code References:	2010 ADAS 504.2				
Performance Sta	ndard: No Quantity: SF As-built : 0				
Barrier Description:	Stair treads are not at least 11" in depth				
Findings:	10-1/4" stair treads depth				
Rec. Solution:	Demolish and construct new stairway				
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open				
Implementation	Priority: 3 Implementation Phase: Implementation Date:				
Notes:					
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 33H				
	3/4/2014 Report Date 3/6/2014 Barrier #: 33H Batcheller Hall Reference Dwg: 5 of 5				
Bldg Name:					
Bldg Name: Location:	Batcheller Hall Reference Dwg: 5 of 5				
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342				
Field Date: Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A				
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Stairways				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 Indard: Yes Quantity: LF or TR As-built: 8				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 Indard: Yes Quantity: LF or TR As-built: 8 No contrasting color on each tread of interior stairway				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 Indard: Yes Quantity: LF or TR As-built: 8 No contrasting color on each tread of interior stairway Treads lack contrasting color defined as 70% contrast Recommended: Consider providing contrasting color on each tread				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 Indard: Yes Quantity: LF or TR As-built: 8 No contrasting color on each tread of interior stairway Treads lack contrasting color defined as 70% contrast Recommended: Consider providing contrasting color on each tread 2 Recommended Cost Est \$280.00 Facility Function: Public Status: Open				



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 33I					
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5					
Location:	Floor 3 - Workroom 342					
X Coordinate:	N/A Y Coordinate: N/A					
Barrier Area:	Stairways					
Barrier Type:	Surface Condition - Existing					
Code References:	2010 ADAS 504.4					
Performance Sta	ndard: No Quantity: SF As-built : 0					
Barrier Description:	Stairway surface is not slip resistant					
Findings:	Slip resistant surface could not be verified					
Rec. Solution:	Demolish and construct new stairway					
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open					
Implementation	Priority: 3 Implementation Phase: Implementation Date:					
Notes:						
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 33J					
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5					
Location:	Floor 3 - Workroom 342					
X Coordinate:	N/A Y Coordinate: N/A					
Barrier Area:	Classrooms					
Barrier Type:	Counter - Surface					
Code References:	2010 ADAS 902					
Performance Sta	ndard: No Quantity: EACH As-built : 1					
Barrier Description:	Counter surface height exceeds 34" high					
Findings:	36" high					
Rec. Solution:	Replace or provide alternative accessible and integrated counter					
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open					
Implementation						
Notes: Stairway	y blocks sink and counter clear floor space					



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 33K				
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5				
Location:	Floor 3 - Workroom 342				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Counters and Tables				
Barrier Type:	Counter - Knee Clearance				
Code References:	2010 ADAS 305.3				
Performance Sta	ndard: No Quantity: EACH As-built : 0				
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide				
Findings:	No knee clearance				
Rec. Solution:	Replace counter. Flip-up counters, adiacent tables and similar devices not permitted				
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open				
Implementation	Priority: 2 Implementation Phase: Implementation Date:				
Notes:					
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 33L				
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 33L Batcheller Hall Reference Dwg: 5 of 5				
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5				
Bldg Name: Location:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342				
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A				
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Controls and Mechanisms				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Forward Reach Obstructed (≤10") 2010 ADAS 308.2				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Forward Reach Obstructed (≤10") 2010 ADAS 308.2				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Forward Reach Obstructed (≤10") 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Forward Reach Obstructed (≤10") 2010 ADAS 308.2 Indard: No Quantity: EACH As-built : 1 Outlet located over an obstruction max. 34" high located above 48"				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Forward Reach Obstructed (≤10") 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1 Outlet located over an obstruction max. 34" high located above 48" 42-1/2 " high over counter obstruction 24" deep Relocate control or mechanism to max. 48" high				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Forward Reach Obstructed (≤10") 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1 Outlet located over an obstruction max. 34" high located above 48" 42-1/2 " high over counter obstruction 24" deep Relocate control or mechanism to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open				



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 33M				
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5				
Location:	Floor 3 - Workroom 342				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Classrooms				
Barrier Type:	Sink Faucet - Operation				
Code References:	2010 ADAS 606.4 & 309				
Performance Sta	ndard: No Quantity: EACH As-built : 1				
Barrier Description:	Faucets force to activate controls is greater than 5 pounds-force lbf (22.2 N).				
Findings:	15 lbf				
Rec. Solution:	Replace faucet				
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open				
Implementation	Priority: 2 Implementation Phase: Implementation Date:				
Notes:					
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 33N				
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5				
Location:	Floor 3 - Workroom 342				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Classrooms				
Barrier Type:	Sink - Depth				
Code References:	Performance Standard				
Performance Sta	ndard: Yes Quantity: EACH As-built: 1				
Barrier Description:	Sink depth exceeds 6-1/2" deep				
Findings:	7" deep				
Rec. Solution:	Replace sink				
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open				
Implementation					
Notes:					



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 330				
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5				
Location:	Floor 3 - Workroom 342				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Classrooms				
Barrier Type:	Sink - Knee Clearance				
Code References:	2010 ADAS 606.2 & 306				
Performance Sta	indard: No Quantity: EACH As-built : 0				
Barrier Description:	Knee clearance of at least 30" wide and 8" deep at 27" high with 11" depth at 9" high				
Findings:	No knee clearance				
Rec. Solution:	Provide min. 3 ft of accessible counter at each type of workstation in room				
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open				
Implementation	Priority: 2 Implementation Phase: Implementation Date:				
Notes:					
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 33P				
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 33P Batcheller Hall Reference Dwg: 5 of 5				
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5				
Bldg Name: Location:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342				
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A				
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground Shelf or cabinet not accessible Provide additional shelf at accessible height or provide assistance				
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Workroom 342 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground Shelf or cabinet not accessible Provide additional shelf at accessible height or provide assistance 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open				



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 34A					
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5					
Location:	Floor 3 - Conference Room 341 N/A Y Coordinate: N/A					
X Coordinate:						
Barrier Area:	Signage					
Barrier Type:	Permanent Room/Space - Tactile Characters					
Code References:	2010 ADAS 216.2					
Performance Sta	ndard: No Quantity: EACH As-built : 1					
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs					
Findings:	No tactile signage provided at door within public route					
Rec. Solution:	Provide accessible sign					
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open					
Implementation	Priority: 3 Implementation Phase: Implementation Date:					
Notes:						
· · · · · · · · · · · · · · · · · · ·						
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 34B					
Field Date: Bldg Name:	3/4/2014 Report Date 3/6/2014 Barrier #: 34B Batcheller Hall Reference Dwg: 5 of 5					
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5					
Bldg Name: Location:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 341					
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 341 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door					
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 341 N/A Y Coordinate: N/A Doors or Gates					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 341 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 341 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 341 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 341 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 341 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 16 lbf					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 341 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 16 lbf Provide automatic door opening device 1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open					



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 34C					
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5					
Location:	Floor 3 - Conference Room 341					
X Coordinate:	N/A Y Coordinate: N/A					
Barrier Area:	Doors or Gates					
Barrier Type:	Door Closer - Interior Sweep Period					
Code References:	2010 ADAS 404.2.8.1					
Performance Sta	ndard: No Quantity: EACH As-built : 0					
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame					
Findings:	3 second sweep					
Rec. Solution:	Provide automatic door opening device					
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open					
Implementation	Priority: 2 Implementation Phase: Implementation Date:					
Notes:						
·						
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 34D					
	3/4/2014 Report Date 3/6/2014 Barrier #: 34D Batcheller Hall Reference Dwg: 5 of 5					
Bldg Name:						
Bldg Name: Location:	Batcheller Hall Reference Dwg: 5 of 5					
Bldg Name: Location: X Coordinate:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 341					
Field Date: Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 341 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 341 N/A Y Coordinate: N/A Doors or Gates					
Bldg Name: Location: X Coordinate: Barrier Area:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 341 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 341 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 341 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 341 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 341 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not accessible Provide new hardware					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Batcheller Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 341 N/A Y Coordinate: N/A Doors or Gates Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not accessible Provide new hardware 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open					



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 34E					
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5					
Location:	Floor 3 - Conference Room 341					
X Coordinate:	N/A Y Coordinate: N/A					
Barrier Area:	Doors or Gates					
Barrier Type:	Vision Lights - Existing					
Code References:	2010 ADAS 404.2.11					
Performance Sta	ndard: No Quantity: EACH As-built : 1					
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground					
Findings:	View panel located higher than 43" above the floor					
Rec. Solution:	Replace door/gate or vision panel					
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open					
Implementation	Priority: 2 Implementation Phase: Implementation Date:					
Notes: At 48" h	igh					
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 34F					
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5					
Location:	Floor 3 - Conference Room 341					
X Coordinate:	N/A Y Coordinate: N/A					
Barrier Area:	Controls and Mechanisms					
Barrier Type:	Electrical Switches - Height					
Code References:	2010 ADAS 308.2					
Performance Sta	ndard: No Quantity: EACH As-built : 1					
Barrier Description:	Light switch control box top edge not at max. 48" high					
Findings:	49-3/4" high					
Rec. Solution:	Relocate switch box top edge to max. 48" high					
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open					
Implementation	Priority: 2 Implementation Phase: Implementation Date:					
Notes:						



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 34G				
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5				
Location:	Floor 3 - Conference Room 341				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Clear Floor Space				
Barrier Type:	Passageway - Min. 36" (Stored Item)				
Code References:	2010 ADAS 403.5.1				
Performance Sta	andard: No Quantity: JOB As-built : 1				
Barrier Description:	Circulation route not min. 36" wide between elements				
Findings:	Passageway less than 36" in multiple locations				
Rec. Solution:	Rearrange furniture or replace to provide access to whiteboard, etc.				
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open				
Implementation	Priority: 2 Implementation Phase: Implementation Date:				
Notes: 27" - 35	" wide circulation route around table				
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 34H				
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5				
Location:	Floor 3 - Conference Room 341				
X Coordinate:	N/A Y Coordinate: N/A				
Barrier Area:	Counters and Tables				
Barrier Type:	Table - Knee Clearance				
Code References:	2010 ADAS 305.3				
Performance Sta	andard: No Quantity: EACH As-built : 1				
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide				
e					
Findings:	26" high knee clearance. Walls block table and easel clear floor space				
Rec. Solution:	26" high knee clearance. Walls block table and easel clear floor space Provide min. 1 accessible table				
J	Provide min. 1 accessible table				
Rec. Solution:	Provide min. 1 accessible table 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open				



Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 34I
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Conference Room 341
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Assembly Areas
Barrier Type:	Shared Assistive Listening System
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	No shared assistive listening system for room with min. 10 seats
Findings:	No device identified durning investigation
Rec. Solution:	Provide shared ALS system
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/4/2014 Report Date 3/6/2014 Barrier #: 34J
Bldg Name:	Batcheller Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Conference Room 341
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Meeting Room
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in meeting room
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	





SUMMARY REPORT

Cost Estimate Total	\$1,857,610.00		
Cost Estimate - Priority 1:	\$1,410,575.00	% of Total Cost Estimate:	75.93%
Cost Estimate - Priority 2:	\$222,325.00	% of Total Cost Estimate:	11.97%
Cost Estimate - Priority 3:	\$224,710.00	% of Total Cost Estimate:	12.10%