SZS CONSULTING GROUP

OREGON STATE UNIVERSITY (OSU)

DEARBORN HALL

ADA ASSESSMENT & SURVEY



Sacramento Office 770 L Street, Suite 950 Sacramento, CA 95814 Tel: 916.669.8750 Fax: 888.211.7441

Silicon Valley Office 2225 E. Bayshore Road, Suite 200

Palo Alto CA 94303 Tel: 866.694.7637 www.szs-consulting.com

January 13, 2015



Angelo Gomez **Executive Director** Office of Equity and Inclusion Oregon State University 330 Snell Hall Corvallis, OR 97331-2128

Re: ADA Accessibility Survey and Assessment - Dearborn Hall

Dear Angelo,

We are pleased to submit this report for Dearborn Hall. This report is part of our project to provide a Campus Accessibility Survey and Assessment for Oregon State University. It is our hope that this report will assist OSU in improving access to people with disabilities to campus facilities.

SZS has been pleased to be a part of this effort to evaluate campus buildings using federal and state statutes and regulations, as well as universal design principles in order to create performance standards that will guide design, construction and maintenance on campus.

We look forward to discussing our findings with your team.

Regards,

Syroun Z. Sanossian, Principal

Syn 2. 8m.

SZS Consulting Group LLC

TABLE OF CONTENTS

1.	EXECUTIV	E SUMMARY OF FINDINGS	p. 1
	a.	Pedestrian Facilities and Exterior Spaces Analyzed	p. 2
	b.	Building Entrances	р. 3
2.	INTERIOR	SPACES	
		Basement	p. 3
		First Floor	p. 5
		Second Floor	p. 5
		Third Floor	p. 6
3.	BARRIEF	R DATA RECORDS	
		Exterior Area Barriers	p. 7
		Interior Area Barriers	p. 16
		Cost Estimate	p. 349

1. EXECUTIVE SUMMARY OF FINDINGS

The field investigation for the interior spaces began on February 25, 2014. The exterior site elements were assessed originally as part of the pedestrian facilities assessment in June-September 2011 and are included as an essential part of this report. Images of each physical element identified in this report were captured in HD digital photos while manual measurements were taken to establish as-built conditions to facilitate the process of cost estimating. Digital photographs are provided within the report for each barrier to access, to facilitate the review of the data collected. We have found that technical data can be difficult to interpret without a visual component; the photos provide a clear connection between the technical data and each barrier to access.

Dearborn Hall is considered a historic structure and many barriers to access were identified in the building. That is quite typical, as barriers to access exist in virtually every building, whether new or existing.

No "perfect" building exists in the real world.

This ADA Assessment and Survey report is intended to not only identify barriers to access, but to provide solutions. The basis for this ADA Assessment and Survey process is the underlying desire on the part of OSU to improve access by relying on higher standards than the minimum requirements in state and federal building codes. SZS intends to provide the information in this report in a clear and easy to understand format. The information in this report is compiled for use by designated OSU staff and other interested persons, so the content is designed to be understood by professionals and laymen alike.

The findings presented are both narrative and technical in nature; barriers to access identified during the field investigation process are documented in two ways;

Narrative Analysis: The analysis of findings is contained in an executive summary in a
narrative form that not only describes each type of barrier identified but also provides a
discussion that analyses the functionality of physical elements. We also provide the
reasoning and research behind the identification of barriers that conflict with universal
design principles. This analysis may be accompanied by digital photographs or
diagrams, where applicable.

NOTE: Understanding building function and usage is essential when interpreting the findings held in this report. The narrative is intended to facilitate this process.

2. <u>Barrier Data Records:</u> Individual barriers to access are entered into the SZS database so that technical information on the barriers can be provided as barrier data records. These barrier data records include digital photographs of each barrier identified, code references that determine the barrier to access, as-built measurements, barrier severity ratings, budgetary cost estimates, recommended solutions for barrier removal and a priority for barrier removal. The information is formatted with two barriers on each report page.

In order to consolidate the report data, some of the more typical barriers found in multiple locations have been grouped within the barrier data records with a description of the locations in which they were found.

A. Pedestrian Facilities and Exterior Spaces Analyzed

This report provides information on campus pedestrian facilities that serve Dearborn Hall. Many physical elements are part of the comprehensive whole that creates a pedestrian facility. The fundamental elements evaluated as to whether they provide accessible pedestrian facilities include the following:

- Sidew alks
- Walkways
- Ramps
- Curb Ramps
- Blended Transitions
- Signalized Intersections
- Stairw ays (94% of people with disabilities are not mobility impaired)
- Benches and other Seating Elements
- Picnic Facilities

The descriptions provided for physical elements in this report are intended to clearly describe the differences between each physical element, such as when a pedestrian route is a sidewalk, rather than a walkway. The descriptions are intended to explain how the elements interact to form a cohesive pedestrian facility. Other more specific information described within this section intends to provide guidance on determinations made in this report.

The key to providing accessible pedestrian facilities is in recognizing that different people with disabilities have different needs. Setting policies that speak to the entire group is essential, rather than focusing one particular subset of the overall group. Universal design principles govern here — physical elements should be usable to everyone that visits campus without having to resort to any adaptation or specialized design.

In summary, an accessible route exists within a building, property boundary or interior space and is separate from the PROW. Pedestrian walkways are similar to sidewalks as paved surfaces improved for use by pedestrians but walkways are not located along or adjacent to the curb line, gutter or roadway and walkways are generally not considered part of the PROW. The pedestrian facility is the combination of the PROW and the accessible route, which functions as a whole to provide pedestrian access to facility entrances.

As a public building governed by the ADA Standards, Dearborn Hall should have at least one accessible entrance. An accessible grade level entrance was identified at the northeast corner of the building. No direct access is provided to this building. The connection to this entrance can only be made by pedestrians who travel from SW Monroe Avenue or SW Campus Way by travelling around several other buildings. The building entrance along SW Campus Way currently provides vertical access by way of stairs. It is recommended to provide vertical access at that location by installing a special access lift (wheelchair lift).

Dearborn Hall has a lengthy connection to the accessible route within campus from the site to accessible parking spaces and accessible passenger loading zones; public streets and sidewalks; and public transportation stops to the accessible building or facility entrance they serve as compared to the 2010 ADA Standard for Accessible Design. Details on barriers identified in that route are provided within the ADA Assessment and Survey of the pedestrian facilities provided as a separate report, as well as in the following records. Please see the barrier data records for details.

B. Building Entrances

The building is located along SW Campus Drive within campus. The building is located west of a staff and faculty parking lot, but a stairway is the only direct connection to the parking lot to the building. Pedestrian entrances to the building are provided by way of a ramp and stairway on the east side of the building, a stairway on the south side of the building and a grade level entrance on the northeast corner of the building on the first floor. The first floor central corridor was identified with an automatic door opening device located at the northeast corridor entrance. ISA directional signage is necessary at other stairway or ramped entrances.

INTERIOR SPACES

BASEMENT

Dearborn Hall is a three-story building with a basement. The building is a historic structure that has retained many of the original doors, stairways flooring and other elements, although some areas have been remodeled. The basement houses classrooms, labs a conference room and offices. The only restroom provided on this level is a non-accessible men's restroom. An elevator provides vertical access through the building.

Barriers identified in these spaces were identified throughout the building in common use areas and include original historic entrance doors that lacked accessible signage, door hardware, door closer operating force/sweep period where door closers were installed and doors with view panels lacked panels that were accessible to short people or wheelchair users. In some instances, entry doors lacked accessible maneuvering clearance as either a result of the original design or due to the location of furniture or other items that encroached into the space needed by wheelchair users to maneuver.

The lack of accessible maneuvering clearance may necessitate the installation of automatic door opening devices at entrance doors to classrooms or offices even in instances where door closers are not provided. In many cases, light switches and outlets were not located within accessible reach range. In some instances, in classrooms and offices, the clear floor space needed to enable use of whiteboards and chalkboards was blocked by furniture or stored items.

.

¹ 2010 ADA Standards for Accessible Design, Section 206.2.1 Site Arrival Points

Most signage in the building provided visual information but lacked tactile information (Braille and raised letters) for the visually impaired. In some common use areas, visual signal appliances (strobes) were not provided to alert the hearing impaired during an emergency. Fire alarm actuators (fire pulls) appeared to be original to the building. The actuators were identified outside of accessible reach range and did not appear to be fist operable for people with hand impairments. That group of people with disabilities is one of the largest groups, as it includes the elderly as well as many people with other mobility issues.

The building has an elevator to provide vertical access to all floors. The elevator lacked accessible signage on door jambs indicating floor level, or discharge level. Other barriers to access identified at the elevator include a lack of accessible door jamb signs (no raised star for discharge level and height accessible), hall call buttons that were not at an accessible height and that did not illuminate for those with visual impairments, no audible signals were provided and the emergency communication system provided necessitated the ability to have voice communication by using a handset to call for help, which is prohibited by the ADA Standards and ASME Standards, as it prevents use by people with speech impairments.

Stairways in the building appeared to have original handrails that lacked accessible extensions and grip height and appeared to lack slip resistant surfaces. Doors in stairway entrances were not identified as accessible and lacked accessible view panels and opening force. Tactile exit signs indicating where doors lead to exits, including exit stairways are also recommended in this building. The stairways lacked level identification signage for the visually impaired and no contrasting color was identified at the stairway treads which can be important to those with low vision. As a performance standard, it is highly recommended to provide contrasting color at stairway treads to improve visibility for all users. An exit door within the central stairway lead directly to the exterior but there was no door landing and the exit path consisted of a significant drop to the grade level ground. Although this exit is not part of an accessible route, it may be used by people with disabilities who do not have mobility impairments.

Two original drinking fountains were provided in the basement corridors and neither fixture was wheelchair accessible. A men's multi-accommodation restroom was provided, but no women's restroom was provided on this floor. The restroom lacked accessible signage and an entry door wide enough to allow a person using a wheelchair to enter. The paper towel dispenser also protruded into the circulation path and other dispensers were not accessible. The toilet room lacked an accessible lavatory or urinal and the toilet stall lacked adequate clear width or maneuvering clearance to allow a wheelchair user to enter or transfer. The room also lacked a strobe device. Accessible fixtures were not provided inside the toilet room although adequate square footage exists to remodel and provide access.

Since there is only one type of restroom provided on this floor of the building, it is recommended to include locations for gender-specific restrooms on lobby informational signage posted at entrances to the building or in each lobby area. As a performance standard, it is recommended that lobby identification signage be provided on each floor in each central corridor that indicates the floor plan, the location of the person viewing the sign and the location of accessible features such as restrooms, elevator and drinking fountains in proximity to the location of the person reading the sign. Although the accessible features provided in the building are located in the central corridor, people with low vision may benefit from the information provided within the recommended lobby identification sign.

Many staff use only areas were identified in the building. These spaces include workrooms, laboratories, janitorial rooms, private faculty offices and associated spaces. Signage at the

door/doorway to these spaces was included in this report as it is located along the public circulation route of travel, but these interior spaces were not investigated as part of this assessment process. In general, institutions and organizations make staff-use-only areas accessible as needed through the reasonable accommodation process between the employer and employee.

FIRST FLOOR

The first floor provides classrooms, offices and teaching labs. The central corridor provides an accessible entrance from the northeast exterior walkway that travels through the building, as well as from Roger Hall. The south entrance provides pedestrian access to the building by way of stairs. Two drinking fountains are located in the central corridor and although only one is a hi-low fixture, both fixtures provide accessible knee clearance for people who use wheelchairs or for short people. Automatic door opening devices are installed at the entry doors from the exterior corridor that travels through the building and connects adjacent buildings to a shared parking lot.

The COE Helpdesk Room 120A, COE Computer Lab Room 119 and several teaching labs were located on this floor. Classroom 118 was identified as an auditorium with two entrances that were constructed with ramped pathways. No handrails were present and the floor surface did not appear to have slip-resistance. Other barriers noted in the auditorium were commonly identified in other teaching settings including non-accessible entry door signage, heavy entry doors or controls and mechanisms such as light switches, outlets, emergency phones and pencil sharpeners that were not in accessible locations or that were located outside of accessible reach ranges. Accessible desks, group tables or PC workstations were not provided in these spaces. The auditorium was designed with multiple levels that lacked an accessible desk on an accessible route from the entrance, although a desk identified with an ISA sign was placed on the upper level of seating. The instructional area was identified with a podium that lacked accessible knee clearance and surface height. Horns or strobes were not identified in the classrooms or restrooms on this floor.

Men and women's accessible restrooms were provided on this floor. The restrooms appeared to have been remodeled recently and were provided with automatic door opening devices, although the device at the men's restroom did not function properly. Minor barriers to access are noted in the barrier data records following this introduction.

The elevator on this floor was identified with non-accessible door jamb signage. Stairways on this level were historic in nature and were identified with the same barriers as described above. Corridors in the first floor were also identified with a lack of accessible signs, including lobby informational signs and information to describe visual elements on display to people with vision impairments. Fire extinguishers and electrical outlets in the corridors were not identified as accessible.

SECOND FLOOR

The second floor houses several teaching labs with raised floors. When the floors were raised, ramps were constructed but those ramps lack adequate maneuvering clearance at the entry door landing that would enable people using wheelchairs to change directions at 90 degrees. The ramps also lacked handrails and the slope of the ramps was not accessible. At some teaching labs on this floor, 2 entrances are provided and one is connected with a ramp where the other door leads to stairs. In these locations, an ISA directional sign is needed to inform people of which entry

door is accessible and which is not. In addition, the non-accessible ramp located at the entrance designated as accessible must be altered to provide access. Accessible desks and other elements were also lacking in these classrooms.

Men and women's non-accessible restrooms are located within the central corridor on this floor. These restrooms lacked accessible signage and an entry door wide enough to allow a person using a wheelchair to enter. The paper towel dispensers also protruded into the circulation path and other dispensers were not accessible. The toilet rooms lacked an accessible lavatory (or urinal in the men's room) and the toilet stall lacked adequate clear width or maneuvering clearance to allow a wheelchair user to enter or transfer. The room also lacked a strobe device. Accessible fixtures were not provided inside the toilet room although adequate square footage exists to remodel and provide access.

Barriers identified in corridors, conference rooms and teaching labs on the second floor are similar to those described above in the basement level.

THIRD FLOOR

This floor is primarily a staff use area although one teaching lab, a conference room and the MIME Workroom located on the floor are considered public use. A non-accessible multi-accommodation men's restroom and janitor's room used by the public were identified on the third floor. Barriers identified in those spaces were identical to those described above including non-accessible signage, narrow entry doors, non-accessible door maneuvering clearance and non-accessible sinks.

Many rooms have adequate square footage to enable access but the spaces have been filled with furniture and desks that combine to hinder or prevent access. Interior spaces generally lacked accessible desks, coat hooks and maneuvering clearance in some cases. In some cases, existing furniture could be rearranged but in many cases, the existing furniture (desks, bookcases, file cabinets, etc.) must be exchanged for smaller versions or removed to ensure access.

The following barrier data records provide more detailed information on the barriers described above.





Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 254A
Bldg Name:	Dearborn Hall Reference Dwg: 1 of 5
Location:	Exterior - East Stairway Entry
X Coordinate:	7478954.088 Y Coordinate: 340822.009
Barrier Area:	Stairways
Barrier Type:	Handrail Height
Code References:	2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built : 0
Barrier Description:	Handrail grip measured at center not 34"- 38" high
Findings:	29" handrail grip height
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 254B
Bldg Name:	Dearborn Hall Reference Dwg: 1 of 5
Location:	Exterior - East Stairway Entry
X Coordinate:	7478954.088 Y Coordinate: 340822.009
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Bottom
Code References:	2010 ADAS 505.10.3
Performance Sta	ndard: No Quantity: LF As-built : 0
Barrier Description:	Extension not sloped for length of one tread beyond the last riser nosing
Findings:	Bottom handrail extension not min. one tread width
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 254C
Bldg Name:	Dearborn Hall Reference Dwg: 1 of 5
Location:	Exterior - East Stairway Entry
X Coordinate:	7478954.088 Y Coordinate: 340822.009
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code References:	2010 ADAS Advisory 504.4
Performance Sta	ndard: Yes Quantity: LF or TR As-built: 0
Barrier Description:	No contrasting color on each tread of exterior stairway
Findings:	Treads lack contrasting color defined as 70% contrast
Rec. Solution:	Recommended: Consider providing contrasting color on each tread
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 254D
Bldg Name:	Dearborn Hall Reference Dwg: 1 of 5
Location:	Exterior - East Stairway Entry
X Coordinate:	7478954.088 Y Coordinate: 340822.009
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Top
Code References:	2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built : 0
Barrier Description:	Top Handrail extension not parallel to ground/floor surface
Findings:	No top handrail extension provided
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 254E
Bldg Name:	Dearborn Hall Reference Dwg: 1 of 5
Location:	Exterior - East Stairway Entry
X Coordinate:	7478954.088 Y Coordinate: 340822.009
Barrier Area:	Stairways
Barrier Type:	Vertical Access - Directional Sign
Code References:	2010 ADAS 403.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	No form of vertical access provided at stairway to reach entry door or upper floors
Findings:	No information on alternate accessible entrance to building
Rec. Solution:	Provide directional sign leading to accessible entry
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 521A
Bldg Name:	Dearborn Hall Reference Dwg: 1 of 5
Location:	Exterior - East Stairway Entry 2
X Coordinate:	7478928.818 Y Coordinate: 340817.759
Barrier Area:	Stairways
Barrier Type:	Handrail Grip
Code References:	2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built : 0
Barrier Description:	Handrail grip is not continuous
Findings:	Handrail grip is not continuous
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 521B
Bldg Name:	Dearborn Hall Reference Dwg: 1 of 5
Location:	Exterior - East Stairway Entry 2
X Coordinate:	7478928.818 Y Coordinate: 340817.759
Barrier Area:	Stairways
Barrier Type:	Handrail Grip
Code References:	2010 ADAS 505.7
Performance Sta	andard: No Quantity: LF As-built : 0
Barrier Description:	Handrail diameter (OD) or gripping surface not between 1-1/4" to 2" or non-circular 4"-4.8"
Findings:	2-1/2" round handrail grip diameter
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 521C
Bldg Name:	Dearborn Hall Reference Dwg: 1 of 5
Location:	Exterior - East Stairway Entry 2
X Coordinate:	7478928.818 Y Coordinate: 340817.759
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code References:	2010 ADAS Advisory 504.4
Performance Sta	andard: Yes Quantity: LF or TR As-built: 0
Barrier Description:	No contrasting color on each tread of exterior stairway
Findings:	Treads lack contrasting color defined as 70% contrast
Rec. Solution:	Recommended: Consider providing contrasting color on each tread
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	2 recommended 300 200 150.00 1 amount Table 3 action Deci
mpiementation	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 521D
Bldg Name:	Dearborn Hall Reference Dwg: 1 of 5
Location:	Exterior - East Stairway Entry 2
X Coordinate:	7478928.818 Y Coordinate: 340817.759
Barrier Area:	Stairways
Barrier Type:	Vertical Access - Directional Sign
Code References:	2010 ADAS 403.1
Performance Sta	ndard: No Quantity: EACH As-built: 0
Barrier Description:	No form of vertical access provided at stairway to reach entry door or upper floors
Findings:	No information on alternate accessible entrance to building
Rec. Solution:	Provide directional sign leading to accessible entry
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 500A
Bldg Name:	Dearborn Hall Reference Dwg: 1 of 5
Location:	Exterior - South Stairway Entry
X Coordinate:	7478888.829 Y Coordinate: 340637.773
Barrier Area:	Stairways
Barrier Type:	Handrail - Both Sides
Code References:	2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built : 0
Barrier Description:	No handrail provided at both sides of stairway
Findings:	No handrail provided at both sides
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 500B
Bldg Name:	Dearborn Hall Reference Dwg: 1 of 5
Location:	Exterior - South Stairway Entry
X Coordinate:	7478888.829 Y Coordinate: 340637.773
Barrier Area:	Stairways
Barrier Type:	Riser Height - Existing
Code References:	2010 ADAS 504.2
Performance Sta	ndard: No Quantity: SF As-built : 0
Barrier Description:	Stair riser height or tread width is not consistent
Findings:	No consistent stair riser height or tread width provided
Rec. Solution:	Demolish and construct new stairway
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 500C
Bldg Name:	Dearborn Hall Reference Dwg: 1 of 5
Location:	Exterior - South Stairway Entry
X Coordinate:	7478888.829 Y Coordinate: 340637.773
Barrier Area:	Stairways
Barrier Type:	Vertical Access - Ramp
Code References:	2010 ADAS 403.1
Performance Sta	ndard: No Quantity: SF As-built : 0
Barrier Description:	No form of vertical access provided at stairway to reach upper floors
Findings:	No form of vertical access provided at stairway
Rec. Solution:	Provide a ramp to reach door landing
Barrier Severity:	
	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	




Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 500D
Bldg Name:	Dearborn Hall Reference Dwg: 1 of 5
Location:	Exterior - South Stairway Entry
X Coordinate:	7478888.829 Y Coordinate: 340637.773
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code References:	2010 ADAS Advisory 504.4
Performance Sta	andard: Yes Quantity: LF or TR As-built: 0
Barrier Description:	No contrasting color on each tread of exterior stairway
Findings:	No contrasting color provided
Rec. Solution:	Consider providing contrasting color on each tread
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 503A
Bldg Name:	Dearborn Hall Reference Dwg: 1 of 5
Location:	Exterior - West Stairway Entry
X Coordinate:	7478821.239 Y Coordinate: 340667.783
Barrier Area:	Stairways
Barrier Type:	Handrail Height
Code References:	2010 ADAS 505.10.2
Performance Sta	andard: No Quantity: LF As-built : 225
Barrier Description:	Handrail grip measured at center not 34"- 38" high
Findings:	32" handrail grip height
Rec. Solution:	Provide handrails at both sides of stairway
Rec. Solution: Barrier Severity:	
	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 503B
Bldg Name:	Dearborn Hall Reference Dwg: 1 of 5
Location:	Exterior - West Stairway Entry
X Coordinate:	7478821.239 Y Coordinate: 340667.783
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Top
Code References:	2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built : 225
Barrier Description:	Top Handrail extension not parallel to ground/floor surface
Findings:	Top handrail extension not parallel to ground surface
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 503C
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 503C Dearborn Hall Reference Dwg: 1 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 1 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 1 of 5 Exterior - West Stairway Entry
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 1 of 5 Exterior - West Stairway Entry 7478821.239 Y Coordinate: 340667.783
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 1 of 5 Exterior - West Stairway Entry 7478821.239 Y Coordinate: 340667.783 Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 1 of 5 Exterior - West Stairway Entry 7478821.239 Y Coordinate: 340667.783 Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 1 of 5 Exterior - West Stairway Entry 7478821.239 Y Coordinate: 340667.783 Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 1 of 5 Exterior - West Stairway Entry 7478821.239 Y Coordinate: 340667.783 Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3 Indard: No Quantity: LF As-built: 225
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 1 of 5 Exterior - West Stairway Entry 7478821.239 Y Coordinate: 340667.783 Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3 Indard: No Quantity: LF As-built: 225 Extension not sloped for length of one tread beyond the last riser nosing
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 1 of 5 Exterior - West Stairway Entry 7478821.239 Y Coordinate: 340667.783 Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3 mdard: No Quantity: LF As-built: 225 Extension not sloped for length of one tread beyond the last riser nosing Bottom handrail extension not min. one tread width Provide handrails at both sides of stairway
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 1 of 5 Exterior - West Stairway Entry 7478821.239 Y Coordinate: 340667.783 Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3 Indard: No Quantity: LF As-built: 225 Extension not sloped for length of one tread beyond the last riser nosing Bottom handrail extension not min. one tread width Provide handrails at both sides of stairway 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 503D
Bldg Name:	Dearborn Hall Reference Dwg: 1 of 5
Location:	Exterior - West Stairway Entry
X Coordinate:	7478821.239 Y Coordinate: 340667.783
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code References:	2010 ADAS Advisory 504.4
Performance Sta	ndard: Yes Quantity: LF or TR As-built : 35
Barrier Description:	No contrasting color on each tread of exterior stairway
Findings:	No contrasting color provided
Rec. Solution:	Consider providing contrasting color on each tread
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 503E
Bldg Name:	Dearborn Hall Reference Dwg: 1 of 5
Location:	Exterior - West Stairway Entry
X Coordinate:	Part of the last o
A Coordinate.	7478821.239 Y Coordinate: 340667.783
Barrier Area:	7478821.239 Y Coordinate: 340667.783 Stairways
Barrier Area:	Stairways
Barrier Area: Barrier Type: Code	Stairways Vertical Access - Directional Sign 2010 ADAS 403.1
Barrier Area: Barrier Type: Code References:	Stairways Vertical Access - Directional Sign 2010 ADAS 403.1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Stairways Vertical Access - Directional Sign 2010 ADAS 403.1 Indard: No Quantity: EACH As-built: 125
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Stairways Vertical Access - Directional Sign 2010 ADAS 403.1 Indard: No Quantity: EACH As-built: 125 No form of vertical access provided at stairway to reach entry door or upper floors
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Stairways Vertical Access - Directional Sign 2010 ADAS 403.1 125 No form of vertical access provided at stairway to reach entry door or upper floors No information on alternate accessible entrance to building Provide directional sign leading to accessible entry
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Stairways Vertical Access - Directional Sign 2010 ADAS 403.1





Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 1A
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway S2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Door Closer - Exterior Adjustment
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: EACH As-built : 2
Barrier Description:	Door opening force exceeds 8. 5 lbf
Findings:	17 lbf
Rec. Solution:	Replace or adjust existing closer. Door does not lead to an accessible route
Barrier Severity:	1 Necessary Cost Est \$900.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Both Sta	airway Corridors
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 1B
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	
LUCALIUII.	Basement - Stairway S2
X Coordinate:	Basement - Stairway S2 N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A Stairways Door Closer - Interior Sweep ADA
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Stairways
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Stairways Door Closer - Interior Sweep ADA 2010 ADAS 404.2.8.1
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Stairways Door Closer - Interior Sweep ADA 2010 ADAS 404.2.8.1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	N/A Stairways Door Closer - Interior Sweep ADA 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Stairways Door Closer - Interior Sweep ADA 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Stairways Door Closer - Interior Sweep ADA 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period 4 second sweep Replace or adjust existing closer. Door does not lead to an accessible route
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Stairways Door Closer - Interior Sweep ADA 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period 4 second sweep Replace or adjust existing closer. Door does not lead to an accessible route 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 1C
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway S2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	9-1/2" strike edge clearance
Rec. Solution:	Replace or adjust existing closer. Door does not lead to an accessible route
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Both Sta	airway Corridors
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 1D
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway S2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Sign - Exit Door
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: EACH As-built : 2
Barrier Description:	Door leading directly into an exit stairway lacks tactile exit sign
Findings:	Door to exit stair with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT STAIR DOWN (or UP)" at latch side of door or doorway
Barrier Severity:	2 Recommended Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Both Sta	airway Corridors



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 1E
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway S2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 4
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$3,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Both Sta	airway Corridors 4 switches
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 1F
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 1F Dearborn Hall Reference Dwg: 2 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway S2
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway S2 N/A Y Coordinate: N/A Stairways Handrail Extension - Bottom
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway S2 N/A Y Coordinate: N/A Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway S2 N/A Y Coordinate: N/A Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway S2 N/A Y Coordinate: N/A Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway S2 N/A Y Coordinate: N/A Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3 Indard: No Quantity: LF As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway S2 N/A Y Coordinate: N/A Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3 Indard: No Quantity: LF As-built: 0 Extension not sloped for length of one tread beyond the last riser nosing
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Basement - Stairway S2 N/A Y Coordinate: N/A Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3 mdard: No Quantity: LF As-built: 0 Extension not sloped for length of one tread beyond the last riser nosing Bottom handrail extension not min. one tread width Provide handrails at both sides of stairway
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway S2 N/A Y Coordinate: N/A Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3 Indard: No Quantity: LF As-built: 0 Extension not sloped for length of one tread beyond the last riser nosing Bottom handrail extension not min. one tread width Provide handrails at both sides of stairway 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 1G
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway S2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Top Length
Code References:	2010 ADAS 505.10.2
Performance Sta	indard: No Quantity: LF As-built : 0
Barrier Description:	Top Handrail extension does not extend for one tread width or min. 12"
Findings:	Top handrail extension not provided
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Both Sta	airway Corridors
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 1H
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway S2
Location: X Coordinate:	Basement - Stairway S2 N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A Stairways Contrasting Color - ADA
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Stairways
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	N/A Y Coordinate: N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 Indard: Yes Quantity: LF or TR As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 Indard: Yes Quantity: LF or TR As-built: 1 No contrasting color on each tread of interior stairway
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 Indard: Yes Quantity: LF or TR As-built: 1 No contrasting color on each tread of interior stairway Treads lack contrasting color defined as 70% contrast Recommended: Consider providing contrasting color on each tread
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Stairways Contrasting Color - ADA 2010 ADAS Advisory 504.4 Indard: Yes Quantity: LF or TR As-built: 1 No contrasting color on each tread of interior stairway Treads lack contrasting color defined as 70% contrast Recommended: Consider providing contrasting color on each tread 2 Recommended Cost Est \$35.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 11
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway S2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Surface Condition - Existing
Code References:	2010 ADAS 504.4
Performance Sta	ndard: No Quantity: SF As-built : 220
Barrier Description:	Stairway surface is not slip resistant
Findings:	Slip resistant surface could not be verified
Rec. Solution:	Demolish and construct new stairway
Barrier Severity:	4 Low Severity Cost Est \$55,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Both Sta	airway Corridors
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 2A
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
	Doors or Gates
Barrier Type:	Hardware - Operation
Barrier Type: Code	Hardware - Operation 2010 ADAS 404.2.7
Barrier Type: Code References:	Hardware - Operation 2010 ADAS 404.2.7
Barrier Type: Code References: Performance Sta Barrier	Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1
Barrier Type: Code References: Performance Sta Barrier Description:	Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not fist operable Provide new hardware
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Hardware - Operation 2010 ADAS 404.2.7 Indard: No Quantity: EACH As-built: 1 Hardware not operable with a closed fist Hardware not fist operable Provide new hardware 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 2B
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50-1/4" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 2C
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	14" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 2D
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Extinguisher - Cabinet Operation
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Fire extinguisher door involves more than 5 lbf to operate
Findings:	Cabinet door hardware not accessible
Rec. Solution:	Relocate fire extinguisher cabinet
Barrier Severity:	4 Low Severity Cost Est \$1,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Fire exti	inguisher case door 6 lbf to open
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 2E
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Operation - Manual (Fist)
Code References:	2010 ADAS 602.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier	
Description:	Operating mechanism at fountain is not operable with a fist
Description: Findings:	Operating mechanism at fountain is not operable with a fist Hardware not fist operable
·	
Findings:	Hardware not fist operable Replace fountain with accessible unit
Findings: Rec. Solution:	Hardware not fist operable Replace fountain with accessible unit 2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 2F
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Bubbler height
Code References:	2010 ADAS 602.4
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Bubbler height exceeds 36"
Findings:	42" bubbler height
Rec. Solution:	Replace drinking fountain with accessible unit or remount existing
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 2G
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	
	Hi-Low Unit
Code References:	Hi-Low Unit 2010 ADAS 211.2 & 602.7
	2010 ADAS 211.2 & 602.7
References:	2010 ADAS 211.2 & 602.7
References: Performance Sta Barrier	2010 ADAS 211.2 & 602.7 ndard: No Quantity: EACH As-built : 1
References: Performance Sta Barrier Description:	2010 ADAS 211.2 & 602.7 ndard: No Quantity: EACH As-built: 1 No hi-low drinking fountain provided on each floor of building
References: Performance Sta Barrier Description: Findings:	ndard: No Quantity: EACH As-built: 1 No hi-low drinking fountain provided on each floor of building Fountain is not wheelchair accessible
References: Performance Sta Barrier Description: Findings: Rec. Solution:	ndard: No Quantity: EACH As-built: 1 No hi-low drinking fountain provided on each floor of building Fountain is not wheelchair accessible Provide min. one hi-low fountain on each floor 1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 2H
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
	03/17/2014 17:02
Code References:	2010 ADAS 216.2
Performance Sta	indard: No Quantity: EACH As-built: 3
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible signs
Barrier Severity:	1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Rooms (09, 13, 14
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 21
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Fire Alarm - Pull Actuator Operation
Code References:	2010 ADAS 309.4
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Fire pull has no usable hardware
Findings:	Hardware not fist operable
Rec. Solution:	Replace fire pull when remodeling
Rec. Solution: Barrier Severity:	
	4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 2J
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Fire Alarm - Pull Actuator Height
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Fire pulls not between 42" and 48" high
Findings:	62" high
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 3A
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 3
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Sign - Permanent Room/Space
Code References:	2010 ADAS 703.1
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	No sign with raised characters and Braille at permanent room or space with visual sign
Findings:	No tactile info on sign with visual information
Rec. Solution:	Provide sign at latch side of entry door, where possible
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Room 10	0, 12



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 3B
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 3
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 3C
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 3
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - Wheelchair Use
Code References:	2010 ADAS 305
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 30" by 48" not provided
Findings:	Stored elements block light switch clear floor space
Findings: Rec. Solution:	Stored elements block light switch clear floor space Move stored items at control or mechanism
_	Move stored items at control or mechanism
Rec. Solution:	Move stored items at control or mechanism 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 3D
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 3
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in corridor
Findings:	No device provided
Rec. Solution:	Provide strobes in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 4A
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 11
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - No Braille/tactile Sign
Code References:	2010 ADAS 703.2.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No Braille/tactile sign at latch side of door
Findings:	Accessible sign not provided
Rec. Solution:	Provide Braille/tactile sign at latch side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 4B
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 11
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - ISA at Accessible Restroom
Code References:	2010 ADAS 216.8
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No ISA symbol on wall sign posted at accessible toilet room
Findings:	No sign indicating the restroom is accessible
Rec. Solution:	Provide ISA symbol on restroom wall sign when remodeling is completed
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 4C
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 11
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	11 - 13 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 4D
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 11
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Sweep
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	12 second sweep
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 4E
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 11
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Clear Width
Code References:	2010 ADAS 404.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clear width passage through door, sliding/folding door or gate is not min. 32"
Findings:	28" clear width
Rec. Solution:	Replace door or gate and frame
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 4F
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 11
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Clearance - Push Side
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door lacks min. 12" strike edge clearance at push side
Findings:	7" strike edge clearance at exit side
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 4G
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 11
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-3/4" high
Rec. Solution:	Delegate quitab hay tan adas to may 40" high
	Relocate switch box top edge to max. 48" high
Barrier Severity:	
Barrier Severity: Implementation	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 4H
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 11
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Wall mounted object (dispensers) protrudes more than 4" from wall
Findings:	Paper towel dispenser protrudes 10" at 41-1/2" high
Rec. Solution:	Relocate dispenser or provide cane-detectable warning
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 41
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 11
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Knee Cl
Code References:	2010 ADAS 606.2 & 306
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Lavatory bottom apron/edge not max 29" reducing to 27" at 8" back from edge
Findings:	26-1/2" high knee clearance
Rec. Solution:	26-1/2" high knee clearance Replace lavatory
_	
Rec. Solution:	Replace lavatory 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 4J
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 11
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Drainpipes
Code References:	2010 ADAS 606.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hot water and drainpipes accessible under lavatory not insulated or covered
Findings:	No insulation provided
Rec. Solution:	Insulate drainpipes and hot water pipes
Barrier Severity:	2 Recommended Cost Est \$220.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 4K
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 11
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
	Restrooms
Barrier Type:	Restrooms
Barrier Type: Code	Mirror 2010 ADAS 603.3
Barrier Type: Code References:	Mirror 2010 ADAS 603.3
Barrier Type: Code References: Performance Sta Barrier	Mirror 2010 ADAS 603.3 Indard: No Quantity: EACH As-built: 1
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Mirror 2010 ADAS 603.3 Indard: No Quantity: EACH As-built: 1 Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Mirror 2010 ADAS 603.3 Indard: No Quantity: EACH As-built: 1 Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface 53" high Replace or remount mirror
Barrier Type: Code References: Performance Sta Barrier Description:	Mirror 2010 ADAS 603.3 Indard: No Quantity: EACH As-built: 1 Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface 53" high Replace or remount mirror 3 Hindrance Cost Est \$375.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 4L
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 11
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Flush Controls
Code References:	2010 ADAS 309
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Urinal flush controls mounted higher than 48" above the floor
Findings:	54-1/2" high
Rec. Solution:	Replace urinal controls where possible or entire urinal
Barrier Severity:	2 Recommended Cost Est \$800.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Four uri	nals present
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 4M
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 11
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Flush Controls
Code References:	2010 ADAS 309
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Urinal flush controls involve more than 5 lbf (22.2 N) to activate
Findings:	7 - 9 lbf
Rec. Solution:	Provide min. 1 accessible urinal
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
Notes: Four uri	nals present



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 4N
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 11
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Rim
Code References:	2010 ADAS 605.2
Performance Sta	indard: No Quantity: JOB As-built : 0
Barrier Description:	Urinal not max. 17" above the floor
Findings:	25-1/2" high rim
Rec. Solution:	Provide min. 1 accessible urinal
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 40
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 11
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Rim
	pangydna ti -o4
Code References:	2010 ADAS 605.2
	2010 ADAS 605.2
References:	2010 ADAS 605.2
References: Performance Sta Barrier	2010 ADAS 605.2 Indard: No Quantity: JOB As-built: 0
References: Performance Sta Barrier Description:	2010 ADAS 605.2 Indard: No Quantity: JOB As-built: 0 Min. 1 urinal has no elongated rim projecting 14" to 17" from wall
References: Performance Sta Barrier Description: Findings:	2010 ADAS 605.2 Indard: No Quantity: JOB As-built: 0 Min. 1 urinal has no elongated rim projecting 14" to 17" from wall 13-1/2" from wall Provide min. 1 accessible urinal
References: Performance Sta Barrier Description: Findings: Rec. Solution:	2010 ADAS 605.2 Indard: No Quantity: JOB As-built: 0 Min. 1 urinal has no elongated rim projecting 14" to 17" from wall 13-1/2" from wall Provide min. 1 accessible urinal 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 4P
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 11
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Clear Width
Code References:	2010 ADAS 404.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 160
Barrier Description:	Door clear width is not min. 32"
Findings:	21-3/4" clear width
Rec. Solution:	Remodel to provide wheelchair access
Barrier Severity:	1 Necessary Cost Est \$92,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: No whe	elchair accessible toilet room
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 4Q
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Men's Restroom 11
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/strobe in sanitary facility
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 5A
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Sign - Permanent Room/Space
Code References:	2010 ADAS 703.1
Performance Sta	ndard: No Quantity: EACH As-built : 5
Barrier Description:	No sign with raised characters and Braille at permanent room or space with visual sign
Findings:	No tactile info on sign with visual information
Rec. Solution:	Provide sign at latch side of entry door, where possible
Barrier Severity:	1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Rooms 2	IA, 1E, 1B, 1D, 09
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 5B
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	
	Electrical Switches - Height
Code References:	Electrical Switches - Height 2010 ADAS 308.2
Code	2010 ADAS 308.2
Code References:	2010 ADAS 308.2
Code References: Performance Sta Barrier	2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1
Code References: Performance Sta Barrier Description:	2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Code References: Performance Sta Barrier Description: Findings:	2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 49-3/4" - 50" high Relocate switch box top edge to max. 48" high
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 49-3/4" - 50" high Relocate switch box top edge to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 5C
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard & 2010 ADAS 904.3.3
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 41" - 51" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 5D
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Electrical box protrudes 9" at 53-1/2" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 5E
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Door
Code References:	2010 ADAS 216.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Ground floor doors that exit to exterior lacks tactile exit sign
Findings:	Exit door with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT" at exit side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 5F
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 5F Dearborn Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 1
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 1 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 1 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 1 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 1 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 1 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 1 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1 No horn or strobe in corridor where fire alarm exists in building
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 1 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1 No Quantity: EACH As-built: 1 No horn or strobe in corridor where fire alarm exists in building No strobe provided Provide horn/strobe in common use area
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 1 N/A Y Coordinate: N/A Corridors Horn/Strobe Device 2010 ADAS 702.1 No horn or strobe in corridor where fire alarm exists in building No strobe provided Provide horn/strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 6A
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not fist operable
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 6B
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Passage
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built : 1
Barrier Description:	Exit thru an exit enclosure/exit passageway lacks tactile exit sign
Findings:	Passageway to exterior exit with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT ROUTE" at exit side of door
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	<u> </u>
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 6C
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	48-1/2" - 64" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 6D
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Lobby L2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in corridor
Findings:	No device provided
Rec. Solution:	Provide strobes in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 7A
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Class Lab 1G
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 7B
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Class Lab 1G
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	14 lbf
Rec. Solution:	Provide automatic door opening device at one door and ISA sign at other doors
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 7C
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Class Lab 1G
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	4 second sweep
Rec. Solution:	Provide automatic door opening device at one door and ISA sign at other doors
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 7D
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Class Lab 1G
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not fist operable
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 7E
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Class Lab 1G
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	4" strike edge clearance to table
Rec. Solution:	Remove stored item
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 7F
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Class Lab 1G
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Sliding Door Closer - Interior
Code References:	2010 ADAS 404.2.9
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	Two heavy sliding doors present; could not undo locking mechanism to test them
Rec. Solution:	Provide ISA directional signage alternative accessible entry
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	
Notes:	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 7G
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Class Lab 1G
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" - 50-1/4" high. Stored elements block light switch clear floor space
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 7H
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Class Lab 1G
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	First Aid Kit - High Reach Range
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Opening mechanism on first aid kit not at max. 48" high for side reach
Findings:	62-1/2" high
Rec. Solution:	Relocate control or mechanism to max. 48" high
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 71
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Class Lab 1G
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Stored elements block fire extinguisher clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 7J
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Class Lab 1G
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24-1/4" knee clearance
Rec. Solution:	Provide min. 1 accessible desk of each type
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 7K
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Class Lab 1G
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Shelves or Cabinets
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Shelf or cabinet not mounted max. 48" above floor or ground
Findings:	Shelf or cabinet not accessible
Rec. Solution:	Provide additional shelf at accessible height or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 49-1/2"	high
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 7L
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Class Lab 1G
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Workstation - Surface Max. 34"
Code References:	2010 ADAS 902
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Workstation surface height exceeds 34" high
Findings:	39-1/4" surface height and 14" deep knee clearance at workstations
Rec. Solution:	Provide min. 1 accessible workstation
Rec. Solution: Barrier Severity:	
	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 7M
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Class Lab 1G
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space for wheelchair not provided at control or mechanism
Findings:	Stored items block chalkboard clear floor space
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 7N
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Class Lab 1G
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Space - Stored Elements
Cada	Jeleur Floor Space Stored Elements
Code References:	2010 ADAS 305.3
	2010 ADAS 305.3
References:	2010 ADAS 305.3
References: Performance Sta Barrier	2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1
References: Performance Sta Barrier Description:	2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism
References: Performance Sta Barrier Description: Findings:	2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Stored elements block tool chest clear floor space Move stored items
References: Performance Sta Barrier Description: Findings: Rec. Solution:	2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Stored elements block tool chest clear floor space Move stored items 1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 70
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Class Lab 1G
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Surface Height
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No section at least 3 feet long between 28" and 34" provided at existing counter
Findings:	36-1/4" high surface and 24" knee clearance at tool fitting counter
Rec. Solution:	Provide min. 3 ft long section of counter at max. 34" high
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 7P
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Class Lab 1G
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	Computer workstation has no knee clearance
Rec. Solution:	Provide accessible computer desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 7Q
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Class Lab 1G
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard & 2010 ADAS 904.3.3
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 41-1/4" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 7R
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Locations	
Location:	Basement - Class Lab 1G
X Coordinate:	Basement - Class Lab 1G N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Controls and Mechanisms
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Stored elements block cabinet clear floor space Move stored items
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Stored elements block cabinet clear floor space Move stored items 1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 7S
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Class Lab 1G
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - High Unobstructed
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	11-1/2" high
Rec. Solution:	Relocate outlet to min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 7T
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Class Lab 1G
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Barrier Type: Code References:	
Code	Horn/Strobe 2010 ADAS 702.1
Code References:	Horn/Strobe 2010 ADAS 702.1
Code References: Performance Sta Barrier	Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1
Code References: Performance Sta Barrier Description:	Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas
Code References: Performance Sta Barrier Description: Findings:	Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas No device provided Provide strobe in common use area
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas No device provided Provide strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 8A
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Vestibule 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Hallway	H001 and Room 008
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 8B
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Vestibule 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	10 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	
Notes:	implementation ruse.



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 8C
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Vestibule 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	2 second sweep
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 8D
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Vestibule 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not fist operable
Rec. Solution:	Provide new hardware
Rec. Solution: Barrier Severity:	
	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 8E
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Vestibule 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-3/4" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 8F
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Vestibule 1
Location:	
Location:	Basement - Vestibule 1
Location: X Coordinate:	Basement - Vestibule 1 N/A Y Coordinate: N/A Alarms Horn/Strobe
Location: X Coordinate: Barrier Area:	Basement - Vestibule 1 N/A Y Coordinate: N/A Alarms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Basement - Vestibule 1 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Basement - Vestibule 1 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Basement - Vestibule 1 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Basement - Vestibule 1 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Basement - Vestibule 1 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas No strobe provided Provide strobe in common use area
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Basement - Vestibule 1 N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas No strobe provided Provide strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 9A
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 4
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$1,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Rooms (002, 004, 005B, 007
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 9B
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Fist Operable
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not usable with a closed fist
Findings:	Fire extinguisher door hardware not fist operable and more than 5 lbf is needed to operate
Rec. Solution:	Replace operating control
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 9C
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Counter protrudes 6" at 37-1/4" high
Rec. Solution:	Provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 9D
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Surface Height
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	No section at least 3 feet long between 28" and 34" provided at existing counter
Findings:	37-1/4" high
Rec. Solution:	Provide min. 3 ft long section of counter at max. 34" high
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Service	counter



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 9E
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Hi-Low Unit
Code References:	2010 ADAS 211.2 & 602.7
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	No hi-low drinking fountain provided on each floor of building
Findings:	No wheelchair fountain provided on basement floor
Rec. Solution:	Provide min. one hi-low fountain on each floor
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Second	non-accessible fountain on basement floor
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 9F
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Operation - Manual (Fist)
Code References:	2010 ADAS 602.3
Performance Sta	indard: No Quantity: EACH As-built : 0
Barrier Description:	Operating mechanism at fountain is not operable with a fist
Findings:	Not fist operable
Rec. Solution:	
	Replace fountain with accessible unit
Barrier Severity:	
Barrier Severity: Implementation	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 9G
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Bubbler water flow
Code References:	2010 ADAS 602.6
Performance Sta	indard: No Quantity: JOB As-built : 0
Barrier Description:	Water flow from bubbler not min. 4" high
Findings:	2-1/4" high water flow from bubbler
Rec. Solution:	Adiust drinking fountain to provide min. 4" high water flow
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
-	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 9H
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 9H Dearborn Hall Reference Dwg: 2 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 2
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 2 N/A Y Coordinate: N/A Drinking Fountains Bubbler height
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 2 N/A Y Coordinate: N/A Drinking Fountains
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 2 N/A Y Coordinate: N/A Drinking Fountains Bubbler height 2010 ADAS 602.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 2 N/A Y Coordinate: N/A Drinking Fountains Bubbler height 2010 ADAS 602.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 2 N/A Y Coordinate: N/A Drinking Fountains Bubbler height 2010 ADAS 602.4 Indard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 2 N/A V Coordinate: N/A Drinking Fountains Bubbler height 2010 ADAS 602.4 andard: No Quantity: EACH As-built: 0 Bubbler height exceeds 36"
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 2 N/A Y Coordinate: N/A Drinking Fountains Bubbler height 2010 ADAS 602.4 andard: No Quantity: EACH As-built: 0 Bubbler height exceeds 36" 43" bubbler height Provide additional wheelchair accessible drinking fountain
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 2 N/A Y Coordinate: N/A Drinking Fountains Bubbler height 2010 ADAS 602.4 andard: No Quantity: EACH As-built: 0 Bubbler height exceeds 36" 43" bubbler height Provide additional wheelchair accessible drinking fountain 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 91
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull 03/18/2014, 13:17
Code References:	2010 ADAS 309.4
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Fire pull has no usable hardware
Findings:	Fire pull not fist operable
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 9J
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull 03/18/2014, 13:17
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Fire pulls not between 42" and 48" high
Findings:	63" high
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
	, passes passes and passes are passes and passes are passes and passes are passes are passes and passes are pa
implementation	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 9K
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	51" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	Device H. Device Date Transfer H. Device H. De
riela Date.	3/25/2014 Report Date 5/27/2014 Barrier #: 9L
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
	The state of the s
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 2
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 2 N/A Y Coordinate: N/A Corridors Protruding Object
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 2 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 2 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 2 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 2 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 2 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 2 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high Fire extinguisher protrudes 5" at 33-1/2" high Remove object or provide detectable warning (wing walls)
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Hallway 2 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high Fire extinguisher protrudes 5" at 33-1/2" high Remove object or provide detectable warning (wing walls) I Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 9M
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Top
Code References:	2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built : 2
Barrier Description:	Top Handrail extension not parallel to ground/floor surface
Findings:	Top handrail extension not provided
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 9N
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Bottom
Code References:	2010 ADAS 505.10.3
Performance Sta	ndard: No Quantity: LF As-built : 2
Barrier Description:	Extension not sloped for length of one tread beyond the last riser nosing
Findings:	Bottom handrail extension not provided
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 90
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code References:	2010 ADAS Advisory 504.4
Performance Sta	andard: Yes Quantity: LF or TR As-built : 20
Barrier Description:	No contrasting color on each tread of interior stairway
Findings:	Treads lack contrasting color defined as 70% contrast
Rec. Solution:	Recommended: Consider providing contrasting color on each tread
Barrier Severity:	2 Recommended Cost Est \$700.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 9P
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Door
Code References:	2010 ADAS 216.4.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Ground floor doors that exit to exterior lacks tactile exit sign
Findings:	Exit door with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT" at exit side of door
Rec. Solution: Barrier Severity:	
	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 9Q
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Exterior Adjustment
Code References:	Performance Standard
Performance Sta	indard: Yes Quantity: EACH As-built: 1
Barrier Description:	Door opening force exceeds 8.5 lbf
Findings:	30 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Door to	exterior stairway, but not on an accessible route
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 9R
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
	Doors or Gates
Barrier Type:	Door Closer - Sweep Period
Barrier Type: Code	Door Closer - Sweep Period 2010 ADAS 404.2.8.1
Barrier Type: Code References:	Door Closer - Sweep Period 2010 ADAS 404.2.8.1
Barrier Type: Code References: Performance Sta Barrier	Door Closer - Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0
Barrier Type: Code References: Performance Sta Barrier Description:	Door Closer - Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Door Closer - Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period 2 second sweep Replace or adjust existing closer
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Door Closer - Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period 2 second sweep Replace or adjust existing closer 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 9S
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not fist operable
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 9T
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Clear Width
Code References:	2010 ADAS 404.2.3
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Clear width passage through door, sliding/folding door or gate is not min. 32"
Findings:	28-3/4" clear width
Rec. Solution:	No remediation recommended. Door not on an accessible route
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
	Truccessary Cost Est 150.00 radiately randicion I abile
Implementation	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 9U
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Recessed Door
Code References:	2010 ADAS Figure 404.2.4.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Door in alcove deeper than 8" does not have min. 18" strike edge clearance
Findings:	Door recessed 10-1/2"
Rec. Solution:	No remediation recommended. Door not on an accessible route
Barrier Severity:	1 Necessary Cost Est \$775.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 9V
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	-1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	Threshold - Height exceeding 1/2"
	2010 ADAS 404.2.5
Code References: Performance Sta	2010 ADAS 404.2.5
References:	2010 ADAS 404.2.5
References: Performance Sta Barrier	2010 ADAS 404.2.5 andard: No Quantity: EACH As-built: 1
References: Performance Sta Barrier Description: Findings:	2010 ADAS 404.2.5 andard: No Quantity: EACH As-built: 1 Door/Gate threshold exceeds 1/2" in height
References: Performance Sta Barrier Description: Findings: Rec. Solution:	2010 ADAS 404.2.5 andard: No Quantity: EACH As-built: 1 Door/Gate threshold exceeds 1/2" in height 3/4" high Provide new door threshold
References: Performance Sta Barrier Description:	2010 ADAS 404.2.5 andard: No Quantity: EACH As-built: 1 Door/Gate threshold exceeds 1/2" in height 3/4" high Provide new door threshold 1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open



Field Date:	2/25/2014 Poport Data 15/27/2014 Parrier #: 10W
	3/25/2014 Report Date 5/27/2014 Barrier #: 9W
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Hallway 2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in corridor
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 10A
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Activity Room 3
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	
Implementation	
Notes: Rooms (



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 10B
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Activity Room 3
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	11 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 10C
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 10C Dearborn Hall Reference Dwg: 2 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Activity Room 3
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Activity Room 3 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Activity Room 3 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 2 of 5 Basement - Activity Room 3 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Activity Room 3 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 2 of 5 Basement - Activity Room 3 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Activity Room 3 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 1 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Activity Room 3 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 1 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame 2 second sweep Provide automatic door opening device
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Activity Room 3 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 1 Door closer lacks min. 5 second sweep period or does not stop 5" from door frame 2 second sweep Provide automatic door opening device 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 10D
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Activity Room 3
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Clear Width
Code References:	2010 ADAS 404.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Clear width passage through door, sliding/folding door or gate is not min. 32"
Findings:	31" clear width to cabinet
Rec. Solution:	Remove cabinet
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 10E
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Activity Room 3
Location: X Coordinate:	Basement - Activity Room 3 N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Controls and Mechanisms
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high Relocate switch box top edge to max. 48" high
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high So" high Relocate switch box top edge to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 10F
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Activity Room 3
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Hi/low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of control involves low reach of less than 15" above floor or more than 48" high
Findings:	Emergency trip breaker button 53" high
Rec. Solution:	Relocate to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 10G
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Activity Room 3
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	First Aid Kit - Obstructed Reach Range
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Opening mechanism on first aid kit not at max. 44" over an obstruction of max. 25"
Findings:	50-1/2" high and 20" deep over an obstruction 29" high. Mechanism not fist operable
Rec. Solution:	Relocate control or mechanism
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	Discrition la Local amountation Discritical Local amountation Dates.
Notes:	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 10H
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Activity Room 3
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24-1/2" high knee clearance
Rec. Solution:	Provide min. 1 accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 10I
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Activity Room 3
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Area: Barrier Type:	Controls and Mechanisms Shelves or Cabinets
Barrier Type: Code	Shelves or Cabinets 2010 ADAS 305.3
Barrier Type: Code References:	Shelves or Cabinets 2010 ADAS 305.3
Barrier Type: Code References: Performance Sta Barrier	Shelves or Cabinets 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1
Barrier Type: Code References: Performance Sta Barrier Description:	Shelves or Cabinets 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Shelves or Cabinets 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground Shelf or cabinet not accessible Provide additional shelf at accessible height or provide assistance
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Shelves or Cabinets 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground Shelf or cabinet not accessible Provide additional shelf at accessible height or provide assistance 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 10J
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Activity Room 3
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard & 2010 ADAS 904.3.3
Performance Sta	indard: Yes Quantity: EACH As-built : 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 47-3/4" high from floor. Cart blocks whiteboard clear floor space
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 10K
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Activity Room 3
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
barrier Area.	Controls and Mechanisms
Barrier Type:	Actuator/Control - Side Reach Obstructed (10")
Barrier Type: Code	Actuator/Control - Side Reach Obstructed (10") 2010 ADAS 305.3
Barrier Type: Code References:	Actuator/Control - Side Reach Obstructed (10") 2010 ADAS 305.3
Barrier Type: Code References: Performance Sta Barrier	Actuator/Control - Side Reach Obstructed (10") 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1
Barrier Type: Code References: Performance Sta Barrier Description:	Actuator/Control - Side Reach Obstructed (10") 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Control or mechanism over an obstruction max. 34" high located above 48"
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Actuator/Control - Side Reach Obstructed (10") 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Control or mechanism over an obstruction max. 34" high located above 48" Electrical board 41-1/2" high and 29" deep over an obstruction 30-1/2" high Relocate control or mechanism to max. 48" high
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Actuator/Control - Side Reach Obstructed (10") 2010 ADAS 305.3 Indard: No Quantity: EACH As-built: 1 Control or mechanism over an obstruction max. 34" high located above 48" Electrical board 41-1/2" high and 29" deep over an obstruction 30-1/2" high Relocate control or mechanism to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 10L
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Activity Room 3
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24-1/2" - 26-1/2" high knee clearance
Rec. Solution:	Provide min. 1 accessible table
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 10M
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Activity Room 3
Location: X Coordinate:	N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Alarms
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1 andard: No Quantity: EACH As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Alarms Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas No device provided Provide strobe in common use area
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Y Coordinate: N/A Alarms Horn/Strobe 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas No device provided Provide strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 11A
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Conference Rm 5
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Room 0	05, 005A
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 11B
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Conference Rm 5
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 1
Performance Sta Barrier Description:	andard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf
Barrier	
Barrier Description:	Door opening force exceeds 5 lbf
Barrier Description: Findings: Rec. Solution:	Door opening force exceeds 5 lbf 11 lbf Replace or adjust existing closer
Barrier Description: Findings:	Door opening force exceeds 5 lbf 11 lbf Replace or adjust existing closer 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 11C
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Conference Rm 5
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	3 second sweep
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 11D
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Conference Rm 5
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Door knob not fist operable
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 11E
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Conference Rm 5
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50-1/4" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 11F
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 11F Dearborn Hall Reference Dwg: 2 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Conference Rm 5
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Conference Rm 5 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Conference Rm 5 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Conference Rm 5 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Conference Rm 5 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Conference Rm 5 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Conference Rm 5 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Conference Rm 5 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Chairs block whiteboard clear floor space Move stored items
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Conference Rm 5 N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Chairs block whiteboard clear floor space Move stored items 1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 11G
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Conference Rm 5
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Workstation - Ratio
Code References:	2010 ADAS 902
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	At least 1 table or 5% of all workstations is not accessible
Findings:	Accessible workstation not provided
Rec. Solution:	Provide at least 1 accessible workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 7 works	tations and none are accessible
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 11H
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 11H Dearborn Hall Reference Dwg: 2 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Conference Rm 5
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Conference Rm 5 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Conference Rm 5 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Conference Rm 5 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Side Reach Obstructed (10"-24") 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Conference Rm 5 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Side Reach Obstructed (10"-24") 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Conference Rm 5 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Conference Rm 5 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Control or mechanism over an 10" to 24" obstruction max. 34" high located above 46"
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Conference Rm 5 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Control or mechanism over an 10" to 24" obstruction max. 34" high located above 46" Electrical stations 45-1/2" - 58-1/2" high and 16-1/2" deep over an obstruction 35-1/2" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Conference Rm 5 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Side Reach Obstructed (10"-24") 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Control or mechanism over an 10" to 24" obstruction max. 34" high located above 46" Electrical stations 45-1/2" - 58-1/2" high and 16-1/2" deep over an obstruction 35-1/2" high Relocate within accessible reach range 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 111
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Conference Rm 5
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	Passageway less than 36" in multiple locations
Rec. Solution:	Rearrange furniture to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 17" - 30	" wide circulation route around conference table
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 11J
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Conference Rm 5
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Side Reach Obstructed (10"-24")
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Control or mechanism over an 10" to 24" obstruction max. 34" high located above 46"
Findings:	AC unit 60-1/2" high and 20-3/4" deep over an obstruction 35-1/2" high
	<u> </u>
Rec. Solution:	Provide assistance
Rec. Solution: Barrier Severity:	
	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 11K
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Conference Rm 5
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Side Reach Obstructed (10"-24")
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism over an 10" to 24" obstruction max. 34" high located above 46"
Findings:	Gas and air valves 39-3/4" high and 46-1/2" deep over an obstruction 35-1/2" high
Rec. Solution:	Relocate control or mechanism to max. 46" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Gas and	air valves measured at 11 lbf
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 11L
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Conference Rm 5
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
rierererrees.	
Performance Sta	andard: No Quantity: EACH As-built : 1
	nndard: No Quantity: EACH As-built: 1 No horn/strobes in meeting room
Performance Sta Barrier	
Performance Sta Barrier Description: Findings:	No horn/strobes in meeting room
Performance Sta Barrier Description: Findings: Rec. Solution:	No horn/strobes in meeting room No device provided Provide strobe in common use area
Performance Sta Barrier Description:	No horn/strobes in meeting room No device provided Provide strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 12A
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Vestibule V2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Accessible Route - Stored Elements
Code References:	2010 ADAS 305
Performance Sta	indard: No Quantity: JOB As-built: 1
Barrier Description:	Clear floor space does not adjoin an accessible route or another space
Findings:	Clear floor space not accessible
Rec. Solution:	Relocate items to provide connection to accessible route
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Clear wi	dth is 12" wide
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 12B
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Vestibule V2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	Indard: No Quantity: EACH As-built: 1
Performance Sta Barrier Description:	ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Barrier	
Barrier Description:	Light switch control box top edge not at max. 48" high
Barrier Description: Findings:	Light switch control box top edge not at max. 48" high 54" high Relocate switch box top edge to max. 48" high
Barrier Description: Findings: Rec. Solution:	Light switch control box top edge not at max. 48" high 54" high Relocate switch box top edge to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 12C
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Vestibule V2
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	75" high
Rec. Solution:	Provide additional hook
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 13A
Field Date: Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Student Office 6
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Student Office 6 N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built: 2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 Indard: No Quantity: EACH As-built : 2 No tactile characters at sign identifying permanent rooms and spaces with visual signs
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 2 of 5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 No Quantity: EACH As-built: 2 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign I Necessary Cost Est \$500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 13B
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Student Office 6
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	9 - 16 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 13C
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Student Office 6
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door closer lacks min. 5 second sweep period or does not stop 5" from door frame
Findings:	3 - 4 second sweep
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 13D
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Student Office 6
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not fist operable
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 13E
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Student Office 6
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	No strike edge clearance
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 13F
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Student Office 6
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50-3/4" high. Stored items block electrical switch clear floor space
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 13G
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Student Office 6
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	58" high. Stored items block coat hook clear floor space
Rec. Solution:	Provide additional hook
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 13H
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Student Office 6
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Side Reach Obstructed (10")
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Control or mechanism over an obstruction max. 34" high located above 48"
Findings:	AC unit 58" high and 25-3/4" deep over an obstruction 29" high
Rec. Solution:	Provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 13I
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Student Office 6
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	23-1/4" - 26" high knee clearance
Rec. Solution:	Provide min. 1 accessible table
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	<u> </u>
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 13J
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Student Office 6
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Hi/low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Use of control involves low reach of less than 15" above floor or more than 48" high
Findings:	Printer 47" high
Rec. Solution:	Relocate within accessible reach range
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 13K
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Student Office 6
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24" - 26" high and 24-3/4" - 28" wide knee clearance
Rec. Solution:	Provide accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 11 desk	s and none are accessible



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 13L
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Student Office 6
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Depth
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: LF As-built: 3
Barrier Description:	Sink depth exceeds 6-1/2" deep
Findings:	8-1/2" deep. Clear space not provided to approach sink
Rec. Solution:	Provide min. 1 accessible sink
Barrier Severity:	1 Necessary Cost Est \$1,350.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 13M
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Student Office 6
	The State of the S
Location:	Basement - Energy System Student Office 6
Location: X Coordinate:	Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Classrooms Sink - Knee Clearance
Location: X Coordinate: Barrier Area:	Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Classrooms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Classrooms Sink - Knee Clearance 2010 ADAS 606.2 & 306
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Classrooms Sink - Knee Clearance 2010 ADAS 606.2 & 306
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Classrooms Sink - Knee Clearance 2010 ADAS 606.2 & 306 andard: No Quantity: EACH As-built: 0
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Classrooms Sink - Knee Clearance 2010 ADAS 606.2 & 306 andard: No Quantity: EACH As-built: Knee clearance of at least 30" wide and 8" deep at 27" high with 11" depth at 9" high
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Classrooms Sink - Knee Clearance 2010 ADAS 606.2 & 306 andard: No Quantity: EACH As-built: 0 Knee clearance of at least 30" wide and 8" deep at 27" high with 11" depth at 9" high 25-1/2" high knee clearance Replace cabinet and remount sink
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Classrooms Sink - Knee Clearance 2010 ADAS 606.2 & 306 Andard: No Quantity: EACH As-built: 0 Knee clearance of at least 30" wide and 8" deep at 27" high with 11" depth at 9" high 25-1/2" high knee clearance Replace cabinet and remount sink 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 13N
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Student Office 6
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Exposed Pipes
Code References:	2010 ADAS 606.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Exposed hot water/drain pipes not insulated or configured so as to protect against contact
Findings:	No insulation provided
Rec. Solution:	Provide insulation at drain pipes
Barrier Severity:	2 Recommended Cost Est \$120.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 130
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
2.08.10	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Student Office 6
	The HAVE BE
Location:	Basement - Energy System Student Office 6
Location: X Coordinate:	Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Forward Reach Obstructed (10")
Location: X Coordinate: Barrier Area:	Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Controls and Mechanisms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Forward Reach Obstructed (10") 2010 ADAS 308.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Forward Reach Obstructed (10") 2010 ADAS 308.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Forward Reach Obstructed (10") 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Forward Reach Obstructed (10") 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1 Control or mechanism over an obstruction max. 34" high located above 48" Paper towel and soap dispensers 47" to 63" high and 22" deep over an obstruction 35-1/4"
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Forward Reach Obstructed (10") 2010 ADAS 308.2 andard: No Quantity: EACH As-built: 1 Control or mechanism over an obstruction max. 34" high located above 48" Paper towel and soap dispensers 47" to 63" high and 22" deep over an obstruction 35-1/4" high
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Controls and Mechanisms Actuator/Control - Forward Reach Obstructed (10") 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1 Control or mechanism over an obstruction max. 34" high located above 48" Paper towel and soap dispensers 47" to 63" high and 22" deep over an obstruction 35-1/4" high Relocate control or mechanism to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 13P
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Student Office 6
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	First Aid Kit - High Reach Range
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Opening mechanism on first aid kit not at max. 48" high for side reach
Findings:	67" high
Rec. Solution:	Relocate control or mechanism to max. 48" high
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 13Q
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 13Q Dearborn Hall Reference Dwg: 2 of 5
	Defended Day
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Student Office 6
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Student Office 6 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Clear Floor Space
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 305
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 305
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 305 ndard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 305 ndard: No Quantity: JOB As-built: 1 Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Student Office 6 N/A
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Energy System Student Office 6 N/A Y Coordinate: N/A Clear Floor Space Clear Floor Space - 60" Turning Circle 2010 ADAS 305 ndard: No Quantity: JOB As-built: 1 Clear floor space of min. 60" in diameter not provided where 360 degree turn is made 49-1/2" turning circle at the end of the row of desks Move stored items blocking maneuvering clearance 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 13R
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Energy System Student Office 6
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 14A
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 14A Dearborn Hall Reference Dwg: 2 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Elevator 1
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Elevator 1 N/A Y Coordinate: N/A Elevators Hall call buttons
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Elevator 1 N/A Y Coordinate: N/A Elevators
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 2 of 5 Basement - Elevator 1 N/A Y Coordinate: N/A Elevators Hall call buttons 2010 ADAS 407.2.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Elevator 1 N/A Y Coordinate: N/A Elevators Hall call buttons 2010 ADAS 407.2.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 2 of 5 Basement - Elevator 1 N/A Y Coordinate: N/A Elevators Hall call buttons 2010 ADAS 407.2.1 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Elevator 1 N/A Y Coordinate: N/A Elevators Hall call buttons 2010 ADAS 407.2.1 Indard: No Quantity: EACH As-built: 1 The centerline of the hall call buttons not max. 42" above the floor
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Elevator 1 N/A Y Coordinate: N/A Elevators Hall call buttons 2010 ADAS 407.2.1 The centerline of the hall call buttons not max. 42" above the floor 40-1/2" high Replace hall call buttons
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Elevator 1 N/A Y Coordinate: N/A Elevators Hall call buttons 2010 ADAS 407.2.1 The centerline of the hall call buttons not max. 42" above the floor 40-1/2" high Replace hall call buttons I Necessary Cost Est \$3,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 14B
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Elevator 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Doorjamb marking
Code References:	2010 ADAS 407.2.3.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Elevator landing door jamb signage not located 60" on center on both jamb panels
Findings:	54" high on center
Rec. Solution:	Replace door jamb signage
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 14C
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Elevator 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Audible Signals
Code References:	2010 ADAS 407.2.2.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Audible signals or verbal announcement does not sound when the car passes a floor or stops
Findings:	No audible signals when car answers call, to indicate travel direction, or when car passes floor
Rec. Solution:	Replace car controls
Barrier Severity:	2 Recommended Cost Est \$2,750.00 Facility Function: Public Status: Open
Implementation	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 14D
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Elevator 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Door Delay Duration
Code References:	2010 ADAS 407.3.3.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Door reopening devices does not remain effective for 20 seconds minimum
Findings:	Doors remain open for 8 seconds
Rec. Solution:	Adiust door delav
Barrier Severity:	1 Necessary Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
-	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 14E
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 14E Dearborn Hall Reference Dwg: 2 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Elevator 1
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Elevator 1 N/A Y Coordinate: N/A Elevators Illumination
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Elevator 1 N/A Y Coordinate: N/A Elevators
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 2 of 5 Basement - Elevator 1 N/A Y Coordinate: N/A Elevators Illumination 2010 ADAS 407.4.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Elevator 1 N/A Y Coordinate: N/A Elevators Illumination 2010 ADAS 407.4.5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 2 of 5 Basement - Elevator 1 N/A Y Coordinate: N/A Elevators Illumination 2010 ADAS 407.4.5 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Elevator 1 N/A Y Coordinate: N/A Elevators Illumination 2010 ADAS 407.4.5 Indard: No Quantity: EACH As-built: 1 The minimum illumination at the car controls threshold and landing is not min. 5 foot-candles
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Elevator 1 N/A Y Coordinate: N/A Elevators Illumination 2010 ADAS 407.4.5 The minimum illumination at the car controls threshold and landing is not min. 5 foot-candles Car poorly illuminated Replace lighting system in elevator or at landing
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Elevator 1 N/A Y Coordinate: N/A Elevators Illumination 2010 ADAS 407.4.5 Indard: No Quantity: EACH As-built: 1 The minimum illumination at the car controls threshold and landing is not min. 5 foot-candles Car poorly illuminated Replace lighting system in elevator or at landing 2 Recommended Cost Est \$2,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 14F
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Elevator 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Car Control Buttons
Code References:	2010 ADAS 407.4.8
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Visual floor buttons do not illuminate as the car passes floors or stops
Findings:	Visible position indicators do not illuminate floor level or direction of travel
Rec. Solution:	Replace car controls
Barrier Severity:	2 Recommended Cost Est \$2,750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 14G
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Elevator 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Car Control Signage
Code References:	2010 ADAS 407.4.7.1.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control buttons not designated by Grade 2 Braille immediately below the character or symbol
Findings:	No braille information provided at control panel
Rec. Solution:	Replace car control signage
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 14H
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Elevator 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Emergency Contols - Handset
Code References:	2010 ADAS Advisory 105.2.2 ASME
Performance Sta	ndard: Yes Quantity: EACH As-built: 1
Barrier Description:	The use of a handset by the communications system is needed to reach emergency personnel
Findings:	Phone (voice communication) needed for emergency communication
Rec. Solution:	Replace communication system
Barrier Severity:	1 Necessary Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 14
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Elevator 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Emergency Controls - Cabinet
Code References:	2010 ADAS 407.4.6.4.1 and 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Cabinet housing emergency controls lacks accessible hardware
Findings:	Hardware not fist operable
Rec. Solution:	Replace cabinet hardware
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	
Notes: Hardwa	re also at 30" high



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 14J
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Elevator 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Emergency Controls - Handset
Code References:	2010 ADAS 409.4.7
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Emergency telephone handset provided for use
Findings:	The use of a handset is needed by the communications system
Rec. Solution:	Replace emergency system
Barrier Severity:	1 Necessary Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Cord is o	only 12" long
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 14K
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Elevator 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	4+ Story Bldgs - Emergency Access
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: JOB As-built : 1
Barrier Description:	Min. one car in building of more than 4 stories lacks 24" x 84" space for ambulance stretcher
Findings:	No emergency elevator provided
Rec. Solution:	Provide emergency elevator
Barrier Severity:	1 Necessary Cost Est \$1,250,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 15A
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	10 - 16 lbf
Rec. Solution:	Replace or adjust existing closer. Door not on an accessible route
Barrier Severity:	1 Necessary Cost Est \$900.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: For doo	r in basement and mid-floor landing
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 15B
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway 1
X Coordinate:	
	N/A Y Coordinate: N/A
Barrier Area:	N/A Y Coordinate: N/A Doors or Gates
Barrier Area:	Doors or Gates
Barrier Area: Barrier Type: Code	Doors or Gates Door Closer - Sweep Period 2010 ADAS 404.2.8.1
Barrier Area: Barrier Type: Code References:	Doors or Gates Door Closer - Sweep Period 2010 ADAS 404.2.8.1
Barrier Area: Barrier Type: Code References: Performance Sta	Doors or Gates Door Closer - Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Door Closer - Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Doors or Gates Door Closer - Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period 3 second sweep Replace or adjust existing closer. Door not on an accessible route
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Doors or Gates Door Closer - Sweep Period 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period Replace or adjust existing closer. Door not on an accessible route 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 15C
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Stairway
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Door leading directly into an exit stairway lacks tactile exit sign
Findings:	Door to exit stair with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT STAIR DOWN (or UP)" at latch side of door
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Baseme	nt
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 15D
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 15D Dearborn Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway 1
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Sign - Encl Stairway Level
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Sign - Encl Stairway Level ICC A117.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Sign - Encl Stairway Level ICC A117.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Sign - Encl Stairway Level ICC A117.1 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Sign - Encl Stairway Level ICC A117.1 ndard: No Quantity: EACH As-built: 1 Tactile stairway signage not provided to indicate floor level
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Sign - Encl Stairway Level ICC A117.1 ndard: No Quantity: EACH As-built: 1 Tactile stairway signage not provided to indicate floor level No tactile sign provided to indicate floor level Provide sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Sign - Encl Stairway Level ICC A117.1 ndard: No Quantity: EACH As-built: 1 Tactile stairway signage not provided to indicate floor level No tactile sign provided to indicate floor level Provide sign 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 16A
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Door
Code References:	2010 ADAS 216.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Ground floor doors that exit to exterior lacks tactile exit sign
Findings:	Exit door with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT" at exit side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Mid-floo	or landing
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 16B
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	<u> </u>



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 16C
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Backcheck
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Door closer does not stop at least 5" from door frame (no back check)
Findings:	Does not stop at least 5" from close
Rec. Solution:	Adiust existing door closer. Door not on an accessible route
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Mid-floo	or landing
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 16D
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not fist operable
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Mid-floo	-
	or landing



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 16E
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Doormat
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Doormat not anchored to floor (possible trip hazard)
Findings:	Door mat not secured
Rec. Solution:	Secure exiting doormat or replace
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Mid-floo	or landing
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 16F
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Landing - Length
Code References:	2010 ADAS 404.2.4
Performance Sta	indard: No Quantity: SF As-built : 40
Barrier Description:	Landing length is not at least 44" in direction of pedestrian travel
Findings:	Outside landing ends abruptly and drops off to the grass
Rec. Solution:	Construct level landing to provide for safe emergency egress
Barrier Severity:	
Implementation	
Notes: Mid-floo	implementation rade.



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 16G
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Bottom
Code References:	2010 ADAS 505.10.3
Performance Sta	ndard: No Quantity: LF As-built : 68
Barrier Description:	Extension not sloped for length of one tread beyond the last riser nosing
Findings:	Bottom handrail extension not provided
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$15,300.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 16H
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Top
Code References:	2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built : 0
Barrier Description:	Top Handrail extension not parallel to ground/floor surface
Findings:	Top handrail extension not provided
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	2 Recommended 550.00 Family Landson Deli



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 16I
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code References:	2010 ADAS Advisory 504.4
Performance Sta	ndard: Yes Quantity: LF or TR As-built: 128
Barrier Description:	No contrasting color on each tread of interior stairway
Findings:	Treads lack contrasting color defined as 70% contrast
Rec. Solution:	Recommended: Consider providing contrasting color on each tread
Barrier Severity:	2 Recommended Cost Est \$4,480.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 16J
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 16J Dearborn Hall Reference Dwg: 2 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway 1
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Surface Condition - Existing
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Surface Condition - Existing 2010 ADAS 504.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Surface Condition - Existing 2010 ADAS 504.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Surface Condition - Existing 2010 ADAS 504.4 Indard: No Quantity: SF As-built: 240
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Surface Condition - Existing 2010 ADAS 504.4 Indard: No Quantity: SF As-built: 240 Stairway surface is not slip resistant
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Surface Condition - Existing 2010 ADAS 504.4 Indard: No Quantity: SF As-built: 240 Stairway surface is not slip resistant Slip resistant surface could not be verified Demolish and construct new stairway
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 2 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Surface Condition - Existing 2010 ADAS 504.4 Indard: No Quantity: SF As-built: 240 Stairway surface is not slip resistant Slip resistant surface could not be verified Demolish and construct new stairway A Low Severity Cost Est \$60,000.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 16K
Bldg Name:	Dearborn Hall Reference Dwg: 2 of 5
Location:	Basement - Stairway 1
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 4
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$22,000.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 16L
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 16L Dearborn Hall Reference Dwg: 3 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 3 of 5 Basement - Stairway 1
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 3 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Level
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 3 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 3 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Level ICC A117.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 3 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Level ICC A117.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 3 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Level ICC A117.1 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 3 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Level ICC A117.1 ndard: No Quantity: EACH As-built: 1 Tactile stairway signage not provided to indicate floor level
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 3 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Level ICC A117.1 Idard: No Quantity: EACH As-built: 1 Tactile stairway signage not provided to indicate floor level No sign provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 3 of 5 Basement - Stairway 1 N/A Y Coordinate: N/A Stairways Sign - Enclosed Exit Stairway Level ICC A117.1 Indard: No Quantity: EACH As-built: 1 Tactile stairway signage not provided to indicate floor level No sign provided Provide sign 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17A
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Lobby Info Sign
Code References:	Performance Standard
Performance Sta	ndard: Yes Quantity: EACH As-built : 2
Barrier Description:	No lobby informational sign with location of accessible elements
Findings:	Accessible sign not provided
Rec. Solution:	Provide lobby informational sign in both entry areas of lobby
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17B
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 17B Dearborn Hall Reference Dwg: 3 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high Relocate switch box top edge to max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 Indianate: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high Relocate switch box top edge to max. 48" high Relocate switch box top edge to max. 48" high Relocate switch box top edge to max. 48" high Relocate switch box top edge to max. 48" high Relocate switch box top edge to max. 48" high



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17C
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Sign - Permanent Room/Space
Code References:	2010 ADAS 703.1
Performance Sta	andard: No Quantity: EACH As-built : 6
Barrier Description:	No sign with raised characters and Braille at permanent room or space with visual sign
Findings:	No tactile info on sign with visual information
Rec. Solution:	Provide sign at latch side of entry door, where possible
Barrier Severity:	1 Necessary Cost Est \$1,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Rooms	112, 111, 110, 109, 108, 122
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17D
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Extinguisher - Cabinet Hardware
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Fire extinguisher door hardware not usable by those with hand impairments
Findings:	Cabinet door hardware not accessible
Rec. Solution:	Relocate fire extinguisher hardware
Barrier Severity:	
	4 Low Severity Cost Est \$1,500.00 Facility Function: Public Status: Open
Implementation	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17E
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Extinguisher - Cabinet Operation
Code References:	2010 ADAS 308.2.2
Performance Sta	indard: No Quantity: JOB As-built : 0
Barrier Description:	Fire extinguisher door involves more than 5 lbf to operate
Findings:	Cabinet door hardware not accessible
Rec. Solution:	Relocate fire extinguisher cabinet
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 9 lbf	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17F
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 17F Dearborn Hall Reference Dwg: 3 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A
Bldg Name: Location:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Corridors Protruding Object
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 3 of 5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high Electrical box protrudes 6-1/4" at 48" high Remove object or provide detectable warning (wing walls) I Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17G
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Visual Information Provided (Exhibitions)
Code References:	ADA Title II Technical Assistance Manual 3.2000 Denial of participation
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Visual sign providing information for program, service or activity not accessible
Findings:	Accessible sign not provided
Rec. Solution:	Provide information in alternate format to provide access to people with vision impairments
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: 3 resear	ch boards
Et al I Barra	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17H
Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 17H
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Drinking Fountains
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Drinking Fountains Alcove - Existing (pre-1992) 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Drinking Fountains Alcove - Existing (pre-1992) 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Drinking Fountains Alcove - Existing (pre-1992) 2010 ADAS 307.2 ndard: No Quantity: SF As-built: 1 Fountain with a leading edge between 27" and 80" high protrudes more than 4" into the
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Drinking Fountains Alcove - Existing (pre-1992) 2010 ADAS 307.2 ndard: No Quantity: SF As-built: 1 Fountain with a leading edge between 27" and 80" high protrudes more than 4" into the circulation path.
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Drinking Fountains Alcove - Existing (pre-1992) 2010 ADAS 307.2 Indard: No Quantity: SF As-built: 1 Fountain with a leading edge between 27" and 80" high protrudes more than 4" into the circulation path. Fountain protrudes 7-1/2" from alcove at 30" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Drinking Fountains Alcove - Existing (pre-1992) 2010 ADAS 307.2 rountain with a leading edge between 27" and 80" high protrudes more than 4" into the circulation path. Fountain protrudes 7-1/2" from alcove at 30" high Provide wing walls as detectable warning (existing unit only) 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17I
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Operation - Replacement
Code References:	2010 ADAS 602.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Operating mechanism involves more than 5 lbf to operate
Findings:	Push bar on fountain is badly damaged and has sharp edges
Rec. Solution:	Replace drinking fountain with accessible unit
Barrier Severity:	2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17J
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Bubbler water flow
Code References:	2010 ADAS 602.6
Performance Sta	andard: No Quantity: JOB As-built: 1
Performance Sta Barrier Description:	Mater flow from bubbler not min. 4" high
Barrier	
Barrier Description:	Water flow from bubbler not min. 4" high
Barrier Description: Findings:	Water flow from bubbler not min. 4" high 2-1/2" high water flow from bubbler Adjust drinking fountain to provide min. 4" high water flow
Barrier Description: Findings: Rec. Solution:	Water flow from bubbler not min. 4" high 2-1/2" high water flow from bubbler Adjust drinking fountain to provide min. 4" high water flow 2 Recommended Cost Est \$275.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17K
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Fire Alarm - Pull Actuator Operation
Code References:	2010 ADAS 309.4
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Fire pull has no usable hardware
Findings:	Hardware not accessible
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17L
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Fire Alarm - Pull Actuator Height
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Fire pulls not between 42" and 48" high
Findings:	62" high
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17M
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door Mat 03/17/2014 15:22
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance Sta	ndard: No Quantity: EACH As-built : 4
Barrier Description:	Recessed doormat not anchored to floor (possible trip hazard)
Findings:	Door mats not secured
Rec. Solution:	Replace door mat
Barrier Severity:	1 Necessary Cost Est \$2,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: North a	nd south entrances
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17N
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 17N Dearborn Hall Reference Dwg: 3 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3 ndard: No Quantity: LF As-built: 4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3 ndard: No Quantity: LF As-built: 4 Extension not sloped for length of one tread beyond the last riser nosing
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3 ndard: No Quantity: LF As-built: 4 Extension not sloped for length of one tread beyond the last riser nosing Bottom handrail extension not provided Provide extensions at both sides of stairway
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Stairways Handrail Extension - Bottom 2010 ADAS 505.10.3 ndard: No Quantity: LF As-built: 4 Extension not sloped for length of one tread beyond the last riser nosing Bottom handrail extension not provided Provide extensions at both sides of stairway 2 Recommended Cost Est \$900.00 Facility Function: Public Status: Open



Et al la Davis	Distriction of Distri
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 170
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code References:	2010 ADAS Advisory 504.4
Performance Sta	andard: Yes Quantity: LF or TR As-built : 24
Barrier Description:	No contrasting color on each tread of interior stairway
Findings:	Treads lack contrasting color defined as 70% contrast
Rec. Solution:	Recommended: Consider providing contrasting color on each tread
Barrier Severity:	2 Recommended Cost Est \$840.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: South E	ntrance
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17P
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Surface Condition - Existing
Code References:	2010 ADAS 504.4
Performance Sta	andard: No Quantity: SF As-built: 10
Barrier Description:	Stairway surface is not slip resistant
Findings:	Slip resistant surface could not be verified
Rec. Solution:	Demolish and construct new stairway
Barrier Severity:	4 Low Severity Cost Est \$2,500.00 Facility Function: Public Status: Open
Implementation	·
	Priority: 3 Implementation Phase: Implementation Date:



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17Q
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door Closer - Exterior Adjustment
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 8.5 lbf
Findings:	14 - 15 lbf
Rec. Solution:	Replace or adjust existing closer. Door does not lead to an accessible route
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: South E	ntrance
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17R
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door Closer - Exterior Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier	Door closer lacks min. 5 second sweep period
Description:	<u> </u>
Findings:	4 second sweep
·	
Findings:	4 second sweep Replace or adjust existing closer. Door does not lead to an accessible route
Findings: Rec. Solution:	4 second sweep Replace or adjust existing closer. Door does not lead to an accessible route 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17S
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door Threshold - >1/2"
Code References:	2010 ADAS 404.2.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate threshold exceeds 1/2" in height
Findings:	1-1/2" high
Rec. Solution:	Provide new door threshold
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes: South E	ntrance
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17T
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Bldg Name: Location:	
	Dearborn Hall Reference Dwg: 3 of 5
Location:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102
Location: X Coordinate:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Corridors Sign - Tactile Exit Sign at Door
Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Corridors
Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Corridors Sign - Tactile Exit Sign at Door 2010 ADAS 216.4.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Corridors Sign - Tactile Exit Sign at Door 2010 ADAS 216.4.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Corridors Sign - Tactile Exit Sign at Door 2010 ADAS 216.4.1 Indard: No Quantity: EACH As-built: 2
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Corridors Sign - Tactile Exit Sign at Door 2010 ADAS 216.4.1 Indard: No Quantity: EACH As-built: 2 Ground floor doors that exit directly to the exterior lacks tactile exit sign Accessible signs not provided Provide new sign stating "EXIT" at exiting side of door
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Corridors Sign - Tactile Exit Sign at Door 2010 ADAS 216.4.1 Indard: No Quantity: EACH As-built: 2 Ground floor doors that exit directly to the exterior lacks tactile exit sign Accessible signs not provided Provide new sign stating "EXIT" at exiting side of door 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17U
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Horn/Strobe Device
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	No horn or strobe in corridor where fire alarm exists in building
Findings:	No horn/strobe provided
Rec. Solution:	Provide horn/strobe in corridor every 50 feet
Barrier Severity:	1 Necessary Cost Est \$11,000.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17V
	3/25/2014 Report Date 5/27/2014 Barrier #: 17V Dearborn Hall Reference Dwg: 3 of 5
Bldg Name:	
Bldg Name: Location:	Dearborn Hall Reference Dwg: 3 of 5
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102
Field Date: Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Drinking Fountains Alcove - Existing (pre-1992)
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Drinking Fountains Alcove - Existing (pre-1992) 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Drinking Fountains Alcove - Existing (pre-1992) 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Drinking Fountains Alcove - Existing (pre-1992) 2010 ADAS 307.2 ndard: No Quantity: SF As-built: 1 Fountain with a leading edge between 27" and 80" high protrudes more than 4" into the
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Drinking Fountains Alcove - Existing (pre-1992) 2010 ADAS 307.2 ndard: No Quantity: SF As-built: 1 Fountain with a leading edge between 27" and 80" high protrudes more than 4" into the circulation path.
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Drinking Fountains Alcove - Existing (pre-1992) 2010 ADAS 307.2 Indard: No Quantity: SF As-built: 1 Fountain with a leading edge between 27" and 80" high protrudes more than 4" into the circulation path. Fountain protrudes 8" from alcove at 31-3/4" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Drinking Fountains Alcove - Existing (pre-1992) 2010 ADAS 307.2 ndard: No Quantity: SF As-built: 1 Fountain with a leading edge between 27" and 80" high protrudes more than 4" into the circulation path. Fountain protrudes 8" from alcove at 31-3/4" high Provide wing walls as detectable warning (existing unit only) 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17W
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Operation - Adjustment
Code References:	2010 ADAS 602.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Operating mechanism involves more than 5 lbf to operate
Findings:	18 lbf needs to operate
Rec. Solution:	Adjust existing controls to make accessible
Barrier Severity:	2 Recommended Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: North si	de of corridor
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17X
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
_	
Location:	Floor 1 - Central Hallway H102
Location: X Coordinate:	Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height
Location: X Coordinate: Barrier Area:	Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Controls and Mechanisms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 50" high
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: Barrier Severity:	Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 50" high Relocate switch box top edge to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: Barrier Severity: Implementation	Floor 1 - Central Hallway H102 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 50" high Relocate switch box top edge to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17Y
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Reopening
Code References:	2010 ADA 404.3.2
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Automatic doors do not reopen after encountering an obstruction
Findings:	Door does not reopen after encountering obstruction
Rec. Solution:	Adiust door mechanism
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes: North e	ntrance
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17Z
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Doormat Controlled Street
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Doormat not anchored to floor (possible trip hazard)
Findings:	Doormat not secured
Rec. Solution:	Secure exiting doormat or replace
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: North e	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 17AA
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Central Hallway H102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Door
Code References:	2010 ADAS 216.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Ground floor doors that exit to exterior lacks tactile exit sign
Findings:	Exit door with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT" at exit side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: North e	ntrance
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 18A
	3/25/2014 Report Date 5/27/2014 Barrier #: 18A Dearborn Hall Reference Dwg: 3 of 5
Bldg Name:	
Bldg Name: Location:	Dearborn Hall Reference Dwg: 3 of 5
Field Date: Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 107
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 107 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 107 N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 107 N/A Y Coordinate: N/A Restrooms Sign - Location 2010 ADAS 703.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 107 N/A Y Coordinate: N/A Restrooms Sign - Location 2010 ADAS 703.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 107 N/A Y Coordinate: N/A Restrooms Sign - Location 2010 ADAS 703.4.1 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 107 N/A Y Coordinate: N/A Restrooms Sign - Location 2010 ADAS 703.4.1 Indard: No Quantity: EACH As-built : 1 Braille/Tactile sign not mounted between 48" and 60" from floor
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 107 N/A Y Coordinate: N/A Restrooms Sign - Location 2010 ADAS 703.4.1 mdard: No Quantity: EACH As-built: 1 Braille/Tactile sign not mounted between 48" and 60" from floor 63-3/4" high Remount Braille/tactile sign at latch side of door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Women's Restroom 107 N/A Y Coordinate: N/A Restrooms Sign - Location 2010 ADAS 703.4.1 Braille/Tactile sign not mounted between 48" and 60" from floor 63-3/4" high Remount Braille/tactile sign at latch side of door 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 18B
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 107
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Reopening
Code References:	2010 ADA 404.3.2
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Automatic doors do not reopen after encountering an obstruction
Findings:	Door does not reopen after encountering obstruction
Rec. Solution:	Adjust door mechanism
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 18C
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 107
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-3/4" high
Rec. Solution:	
	Relocate switch box top edge to max. 48" high
Barrier Severity:	
Barrier Severity: Implementation	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 18D
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 107
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding dispenser creates protruding hazard in path of travel
Findings:	Paper towel dispenser protrudes 9-1/4" at 40-1/2" high
Rec. Solution:	Relocate dispenser or provide cane-detectable warning
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 18E
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 107
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	14-1/2" high under lavatory
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
	13 Hillurance Cost Est 13730.00 Tacinty Function. Public Status. Popeli
Implementation	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 18F
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 107
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Door Hardware
Code References:	2010 ADAS 604.8.1.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Stall door hardware involves tight grasping/pinching to close and no U-pull provided
Findings:	No U-pull provided
Rec. Solution:	Provide U-pull hardware on outside and inside of stall door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 18G
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 107
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Grab Bars
Code References:	2010 ADAS 604.5 & 609.8
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Grab bars not secure or cannot bear min. 250 N of force
Findings:	Side grab bar is mounted on the partition wall
Rec. Solution:	Replace grab bars with reinforcement
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	Friority. [3] Implementation Friase.



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 18H
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Women's Restroom 107
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/stobe in sanitary facility
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 19A
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Men's Restroom 106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - Location
Code References:	2010 ADAS 703.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Braille/Tactile sign not mounted between 48" and 60" from floor
Findings:	63-3/4" high
Rec. Solution:	Remount Braille/tactile sign at latch side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Also, bra	aille not located directly below tactile characters between 3/8" and max. 1/2" from tactile



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 19B
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Men's Restroom 106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Timing
Code References:	2010 ADAS 404.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Door does not remain open for at least 6 seconds
Findings:	Could not test opening timing as opening mechanism was not functioning
Rec. Solution:	Repair actuation device
Barrier Severity:	1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 19C
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 19C Dearborn Hall Reference Dwg: 3 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Men's Restroom 106A
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Men's Restroom 106A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Men's Restroom 106A N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Men's Restroom 106A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Men's Restroom 106A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Men's Restroom 106A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Men's Restroom 106A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Men's Restroom 106A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high S1-1/2" high Relocate switch box top edge to max. 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Men's Restroom 106A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high S1-1/2" high Relocate switch box top edge to max. 48" high Relocate switch box top edge to max. 48" high A Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 19D
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Men's Restroom 106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Floor Drain - Existing
Code References:	2010 ADAS 304.2
Performance Sta	ndard: No Quantity: SF As-built: 60
Barrier Description:	Floor drain located within clear floor space of fixture
Findings:	3% slope and located in clear floor space of accessible sink
Rec. Solution:	Remodel to provide level landing at fixtures
Barrier Severity:	3 Hindrance Cost Est \$15,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 19E
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Men's Restroom 106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Entry - Front Approach -Pull
Code References:	2010 ADAS 604.8.1.2 & Table 404.2.4.1
Performance Sta	ndard: No Quantity: JOB As-built: 1
Barrier Description:	Door with front approach corridor (pull side) lacks min. 60" space perpendicular to door
Findings:	39" perpendicular to door
Rec. Solution:	Replace compartment or remove screen
Barrier Severity:	2 Recommended Cost Est \$1,650.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: To urina	ll privacy screen



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 19F
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Men's Restroom 106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Door Hardware
Code References:	2010 ADAS 604.8.1.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Stall door hardware involves tight grasping/pinching to close and no U-pull provided
Findings:	No U-pull provided
Rec. Solution:	Provide U-pull hardware on outside and inside of stall door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 19G
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Men's Restroom 106A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/strobe in sanitary facility
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 20
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Elevator E101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Doorjamb marking
Code References:	2010 ADAS 407.2.3.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Elevator landing door jamb signage not located 60" on center on both jamb panels
Findings:	54" high on center
Rec. Solution:	Replace door jamb signage
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 56" to t	ор
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 21A
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Hallway H101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Sign - Permanent Room/Space
Code References:	2010 ADAS 703.1
Performance Sta	indard: No Quantity: EACH As-built : 6
Barrier Description:	No sign with raised characters and Braille at permanent room or space with visual sign
Findings:	No tactile info on sign with visual information
Rec. Solution:	Provide sign at latch side of entry door, where possible
Barrier Severity:	1 Necessary Cost Est \$1,500.00 Facility Function: Public Status: Open
Implementation	
Notes: Rooms	100, 101, 102, 104, 105, 106
ļ	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 21B
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Hallway H101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Braille - Location Below Characters
Code References:	2010 ADAS 703.2.3.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Braille on sign not located directly below tactile characters
Findings:	Accessible sign not provided
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Room 1	03. Also, Contracted (Grade 2) Braille not used on sign
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 21C
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Hallway H101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 21D
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Hallway H101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Mailbox - High Reach Range
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Mailbox opening is above 48" high
Findings:	73-1/2" high
Rec. Solution:	Relocate to provide opening at max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 21E
	3/25/2014 Report Date 5/27/2014 Barrier #: 21E Dearborn Hall Reference Dwg: 3 of 5
Field Date: Bldg Name: Location:	
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Hallway H101
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Hallway H101 N/A Y Coordinate: N/A Corridors Protruding Object
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Hallway H101 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Hallway H101 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Hallway H101 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Hallway H101 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Hallway H101 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Hallway H101 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high Mailbox protrudes 8" at 59-1/2" high Remove object or provide detectable warning (wing walls)
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance State Barrier Description:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Hallway H101 N/A Y Coordinate: N/A Corridors Protruding Object 2010 ADAS 307 Indard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high Mailbox protrudes 8" at 59-1/2" high Remove object or provide detectable warning (wing walls) I Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 21F
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Hallway H101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Extinguisher - Side Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Fire extinguisher forward or side reach exceeds 48"
Findings:	50" high cabinet hardware
Rec. Solution:	Relocate fire extinguisher
Barrier Severity:	4 Low Severity Cost Est \$1,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 21G
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Hallway H101
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No strobe provided in corridor where horn is provided where fire alarm exists in building
Findings:	No strobe where horn is provided
Rec. Solution:	Provide strobe in common use area
Rec. Solution: Barrier Severity:	
	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 22A
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Entry do	oor and Class Lab Support 120A in classroom
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 22B
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	13 - 14 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 22C
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	2 - 3 second sweep
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 22D
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not fist operable
Rec. Solution:	Replace hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	implementation rhase.



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 22E
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Door Stop
Code References:	2010 ADAS 404.2.10
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door stop interrupts min.10" smooth bottom surface
Findings:	Door stop at bottom of door can create trapping condition
Rec. Solution:	Remove door stop or other element at bottom of door at push side
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 22F
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Doorway - Front App 48"
Code References:	2010 ADAS 404.2.4.2
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door opening lacks min. 48" perpendicular to door
Findings:	Maneuvering clearance perpendicular to door measured at less than 48"
Rec. Solution:	Remove desks and garbage can
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
Notes: 33" perp	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 22G
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	58-3/4" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 22H
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	First Aid Kit - Obstructed Reach Range
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Opening mechanism on first aid kit not at max. 44" over an obstruction of max. 25"
Findings:	63" high and 21-1/4" deep over an obstruction 29-1/4" high
Rec. Solution:	Relocate control or mechanism
	inclocate control of mechanism
Barrier Severity:	
Barrier Severity: Implementation	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 22I
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Ratio
Code References:	2010 ADAS 902
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	At least 1 desk or 5% of all desks are not accessible
Findings:	Accessible desks not provided
Rec. Solution:	Provide at least 2 accessible desks
Barrier Severity:	3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 26 desk	s. None are accessible
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 22J
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	25-1/4" high, 11-1/2" deep, 29-1/4" wide knee clearance
Rec. Solution:	Provide accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 26 desk	s. None are accessible



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 22K
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	Passageway less than 36" in multiple locations
Rec. Solution:	Rearrange furniture to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 18" - 31	" wide circulation route between desks
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 22L
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Display case protrudes 11-1/2" at 42-1/2" high
-	Display case protrudes 11-1/2" at 42-1/2" high Remove object or provide detectable warning (wing walls)
Findings: Rec. Solution: Barrier Severity:	Remove object or provide detectable warning (wing walls)
Rec. Solution:	Remove object or provide detectable warning (wing walls) 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 22M
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24-1/4" high knee clearance
Rec. Solution:	Provide accessible workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 13 work	stations and none are accessible
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 22N
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Shelves or Cabinets
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Shelf or cabinet not mounted max. 48" above floor or ground
Findings:	Shelf or cabinet not accessible
Rec. Solution:	Provide additional shelf at accessible height or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
	a minurance Cost Est 50.00 Facility Function: Public Status. Open
Implementation	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 220
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Forward Reach High Unobstructed
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Electrical devices 45-3/4" - 61-3/4" high over 21-1/2" deep desk obstruction 29" high
Rec. Solution:	Relocate within accessible reach range
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 22P
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Darrian Tunas	Joseph Million Williams
Barrier Type:	Actuator/Control - Hi/low Reach
Code References:	
Code	Actuator/Control - Hi/low Reach 2010 ADAS 308.2.2
Code References:	Actuator/Control - Hi/low Reach 2010 ADAS 308.2.2
Code References: Performance Sta Barrier	Actuator/Control - Hi/low Reach 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 1
Code References: Performance Sta Barrier Description:	Actuator/Control - Hi/low Reach 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 1 Use of control involves low reach of less than 15" above floor or more than 48" high
Code References: Performance Sta Barrier Description: Findings:	Actuator/Control - Hi/low Reach 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 1 Use of control involves low reach of less than 15" above floor or more than 48" high Electrical control box 54-1/2" high Relocate to area at min. 15" or max. 48" high
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Actuator/Control - Hi/low Reach 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 1 Use of control involves low reach of less than 15" above floor or more than 48" high Electrical control box 54-1/2" high Relocate to area at min. 15" or max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 22Q
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code	2010 ADAS 307
References:	
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	TV protrudes 6-3/4" at 43-1/4" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 22R
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard & 2010 ADAS 904.3.3
Performance Sta	indard: Yes Quantity: EACH As-built : 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 45-1/4" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
and the second s	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 22S
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 120
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 23A
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - COE Helpdesk Room 120A College of
X Coordinate:	N/A Y Coordinate: N/A Englering Help Desk
Barrier Area:	Signage
Barrier Type:	Braille - Multi-lined Braille
Code References:	2010 ADAS .2.3.2
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Braille not placed below all multi-lined tactile characters in one line together
Findings:	Accessible sign not provided
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Also, Br	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 23B
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - COE Helpdesk Room 120A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not fist operable
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 23C
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - COE Helpdesk Room 120A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 60" - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	indard: No Quantity: ADMINI As-built: 1
Barrier Description:	Door/Gate at with min. 18" at pull side lacks min. 60" perpendicular to door
Findings:	Maneuvering clearance perpendicular to door measured at less than 48"
Rec. Solution:	Remove stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 23D
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - COE Helpdesk Room 120A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Lockers - Control
Code References:	2010 ADAS 803.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Locker mechanism not operable with fist or involves turning and grasping
Findings:	Mechanism not fist operable
Rec. Solution:	Provide min. 1 accessible locker or 5% overall
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 23E
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - COE Helpdesk Room 120A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard & 2010 ADAS 904.3.3
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 46" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 23F
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - COE Helpdesk Room 120A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Hi/low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Use of control involves low reach of less than 15" above floor or more than 48" high
Findings:	Hooks 74" high. Table and chair block hooks clear floor space
Rec. Solution:	Relocate to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 23G
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - COE Helpdesk Room 120A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	andard: No Quantity: JOB As-built: 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	Passageway less than 36" in multiple locations
Rec. Solution:	Rearrange furniture to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 27-1/2"	wide circulation route between table and desk



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 23H
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - COE Helpdesk Room 120A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 304.3.1
Performance Sta	andard: No Quantity: SF As-built : 20
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	32" turning circle behind desk
Rec. Solution:	Remodel area to provide min. 60" turning space
Barrier Severity:	2 Recommended Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 23I
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - COE Helpdesk Room 120A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Rec. Solution: Barrier Severity:	
	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 24A
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - COE Computer Lab Room 119
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: COE Cor	mputer Lab and Room 120A
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 24B
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 24B Dearborn Hall Reference Dwg: 3 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - COE Computer Lab Room 119
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - COE Computer Lab Room 119 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - COE Computer Lab Room 119 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - COE Computer Lab Room 119 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - COE Computer Lab Room 119 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - COE Computer Lab Room 119 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - COE Computer Lab Room 119 N/A
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - COE Computer Lab Room 119 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 13 lbf Provide automatic door opening device
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - COE Computer Lab Room 119 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf Provide automatic door opening device I Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 24C
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - COE Computer Lab Room 119
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	2 second sweep
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 24D
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - COE Computer Lab Room 119
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	4" strike edge clearance to recycling bin
Rec. Solution:	Remove stored item
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 24E
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - COE Computer Lab Room 119
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Passage
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built: 1
Barrier Description:	Exit thru an exit enclosure/exit passageway lacks tactile exit sign
Findings:	Passageway to exterior exit with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT ROUTE" at exit side of door
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 24F
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - COE Computer Lab Room 119
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	58-1/4" high. Garbage can blocks light switch clear floor space
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	: 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 24G
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - COE Computer Lab Room 119
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Surface Height
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Surface height exceeds 34" high
Findings:	44" high standing desk at display
Rec. Solution:	Provide min. 1 accessible desk or workstation in this area of lab
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 24H
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - COE Computer Lab Room 119
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Hi/low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of control involves low reach of less than 15" above floor or more than 48" high
Findings:	Projector screen pull 66" high
Rec. Solution:	Relocate to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 24I
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - COE Computer Lab Room 119
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Ratio
Code References:	2010 ADAS 902
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	At least 1 desk or 5% of all desks are not accessible
Findings:	Accessible desks not provided
Rec. Solution:	Provide at least 2 accessible desks
Barrier Severity:	3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 28 work	stations. None are accessible
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 24J
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 24J Dearborn Hall Reference Dwg: 3 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - COE Computer Lab Room 119
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - COE Computer Lab Room 119 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - COE Computer Lab Room 119 N/A Y Coordinate: N/A Counters and Tables
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - COE Computer Lab Room 119 N/A Y Coordinate: N/A Counters and Tables Desk - Knee Clearance 2010 ADAS 902.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - COE Computer Lab Room 119 N/A Y Coordinate: N/A Counters and Tables Desk - Knee Clearance 2010 ADAS 902.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - COE Computer Lab Room 119 N/A Y Coordinate: N/A Counters and Tables Desk - Knee Clearance 2010 ADAS 902.3 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - COE Computer Lab Room 119 N/A Y Coordinate: N/A Counters and Tables Desk - Knee Clearance 2010 ADAS 902.3 ndard: No Quantity: EACH As-built: 0 Knee clearance not min. 27" high, 19" deep or 30" wide
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - COE Computer Lab Room 119 N/A Y Coordinate: N/A Counters and Tables Desk - Knee Clearance 2010 ADAS 902.3 ndard: No Quantity: EACH As-built: 0 Knee clearance not min. 27" high, 19" deep or 30" wide 25" high knee clearance Provide accessible desk or workstation
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - COE Computer Lab Room 119 N/A Y Coordinate: N/A Counters and Tables Desk - Knee Clearance 2010 ADAS 902.3 ndard: No Quantity: EACH As-built: 0 Knee clearance not min. 27" high, 19" deep or 30" wide 25" high knee clearance Provide accessible desk or workstation 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 24K
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - COE Computer Lab Room 119
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Podium - Surface Height
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Surface height exceeds 34" high
Findings:	44" surface height. Recycling bins block podium clear floor space
Rec. Solution:	Provide min. 1 accessible podium
Barrier Severity:	3 Hindrance Cost Est \$1,275.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 24L
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - COE Computer Lab Room 119
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code	PRODUCTION OF THE PROPERTY OF
References:	2010 ADAS 702.1
References:	
References: Performance Sta Barrier	andard: No Quantity: EACH As-built : 1
References: Performance Sta Barrier Description:	nndard: No Quantity: EACH As-built : 1 No horn/strobes in common use areas
References: Performance Sta Barrier Description: Findings:	No Quantity: EACH As-built: 1 No horn/strobes in common use areas No device provided Provide strobe in common use area
References: Performance Sta Barrier Description: Findings: Rec. Solution:	No Quantity: EACH As-built: 1 No horn/strobes in common use areas No device provided Provide strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25A
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 4
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$1,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Rooms 2	118 (north entrance), 118B, 188C
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25B
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Location - 48" to 60" high
Code References:	2010 ADAS 703.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor
Findings:	63-1/4" high
Rec. Solution:	Provide accessible sign and mount at proper height
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Also, Co	ontracted (Grade 2) Braille not used on sign



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25C
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	10 - 16 lbf
Rec. Solution:	Provide automatic door opening device at one door and ISA sign at other door
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25D
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Door Closer - Sweep 03/18/2014 17:19
Code References:	2010 ADAS 404.2.8.1
Performance Sta	indard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	3 - 4 second sweep
Rec. Solution:	Provide automatic door opening device at one door and ISA sign at other door
Barrier Severity:	Cost Est. 60.00 Escilitu Europiana D. U. Chatura
	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25E
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Door Hardware
Code References:	2010 ADAS 404.2.10
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door stop interrupts min. 10" smooth bottom surface
Findings:	Door stop at bottom of door can create trapping condition
Rec. Solution:	Remove door stop or other element at bottom of accessible entry door at push side
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25F
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Door
Code References:	2010 ADAS 216.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	Ground floor doors that exit to exterior lacks tactile exit sign
Findings:	Exit door with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT" at exit side of door
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Both en	try doors



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25G
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Ramps
Barrier Type:	Ramp Landing - Top Landing
Code References:	2010 ADAS 405.7.3
Performance Sta	ndard: No Quantity: LF As-built : 18
Barrier Description:	Top landing is not min. 60" long
Findings:	39" and 40-1/2" top landing length on inside of ramp
Rec. Solution:	Replace handrails at both sides of one ramp designated as accessible entrance
Barrier Severity:	2 Recommended Cost Est \$3,600.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Both en	try doors have ramps - Slope is 4.7% and 4.6% Outside edge of landing length 72" and 74-1/3"
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25H
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Ramps
Barrier Type:	Handrail
Code References:	2010 ADAS 505.2
Performance Sta	ndard: No Quantity: LF As-built : 22
Barrier Description:	No handrail provided at both sides
Findings:	Ramp lacks handrail at both sides
Rec. Solution:	Replace handrails at both sides of one ramp designated as accessible entrance
Barrier Severity:	1 Necessary Cost Est \$4,950.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Both en	try doors have ramps. No hand rails on either side



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 251
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	56" - 60-1/4" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25J
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Actuator/Control - Forward Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Red phone at 50" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	Control Here on the state of the control form
	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25K
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12-1/4" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25L
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Actuator/Control - Forward Reach High Unobstructed
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	Control or mechanism not at min. 15" or max. 48" high
Findings:	Heating, vent controls and projector control 57-1/2" - 68" high
Rec. Solution:	Relocate control or mechanism to min. 15" or max. 48" high
Barrier Severity:	
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25M
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Ratio
Code References:	2010 ADAS 902
Performance Sta	ndard: No Quantity: EACH As-built : 8
Barrier Description:	At least 1 desk or 5% of all desks are not accessible
Findings:	Accessible desks not provided
Rec. Solution:	Provide at least 8 accessible desks
Barrier Severity:	3 Hindrance Cost Est \$7,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 150 des	ks provided. None are accessible
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25N
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 25N Dearborn Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Auditorium 118
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Auditorium 118 N/A Y Coordinate: N/A Classrooms Desk - Knee Clearance
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Auditorium 118 N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Auditorium 118 N/A Y Coordinate: N/A Classrooms Desk - Knee Clearance 2010 ADAS 902
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Auditorium 118 N/A Y Coordinate: N/A Classrooms Desk - Knee Clearance 2010 ADAS 902
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Auditorium 118 N/A Y Coordinate: N/A Classrooms Desk - Knee Clearance 2010 ADAS 902 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Auditorium 118 N/A Y Coordinate: N/A Classrooms Desk - Knee Clearance 2010 ADAS 902 ndard: No Quantity: EACH As-built: 0 Knee clearance of at least 27" high, 30" wide and 8" deep not provided underneath desk
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Auditorium 118 N/A Y Coordinate: N/A Classrooms Desk - Knee Clearance 2010 ADAS 902 Indard: No Quantity: EACH As-built: 0 Knee clearance of at least 27" high, 30" wide and 8" deep not provided underneath desk 10" deep, 18-1/2" wide knee clearance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Auditorium 118 N/A Y Coordinate: N/A Classrooms Desk - Knee Clearance 2010 ADAS 902 March Reference Dwg: 3 of 5 N/A Y Coordinate: N/A Classrooms Desk - Knee Clearance 2010 ADAS 902 March Reference Dwg: 3 of 5 N/A Y Coordinate: N/A Desk - Knee Clearance 2010 ADAS 902 March Reference Dwg: 3 of 5 N/A Post Reference Dwg: 3 of 5 N/A Post Reference Dwg: 3 of 5 N/A N/A N/A Post Reference Dwg: 3 of 5 N/A N/A N/A N/A Post Reference Dwg: 3 of 5 N/A N/A Post Reference Dwg: 3 of 5 N/A N/A N/A N/A N/A N/A N/A N/



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 250
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Integration
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 8
Barrier Description:	Desk not integrated into assembly seating
Findings:	Desk identified as accessible is not integrated into typical seating
Rec. Solution:	Provide min. 8 accessible desks and move into integrated setting
Barrier Severity:	2 Necessary Cost Est \$7,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25P
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 25P Dearborn Hall Reference Dwg: 3 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Auditorium 118
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Auditorium 118 N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Auditorium 118 N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Auditorium 118 N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Auditorium 118 N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Auditorium 118 N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2 Indard: No Quantity: SF As-built: 5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 3 of 5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Auditorium 118 N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2 Indard: No Quantity: SF As-built: 5 Podium knee clearance not min. 27" high, 19" deep or 30" wide 14-1/2" deep knee clearance Provide min. 1 accessible podium
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Auditorium 118 N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2 Indard: No Quantity: SF As-built: 5 Podium knee clearance not min. 27" high, 19" deep or 30" wide 14-1/2" deep knee clearance Provide min. 1 accessible podium A Low Severity Cost Est \$1,250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25Q
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Workstation - Surface Max. 34"
Code References:	2010 ADAS 902
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Workstation surface height exceeds 34" high
Findings:	36" high workstation surface at front of room
Rec. Solution:	Provide accessible workstation where students may give presentations
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25R
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Stairway Handrail - Both Sides
Code References:	2010 ADAS 306.3.2
Performance Sta	ndard: No Quantity: JOB As-built : 24
Barrier Description:	No handrail provided at both sides of stairway
Findings:	No handrail provided at both sides
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	1 Necessary Cost Est \$5,400.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25S
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Stairway Tread - Contrasting Color
Code References:	2010 ADAS Advisory 504.4
Performance Sta	andard: Yes Quantity: LF or TR As-built: 36
Barrier Description:	No contrasting color on each tread of interior stairway
Findings:	Treads lack contrasting color defined as 70% contrast
Rec. Solution:	Recommended: Consider providing contrasting color on each tread
Barrier Severity:	2 Recommended Cost Est \$1,260.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25T
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Surface Condition - Existing
Code References:	2010 ADAS 504.4
Performance Sta	andard: No Quantity: SF As-built: 16
Barrier Description:	Stairway surface is not slip resistant
Findings:	Slip resistant surface could not be verified
	<u> </u>
Rec. Solution:	Demolish and construct new stairway
Rec. Solution: Barrier Severity:	
	4 Low Severity Cost Est \$4,000.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25U
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Accessible Route - Remodel
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 150
Barrier Description:	Clear floor space does not adjoin an accessible route or another space
Findings:	No accessible route to teacher's desk because of stairs
Rec. Solution:	Remodel path of travel to provide connection to accessible route
Barrier Severity:	2 Recommended Cost Est \$26,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 25V
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Auditorium 118
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Alarm - No Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 26A
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Exterior Hall and Stairway S102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Door Closer - Exterior Adjustment
Code References:	Performance Standard
Performance Sta	indard: Yes Quantity: EACH As-built : 2
Barrier Description:	Door opening force exceeds 8. 5 lbf
Findings:	12 - 15 lbf
Rec. Solution:	Replace or adjust existing closer. Door does not lead to an accessible route
Barrier Severity:	1 Necessary Cost Est \$900.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Both do	ors to the indoor stairway on the first level
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 26B
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Exterior Hall and Stairway S102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
Dairiei Area.	Stairways
Barrier Type:	Stairways Door Closer - Interior Sweep ADA
	Stairways
Barrier Type: Code	Stairways Door Closer - Interior Sweep ADA 2010 ADAS 404.2.8.1
Barrier Type: Code References:	Stairways Door Closer - Interior Sweep ADA 2010 ADAS 404.2.8.1
Barrier Type: Code References: Performance Sta Barrier	Stairways Door Closer - Interior Sweep ADA 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0
Barrier Type: Code References: Performance Sta Barrier Description:	Stairways Door Closer - Interior Sweep ADA 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Stairways Door Closer - Interior Sweep ADA 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period 4 second sweep Replace or adjust existing closer. Door does not lead to an accessible route
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Stairways Door Closer - Interior Sweep ADA 2010 ADAS 404.2.8.1 Indard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period 4 second sweep Replace or adjust existing closer. Door does not lead to an accessible route 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 26C
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Exterior Hall and Stairway S102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	8" - 10" strike edge clearance
Rec. Solution:	No remediation recommended. Door does not lead to an accessible route
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Both do	ors to the indoor stairway on the first level
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 26D
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Exterior Hall and Stairway S102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	
Notes: North de	oor



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 26E
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Exterior Hall and Stairway S102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Bottom
Code References:	2010 ADAS 505.10.3
Performance Sta	indard: No Quantity: LF As-built: 0
Barrier Description:	Extension not sloped for length of one tread beyond the last riser nosing
Findings:	Bottom handrail extension not provided
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 26F
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Exterior Hall and Stairway S102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Top Length
Code References:	2010 ADAS 505.10.2
Performance Sta	indard: No Quantity: LF As-built : 0
Barrier Description:	Top Handrail extension does not extend for one tread width or min. 12"
Findings:	Top handrail extension not provided
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 26G
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Exterior Hall and Stairway S102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code References:	2010 ADAS Advisory 504.4
Performance Sta	andard: Yes Quantity: LF or TR As-built : 16
Barrier Description:	No contrasting color on each tread of interior stairway
Findings:	Treads lack contrasting color defined as 70% contrast
Rec. Solution:	Recommended: Consider providing contrasting color on each tread
Barrier Severity:	2 Recommended Cost Est \$560.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 26H
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Exterior Hall and Stairway S102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Surface Condition - Existing
Code References:	2010 ADAS 504.4
Performance Sta	indard: No Quantity: SF As-built: 18
Barrier Description:	Stairway surface is not slip resistant
Findings:	Slip resistant surface could not be verified
Rec. Solution:	Demolish and construct new stairway
Barrier Severity:	
	4 Low Severity Cost Est \$4,500.00 Facility Function: Public Status: Open
Implementation	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 261
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Exterior Hall and Stairway S102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built: 3
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$16,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 26J
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Exterior Hall and Stairway S102
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Threshold - Height exceeding 1/2"
Code References:	2010 ADAS 404.2.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate threshold exceeds 1/2" in height
Findings:	1-1/2" high
Rec. Solution:	Provide new door threshold
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes: Part of t	he route to the north accessible entry to Dearborn Hall



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 27A
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - North Hallway H105
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - BHMA Sign
Code References:	ANSI/BHMA A156.10-1999
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No sign on door visible from both sides reading, "AUTOMATIC DOOR"
Findings:	No sign provided
Rec. Solution:	Provide new sign on both sides of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes: ISA sign	provided
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 27B
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - North Hallway H105
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Automatic Doors - Reopening
Code References:	2010 ADA 404.3.2
	,
Performance Sta	ndard: No Quantity: JOB As-built : 1
Performance Sta Barrier Description:	Automatic doors do not reopen after encountering an obstruction
Barrier	
Barrier Description:	Automatic doors do not reopen after encountering an obstruction
Barrier Description: Findings:	Automatic doors do not reopen after encountering an obstruction Door does not reopen after encountering obstruction Adjust door mechanism
Barrier Description: Findings: Rec. Solution:	Automatic doors do not reopen after encountering an obstruction Door does not reopen after encountering obstruction Adjust door mechanism 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 27C
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - North Hallway H105
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Door
Code References:	2010 ADAS 216.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Ground floor doors that exit to exterior lacks tactile exit sign
Findings:	Exit door with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Provide sign stating "EXIT" at exit side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 27D
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - North Hallway H105
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Door Hardware
Code References:	2010 ADAS 404.2.10
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door stop interrupts min. 10" smooth bottom surface
Findings:	Door stop at bottom of door can create trapping condition
Rec. Solution:	No remediation recommended. Mechanism not present on door equipped with opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 27E
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - North Hallway H105
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Door Mat
Code References:	2010 ADAS 302.2 & Advisory 302.2
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	Recessed doormat not anchored to floor (possible trip hazard)
Findings:	Door mats not secured
Rec. Solution:	Replace door mat
Barrier Severity:	1 Necessary Cost Est \$1,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Door Ba	rriers to Rogers Hall noted in Rogers Database
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 27F
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - North Hallway H105
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" - 50-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	
Notes: Door Ba	rriers to Rogers Hall noted in Rogers Database



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 27G
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - North Hallway H105
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Sign - Permanent Room/Space
Code References:	2010 ADAS 703.1
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	No sign with raised characters and Braille at permanent room or space with visual sign
Findings:	No tactile info on sign with visual information
Rec. Solution:	Provide sign at latch side of entry door, where possible
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Rooms 2	113, 114
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 27H
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - North Hallway H105
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Horn/Strobe Device
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn or strobe in corridor where fire alarm exists in building
Findings:	No horn/strobe provided
Rec. Solution:	Provide horn/strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes: Door Ba	rriers to Rogers Hall noted in Rogers Database



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 28A
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 115
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Both do	ors
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 28B
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 115
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	11 - 13 lbf
Rec. Solution:	Provide automatic door opening device at one door and ISA sign at other door
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 28C
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 115
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	3 - 4 second sweep
Rec. Solution:	Provide automatic door opening device at one door and ISA sign at other door
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 28D
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 115
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	View panel located higher than 43" above the floor
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	· · · · · · · · _
Notes: 47-1/4"	high



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 28E
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 115
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Threshold
Code References:	2010 ADAS 404.2.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate threshold exceeds 1/2" in height
Findings:	Threshold has multiple lips
Rec. Solution:	Provide new threshold
Barrier Severity:	1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 28F
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 115
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Doors or Gates
	Doors or Gates Recessed Door - Push Side
Barrier Area:	Doors or Gates
Barrier Area: Barrier Type: Code	Doors or Gates Recessed Door - Push Side 2010 ADAS 404.2.4.3
Barrier Area: Barrier Type: Code References:	Doors or Gates Recessed Door - Push Side 2010 ADAS 404.2.4.3
Barrier Area: Barrier Type: Code References: Performance Sta	Doors or Gates Recessed Door - Push Side 2010 ADAS 404.2.4.3 ndard: No Quantity: EACH As-built: 0
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Doors or Gates Recessed Door - Push Side 2010 ADAS 404.2.4.3 ndard: No Quantity: EACH As-built: 0 Door recessed by more than 8" lacks at least 12" clearance at push side of door
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Doors or Gates Recessed Door - Push Side 2010 ADAS 404.2.4.3 ndard: No Quantity: EACH As-built: 0 Door recessed by more than 8" lacks at least 12" clearance at push side of door Door to exterior corridor recessed 11-1/2" at push side
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Doors or Gates Recessed Door - Push Side 2010 ADAS 404.2.4.3 ndard: No Quantity: EACH As-built: 0 Door recessed by more than 8" lacks at least 12" clearance at push side of door Door to exterior corridor recessed 11-1/2" at push side Provide ISA directional sign to accessible entrance/exit door 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 28G
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 115
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	11-1/4" strike edge clearance
Rec. Solution:	Move copier machine
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Door to	H105 exterior corridor
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 28H
Dida Namas	
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Teaching Lab 115
•	
Location:	Floor 1 - Teaching Lab 115
Location: X Coordinate:	Floor 1 - Teaching Lab 115 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height
Location: X Coordinate: Barrier Area:	Floor 1 - Teaching Lab 115 N/A Y Coordinate: N/A Controls and Mechanisms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 1 - Teaching Lab 115 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 1 - Teaching Lab 115 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 1 - Teaching Lab 115 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 andard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 1 - Teaching Lab 115 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 andard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 1 - Teaching Lab 115 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 andard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high Relocate switch box top edge to max. 48" high
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 1 - Teaching Lab 115 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2 Andard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 49-3/4" - 50" high Relocate switch box top edge to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 281
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 115
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Router cabinet protrudes 26" at 69" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 28J
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 115
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Ratio
Code References:	2010 ADAS 902
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	At least 1 desk or 5% of all desks are not accessible
Findings:	Accessible desks not provided
Rec. Solution:	Provide at least 3 accessible desks or workstations
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	
Notes: 20 desk	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 28K
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 115
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	25-1/2" high knee clearance
Rec. Solution:	Provide min. 1 accessible PC desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: At 20 de	esks
-	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 28L
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 28L Dearborn Hall Reference Dwg: 3 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Teaching Lab 115
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Teaching Lab 115 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Teaching Lab 115 N/A Y Coordinate: N/A Classrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Teaching Lab 115 N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Teaching Lab 115 N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Teaching Lab 115 N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2 Indard: No Quantity: SF As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Teaching Lab 115 N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2 Indard: No Quantity: SF As-built : 1 Podium knee clearance not min. 27" high, 19" deep or 30" wide
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 3 of 5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 3 of 5 Floor 1 - Teaching Lab 115 N/A Y Coordinate: N/A Classrooms Podium - Knee Clearance 2010 ADAS 504.2 Indard: No Quantity: SF As-built: 1 Podium knee clearance not min. 27" high, 19" deep or 30" wide 14-3/4" deep knee clearance. Podium blocks AV controls clear floor space Provide min. 1 accessible podium where students may give presentations 4 Low Severity Cost Est \$1,275.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 28M
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 115
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24-1/2" high, 27-1/4" wide knee clearance
Rec. Solution:	Provide min. 1 accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 4 tables	and none are accessible
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 28N
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 115
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	9" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
	,
Barrier Severity:	
Barrier Severity: Implementation	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 280
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 115
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 304.3.1
Performance Sta	andard: No Quantity: SF As-built: 100
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	36" - 42" turning circle at ends of rows
Rec. Solution:	Remodel area to provide min. 60" turning space
Barrier Severity:	2 Recommended Cost Est \$17,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 28P
Bldg Name:	Dearborn Hall Reference Dwg: 3 of 5
Location:	Floor 1 - Teaching Lab 115
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 29A
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 3
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	8 - 12 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$1,350.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 29B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier	Door closer lacks min. 5 second sweep period
Description:	<u> </u>
Description: Findings:	2 - 3 second sweep
·	2 - 3 second sweep Replace or adjust existing closer
Findings:	Replace or adjust existing closer
Findings: Rec. Solution:	Replace or adjust existing closer 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 29C
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Enclosed Stairway
Code References:	ICC A117.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Tactile stairway signage not provided to indicate stair level
Findings:	Tactile sign not provided inside stairway at landing
Rec. Solution:	Provide accessible sign
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 29D
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Tactile Exit Signs - Passage
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built : 1
Barrier Description:	Exit thru an exit enclosure/exit passageway lacks tactile exit sign
Findings:	Passageway to exterior exit with low level illuminated sign lacks tactile exit sign
Rec. Solution:	Described to the MENIT DOLLTEN of the State of the second streets of
	Provide sign stating "EXIT ROUTE" at exit side of door entering stairway
Barrier Severity:	
Barrier Severity: Implementation	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 29E
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Height
Code References:	2010 ADAS 505.10.2
Performance Sta	andard: No Quantity: LF As-built : 36
Barrier Description:	Handrail grip measured at center not 34"- 38" high
Findings:	29-1/2" - 30-1/2" handrail grip height
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$8,100.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 29F
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Bottom
Code References:	2010 ADAS 505.10.3
Performance Sta	andard: No Quantity: LF As-built : 0
Performance Sta Barrier Description:	Extension not sloped for length of one tread beyond the last riser nosing
Barrier	
Barrier Description:	Extension not sloped for length of one tread beyond the last riser nosing
Barrier Description: Findings:	Extension not sloped for length of one tread beyond the last riser nosing Bottom handrail extension not provided Provide handrails at both sides of stairway
Barrier Description: Findings: Rec. Solution:	Extension not sloped for length of one tread beyond the last riser nosing Bottom handrail extension not provided Provide handrails at both sides of stairway 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 29G
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Handrail Extension - Top
Code References:	2010 ADAS 505.10.2
Performance Sta	ndard: No Quantity: LF As-built : 0
Barrier Description:	Top Handrail extension not parallel to ground/floor surface
Findings:	Top handrail extension not provided
Rec. Solution:	Provide handrails at both sides of stairway
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 29H
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Contrasting Color - ADA
Code References:	2010 ADAS Advisory 504.4
Performance Sta	ndard: Yes Quantity: LF or TR As-built : 48
Barrier Description:	No contrasting color on each tread of interior stairway
Findings:	Treads lack contrasting color defined as 70% contrast
Rec. Solution:	Recommended: Consider providing contrasting color on each tread
Barrier Severity:	2 Recommended Cost Est \$1,680.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 29I
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Surface Condition - Existing
Code References:	2010 ADAS 504.4
Performance Sta	andard: No Quantity: SF As-built: 110
Barrier Description:	Stairway surface is not slip resistant
Findings:	Slip resistant surface could not be verified
Rec. Solution:	Demolish and construct new stairway
Barrier Severity:	4 Low Severity Cost Est \$27,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 29J
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	indard: No Quantity: EACH As-built : 2
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$11,000.00 Facility Function: Public Status: Open
Implementation	<u> </u>
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 30A
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Hallway H204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 3
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible signs
Barrier Severity:	1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Rooms 2	201, 220, 221
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 30B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Hallway H204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Visual Information Provided (Exhibitions)
Code	
References:	ADA Title II Technical Assistance Manual 3.2000 Denial of participation
кетегепсеs: Performance Sta	participation
	participation
Performance Sta Barrier	participation ndard: No Quantity: JOB As-built: 1
Performance Sta Barrier Description: Findings:	participation ndard: No Quantity: JOB As-built: 1 Visual sign providing information for program, service or activity not accessible
Performance Sta Barrier Description: Findings: Rec. Solution:	participation ndard: No Quantity: JOB As-built: 1 Visual sign providing information for program, service or activity not accessible Accessible sign not provided Provide information in alternate format to provide access to people with vision impairments
Performance Sta Barrier Description: Findings: Rec. Solution: Barrier Severity:	participation Indard: No Quantity: JOB As-built: 1 Visual sign providing information for program, service or activity not accessible Accessible sign not provided Provide information in alternate format to provide access to people with vision impairments 1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Performance Sta Barrier Description:	participation Indard: No Quantity: JOB As-built: 1 Visual sign providing information for program, service or activity not accessible Accessible sign not provided Provide information in alternate format to provide access to people with vision impairments 1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open Priority: 3 Implementation Phase: Implementation Date:



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 30C
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Hallway H204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull - Operation
Code References:	2010 ADAS 309.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Fire pull has no fist operable hardware
Findings:	Fire pull not fist operable
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 30D
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 30D Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - North Hallway H204
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - North Hallway H204 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - North Hallway H204 N/A Y Coordinate: N/A Alarms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - North Hallway H204 N/A Y Coordinate: N/A Alarms Fire Pull - Height 2010 ADAS 308.2.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - North Hallway H204 N/A Y Coordinate: N/A Alarms Fire Pull - Height 2010 ADAS 308.2.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - North Hallway H204 N/A Alarms Fire Pull - Height 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - North Hallway H204 N/A Y Coordinate: N/A Alarms Fire Pull - Height 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 0 Fire pulls not between 42" and 48" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - North Hallway H204 N/A N/A Alarms Fire Pull - Height 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 0 Fire pulls not between 42" and 48" high 51-1/2" high
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - North Hallway H204 N/A Alarms Fire Pull - Height 2010 ADAS 308.2.2 ndard: No Quantity: EACH As-built: 0 Fire pulls not between 42" and 48" high 51-1/2" high Replace fire pull when remodeling A Low Severity Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 30E
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Hallway H204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	11-1/2" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 30F
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Hallway H204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 30G
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - North Hallway H204
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn - No Strobe
Code References:	2010 ADAS 702
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Horn provided in location where no strobe is provided
Findings:	No strobe device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 31A
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 222
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	<u> </u>
Notes:	- 1, 5



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 31B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 222
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	14 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 31C
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 222
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Backcheck
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: JOB As-built : 0
Barrier Description:	Door closer does not stop at least 5" from door frame (no back check)
Findings:	Does not stop at least 5" from close
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 31D
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 222
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	View panel located higher than 43" above the floor
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 52" high	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 31E
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 222
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Threshold - Height exceeding 1/4" without bevel
Code References:	2010 ADAS 404.2.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate threshold exceeds 1/4" in height withouth a bevel
Findings:	Provide firm and stable threshold
Rec. Solution:	Provide new door threshold
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 31F
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 222
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Ramps
Barrier Type:	Ramp Landing - Change in Direction
Code References:	2010 ADAS 405.7.4
Performance Sta	ndard: No Quantity: LF As-built: 14
Barrier Description:	Change in direction at landing is not min. 60" x 60"
Findings:	47-3/4" deep at change of direction
Rec. Solution:	Demolish existing and construct new ramp
Barrier Severity:	2 Recommended Cost Est \$2,800.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 31G
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 222
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Ramps
Barrier Type:	Handrail
Code References:	2010 ADAS 505.2
Performance Sta	ndard: No Quantity: LF As-built : 12
Barrier Description:	No handrail provided at both sides
Findings:	Ramp lacks handrail at both sides
Rec. Solution:	Replace handrails at both sides of ramp
Barrier Severity:	1 Necessary Cost Est \$2,700.00 Facility Function: Public Status: Open
Implementation	
Notes: 86-1/4"	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 31H
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 222
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Ramps
Barrier Type:	Running Slope - Existing (9.0% - 9.4%)
Code References:	2010 ADAS 405.3
Performance Sta	ndard: No Quantity: LF As-built : 10
Barrier Description:	Running slope exceeds 8.33% (9.0% - 9.4%)
Findings:	9.1% running slope
Rec. Solution:	Demolish existing and construct new ramp
Barrier Severity:	2 Recommended Cost Est \$2,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Thresho	ld at bottom ramp 12.5% running slope
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 311
	15/25/2014 Report Date 15/27/2014 Darrier III 1511
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 222
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 222 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 222 N/A Y Coordinate: N/A Ramps
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 222 N/A Y Coordinate: N/A Ramps Edge Protection - Wheel Guides 2010 ADAS 405.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 222 N/A Y Coordinate: N/A Ramps Edge Protection - Wheel Guides 2010 ADAS 405.9
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 222 N/A Y Coordinate: N/A Ramps Edge Protection - Wheel Guides 2010 ADAS 405.9 ndard: No Quantity: LF As-built: 10
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 222 N/A Y Coordinate: N/A Ramps Edge Protection - Wheel Guides 2010 ADAS 405.9 ndard: No Quantity: LF As-built: 10 No wheel guides where the ramp surface is not bounded by a wall
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 222 N/A Y Coordinate: N/A Ramps Edge Protection - Wheel Guides 2010 ADAS 405.9 ndard: No Quantity: LF As-built: 10 No wheel guides where the ramp surface is not bounded by a wall Large holes in ramp where conduit passes through Provide min. 2" curb or wheel guide centered at 3" above ground at both sides of ramp
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 222 N/A Y Coordinate: N/A Ramps Edge Protection - Wheel Guides 2010 ADAS 405.9 ndard: No Quantity: LF As-built: 10 No wheel guides where the ramp surface is not bounded by a wall Large holes in ramp where conduit passes through Provide min. 2" curb or wheel guide centered at 3" above ground at both sides of ramp 1 Necessary Cost Est \$2,000.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 31J
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 222
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-1/4" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 31K
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 222
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Lockers - Control
Code References:	2010 ADAS 803.5
Performance Sta	ndard: No Quantity: EACH As-built : 3
Barrier Description:	Locker mechanism not operable with fist or involves turning and grasping
Findings:	Mechanism not fist operable
Rec. Solution:	Provide min. 1 accessible locker or 5% overall
Barrier Severity:	1 Necessary Cost Est \$1,350.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 48 locke	, <u> </u>



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 31L
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 222
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	First Aid Kit - High Reach Range
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Opening mechanism on first aid kit not at max. 48" high for side reach
Findings:	71" high. Mechanism not fist operable; desk and lockers block first aid kit clear floor space
Rec. Solution:	Relocate control or mechanism to max. 48" high at min. 5% of lockers
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 31M
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 222
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	26-3/4" high, 17" deep knee clearance
Rec. Solution:	Provide min. 1 accessible group desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 6 group	desks and none are accessible



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 31N
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 222
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	TV protrudes 6-1/4" at 57-1/2" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 310
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 222
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	and and the Country of the Country o
	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Description: Findings:	Knee clearance not min. 27" high, 19" deep or 30" wide 25-1/2" high knee clearance Provide min. 1 accessible table
Description: Findings: Rec. Solution:	Knee clearance not min. 27" high, 19" deep or 30" wide 25-1/2" high knee clearance Provide min. 1 accessible table 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 31P
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 222
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Shelves or Cabinets
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Shelf or cabinet not mounted max. 48" above floor or ground
Findings:	Shelf or cabinet not accessible
Rec. Solution:	Provide additional shelf at accessible height or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Shelves	over tables 47-1/2" high over 21-3/4" deep desk obstruction at 27-3/4" high
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 31Q
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 31Q Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 222
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 222 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 222 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 222 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Forward Reach Obstructed (10"-25") 2010 ADAS 308.2.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 222 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Forward Reach Obstructed (10"-25") 2010 ADAS 308.2.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 222 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Forward Reach Obstructed (10"-25") 2010 ADAS 308.2.2 andard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance State Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 222 N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Forward Reach Obstructed (10"-25") 2010 ADAS 308.2.2 andard: No Quantity: EACH As-built: 1 Outlet located over an 10" to 25" obstruction max. 34" high located above 44"
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 31R
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 222
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Accessible Route
Code References:	2010 ADAS 305
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space does not adjoin an accessible route or another space
Findings:	Multiple holes in floor
Rec. Solution:	Cover holes in circulation path
Barrier Severity:	2 Recommended Cost Est \$175.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 315
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 222
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	
Implementation	Priority: 1 Implementation Phase: Implementation Date:



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 32A
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Fire Alarm - Pull Actuator Operation
Code References:	2010 ADAS 309.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Fire pull has no usable hardware
Findings:	Hardware not accessible
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 32B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Extinguisher - Cabinet Hardware
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Fire extinguisher door hardware not usable by those with hand impairments
Findings:	Cabinet door hardware not accessible
Rec. Solution:	Relocate fire extinguisher hardware
Barrier Severity:	4 Low Severity Cost Est \$1,500.00 Facility Function: Public Status: Open
Implementation	
Notes: Fire exti	nguisher case doors 11 - 19 lbf



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 32C
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Sign - Permanent Room/Space
Code References:	2010 ADAS 703.1
Performance Sta	andard: No Quantity: EACH As-built : 10
Barrier Description:	No sign with raised characters and Braille at permanent room or space with visual sign
Findings:	No tactile info on sign with visual information
Rec. Solution:	Provide signs at latch side of entry doors, where possible
Barrier Severity:	1 Necessary Cost Est \$2,500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Rooms 2	201, 202, 202A, 215, 216, 217, 218, 218A, 219, 219A
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 32D
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Sign - Visual Sign
Code References:	2010 ADAS 703.3
Performance Sta	andard: No Quantity: EACH As-built: 1
Performance Sta Barrier Description:	ndard: No Quantity: EACH As-built: 1 No Braille/tactile information on visual sign
Barrier	
Barrier Description:	No Braille/tactile information on visual sign
Barrier Description: Findings:	No Braille/tactile information on visual sign Accessible sign not provided Provide Braille/tactile sign
Barrier Description: Findings: Rec. Solution:	No Braille/tactile information on visual sign Accessible sign not provided Provide Braille/tactile sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 32E
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 32F
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Operation - Manual (Fist)
Code References:	2010 ADAS 602.3
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Operating mechanism at fountain is not operable with a fist
Findings:	Not fist operable
i iliuliigs.	
Rec. Solution:	Replace fountain with accessible unit
-	Replace fountain with accessible unit
Rec. Solution:	Replace fountain with accessible unit 2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 32G
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Bubbler height
Code References:	2010 ADAS 602.4
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Bubbler height exceeds 36"
Findings:	43-1/2" bubbler height
Rec. Solution:	Replace drinking fountain with accessible unit or remount existing
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 32H
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H203
_	
Location:	Floor 2 - Hallway H203
Location: X Coordinate:	Floor 2 - Hallway H203 N/A Y Coordinate: N/A Drinking Fountains Bubbler water flow
Location: X Coordinate: Barrier Area:	Floor 2 - Hallway H203 N/A Y Coordinate: N/A Drinking Fountains
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 2 - Hallway H203 N/A Y Coordinate: N/A Drinking Fountains Bubbler water flow 2010 ADAS 602.6
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 2 - Hallway H203 N/A Y Coordinate: N/A Drinking Fountains Bubbler water flow 2010 ADAS 602.6
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 2 - Hallway H203 N/A Y Coordinate: N/A Drinking Fountains Bubbler water flow 2010 ADAS 602.6 andard: No Quantity: JOB As-built: 0
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 2 - Hallway H203 N/A Y Coordinate: N/A Drinking Fountains Bubbler water flow 2010 ADAS 602.6 andard: No Quantity: JOB As-built: 0 Water flow from bubbler not min. 4" high
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 2 - Hallway H203 N/A Y Coordinate: N/A Drinking Fountains Bubbler water flow 2010 ADAS 602.6 andard: No Quantity: JOB As-built: 0 Water flow from bubbler not min. 4" high 1" high water flow from bubbler Adjust drinking fountain to provide min. 4" high water flow
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 2 - Hallway H203 N/A Y Coordinate: N/A Drinking Fountains Bubbler water flow 2010 ADAS 602.6 Mandard: No Quantity: JOB As-built: 0 Water flow from bubbler not min. 4" high 1" high water flow from bubbler Adjust drinking fountain to provide min. 4" high water flow 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 32I
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Depth (MANUSCOME 18:30)
Code References:	2010 ADAS 602.5
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Wall/post mounted fountain not min. 18" deep
Findings:	13-1/4" deep
Rec. Solution:	Replace fountain with accessible unit
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 32J
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Hi-Low Unit
Code References:	2010 ADAS 211.2 & 602.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No hi-low drinking fountain provided on each floor of building
Findings:	No low drinking fountain on second floor
Rec. Solution:	Provide min. one hi-low fountain on each floor
Barrier Severity:	1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 32K
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard & 2010 ADAS 904.3.3
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 54" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Whitebo	oard outside of office
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 32L
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Electrical box protrudes 9-3/4" at 48-1/4" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Rec. Solution: Barrier Severity:	
	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 32M
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Strobe
Code References:	2010 ADAS 702.1
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	No strobe provided in corridor where horn is provided where fire alarm exists in building
Findings:	No strobe where horn is provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 33A
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 33A Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Sign - No Braille/tactile Sign 2010 ADAS 703.2.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Sign - No Braille/tactile Sign 2010 ADAS 703.2.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Sign - No Braille/tactile Sign 2010 ADAS 703.2.3 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Sign - No Braille/tactile Sign 2010 ADAS 703.2.3 Indard: No Quantity: EACH As-built: 1 No Braille/tactile sign at latch side of door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Sign - No Braille/tactile Sign 2010 ADAS 703.2.3 Indard: No Quantity: EACH As-built: 1 No Braille/tactile sign at latch side of door Accessible sign not provided Provide Braille/tactile sign at latch side of door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Sign - No Braille/tactile Sign 2010 ADAS 703.2.3 andard: No Quantity: EACH As-built: 1 No Braille/tactile sign at latch side of door Accessible sign not provided Provide Braille/tactile sign at latch side of door 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 33B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 219B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Viewing From Distance - >70" high
Code References:	2010 ADAS 703.5.5 and Table 703.5.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Signs between 70" and 120" high lack characters at least 2" high
Findings:	Characters on sign above door not large enough to view from a distance
Rec. Solution:	Replace sign with characters min. 2" in height for viewing at a distance
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: 1" tall	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 33C
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 219B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	7 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 33D
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 219B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Backcheck
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Door closer does not stop at least 5" from door frame (no back check)
Findings:	Does not stop at least 5" from close
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 33E
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 33E Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Door Clearance - Pull Side
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Door Clearance - Pull Side 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Door Clearance - Pull Side 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Door Clearance - Pull Side 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Door Clearance - Pull Side 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0 Door lacks min. 18" strike edge clearance at pull side
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Door Clearance - Pull Side 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0 Door lacks min. 18" strike edge clearance at pull side 16-1/2 " strike edge clearance at exit side of door Provide automatic door opening device
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Door Clearance - Pull Side 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0 Door lacks min. 18" strike edge clearance at pull side 16-1/2 " strike edge clearance at exit side of door Provide automatic door opening device 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 33F
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 219B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 33G
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 219B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	
	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
	2010 ADAS 308.2.2
References:	2010 ADAS 308.2.2
References: Performance Sta Barrier	2010 ADAS 308.2.2 andard: No Quantity: EACH As-built : 1
References: Performance Sta Barrier Description:	2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high
References: Performance Sta Barrier Description: Findings:	2010 ADAS 308.2.2 andard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 9" high Relocate outlet to area at min. 15" or max. 48" high
References: Performance Sta Barrier Description: Findings: Rec. Solution:	2010 ADAS 308.2.2 andard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high 9" high Relocate outlet to area at min. 15" or max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 33H
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 219B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Shelf protrudes 5" at 39-1/4" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 33I
	13/25/2014 Report Date 15/27/2014 Barrier #. 1331
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Trash cans block mirror shelf clear floor space Move stored items
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Trash cans block mirror shelf clear floor space Move stored items 1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 33J
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 219B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Knee Clearance
Code References:	2010 ADAS 606.2 & 306
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Lavatory bottom apron/edge not max 29" reducing to 27" at 8" back from edge
Findings:	26-1/4" high knee clearance
Rec. Solution:	Provide min. 1 accessible lavatory
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 33K
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 219B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Surfaces
Code References:	2010 ADAS 606.5
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Lavatory has sharp or abrasive surfaces on edge, rim or apron
Findings:	Lavatory has sharp surfaces
Rec. Solution:	Replace lavatory
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	· · · · · · · · · · · · · · · · · · ·



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 33L
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 219B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Operation
Code References:	2010 ADAS 307.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Dispenser operating mechanism not fist operable
Findings:	Feminine product dispenser not fist operable
Rec. Solution:	Replace dispenser
Barrier Severity:	1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 33M
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 219B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Door - Self-closing
Code References:	2010 ADAS 604.8.1.2
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Stall door not equipped with a self-closing door
Findings:	Door is not self-closing
Rec. Solution:	Replace compartment hinge with adjustible mechanism
Barrier Severity:	2 Recommended Cost Est \$1,650.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 33N
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 219B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Stall - Door Hardware
Code References:	2010 ADAS 604.8.1.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Inside of compartment door lacks a loop or U-pull below latch
Findings:	No U-pull provided
Rec. Solution:	Provide hardware
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 330
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B
_	
Location:	Floor 2 - Women's Restroom 219B
Location: X Coordinate:	Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Toilet - Clear Space (post-ADA)
Location: X Coordinate: Barrier Area:	Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Toilet - Clear Space (post-ADA) 2010 ADAS 604.3.1 & 604.8.1.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Toilet - Clear Space (post-ADA) 2010 ADAS 604.3.1 & 604.8.1.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Toilet - Clear Space (post-ADA) 2010 ADAS 604.3.1 & 604.8.1.1 Indard: No Quantity: SF As-built: 140
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 2 - Women's Restroom 219B N/A Restrooms Toilet - Clear Space (post-ADA) 2010 ADAS 604.3.1 & 604.8.1.1 Indard: No Quantity: SF As-built: 140 Water closet clear space not min. 60" measured wall-to-wall
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Toilet - Clear Space (post-ADA) 2010 ADAS 604.3.1 & 604.8.1.1 Indard: No Quantity: SF As-built: 140 Water closet clear space not min. 60" measured wall-to-wall 2 toilet stalls provided and neither stall is wheelchair accessible Remodel toilet room to provide clear width
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Toilet - Clear Space (post-ADA) 2010 ADAS 604.3.1 & 604.8.1.1 Mater closet clear space not min. 60" measured wall-to-wall 2 toilet stalls provided and neither stall is wheelchair accessible Remodel toilet room to provide clear width 2 Recommended Cost Est \$80,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 33P
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Women's Restroom 219B
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Floor Drain - Existing
Code References:	2010 ADAS 304.2
Performance Sta	ndard: No Quantity: SF As-built : 60
Barrier Description:	Floor drain located within clear floor space of fixture
Findings:	Flooring throughout restroom slopes up to 3.9%
Rec. Solution:	Remodel drain inlet to have less than 1/2" lip
Barrier Severity:	3 Hindrance Cost Est \$15,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	Description of Data Interference Description in the Interferen
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 33Q
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Alarm - Horn/Strobe
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Alarm - Horn/Strobe 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Alarm - Horn/Strobe 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Alarm - Horn/Strobe 2010 ADAS 702.1 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Alarm - Horn/Strobe 2010 ADAS 702.1 mdard: No Quantity: EACH As-built: 1 Where a fire alarm is installed, no horn/strobe provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Alarm - Horn/Strobe 2010 ADAS 702.1 mdard: No Quantity: EACH As-built: 1 Where a fire alarm is installed, no horn/strobe provided No device provided
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Women's Restroom 219B N/A Y Coordinate: N/A Restrooms Alarm - Horn/Strobe 2010 ADAS 702.1 mdard: No Quantity: EACH As-built: 1 Where a fire alarm is installed, no horn/strobe provided No device provided Provide horn/strobe in sanitary facility I Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34A
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Men's Restroom 215A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - No Braille/tactile Sign
Code References:	2010 ADAS 703.2.3
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	No Braille/tactile sign at latch side of door
Findings:	Accessible sign not provided
Rec. Solution:	Provide Braille/tactile sign at latch side of door
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Men's Restroom 215A
Location: X Coordinate:	Total Control of the
	Floor 2 - Men's Restroom 215A
X Coordinate:	Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high
X Coordinate: Barrier Area:	Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Signage
X Coordinate: Barrier Area: Barrier Type: Code	Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5
X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5 Indard: No Quantity: EACH As-built: 0
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5 Indard: No Quantity: EACH As-built: Signs between 70" and 120" high lack characters at least 2" high
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5 Indard: No Quantity: EACH As-built: 0 Signs between 70" and 120" high lack characters at least 2" high Characters on sign above door not large enough to view from a distance Replace sign with characters min. 2" in height for viewing at a distance
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Signage Viewing From Distance - >70" high 2010 ADAS 703.5.5 and Table 703.5.5 Indard: No Quantity: EACH As-built: 0 Signs between 70" and 120" high lack characters at least 2" high Characters on sign above door not large enough to view from a distance Replace sign with characters min. 2" in height for viewing at a distance 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34C
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Men's Restroom 215A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	16 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34D
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Men's Restroom 215A
	JFIOOT 2 - IVIEN'S RESTROOM 215A
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	
	N/A Y Coordinate: N/A Doors or Gates Door Closer - Backcheck
Barrier Area:	N/A Y Coordinate: N/A Doors or Gates
Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Doors or Gates Door Closer - Backcheck 2010 ADAS 404.2.8.1
Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Doors or Gates Door Closer - Backcheck 2010 ADAS 404.2.8.1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Y Coordinate: N/A Doors or Gates Door Closer - Backcheck 2010 ADAS 404.2.8.1 ndard: No Quantity: JOB As-built: 0
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Y Coordinate: N/A Doors or Gates Door Closer - Backcheck 2010 ADAS 404.2.8.1 ndard: No Quantity: JOB As-built: 0 Door closer does not stop at least 5" from door frame (no back check)
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Doors or Gates Door Closer - Backcheck 2010 ADAS 404.2.8.1 ndard: No Quantity: JOB As-built: 0 Door closer does not stop at least 5" from door frame (no back check) Does not stop at least 5" from close
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Y Coordinate: N/A Doors or Gates Door Closer - Backcheck 2010 ADAS 404.2.8.1 Door closer does not stop at least 5" from door frame (no back check) Does not stop at least 5" from close Provide automatic door opening device 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34E
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Men's Restroom 215A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Clearance - Push Side
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door lacks min. 12" strike edge clearance at push side
Findings:	2-3/4" strike edge clearance
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34F
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Men's Restroom 215A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
	Stilliarance See 250 3750:00 Table States: Open
Implementation	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34G
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Men's Restroom 215A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding dispenser creates protruding hazard in path of travel
Findings:	Paper towel dispenser protrudes 10" at 46-3/4" high
Rec. Solution:	Relocate dispenser or provide cane-detectable warning
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34H
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 34H Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Protruding Object - Wall-mounted
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Protruding Object - Wall-mounted 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Protruding Object - Wall-mounted 2010 ADAS 307.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Protruding Object - Wall-mounted 2010 ADAS 307.2 andard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Protruding Object - Wall-mounted 2010 ADAS 307.2 andard: No Quantity: JOB As-built: 1 Object protrudes more than 4" into circulation path
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Protruding Object - Wall-mounted 2010 ADAS 307.2 andard: No Quantity: JOB As-built: 1 Object protrudes more than 4" into circulation path Shelf protrudes 5" at 39-1/2" high Relocate protruding elements out of pedestrian way or provide cane-detectable warning 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34I
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Men's Restroom 215A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	11" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34J
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Men's Restroom 215A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Floor Drain - Existing
Code References:	2010 ADAS 304.2
Performance Sta	andard: No Quantity: SF As-built : 60
Barrier Description:	Floor drain located within clear floor space of fixture
Findings:	2.8% cross-slope at lavatories
Rec. Solution:	
	Remodel drain inlet to have less than 1/2" lip
Barrier Severity:	
Barrier Severity: Implementation	3 Hindrance Cost Est \$34,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34K
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Men's Restroom 215A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Drainpipes
Code References:	2010 ADAS 606.5
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Hot water and drainpipes accessible under lavatory not insulated or covered
Findings:	No insulation provided
Rec. Solution:	Insulate drainpipes and hot water pipes
Barrier Severity:	2 Recommended Cost Est \$220.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34L
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Men's Restroom 215A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Mirror
	n2/20/20/20/20 10 12/20
Code References:	2010 ADAS 603.3
	2010 ADAS 603.3
References:	2010 ADAS 603.3
References: Performance Sta Barrier	2010 ADAS 603.3 Indard: No Quantity: EACH As-built: 1
References: Performance Sta Barrier Description:	2010 ADAS 603.3 Indard: No Quantity: EACH As-built: 1 Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface
References: Performance Sta Barrier Description: Findings:	2010 ADAS 603.3 Indard: No Quantity: EACH As-built: 1 Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface 40-1/2 - 52-3/4" high Replace or remount mirror
References: Performance Sta Barrier Description: Findings: Rec. Solution:	2010 ADAS 603.3 Indard: No Quantity: EACH As-built: 1 Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface 40-1/2 - 52-3/4" high Replace or remount mirror 3 Hindrance Cost Est \$375.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34M
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Men's Restroom 215A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Flush Controls
Code References:	2010 ADAS 309
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Urinal flush controls mounted higher than 48" above the floor
Findings:	47" high
Rec. Solution:	Replace urinal controls where possible or entire urinal
Barrier Severity:	2 Recommended Cost Est \$800.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34N
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 34N Dearborn Hall Reference Dwg: 4 of 5
	the second second
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Urinal - Flush Controls 2010 ADAS 309
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Urinal - Flush Controls 2010 ADAS 309
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Urinal - Flush Controls 2010 ADAS 309 ndard: No Quantity: JOB As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Urinal - Flush Controls 2010 ADAS 309 ndard: No Quantity: JOB As-built: 0 Urinal flush controls involve more than 5 lbf (22.2 N) to activate
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Urinal - Flush Controls 2010 ADAS 309 Idard: No Quantity: JOB As-built: 0 Urinal flush controls involve more than 5 lbf (22.2 N) to activate
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Urinal - Flush Controls 2010 ADAS 309 Identity: JOB As-built: 0 Urinal flush controls involve more than 5 lbf (22.2 N) to activate 7 lbf Replace urinal controls where possible or entire urinal 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 340
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Men's Restroom 215A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Rim
Code References:	2010 ADAS 605.2
Performance Sta	indard: No Quantity: JOB As-built : 1
Barrier Description:	Urinal not max. 17" above the floor
Findings:	17-1/2" high rim
Rec. Solution:	Provide min. 1 accessible urinal
Barrier Severity:	2 Recommended Cost Est \$800.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
·	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34P
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 34P Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Urinal - Rim
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Urinal - Rim 2010 ADAS 605.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Urinal - Rim 2010 ADAS 605.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Urinal - Rim 2010 ADAS 605.2 Indard: No Quantity: JOB As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Urinal - Rim 2010 ADAS 605.2 Indard: No Quantity: JOB As-built: 0 Min. 1 urinal has no elongated rim projecting 14" to 17" from wall
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Urinal - Rim 2010 ADAS 605.2 Min. 1 urinal has no elongated rim projecting 14" to 17" from wall 11-1/2" from wall Provide min. 1 accessible urinal
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Urinal - Rim 2010 ADAS 605.2 Indard: No Quantity: JOB As-built: 0 Min. 1 urinal has no elongated rim projecting 14" to 17" from wall 11-1/2" from wall Provide min. 1 accessible urinal 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34Q
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Men's Restroom 215A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Door - Self-closing
Code References:	2010 ADAS 604.8.1.2
Performance Sta	indard: No Quantity: JOB As-built : 1
Barrier Description:	Stall door not equipped with a self-closing door
Findings:	Door is not self-closing
Rec. Solution:	Replace compartment hinge with adjustible mechanism
Barrier Severity:	2 Recommended Cost Est \$1,650.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34R
-11	
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Men's Restroom 215A
Location:	Floor 2 - Men's Restroom 215A
Location: X Coordinate:	Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Stall Door Hardware 2010 ADAS 604.8.1.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Stall Door Hardware 2010 ADAS 604.8.1.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Stall Door Hardware 2010 ADAS 604.8.1.2 andard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Stall Door Hardware 2010 ADAS 604.8.1.2 Indard: No Quantity: EACH As-built: 1 Stall door hardware involves tight grasping/pinching to close and no U-pull provided
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Stall Door Hardware 2010 ADAS 604.8.1.2 Indard: No Quantity: EACH As-built: 1 Stall door hardware involves tight grasping/pinching to close and no U-pull provided No U-pull provided Provide U-pull hardware on outside and inside of stall door
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 2 - Men's Restroom 215A N/A Y Coordinate: N/A Restrooms Stall Door Hardware 2010 ADAS 604.8.1.2 Indard: No Quantity: EACH As-built: 1 Stall door hardware involves tight grasping/pinching to close and no U-pull provided No U-pull provided Provide U-pull hardware on outside and inside of stall door 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34S
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Men's Restroom 215A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Coat Hook
Code References:	2010 ADAS 603.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	64-1/2" high
Rec. Solution:	Provide additional hook
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34T
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Men's Restroom 215A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Clear Space (post-ADA)
Code References:	2010 ADAS 604.3.1 & 604.8.1.1
Performance Sta	indard: No Quantity: SF As-built: 140
Barrier Description:	Water closet clear space not min. 60" measured wall-to-wall
Findings:	2 toilet stalls provided and neither stall is wheelchair accessible
Rec. Solution:	Remodel toilet room to provide clear width
Barrier Severity:	2 Recommended Cost Est \$80,500.00 Facility Function: Public Status: Open
Implementation	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 34U
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Men's Restroom 215A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/strobe in sanitary facility
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
·	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 35A
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 35A Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Admin Office 203A
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Admin Office 203A N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Admin Office 203A N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Admin Office 203A N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Admin Office 203A N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Admin Office 203A N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Admin Office 203A N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Admin Office 203A N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Admin Office 203A N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 35B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Admin Office 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	11 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 35C
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 35C Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Admin Office 203A
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Admin Office 203A N/A Y Coordinate: N/A Doors or Gates Door Closer - Sweep Period
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Admin Office 203A N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Admin Office 203A N/A Y Coordinate: N/A Doors or Gates Door Closer - Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Admin Office 203A N/A Y Coordinate: N/A Doors or Gates Door Closer - Sweep Period 2010 ADAS 404.2.8.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Admin Office 203A N/A Y Coordinate: N/A Doors or Gates Door Closer - Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Admin Office 203A N/A Y Coordinate: N/A Doors or Gates Door Closer - Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Admin Office 203A N/A Y Coordinate: N/A Doors or Gates Door Closer - Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period 3 second sweep Provide automatic door opening device
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Admin Office 203A N/A Y Coordinate: N/A Doors or Gates Door Closer - Sweep Period 2010 ADAS 404.2.8.1 ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period 3 second sweep Provide automatic door opening device 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 35D
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Admin Office 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Door Hardware
Code References:	2010 ADAS 404.2.10
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door hardware interrupts min. 10" smooth bottom surface
Findings:	Door stop at bottom of door can create trapping condition
Rec. Solution:	Remove element at bottom of door at push side
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 35E
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Admin Office 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	6-1/4" strike edge clearance within door landing
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority Developmentation Phase
Notes:	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 35F
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Admin Office 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Accessible Route
Code References:	2010 ADAS 305
Performance Sta	andard: No Quantity: JOB As-built : 0
Barrier Description:	Clear floor space does not adjoin an accessible route or another space
Findings:	Step at entry 7" high
Rec. Solution:	Remodel area to provide accessible ramp at entrance
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 35G
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Admin Office 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Landing - Length
Code References:	2010 ADAS 404.2.4
Performance Sta	indard: No Quantity: SF As-built : 40
Barrier Description:	Landing length is not at least 44" in direction of pedestrian travel
Findings:	23-3/4" long and 47-1/4" wide landing
Rec. Solution:	Demolish and reconstruct level landing
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	
	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 35H
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Admin Office 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	65-1/2" high
Rec. Solution:	Provide additional hook
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 35I
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Admin Office 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard & 2010 ADAS 904.3.3
Performance Sta	indard: Yes Quantity: EACH As-built : 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 42" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 35J
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Admin Office 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Forward Reach Obstructed (10"-25")
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44"
Findings:	42" high and 40" deep over couch obstruction 27" high; mini-fridge is a less severe obstruction, too
Rec. Solution:	Move whiteboard or couch to provide access to whiteboard
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 35K
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Admin Office 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	Passageway less than 36" in multiple locations
Rec. Solution:	Rearrange furniture to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 13-1/4"	wide circulation route between couch and desk



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 35L
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Admin Office 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Accessible Route
Code References:	2010 ADAS 305
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space does not adjoin an accessible route or another space
Findings:	Multiple holes in floor
Rec. Solution:	Cover holes in floor within circulation route
Barrier Severity:	2 Recommended Cost Est \$175.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 35M
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Admin Office 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24-1/2" high knee clearance
Rec. Solution:	Provide min. 1 accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 35N
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Admin Office 203A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 36A
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 5
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	
	Provide accessible sign
Barrier Severity:	
Barrier Severity: Implementation	1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 36B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	ISA - Non-Accessible Entry
Code References:	2010 ADAS 216.6
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Sign directing people to accessible entrance needed where all doors are not accessible
Findings:	Accessible sign not provided at double-doors
Rec. Solution:	Provide ISA directional sign with arrow directing people to accessible entrance
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: 2 entry of accessib	doors. One entry door leads to a ramp and the other leads to steps. One must be identified as le
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 36C
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Florida Transfer Ltd 202
Location.	Floor 2 - Teaching Lab 203
	N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Doors or Gates
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	N/A Poors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Poors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Poors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 8 - 13 lbf Provide automatic door opening device at one door and ISA sign at other door
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Poors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf Provide automatic door opening device at one door and ISA sign at other door I Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 36D
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	4 second sweep
Rec. Solution:	Provide automatic door opening device at one door and ISA sign at other door
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 36E
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Backcheck
Code References:	2010 ADAS 404.2.8.1
Performance Sta	andard: No Quantity: JOB As-built : 0
Barrier Description:	Door closer does not stop at least 5" from door frame (no back check)
Findings:	Does not stop at least 5" from close
Rec. Solution:	Provide automatic door opening device at one door and ISA sign at other door
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 36F
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Kickplate
Code References:	2010 ADAS 404.2.10
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate lacks min. 10" smooth uninterrupted bottom surface
Findings:	Bottom of door not smooth and uninterrupted. Bevel on door is 9-1/2" high
Rec. Solution:	Provide min. 10" high smooth surface at push side of accessible door
Barrier Severity:	1 Necessary Cost Est \$225.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: At both	doors
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 36G
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Clear Width
Code References:	2010 ADAS 404.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clear width passage through door, sliding/folding door or gate is not min. 32"
Findings:	27-1/2" clear width for single door leaf
Rec. Solution:	Replace door or gate and frame if this entrance is made accessible
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Double	door entry



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 36H
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Threshold - Ramp
Code References:	2010 ADAS 404.2.5
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate threshold exceeds 1/2" in height
Findings:	Threshold exceeds 1/2" when exiting room
Rec. Solution:	Provide accessible threshold at accessible door
Barrier Severity:	1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 36I
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 203
Location:	Floor 2 - Teaching Lab 203
Location: X Coordinate:	Floor 2 - Teaching Lab 203 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC
Location: X Coordinate: Barrier Area:	Floor 2 - Teaching Lab 203 N/A Y Coordinate: N/A Doors or Gates
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 2 - Teaching Lab 203 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 2 - Teaching Lab 203 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 2 - Teaching Lab 203 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 andard: No Quantity: EACH As-built: 0
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 2 - Teaching Lab 203 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 andard: No Quantity: EACH As-built: 0 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 2 - Teaching Lab 203 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 andard: No Quantity: EACH As-built: 0 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer 10-1/4" strike edge clearance and ramp landing at accessible entry door Provide automatic door opening device at one door and ISA sign at other door
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 2 - Teaching Lab 203 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 andard: No Quantity: EACH As-built: 0 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer 10-1/4" strike edge clearance and ramp landing at accessible entry door Provide automatic door opening device at one door and ISA sign at other door 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 36J
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Landing - Length
Code References:	2010 ADAS 404.2.4
Performance Sta	andard: No Quantity: SF As-built : 40
Barrier Description:	Landing length is not at least 44" in direction of pedestrian travel
Findings:	No level landing provided inside accessible door leading to ramp. Threshold running slope 11.7%
Rec. Solution:	Demolish and reconstruct level landing
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 36K
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 203
Location: X Coordinate:	N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A Ramps Handrail
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Ramps
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Ramps Handrail 2010 ADAS 505.2
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Ramps Handrail 2010 ADAS 505.2
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	N/A Y Coordinate: N/A Ramps Handrail 2010 ADAS 505.2 Indard: No Quantity: LF As-built: 14
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Y Coordinate: N/A Ramps Handrail 2010 ADAS 505.2 Indard: No Quantity: LF As-built: 14 No handrail provided at both sides
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Ramps Handrail 2010 ADAS 505.2 Indard: No Quantity: LF As-built: 14 No handrail provided at both sides Ramp lacks handrail at both sides Replace handrails at both sides of ramp
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Y Coordinate: N/A Ramps Handrail 2010 ADAS 505.2 Indard: No Quantity: LF As-built: 14 No handrail provided at both sides Ramp lacks handrail at both sides Replace handrails at both sides of ramp 1 Necessary Cost Est \$3,150.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 36L
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 36M
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard & 2010 ADAS 904.3.3
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 38-3/4" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	
Notes:	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 360
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Accessible Route
Code References:	2010 ADAS 305
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space does not adjoin an accessible route or another space
Findings:	Multiple holes in flooring
Rec. Solution:	Cover holes in floor within circulation route
Barrier Severity:	2 Recommended Cost Est \$175.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 36P
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Desk - Ratio
Code References:	2010 ADAS 902
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	At least 1 desk or 5% of all desks not accessible
Findings:	Min. 1 accessible desk not provided of each type. PC stations not accessible
Rec. Solution:	Provide min. 1 accessible desk
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Group d	Friority. 2 implementation Friase. implementation Date.



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 36Q
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	25-1/2" knee clearance at PC stations
Rec. Solution:	Provide min. 2 accessible PC workstations
Barrier Severity:	3 Hindrance Cost Est \$1,750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 23 desk	s and none are accessible
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 36R
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 203
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
neierences.	
Performance Sta	andard: No Quantity: EACH As-built : 1
	nndard: No Quantity: EACH As-built : 1 No horn/strobes in common use areas
Performance Sta Barrier	
Performance Sta Barrier Description:	No horn/strobes in common use areas
Performance Sta Barrier Description: Findings:	No horn/strobes in common use areas No device provided Provide strobe in common use area
Performance Sta Barrier Description: Findings: Rec. Solution:	No horn/strobes in common use areas No device provided Provide strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 37A
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lockers - Control
Code References:	2010 ADAS 803.5
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	Locker mechanism not operable with fist or involves turning and grasping
Findings:	Mechanism not fist operable
Rec. Solution:	Provide min. 1 accessible locker or 5% overall
Barrier Severity:	1 Necessary Cost Est \$900.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 30 locke	rs
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 37B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
	Corridors
Barrier Type:	Sign - Permanent Room/Space
Barrier Type: Code	Sign - Permanent Room/Space 2010 ADAS 703.1
Barrier Type: Code References:	Sign - Permanent Room/Space 2010 ADAS 703.1
Barrier Type: Code References: Performance Sta Barrier	Sign - Permanent Room/Space 2010 ADAS 703.1 ndard: No Quantity: EACH As-built: 2
Barrier Type: Code References: Performance Sta Barrier Description:	Sign - Permanent Room/Space 2010 ADAS 703.1 ndard: No Quantity: EACH As-built: 2 No sign with raised characters and Braille at permanent room or space with visual sign
Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Sign - Permanent Room/Space 2010 ADAS 703.1 ndard: No Quantity: EACH As-built: 2 No sign with raised characters and Braille at permanent room or space with visual sign No tactile info on sign with visual information Provide sign at latch side of entry door, where possible
Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Sign - Permanent Room/Space 2010 ADAS 703.1 ndard: No Quantity: EACH As-built: 2 No sign with raised characters and Braille at permanent room or space with visual sign No tactile info on sign with visual information Provide sign at latch side of entry door, where possible 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 37C
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H202
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Horn/Strobe Device
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn or strobe in corridor where fire alarm exists in building
Findings:	No horn/strobe provided
Rec. Solution:	Provide horn/strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 38A
	3/25/2014 Report Date 5/27/2014 Barrier #: 38A Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H206
Field Date: Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H206 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H206 N/A Y Coordinate: N/A Corridors
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H206 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H206 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H206 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H206 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 ndard: No Quantity: EACH As-built: 1 No sign with raised characters and Braille at permanent room or space with visual sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H206 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 No Quantity: EACH As-built: 1 No sign with raised characters and Braille at permanent room or space with visual sign No tactile info on sign with visual information Provide sign at latch side of entry door, where possible
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H206 N/A Y Coordinate: N/A Corridors Sign - Permanent Room/Space 2010 ADAS 703.1 No sign with raised characters and Braille at permanent room or space with visual sign No tactile info on sign with visual information Provide sign at latch side of entry door, where possible 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 38B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 38C
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
J	Dearborn Hall
Location:	Floor 2 - Hallway H206
•	
Location:	Floor 2 - Hallway H206
Location: X Coordinate:	Floor 2 - Hallway H206 N/A Y Coordinate: N/A Corridors Door Closer - Interior Automatic Door
Location: X Coordinate: Barrier Area:	Floor 2 - Hallway H206 N/A Y Coordinate: N/A Corridors
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 2 - Hallway H206 N/A Y Coordinate: N/A Corridors Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 2 - Hallway H206 N/A Y Coordinate: N/A Corridors Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 2 - Hallway H206 N/A Y Coordinate: N/A Corridors Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 2 - Hallway H206 N/A Y Coordinate: N/A Corridors Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 2 - Hallway H206 N/A V Coordinate: N/A Corridors Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 17 lbf Provide automatic door opening device at door to Covell Hall
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 2 - Hallway H206 N/A Y Coordinate: N/A Corridors Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 17 lbf Provide automatic door opening device at door to Covell Hall 1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 38D
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	4 second sweep
Rec. Solution:	Provide automatic door opening device at door to Covell Hall
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 38E
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
Barrier Type:	Doors or Gates
barrier Type.	Front App/pull 18" SEC - Relocate Door
Code References:	
Code	Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1
Code References:	Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1
Code References: Performance Sta Barrier	Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1 Indard: No Quantity: EACH As-built: 0
Code References: Performance Sta Barrier Description:	Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1 Indard: No Quantity: EACH As-built: 0 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Code References: Performance Sta Barrier Description: Findings:	Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1 Indard: No Quantity: EACH As-built: 0 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side 16" strike edge clearance Provide automatic door opening device at door to Covell Hall
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Front App/pull 18" SEC - Relocate Door 2010 ADAS Figure 404.2.4.1 Indard: No Quantity: EACH As-built: 0 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side 16" strike edge clearance Provide automatic door opening device at door to Covell Hall 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 38F
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Horn/Strobe Device
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn or strobe in corridor where fire alarm exists in building
Findings:	No horn/strobe provided
Rec. Solution:	Provide horn/strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 39A
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 3
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: 3 entries	s with signage into this room



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 39B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	ISA - Directional Sign
Code References:	2010 ADAS 216.6 Advisory
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No directional signage provided where accessible route diverges from main route
Findings:	Accessible sign not provided at non-accessible door
Rec. Solution:	Provide directional signage
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 39C
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
Location: X Coordinate:	Floor 2 - Teaching Lab 208 N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	N/A V Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 andard: No Quantity: EACH As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 andard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Doors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 andard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf Provide automatic door opening device at one door and ISA sign at other door
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Poors or Gates Door Closer - Interior Automatic Door 2010 ADAS 404.2.9 Indard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf Provide automatic door opening device at one door and ISA sign at other door 1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 39D
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	indard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	4 second sweep
Rec. Solution:	Provide automatic door opening device at one door and ISA sign at other door
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 39E
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Door knob not fist operable
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 39F
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Kickplate
Code References:	2010 ADAS 404.2.10
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate lacks min. 10" smooth uninterrupted bottom surface
Findings:	Bottom of door not smooth and uninterrupted. Bevel on door is 9-1/2" high
Rec. Solution:	Provide min. 10" high kick plate at push side of door
Barrier Severity:	1 Necessary Cost Est \$225.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Bevel or	n door is 9-1/2" high
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 39G
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Clear Width
Code References:	2010 ADAS 404.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clear width passage through door, sliding/folding door or gate is not min. 32"
Findings:	27-1/2" clear width for one active leaf of the double doors
Rec. Solution:	Replace door or gate and frame if this entrance is made accessible
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	Friority. 12 Implementation Friase. 1 Implementation Date.



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 39H
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Threshold - Height exceeding 1/4" without bevel
Code References:	2010 ADAS 404.2.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate threshold exceeds 1/4" in height without a bevel
Findings:	Threshold is deteriorating
Rec. Solution:	Replace door threshold
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 391
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Ramps
Barrier Type:	Handrail 03//9/2013 15 15
Code References:	2010 ADAS 505.2
Performance Sta	ndard: No Quantity: LF As-built : 14
Barrier Description:	No handrail provided at both sides
Findings:	Ramp lacks handrail at both sides
Rec. Solution:	Replace handrails at both sides of ramp
Barrier Severity:	1 Necessary Cost Est \$3,150.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 39J
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Ramps
Barrier Type:	Ramp Landing - Top Landing
Code References:	2010 ADAS 405.7.3
Performance Sta	ndard: No Quantity: LF As-built : 0
Barrier Description:	Top landing is not min. 60" long
Findings:	Items in top landing clear floor space
Rec. Solution:	Remove stored items at top of ramp to provide accessible space or change of direction
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 39K
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 39L
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Hi/low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Use of control involves low reach of less than 15" above floor or more than 48" high
Findings:	Fan switch 68" high
Rec. Solution:	Relocate to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 39M
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	TV protrudes 8-1/2" at 48-3/4" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	
	Priority: 1 Implementation Phase: Implementation Date:



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 39N
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard & 2010 ADAS 904.3.3
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 38-1/2" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 390
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Lockers - Control
Code References:	2010 ADAS 803.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Locker mechanism not operable with fist or involves turning and grasping
Findings:	Mechanism not fist operable
Rec. Solution:	Provide min. 1 accessible locker or 5% overall
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	
	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 39P
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	25-1/2" knee clearance
Rec. Solution:	Provide accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 13 desk	s and none are accessible
, I	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 39Q
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 39Q Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 208
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 208 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 208 N/A Y Coordinate: N/A Controls and Mechanisms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 208 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 208 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 208 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Teaching Lab 208 N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 39R
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	Passageway less than 36" in multiple locations
Rec. Solution:	Rearrange furniture to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 17-3/4"	wide circulation route between table and desks
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 395
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 305
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	44" - 57" turning circle between each row of desks
Rec. Solution:	Rearrange furniture to provide accessible maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 39T
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Teaching Lab 208
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in classroom
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 40A
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Storage Room 207
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
D	
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	<u> </u>



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 40B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Storage Room 207
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not fist operable
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 40C
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 40C Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Storage Room 207
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Storage Room 207 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Storage Room 207 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Storage Room 207 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Storage Room 207 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Storage Room 207 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Storage Room 207 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 1 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Storage Room 207 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 1 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side 13" strike edge clearance Move furniture to provide access
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Storage Room 207 N/A Y Coordinate: N/A Doors or Gates Front App/pull 18" SEC - Blocked 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: ADMINI As-built: 1 Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side 13" strike edge clearance Move furniture to provide access 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 40D
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Storage Room 207
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	3" strike edge clearance
Rec. Solution:	Move stored items
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 40E
	3/25/2014 Report Date 5/27/2014 Barrier #: 40E Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Storage Room 207
Field Date: Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Storage Room 207 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Storage Room 207 N/A Y Coordinate: N/A Controls and Mechanisms First Aid Kit - High Reach Range
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Storage Room 207 N/A Y Coordinate: N/A Controls and Mechanisms First Aid Kit - High Reach Range 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Storage Room 207 N/A Y Coordinate: N/A Controls and Mechanisms First Aid Kit - High Reach Range 2010 ADAS 305.3
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Storage Room 207 N/A Y Coordinate: N/A Controls and Mechanisms First Aid Kit - High Reach Range 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Storage Room 207 N/A Y Coordinate: N/A Controls and Mechanisms First Aid Kit - High Reach Range 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Opening mechanism on first aid kit not at max. 48" high for side reach
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Storage Room 207 N/A Y Coordinate: N/A Controls and Mechanisms First Aid Kit - High Reach Range 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Opening mechanism on first aid kit not at max. 48" high for side reach 68-1/4" high. Mechanism not fist operable
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Storage Room 207 N/A Y Coordinate: N/A Controls and Mechanisms First Aid Kit - High Reach Range 2010 ADAS 305.3 ndard: No Quantity: EACH As-built: 1 Opening mechanism on first aid kit not at max. 48" high for side reach 68-1/4" high. Mechanism not fist operable Relocate control or mechanism to max. 48" high 1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 40F
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Storage Room 207
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Hi/low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of control involves low reach of less than 15" above floor or more than 48" high
Findings:	Resistor dispenser 62" high
Rec. Solution:	Relocate to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 40G
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Storage Room 207
Location: X Coordinate:	Floor 2 - Storage Room 207 N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Controls and Mechanisms Lockers - Control
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Controls and Mechanisms Lockers - Control 2010 ADAS 803.5
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Controls and Mechanisms Lockers - Control 2010 ADAS 803.5
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	N/A Y Coordinate: N/A Controls and Mechanisms Lockers - Control 2010 ADAS 803.5 Indard: No Quantity: EACH As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Y Coordinate: N/A Controls and Mechanisms Lockers - Control 2010 ADAS 803.5 Indard: No Quantity: EACH As-built: 1 Locker mechanism not operable with fist or involves turning and grasping
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Controls and Mechanisms Lockers - Control 2010 ADAS 803.5 Indard: No Quantity: EACH As-built: 1 Locker mechanism not operable with fist or involves turning and grasping Mechanism not fist operable. Locker cabinet block other cabinet clear floor space Provide min. 1 accessible locker or 5% overall
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Controls and Mechanisms Lockers - Control 2010 ADAS 803.5 Indard: No Quantity: EACH As-built: 1 Locker mechanism not operable with fist or involves turning and grasping Mechanism not fist operable. Locker cabinet block other cabinet clear floor space Provide min. 1 accessible locker or 5% overall 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 40H
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Storage Room 207
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Counter - Surface Height
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No section at least 3 feet long between 28" and 34" provided at existing counter
Findings:	36-1/4" high
Rec. Solution:	Provide min. 3 ft long section of counter at max. 34" high
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 401
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Storage Room 207
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Faucet Operating Force
Code References:	2010 ADAS 606.4 & 309
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Faucets force to activate controls is greater than 5 pounds-force lbf (22.2 N).
Findings:	9 lbf
Rec. Solution:	Replace faucet
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	
Notes:	· - · · · - · · · · - · · · · · ·



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 40J
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Storage Room 207
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Rim or Countertop
Code References:	2010 ADAS 606.3
Performance Sta	andard: No Quantity: LF As-built: 3
Barrier Description:	Sink rim or surface not max. 34" high
Findings:	36" high. Clear space not provided to approach sink
Rec. Solution:	Reposition existing sink or provide min. 1 accessible sink for use in area
Barrier Severity:	1 Necessary Cost Est \$1,110.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 40K
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Storage Room 207
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Depth
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built : 0
Barrier	Sink depth exceeds 6-1/2" deep
Description:	Sink depth exceeds 0-1/2 deep
Description: Findings:	8" deep
·	
Findings:	8" deep Provide min. 1 accessible sink
Findings: Rec. Solution:	8" deep Provide min. 1 accessible sink 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 40L
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Storage Room 207
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Exposed Pipes
Code References:	2010 ADAS 606.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Exposed hot water/drain pipes not insulated or configured so as to protect against contact
Findings:	No insulation provided
Rec. Solution:	Provide insulation at drain pipes
Barrier Severity:	2 Recommended Cost Est \$120.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 40M
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Storage Room 207
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Knee Clearance
Code References:	2010 ADAS 606.2 & 306
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Knee clearance of at least 30" wide and 8" deep at 27" high with 11" depth at 9" high
Findings:	26-3/4" high and 20" wide knee clearance
Rec. Solution:	Replace cabinet and remount sink
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	· — · — · — · — — ·



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 40N
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Storage Room 207
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Forward Reach Obstructed (10"-25")
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44"
Findings:	Paper towel dispenser located 63" high and 18-1/2" deep over an obstruction 36" high
Rec. Solution:	Relocate control or mechanism to max. 44" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 400
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Storage Room 207
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 41A
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 41B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not fist operable
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 41C
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Location
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not located between 34" and 48" above ground/floor
Findings:	29" high
Rec. Solution:	Remount new hardware at max. 48" high
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 41D
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Kickplate
Code References:	2010 ADAS 404.2.10
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate lacks min. 10" smooth uninterrupted bottom surface
Findings:	Bottom of door not smooth and uninterrupted. Opening 2-3/4" high
Rec. Solution:	Provide min. 10" high kick plate at push side of door
Barrier Severity:	1 Necessary Cost Est \$225.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 41E
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Clear Width
Code References:	2010 ADAS 404.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clear width passage through door, sliding/folding door or gate is not min. 32"
Findings:	27-1/4" clear width
Rec. Solution:	Replace door or gate and frame
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 41F
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Relocate Door
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	14-1/2" strike edge clearance
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$4,500.00 Facility Function: Public Status: Open
Implementation	
	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 41G
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Landing - Length
Code References:	2010 ADAS 404.2.4
Performance Sta	andard: No Quantity: SF As-built : 0
Barrier Description:	Landing length is not at least 44" in direction of pedestrian travel
Findings:	19-1/2" long
Rec. Solution:	Rearrange shelves to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 41H
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Accessible Route
Code References:	2010 ADAS 305
Performance Sta	andard: No Quantity: JOB As-built : 100
Barrier Description:	Clear floor space does not adjoin an accessible route or another space
Findings:	Step at entry 7-1/2" high
Rec. Solution:	Remodel area to provide connection to accessible route
Barrier Severity:	2 Recommended Cost Est \$17,500.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 411
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	51" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 41J
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Shelves or Cabinets
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Shelf or cabinet not mounted max. 48" above floor or ground
Findings:	Shelf or cabinet not accessible
Rec. Solution:	Provide additional shelf at accessible height or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 41K
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36"
Code References:	2010 ADAS 403.5.1
Performance Sta	indard: No Quantity: LF As-built : 20
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	Passageway less than 36" in multiple locations
Rec. Solution:	Remodel to provide access
Barrier Severity:	1 Necessary Cost Est \$2,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 11" - 27	-1/2" wide circulation route
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 41L
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	
	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Barrier Type: Code References:	
Code	Clear Floor Space - 60" Turning Circle 2010 ADAS 304.3.1
Code References:	Clear Floor Space - 60" Turning Circle 2010 ADAS 304.3.1
Code References: Performance Sta Barrier	Clear Floor Space - 60" Turning Circle 2010 ADAS 304.3.1 Indard: No Quantity: SF As-built: 0
Code References: Performance Sta Barrier Description:	Clear Floor Space - 60" Turning Circle 2010 ADAS 304.3.1 Indard: No Quantity: SF As-built: 0 Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Code References: Performance Sta Barrier Description: Findings:	Clear Floor Space - 60" Turning Circle 2010 ADAS 304.3.1 Indard: No Quantity: SF As-built: 0 Clear floor space of min. 60" in diameter not provided where 360 degree turn is made 27-1/2" turning circle Remodel area to provide min. 60" turning space
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Clear Floor Space - 60" Turning Circle 2010 ADAS 304.3.1 Indard: No Quantity: SF As-built: 0 Clear floor space of min. 60" in diameter not provided where 360 degree turn is made 27-1/2" turning circle Remodel area to provide min. 60" turning space 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 41M
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 42A
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code	
References:	2010 ADAS 216.2
References: Performance Sta	
Performance Sta Barrier	ndard: No Quantity: EACH As-built : 1
Performance Sta Barrier Description:	ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs
Performance Sta Barrier Description: Findings:	No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign
Performance Sta Barrier Description: Findings: Rec. Solution:	No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 42B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not fist operable
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 42C
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 42C Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Open Lab 206
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Open Lab 206 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Open Lab 206 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Open Lab 206 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Open Lab 206 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Open Lab 206 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Open Lab 206 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10 ndard: No Quantity: EACH As-built: 1 Door/Gate lacks min. 10" smooth uninterrupted bottom surface
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Open Lab 206 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10 ndard: No Quantity: EACH As-built: 1 Door/Gate lacks min. 10" smooth uninterrupted bottom surface Bottom of door not smooth and uninterrupted. 9" high bevel at bottom of door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Open Lab 206 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10 ndard: No Quantity: EACH As-built: 1 Door/Gate lacks min. 10" smooth uninterrupted bottom surface Bottom of door not smooth and uninterrupted. 9" high bevel at bottom of door Provide min. 10" high kick plate at push side of door 1 Necessary Cost Est \$225.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 42D
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Relocate Door
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	12" strike edge clearance to raised floor
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$4,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 42E
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Latch App/pull 54"
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	andard: No Quantity: EACH As-built : 20
Barrier Description:	Door/Gate with latch approach with closer at pull side lacks min. 54" perpendicular to door
Findings:	48-1/2" perpendicular to door/gate. Step at entry 7-1/2" high
Rec. Solution:	Remodel area to provide accessible route into room
Barrier Severity:	1 Necessary Cost Est \$45,000.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 42F
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 42G
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard & 2010 ADAS 904.3.3
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 38" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	
Notes: Bottom	edge of whiteboard surface at 38" high over an obstruction higher than 34"



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 42H
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24-1/4" high knee clearance
Rec. Solution:	Provide min. 1 accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 421
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Shelves or Cabinets
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Shelf or cabinet not mounted max. 48" above floor or ground
Findings:	Shelf or cabinet not accessible
Rec. Solution:	Provide additional shelf at accessible height or provide assistance
Barrier Severity:	
Implementation	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
implementation	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 42J
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36"
Code References:	2010 ADAS 403.5.1
Performance Sta	andard: No Quantity: LF As-built: 100
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	21" - 27" wide circulation route
Rec. Solution:	Remodel to provide accessible passageway
Barrier Severity:	1 Necessary Cost Est \$12,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 42K
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Accessible Route
Code References:	2010 ADAS 305
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space does not adjoin an accessible route or another space
Findings:	Multiple holes in floor
Rec. Solution:	Cover holes in floor within circulation route
Rec. Solution: Barrier Severity:	
	2 Recommended Cost Est \$175.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 42L
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 206
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 43A
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - System Administration Laboratory 205
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 43B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - System Administration Laboratory 205
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Kickplate
Code References:	2010 ADAS 404.2.10
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate lacks min. 10" smooth uninterrupted bottom surface
Findings:	Bottom of door not smooth and uninterrupted. Panel 8-3/4" high ta bottom of door
Rec. Solution:	Provide min. 10" high kick plate at push side of door
Barrier Severity:	1 Necessary Cost Est \$225.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 43C
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 43C Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - System Administration Laboratory 205
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - System Administration Laboratory 205 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - System Administration Laboratory 205 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - System Administration Laboratory 205 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - System Administration Laboratory 205 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - System Administration Laboratory 205 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - System Administration Laboratory 205 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 1 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - System Administration Laboratory 205 N/A Y Coordinate: N/A Doors or Gates Front App/push 12" SEC 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 1 Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer 9" strike edge clearance Relocate door or gate to provide maneuvering clearance 1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 43D
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - System Administration Laboratory 205
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Doorway - Front App 48"
Code References:	2010 ADAS 404.2.4.2
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door opening lacks min. 48" perpendicular to door
Findings:	Maneuvering clearance perpendicular to door measured at less than 48"
Rec. Solution:	Remodel to provide maneuvering clearance
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 26" to tl	he trash can at entry
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 43E
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 43E Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - System Administration Laboratory 205
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - System Administration Laboratory 205 N/A Y Coordinate: N/A Doors or Gates Landing - Length
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - System Administration Laboratory 205 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - System Administration Laboratory 205 N/A Y Coordinate: N/A Doors or Gates Landing - Length 2010 ADAS 404.2.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - System Administration Laboratory 205 N/A Y Coordinate: N/A Doors or Gates Landing - Length 2010 ADAS 404.2.4
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - System Administration Laboratory 205 N/A Y Coordinate: N/A Doors or Gates Landing - Length 2010 ADAS 404.2.4 Indard: No Quantity: SF As-built: 120
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - System Administration Laboratory 205 N/A Y Coordinate: N/A Doors or Gates Landing - Length 2010 ADAS 404.2.4 Indard: No Quantity: SF As-built: 120 Landing length is not at least 44" in direction of pedestrian travel
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - System Administration Laboratory 205 N/A Y Coordinate: N/A Doors or Gates Landing - Length 2010 ADAS 404.2.4 Indard: No Quantity: SF As-built: 120 Landing length is not at least 44" in direction of pedestrian travel 42-3/4" long to 7-1/2" high step at entry Demolish and reconstruct accessible ramp
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - System Administration Laboratory 205 N/A Y Coordinate: N/A Doors or Gates Landing - Length 2010 ADAS 404.2.4 Indard: No Quantity: SF As-built: 120 Landing length is not at least 44" in direction of pedestrian travel 42-3/4" long to 7-1/2" high step at entry Demolish and reconstruct accessible ramp 1 Necessary Cost Est \$15,000.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 43F
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - System Administration Laboratory 205
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 43G
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - System Administration Laboratory 205
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Clear Floor Chase Stared Floments
Code	Clear Floor Space - Stored Elements
References:	2010 ADAS 305.3
	2010 ADAS 305.3
References:	2010 ADAS 305.3
References: Performance Sta Barrier	2010 ADAS 305.3 andard: No Quantity: JOB As-built : 1
References: Performance Sta Barrier Description:	2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism
References: Performance Sta Barrier Description: Findings:	2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Whiteboard blocks cabinet clear floor space Move stored items
References: Performance Sta Barrier Description: Findings: Rec. Solution:	2010 ADAS 305.3 andard: No Quantity: JOB As-built: 1 Clear floor space for wheelchair not provided at control or mechanism Whiteboard blocks cabinet clear floor space Move stored items 1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 43H
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - System Administration Laboratory 205
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Accessible Route
Code References:	2010 ADAS 305
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space does not adjoin an accessible route or another space
Findings:	Multiple holes in floor
Rec. Solution:	Cover holes in floor in circulation route
Barrier Severity:	2 Recommended Cost Est \$175.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 431
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - System Administration Laboratory 205
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	26" knee clearance
Rec. Solution:	Provide min. one accessible desk or workstation
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open
Implementation	
Notes: 6 desks	and none are accessible



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 43J
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - System Administration Laboratory 205
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Shelves or Cabinets
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Shelf or cabinet not mounted max. 48" above floor or ground
Findings:	Shelf or cabinet not accessible
Rec. Solution:	Provide additional shelf at accessible height or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Shelves	on top of desks 48" high
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 43K
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - System Administration Laboratory 205
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Clear Floor Space - 60" Turning Circle
Code References:	2010 ADAS 305
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space of min. 60" in diameter not provided where 360 degree turn is made
Findings:	57" turning circle on each side of the room
Rec. Solution:	Move stored items blocking maneuvering clearance
Barrier Severity:	
	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 43L
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - System Administration Laboratory 205
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 44A
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 44A Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H201
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H201 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H201 N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H201 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H201 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H201 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H201 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 2 No tactile characters at sign identifying permanent rooms and spaces with visual signs
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H201 N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H201 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 44B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Hallway H201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-3/4" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	2/25/2044 Poport Data 5/27/2044 Darrior #1 140
ricia Date.	3/25/2014 Report Date 5/27/2014 Barrier #: 44C
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H201
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H201 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H201 N/A Y Coordinate: N/A Alarms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H201 N/A Y Coordinate: N/A Alarms Horn/Strobe - Corridor 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H201 N/A Y Coordinate: N/A Alarms Horn/Strobe - Corridor 2010 ADAS 702.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H201 N/A Y Coordinate: N/A Alarms Horn/Strobe - Corridor 2010 ADAS 702.1 andard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H201 N/A N/A Alarms Horn/Strobe - Corridor 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in corridor
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H201 N/A Alarms Horn/Strobe - Corridor 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in corridor No device provided Provide strobe in common use area
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Hallway H201 N/A V Coordinate: N/A Alarms Horn/Strobe - Corridor 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in corridor No device provided Provide strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 45A
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code	2010 ADAS 216.2
References:	2010 ADAS 210.2
Performance Sta	andard: No Quantity: EACH As-built : 4
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$1,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Rooms	211, 211A, 210 and 209
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 45B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	10 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	
	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 45C
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	3 second sweep
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 45D
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
=	5 [10.0
Location:	Floor 2 - Open Lab 211
•	
Location:	Floor 2 - Open Lab 211
Location: X Coordinate:	Floor 2 - Open Lab 211 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 2 - Open Lab 211 N/A Y Coordinate: N/A Doors or Gates
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 2 - Open Lab 211 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 2 - Open Lab 211 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 2 - Open Lab 211 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10 Indard: No Quantity: EACH As-built: 0
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 2 - Open Lab 211 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10 andard: No Quantity: EACH As-built: 0 Door/Gate lacks min. 10" smooth uninterrupted bottom surface
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 2 - Open Lab 211 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10 Indard: No Quantity: EACH As-built: 0 Door/Gate lacks min. 10" smooth uninterrupted bottom surface Bottom of door not smooth and uninterrupted. 9-3/4" high panel at bottom of door Provide automatic door opening device
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 2 - Open Lab 211 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10 mdard: No Quantity: EACH As-built: 0 Door/Gate lacks min. 10" smooth uninterrupted bottom surface Bottom of door not smooth and uninterrupted. 9-3/4" high panel at bottom of door Provide automatic door opening device 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 45E
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Ramps
Barrier Type:	Ramp Landing - Change in Direction
Code References:	2010 ADAS 405.7.4
Performance Sta	ndard: No Quantity: LF As-built : 20
Barrier Description:	Change in direction at landing is not min. 60" x 60"
Findings:	42-1/4" long
Rec. Solution:	Demolish and reconstruct level landing at ramp to allow change of direction
Barrier Severity:	2 Recommended Cost Est \$4,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Ramp 4	2-1/2" wide at electrical box
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 45F
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Ramps
Barrier Type:	Handrail
Code References:	2010 ADAS 505.2
Performance Sta	ndard: No Quantity: LF As-built: 14
Barrier Description:	No handrail provided at both sides
Findings:	Ramp lacks handrail at both sides
Rec. Solution:	Replace handrails at both sides of ramp
Barrier Severity:	1 Necessary Cost Est \$3,150.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	· · · · · · · · · · · · · · · · · · ·



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 45G
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49" high. Garbage can blocks switch clear floor space
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 45H
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard & 2010 ADAS 904.3.3
Performance Sta	ndard: Yes Quantity: EACH As-built : 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 38-1/2" high from floor. Garbage cans block whiteboard clear floor space
Rec. Solution:	
	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	
Barrier Severity: Implementation	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 45I
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Hi/low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Use of control involves low reach of less than 15" above floor or more than 48" high
Findings:	Printer controls 52-1/2" high. Stored elements block printer clear floor space
Rec. Solution:	Relocate within accessible reach range
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 45J
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Shelf protrudes 8" at 74" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	7



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 45K	
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5	Market Day
Location:	Floor 2 - Open Lab 211	
X Coordinate:	N/A Y Coordinate: N/A	
Barrier Area:	Counters and Tables	
Barrier Type:	Desk - Knee Clearance	02/00/01/01/01/02/02
Code References:	2010 ADAS 902.3	
Performance Sta	ndard: No Quantity: EACH As-built : 1	
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide	
Findings:	26-3/4" knee clearance	
Rec. Solution:	Provide min. one accessible desk or workstation	
Barrier Severity:	3 Hindrance Cost Est \$875.00 Facility Fur	nction: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Imp	lementation Date:
Notes:		
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 45L	AFF F
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5	
Location:	Floor 2 - Open Lab 211	
X Coordinate:	N/A Y Coordinate: N/A	
Barrier Area:	Controls and Mechanisms	
Barrier Type:	Shelves or Cabinets	03/20/2014 12:00
Code References:	2010 ADAS 305.3	
Performance Sta	ndard: No Quantity: JOB As-built : 1	
Barrier Description:	Shelf or cabinet not mounted max. 48" above floor or grour	nd
Findings:	Shelf or cabinet not accessible	
Rec. Solution:	Provide additional shelf at accessible height or provide assis	stance
Barrier Severity:	C. J. S. J. Box S. J. S. J. J. S. J.	
	3 Hindrance Cost Est \$0.00 Facility Fur	nction: Public Status: Open
Implementation		nction: Public Status: Open lementation Date:



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 45M
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Forward Reach Obstructed (10"-25")
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44"
Findings:	Electrical outlets at desks 33-1/4" high and 34-1/2" deep over desk obstruction 29-3/4" high
Rec. Solution:	Relocate control or mechanism to max. 44" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 45N
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	TV protrudes 7" at 47-1/2" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 450
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 211
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Accessible Route
Code References:	2010 ADAS 305
Performance Sta	indard: No Quantity: JOB As-built : 1
Barrier Description:	Clear floor space does not adjoin an accessible route or another space
Findings:	Multiple holes in floor but are under workstations/desks
Rec. Solution:	Cover holes in floor within circulation route
Barrier Severity:	2 Recommended Cost Est \$175.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 45P
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Open Lab 211
	JFIOOT 2 - Open Lab 211
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A Alarms Horn/Strobe - Common Use Area
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Alarms
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Alarms Horn/Strobe - Common Use Area 2010 ADAS 702.1
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Alarms Horn/Strobe - Common Use Area 2010 ADAS 702.1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	N/A Alarms Horn/Strobe - Common Use Area 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Alarms Horn/Strobe - Common Use Area 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Alarms Horn/Strobe - Common Use Area 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas No device provided Provide strobe in common use area
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Y Coordinate: N/A Alarms Horn/Strobe - Common Use Area 2010 ADAS 702.1 Indard: No Quantity: EACH As-built: 1 No horn/strobes in common use areas No device provided Provide strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 46A
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Grad Student Office 212
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 46B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Grad Student Office 212
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 46C
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Grad Student Office 212
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Electrical box protrudes 6-1/4" at 46-1/4" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 46D
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Grad Student Office 212
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard & 2010 ADAS 904.3.3
Performance Sta	andard: Yes Quantity: EACH As-built: 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 41-1/4" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 46E
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Grad Student Office 212
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24-1/4" high knee clearance
Rec. Solution:	Provide min. 1 accessible table
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Center t	able
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 46F
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Grad Student Office 212
Location: X Coordinate:	Floor 2 - Grad Student Office 212 N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Classrooms Sink - Faucet Operating Force
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Classrooms Sink - Faucet Operating Force 2010 ADAS 606.4 & 309
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Classrooms Sink - Faucet Operating Force 2010 ADAS 606.4 & 309
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	N/A Y Coordinate: N/A Classrooms Sink - Faucet Operating Force 2010 ADAS 606.4 & 309 Indard: No Quantity: EACH As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Y Coordinate: N/A Classrooms Sink - Faucet Operating Force 2010 ADAS 606.4 & 309 Indard: No Quantity: EACH As-built: 1 Faucets force to activate controls is greater than 5 pounds-force lbf (22.2 N).
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Classrooms Sink - Faucet Operating Force 2010 ADAS 606.4 & 309 Indard: No Quantity: EACH As-built: 1 Faucets force to activate controls is greater than 5 pounds-force lbf (22.2 N). Replace faucet Replace faucet
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Y Coordinate: N/A Classrooms Sink - Faucet Operating Force 2010 ADAS 606.4 & 309 Indard: No Quantity: EACH As-built: 1 Faucets force to activate controls is greater than 5 pounds-force lbf (22.2 N). 12 lbf Replace faucet 1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 46G
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Grad Student Office 212
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Rim or Countertop
Code References:	2010 ADAS 606.3
Performance Sta	indard: No Quantity: LF As-built : 3
Barrier Description:	Sink rim or surface not max. 34" high
Findings:	36-1/2" high
Rec. Solution:	Reposition existing sink or provide min. 1 accessible sink for use in area
Barrier Severity:	1 Necessary Cost Est \$1,110.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Faucet h	nardware also 46" high over 18" deep rim at 36-1/2" high
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 46H
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Grad Student Office 212
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Depth (09/20/2014 19:3)
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built : 0
Barrier Description:	Sink depth exceeds 6-1/2" deep
Findings:	12" deep
Rec. Solution:	Provide min. 1 accessible sink
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 46I
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Grad Student Office 212
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Knee Clearance
Code References:	2010 ADAS 606.2 & 306
Performance Sta	indard: No Quantity: EACH As-built : 0
Barrier Description:	Knee clearance of at least 27" high, 19" deep and 30" wide not provided
Findings:	24-1/4" high and 16" wide knee clearance
Rec. Solution:	Replace sink
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 46J
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Grad Student Office 212
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Exposed Pipes
Code References:	2010 ADAS 606.5
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Exposed hot water/drain pipes not insulated or configured so as to protect against contact
Findings:	No insulation provided
Rec. Solution:	Provide insulation at drain pipes
Barrier Severity:	2 Recommended Cost Est \$120.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 46K
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Grad Student Office 212
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Forward Reach Obstructed (10"-25")
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44"
Findings:	Soap dispenser 40" high and 19-1/2" deep over sink rim 36-1/2" high
Rec. Solution:	Relocate control or mechanism to max. 44" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 46L
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Grad Student Office 212
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Hi/low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of control involves low reach of less than 15" above floor or more than 48" high
Findings:	Printer controls 54" high
Rec. Solution:	Relocate with accessible reach range
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 46M
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Grad Student Office 212
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	ndard: No Quantity: JOB As-built: 1
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	Passageway less than 36" in multiple locations
Rec. Solution:	Rearrange furniture to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 17" wide	e circulation route to bookcase
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 46N
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Grad Student Office 212
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Desk - Knee Clearance
Code References:	2010 ADAS 902.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24-1/2" - 25-1/2" high and 24-1/2" wide knee clearance
Rec. Solution:	Provide min. one accessible desk or workstation
Barrier Severity:	
Implementation	
Notes: 3 desks	implementation rade.



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 460
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Grad Student Office 212
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 47A
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Elevator E201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Emergency Sign at Call Station
Code References:	Performance Standard & 2010 ADAS 703.1
Performance Sta	andard: Yes Quantity: EACH As-built: 1
Barrier Description:	Sign stating "IN FIRE EMERGENCY, DO NOT USE ELEVATOR. USE EXIT STAIRS" not provided with tactile information
Findings:	No tactile information on sign
Findings: Rec. Solution:	No tactile information on sign Replace sign
_	Replace sign
Rec. Solution:	Replace sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 47B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Elevator E201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Doorjamb marking - Height
Code References:	2010 ADAS 407.2.3.1
Performance Sta	indard: No Quantity: EACH As-built: 1
Barrier Description:	Elevator landing door jamb signage not located 60" on center on both jamb panels
Findings:	54" high
Rec. Solution:	Replace door jamb signage
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 47C
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Elevator E201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Hall lanterns - Visible at Entry
Code References:	2010 ADAS 407.2.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Visual and audible signals not provided at each hoistway entrance to answer calls
Findings:	Hall lanterns not provided from outer side of elevator
Rec. Solution:	Provide hall lanterns visible from outer side of elevator
Barrier Severity:	1 Necessary Cost Est \$3,675.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 48A
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Viewing From Distance - >70" high
Code References:	2010 ADAS 703.5.5 and Table 703.5.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Signs between 70" and 120" high lack characters at least 2" high
Findings:	Characters on sign above door not large enough to view from a distance
Rec. Solution:	Replace sign with characters min. 2" in height for viewing at a distance
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 48B
riela Date.	15/25/2014 Report Date 15/27/2014 Burner #. 146B
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S201
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S201 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S201 N/A Y Coordinate: N/A Stairways
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S201 N/A Y Coordinate: N/A Stairways Sign - Exit Door Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S201 N/A Y Coordinate: N/A Stairways Sign - Exit Door Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S201 N/A Y Coordinate: N/A Stairways Sign - Exit Door Performance Standard Indard: Yes Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S201 N/A Y Coordinate: N/A Stairways Sign - Exit Door Performance Standard Indard: Yes Quantity: EACH As-built: 1 Door leading directly into an exit stairway lacks tactile exit sign
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S201 N/A Y Coordinate: N/A Stairways Sign - Exit Door Performance Standard ndard: Yes Quantity: EACH As-built: 1 Door leading directly into an exit stairway lacks tactile exit sign Door to exit stair with low level illuminated sign lacks tactile exit sign Provide sign stating "EXIT STAIR DOWN (or UP)" at latch side of door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 4 of 5 Floor 2 - Stairway S201 N/A Y Coordinate: N/A Stairways Sign - Exit Door Performance Standard ndard: Yes Quantity: EACH As-built: 1 Door leading directly into an exit stairway lacks tactile exit sign Door to exit stair with low level illuminated sign lacks tactile exit sign Provide sign stating "EXIT STAIR DOWN (or UP)" at latch side of door 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 48C
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Door Closer - Interior Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	35 lbf
Rec. Solution:	Replace or adjust existing closer. Door does not lead to an accessible route
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 48D
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Door Closer - Interior Sweep ADA
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	4 second sweep
Rec. Solution:	Replace or adjust existing closer. Door does not lead to an accessible route
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 48E
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Relocate Door
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	10-3/4" strike edge clearance
Rec. Solution:	No remediation recommended. Door does not lead to an accessible route
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 48F
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Sign - Encl Stairway Level
Code References:	ICC A117.1
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Tactile stairway signage not provided to indicate floor level
Findings:	No tactile sign provided to indicate floor level
Rec. Solution:	Provide sign
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 48G
Bldg Name:	Dearborn Hall Reference Dwg: 4 of 5
Location:	Floor 2 - Stairway S201
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 49A
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Bldg Name: Location:	
	Dearborn Hall Reference Dwg: 5 of 5
Location:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S301
Location: X Coordinate:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S301 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S301 N/A Y Coordinate: N/A Stairways
Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S301 N/A Y Coordinate: N/A Stairways Sign - Exit Door Performance Standard
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S301 N/A Y Coordinate: N/A Stairways Sign - Exit Door Performance Standard
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S301 N/A Y Coordinate: N/A Stairways Sign - Exit Door Performance Standard ndard: Yes Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S301 N/A Y Coordinate: N/A Stairways Sign - Exit Door Performance Standard Indard: Yes Quantity: EACH As-built: 1 Door leading directly into an exit stairway lacks tactile exit sign
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S301 N/A Y Coordinate: N/A Stairways Sign - Exit Door Performance Standard ndard: Yes Quantity: EACH As-built: 1 Door leading directly into an exit stairway lacks tactile exit sign Door to exit stair with low level illuminated sign lacks tactile exit sign Provide sign stating "EXIT STAIR DOWN (or UP)" at latch side of door
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S301 N/A Y Coordinate: N/A Stairways Sign - Exit Door Performance Standard ndard: Yes Quantity: EACH As-built: 1 Door leading directly into an exit stairway lacks tactile exit sign Door to exit stair with low level illuminated sign lacks tactile exit sign Provide sign stating "EXIT STAIR DOWN (or UP)" at latch side of door 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 49B
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Stairway S301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Door Closer - Interior Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	17 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 49C
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Stairway S301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Door Closer - Backcheck
Code	
References:	CBC 1133B.2.5 and 2010 ADAS 404.2.8.1
References: Performance Sta	
Performance Sta Barrier	ndard: No Quantity: JOB As-built : 0
Performance Sta Barrier Description:	ndard: No Quantity: JOB As-built : 0 Door closer does not stop at least 5" from door frame (no back check)
Performance Sta Barrier Description: Findings:	Door closer does not stop at least 5" from door frame (no back check) Does not stop at least 5" from close Adjust existing door closer
Performance Sta Barrier Description: Findings: Rec. Solution:	Door closer does not stop at least 5" from door frame (no back check) Does not stop at least 5" from close Adiust existing door closer 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 49D
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Stairway S301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Stairways
Barrier Type:	Sign - Encl Stairway Level
Code References:	ICC A117.1
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Tactile stairway signage not provided to indicate floor level
Findings:	No tactile sign provided to indicate floor level
Rec. Solution:	Provide sign
Barrier Severity:	2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 49E
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Stairway S301
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Stairways
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Stairways Sign - Encl Stairway (Ch 10) ICC A117.1
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Stairways Sign - Encl Stairway (Ch 10) ICC A117.1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	N/A Stairways Sign - Encl Stairway (Ch 10) ICC A117.1 Indard: No Quantity: EACH As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Stairways Sign - Encl Stairway (Ch 10) ICC A117.1 Indard: No Quantity: EACH As-built: 1 Tactile stairway signage incorrectly indicates roof access
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Stairways Sign - Encl Stairway (Ch 10) ICC A117.1 Indard: No Quantity: EACH As-built: 1 Tactile stairway signage incorrectly indicates roof access Accessible sign not provided Replace sign and provide separate tactile stairway level sign at latch side of door
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Y Coordinate: N/A Stairways Sign - Encl Stairway (Ch 10) ICC A117.1 Indard: No Quantity: EACH As-built: 1 Tactile stairway signage incorrectly indicates roof access Accessible sign not provided Replace sign and provide separate tactile stairway level sign at latch side of door 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 49F
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Stairway S301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 50A
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hallway H301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code	
References:	2010 ADAS 216.2
References: Performance Sta	
Performance Sta Barrier	andard: No Quantity: EACH As-built : 10
Performance Sta Barrier Description:	Andard: No Quantity: EACH As-built: 10 No tactile characters at sign identifying permanent rooms and spaces with visual signs
Performance Sta Barrier Description: Findings:	No Quantity: EACH As-built: 10 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign
Performance Sta Barrier Description: Findings: Rec. Solution:	No Quantity: EACH As-built: 10 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign 1 Necessary Cost Est \$2,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 50B
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hallway H301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Extinguisher - Cabinet Hardware
Code References:	2010 ADAS 308.2.2
Performance Sta	indard: No Quantity: JOB As-built : 1
Barrier Description:	Fire extinguisher door hardware not usable by those with hand impairments
Findings:	Cabinet door hardware not accessible
Rec. Solution:	Relocate fire extinguisher hardware
Barrier Severity:	4 Low Severity Cost Est \$1,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: Fire exti	nguisher cabinets not fist operable
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 50C
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hallway H301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Extinguisher - Cabinet Operation
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Fire extinguisher door involves more than 5 lbf to operate
Findings:	Cabinet door hardware not accessible
Rec. Solution:	Relocate fire extinguisher cabinet
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Traditor Traditor



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 50D
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hallway H301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 50E
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hallway H301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull
Code References:	2010 ADAS 309.4
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Fire pull has no usable hardware
Findings:	Fire pull not fist operable
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 50F
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hallway H301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull - Height
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built : 0
Barrier Description:	Fire pulls not between 42" and 48" high
Findings:	61-3/4" high
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 50G
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hallway H301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Alcove - Existing (pre-1992)
Code	2010 ADAS 307.2
References:	2010 ADAS 307.2
References: Performance Sta	
Performance Sta Barrier	Andard: No Quantity: SF As-built: 2 Fountain with a leading edge between 27" and 80" high protrudes more than 4" into the
Performance Sta Barrier Description:	Fountain with a leading edge between 27" and 80" high protrudes more than 4" into the circulation path.
Performance Sta Barrier Description: Findings:	Fountain with a leading edge between 27" and 80" high protrudes more than 4" into the circulation path. Fountain protrudes 6-3/4" at 37-1/4" high outside of alcove Provide wing walls as detectable warning (existing unit only)
Performance Sta Barrier Description: Findings: Rec. Solution:	Fountain with a leading edge between 27" and 80" high protrudes more than 4" into the circulation path. Fountain protrudes 6-3/4" at 37-1/4" high outside of alcove Provide wing walls as detectable warning (existing unit only) 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 50H
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hallway H301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Bubbler water flow
Code References:	2010 ADAS 602.6
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Water flow from bubbler not min. 4" high
Findings:	2-1/2" high water flow from bubbler
Rec. Solution:	Adjust drinking fountain to provide min. 4" high water flow
Barrier Severity:	2 Recommended Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 50I
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 50I Dearborn Hall Reference Dwg: 5 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Hallway H301
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Hallway H301 N/A Y Coordinate: N/A Drinking Fountains Directional ISA
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Hallway H301 N/A Y Coordinate: N/A Drinking Fountains
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Hallway H301 N/A Y Coordinate: N/A Drinking Fountains Directional ISA Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Hallway H301 N/A Y Coordinate: N/A Drinking Fountains Directional ISA Performance Standard
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Hallway H301 N/A Prinking Fountains Directional ISA Performance Standard Name of the property of the prop
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Hallway H301 N/A V Coordinate: N/A Drinking Fountains Directional ISA Performance Standard ndard: Yes Quantity: EACH As-built: 1 Drinking fountain not accessible
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Hallway H301 N/A Prinking Fountains Directional ISA Performance Standard Performance Standard Drinking fountain not accessible Hi fountain not usable for short people or people using wheelchairs
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Hallway H301 N/A Y Coordinate: N/A Drinking Fountains Directional ISA Performance Standard ndard: Yes Quantity: EACH As-built: 1 Drinking fountain not accessible Hi fountain not usable for short people or people using wheelchairs Provide directional ISA at accessible fountain in building 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 50J
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hallway H301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	12-1/2" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 50K
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Hallway H301
Location:	Floor 3 - Hallway H301
Location: X Coordinate:	Floor 3 - Hallway H301 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Floor 3 - Hallway H301 N/A Y Coordinate: N/A Corridors
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 3 - Hallway H301 N/A Y Coordinate: N/A Corridors Sign - Visual Sign 2010 ADAS 703.3
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 3 - Hallway H301 N/A Y Coordinate: N/A Corridors Sign - Visual Sign 2010 ADAS 703.3
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 3 - Hallway H301 N/A Y Coordinate: N/A Corridors Sign - Visual Sign 2010 ADAS 703.3 Indard: No Quantity: EACH As-built: 13
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 3 - Hallway H301 N/A Y Coordinate: N/A Corridors Sign - Visual Sign 2010 ADAS 703.3 Indard: No Quantity: EACH As-built: 13 No Braille/tactile information on visual sign
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 3 - Hallway H301 N/A Y Coordinate: N/A Corridors Sign - Visual Sign 2010 ADAS 703.3 Indard: No Quantity: EACH As-built: 13 No Braille/tactile information on visual sign Accessible sign not provided Provide Braille/tactile sign
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 3 - Hallway H301 N/A Y Coordinate: N/A Corridors Sign - Visual Sign 2010 ADAS 703.3 Accessible sign not provided Provide Braille/tactile sign 1 Necessary Cost Est \$3,250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 50L
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hallway H301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Protruding Object
Code References:	2010 ADAS 307
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding object in circulation path protrudes more than 4" between 27" and 80" high
Findings:	Electrical panel/key box protrudes 9-1/2" at 48" high
Rec. Solution:	Remove object or provide detectable warning (wing walls)
Barrier Severity:	1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 50M
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Hallway H301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Corridors
Barrier Type:	Horn/Strobe Device
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier	No house or studies in consider whose five clause exists in building
Description:	No horn or strobe in corridor where fire alarm exists in building
	No horn/strobe in corridor where lire alarm exists in building No horn/strobe provided
Description:	
Description: Findings:	No horn/strobe provided Provide horn/strobe in common use area
Description: Findings: Rec. Solution:	No horn/strobe provided Provide horn/strobe in common use area 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 51A
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Elevator E301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Elevators
Barrier Type:	Hall call buttons
Code References:	2010 ADAS 407.2.1
Performance Sta	indard: No Quantity: EACH As-built: 1
Barrier Description:	The centerline of the hall call buttons not max. 42" above the floor
Findings:	41-3/8" high
Rec. Solution:	Replace hall call buttons
Barrier Severity:	1 Necessary Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 52B
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 52B Dearborn Hall Reference Dwg: 5 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Elevator E301
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Elevator E301 N/A Y Coordinate: N/A Elevators Doorjamb marking
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Elevator E301 N/A Y Coordinate: N/A Elevators
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Elevator E301 N/A Y Coordinate: N/A Elevators Doorjamb marking 2010 ADAS 407.2.3.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Elevator E301 N/A Y Coordinate: N/A Elevators Doorjamb marking 2010 ADAS 407.2.3.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Elevator E301 N/A Y Coordinate: N/A Elevators Doorjamb marking 2010 ADAS 407.2.3.1 Indard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Elevator E301 N/A Y Coordinate: N/A Elevators Doorjamb marking 2010 ADAS 407.2.3.1 Indard: No Quantity: EACH As-built: 1 Elevator landing door jamb signage not located 60" on center on both jamb panels
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Elevator E301 N/A Y Coordinate: N/A Elevators Doorjamb marking 2010 ADAS 407.2.3.1 Elevator landing door jamb signage not located 60" on center on both jamb panels 54" high on center Replace door iamb signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Elevator E301 N/A Y Coordinate: N/A Elevators Doorjamb marking 2010 ADAS 407.2.3.1 Indard: No Quantity: EACH As-built: 1 Elevator landing door jamb signage not located 60" on center on both jamb panels 54" high on center Replace door jamb signage 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 52A
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 304A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Sign - No Tactile Characters
Code References:	2010 ADAS 703.1
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces
Findings:	Accessible sign not provided
Rec. Solution:	Replace sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 52B
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 304A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	9 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 52C
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 304A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Closer - Sweep
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	4 second sweep
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 52D
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 52D Dearborn Hall Reference Dwg: 5 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 304A
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 304A N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 304A N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 304A N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 304A N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 304A N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 304A N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10 ndard: No Quantity: EACH As-built: 0 Door/Gate lacks min. 10" smooth uninterrupted bottom surface
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 304A N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10 ndard: No Quantity: EACH As-built: 0 Door/Gate lacks min. 10" smooth uninterrupted bottom surface Bottom of door not smooth and uninterrupted. 9-1/2" high panel at bottom of door
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 304A N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10 ndard: No Quantity: EACH As-built: 0 Door/Gate lacks min. 10" smooth uninterrupted bottom surface Bottom of door not smooth and uninterrupted. 9-1/2" high panel at bottom of door Provide automatic door opening device 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 52E
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 304A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Door Clear Width
Code References:	2010 ADAS 404.2.3
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door clear width is not min. 32"
Findings:	27-1/4" clear width
Rec. Solution:	Replace door or gate and frame
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 52F
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 52F Dearborn Hall Reference Dwg: 5 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 304A
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 304A N/A Y Coordinate: N/A Restrooms Door Clearance - Pull Side
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 304A N/A Y Coordinate: N/A Restrooms
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 304A N/A Y Coordinate: N/A Restrooms Door Clearance - Pull Side 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 304A N/A Y Coordinate: N/A Restrooms Door Clearance - Pull Side 2010 ADAS Figure 404.2.4.1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 304A N/A Y Coordinate: N/A Restrooms Door Clearance - Pull Side 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 304A N/A Y Coordinate: N/A Restrooms Door Clearance - Pull Side 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0 Door lacks min. 18" strike edge clearance at pull side
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 304A N/A Y Coordinate: N/A Restrooms Door Clearance - Pull Side 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0 Door lacks min. 18" strike edge clearance at pull side 5-1/4" strike edge clearance
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Men's Restroom 304A N/A Y Coordinate: N/A Restrooms Door Clearance - Pull Side 2010 ADAS Figure 404.2.4.1 ndard: No Quantity: EACH As-built: 0 Door lacks min. 18" strike edge clearance at pull side 5-1/4" strike edge clearance Provide automatic door opening device 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 52G
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 304A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 52H
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 304A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Hi/Low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of outlet involves low reach of less than 15" above floor or more than 48" high
Findings:	11" high
Rec. Solution:	Relocate outlet to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 52I
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 304A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Dispensers - Protruding Object
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Protruding dispenser creates protruding hazard in path of travel
Findings:	Paper towel dispenser protrudes 10" at 41" high
Rec. Solution:	Relocate dispenser or provide cane-detectable warning
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 52J
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 304A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Lavatory - Knee Clearance
Code References:	2010 ADAS 606.2 & 306
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier	Lavatory bottom apron/edge not max 29" reducing to 27" at 8" back from edge
Description:	Lavatory bottom apron/edge not max 29 reducing to 27 at 8 back from edge
	26" high knee clearance
Description:	
Description: Findings:	26" high knee clearance Provide min. 1 accessible lavatory
Description: Findings: Rec. Solution:	26" high knee clearance Provide min. 1 accessible lavatory 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 52K
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 304A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Floor Drain - Existing
Code References:	2010 ADAS 304.2
Performance Sta	andard: No Quantity: SF As-built : 20
Barrier Description:	Floor drain located within clear floor space of fixture
Findings:	2.2% slope at lavatories
Rec. Solution:	Remodel to provide level floor
Barrier Severity:	3 Hindrance Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 52L
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 304A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Mirror 03/24/2014 16:50
Code References:	2010 ADAS 603.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface
Findings:	53-1/4" high
Rec. Solution:	Replace or remount mirror
Barrier Severity:	3 Hindrance Cost Est \$375.00 Facility Function: Public Status: Open
	13 Timerance 300 200 13575.00 Table 300 100 100 100 100 100 100 100 100 100
Implementation	Priority: 3 Implementation Phase: Implementation Date:



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 52M
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 304A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Flush Controls
Code References:	2010 ADAS 309
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Urinal flush controls mounted higher than 48" above the floor
Findings:	52-1/2" high
Rec. Solution:	Replace urinal controls where possible or entire urinal
Barrier Severity:	2 Recommended Cost Est \$800.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 52N
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 304A
	Men's Restroom so in
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	
	N/A Y Coordinate: N/A
Barrier Area:	N/A Y Coordinate: N/A Restrooms Urinal - Rim
Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Restrooms Urinal - Rim 2010 ADAS 605.2
Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Restrooms Urinal - Rim 2010 ADAS 605.2
Barrier Area: Barrier Type: Code References: Performance Sta Barrier	N/A Y Coordinate: N/A Restrooms Urinal - Rim 2010 ADAS 605.2 ndard: No Quantity: JOB As-built: 1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	N/A Y Coordinate: N/A Restrooms Urinal - Rim 2010 ADAS 605.2 ndard: No Quantity: JOB As-built: 1 Urinal not max. 17" above the floor
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Restrooms Urinal - Rim 2010 ADAS 605.2 ndard: No Quantity: JOB As-built: 1 Urinal not max. 17" above the floor 25" high rim Provide min. 1 accessible urinal
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Restrooms Urinal - Rim 2010 ADAS 605.2 Indard: No Quantity: JOB As-built: 1 Urinal not max. 17" above the floor 25" high rim Provide min. 1 accessible urinal 2 Recommended Cost Est \$800.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 520
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 304A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Urinal - Rim
Code References:	2010 ADAS 605.2
Performance Sta	andard: No Quantity: JOB As-built : 0
Barrier Description:	Min. 1 urinal has no elongated rim projecting 14" to 17" from wall
Findings:	12-1/4" from wall
Rec. Solution:	Provide min. 1 accessible urinal
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 52P
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 304A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet - Clear Space (post-ADA)
Barrier Type: Code References:	Toilet - Clear Space (post-ADA) 2010 ADAS 604.3.1 & 604.8.1.1
Code	2010 ADAS 604.3.1 & 604.8.1.1
Code References:	2010 ADAS 604.3.1 & 604.8.1.1
Code References: Performance Sta Barrier	2010 ADAS 604.3.1 & 604.8.1.1 andard: No Quantity: SF As-built: 140
Code References: Performance Sta Barrier Description:	2010 ADAS 604.3.1 & 604.8.1.1 Indard: No Quantity: SF As-built: 140 Water closet clear space not min. 60" measured wall-to-wall
Code References: Performance Sta Barrier Description: Findings:	2010 ADAS 604.3.1 & 604.8.1.1 andard: No Quantity: SF As-built: 140 Water closet clear space not min. 60" measured wall-to-wall 33" clear width Remodel toilet room to provide clear width
Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	2010 ADAS 604.3.1 & 604.8.1.1 Indard: No Quantity: SF As-built: 140 Water closet clear space not min. 60" measured wall-to-wall 33" clear width Remodel toilet room to provide clear width 2 Recommended Cost Est \$80,500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 52Q
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 304A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Stall Door Closer
Code References:	2010 ADAS 604.8.1.2
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Stall door not equipped with an automatic closing device
Findings:	Door does not self-close
Rec. Solution:	Replace compartment hinge with adjustable mechanism
Barrier Severity:	2 Recommended Cost Est \$1,650.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 52R
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 304A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Toilet Stall - Door Hardware
Code References:	2010 ADAS 604.8.1.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier	Outside of compartment door lacks a loop or U-pull below latch
Description:	Outside of compartment door facks a loop of o-pull below fatch
Description: Findings:	No U-pull provided
·	
Findings:	No U-pull provided Provide hardware
Findings: Rec. Solution:	No U-pull provided Provide hardware 1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 52S
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Men's Restroom 304A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Restrooms
Barrier Type:	Alarm - Horn/Strobe
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Where a fire alarm is installed, no horn/strobe provided
Findings:	No device provided
Rec. Solution:	Provide horn/strobe in sanitary facility
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 53A
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Conference Room 303
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built: 7
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$1,750.00 Facility Function: Public Status: Open
Implementation	
Notes: Rooms 3	303, 303B, C, D, E, F, and G



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 53B
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Conference Room 303
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Adjustment
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	10 lbf
Rec. Solution:	Replace or adjust existing closer
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 53C
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 53C Dearborn Hall Reference Dwg: 5 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 303
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 303 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 303 N/A Y Coordinate: N/A Doors or Gates
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 303 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 303 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 303 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 303 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10 ndard: No Quantity: EACH As-built: 1 Door/Gate lacks min. 10" smooth uninterrupted bottom surface
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 5 of 5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Conference Room 303 N/A Y Coordinate: N/A Doors or Gates Door 10" Bottom Surface - Kickplate 2010 ADAS 404.2.10 ndard: No Quantity: EACH As-built: 1 Door/Gate lacks min. 10" smooth uninterrupted bottom surface Bottom of door not smooth and uninterrupted. 9-1/4" high panel at bottom of door Provide min. 10" high kick plate at push side of door 1 Necessary Cost Est \$225.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 53D
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Conference Room 303
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Clear Width
Code References:	2010 ADAS 404.2.3
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Clear width passage through door, sliding/folding door or gate is not min. 32"
Findings:	27-3/4" clear width for single active leaf of double door
Rec. Solution:	Replace door or gate and frame
Barrier Severity:	1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 53E
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Conference Room 303
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	49-1/2" - 50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	
barrier Severity.	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 53F
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Conference Room 303
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Coat Hook - Height
Code References:	2010 ADAS 308.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Clothing hooks not max. 48" high AFF
Findings:	61-1/2" high
Rec. Solution:	Provide additional hook
Barrier Severity:	2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 53G
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Conference Room 303
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Hi/low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Use of control involves low reach of less than 15" above floor or more than 48" high
Findings:	Projector screen pull 70" high
Rec. Solution:	Relocate to area at min. 15" or max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 53H
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Conference Room 303
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Faucet Operating Force
Code References:	2010 ADAS 606.4 & 309
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Faucets force to activate controls is greater than 5 pounds-force lbf (22.2 N).
Findings:	17 lbf
Rec. Solution:	Replace faucet
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 53I
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Conference Room 303
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Knee Clearance
Code References:	2010 ADAS 606.2 & 306
Performance Sta	indard: No Quantity: LF As-built : 3
Barrier Description:	Knee clearance of at least 27" high, 19" deep and 30" wide not provided
Findings:	26-1/2" high, 10-1/2" deep knee clearance. Clear space not provided to approach sink
Rec. Solution:	Replace cabinet and remount sink
Barrier Severity:	
	1 Necessary Cost Est \$1,350.00 Facility Function: Public Status: Open
Implementation	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 53J
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Conference Room 303
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Exposed Pipes
Code References:	2010 ADAS 606.5
Performance Sta	indard: No Quantity: EACH As-built : 1
Barrier Description:	Exposed hot water/drain pipes not insulated or configured so as to protect against contact
Findings:	No insulation provided
Rec. Solution:	Provide insulation at drain pipes
Barrier Severity:	2 Recommended Cost Est \$120.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 53K
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Conference Room 303
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Chalkboard/Whiteboard - Area of Use
Code References:	Performance Standard & 2010 ADAS 904.3.3
Performance Sta	indard: Yes Quantity: EACH As-built : 1
Barrier Description:	Bottom edge of writing surface not max. 38" high
Findings:	Lower edge of writing surface 45-3/4" high from floor
Rec. Solution:	Remount whiteboard/chalkboard or provide alternate for use by short people
Barrier Severity:	3 Hindrance Cost Est \$1,200.00 Facility Function: Public Status: Open
Implementation	15 minutance States 51,200.00
	· _ · · · <u> </u>



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 53L
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Conference Room 303
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 54A
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - MIME Workroom 303A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	andard: No Quantity: EACH As-built : 2
Barrier	
Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
	No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route
Description:	
Description: Findings:	No tactile signage provided at door within public route Provide accessible sign
Description: Findings: Rec. Solution:	No tactile signage provided at door within public route Provide accessible sign 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 54B
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - MIME Workroom 303A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	15 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 54C
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - MIME Workroom 303A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	4 second sweep
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 54D
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - MIME Workroom 303A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not fist operable
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 54E
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - MIME Workroom 303A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Vision Lights - Existing
Code References:	2010 ADAS 404.2.11
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	View panels in or adjacent to doors or gates not max. 43" above floor or ground
Findings:	View panel located higher than 43" above the floor
Rec. Solution:	Replace door/gate or vision panel
Barrier Severity:	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open
implementation	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 54F
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - MIME Workroom 303A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Door Stop
Code References:	2010 ADAS 404.2.10
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door stop interrupts min. 10" smooth bottom surface
Findings:	Door stop at bottom of door can create trapping condition
Rec. Solution:	Remove door stop or other element at bottom of door at push side
Barrier Severity:	1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 54G
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - MIME Workroom 303A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 18" SEC - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side
Findings:	7-1/2" strike edge clearance to table
Rec. Solution:	Remove table
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 54H
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - MIME Workroom 303A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/pull 60" - Blocked
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	ndard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at with min. 18" at pull side lacks min. 60" perpendicular to door
Findings:	40" clear floor space perpendicular from conference room door to cabinet
Rec. Solution:	Remove cabinet
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 40" clea	r floor space perpendicular from conference room door to cabinet
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 541
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - MIME Workroom 303A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 48"
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	indard: No Quantity: ADMINI As-built : 1
Barrier Description:	Door/Gate at push side with min. 18" lacks min. 48" perpendicular to door
Findings:	Maneuvering clearance perpendicular to door measured at less than 48"
Rec. Solution:	Remove stored item
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 20-1/2"	clear floor space perpendicular to hall door to table



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 54J
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - MIME Workroom 303A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 54K
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - MIME Workroom 303A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Actuator/Control - Hi/low Reach
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built: 1
Barrier Description:	Use of control involves low reach of less than 15" above floor or more than 48" high
Description.	<u></u>
Findings:	Printer controls 50" - 63" high
·	Printer controls 50" - 63" high Relocate to area at min. 15" or max. 48" high
Findings:	Relocate to area at min. 15" or max. 48" high
Findings: Rec. Solution:	Relocate to area at min. 15" or max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 54L
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - MIME Workroom 303A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Table - Knee Clearance
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Knee clearance not min. 27" high, 19" deep or 30" wide
Findings:	24" - 26-1/2" high knee clearance
Rec. Solution:	Provide min. 1 accessible table
Barrier Severity:	3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 4 tables	and none are accessible
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 54M
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - MIME Workroom 303A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Outlets - Forward Reach Obstructed (10"-25")
Code References:	2010 ADAS 308.2.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Outlet located over an 10" to 25" obstruction max. 34" high located above 44"
Findings:	30-1/2" deep over an obstruction 29-1/2" high
Rec. Solution:	Relocate control or mechanism to max. 44" high
Barrier Severity:	2 Uindower Cost Est (750.00 Facility Eupstion: Dublic Status: Ones
	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 54N
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - MIME Workroom 303A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Clear Floor Space
Barrier Type:	Passageway - Min. 36" (Stored Item)
Code References:	2010 ADAS 403.5.1
Performance Sta	ndard: No Quantity: JOB As-built : 0
Barrier Description:	Circulation route not min. 36" wide between elements
Findings:	Passageway less than 36" in multiple locations
Rec. Solution:	Remove furniture or remodel to provide access
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 28-3/4"	circulation route between table and cabinets
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 540
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - MIME Workroom 303A
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 55A
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Teaching Lab 302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 2
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: Rooms 3	302, 302A
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 55B
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Teaching Lab 302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Interior Automatic Door
Code References:	2010 ADAS 404.2.9
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Door opening force exceeds 5 lbf
Findings:	10 lbf
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 55C
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Teaching Lab 302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door Closer - Sweep Period
Code References:	2010 ADAS 404.2.8.1
Performance Sta	ndard: No Quantity: EACH As-built : 0
Barrier Description:	Door closer lacks min. 5 second sweep period
Findings:	3 second sweep
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 55D
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Teaching Lab 302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Front App/push 12" SEC
Code References:	2010 ADAS Figure 404.2.4.1
Performance Sta	indard: No Quantity: EACH As-built : 0
Barrier Description:	Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer
Findings:	11-3/4" strike edge clearance
Rec. Solution:	Provide automatic door opening device
Barrier Severity:	1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	12 Treeessary
Implementation	Priority: 2 Implementation Phase: Implementation Date:



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 55E
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Teaching Lab 302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50-1/2" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 55F
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Teaching Lab 302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Counters and Tables
Barrier Type:	Workstation - Surface Max. 34"
Code References:	2010 ADAS 902
Performance Sta	andard: No Quantity: EACH As-built: 1
renomiance sta	The Country Liver 1
Barrier Description:	Workstation surface height exceeds 34" high
Barrier	
Barrier Description:	Workstation surface height exceeds 34" high
Barrier Description: Findings:	Workstation surface height exceeds 34" high 36-1/2 " high workstation surface and 24-1/2" high knee clearance Provide min. 1 accessible workstation or ensure that min. 5% overall are accessible
Barrier Description: Findings: Rec. Solution:	Workstation surface height exceeds 34" high 36-1/2 " high workstation surface and 24-1/2" high knee clearance Provide min. 1 accessible workstation or ensure that min. 5% overall are accessible 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 55G
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Teaching Lab 302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Shelves or Cabinets
Code References:	2010 ADAS 305.3
Performance Sta	andard: No Quantity: JOB As-built : 1
Barrier Description:	Shelf or cabinet not mounted max. 48" above floor or ground
Findings:	Shelves 48" - 55-1/2" high and 21-3/4" deep over tables 28-1/4" to 36-1/2" high
Rec. Solution:	Provide additional shelf at accessible height or provide assistance
Barrier Severity:	3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 55H
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Teaching Lab 302
Location:	Floor 3 - Teaching Lab 302
Location: X Coordinate:	Floor 3 - Teaching Lab 302 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance
Location: X Coordinate: Barrier Area:	Floor 3 - Teaching Lab 302 N/A Y Coordinate: N/A Counters and Tables
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 3 - Teaching Lab 302 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 3 - Teaching Lab 302 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 3 - Teaching Lab 302 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 andard: No Quantity: EACH As-built: 1
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 3 - Teaching Lab 302 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 andard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 3 - Teaching Lab 302 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 Andard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide 24-1/8" high knee clearance at tables Provide min. 1 accessible table or ensure that min. 5% overall are accessible
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 3 - Teaching Lab 302 N/A Y Coordinate: N/A Counters and Tables Table - Knee Clearance 2010 ADAS 305.3 Andard: No Quantity: EACH As-built: 1 Knee clearance not min. 27" high, 19" deep or 30" wide 24-1/8" high knee clearance at tables Provide min. 1 accessible table or ensure that min. 5% overall are accessible 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 551
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Teaching Lab 302
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 56A
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Janitor's Room 301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Permanent Room/Space - Tactile Characters
Code References:	2010 ADAS 216.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	No tactile characters at sign identifying permanent rooms and spaces with visual signs
Findings:	No tactile signage provided at door within public route
Rec. Solution:	Provide accessible sign
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes:	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 56B
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Janitor's Room 301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Hardware - Operation
Code References:	2010 ADAS 404.2.7
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Hardware not operable with a closed fist
Findings:	Hardware not fist operable
Rec. Solution:	Provide new hardware
Barrier Severity:	1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 56C
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Janitor's Room 301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Door 10" Bottom Surface - Kickplate
Code References:	2010 ADAS 404.2.10
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Door/Gate lacks min. 10" smooth uninterrupted bottom surface
Findings:	Bottom of door not smooth and uninterrupted. 8-3/4" high panel at bottom of door
Rec. Solution:	Provide min. 10" high kick plate at push side of door
	IFTOVIDE ITHIT. 10 THEFT KICK DIALE AL DUSTI SIDE OF DOOL
Barrier Severity:	
Barrier Severity: Implementation	1 Necessary Cost Est \$225.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 56D
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Janitor's Room 301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Doors or Gates
Barrier Type:	Doorway - Front App
Code References:	2010 ADAS Figure 404.2.4.2
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Doorway without door lacks min. 48" clear space perpendicular to doorway
Findings:	42-3/4" perpendicular to door to sink
Rec. Solution:	Remodel to provide access
Barrier Severity:	2 Recommended Cost Est \$2,250.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 56E
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Janitor's Room 301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Light switch control box top edge not at max. 48" high
Findings:	50-1/4" high
Rec. Solution:	Relocate switch box top edge to max. 48" high
Barrier Severity:	
	3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open
Implementation	



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 56F
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Janitor's Room 301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Faucet
Code References:	2010 ADAS 606.4 & 309
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Faucets lack controls and operating mechanisms involve tight grasping, pinching or twisting of the wrist
Findings:	Faucet not fist operable
Rec. Solution:	Replace faucet
Barrier Severity:	1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 56G
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Bldg Name: Location:	
	Dearborn Hall Reference Dwg: 5 of 5
Location:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Janitor's Room 301
Location: X Coordinate:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Janitor's Room 301 N/A Y Coordinate: N/A Classrooms Sink - Faucet Operating Force
Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Janitor's Room 301 N/A Y Coordinate: N/A Classrooms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Janitor's Room 301 N/A Y Coordinate: N/A Classrooms Sink - Faucet Operating Force 2010 ADAS 606.4 & 309
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Janitor's Room 301 N/A Y Coordinate: N/A Classrooms Sink - Faucet Operating Force 2010 ADAS 606.4 & 309
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Janitor's Room 301 N/A Y Coordinate: N/A Classrooms Sink - Faucet Operating Force 2010 ADAS 606.4 & 309 andard: No Quantity: EACH As-built: 0
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Janitor's Room 301 N/A Y Coordinate: N/A Classrooms Sink - Faucet Operating Force 2010 ADAS 606.4 & 309 andard: No Quantity: EACH As-built: 0 Faucets force to activate controls is greater than 5 pounds-force lbf (22.2 N).
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Janitor's Room 301 N/A Y Coordinate: N/A Classrooms Sink - Faucet Operating Force 2010 ADAS 606.4 & 309 andard: No Quantity: EACH As-built: 0 Faucets force to activate controls is greater than 5 pounds-force lbf (22.2 N). 10 - 18 lbf Replace faucet 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 56H
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Janitor's Room 301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Depth
Code References:	Performance Standard
Performance Sta	andard: Yes Quantity: EACH As-built : 1
Barrier Description:	Sink depth exceeds 6-1/2" deep
Findings:	12" deep. Clear space not provided to approach sink
Rec. Solution:	Provide min. 1 accessible sink
Barrier Severity:	1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes: 42-3/4"	to door
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 56I
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Janitor's Room 301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Knee Clearance
Code References:	2010 ADAS 606.2 & 306
Performance Sta	andard: No Quantity: LF As-built: 3
Barrier Description:	Knee clearance of at least 27" high, 19" deep and 30" wide not provided
Findings:	15-3/4" high and 7-1/2" deep knee clearance
	1
Rec. Solution:	Replace cabinet and remount sink
Rec. Solution: Barrier Severity:	
	1 Necessary Cost Est \$1,350.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 56J
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Janitor's Room 301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Classrooms
Barrier Type:	Sink - Exposed Pipes
Code References:	2010 ADAS 606.5
Performance Sta	ndard: No Quantity: EACH As-built : 1
Barrier Description:	Exposed hot water/drain pipes not insulated or configured so as to protect against contact
Findings:	No insulation provided
Rec. Solution:	Provide insulation at drain pipes
Barrier Severity:	2 Recommended Cost Est \$120.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 56K
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Janitor's Room 301
	Floor 3 - Janitor's Room 301 N/A Y Coordinate: N/A
X Coordinate:	N/A Y Coordinate: N/A
X Coordinate: Barrier Area:	N/A Y Coordinate: N/A Controls and Mechanisms
X Coordinate: Barrier Area: Barrier Type: Code	N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3
X Coordinate: Barrier Area: Barrier Type: Code References:	N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Y Coordinate: N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground Shelf or cabinet not accessible Provide additional shelf at accessible height or provide assistance
X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	N/A Controls and Mechanisms Shelves or Cabinets 2010 ADAS 305.3 Indard: No Quantity: JOB As-built: 1 Shelf or cabinet not mounted max. 48" above floor or ground Shelf or cabinet not accessible Provide additional shelf at accessible height or provide assistance 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 56L
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Janitor's Room 301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Horn/Strobe - Common Use Area
Code References:	2010 ADAS 702.1
Performance Sta	ndard: No Quantity: EACH As-built: 1
Barrier Description:	No horn/strobes in common use areas
Findings:	No device provided
Rec. Solution:	Provide strobe in common use area
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 57A
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 57A Dearborn Hall Reference Dwg: 5 of 5
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Bldg Name: Location:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Lobby L301
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Lobby L301 N/A Y Coordinate: N/A
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Lobby L301 N/A Y Coordinate: N/A Signage
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Lobby L301 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Lobby L301 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Lobby L301 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 5 of 5
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Lobby L301 N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Lobby L301 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2 ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs No tactile signage provided at door within public route Provide accessible sign 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 57B
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Lobby L301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Signage
Barrier Type:	Visual Information Provided (Exhibitions)
Code References:	ADA Title II Technical Assistance Manual 3.2000 Denial of participation
Performance Sta	ndard: No Quantity: JOB As-built : 1
Barrier Description:	Visual sign providing information for program, service or activity not accessible
Findings:	Accessible sign not provided
Rec. Solution:	Provide information in alternate format to provide access to people with vision impairments
Barrier Severity:	1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open
Implementation	Priority: 3 Implementation Phase: Implementation Date:
Notes: 4 resear	ch boards
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 57C
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Lobby L301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Controls and Mechanisms
Barrier Type:	Electrical Switches - Height
Code References:	2010 ADAS 308.2
Performance Sta	
Performance Sta Barrier Description:	
Barrier	ndard: No Quantity: EACH As-built : 1
Barrier Description:	ndard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high
Barrier Description: Findings:	Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 50" high Relocate switch box top edge to max. 48" high
Barrier Description: Findings: Rec. Solution:	Indard: No Quantity: EACH As-built: 1 Light switch control box top edge not at max. 48" high 50" high Relocate switch box top edge to max. 48" high 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 57D
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Lobby L301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Alarms
Barrier Type:	Fire Pull - Operation
Code References:	2010 ADAS 309.4
Performance Sta	andard: No Quantity: EACH As-built : 1
Barrier Description:	Fire pull has no fist operable hardware
Findings:	Fire pull not fist operable
Rec. Solution:	Replace fire pull when remodeling
Barrier Severity:	4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open
Implementation	Priority: 2 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 57E
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Bldg Name: Location:	
	Dearborn Hall Reference Dwg: 5 of 5
Location:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Lobby L301
Location: X Coordinate:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Lobby L301 N/A Y Coordinate: N/A
Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Lobby L301 N/A Y Coordinate: N/A Alarms
Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Lobby L301 N/A Y Coordinate: N/A Alarms Fire Pull - Height 2010 ADAS 308.2.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Lobby L301 N/A Y Coordinate: N/A Alarms Fire Pull - Height 2010 ADAS 308.2.2
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Lobby L301 N/A Y Coordinate: N/A Alarms Fire Pull - Height 2010 ADAS 308.2.2 andard: No Quantity: EACH As-built: 0
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Lobby L301 N/A Alarms Fire Pull - Height 2010 ADAS 308.2.2 Indard: No Quantity: EACH As-built: 0 Fire pulls not between 42" and 48" high
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Lobby L301 N/A Y Coordinate: N/A Alarms Fire Pull - Height 2010 ADAS 308.2.2 Andard: No Quantity: EACH As-built: 0 Fire pulls not between 42" and 48" high 64-1/2" high Replace fire pull when remodeling
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Lobby L301 N/A Y Coordinate: N/A Alarms Fire Pull - Height 2010 ADAS 308.2.2 andard: No Quantity: EACH As-built: 0 Fire pulls not between 42" and 48" high 64-1/2" high Replace fire pull when remodeling 4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 57F
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Lobby L301
X Coordinate:	N/A Y Coordinate: N/A
Barrier Area:	Drinking Fountains
Barrier Type:	Alcove - Existing (pre-1992)
Code References:	2010 ADAS 307.2
Performance Sta	andard: No Quantity: SF As-built: 1
Barrier Description:	Fountain with a leading edge between 27" and 80" high protrudes more than 4" into the circulation path.
Findings:	Fountain protrudes 8-3/4" from alcove at 27-1/2" high
Rec. Solution:	Provide wing walls as detectable warning (existing unit only)
Barrier Severity:	1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open
Implementation	Priority: 1 Implementation Phase: Implementation Date:
Notes:	
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 57G
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5
Location:	Floor 3 - Lobby L301
X Coordinate:	
A Coordinate.	N/A Y Coordinate: N/A
Barrier Area:	N/A Y Coordinate: N/A Drinking Fountains
Barrier Area:	Drinking Fountains
Barrier Area: Barrier Type: Code	Drinking Fountains Bubbler water flow 2010 ADAS 602.6
Barrier Area: Barrier Type: Code References:	Drinking Fountains Bubbler water flow 2010 ADAS 602.6
Barrier Area: Barrier Type: Code References: Performance Sta	Drinking Fountains Bubbler water flow 2010 ADAS 602.6 andard: No Quantity: JOB As-built: 1
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Drinking Fountains Bubbler water flow 2010 ADAS 602.6 andard: No Quantity: JOB As-built: 1 Water flow from bubbler not min. 4" high
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Drinking Fountains Bubbler water flow 2010 ADAS 602.6 Indard: No Quantity: JOB As-built: 1 Water flow from bubbler not min. 4" high 3-1/2" high water flow from bubbler Adjust drinking fountain to provide min. 4" high water flow
Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Drinking Fountains Bubbler water flow 2010 ADAS 602.6 andard: No Quantity: JOB As-built: 1 Water flow from bubbler not min. 4" high 3-1/2" high water flow from bubbler Adiust drinking fountain to provide min. 4" high water flow 2 Recommended Cost Est \$275.00 Facility Function: Public Status: Open



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 57H					
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5					
Location:	Floor 3 - Lobby L301					
X Coordinate:	N/A Y Coordinate: N/A					
Barrier Area:	Alarms					
Barrier Type:	Horn/Strobe - Common Use Area					
Code References:	2010 ADAS 702.1					
Performance Sta	ndard: No Quantity: EACH As-built : 1					
Barrier Description:	No horn/strobes in common use areas					
Findings:	No device provided					
Rec. Solution:	Provide strobe in common use area					
Barrier Severity:						
Implementation	Priority: 1 Implementation Phase: Implementation Date:					
Notes:						
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 58A					
Field Date: Bldg Name:	3/25/2014 Report Date 5/27/2014 Barrier #: 58A Dearborn Hall Reference Dwg: 5 of 5					
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5					
Bldg Name: Location:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S302					
Bldg Name: Location: X Coordinate:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S302 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Adjustment					
Bldg Name: Location: X Coordinate: Barrier Area:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S302 N/A Y Coordinate: N/A Doors or Gates					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S302 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Adjustment 2010 ADAS 404.2.9					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S302 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Adjustment 2010 ADAS 404.2.9					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S302 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Adjustment 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S302 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Adjustment 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S302 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Adjustment 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 10 - 11 lbf					
Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S302 N/A Y Coordinate: N/A Doors or Gates Door Closer - Interior Adjustment 2010 ADAS 404.2.9 ndard: No Quantity: EACH As-built: 1 Door opening force exceeds 5 lbf 10 - 11 lbf Replace or adjust existing closer 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open					



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 58B					
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5					
Location:	Floor 3 - Stairway S302					
X Coordinate:	N/A Y Coordinate: N/A					
Barrier Area:	Doors or Gates					
Barrier Type:	Door Closer - Sweep Period					
Code References:	2010 ADAS 404.2.8.1					
Performance Sta	andard: No Quantity: EACH As-built : 2					
Barrier Description:	Door closer lacks min. 5 second sweep period					
Findings:	3 - 4 second sweep					
Rec. Solution:	Replace or adjust existing closer					
Barrier Severity:	2 Recommended Cost Est \$500.00 Facility Function: Public Status: Open					
Implementation	Priority: 3 Implementation Phase: Implementation Date:					
Notes: Double	doors					
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 58C					
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5					
Location:	Floor 3 - Stairway S302					
X Coordinate:	N/A Y Coordinate: N/A					
Barrier Area:	Doors or Gates					
Barrier Type:	Vision Lights - Existing					
Code References:	2010 ADAS 404.2.11					
Performance Sta	andard: No Quantity: EACH As-built : 1					
Barrier	View panels in or adjacent to doors or gates not max. 43" above floor or ground					
Description:	<u> </u>					
Description: Findings:	View panel located higher than 43" above the floor					
·	View panel located higher than 43" above the floor Replace door/gate or vision panel					
Findings:	Replace door/gate or vision panel					
Findings: Rec. Solution:	Replace door/gate or vision panel 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open					



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 58D					
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5					
Location:	Floor 3 - Stairway S302					
X Coordinate:	N/A Y Coordinate: N/A					
Barrier Area:	Doors or Gates					
Barrier Type:	Threshold - Ramp					
Code References:	2010 ADAS 404.2.5					
Performance Sta	ndard: No Quantity: EACH As-built : 2					
Barrier Description:	Door/Gate threshold exceeds 1/2" in height					
Findings:	No bevel provided					
Rec. Solution:	Provide ramp leading to new level landing at door					
Barrier Severity:	/: 1 Necessary Cost Est \$1,500.00 Facility Function: Public Status: Open					
Implementation	Priority: 1 Implementation Phase: Implementation Date:					
Notes:						
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 58E					
51.1.41						
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5					
Location:	Dearborn Hall Reference Dwg: 5 of 5					
Location:	Floor 3 - Stairway S302					
Location: X Coordinate:	Floor 3 - Stairway S302 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Stairway					
Location: X Coordinate: Barrier Area:	Floor 3 - Stairway S302 N/A Y Coordinate: N/A Signage					
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 3 - Stairway S302 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Stairway Performance Standard					
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 3 - Stairway S302 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Stairway Performance Standard					
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 3 - Stairway S302 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Stairway Performance Standard andard: Yes Quantity: EACH As-built: 1					
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 3 - Stairway S302 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Stairway Performance Standard andard: Yes Quantity: EACH As-built: 1 Door leading directly into an exit stairway lacks tactile exit sign					
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 3 - Stairway S302 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Stairway Performance Standard andard: Yes Quantity: EACH As-built: 1 Door leading directly into an exit stairway lacks tactile exit sign Door to exit stair with low level illuminated sign lacks tactile exit sign Provide sign stating "EXIT STAIR DOWN (or UP)" at latch side of door					
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 3 - Stairway S302 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Stairway Performance Standard andard: Yes Quantity: EACH As-built: 1 Door leading directly into an exit stairway lacks tactile exit sign Door to exit stair with low level illuminated sign lacks tactile exit sign Provide sign stating "EXIT STAIR DOWN (or UP)" at latch side of door 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open					



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 58F					
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5					
Location:	Floor 3 - Stairway S302					
X Coordinate:	N/A Y Coordinate: N/A					
Barrier Area:	Stairways					
Barrier Type:	Sign - Encl Stairway Level					
Code References:	ICC A117.1					
Performance Sta	ndard: No Quantity: EACH As-built : 1					
Barrier Description:	Tactile stairway signage not provided to indicate floor level					
Findings:	No sign provided inside stairway at landing					
Rec. Solution:	Provide sign					
Barrier Severity:	2: 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open					
Implementation	Priority: 3 Implementation Phase: Implementation Date:					
Notes:						
Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 58G					
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5					
Bldg Name: Location:	Dearborn Hall Reference Dwg: 5 of 5 Floor 3 - Stairway S302					
Location:	Floor 3 - Stairway S302					
Location: X Coordinate:	Floor 3 - Stairway S302 N/A Y Coordinate: N/A Controls and Mechanisms Vending Machine - High Reach Range					
Location: X Coordinate: Barrier Area:	Floor 3 - Stairway S302 N/A Y Coordinate: N/A Controls and Mechanisms					
Location: X Coordinate: Barrier Area: Barrier Type: Code	Floor 3 - Stairway S302 N/A Y Coordinate: N/A Controls and Mechanisms Vending Machine - High Reach Range 2010 ADAS 305.3					
Location: X Coordinate: Barrier Area: Barrier Type: Code References:	Floor 3 - Stairway S302 N/A Y Coordinate: N/A Controls and Mechanisms Vending Machine - High Reach Range 2010 ADAS 305.3					
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta	Floor 3 - Stairway S302 N/A Y Coordinate: N/A Controls and Mechanisms Vending Machine - High Reach Range 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1					
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:	Floor 3 - Stairway S302 N/A Y Coordinate: N/A Controls and Mechanisms Vending Machine - High Reach Range 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Vending machine point of control not at max. 48" high for side reach					
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:	Floor 3 - Stairway S302 N/A Y Coordinate: N/A Controls and Mechanisms Vending Machine - High Reach Range 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Vending machine point of control not at max. 48" high for side reach Top control 52" high					
Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution:	Floor 3 - Stairway S302 N/A Y Coordinate: N/A Controls and Mechanisms Vending Machine - High Reach Range 2010 ADAS 305.3 ndard: No Quantity: JOB As-built: 1 Vending machine point of control not at max. 48" high for side reach Top control 52" high Contact vendor to obtain replacement 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open					



Field Date:	3/25/2014 Report Date 5/27/2014 Barrier #: 58H					
Bldg Name:	Dearborn Hall Reference Dwg: 5 of 5					
Location:	Floor 3 - Stairway S302					
X Coordinate:	N/A Y Coordinate: N/A					
Barrier Area:	Alarms					
Barrier Type:	Horn/Strobe - Common Use Area					
Code References:	2010 ADAS 702.1					
Performance Sta	ndard: No Quantity: EACH As-built : 1					
Barrier Description:	No horn/strobes in common use areas					
Findings:	No device provided					
Rec. Solution:	Provide strobe in common use area					
Barrier Severity:	1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open					
Implementation	Priority: 1 Implementation Phase: Implementation Date:					
Notes:						





SUMMARY REPORT

Cost Estimate Total	\$2,785,915.00		
Cost Estimate - Priority 1:	\$318,650.00 \$1,748,930.00	% of Total Cost Estimate: % of Total Cost Estimate:	11.44% 62.78%
Cost Estimate - Priority 2: Cost Estimate - Priority 3:	\$7,746,930.00	% of Total Cost Estimate:	25.78%