# SZS CONSULTING GROUP

## **MERRYFIELD HALL**

**ADA ASSESSMENT & SURVEY** 



Sacramento Office 770 L Street, Suite 950 Sacramento, CA 95814 Tel: 916.669.8750 Fax: 888.211.7441

Silicon Valley Office 2225 E. Bayshore Road, Suite 200 Palo Alto CA 94303 Tel: 866.694.7637 www.szs-consulting.com

March 8, 2017



GABRIEL MERRELL DIRECTOR, ACCESS AND AFFIRMATIVE ACTION OFFICE OF EQUAL OPPORTUNITY AND ACCESS **OREGON STATE UNIVERSITY** 330 SNELL HALL CORVALLIS, OR 97331

Re: ADA Accessibility Survey and Assessment – Merryfield Hall

Dear Gabriel,

We are pleased to submit this report for Merryfield Hall. This report is part of our project to provide a Campus Accessibility Survey and Assessment for Oregon State University. It is our hope that this report will assist OSU in improving access to people with disabilities to campus facilities.

SZS has been pleased to be a part of this effort to evaluate campus buildings using federal and state statutes and regulations, as well as universal design principles in order to create performance standards that will guide design, construction and maintenance on campus.

We look forward to discussing our findings with your team.

Regards,

Syroun Z. Sanossian, Principal

Syn Z. Somi

SZS Consulting Group LLC

#### **TABLE OF CONTENTS**

| Ι. | EXECUTI   | VE SUMMARY OF FINDINGS                                | <b>p.</b> 1 |
|----|-----------|---|-------------|
|    | <i>a.</i> | Pedestrian Facilities and Exterior<br>Spaces Analyzed | p. 2        |
|    | b.        | Building Entrances                                    | p. 3        |
| 2. | INTERIOR  | R SPACES  |             |
|    |           | First Floor   | p. 3        |
|    |           | Second Floor  | p. 4        |
| 3. | BARRIE    | R DATA RECORDS  |             |
|    |           | Exterior Area Barriers                                | p. 5        |
|    |           | Interior Area Barriers                                | p. 25       |
|    |           | Cost Estimate   | p. 244      |

#### 1. EXECUTIVE SUMMARY OF FINDINGS

The field investigation for the interior spaces began on January 26, 2017. The exterior site elements were assessed originally as part of the pedestrian facilities assessment in June-September 2011 and are included as an essential part of this report. Images of each physical element identified in this report were captured in HD digital photos while manual measurements were taken to establish as-built conditions to facilitate the process of cost estimating. Digital photographs are provided within the report for each barrier to access, to facilitate the review of the data collected. We have found that technical data can be difficult to interpret without a visual component; the photos provide a clear connection between the technical data and each barrier to access.

Merryfield Hall is a historic structure and many barriers to access were identified in the building. That is quite typical, as barriers to access exist in virtually every building, whether new or existing.

No "perfect" building exists in the real world.

This ADA Assessment and Survey report is intended to not only identify barriers to access, but to provide solutions. The basis for this ADA Assessment and Survey process is the underlying desire on the part of OSU to improve access by relying on higher standards than the minimum requirements in state and federal building codes. SZS intends to provide the information in this report in a clear and easy to understand format. The information in this report is compiled for use by designated OSU staff and other interested persons, so the content is designed to be understood by professionals and laymen alike.

The findings presented are both narrative and technical in nature; barriers to access identified during the field investigation process are documented in two ways;

1. Narrative Analysis: The analysis of findings is contained in an executive summary in a narrative form that not only describes each type of barrier identified, but also provides a discussion that analyses the functionality of physical elements. We also provide the reasoning and research behind the identification of barriers that conflict with universal design principles. This analysis may be accompanied by digital photographs or diagrams, where applicable.

NOTE: Understanding building function and usage is essential when interpreting the findings held in this report. The narrative is intended to facilitate this process.

2. Barrier Data Records: Individual barriers to access are entered into the SZS database so that technical information on the barriers can be provided as barrier data records. These barrier data records include digital photographs of each barrier identified, code references that determine the barrier to access, as-built measurements, barrier severity ratings, budgetary cost estimates, recommended solutions for barrier removal and a priority for barrier removal. The information is formatted with two barriers on each report page.

In order to consolidate the report data, some of the more typical barriers found in multiple locations have been grouped within the barrier data records with a description of the locations in which they were found.

#### A. Pedestrian Facilities and Exterior Spaces Analyzed

This report provides information on campus pedestrian facilities that serve Merryfield Hall. Many physical elements are part of the comprehensive whole that creates a pedestrian facility. The fundamental elements evaluated as to whether they provide accessible pedestrian facilities include the following:

- Sidewalks
- Walkways
- Ramps
- **Curb Ramps**
- **Blended Transitions**
- Signalized Intersections
- Stairways (94% of people with disabilities are not mobility impaired)
- Benches and other Seating Elements
- Picnic Facilities

The descriptions provided for physical elements in this report are intended to clearly describe the differences between each physical element, such as when a pedestrian route is a sidewalk, rather than a walkway. The descriptions are intended to explain how the elements interact to form a cohesive pedestrian facility. Other more specific information described within this section intends to provide guidance on determinations made in this report.

The key to providing accessible pedestrian facilities is in recognizing that different people with disabilities have different needs. Setting policies that speak to the entire group is essential, rather than focusing on one particular subset of the overall group. Universal design principles govern here – physical elements should be usable to everyone that visits campus without having to resort to any adaptation or specialized design.

In summary, an accessible route exists within a building, property boundary or interior space and is separate from the PROW. Pedestrian walkways are similar to sidewalks as paved surfaces improved for use by pedestrians, but walkways are not located along or adjacent to the curb line, gutter or roadway and walkways are generally not considered part of the PROW. The pedestrian facility is the combination of the PROW and the accessible route, which functions as a whole to provide pedestrian access to facility entrances.

As a public building that was constructed prior to the passage of the ADA, Merryfield Hall should have at least one accessible entrance, which was identified along the south side of the building. These entrances were provided at ground level and the entrance to the northwest main lobby provides access to the second floor by way of stairs.

Merryfield Hall has an accessible route provided within the site from accessible parking spaces and accessible passenger loading zones; public streets and sidewalks; and public

transportation stops to the accessible building or facility entrance they serve as compared to the 2010 ADA Standard for Accessible Design. Details on barriers identified in that route are provided within the ADA Assessment and Survey of the pedestrian facilities (provided as a separate report) as well as in the following records. Please see the barrier data records for details.

#### **B.** Building Entrances

The building is located between NW Monroe Avenue and NW Campus Drive. Accessible off-street parking is provided on the west of the building and a bus stop is located north of the building along NW Monroe Avenue. Two accessible entrances are provided on the south side of the building with pedestrian connections from Campus Drive. The north entrance located along Monroe Avenue is not accessible, as the pedestrian connection to the building is by way of a stairway. ISA directional signs should be placed strategically around the building to avoid forcing members of the public to have to retrace their steps.

#### **INTERIOR SPACES**

#### FIRST FLOOR

Merryfield Hall is an L-shaped building with two stories. The first floor provides public spaces including classrooms, lab spaces, a computer room, men's and women's restroom, and workrooms. No drinking fountains were identified in this two story building.

Accessible entrance doors were identified with sloped door landings, which would necessitate the alteration of the landing and surrounding area or the installation of an automatic door opening device at each entry door leading to a separate classroom or lab. Barriers identified on the first floor were commonly identified throughout the building in common use areas and include entrance doors that lacked accessible signage, door hardware, door closer operating force/sweep period where door closers were installed and where doors were identified with view panels, the panels were not accessible to short people or wheelchair users.

Laboratory spaces were not identified as accessible, including workstations, desks, sinks, and fume hoods. These spaces also did not have an accessible connection with the main corridor and can only be entered from the exterior walkway. The lab equipment was not within accessible reach range and may need assistance to operate, although workstations at each type of testing area should be accessible for short people or those who use wheelchairs. Due to the placement of equipment, storage and gas tanks, an accessible circulation route was not present for persons who use mobility assist devices to allow circulation through the room. The emergency eye wash equipment in labs were also not located in an accessible location with controls within accessible reach ranges and knee clearance was also not accessible.

A men's, women's, and unisex restroom are located on the first floor. The unisex restroom, located within Workroom 100S appeared to have been altered recently. The location of the entrance door, adjacent to a fixed counter, lacked accessible strike edge clearance which

<sup>&</sup>lt;sup>1</sup> 2010 ADA Standards for Accessible Design, Section 206.2.1 Site Arrival Points

also left too little space for approach by a blind person to allow them to read the tactile sign posted on the wall at latch side of the entrance door. No door closer was installed and other barriers were identified such as non-accessible dispenser controls, a lack of insulation at lavatory drainpipes and the rear grab bar was installed so close to the toilet tank that it was not usable. Additional single accommodation men and women's restrooms are provide in the west end of the building. These toilet rooms were identified with adequate maneuvering space at the entrance doors and lavatory, but side transfer space was not provided at the water closet and the floor drains were located in the center of each room with an abrupt change in level that was directly in the path of travel to the lavatory and water closet. A flush transition to these drain inlets should be provided to facilitate maneuvering within the spaces for people who use wheelchairs. No multi-accommodation restrooms were provided in this building.

Many staff use only areas were identified in the building. These spaces include IT rooms, janitorial rooms, private faculty offices and associated spaces. Signage at the door/doorway to these spaces was included in this report as it is located along the public circulation route of travel, but these interior spaces were not investigated as part of this assessment process. In general, institutions and organizations make staff-use-only areas accessible as needed through the reasonable accommodation iterative process between the employer and employee.

#### SECOND FLOOR

No elevator was provided in the building and the only form of vertical access is a stairway located in the northwest section of the building. The second story extends over the northsouth segment of the building where most of the spaces are used by faculty members. Spaces on this floor that are open to the public include a vestibule, exit corridor, workroom, breakroom, and a unisex restroom. Doors to these spaces have similar barriers to those stated above regarding a lack of tactile signage. Also, no lobby informational signage is provided in the vestibule that serves as the lobby for this floor.

The stairway lacked accessible tactile signage including level identification signage for the visually impaired and accessible handrails. No contrasting color was identified at the stairway treads which can be important to those with low vision. As a performance standard, it is highly recommended to provide contrasting color at stairway treads to improve visibility for all users.

The break room on the second floor is a small space where a fixed counter and lavatory were located. The counter lacked an accessible section, as well as accessible electrical outlets and controls at the existing first aid kit provided. A lavatory was provided in the breakroom space and was located at the end of a long, narrow alcove. The second floor is not accessible to people who use mobility assist devices, but future alterations to add an elevator and additional space would necessitate the provision of wheelchair accessible features such as an accessible breakroom and toilet room.

The following barrier data records provide more detailed information on the barriers described above.





| Field Date:  | 6/28/2011 Report Date 6/28/2011 Barrier #: 264A  |
|--|--|
| Bldg Name:   | Merryfield Hall Reference Dwg: 1 of 3  |
| Location:  | Exterior - NW 16th St and NW Monroe Ave  |
| X Coordinate:  | 7479258.347 Y Coordinate: 340889.191   |
| Barrier Area:  | Curb Ramps   |
| Barrier Type:  | Detectable Warnings - Truncated Domes  |
| Code<br>References:  | OSSC 1103.2.3.1 and 2010 ADAS 705.1.3  |
| Performance Sta  | ndard: No Quantity: EACH As-built : 1000   |
| Barrier<br>Description:  | No truncated domes provided at curb ramp   |
| Findings:  | No detectable warnings at curb ramp  |
| Rec. Solution:   | Provide accessible truncated domes   |
| Barrier Severity:  | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open   |
| Implementation   | Priority: 1 Implementation Phase: Implementation Date:   |
| Notes: Three - v   | way intersection corners A,B,D   |
| Field Date:  | 6/28/2011 Report Date 6/28/2011 Barrier #: 264B  |
| Bldg Name:   | Merryfield Hall Reference Dwg: 1 of 3  |
| Location:  | Exterior - NW 16th St and NW Monroe Ave  |
| X Coordinate:  |  |
| Barrier Area:  | 7479258.347 Y Coordinate: 340889.191   |
| Dairiei Area.  | 7479258.347  |
| Barrier Type:  |  |
|  | Curb Ramps   |
| Barrier Type:<br>Code  | Curb Ramps Lip - Bottom of Ramp at Flow Line OSSC 1103.2.2.1 and 2010 ADAS 303.3   |
| Barrier Type:<br>Code<br>References:   | Curb Ramps Lip - Bottom of Ramp at Flow Line OSSC 1103.2.2.1 and 2010 ADAS 303.3   |
| Barrier Type:<br>Code<br>References:<br>Performance Sta<br>Barrier                           | Curb Ramps  Lip - Bottom of Ramp at Flow Line  OSSC 1103.2.2.1 and 2010 ADAS 303.3  ndard: No Quantity: EACH As-built: 250   |
| Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Curb Ramps  Lip - Bottom of Ramp at Flow Line  OSSC 1103.2.2.1 and 2010 ADAS 303.3  ndard: No Quantity: EACH As-built: 250  Transition at ramp bottom (flow line) is not flush and free of any lip   |
| Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Curb Ramps  Lip - Bottom of Ramp at Flow Line  OSSC 1103.2.2.1 and 2010 ADAS 303.3  ndard: No Quantity: EACH As-built: 250  Transition at ramp bottom (flow line) is not flush and free of any lip  1/2" lip at flow line  |
| Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Curb Ramps  Lip - Bottom of Ramp at Flow Line  OSSC 1103.2.2.1 and 2010 ADAS 303.3  ndard: No Quantity: EACH As-built: 250  Transition at ramp bottom (flow line) is not flush and free of any lip  1/2" lip at flow line  Remove lip to create flush transition  1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open |



| Field Date:   | 6/28/2011 Report Date 6/28/2011 Barrier #: 265A   |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 1 of 3   |
| Location:   | Exterior - Northwest Stairway at Monroe Ave   |
| X Coordinate:   | 7479272.91 Y Coordinate: 340870.478   |
| Barrier Area:   | Stairways   |
| Barrier Type:   | Handrail - Both Sides   |
| Code<br>References:   | OSSC 1109.8.6 and 2010 ADAS 505.10.2  |
| Performance Sta   | ndard: No Quantity: LF As-built: 225  |
| Barrier<br>Description:   | No handrail provided at both sides of stairway  |
| Findings:   | No handrail provided at both sides  |
| Rec. Solution:  | Provide accessible handrails at both sides of stairway  |
| Barrier Severity:   | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 1 Implementation Phase: Implementation Date:  |
| Notes:  |   |
|   |   |
| Field Date:   | 6/28/2011 Report Date 6/28/2011 Barrier #: 265B   |
| Field Date:<br>Bldg Name:   | 6/28/2011 Report Date 6/28/2011 Barrier #: 265B  Merryfield Hall Reference Dwg: 1 of 3  |
|   |   |
| Bldg Name:  | Merryfield Hall Reference Dwg: 1 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall  Reference Dwg: 1 of 3  Exterior - Northwest Stairway at Monroe Ave   |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 1 of 3  Exterior - Northwest Stairway at Monroe Ave  7479272.91  Y Coordinate: 340870.478   |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 1 of 3  Exterior - Northwest Stairway at Monroe Ave  7479272.91  Y Coordinate: 340870.478  Stairways  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 1 of 3  Exterior - Northwest Stairway at Monroe Ave  7479272.91  Y Coordinate: 340870.478  Stairways  Contrasting Color - ADA  2010 ADAS Advisory 504.4   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 1 of 3  Exterior - Northwest Stairway at Monroe Ave  7479272.91  Y Coordinate: 340870.478  Stairways  Contrasting Color - ADA  2010 ADAS Advisory 504.4   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Northwest Stairway at Monroe Ave 7479272.91 Y Coordinate: 340870.478  Stairways  Contrasting Color - ADA 2010 ADAS Advisory 504.4  ndard: Yes Quantity: LF or TR As-built: 35   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Northwest Stairway at Monroe Ave  7479272.91 Y Coordinate: 340870.478  Stairways  Contrasting Color - ADA  2010 ADAS Advisory 504.4  Indard: Yes Quantity: LF or TR As-built: 35  No contrasting color on each tread of exterior stairway   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Northwest Stairway at Monroe Ave 7479272.91 Y Coordinate: 340870.478  Stairways  Contrasting Color - ADA  2010 ADAS Advisory 504.4  Indard: Yes Quantity: LF or TR As-built: 35  No contrasting color on each tread of exterior stairway  No contrasting color provided  Consider providing contrasting color on each tread   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Northwest Stairway at Monroe Ave 7479272.91 Y Coordinate: 340870.478  Stairways  Contrasting Color - ADA  2010 ADAS Advisory 504.4  Indard: Yes Quantity: LF or TR As-built: 35  No contrasting color on each tread of exterior stairway  No contrasting color provided  Consider providing contrasting color on each tread  2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open |



| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 265C                                     |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3   |
| Location:               | Exterior - Northwest Stairway at Monroe Ave   |
| X Coordinate:           | 7479272.91 Y Coordinate: 340870.478   |
| Barrier Area:           | Stairways   |
| Barrier Type:           | Vertical Access - Directional Sign  |
| Code<br>References:     | 2010 ADAS 403.1   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 125   |
| Barrier<br>Description: | No form of vertical access provided at stairway to reach entry door or upper floors |
| Findings:               | No information on alternate accessible entrance to building                         |
| Rec. Solution:          | Provide directional sign leading to accessible entry                                |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open                  |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |
| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 266                                      |
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3   |
| Location:               | Exterior - NW Monroe Ave - South  |
| X Coordinate:           | 7479274.589 Y Coordinate: 340878.115  |
| Barrier Area:           | Sidewalks   |
| Barrier Type:           | Cross Slope - Existing (3.1% to 4.0%)   |
| Code<br>References:     | OSSC 1109.4.4 and 2010 ADAS 403.3   |
| Performance Sta         | ndard: No Quantity: LF As-built : 45  |
| Barrier<br>Description: | Cross slope exceeds 2.0% (3.1% to 4.0%)   |
| Findings:               | 3.3% cross slope  |
| Rec. Solution:          | Demolish existing and construct new route   |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open                  |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |



| Field Date:   | 6/28/2011 Report Date 6/28/2011 Barrier #: 270A  |
|---|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 1 of 3  |
| Location:   | Exterior - NW 15th St and NW Monroe Ave  |
| X Coordinate:   | 7479500.262 Y Coordinate: 340798.087   |
| Barrier Area:   | Curb Ramps   |
| Barrier Type:   | Flares - Existing (10.8% to 11%)   |
| Code<br>References:   | OSSC 1103.2.2.3 and 2010 ADAS 406.3  |
| Performance Sta   | ndard: No Quantity: EACH As-built: 3000  |
| Barrier<br>Description:   | Ramp flare slope exceeds 10.0% (10.8% to 11%)  |
| Findings:   | 10.5% flare slope  |
| Rec. Solution:  | Demolish existing and construct new curb ramp  |
| Barrier Severity:   | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open   |
| Implementation  | Priority: 1 Implementation Phase: Implementation Date:   |
| Notes: Three - v  | way intersection corners A,B,D   |
|   |  |
| Field Date:   | 6/28/2011 Report Date 6/28/2011 Barrier #: 270B  |
|   | 6/28/2011 Report Date 6/28/2011 Barrier #: 270B  Merryfield Hall Reference Dwg: 1 of 3   |
| Bldg Name:  |  |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 1 of 3  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall Reference Dwg: 1 of 3  Exterior - NW 15th St and NW Monroe Ave   |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 1 of 3  Exterior - NW 15th St and NW Monroe Ave  7479500.262  Y Coordinate: 340798.087   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 1 of 3  Exterior - NW 15th St and NW Monroe Ave  7479500.262  Y Coordinate: 340798.087  Curb Ramps   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 1 of 3  Exterior - NW 15th St and NW Monroe Ave  7479500.262  Y Coordinate: 340798.087  Curb Ramps  Detectable Warnings - Truncated Domes  OSSC 1103.2.3.1 and 2010 ADAS 705.1.3   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 1 of 3  Exterior - NW 15th St and NW Monroe Ave  7479500.262  Y Coordinate: 340798.087  Curb Ramps  Detectable Warnings - Truncated Domes  OSSC 1103.2.3.1 and 2010 ADAS 705.1.3   |
| Field Date: Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:    | Merryfield Hall Reference Dwg: 1 of 3  Exterior - NW 15th St and NW Monroe Ave 7479500.262 Y Coordinate: 340798.087  Curb Ramps Detectable Warnings - Truncated Domes OSSC 1103.2.3.1 and 2010 ADAS 705.1.3  ndard: No Quantity: EACH As-built: 0  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 1 of 3  Exterior - NW 15th St and NW Monroe Ave  7479500.262 Y Coordinate: 340798.087  Curb Ramps  Detectable Warnings - Truncated Domes  OSSC 1103.2.3.1 and 2010 ADAS 705.1.3  ndard: No Quantity: EACH As-built: 0  No truncated domes provided at curb ramp   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 1 of 3  Exterior - NW 15th St and NW Monroe Ave  7479500.262 Y Coordinate: 340798.087  Curb Ramps Detectable Warnings - Truncated Domes  OSSC 1103.2.3.1 and 2010 ADAS 705.1.3  ndard: No Quantity: EACH As-built: 0  No truncated domes provided at curb ramp  No detectable warnings at curb ramp  Provide accessible truncated domes   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 1 of 3  Exterior - NW 15th St and NW Monroe Ave  7479500.262 Y Coordinate: 340798.087  Curb Ramps Detectable Warnings - Truncated Domes  OSSC 1103.2.3.1 and 2010 ADAS 705.1.3  ndard: No Quantity: EACH As-built: 0  No truncated domes provided at curb ramp  No detectable warnings at curb ramp  Provide accessible truncated domes  2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open |



| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 270C                    |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3                              |
| Location:               | Exterior - NW 15th St and NW Monroe Ave                            |
| X Coordinate:           | 7479500.262 Y Coordinate: 340798.087                               |
| Barrier Area:           | Sidewalks  |
| Barrier Type:           | Grate in Route   |
| Code<br>References:     | OSSC 1109.6.4 and 2010 ADAS 302.3                                  |
| Performance Sta         | andard: No Quantity: EACH As-built: 250                            |
| Barrier<br>Description: | Grate in pedestrian route has openings that exceed 1/2"            |
| Findings:               | 1-1/2" grate openings directly in path of travel                   |
| Rec. Solution:          | Replace grate  |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:             |
| Notes: Three -          | way intersection corners A,B,D                                     |
| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 214                     |
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3                              |
| Location:               | Exterior - Southeast Walkway                                       |
| X Coordinate:           | 7479463.617 Y Coordinate: 340727.524                               |
| Barrier Area:           | Walkways   |
| Barrier Type:           | Grate in Route   |
| Code<br>References:     | OSSC 1103.2.4.5 and 2010 ADAS 303.3                                |
| Performance Sta         | andard: No Quantity: EACH As-built: 250                            |
| Barrier<br>Description: | Grate in walkway has openings that exceed 1/2"                     |
| Findings:               | 1" grate openings  |
| Rec. Solution:          | Replace grate  |
| Barrier Severity:       |  |
| barrier severity.       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open |
| Implementation          |  |



| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 215                        |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3                                 |
| Location:               | Exterior - Southeast Walkway  |
| X Coordinate:           | 7479460.431 Y Coordinate: 340717.791                                  |
| Barrier Area:           | Walkways  |
| Barrier Type:           | Running Slope - New Construction                                      |
| Code<br>References:     | OSSC 1103.2.4.3 and 2010 ADAS 403.3                                   |
| Performance Sta         | andard: No Quantity: LF As-built : 45                                 |
| Barrier<br>Description: | Walkway running slope exceeds 5.0%                                    |
| Findings:               | 6.5% running slope  |
| Rec. Solution:          | Provide accessible handrails at both sides with landings where needed |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open    |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                |
| Notes:                  |   |
| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 216                        |
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3                                 |
| Location:               | Exterior - Southeast Walkway  |
| X Coordinate:           | 7479443.543 Y Coordinate: 340727.951                                  |
| Barrier Area:           | Walkways  |
| Barrier Type:           | Cross Slope - Existing (5.0% or more)                                 |
| Code<br>References:     | OSSC 1103.2.4.3 and 2010 ADAS 403.3                                   |
| Performance Sta         | andard: No Quantity: LF As-built : 45                                 |
| Barrier<br>Description: | Cross slope exceeds 2.0% (5.0% or more)                               |
| Findings:               | 6.5% cross slope  |
| Rec. Solution:          | Demolish existing and construct new route                             |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open    |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                |
| Notes:                  |   |



| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 217A                    |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3                              |
| Location:               | Exterior - Southeast Walkway                                       |
| X Coordinate:           | 7479462.654 Y Coordinate: 340732.608                               |
| Barrier Area:           | Ramps  |
| Barrier Type:           | Handrail Height  |
| Code<br>References:     | OSSC 1109.7.6 and 2010 ADAS 505.4                                  |
| Performance Sta         | andard: No Quantity: LF As-built: 225                              |
| Barrier<br>Description: | Handrails not 34"-38" high   |
| Findings:               | 32" handrail grip height   |
| Rec. Solution:          | Provide accessible handrails at both sides of ramp                 |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:             |
| Notes:                  |  |
| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 217B                    |
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3                              |
| Location:               | Exterior - Southeast Walkway                                       |
| X Coordinate:           | 7479462.654 Y Coordinate: 340732.608                               |
| Barrier Area:           | Ramps  |
| Barrier Type:           | Handrail   |
| Code<br>References:     | OSSC 1109.7.6 and 2010 ADAS 505.2                                  |
| Performance Sta         | andard: No Quantity: LF As-built : 225                             |
| Barrier<br>Description: | No handrail provided at both sides                                 |
| Findings:               | No handrail provided at both sides                                 |
| Rec. Solution:          | Provide accessible handrails at both sides of ramp                 |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:             |
| Notes:                  |  |



| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 217C                      |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3                                |
| Location:               | Exterior - Southeast Walkway   |
| X Coordinate:           | 7479462.654 Y Coordinate: 340732.608                                 |
| Barrier Area:           | Ramps  |
| Barrier Type:           | Handrail Extension - Length  |
| Code<br>References:     | OSSC 1109.7.6 and 2010 ADAS 505.10                                   |
| Performance Sta         | andard: No Quantity: LF As-built: 225                                |
| Barrier<br>Description: | Handrail extension not min. 12" long                                 |
| Findings:               | Handrail extension not min. 12" long                                 |
| Rec. Solution:          | Provide accessible handrails at both sides of ramp                   |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open   |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:               |
| Notes:                  |  |
| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 219                       |
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3                                |
| Location:               | Exterior - Southeast Walkway   |
| X Coordinate:           | 7479364.143 Y Coordinate: 340775.476                                 |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Door/Gate Landing - Existing (4.1% to 4.9%)                          |
| Code<br>References:     | 2010 ADAS 404.2.4.4  |
| Performance Sta         | andard: No Quantity: SF As-built: 125                                |
| Barrier<br>Description: | Door or gate lacks landing on both sides of door                     |
| Findings:               | 4.4% slope   |
| Rec. Solution:          | Demolish and reconstruct level landing                               |
| Barrier Severity:       | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:               |
| Notes:                  |  |



| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 220                     |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3                              |
| Location:               | Exterior - Southeast Walkway                                       |
| X Coordinate:           | 7479341.075 Y Coordinate: 340774.337                               |
| Barrier Area:           | Walkways   |
| Barrier Type:           | Running Slope - Existing (8.3% or more)                            |
| Code<br>References:     | OSSC 1103.2.4.3 and 2010 ADAS 403.3                                |
| Performance Sta         | ndard: No Quantity: LF As-built: 125                               |
| Barrier<br>Description: | Walkway running slope exceeds 5.0% (8.3% or more)                  |
| Findings:               | 20.0% running slope  |
| Rec. Solution:          | Demolish and reconstruct walkway with accessible slope             |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:             |
| Notes:                  |  |
| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 221                     |
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3                              |
| Location:               | Exterior - Southeast Walkway                                       |
| X Coordinate:           | 7479346.195 Y Coordinate: 340782.72                                |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Door/Gate Landing - Existing (3.1% to 4.0%)                        |
| Code<br>References:     | 2010 ADAS 404.2.4.4  |
| Performance Sta         | ndard: No Quantity: SF As-built: 125                               |
| Barrier<br>Description: | Door or gate lacks landing on both sides of door                   |
| Findings:               | 3.3%   |
| Rec. Solution:          | Demolish and reconstruct level landing                             |
| Barrier Severity:       |  |
| •                       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open |
| Implementation          |  |



| Field Date:                         | 6/28/2011 Report Date 6/28/2011 Barrier #: 222                     |
|-------------------------------------|--|
| Bldg Name:                          | Merryfield Hall Reference Dwg: 1 of 3                              |
| Location:                           | Exterior - Southeast Walkway                                       |
| X Coordinate:                       | 7479335.69 Y Coordinate: 340786.632                                |
| Barrier Area:                       | Doors or Gates   |
| Barrier Type:                       | Door/Gate Landing - Existing (3.1% to 4.0%)                        |
| Code<br>References:                 | 2010 ADAS 404.2.4.4  |
| Performance Sta                     | ndard: No Quantity: SF As-built: 125                               |
| Barrier<br>Description:             | Door or gate lacks landing on both sides of door                   |
| Findings:                           | 3.1%   |
| Rec. Solution:                      | Demolish and reconstruct level landing                             |
| Barrier Severity:                   | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open |
| Implementation                      | Priority: 1 Implementation Phase: Implementation Date:             |
| Notes:                              |  |
| Field Date:                         | 6/28/2011 Report Date 6/28/2011 Barrier #: 223                     |
| Bldg Name:                          | Merryfield Hall Reference Dwg: 1 of 3                              |
| Location:                           | Exterior - Southeast Main Entrance                                 |
| X Coordinate:                       | 7479273.344 Y Coordinate: 340804.808                               |
| Barrier Area:                       | Doors or Gates   |
| Barrier Type:                       | Door/Gate Landing - Existing (3.1% to 4.0%)                        |
| Code<br>References:                 | 2010 ADAS 404.2.4.4  |
| Performance Sta                     | ndard: No Quantity: SF As-built: 125                               |
| Barrier<br>Description:             | Door or gate lacks landing on both sides of door                   |
| Findings:                           | 3.1%   |
| Rec. Solution:                      | Demolish and reconstruct level landing                             |
|                                     |  |
| Barrier Severity:                   | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open |
| Barrier Severity:<br>Implementation |  |



| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 224A                    |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3                              |
| Location:               | Exterior - Northeast Walkway                                       |
| X Coordinate:           | 7479266.595 Y Coordinate: 340762.41                                |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Door/Gate Landing - Existing (3.1% to 4.0%)                        |
| Code<br>References:     | 2010 ADAS 404.2.4.4  |
| Performance Sta         | ndard: No Quantity: SF As-built: 125                               |
| Barrier<br>Description: | Door or gate lacks landing on both sides of door                   |
| Findings:               | 3.1%   |
| Rec. Solution:          | Demolish and reconstruct level landing                             |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:             |
| Notes:                  |  |
| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 224B                    |
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3                              |
| Location:               | Exterior - Northeast Walkway                                       |
| X Coordinate:           | 7479266.595 Y Coordinate: 340762.41                                |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Abrupt Change in Level   |
| Code<br>References:     | OSSC 1109.9.3 and 2010 ADAS 303.3                                  |
| Performance Sta         | andard: No Quantity: LF As-built : 250                             |
| Barrier<br>Description: | Change in level of 1/2" without a 1:2 bevel leading to door        |
| Findings:               | 1/2" lip   |
| Rec. Solution:          | Grind or repair to remove trip hazard                              |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:             |
| Notes:                  |  |



| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 225                     |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3                              |
| Location:               | Exterior - Northeast Walkway                                       |
| X Coordinate:           | 7479226.991 Y Coordinate: 340676.544                               |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Door/Gate Landing - Existing (≥ 5.0%)                              |
| Code<br>References:     | 2010 ADAS 404.2.4.4  |
| Performance Sta         | ndard: No Quantity: SF As-built : 125                              |
| Barrier<br>Description: | Door or gate lacks landing on both sides of door                   |
| Findings:               | 5.0% slope   |
| Rec. Solution:          | Demolish and reconstruct level landing                             |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:             |
| Notes:                  |  |
| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 226                     |
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3                              |
| Location:               | Exterior - Northeast Walkway                                       |
| X Coordinate:           | 7479214.969 Y Coordinate: 340659.135                               |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Door/Gate Landing - Existing (≥ 5.0%)                              |
| Code<br>References:     | 2010 ADAS 404.2.4.4  |
| Performance Sta         | ndard: No Quantity: SF As-built : 125                              |
| Barrier<br>Description: | Door or gate lacks landing on both sides of door                   |
| Findings:               | 5.1% slope   |
| Rec. Solution:          | Demolish and reconstruct level landing                             |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open |
| Implementation          |  |
| Notes:                  |  |



| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 227                     |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3                              |
| Location:               | Exterior - Northeast Walkway                                       |
| X Coordinate:           | 7479227.113 Y Coordinate: 340673.502                               |
| Barrier Area:           | Walkways   |
| Barrier Type:           | Cross Slope - Existing (5.0% or more)                              |
| Code<br>References:     | OSSC 1103.2.4.3 and 2010 ADAS 403.3                                |
| Performance Sta         | andard: No Quantity: LF As-built : 45                              |
| Barrier<br>Description: | Cross slope exceeds 2.0% (5.0% or more)                            |
| Findings:               | 5.4% cross slope   |
| Rec. Solution:          | Demolish existing and construct new route                          |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:             |
| Notes:                  |  |
| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 228                     |
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3                              |
| Location:               | Exterior - Northeast Walkway                                       |
| X Coordinate:           | 7479210.951 Y Coordinate: 340649.62                                |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Door/Gate Landing - Existing (≥ 5.0%)                              |
| Code<br>References:     | 2010 ADAS 404.2.4.4  |
| Performance Sta         | andard: No Quantity: SF As-built: 125                              |
| Barrier<br>Description: | Door or gate lacks landing on both sides of door                   |
| Findings:               | 5.1% slope   |
| Rec. Solution:          | Demolish and reconstruct level landing                             |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:             |
| Notes:                  |  |



| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 229   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3  |
| Location:               | Exterior - Northeast Walkway   |
| X Coordinate:           | 7479229.564 Y Coordinate: 340645.843   |
| Barrier Area:           | Walkways   |
| Barrier Type:           | Abrupt Change in Level   |
| Code<br>References:     | OSSC 1103.2.4.5 and 2010 ADAS 303.3  |
| Performance Sta         | ndard: No Quantity: LF As-built : 45   |
| Barrier<br>Description: | Change in level greater or equal to 1/2" without a 1:2 bevel                           |
| Findings:               | 1/2" lip in walkway surface without a bevel  |
| Rec. Solution:          | Grind or repair to remove trip hazard  |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open                     |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                                 |
| Notes:                  |  |
| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 234   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3  |
| Location:               | Exterior - Walkway SW Campus Way   |
| X Coordinate:           | 7479165.429 Y Coordinate: 340590.286   |
| Barrier Area:           | Walkways   |
| Barrier Type:           | Construction Site - No Access  |
| Code<br>References:     | MUTCD Section 6D.01  |
| Performance Sta         | ndard: No Quantity: LF As-built : 45   |
| Barrier<br>Description: | Construction site creates barriers to pedestrians where no alternate route is provided |
| Findings:               | No detectable warning provided at construction barricade                               |
| Rec. Solution:          | Provide cane detectable warning across the full width of sidewalk                      |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open                     |
| Implementation          |  |
| Notes: People v         | with disabilities may be forced to retrace their steps                                 |



| Field Date:                 | 6/28/2011 Report Date 6/28/2011 Barrier #: 237   |
|-----------------------------|--|
|                             |  |
| Bldg Name:                  | Merryfield Hall Reference Dwg: 1 of 3  |
| Location:                   | Exterior - Covell Hall/Graf Hall - Parking Lot   |
| X Coordinate:               | 7479181.192 Y Coordinate: 340776.673   |
| Barrier Area:               | Walkways   |
| Barrier Type:               | Detectable Warnings - Incorrect Application  |
| Code<br>References:         | Performance Standard   |
| Performance Sta             | ndard: Yes Quantity: JOB As-built : 500  |
| Barrier<br>Description:     | Detectable warning (truncated domes) incorrectly installed   |
| Findings:                   | Incorrect placement of detectable warning in parking lot where pedestrian route ends                               |
| Rec. Solution:              | Remove truncated domes where no hazardous situation exists. Accessible parking is located ne                       |
| Barrier Severity:           | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open   |
| Implementation              | Priority: 1 Implementation Phase: Implementation Date:   |
|                             | nended: designate accessible route to ensure that such locations are not incorrectly identified tectable warnings. |
| Field Date:                 | 6/28/2011 Report Date 6/28/2011 Barrier #: 238   |
| Bldg Name:                  | Merryfield Hall Reference Dwg: 1 of 3  |
| Location:                   | Exterior - Covell Hall/Graf Hall - Parking Lot   |
| X Coordinate:               | 7479184.976 Y Coordinate: 340767.819   |
| Barrier Area:               | Signage  |
| Barrier Type:               | Directional Sign   |
| Code<br>References:         | 2010 ADAS 216.4.3 and 703.5  |
| Performance Sta             | ndard: No Quantity: EACH As-built : 250  |
| Barrier<br>Description:     | No directional signage provided where accessible route diverges from main route                                    |
|                             |  |
| Findings:                   | No directional signage provided  |
| Findings:<br>Rec. Solution: | No directional signage provided  Provide accessible directional signage  |
| _                           | Provide accessible directional signage   |
| Rec. Solution:              | Provide accessible directional signage  1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open         |



| Field Date:             | 11/16/2011 Report Date ######## Barrier #: 243A   |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3   |
| Location:               | Exterior - Covell Hall/Graf Hall - Parking Lot  |
| X Coordinate:           | 7479198.819 Y Coordinate: 340801.834  |
| Barrier Area:           | Parking   |
| Barrier Type:           | Van Accessible Stall  |
| Code<br>References:     | OSSC 1104.1 and ORS 447.233.2.(b)   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 475   |
| Barrier<br>Description: | No van accessible stall provided in parking lot/structure   |
| Findings:               | No van accessible stall provided  |
| Rec. Solution:          | Provide min. one van accessible stall   |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open                                      |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:  |
| Notes: 6 access stall   | sible stalls, 2 existing accessible stalls + 4 new accessible stalls (0 van access), no wheelchair only |
| Field Date:             | 11/16/2011 Report Date ######## Barrier #: 243B   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3   |
| Location:               | Exterior - Covell Hall/Graf Hall - Parking Lot  |
| X Coordinate:           | 7479198.819 Y Coordinate: 340801.834  |
| Barrier Area:           | Parking   |
| Barrier Type:           | Wheelchair User Only Stalls - 5+ Stalls   |
| Code<br>References:     | OSSC 1104.1 and ORS 447.233.2.(b)   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 250   |
| Barrier<br>Description: | With 5 or more van accessible stalls, no stall reserved for wheelchair users                            |
| Findings:               | No stall reserved for wheelchair user provided  |
| Rec. Solution:          | Reserve stall as "Wheelchair User Only" with signage as identification                                  |
| Barrier Severity:       |   |
| •                       | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open                                    |
| Implementation          |   |



| Field Date:   | 11/16/2011 Report Date ######## Barrier #: 244  |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 1 of 3   |
| Location:   | Exterior - Covell Hall/Graf Hall - Parking Lot  |
| X Coordinate:   | 7479204.98 Y Coordinate: 340812.145   |
| Barrier Area:   | Parking   |
| Barrier Type:   | Stall Dimensions - New Construction   |
| Code<br>References:   | OSSC 1104.4.3   |
| Performance Sta   | ndard: No Quantity: SF As-built: 100  |
| Barrier<br>Description:   | Accessible stall & aisle not max. 2.0% in all directions  |
| Findings:   | 2.7%  |
| Rec. Solution:  | Regrade stall to make level and restripe  |
| Barrier Severity:   | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 1 Implementation Phase: Implementation Date: 1  |
| Notes:  |   |
|   |   |
| Field Date:   | 11/16/2011 Report Date ######## Barrier #: 245  |
| Field Date:<br>Bldg Name:   | 11/16/2011   Report Date   ########   Barrier #:   245     245  |
|   |   |
| Bldg Name:  | Merryfield Hall Reference Dwg: 1 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Covell Hall/Graf Hall - Parking Lot   |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Covell Hall/Graf Hall - Parking Lot  7479198.819 Y Coordinate: 340801.834   |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Covell Hall/Graf Hall - Parking Lot  7479198.819 Y Coordinate: 340801.834  Parking  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Covell Hall/Graf Hall - Parking Lot  7479198.819 Y Coordinate: 340801.834  Parking Stall Dimensions - New Construction  OSSC 1104.4.3   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Covell Hall/Graf Hall - Parking Lot  7479198.819 Y Coordinate: 340801.834  Parking Stall Dimensions - New Construction  OSSC 1104.4.3   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Covell Hall/Graf Hall - Parking Lot  7479198.819 Y Coordinate: 340801.834  Parking  Stall Dimensions - New Construction  OSSC 1104.4.3  ndard: No Quantity: SF As-built: 100  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Covell Hall/Graf Hall - Parking Lot  7479198.819 Y Coordinate: 340801.834  Parking  Stall Dimensions - New Construction  OSSC 1104.4.3  Indard: No Quantity: SF As-built: 100  Accessible stall & aisle not max. 2.0% in all directions   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Covell Hall/Graf Hall - Parking Lot  7479198.819 Y Coordinate: 340801.834  Parking  Stall Dimensions - New Construction  OSSC 1104.4.3  ndard: No Quantity: SF As-built: 100  Accessible stall & aisle not max. 2.0% in all directions  2.6%  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Covell Hall/Graf Hall - Parking Lot  7479198.819 Y Coordinate: 340801.834  Parking  Stall Dimensions - New Construction  OSSC 1104.4.3  Indard: No Quantity: SF As-built: 100  Accessible stall & aisle not max. 2.0% in all directions  2.6%  Regrade stall to make level and restripe  2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open |




| Field Date:   | 6/28/2011 Report Date 6/28/2011 Barrier #: 248A   |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 1 of 3   |
| Location:   | Exterior - Northwest Stairway from Parking Lot  |
| X Coordinate:   | 7479228.399 Y Coordinate: 340820.684  |
| Barrier Area:   | Stairways   |
| Barrier Type:   | Riser Height - Existing   |
| Code<br>References:   | 2010 ADAS 504.2   |
| Performance Sta   | ndard: No Quantity: SF As-built : 250   |
| Barrier<br>Description:   | Stair riser height or tread width is not consistent   |
| Findings:   | Consistent stair riser height or tread width not provided   |
| Rec. Solution:  | Demolish and construct new accessible stairway  |
| Barrier Severity:   | 4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open   |
| Implementation  | Priority: 1 Implementation Phase: Implementation Date:  |
| Notes:  |   |
|   |   |
| Field Date:   | 6/28/2011 Report Date 6/28/2011 Barrier #: 248B   |
| Field Date:<br>Bldg Name:   | 6/28/2011 Report Date 6/28/2011 Barrier #: 248B  Merryfield Hall Reference Dwg: 1 of 3  |
|   |   |
| Bldg Name:  | Merryfield Hall Reference Dwg: 1 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall  Reference Dwg: 1 of 3  Exterior - Northwest Stairway from Parking Lot  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 1 of 3  Exterior - Northwest Stairway from Parking Lot  7479228.399  Y Coordinate: 340820.684   |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Northwest Stairway from Parking Lot  7479228.399 Y Coordinate: 340820.684  Stairways  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Northwest Stairway from Parking Lot 7479228.399 Y Coordinate: 340820.684  Stairways Handrail Grip OSSC 1109.8.6.(1) and 2010 ADAS 505.10.2  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Northwest Stairway from Parking Lot 7479228.399 Y Coordinate: 340820.684  Stairways  Handrail Grip  OSSC 1109.8.6.(1) and 2010 ADAS 505.10.2  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Northwest Stairway from Parking Lot 7479228.399 Y Coordinate: 340820.684  Stairways Handrail Grip OSSC 1109.8.6.(1) and 2010 ADAS 505.10.2  Indard: No Quantity: LF As-built: 225   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Northwest Stairway from Parking Lot 7479228.399 Y Coordinate: 340820.684  Stairways  Handrail Grip  OSSC 1109.8.6.(1) and 2010 ADAS 505.10.2  Indard: No Quantity: LF As-built: 225  Handrail grip is not continuous  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Northwest Stairway from Parking Lot 7479228.399 Y Coordinate: 340820.684  Stairways Handrail Grip OSSC 1109.8.6.(1) and 2010 ADAS 505.10.2  Indard: No Quantity: LF As-built: 225  Handrail grip is not continuous  Handrail grip is not continuous  Provide accessible handrails at both sides of stairway   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 1 of 3  Exterior - Northwest Stairway from Parking Lot 7479228.399 Y Coordinate: 340820.684  Stairways  Handrail Grip OSSC 1109.8.6.(1) and 2010 ADAS 505.10.2  Indard: No Quantity: LF As-built: 225  Handrail grip is not continuous  Handrail grip is not continuous  Provide accessible handrails at both sides of stairway 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open |



| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 248C                      |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3                                |
| Location:               | Exterior - Northwest Stairway from Parking Lot                       |
| X Coordinate:           | 7479228.399 Y Coordinate: 340820.684                                 |
| Barrier Area:           | Stairways  |
| Barrier Type:           | Handrail Extension - Bottom  |
| Code<br>References:     | OSSC 1109.8.6.(2)  |
| Performance Sta         | andard: No Quantity: LF As-built : 225                               |
| Barrier<br>Description: | Bottom handrail extension not min. 12" + tread width at stair bottom |
| Findings:               | Bottom handrail extension not min. 12" + tread width                 |
| Rec. Solution:          | Provide accessible handrails at both sides of stairway               |
| Barrier Severity:       | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:               |
| Notes:                  |  |
| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 248D                      |
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3                                |
| Location:               | Exterior - Northwest Stairway from Parking Lot                       |
| X Coordinate:           | 7479228.399 Y Coordinate: 340820.684                                 |
| Barrier Area:           | Stairways  |
| Barrier Type:           | Handrail Extension - Top   |
| Code<br>References:     | OSSC 1109.8.6.(2)  |
| Performance Sta         | andard: No Quantity: LF As-built : 225                               |
| Barrier<br>Description: | Top Handrail extension not parallel to ground/floor surface          |
| Findings:               | No top handrail extension provided                                   |
| Rec. Solution:          | Provide accessible handrails at both sides of stairway               |
| Barrier Severity:       | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open |
| Implementation          |  |
| piememaa.on             |  |



| Field Date:             | 6/28/2011 Report Date 6/28/2011 Barrier #: 248E                                     |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 1 of 3   |
| Location:               | Exterior - Northwest Stairway from Parking Lot                                      |
| X Coordinate:           | 7479228.399 Y Coordinate: 340820.684  |
| Barrier Area:           | Stairways   |
| Barrier Type:           | Vertical Access - Directional Sign  |
| Code<br>References:     | 2010 ADAS 403.1   |
| Performance Sta         | andard: No Quantity: EACH As-built: 125   |
| Barrier<br>Description: | No form of vertical access provided at stairway to reach entry door or upper floors |
| Findings:               | No information on alternate accessible entrance to building                         |
| Rec. Solution:          | Provide directional sign leading to accessible entry                                |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open                  |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #:  |
| Bldg Name:              | Merryfield Hall Reference Dwg:  |
| Location:               |   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           |   |
| Barrier Type:           |   |
| Code<br>References:     |   |
| Performance Sta         | andard: Quantity: As-built :  |
| Barrier<br>Description: |   |
| Findings:               |   |
| Rec. Solution:          |   |
| Barrier Severity:       | Cost Est Facility Function: Public Status: Open                                     |
| Implementation          | Priority: Implementation Phase: Implementation Date:                                |
| Notes: Barrier i        | record intentionally left blank to facilitate printing                              |





| Field Date:  | 1/26/2017 Report Date 2/22/2017 Barrier #: 1  |
|--|---|
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Exterior - Northeast Corner at NW Monroe Ave  |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  | Signage   |
| Barrier Type:  | ISA - Directional Sign  |
| Code<br>References:  | 2010 ADAS 216.6 Advisory  |
| Performance Sta  | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:  | No directional signage provided where accessible route diverges from main route   |
| Findings:  | Accessible sign not provided at Northeast corner of the building along NW Monroe Ave  |
| Rec. Solution:   | Provide directional signage indicating location of and route to accessible building entrance  |
| Barrier Severity:  | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open  |
| Implementation   | Priority: 3 Implementation Phase: Implementation Date:  |
| Notes:   |   |
| Field Date:  | 1/26/2017 Report Date 2/22/2017 Barrier #: 2  |
| Dida Nama  |   |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Merryfield Hall  Reference Dwg:  2 of 3  Exterior - Southeast Corner of Building  |
| _  |   |
| Location:  | Exterior - Southeast Corner of Building   |
| Location:<br>X Coordinate:   | Exterior - Southeast Corner of Building  N/A  Y Coordinate: N/A   |
| Location:<br>X Coordinate:<br>Barrier Area:  | Exterior - Southeast Corner of Building  N/A  Y Coordinate: N/A  Signage  |
| Location:<br>X Coordinate:<br>Barrier Area:<br>Barrier Type:<br>Code   | Exterior - Southeast Corner of Building  N/A  Y Coordinate: N/A  Signage  ISA - Directional Sign  2010 ADAS 216.6 Advisory  |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Exterior - Southeast Corner of Building  N/A  Y Coordinate: N/A  Signage  ISA - Directional Sign  2010 ADAS 216.6 Advisory  |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Exterior - Southeast Corner of Building  N/A  Y Coordinate: N/A  Signage  ISA - Directional Sign  2010 ADAS 216.6 Advisory  ndard: No Quantity: EACH As-built: 1  |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Exterior - Southeast Corner of Building  N/A  Y Coordinate: N/A  Signage  ISA - Directional Sign  2010 ADAS 216.6 Advisory  ndard: No Quantity: EACH As-built: 1  No directional signage provided where accessible route diverges from main route   |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Exterior - Southeast Corner of Building  N/A  Y Coordinate: N/A  Signage  ISA - Directional Sign  2010 ADAS 216.6 Advisory  ndard: No Quantity: EACH As-built: 1  No directional signage provided where accessible route diverges from main route  Accessible sign not provided at southeast corner of building approaching NW Monroe Ave   |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Exterior - Southeast Corner of Building  N/A  Y Coordinate: N/A  Signage  ISA - Directional Sign  2010 ADAS 216.6 Advisory  ndard: No Quantity: EACH As-built: 1  No directional signage provided where accessible route diverges from main route  Accessible sign not provided at southeast corner of building approaching NW Monroe Ave  Provide directional signage indicating location of and route to accessible building entrance  1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open |



| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 3A  |
|---|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:   | Exterior - Southeast Corner at SW Campus Way   |
| X Coordinate:   | N/A Y Coordinate: N/A  |
| Barrier Area:   | Signage  |
| Barrier Type:   | ISA - Directional Sign   |
| Code<br>References:   | 2010 ADAS 216.6 Advisory   |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:   | No directional signage provided where accessible route diverges from main route  |
| Findings:   | Accessible sign not provided at southeast of building along SW Campus way  |
| Rec. Solution:  | Provide directional signage indicating location of and route to accessible building entrance   |
| Barrier Severity:   | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open   |
| Implementation  | Priority: 3 Implementation Phase: Implementation Date:   |
| Notes:  |  |
| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 3B  |
|   | 2/20/2017  |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
|   |  |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 2 of 3  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Exterior - Southeast Corner at SW Campus Way   |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Exterior - Southeast Corner at SW Campus Way  N/A  Y Coordinate: N/A   |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Exterior - Southeast Corner at SW Campus Way  N/A  Y Coordinate: N/A  Signage  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Exterior - Southeast Corner at SW Campus Way  N/A  Y Coordinate: N/A  Signage  Permanent Room/Space - Tactile Characters  2010 ADAS 216.2  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Exterior - Southeast Corner at SW Campus Way  N/A  Y Coordinate: N/A  Signage  Permanent Room/Space - Tactile Characters  2010 ADAS 216.2  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier                                       | Merryfield Hall Reference Dwg: 2 of 3  Exterior - Southeast Corner at SW Campus Way  N/A Y Coordinate: N/A  Signage  Permanent Room/Space - Tactile Characters  2010 ADAS 216.2  ndard: No Quantity: EACH As-built: 4  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 2 of 3  Exterior - Southeast Corner at SW Campus Way  N/A Y Coordinate: N/A  Signage  Permanent Room/Space - Tactile Characters  2010 ADAS 216.2  ndard: No Quantity: EACH As-built: 4  No tactile characters at sign identifying permanent rooms and spaces with visual signs  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3  Exterior - Southeast Corner at SW Campus Way  N/A  Y Coordinate: N/A  Signage  Permanent Room/Space - Tactile Characters  2010 ADAS 216.2  ndard: No Quantity: EACH As-built: 4  No tactile characters at sign identifying permanent rooms and spaces with visual signs  No tactile signage provided at door within public route  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 2 of 3  Exterior - Southeast Corner at SW Campus Way  N/A  Y Coordinate: N/A  Signage  Permanent Room/Space - Tactile Characters  2010 ADAS 216.2  ndard: No Quantity: EACH As-built: 4  No tactile characters at sign identifying permanent rooms and spaces with visual signs  No tactile signage provided at door within public route  Provide accessible sign  1 Necessary Cost Est \$1,000.00 Facility Function: Public Status: Open |



| Field Date:                 | 1/26/2017 Report Date 2/22/2017 Barrier #: 4A  |
|-----------------------------|--|
| Bldg Name:                  | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:                   | Floor 1 - Study Group Room 0100E   |
| X Coordinate:               | N/A Y Coordinate: N/A  |
| Barrier Area:               | Signage  |
| Barrier Type:               | Permanent Room/Space - Tactile Characters  |
| Code<br>References:         | 2010 ADAS 216.2  |
| Performance Sta             | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:     | No tactile characters at sign identifying permanent rooms and spaces with visual signs   |
| Findings:                   | No tactile signage provided at door within public route  |
| Rec. Solution:              | Provide accessible sign  |
| Barrier Severity:           | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open   |
| Implementation              | Priority: 3 Implementation Phase: Implementation Date:   |
|                             | neering School of Chemical, Biological, and Environmental Engineering  |
| Field Date:                 | 1/26/2017 Report Date 2/22/2017 Barrier #: 4B  |
| Bldg Name:                  | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:                   | Floor 1 - Study Group Room 0100E   |
| X Coordinate:               | N/A Y Coordinate: N/A  |
| Barrier Area:               | Doors or Gates   |
| Barrier Type:               | Automatic Doors - Sign   |
| Code<br>References:         | Performance Standard   |
| Performance Sta             | ndard: Yes Quantity: JOB As-built : 2  |
| Barrier                     |  |
| Description:                | ISA symbol at automatic door opening device not min. 4" x 4" in size   |
| Description:<br>Findings:   | ISA symbol at automatic door opening device not min. 4" x 4" in size  Existing symbol 1-3/4" high. Nor visible from a distance   |
| ·                           |  |
| Findings:                   | Existing symbol 1-3/4" high. Nor visible from a distance  Recommended: Provide ISA symbol min. 4" x 4" in size on both actuators   |
| Findings:<br>Rec. Solution: | Existing symbol 1-3/4" high. Nor visible from a distance  Recommended: Provide ISA symbol min. 4" x 4" in size on both actuators  1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open |



| Field Date:                         | 1/26/2017 Report Date 2/22/2017 Barrier #: 4C                                   |
|-------------------------------------|---|
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:                           | Floor 1 - Study Group Room 0100E  |
| X Coordinate:                       | N/A Y Coordinate: N/A   |
| Barrier Area:                       | Doors or Gates  |
| Barrier Type:                       | Automatic Doors - BHMA Sign   |
| Code<br>References:                 | ANSI/BHMA A156.10-1999  |
| Performance Sta                     | ndard: No Quantity: EACH As-built : 2   |
| Barrier<br>Description:             | Sign on door reading "AUTOMATIC DOOR" not visible from both sides               |
| Findings:                           | No sign provided  |
| Rec. Solution:                      | Provide new sign on both sides of door  |
| Barrier Severity:                   | 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open            |
| Implementation                      | Priority: 2 Implementation Phase: Implementation Date:                          |
| Notes:                              |   |
| Field Date:                         | 1/26/2017 Report Date 2/22/2017 Barrier #: 4D                                   |
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:                           | Floor 1 - Study Group Room 0100E  |
| X Coordinate:                       | N/A Y Coordinate: N/A   |
| Barrier Area:                       | Doors or Gates  |
| Barrier Type:                       | Automatic Doors - Timing  |
| Code<br>References:                 | 2010 ADAS 404.3   |
| Performance Sta                     | ndard: No Quantity: JOB As-built : 1  |
| Barrier<br>Description:             | Door does not re-open when encountering an obstruction other than the door jamb |
| Findings:                           | Door does not re-open   |
|                                     |   |
| Rec. Solution:                      | Repair actuation device   |
| Rec. Solution:<br>Barrier Severity: |   |
|                                     | 1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open          |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 4E  |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Study Group Room 0100E   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Landing - Existing (2.1% to 3.0%)  |
| Code<br>References:     | 2010 ADAS 404.2.4.4  |
| Performance Sta         | ndard: No Quantity: SF As-built : 25   |
| Barrier<br>Description: | Door or gate lacks landing on both sides of door                                     |
| Findings:               | 10.7% slope  |
| Rec. Solution:          | Demolish and reconstruct level landing   |
| Barrier Severity:       | 4 Low Severity Cost Est \$3,125.00 Facility Function: Public Status: Open            |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                               |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 4F  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Study Group Room 0100E   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Controls and Mechanisms  |
| Barrier Type:           | Clear Floor Space - Stored Elements  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | ndard: No Quantity: JOB As-built : 1   |
| Barrier<br>Description: | Clear floor space for wheelchair not provided at control or mechanism                |
| Findings:               | Potted plant blocks ADOD, tactile exit sign, and electrical switch clear floor space |
| Rec. Solution:          | Move stored items  |
| Barrier Severity:       |  |
|                         | 1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open                 |
| Implementation          | 1 Necessary   Cost Est   \$125.00   Facility Function:   Public   Status:   Open     |



| Field Date:                         | 1/26/2017 Report Date 2/22/2017 Barrier #: 4G  |
|-------------------------------------|--|
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:                           | Floor 1 - Study Group Room 0100E   |
| X Coordinate:                       | N/A Y Coordinate: N/A  |
| Barrier Area:                       | Clear Floor Space  |
| Barrier Type:                       | Protruding Object  |
| Code<br>References:                 | 2010 ADAS 307  |
| Performance Sta                     | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:             | Protruding object in circulation path protrudes more than 4" between 27" and 80" high                        |
| Findings:                           | Foliage protrudes into circulation path  |
| Rec. Solution:                      | Remove object or provide detectable warning (wing walls)   |
| Barrier Severity:                   | 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open   |
| Implementation                      | Priority: 1 Implementation Phase: Implementation Date:   |
| Notes:                              |  |
| Field Date:                         | 1/26/2017 Report Date 2/22/2017 Barrier #: 4H  |
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:                           | Floor 1 - Study Group Room 0100E   |
| X Coordinate:                       | N/A Y Coordinate: N/A  |
| Barrier Area:                       | Signage  |
| Barrier Type:                       | Location - Within 18" of Door  |
| Code<br>References:                 | 2010 ADAS 703.4.2  |
| Performance Sta                     | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:             | Approach to tactile characters on sign not centered at 18" minimum from door swing                           |
| Findings:                           | Tactile exit sign not located within 18" of door. May prevent the visually impaired from                     |
|                                     | approaching the sign to read by touch  |
| Rec. Solution:                      | 1  |
| Rec. Solution:<br>Barrier Severity: | Relocate sign to window near exit door   |
|                                     | Relocate sign to window near exit door  1 Necessary Cost Est \$150.00 Facility Function: Public Status: Open |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 4   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Study Group Room 0100E   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Controls and Mechanisms  |
| Barrier Type:           | Clear Floor Space - Stored Elements  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | ndard: No Quantity: JOB As-built : 0   |
| Barrier<br>Description: | Clear floor space for wheelchair not provided at control or mechanism                    |
| Findings:               | Stored items block approach to tactile signs at rooms 102,102A                           |
| Rec. Solution:          | Move stored items  |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open                       |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                   |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 4J  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Study Group Room 0100E   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Signage  |
| Barrier Type:           | Location - 48" to 60" high   |
| Code<br>References:     | 2010 ADAS 703.4.1  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 5  |
| Barrier<br>Description: | Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor |
| Findings:               | 62" high at rooms 100, 100A, 100B, 102, 102A   |
| Rec. Solution:          | Provide Braille/tactile signs at latch side of door                                      |
| Barrier Severity:       | 1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open                   |
| Implementation          |  |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 4K  |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Study Group Room 0100E   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Signage  |
| Barrier Type:           | Permanent Room/Space - Tactile Characters  |
| Code<br>References:     | 2010 ADAS 216.2  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | No tactile characters at sign identifying permanent rooms and spaces with visual signs |
| Findings:               | No tactile signage provided at door within public route                                |
| Rec. Solution:          | Provide accessible sign  |
| Barrier Severity:       | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open                   |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                                 |
| Notes: No sign          | for "No Exit" door   |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 4L  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Study Group Room 0100E   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Counters and Tables  |
| Barrier Type:           | Table - Knee Clearance   |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide                                 |
| Findings:               | 17" deep knee clearance to support   |
| Rec. Solution:          | Provide min. 1 accessible table. Avoid pedestal base tables.                           |
| Barrier Severity:       | 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open                   |
|                         | S Hilliance Cost Est 3450.00 Tacinty Function. Public Status. Open                     |
| implementation          | Priority: 2 Implementation Phase: Implementation Date:                                 |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 4M                         |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                 |
| Location:               | Floor 1 - Study Group Room 0100E                                      |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Controls and Mechanisms   |
| Barrier Type:           | Clear Floor Space - Stored Elements                                   |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | andard: No Quantity: JOB As-built : 1                                 |
| Barrier<br>Description: | Clear floor space for wheelchair not provided at control or mechanism |
| Findings:               | Table and items block whiteboard and projector clear floor space      |
| Rec. Solution:          | Rearrange furniture to provide accessible maneuvering clearance       |
| Barrier Severity:       | 1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open  |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                |
| Notes:                  |   |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 4N                         |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                 |
| Location:               | Floor 1 - Study Group Room 0100E                                      |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Classrooms  |
| Barrier Type:           | Projector Screen Pull   |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                                |
| Barrier<br>Description: | Screen pull not at max. 48" high for side reach                       |
| Findings:               | Projector screen pull 57" high  |
| Rec. Solution:          | Relocate to max. 48" high or provide extension                        |
| Barrier Severity:       | 3 Hindrance Cost Est \$75.00 Facility Function: Public Status: Open   |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                |
| Notes:                  |   |



| Field Date:  | 1/26/2017 Report Date 2/22/2017 Barrier #: 40   |
|--|---|
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Study Group Room 0100E  |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  | Controls and Mechanisms   |
| Barrier Type:  | Clear Floor Space - Stored Elements   |
| Code<br>References:  | 2010 ADAS 305.3   |
| Performance Sta  | ndard: No Quantity: JOB As-built : 1  |
| Barrier<br>Description:  | Clear floor space for wheelchair not provided at control or mechanism   |
| Findings:  | Items block use of closet   |
| Rec. Solution:   | Move stored items   |
| Barrier Severity:  | 1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open  |
| Implementation   | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:   |   |
| Field Date:  | 1/26/2017 Report Date 2/22/2017 Barrier #: 4P   |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Study Group Room 0100E  |
| X Coordinate:  | N/A Y Coordinate: N/A   |
|  | IN//  |
| Barrier Area:  | Controls and Mechanisms   |
| Barrier Area:<br>Barrier Type:   |   |
|  | Controls and Mechanisms   |
| Barrier Type:<br>Code  | Controls and Mechanisms  Coat Hook - Height  2010 ADAS 308.2  |
| Barrier Type:<br>Code<br>References:   | Controls and Mechanisms  Coat Hook - Height  2010 ADAS 308.2  |
| Barrier Type:<br>Code<br>References:<br>Performance Sta<br>Barrier                           | Controls and Mechanisms  Coat Hook - Height  2010 ADAS 308.2  Indard: No Quantity: EACH As-built: 1   |
| Barrier Type: Code References: Performance Sta Barrier Description:                          | Controls and Mechanisms  Coat Hook - Height  2010 ADAS 308.2  Indard: No Quantity: EACH As-built: 1  Clothing hooks not max. 48" high AFF   |
| Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Controls and Mechanisms  Coat Hook - Height  2010 ADAS 308.2  Indard: No Quantity: EACH As-built: 1  Clothing hooks not max. 48" high AFF  55" high clothing rod  Provide additional clothing rod within accessible reach range in an accessible location   |
| Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Controls and Mechanisms  Coat Hook - Height  2010 ADAS 308.2  Indard: No Quantity: EACH As-built: 1  Clothing hooks not max. 48" high AFF  55" high clothing rod  Provide additional clothing rod within accessible reach range in an accessible location  2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 4Q                          |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                  |
| Location:               | Floor 1 - Study Group Room 0100E                                       |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Controls and Mechanisms  |
| Barrier Type:           | Shelves or Cabinets  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | andard: No Quantity: JOB As-built : 1                                  |
| Barrier<br>Description: | Shelf or cabinet not mounted max. 48" above floor or ground            |
| Findings:               | Shelf or cabinet not accessible. Provide assistance.                   |
| Rec. Solution:          | Provide additional shelf at accessible height or provide assistance    |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open     |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                 |
| Notes: 73" high         | n  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 4R                          |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                  |
| Location:               | Floor 1 - Study Group Room 0100E                                       |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Alarms   |
| Barrier Type:           | Horn/Strobe - Common Use Area  |
| Code<br>References:     | 2010 ADAS 702.1  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                                 |
| Barrier<br>Description: | No horn/strobes in common use areas                                    |
| Findings:               | No device provided   |
| Rec. Solution:          | Provide strobe in common use area                                      |
| Barrier Severity:       | 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                 |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 5A   |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Workroom 0100D  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Counters and Tables   |
| Barrier Type:           | Counter - Surface Height  |
| Code<br>References:     | 2010 ADAS 902.3   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | No section at least 3 feet long between 28" and 34" provided at existing counter                  |
| Findings:               | 36-1/2" high  |
| Rec. Solution:          | Provide min. 3 ft long section of counter at max. 34" high  |
| Barrier Severity:       | 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open                              |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:                  |   |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 5B   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Workroom 0100D  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Counters and Tables   |
| Barrier Type:           | Counter - Knee Clearance  |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide  |
| Findings:               | No knee clearance   |
| Rec. Solution:          | Provide min. 3 ft segment of accessible counter. Flip-up counters, adiacent tables and similar de |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open                                |
| Implementation          |   |
| Notes:                  |   |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 5C  |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Workroom 0100D   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Controls and Mechanisms  |
| Barrier Type:           | Actuator/Control - Hi/low Reach  |
| Code<br>References:     | 2010 ADAS 308.2.2  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Use of control involves low reach of less than 15" above floor or more than 48" high |
| Findings:               | Printer 55" high   |
| Rec. Solution:          | Relocate to area at min. 15" or max. 48" high  |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open                 |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                               |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 5D  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Workroom 0100D   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Controls and Mechanisms  |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed                                      |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high                                |
| Findings:               | Freezer compartment control 55" high   |
| Rec. Solution:          | Replace with accessible unit, relocate to accessible location or provide assistance  |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open                   |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                               |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 5E                                    |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Workroom 0100D   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Counters and Tables  |
| Barrier Type:           | Counter - Surface Height   |
| Code<br>References:     | 2010 ADAS 902.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | No section at least 3 feet long between 28" and 34" provided at existing counter |
| Findings:               | 36-1/2" high kitchenette counter   |
| Rec. Solution:          | Provide min. 3 ft long section of counter at max. 34" high                       |
| Barrier Severity:       | 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open             |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 5F                                    |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Workroom 0100D   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Counters and Tables  |
| Barrier Type:           | Counter - Knee Clearance   |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide                           |
| Findings:               | No knee clearance kitchenette counter  |
| Rec. Solution:          | Move stored objects  |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open               |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 5G  |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Workroom 0100D   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Controls and Mechanisms  |
| Barrier Type:           | Actuator/Control - Hi/low Reach  |
| Code<br>References:     | 2010 ADAS 308.2.2  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Use of control involves low reach of less than 15" above floor or more than 48" high |
| Findings:               | Coffee maker control 58" high. Mail boxes 51" high                                   |
| Rec. Solution:          | Relocate to area at min. 15" or max. 48" high  |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open                 |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                               |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 5H  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Workroom 0100D   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Alarms   |
| Barrier Type:           | Horn/Strobe - Common Use Area  |
| Code<br>References:     | 2010 ADAS 702.1  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | No horn/strobes in common use areas  |
| Findings:               | No device provided   |
| Rec. Solution:          | Provide strobe in common use area  |
| Barrier Severity:       | 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open               |
| Implementation          |  |
|                         | Priority: 1 Implementation Phase: Implementation Date:                               |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 6A                        |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Unisex Restroom 0101                                       |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Sign - Approach  |
| Code<br>References:     | 2010 ADAS 703.2.3  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                |
| Barrier<br>Description: | Approach to sign not within 18" due to protruding object             |
| Findings:               | Fixed counter blocks approach to sign                                |
| Rec. Solution:          | Relocate sign or replace   |
| Barrier Severity:       | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:               |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 6B                        |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Unisex Restroom 0101                                       |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Door Clearance - Pull Side   |
| Code<br>References:     | 2010 ADAS Figure 404.2.4.1   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 0                                |
| Barrier<br>Description: | Door lacks min. 18" strike edge clearance at pull side               |
| Findings:               | 16" strike edge clearance to fixed counter                           |
| Rec. Solution:          | Provide automatic door opening device                                |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open   |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:               |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 6C                            |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                    |
| Location:               | Floor 1 - Unisex Restroom 0101   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Door 10" Bottom Surface  |
| Code<br>References:     | 2010 ADAS 404.2.10   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                    |
| Barrier<br>Description: | Door/Gate lacks min. 10" smooth uninterrupted bottom surface             |
| Findings:               | 8" high at indented panel in door  |
| Rec. Solution:          | Provide kick plate at push side of door                                  |
| Barrier Severity:       | 1 Necessary Cost Est \$225.00 Facility Function: Public Status: Open     |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                   |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 6D                            |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                    |
| Location:               | Floor 1 - Unisex Restroom 0101   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Stall Door Closer  |
| Code<br>References:     | 2010 ADAS 604.8.1.2  |
| Performance Sta         | ndard: No Quantity: JOB As-built : 1                                     |
| Barrier<br>Description: | Stall door not equipped with an automatic closing device                 |
| Findings:               | Door does not self close   |
| Rec. Solution:          | Provide automatic door opening device                                    |
| Barrier Severity:       | 2 Recommended Cost Est \$5,000.00 Facility Function: Public Status: Open |
| Implementation          |  |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 6E  |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Unisex Restroom 0101   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Lavatory - Drainpipes  |
| Code<br>References:     | 2010 ADAS 606.5  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Hot water and drainpipes accessible under lavatory not insulated or covered          |
| Findings:               | Insulation does not cover drainpipes fully   |
| Rec. Solution:          | Insulate drainpipes and hot water pipes  |
| Barrier Severity:       | 2 Recommended Cost Est \$220.00 Facility Function: Public Status: Open               |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                               |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 6F  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Unisex Restroom 0101   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Dispensers - Protruding Object   |
| Code<br>References:     | 2010 ADAS 307.2  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Protruding dispenser creates protruding object in path of travel                     |
| Findings:               | Dispenser protrudes 10" at 41" high. Trash bin is not a permanent detectable warning |
| Rec. Solution:          | Relocate dispenser or provide cane-detectable warning                                |
| Barrier Severity:       | 2 Recommended Cost Est \$550.00 Facility Function: Public Status: Open               |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                               |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 6G                            |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                    |
| Location:               | Floor 1 - Unisex Restroom 0101   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Toilet - Grab Bars   |
| Code<br>References:     | 2010 ADAS 609.3  |
| Performance Sta         | andard: No Quantity: JOB As-built : 1                                    |
| Barrier<br>Description: | Space between the wall and the grab bars is not an absolute 1-½"         |
| Findings:               | 3/4" between grab bar and toilet tank preventing use of grab bar         |
| Rec. Solution:          | Replace grab bars  |
| Barrier Severity:       | 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open     |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                   |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 6H                            |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                    |
| Location:               | Floor 1 - Unisex Restroom 0101   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Toilet - Rear Grab Bar   |
| Code<br>References:     | 2010 ADAS 604.5.2  |
| Performance Sta         | andard: No Quantity: JOB As-built : 1                                    |
| Barrier<br>Description: | Rear grab bar not centered 12" from wall and 24" on the other side of WC |
| Findings:               | 11-1/2" on center  |
| Rec. Solution:          | Replace grab bars with reinforcement                                     |
| Barrier Severity:       | 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open     |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                   |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 61                                    |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Unisex Restroom 0101   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Seat Cover Dispenser   |
| Code<br>References:     | 2010 ADAS 307.2  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Seat cover dispenser not located on an accessible route. Blocked by water closet |
| Findings:               | Access to dispenser blocked by water closet                                      |
| Rec. Solution:          | Replace or remount dispenser on an accessible route with clear floor space       |
| Barrier Severity:       | 2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open           |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 6J                                    |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Unisex Restroom 0101   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Alarm - Horn/Strobe  |
| Code<br>References:     | 2010 ADAS 702.1  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Where a fire alarm is installed, no horn/strobe provided                         |
| Findings:               | No device provided   |
| Rec. Solution:          | Provide horn/strobe in sanitary facility   |
| Barrier Severity:       | 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open           |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |



| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 7A  |
|---|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:   | Floor 1 - Kiewit Materials Performance Lab 0109  |
| X Coordinate:   | N/A Y Coordinate: N/A  |
| Barrier Area:   | Signage  |
| Barrier Type:   | Permanent Room/Space - Tactile Characters  |
| Code<br>References:   | 2010 ADAS 216.2  |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:   | No tactile characters at sign identifying permanent rooms and spaces with visual signs   |
| Findings:   | No tactile signage provided at door within public route  |
| Rec. Solution:  | Provide accessible sign  |
| Barrier Severity:   | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open   |
| Implementation  | Priority: 3 Implementation Phase: Implementation Date:   |
| Notes:  |  |
|   |  |
| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 7B  |
| Field Date:<br>Bldg Name:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 7B  Merryfield Hall Reference Dwg: 2 of 3   |
|   |  |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
| Bldg Name:<br>Location:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A  V Coordinate: N/A  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities  Door Closer - Automatic Device  2010 ADAS 404.2.9  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities  Door Closer - Automatic Device  2010 ADAS 404.2.9  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities  Door Closer - Automatic Device  2010 ADAS 404.2.9  ndard: No Quantity: EACH As-built: 1  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A Y Coordinate: N/A  Laboratory Facilities  Door Closer - Automatic Device  2010 ADAS 404.2.9  Indard: No Quantity: EACH As-built: 1  Door opening force exceeds 5 lbf   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Kiewit Materials Performance Lab 0109 N/A Y Coordinate: N/A Laboratory Facilities Door Closer - Automatic Device 2010 ADAS 404.2.9  ndard: No Quantity: EACH As-built: 1  Door opening force exceeds 5 lbf  14 lbf and door landing slope at 3.3%  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities  Door Closer - Automatic Device  2010 ADAS 404.2.9  Indard: No Quantity: EACH As-built: 1  Door opening force exceeds 5 lbf  14 lbf and door landing slope at 3.3%  Provide automatic door opening device  1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open |



| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 7C  |
|--|--|
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:  | Floor 1 - Kiewit Materials Performance Lab 0109  |
| X Coordinate:  | N/A Y Coordinate: N/A  |
| Barrier Area:  | Laboratory Facilities  |
| Barrier Type:  | Door Closer - Sweep  |
| Code<br>References:  | 2010 ADAS 404.2.8.1  |
| Performance Sta  | ndard: No Quantity: EACH As-built : 0  |
| Barrier<br>Description:  | Door closer lacks min. 5 second sweep period   |
| Findings:  | 1 second sweep   |
| Rec. Solution:   | Provide automatic door opening device  |
| Barrier Severity:  | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open   |
| Implementation   | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:   |  |
| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 7D  |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3  |
|  |  |
| Location:  | Floor 1 - Kiewit Materials Performance Lab 0109  |
| Location:<br>X Coordinate:   | Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  |
|  | N/A V Coordinate: N/A  |
| X Coordinate:  | N/A Y Coordinate: N/A  |
| X Coordinate:<br>Barrier Area:   | N/A Y Coordinate: N/A  Laboratory Facilities   |
| X Coordinate:<br>Barrier Area:<br>Barrier Type:<br>Code  | N/A Y Coordinate: N/A  Laboratory Facilities  Doors - Vision Lights  2010 ADAS 404.2.11  |
| X Coordinate: Barrier Area: Barrier Type: Code References:   | N/A Y Coordinate: N/A  Laboratory Facilities  Doors - Vision Lights  2010 ADAS 404.2.11  |
| X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | N/A  Laboratory Facilities  Doors - Vision Lights  2010 ADAS 404.2.11  ndard: No Quantity: EACH As-built: 1  |
| X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | N/A  Laboratory Facilities  Doors - Vision Lights  2010 ADAS 404.2.11  Indard: No Quantity: EACH As-built: 1  View panels in or adjacent to doors or gates not max. 43" above floor or ground  |
| X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | N/A  Laboratory Facilities  Doors - Vision Lights  2010 ADAS 404.2.11  Indard: No Quantity: EACH As-built: 1  View panels in or adjacent to doors or gates not max. 43" above floor or ground  48-1/2" high  |
| X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | N/A  Laboratory Facilities  Doors - Vision Lights  2010 ADAS 404.2.11  Indard: No Quantity: EACH As-built: 1  View panels in or adjacent to doors or gates not max. 43" above floor or ground  48-1/2" high  Replace door/gate or vision panel  3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7E                          |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                  |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                        |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Electrical Switches - High Unobstructed                                |
| Code<br>References:     | 2010 ADAS 308.2.1  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                  |
| Barrier<br>Description: | Light switch control box top edge not at max. 48" high                 |
| Findings:               | 52" high   |
| Rec. Solution:          | Relocate switch box top edge to max. 48" high                          |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open   |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                 |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7F                          |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                  |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                        |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Controls and Mechanisms  |
| Barrier Type:           | First Aid Kit - High Reach Range                                       |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                  |
| Barrier<br>Description: | Opening mechanism on first aid kit not at max. 48" high for side reach |
| Findings:               | 59" high   |
| Rec. Solution:          | Relocate control or mechanism to max. 48" high                         |
| Barrier Severity:       | 1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open   |
| Implementation          |  |
| Notes:                  |  |



| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 7G   |
|--|---|
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Kiewit Materials Performance Lab 0109   |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  | Alarms  |
| Barrier Type:  | Fire Pull - Operation   |
| Code<br>References:  | 2010 ADAS 309.4   |
| Performance Sta  | andard: No Quantity: EACH As-built : 0  |
| Barrier<br>Description:  | Fire pull has no fist operable hardware   |
| Findings:  | Fire pull not fist operable   |
| Rec. Solution:   | Replace fire pull when remodeling   |
| Barrier Severity:  | 4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open   |
| Implementation   | Priority: 1 Implementation Phase: Implementation Date:  |
| Notes:   |   |
| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 7H   |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Kiewit Materials Performance Lab 0109   |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  | Alarms  |
| Darrier Tunes  |   |
| Barrier Type:  | Fire Pull - Height  |
| Barrier Type:<br>Code<br>References:   | Fire Pull - Height 2010 ADAS 308.2.2  |
| Code   | 2010 ADAS 308.2.2   |
| Code<br>References:  | 2010 ADAS 308.2.2   |
| Code<br>References:<br>Performance Sta<br>Barrier                              | 2010 ADAS 308.2.2 andard: No Quantity: EACH As-built: 1   |
| Code<br>References:<br>Performance Sta<br>Barrier<br>Description:              | 2010 ADAS 308.2.2  andard: No Quantity: EACH As-built: 1  Fire pulls not between 42" and 48" high   |
| Code References: Performance Sta Barrier Description: Findings:                | 2010 ADAS 308.2.2  andard: No Quantity: EACH As-built: 1  Fire pulls not between 42" and 48" high  49" high  Replace fire pull when remodeling  |
| Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | 2010 ADAS 308.2.2  andard: No Quantity: EACH As-built: 1  Fire pulls not between 42" and 48" high  49" high  Replace fire pull when remodeling  4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7                                |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                       |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                             |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Shelves or Cabinet  |
| Code<br>References:     | 2010 ADAS 603.4   |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                                      |
| Barrier<br>Description: | Shelf or cabinet not mounted between 40" and 48" above floor or ground      |
| Findings:               | Storage shelves 9" - 63" high   |
| Rec. Solution:          | Provide additional shelf/cabinet at accessible height or provide assistance |
| Barrier Severity:       | 2 Recommended Cost Est \$75.00 Facility Function: Public Status: Open       |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                      |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7J                               |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                       |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                             |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Clear Floor Space   |
| Barrier Type:           | Passageway - Min. 36" (Stored Item)   |
| Code<br>References:     | 2010 ADAS 403.5.1   |
| Performance Sta         | andard: No Quantity: JOB As-built: 1  |
| Barrier<br>Description: | Circulation route not min. 36" wide between elements                        |
| Findings:               | 23" wide circulation route  |
| Rec. Solution:          | Removed stored items to provide accessible circulation route through lab    |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open          |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                      |
| Notes:                  |   |



| Field Date:                         | 4 /27 /2047 Percet Date   2 /22 /2247 Persion #1   71/                                      |
|-------------------------------------|---|
| Field Date:                         | 1/27/2017 Report Date   2/22/2017 Barrier #:   7K   |
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:                           | Floor 1 - Kiewit Materials Performance Lab 0109   |
| X Coordinate:                       | N/A Y Coordinate: N/A   |
| Barrier Area:                       | Laboratory Facilities   |
| Barrier Type:                       | Clear Floor Space - Controls  |
| Code<br>References:                 | 2010 ADAS 305.3   |
| Performance Sta                     | andard: No Quantity: JOB As-built : 1   |
| Barrier<br>Description:             | Clear floor space of min. 30" by 48" not provided   |
| Findings:                           | Boxes block freezer clear floor space   |
| Rec. Solution:                      | Removed stored items to provide accessible circulation route through lab                    |
| Barrier Severity:                   | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open                          |
| Implementation                      | Priority: 2 Implementation Phase: Implementation Date:                                      |
| Notes:                              |   |
| Field Date:                         | 1/27/2017 Report Date 2/22/2017 Barrier #: 7L   |
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:                           | Floor 1 - Kiewit Materials Performance Lab 0109   |
| X Coordinate:                       | N/A Y Coordinate: N/A   |
| Barrier Area:                       | Laboratory Facilities   |
| Barrier Type:                       | Protruding Object   |
| Code<br>References:                 | 2010 ADAS 307.2   |
| Performance Sta                     | andard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:             | Wall mounted object (dispensers) protrudes more than 4" from wall                           |
| Findings:                           | Mechanical box protrudes 6-1/4" at 38" high   |
|                                     | I   |
| Rec. Solution:                      | Relocate, remove object (dispenser) or provide detectable warning for the visually impaired |
| Rec. Solution:<br>Barrier Severity: |   |
|                                     | 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open                        |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7M                               |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                       |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                             |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Clear Floor Space - Controls  |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | ndard: No Quantity: JOB As-built : 1  |
| Barrier<br>Description: | Clear floor space of min. 30" by 48" not provided                           |
| Findings:               | Machine blocks clear floor space at shelves                                 |
| Rec. Solution:          | Move stored items at control or mechanism                                   |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open          |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                      |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7N                               |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                       |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                             |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Shelves or Cabinet  |
| Code<br>References:     | 2010 ADAS 603.4   |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                                      |
| Barrier<br>Description: | Shelf or cabinet not mounted between 40" and 48" above floor or ground      |
| Findings:               | 59" - 78" high  |
| Rec. Solution:          | Provide additional shelf/cabinet at accessible height or provide assistance |
| Barrier Severity:       | 2 Recommended Cost Est \$75.00 Facility Function: Public Status: Open       |
| Implementation          |   |
| piementation            | Priority: 2 Implementation Phase: Implementation Date:                      |



| Field Date:                                      | 1/27/2017 Report Date 2/22/2017 Barrier #: 70  |
|--|--|
| Bldg Name:                                       | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:  | Floor 1 - Kiewit Materials Performance Lab 0109  |
| X Coordinate:                                    | N/A Y Coordinate: N/A  |
| Barrier Area:                                    | Laboratory Facilities  |
| Barrier Type:                                    | Protruding Object  |
| Code<br>References:                              | 2010 ADAS 307.2  |
| Performance Sta                                  | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:                          | Wall mounted object (dispensers) protrudes more than 4" from wall  |
| Findings:  | Shelves protrude 18" at 56-1/2" high   |
| Rec. Solution:                                   | Relocate, remove object (dispenser) or provide detectable warning for the visually impaired  |
| Barrier Severity:                                | 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open   |
| Implementation                                   | Priority: 1 Implementation Phase: Implementation Date:   |
| Notes:   |  |
| Field Date:                                      | 1/27/2017 Report Date 2/22/2017 Barrier #: 7P  |
| Bldg Name:                                       | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:  | Floor 1 - Kiewit Materials Performance Lab 0109  |
| X Coordinate:                                    | N/A Y Coordinate: N/A  |
| Barrier Area:                                    | Laboratory Facilities  |
| Barrier Type:                                    | Actuator/Control - Side Reach High Unobstructed  |
| Code<br>References:                              | 2010 ADAS 305.3  |
| Performance Sta                                  | andard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description:                          | Control or mechanism not at min. 15" or max. 48" high  |
|  |  |
| Findings:  | Freezer controls 65" high  |
| _  | Freezer controls 65" high  Relocate control or mechanism to min. 15" or max. 48" high or provide assistance  |
| Findings:<br>Rec. Solution:<br>Barrier Severity: | Relocate control or mechanism to min. 15" or max. 48" high or provide assistance   |
| Rec. Solution:                                   | Relocate control or mechanism to min. 15" or max. 48" high or provide assistance  3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open |



| Field Date:                 | 1/27/2017 Report Date 2/22/2017 Barrier #: 7Q   |
|-----------------------------|---|
| Bldg Name:                  | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:                   | Floor 1 - Kiewit Materials Performance Lab 0109   |
| X Coordinate:               | N/A Y Coordinate: N/A   |
| Barrier Area:               | Laboratory Facilities   |
| Barrier Type:               | Workstation - Ratio   |
| Code<br>References:         | 2010 ADAS 902   |
| Performance Sta             | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:     | At least 1 table or 5% of all workstations is not accessible  |
| Findings:                   | 4 workstations with no accessible work station provided   |
| Rec. Solution:              | Provide min. 1 accessible workstation in lab for each type of work area associated with specific  |
| Barrier Severity:           | 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open  |
| Implementation              | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:                      |   |
| Field Date:                 | 1/27/2017 Report Date 2/22/2017 Barrier #: 7R   |
| Bldg Name:                  | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:                   | Floor 1 - Kiewit Materials Performance Lab 0109   |
| X Coordinate:               | N/A Y Coordinate: N/A   |
| Barrier Area:               | Laboratory Facilities   |
| Barrier Type:               | Workstation - Surface   |
| Code<br>References:         | 2010 ADAS 902   |
| Performance Sta             | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:     | Table an organization confers beight accorde 24ll bink  |
|                             | Table or workstation surface height exceeds 34" high  |
| Findings:                   | 37" workstation surface height at workstation near entry door   |
| Findings:<br>Rec. Solution: |   |
| J                           | 37" workstation surface height at workstation near entry door  Provide min. 1 accessible workstation of each type or overall 5%   |
| Rec. Solution:              | 37" workstation surface height at workstation near entry door  Provide min. 1 accessible workstation of each type or overall 5%  3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open |



| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 75  |
|---|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:   | Floor 1 - Kiewit Materials Performance Lab 0109  |
| X Coordinate:   | N/A Y Coordinate: N/A  |
| Barrier Area:   | Laboratory Facilities  |
| Barrier Type:   | Workstation - Knee Clearance   |
| Code<br>References:   | 2010 ADAS 902  |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:   | Knee clearance not min. 27" high, 19" deep or 30" wide   |
| Findings:   | Items block knee clearance   |
| Rec. Solution:  | Remove stored items in knee clearance space  |
| Barrier Severity:   | 1 Necessary Cost Est \$875.00 Facility Function: Public Status: Open   |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:  |  |
|   |  |
| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 7T  |
|   | 1/27/2017 Report Date 2/22/2017 Barrier #: 7T  Merryfield Hall Reference Dwg: 2 of 3   |
| Bldg Name:  |  |
| Field Date:<br>Bldg Name:<br>Location:<br>X Coordinate:   | Merryfield Hall Reference Dwg: 2 of 3  |
| Bldg Name:<br>Location:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities  Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities  Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities  Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 0   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A Y Coordinate: N/A  Laboratory Facilities  Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 0  Control or mechanism not at min. 15" or max. 48" high  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Kiewit Materials Performance Lab 0109 N/A Y Coordinate: N/A  Laboratory Facilities Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 0  Control or mechanism not at min. 15" or max. 48" high  Machine controls 55" high   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities  Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 0  Control or mechanism not at min. 15" or max. 48" high  Machine controls 55" high  Relocate control or mechanism to min. 15" or max. 48" high or provide assistance  3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7U                                       |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                                     |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Electrical Outlets - Forward Reach Obstructed (10"-25")                             |
| Code<br>References:     | 2010 ADAS 306.3.2   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description: | Outlet located over an 10" to 25" obstruction max. 34" high located above 44"       |
| Findings:               | 44" high and 28" deep over an obstruction 37" high                                  |
| Rec. Solution:          | Relocate control or mechanism to max. 44" high or provide assistance                |
| Barrier Severity:       | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open                |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7V                                       |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                                     |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Actuator/Control - Forward Reach Obstructed (10"-25")                               |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44" |
| Findings:               | Spigots 40" high and 24" deep over an obstruction 37" high                          |
| Rec. Solution:          | Relocate control or mechanism to max. 44" high                                      |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open                |
| Implementation          | 7   |
| •                       |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7W                            |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                    |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                          |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Workstation - Surface  |
| Code<br>References:     | 2010 ADAS 902  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                    |
| Barrier<br>Description: | Table or workstation surface height exceeds 34" high                     |
| Findings:               | 36-1/2" workstation surface height at 3 workstations provided along wall |
| Rec. Solution:          | Provide min. 1 accessible workstation of each type or overall 5%         |
| Barrier Severity:       | 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open     |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                   |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7X                            |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                    |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                          |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Workstation - Knee Clearance   |
| Code<br>References:     | 2010 ADAS 902  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 0                                    |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide                   |
| Findings:               | Stored items block knee clearance  |
| Rec. Solution:          | Remove obstructions  |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open       |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                   |
| Notes:                  |  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7Y                                    |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                                  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Electrical Outlets - Forward Reach Obstructed (10"-25")                          |
| Code<br>References:     | 2010 ADAS 306.3.2  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Outlet located over an 10" to 25" obstruction max. 34" high located above 44"    |
| Findings:               | 46" high and 29" deep over an obstruction 36-1/2" high                           |
| Rec. Solution:          | Relocate control or mechanism to max. 44" high                                   |
| Barrier Severity:       | 2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open           |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7Z                                    |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                                  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed                                  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high                            |
| Findings:               | White device has controls at 54" high  |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high or provide assistance |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open               |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AA                              |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                       |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                             |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Shelves or Cabinet  |
| Code<br>References:     | 2010 ADAS 603.4   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                       |
| Barrier<br>Description: | Shelf or cabinet not mounted between 40" and 48" above floor or ground      |
| Findings:               | Shelf or cabinet not accessible. Provide assistance.                        |
| Rec. Solution:          | Provide additional shelf/cabinet at accessible height or provide assistance |
| Barrier Severity:       | 2 Recommended Cost Est \$75.00 Facility Function: Public Status: Open       |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                      |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AB                              |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                       |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                             |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Sink - Rim or Countertop  |
| Code<br>References:     | 2010 ADAS 606.3   |
| Performance Sta         | ndard: No Quantity: LF As-built : 1   |
| Barrier<br>Description: | Sink rim or surface not max. 34" high                                       |
| Findings:               | 36-1/2" high  |
| Rec. Solution:          | Reposition existing sink or provide additional sink for use in area         |
| Barrier Severity:       | 1 Necessary Cost Est \$370.00 Facility Function: Public Status: Open        |
| Implementation          |   |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AC   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Sink - Knee Clearance  |
| Code<br>References:     | 2010 ADAS 606.2 & 306  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide                                 |
| Findings:               | No knee clearance  |
| Rec. Solution:          | Replace cabinet and remount sink   |
| Barrier Severity:       | 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open                   |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                 |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AD   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Actuator/Control - Forward Reach Obstructed (10"-25")                                  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 2  |
| Barrier<br>Description: | Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44"    |
| Findings:               | Paper towel and soap dispensers 44" high and 29" deep over an obstruction 36-1/2" high |
| Rec. Solution:          | Relocate control or mechanism to max. 44" high   |
| Barrier Severity:       | 3 Hindrance Cost Est \$1,500.00 Facility Function: Public Status: Open                 |
| Implementation          |  |
| Notes:                  |  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AE                       |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                      |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Counters and Tables  |
| Barrier Type:           | Table - Surface Height   |
| Code<br>References:     | 2010 ADAS 902.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                               |
| Barrier<br>Description: | Surface height exceeds 34" high                                      |
| Findings:               | 35-1/2" surface height at table next to testing equipment            |
| Rec. Solution:          | Provide min. 1 accessible table. Avoid pedestal base tables.         |
| Barrier Severity:       | 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AF                       |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                      |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Counters and Tables  |
| Barrier Type:           | Table - Knee Clearance   |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                               |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide               |
| Findings:               | Stored items block knee clearance                                    |
| Rec. Solution:          | Move stored objects  |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open   |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AG                       |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                      |
|                         | N/A Y Coordinate: N/A  |
| Barrier Area:           | Counters and Tables  |
| Barrier Type:           | Table - Surface Height   |
| Code                    | 2010 ADAS 902.3  |
| References:             | 2010 / 15/15 302.3   |
| Performance Sta         | ndard: No Quantity: EACH As-built: 1                                 |
| Barrier<br>Description: | Surface height exceeds 34" high                                      |
| Findings:               | 35-1/2" surface height   |
| Rec. Solution:          | Provide min. 1 accessible table. Avoid pedestal base tables.         |
| Barrier Severity:       | 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AH                       |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                      |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Counters and Tables  |
| Barrier Type:           | Table - Knee Clearance   |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide               |
| Findings:               | Stored items block knee clearance                                    |
| Rec. Solution:          | Move stored objects  |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open   |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |



| Field Date:                                   | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AI  |
|---|---|
| Bldg Name:                                    | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:                                     | Floor 1 - Kiewit Materials Performance Lab 0109   |
| X Coordinate:                                 | N/A Y Coordinate: N/A   |
| Barrier Area:                                 | Laboratory Facilities   |
| Barrier Type:                                 | Actuator/Control - Side Reach High Unobstructed   |
| Code<br>References:                           | 2010 ADAS 305.3   |
| Performance Sta                               | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:                       | Control or mechanism not at min. 15" or max. 48" high   |
| Findings:                                     | Hobart mixer controls 61" high  |
| Rec. Solution:                                | Relocate control or mechanism to min. 15" or max. 48" high  |
| Barrier Severity:                             | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open  |
| Implementation                                | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:  |   |
| Field Date:                                   | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AJ  |
| Bldg Name:                                    | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:                                     | Floor 1 - Kiewit Materials Performance Lab 0109   |
| X Coordinate:                                 | N/A Y Coordinate: N/A   |
| Barrier Area:                                 | Laboratory Facilities   |
| Barrier Type:                                 | Workstation - Knee Clearance  |
| Code<br>References:                           | 2010 ADAS 902   |
| Performance Sta                               |   |
| remonitative Sta                              | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:                       | Indard: No Quantity: EACH As-built: 1  Knee clearance not min. 27" high, 19" deep or 30" wide   |
| Barrier                                       |   |
| Barrier<br>Description:                       | Knee clearance not min. 27" high, 19" deep or 30" wide  |
| Barrier<br>Description:<br>Findings:          | Knee clearance not min. 27" high, 19" deep or 30" wide  Knee clearance blocked by stored items at otherwise accessible workstation  Remove obstructions   |
| Barrier Description: Findings: Rec. Solution: | Knee clearance not min. 27" high, 19" deep or 30" wide  Knee clearance blocked by stored items at otherwise accessible workstation  Remove obstructions  1 Necessary Cost Est \$875.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AK                                   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                                  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed                                  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high                            |
| Findings:               | VWR machine controls 68" high  |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high or provide assistance |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open               |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AL                                   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109                                  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed                                  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high                            |
| Findings:               | Air gas tank controls 57" high   |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high or provide assistance |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open               |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                           |
| Notes:                  | Priority. 2 implementation Phase.  |



| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AM  |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:   | Floor 1 - Kiewit Materials Performance Lab 0109   |
| X Coordinate:   | N/A Y Coordinate: N/A   |
| Barrier Area:   | Laboratory Facilities   |
| Barrier Type:   | Clear Floor Space - Controls  |
| Code<br>References:   | 2010 ADAS 305.3   |
| Performance Sta   | ndard: No Quantity: JOB As-built : 1  |
| Barrier<br>Description:   | Clear floor space of min. 30" by 48" not provided   |
| Findings:   | Airgas tanks block approach to tool box   |
| Rec. Solution:  | Move stored items or tool box to provide access   |
| Barrier Severity:   | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:  |   |
|   |   |
| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AN  |
| Field Date:<br>Bldg Name:   | 1/27/2017   Report Date   2/22/2017   Barrier #:   7AN     Merryfield Hall   Reference Dwg:   2 of 3  |
|   |   |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109   |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A   |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities  Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities  Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A Y Coordinate: N/A  Laboratory Facilities  Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  Indard: No Quantity: EACH As-built: 1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities  Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  Indard: No Quantity: EACH As-built: 1  Control or mechanism not at min. 15" or max. 48" high  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Kiewit Materials Performance Lab 0109 N/A Y Coordinate: N/A Laboratory Facilities Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 1  Control or mechanism not at min. 15" or max. 48" high  Tool box top shelves 59" high   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities  Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  Indard: No Quantity: EACH As-built: 1  Control or mechanism not at min. 15" or max. 48" high  Tool box top shelves 59" high  Relocate control or mechanism to min. 15" or max. 48" high or provide assistance  3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open |



| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AO  |
|--|---|
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Kiewit Materials Performance Lab 0109   |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  | Laboratory Facilities   |
| Barrier Type:  | Sink - Rim or Countertop  |
| Code<br>References:  | 2010 ADAS 606.3   |
| Performance Sta  | ndard: No Quantity: LF As-built : 1   |
| Barrier<br>Description:  | Sink rim or surface not max. 34" high   |
| Findings:  | 35" high  |
| Rec. Solution:   | Reposition existing sink or provide additional sink for use in area   |
| Barrier Severity:  | 1 Necessary Cost Est \$370.00 Facility Function: Public Status: Open  |
| Implementation   | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:   |   |
| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AP  |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Kiewit Materials Performance Lab 0109   |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  | IN/A I Cooldinate. IN/A   |
|  | Laboratory Facilities   |
| Barrier Type:  |   |
| Barrier Type:<br>Code<br>References:   | Laboratory Facilities   |
| Code   | Laboratory Facilities Sink - Knee Clearance 2010 ADAS 606.2 & 306   |
| Code<br>References:  | Laboratory Facilities Sink - Knee Clearance 2010 ADAS 606.2 & 306   |
| Code<br>References:<br>Performance Sta<br>Barrier                              | Laboratory Facilities  Sink - Knee Clearance  2010 ADAS 606.2 & 306  Indard: No Quantity: EACH As-built: 1  |
| Code<br>References:<br>Performance Sta<br>Barrier<br>Description:              | Laboratory Facilities  Sink - Knee Clearance  2010 ADAS 606.2 & 306  Indard: No Quantity: EACH As-built: 1  Knee clearance not min. 27" high, 19" deep or 30" wide  |
| Code References: Performance Sta Barrier Description: Findings:                | Laboratory Facilities  Sink - Knee Clearance  2010 ADAS 606.2 & 306  Indard: No Quantity: EACH As-built: 1  Knee clearance not min. 27" high, 19" deep or 30" wide  25" high knee clearance   |
| Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Laboratory Facilities  Sink - Knee Clearance  2010 ADAS 606.2 & 306  Indard: No Quantity: EACH As-built: 1  Knee clearance not min. 27" high, 19" deep or 30" wide  25" high knee clearance  Replace cabinet and remount sink  1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AQ   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Sink - Exposed Pipes   |
| Code<br>References:     | 2010 ADAS 606.5  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Exposed hot water/drain pipes not insulated or configured so as to protect against contact |
| Findings:               | No insulation provided   |
| Rec. Solution:          | Provide insulation at drain pipes  |
| Barrier Severity:       | 2 Recommended Cost Est \$120.00 Facility Function: Public Status: Open                     |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                     |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AR   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Actuator/Control - Forward Reach Obstructed (10"-25")                                      |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 2  |
| Barrier<br>Description: | Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44"        |
| Findings:               | Paper towel and soap dispensers 45" high and 24" deep over an obstruction 36" high         |
| Rec. Solution:          |  |
| Barrier Severity:       | Relocate control or mechanism to max. 44" high   |
| barrier severity.       |  |
| Implementation          | 3 Hindrance Cost Est \$1,500.00 Facility Function: Public Status: Open                     |



| Field Date:                         | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AS                                   |
|-------------------------------------|--|
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:                           | Floor 1 - Kiewit Materials Performance Lab 0109                                  |
| X Coordinate:                       | N/A Y Coordinate: N/A  |
| Barrier Area:                       | Laboratory Facilities  |
| Barrier Type:                       | Actuator/Control - Side Reach High Unobstructed                                  |
| Code<br>References:                 | 2010 ADAS 305.3  |
| Performance Sta                     | andard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description:             | Control or mechanism not at min. 15" or max. 48" high                            |
| Findings:                           | Purified water dispenser 74" high. Purified filter controls 78" high             |
| Rec. Solution:                      | Relocate control or mechanism to min. 15" or max. 48" high or provide assistance |
| Barrier Severity:                   | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open               |
| Implementation                      | Priority: 2 Implementation Phase: Implementation Date:                           |
| Notes:                              |  |
| Field Date:                         | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AT                                   |
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:                           | Floor 1 - Kiewit Materials Performance Lab 0109                                  |
| X Coordinate:                       | N/A Y Coordinate: N/A  |
| Barrier Area:                       | Laboratory Facilities  |
| Barrier Type:                       | Eye Wash - Bubbler Height  |
| Code<br>References:                 | 2010 ADAS 602.4  |
| Performance Sta                     | andard: No Quantity: JOB As-built: 1   |
| Barrier<br>Description:             | Eye wash bubbler height not max. 36"   |
| Findings:                           | 39" high bubbler   |
|                                     |  |
| Rec. Solution:                      | Reposition eve wash or provide additional eve wash for use in area               |
| Rec. Solution:<br>Barrier Severity: |  |
|                                     | 1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open           |



| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AU  |
|--|---|
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Kiewit Materials Performance Lab 0109   |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  | Laboratory Facilities   |
| Barrier Type:  | Eye Wash - Rim or Countertop  |
| Code<br>References:  | 2010 ADAS 606.3   |
| Performance Sta  | ndard: No Quantity: JOB As-built : 1  |
| Barrier<br>Description:  | No accessible section of counter at max 34" high provided   |
| Findings:  | 36" counter height  |
| Rec. Solution:   | Reposition eve wash or provide additional eve wash for use in area  |
| Barrier Severity:  | 1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open  |
| Implementation   | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:   |   |
| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AV  |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  |   |
|  | Floor 1 - Kiewit Materials Performance Lab 0109   |
| X Coordinate:  | Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A   |
| X Coordinate:<br>Barrier Area:   |   |
|  | N/A Y Coordinate: N/A   |
| Barrier Area:  | N/A Y Coordinate: N/A  Laboratory Facilities  |
| Barrier Area:<br>Barrier Type:<br>Code   | N/A Y Coordinate: N/A  Laboratory Facilities  Eye Wash - Knee Clearance  2010 ADAS 602.2 & 306  |
| Barrier Area:<br>Barrier Type:<br>Code<br>References:  | N/A Y Coordinate: N/A  Laboratory Facilities  Eye Wash - Knee Clearance  2010 ADAS 602.2 & 306  |
| Barrier Area:<br>Barrier Type:<br>Code<br>References:<br>Performance Sta<br>Barrier                        | N/A  Y Coordinate: N/A  Laboratory Facilities  Eye Wash - Knee Clearance  2010 ADAS 602.2 & 306  ndard: No Quantity: EACH As-built: 1   |
| Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | N/A  Laboratory Facilities  Eye Wash - Knee Clearance  2010 ADAS 602.2 & 306  ndard: No Quantity: EACH As-built: 1  Knee clearance not min. 27" high, 19" deep or 30" wide  |
| Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | N/A  Laboratory Facilities  Eye Wash - Knee Clearance  2010 ADAS 602.2 & 306  ndard: No Quantity: EACH As-built: 1  Knee clearance not min. 27" high, 19" deep or 30" wide  25" high knee clearance   |
| Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | N/A  Laboratory Facilities  Eye Wash - Knee Clearance  2010 ADAS 602.2 & 306  ndard: No Quantity: EACH As-built: 1  Knee clearance not min. 27" high, 19" deep or 30" wide  25" high knee clearance  Remount eye wash  1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open |



| Field Date:  | 4/37/2047 Papart Data   2/22/2047 Parrier #:   7444   |
|--|---|
|  | 1/27/2017 Report Date   2/22/2017 Barrier #:   7AW   Peferance Durg:   2 - f 2  |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Kiewit Materials Performance Lab 0109   |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  | Laboratory Facilities   |
| Barrier Type:  | Clear Floor Space - Controls  |
| Code<br>References:  | 2010 ADAS 305.3   |
| Performance Sta  | ndard: No Quantity: JOB As-built : 1  |
| Barrier<br>Description:  | Clear floor space of min. 30" by 48" not provided   |
| Findings:  | Blue cabinet blocks clear floor space at fume hood  |
| Rec. Solution:   | Move cabinet to provide access to fume hood   |
| Barrier Severity:  | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open  |
| Implementation   | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:   |   |
| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AX  |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  |   |
|  | Floor 1 - Kiewit Materials Performance Lab 0109   |
| X Coordinate:  |   |
| X Coordinate:<br>Barrier Area:   | Floor 1 - Kiewit Materials Performance Lab 0109   |
|  | Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A   |
| Barrier Area:  | Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities  |
| Barrier Area:<br>Barrier Type:<br>Code   | Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate:  N/A  Laboratory Facilities  Fume Hood - Work Surface Rim  2010 ADAS 902  |
| Barrier Area:<br>Barrier Type:<br>Code<br>References:  | Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate:  N/A  Laboratory Facilities  Fume Hood - Work Surface Rim  2010 ADAS 902  |
| Barrier Area:<br>Barrier Type:<br>Code<br>References:<br>Performance Sta<br>Barrier                        | Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities  Fume Hood - Work Surface Rim  2010 ADAS 902  Indard: No Quantity: EACH As-built: 1  |
| Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate:  N/A  Laboratory Facilities  Fume Hood - Work Surface Rim  2010 ADAS 902  andard:  No  Quantity:  EACH  As-built:  Work surface height exceeds 34" high   |
| Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities  Fume Hood - Work Surface Rim  2010 ADAS 902  Indard: No Quantity: EACH As-built: 1  Work surface height exceeds 34" high  38-1/2" work surface height  Replace workstation or provide alternative accessible workstation  |
| Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities  Fume Hood - Work Surface Rim  2010 ADAS 902  Indard: No Quantity: EACH As-built: 1  Work surface height exceeds 34" high  38-1/2" work surface height  Replace workstation or provide alternative accessible workstation  3 Hindrance Cost Est \$12,450.00 Facility Function: Public Status: Open |



| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AY   |
|--|--|
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:  | Floor 1 - Kiewit Materials Performance Lab 0109  |
| X Coordinate:  | N/A Y Coordinate: N/A  |
| Barrier Area:  | Laboratory Facilities  |
| Barrier Type:  | Fume Hood - Knee Clearance   |
| Code<br>References:  | 2010 ADAS 305.3  |
| Performance Sta  | ndard: No Quantity: EACH As-built : 0  |
| Barrier<br>Description:  | Knee clearance not min. 27" high, 19" deep or 30" wide   |
| Findings:  | 5-1/2" deep knee clearance   |
| Rec. Solution:   | Reposition hood to provide knee clearance  |
| Barrier Severity:  | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open   |
| Implementation   | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:   |  |
| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 7AZ   |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3  |
| =  | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:  | Floor 1 - Kiewit Materials Performance Lab 0109  |
| _  |  |
| Location:  | Floor 1 - Kiewit Materials Performance Lab 0109  |
| Location:<br>X Coordinate:   | Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  |
| Location:<br>X Coordinate:<br>Barrier Area:  | Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate:  N/A  Laboratory Facilities  |
| Location:<br>X Coordinate:<br>Barrier Area:<br>Barrier Type:<br>Code   | Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate:  N/A  Laboratory Facilities  Actuator or Control - Operation  2010 ADAS 305.3  |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate:  N/A  Laboratory Facilities  Actuator or Control - Operation  2010 ADAS 305.3  |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate:  N/A  Laboratory Facilities  Actuator or Control - Operation  2010 ADAS 305.3  ndard:  No  Quantity: EACH  As-built: 2   |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate:  N/A  Laboratory Facilities  Actuator or Control - Operation  2010 ADAS 305.3  ndard:  No  Quantity:  EACH  As-built:  2  Control or mechanism not usable with a closed fist   |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities  Actuator or Control - Operation  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 2  Control or mechanism not usable with a closed fist  Spigots and dials not fist operable  |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Floor 1 - Kiewit Materials Performance Lab 0109  N/A  Y Coordinate: N/A  Laboratory Facilities  Actuator or Control - Operation  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 2  Control or mechanism not usable with a closed fist  Spigots and dials not fist operable  Replace operating control  3 Hindrance Cost Est \$1,500.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 7BA   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 3  |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high  |
| Findings:               | Spigots 58-1/2" high. Fume hood climate control 70" high. Fume hood operation switch 64" high  |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high                                     |
| Barrier Severity:       | 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open                         |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #:   7BB   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Kiewit Materials Performance Lab 0109  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high  |
| Findings:               | Drying rack 10" - 34" high on floor  |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high and mount on wall near sink to faci |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open                           |
| Implementation          |  |
| Notes:                  |  |



| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 8A   |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:   | Floor 1 - Workroom 0109A  |
| X Coordinate:   | N/A Y Coordinate: N/A   |
| Barrier Area:   | Signage   |
| Barrier Type:   | Permanent Room/Space - Tactile Characters   |
| Code<br>References:   | 2010 ADAS 216.2   |
| Performance Sta   | andard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:   | No tactile characters at sign identifying permanent rooms and spaces with visual signs  |
| Findings:   | No tactile signage provided at door within public route   |
| Rec. Solution:  | Provide accessible sign   |
| Barrier Severity:   | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 3 Implementation Phase: Implementation Date:  |
| Notes:  |   |
| Field Date:   | 1/27/2017 Papert Data 2/22/2017 Pagrior #: IOD  |
| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 8B   |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
|   |   |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Workroom 0109A  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Workroom 0109A  N/A  Y Coordinate: N/A  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Workroom 0109A  N/A  Y Coordinate: N/A  Laboratory Facilities   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Workroom 0109A N/A Y Coordinate: N/A Laboratory Facilities Doors - Vision Lights 2010 ADAS 404.2.11   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Workroom 0109A N/A Y Coordinate: N/A Laboratory Facilities Doors - Vision Lights 2010 ADAS 404.2.11   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Workroom 0109A N/A Y Coordinate: N/A Laboratory Facilities Doors - Vision Lights 2010 ADAS 404.2.11  Indard: No Quantity: EACH As-built: 1  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Workroom 0109A N/A Y Coordinate: N/A  Laboratory Facilities Doors - Vision Lights 2010 ADAS 404.2.11  Indard: No Quantity: EACH As-built: 1  View panels in or adjacent to doors or gates not max. 43" above floor or ground  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Workroom 0109A N/A Y Coordinate: N/A Laboratory Facilities Doors - Vision Lights 2010 ADAS 404.2.11  view panels in or adjacent to doors or gates not max. 43" above floor or ground  S4" high  Replace door/gate or vision panel   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Workroom 0109A  N/A  Y Coordinate: N/A  Laboratory Facilities  Doors - Vision Lights  2010 ADAS 404.2.11  Indard: No Quantity: EACH As-built: 1  View panels in or adjacent to doors or gates not max. 43" above floor or ground  54" high  Replace door/gate or vision panel  3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8C                        |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Workroom 0109A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed                      |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                               |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high                |
| Findings:               | Thermostat 52" high  |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high           |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8D                        |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Workroom 0109A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Sink - Rim or Countertop   |
| Code<br>References:     | 2010 ADAS 606.3  |
| Performance Sta         | andard: No Quantity: LF As-built: 1                                  |
| Barrier<br>Description: | Sink rim or surface not max. 34" high                                |
| Findings:               | 36" high   |
| Rec. Solution:          | Reposition existing sink or provide additional sink for use in area  |
| Barrier Severity:       | 1 Necessary Cost Est \$370.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |



| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 8E  |
|--|--|
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:  | Floor 1 - Workroom 0109A   |
| X Coordinate:  | N/A Y Coordinate: N/A  |
| Barrier Area:  | Laboratory Facilities  |
| Barrier Type:  | Sink - Knee Clearance  |
| Code<br>References:  | 2010 ADAS 606.2 & 306  |
| Performance Sta  | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:  | Knee clearance not min. 27" high, 19" deep or 30" wide   |
| Findings:  | No knee clearance  |
| Rec. Solution:   | Replace cabinet and remount sink   |
| Barrier Severity:  | 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open   |
| Implementation   | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:   |  |
| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 8F  |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:  | Floor 1 - Workroom 0109A   |
| X Coordinate:  | N/A Y Coordinate: N/A  |
|  |  |
| Barrier Area:  | Laboratory Facilities  |
| Barrier Area:<br>Barrier Type:   | Laboratory Facilities  Actuator/Control - Side Reach High Unobstructed   |
|  |  |
| Barrier Type:<br>Code  | Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3  |
| Barrier Type:<br>Code<br>References:   | Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3  |
| Barrier Type:<br>Code<br>References:<br>Performance Sta<br>Barrier                           | Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  Indard: No Quantity: EACH As-built: 1  |
| Barrier Type: Code References: Performance Sta Barrier Description:                          | Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  Indard: No Quantity: EACH As-built: 1  Control or mechanism not at min. 15" or max. 48" high   |
| Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  Indard: No Quantity: EACH As-built: 1  Control or mechanism not at min. 15" or max. 48" high  Soap dispenser 43" high and 29" deep  Relocate control or mechanism to min. 15" or max. 48" high   |
| Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  Indard: No Quantity: EACH As-built: 1  Control or mechanism not at min. 15" or max. 48" high  Soap dispenser 43" high and 29" deep  Relocate control or mechanism to min. 15" or max. 48" high  3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8G                          |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                  |
| Location:               | Floor 1 - Workroom 0109A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Eye Wash - Bubbler Height  |
| Code<br>References:     | 2010 ADAS 602.4  |
| Performance Sta         | andard: No Quantity: JOB As-built : 1                                  |
| Barrier<br>Description: | Eye wash bubbler height not max. 36"                                   |
| Findings:               | Emergency eye wash control 40" high                                    |
| Rec. Solution:          | Reposition eve wash or provide additional eve wash for use in area     |
| Barrier Severity:       | 1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                 |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8H                          |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                  |
| Location:               | Floor 1 - Workroom 0109A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Eye Wash - Rim or Countertop   |
| Code<br>References:     | 2010 ADAS 606.3  |
| Performance Sta         | andard: No Quantity: JOB As-built: 0                                   |
| Barrier<br>Description: | No accessible section of counter at max 34" high provided              |
| Findings:               | Emergency eye wash mounted on 36" counter height                       |
| Rec. Solution:          | Reposition eve wash or provide additional eve wash for use in area     |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open     |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                 |
| Notes:                  |  |



| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 8I   |
|--|---|
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Workroom 0109A  |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  | Laboratory Facilities   |
| Barrier Type:  | Eye Wash - Knee Clearance   |
| Code<br>References:  | 2010 ADAS 602.2 & 306   |
| Performance Sta  | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:  | Knee clearance not min. 27" high, 19" deep or 30" wide  |
| Findings:  | Emergency eye wash has no knee clearance  |
| Rec. Solution:   | Remount eve wash  |
| Barrier Severity:  | 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open  |
| Implementation   | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:   |   |
| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 8J   |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  |   |
|  | Floor 1 - Workroom 0109A  |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| X Coordinate:<br>Barrier Area:   |   |
|  | N/A Y Coordinate: N/A   |
| Barrier Area:  | N/A Y Coordinate: N/A  Laboratory Facilities  |
| Barrier Area:<br>Barrier Type:<br>Code   | N/A Y Coordinate: N/A  Laboratory Facilities  Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  |
| Barrier Area:<br>Barrier Type:<br>Code<br>References:  | N/A Y Coordinate: N/A  Laboratory Facilities  Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  |
| Barrier Area: Barrier Type: Code References: Performance Sta   | N/A  Y Coordinate: N/A  Laboratory Facilities  Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 1   |
| Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | N/A  Y Coordinate: N/A  Laboratory Facilities  Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 1  Control or mechanism not at min. 15" or max. 48" high  |
| Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | N/A  Laboratory Facilities  Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 1  Control or mechanism not at min. 15" or max. 48" high  Drying rack 45" - 72" high   |
| Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | N/A  Laboratory Facilities  Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 1  Control or mechanism not at min. 15" or max. 48" high  Drying rack 45" - 72" high  Relocate control or mechanism to min. 15" or max. 48" high  3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8K   |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Workroom 0109A  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed   |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | andard: No Quantity: EACH As-built : 0  |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high                                       |
| Findings:               | Prepack 1, purified water dispenser, and Elix controls 60" - 83" high                       |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high or provide assistance            |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open                          |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                      |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8L   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Workroom 0109A  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Electrical Outlets - Forward Reach Obstructed (10"-25")                                     |
| Code<br>References:     | 2010 ADAS 306.3.2   |
| Performance Sta         | andard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Outlet located over an 10" to 25" obstruction max. 34" high located above 44"               |
| Findings:               | 67" high and 30" deep over an obstruction 36" high  |
| Rec. Solution:          | Relocate control or mechanism to max. 44" high or provide additional outlet in general area |
| Barrier Severity:       | 2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open                      |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                      |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8M                           |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                   |
| Location:               | Floor 1 - Workroom 0109A  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Clear Floor Space - Controls  |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | ndard: No Quantity: JOB As-built : 1                                    |
| Barrier<br>Description: | Clear floor space of min. 30" by 48" not provided                       |
| Findings:               | Stored lab equipment blocks clear floor space at fume hood              |
| Rec. Solution:          | Move stored items at control or mechanism                               |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open      |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                  |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8N                           |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                   |
| Location:               | Floor 1 - Workroom 0109A  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Fume Hood - Work Surface Rim  |
| Code<br>References:     | 2010 ADAS 902   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                   |
| Barrier<br>Description: | Work surface height exceeds 34" high                                    |
| Findings:               | 38" work surface height   |
| Rec. Solution:          | Replace workstation or provide alternative accessible workstation       |
| Barrier Severity:       | 3 Hindrance Cost Est \$12,450.00 Facility Function: Public Status: Open |
| Implementation          |   |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 80                          |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                  |
| Location:               | Floor 1 - Workroom 0109A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Fume Hood - Knee Clearance   |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 0                                 |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide                 |
| Findings:               | 5-1/2" deep knee clearance   |
| Rec. Solution:          | Reposition hood to provide knee clearance                              |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open     |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                 |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8P                          |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                  |
| Location:               | Floor 1 - Workroom 0109A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Actuator or Control - Operation  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | andard: No Quantity: EACH As-built: 3                                  |
| Barrier<br>Description: | Control or mechanism not usable with a closed fist                     |
| Findings:               | Spigots and dials not fist operable                                    |
| Rec. Solution:          | Replace operating control  |
| Barrier Severity:       | 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                 |
| Notes:                  |  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8Q                                       |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Workroom 0109A  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed                                     |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 3   |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high                               |
| Findings:               | Spigots 56" high. Fume hood climate control 69" high. Fume hood switch 67-1/2" high |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high                          |
| Barrier Severity:       | 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open              |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8R                                       |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Workroom 0109A  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed                                     |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high                               |
| Findings:               | Vacuum pump 56" high  |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high or provide assistance    |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open                  |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8S                        |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Workroom 0109A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Counters and Tables  |
| Barrier Type:           | Table - Surface Height   |
| Code<br>References:     | 2010 ADAS 902.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                               |
| Barrier<br>Description: | Surface height exceeds 34" high                                      |
| Findings:               | 36" surface height   |
| Rec. Solution:          | Provide min. 1 accessible table. Avoid pedestal base tables.         |
| Barrier Severity:       | 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8T                        |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Workroom 0109A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Counters and Tables  |
| Barrier Type:           | Table - Knee Clearance   |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | andard: No Quantity: EACH As-built: 1                                |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide               |
| Findings:               | Stored items block knee clearance                                    |
| Rec. Solution:          | Move stored objects  |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open   |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8U                                    |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Workroom 0109A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Clear Floor Space - Controls   |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | ndard: No Quantity: JOB As-built : 1   |
| Barrier<br>Description: | Clear floor space of min. 30" by 48" not provided                                |
| Findings:               | Gas tanks block carbon dioxide incubator   |
| Rec. Solution:          | Move stored items at control or mechanism  |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open               |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8V                                    |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Workroom 0109A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Actuator/Control - Forward Reach High Unobstructed                               |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high                            |
| Findings:               | Carbon dioxide incubator control 65-1/2" high. Two gas tank 55" high             |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high or provide assistance |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open               |
| Implementation          |  |
| mpiementation           | Priority: 2 Implementation Phase: Implementation Date:                           |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8W                          |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                  |
| Location:               | Floor 1 - Workroom 0109A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Sink - 30" x 48" Clearance   |
| Code<br>References:     | 2010 ADAS 305  |
| Performance Sta         | andard: No Quantity: EACH As-built : 0                                 |
| Barrier<br>Description: | Sink lacks 30" x 48" clear floor space                                 |
| Findings:               | Air gas tanks block clear floor space at sink                          |
| Rec. Solution:          | Remove tanks   |
| Barrier Severity:       | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open   |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                 |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8X                          |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                  |
| Location:               | Floor 1 - Workroom 0109A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Sink - Rim or Countertop   |
| Code<br>References:     | 2010 ADAS 606.3  |
| Performance Sta         | andard: No Quantity: LF As-built: 3                                    |
| Barrier<br>Description: | Sink rim or surface not max. 34" high                                  |
| Findings:               | 36-1/2" high   |
| Rec. Solution:          | Reposition existing sink or provide additional sink for use in area    |
| Barrier Severity:       | 1 Necessary Cost Est \$1,110.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                 |
| Notes:                  |  |



| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 8Y  |
|---|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:   | Floor 1 - Workroom 0109A   |
| X Coordinate:   | N/A Y Coordinate: N/A  |
| Barrier Area:   | Laboratory Facilities  |
| Barrier Type:   | Sink - Knee Clearance  |
| Code<br>References:   | 2010 ADAS 606.2 & 306  |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:   | Knee clearance not min. 27" high, 19" deep or 30" wide   |
| Findings:   | No knee clearance  |
| Rec. Solution:  | Replace cabinet and remount sink   |
| Barrier Severity:   | 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open   |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:  |  |
|   |  |
| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 8Z  |
| Field Date:<br>Bldg Name:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 8Z  Merryfield Hall Reference Dwg: 2 of 3   |
|   |  |
| Bldg Name:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Workroom 0109A  N/A  Y Coordinate: N/A   |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Workroom 0109A   |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Workroom 0109A  N/A  Y Coordinate: N/A   |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Workroom 0109A  N/A  Y Coordinate: N/A  Laboratory Facilities  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Workroom 0109A  N/A  Y Coordinate: N/A  Laboratory Facilities  Actuator/Control - Forward Reach Obstructed (10"-25")  2010 ADAS 305.3  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Workroom 0109A  N/A  Y Coordinate: N/A  Laboratory Facilities  Actuator/Control - Forward Reach Obstructed (10"-25")  2010 ADAS 305.3  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Workroom 0109A  N/A  Y Coordinate: N/A  Laboratory Facilities  Actuator/Control - Forward Reach Obstructed (10"-25")  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 2  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Workroom 0109A  N/A  Y Coordinate: N/A  Laboratory Facilities  Actuator/Control - Forward Reach Obstructed (10"-25")  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 2  Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44"  Paper towel and soap dispensers 43" - 45" high and 28" - 29" deep over an obstruction 36-1/2"  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Workroom 0109A N/A Y Coordinate: N/A Laboratory Facilities Actuator/Control - Forward Reach Obstructed (10"-25") 2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 2  Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44"  Paper towel and soap dispensers 43" - 45" high and 28" - 29" deep over an obstruction 36-1/2" high  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Workroom 0109A  N/A  Y Coordinate: N/A  Laboratory Facilities  Actuator/Control - Forward Reach Obstructed (10"-25")  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 2  Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44"  Paper towel and soap dispensers 43" - 45" high and 28" - 29" deep over an obstruction 36-1/2" high  Relocate control or mechanism to max. 44" high  3 Hindrance Cost Est \$1,500.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8AA   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Workroom 0109A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Actuator/Control - Forward Reach Obstructed (10"-25")  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 2   |
| Barrier<br>Description: | Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44"                |
| Findings:               | Spigots 47" high and 22" deep, ACCU Jet Pro 50" high and 24" deep over an obstruction 36-1/2" high |
| Rec. Solution:          | Relocate control or mechanism to max. 44" high   |
| Barrier Severity:       | 3 Hindrance Cost Est \$1,500.00 Facility Function: Public Status: Open                             |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8AB   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Workroom 0109A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Electrical Outlets - Forward Reach Obstructed (10"-25")  |
| Code<br>References:     | 2010 ADAS 306.3.2  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Outlet located over an 10" to 25" obstruction max. 34" high located above 44"                      |
| Findings:               | 45" high and 34" deep over an obstruction 36-1/2" high   |
| Rec. Solution:          | Relocate control or mechanism to max. 44" high   |
| Barrier Severity:       | 2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open                             |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:                  |  |



| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 8AC  |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:   | Floor 1 - Workroom 0109A  |
| X Coordinate:   | N/A Y Coordinate: N/A   |
| Barrier Area:   | Laboratory Facilities   |
| Barrier Type:   | Workstation - Ratio   |
| Code<br>References:   | 2010 ADAS 902   |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:   | At least 1 table or 5% of all workstations is not accessible  |
| Findings:   | 4 computer workstations provided and none are accessible  |
| Rec. Solution:  | Provide min. 1 accessible workstation at each type of essential work area   |
| Barrier Severity:   | 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes: 4 comp   | uter workstations. 1 large center workstation   |
| Field Date:   |   |
| ricia bate.   | 1/27/2017 Report Date 2/22/2017 Barrier #: 8AD  |
| Bldg Name:  | 1/27/2017   Report Date   2/22/2017   Barrier #:   8AD     Merryfield Hall   Reference Dwg:   2 of 3  |
|   |   |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Workroom 0109A  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Workroom 0109A  N/A  Y Coordinate: N/A  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Workroom 0109A  N/A  Y Coordinate: N/A  Laboratory Facilities   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Workroom 0109A  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Surface  2010 ADAS 902   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Workroom 0109A  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Surface  2010 ADAS 902   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Workroom 0109A  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Surface  2010 ADAS 902  ndard: No Quantity: EACH As-built: 1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Workroom 0109A  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Surface  2010 ADAS 902  Indard: No Quantity: EACH As-built: 1  Table or workstation surface height exceeds 34" high   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Workroom 0109A N/A Y Coordinate: N/A Laboratory Facilities Workstation - Surface 2010 ADAS 902  Indard: No Quantity: EACH As-built: 1 Table or workstation surface height exceeds 34" high  36-1/2" workstation surface height at 3 workstation seating areas   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Workroom 0109A  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Surface  2010 ADAS 902  Indard: No Quantity: EACH As-built: 1  Table or workstation surface height exceeds 34" high  36-1/2" workstation surface height at 3 workstation seating areas  Provide min. 1 accessible workstation of each type or overall 5%  3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8AE                                |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Workroom 0109A  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Electrical Outlets - Forward Reach Obstructed (10"-25")                       |
| Code<br>References:     | 2010 ADAS 306.3.2   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Outlet located over an 10" to 25" obstruction max. 34" high located above 44" |
| Findings:               | 45" high and 30-1/2" deep over an obstruction 36-1/2" high                    |
| Rec. Solution:          | Relocate control or mechanism to max. 44" high                                |
| Barrier Severity:       | 2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open        |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                        |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8AF                                |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Workroom 0109A  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed                               |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high                         |
| Findings:               | Printer 51-1/2" high  |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high                    |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open          |
| Implementation          |   |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8AG                                      |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Workroom 0109A  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Shelves or Cabinet  |
| Code<br>References:     | 2010 ADAS 603.4   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Shelf or cabinet not mounted between 40" and 48" above floor or ground              |
| Findings:               | 59" - 73" high  |
| Rec. Solution:          | Provide additional shelf/cabinet at accessible height or provide assistance         |
| Barrier Severity:       | 2 Recommended Cost Est \$75.00 Facility Function: Public Status: Open               |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8AH                                      |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Workroom 0109A  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Actuator/Control - Forward Reach Obstructed (10"-25")                               |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44" |
| Findings:               | Ultrasonic bath controls 49-1/2" high and 20" deep over an obstruction 36-1/2" high |
| Rec. Solution:          | Relocate control or mechanism to max. 44" high or provide assistance                |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open                  |
| Implementation          |   |
|                         | Priority: 2 Implementation Phase: Implementation Date:                              |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8AI  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Workroom 0109A  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Actuator/Control - Forward Reach Obstructed (10"-25")   |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 2   |
| Barrier<br>Description: | Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44"                             |
| Findings:               | Spigots 47" high and 30" deep and Metter Toledo controls 52" high and 14" deep over an obstruction 36-1/2" high |
| Rec. Solution:          | Relocate control or mechanism to max. 44" high  |
| Barrier Severity:       | 3 Hindrance Cost Est \$1,500.00 Facility Function: Public Status: Open  |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8AJ  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Workroom 0109A  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed   |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high   |
| Findings:               | Airgas tank 61" high  |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high or provide assistance                                |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open  |
| Implementation          |   |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8AK                                   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Workroom 0109A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed                                  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 0  |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high                            |
| Findings:               | TGA Q50 machine controls 60" high. DCS machine controls 53" high                 |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high or provide assistance |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open               |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8AL                                   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Workroom 0109A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Shelves or Cabinet   |
| Code<br>References:     | 2010 ADAS 603.4  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Shelf or cabinet not mounted between 40" and 48" above floor or ground           |
| Findings:               | 69" - 88" high   |
| Rec. Solution:          | Provide additional shelf/cabinet at accessible height or provide assistance      |
| Barrier Severity:       | 2 Recommended Cost Est \$75.00 Facility Function: Public Status: Open            |
| Implementation          |  |
| Notes:                  | Priority: 2 Implementation Phase: Implementation Date:                           |



| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 8AM  |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:   | Floor 1 - Workroom 0109A  |
| X Coordinate:   | N/A Y Coordinate: N/A   |
| Barrier Area:   | Laboratory Facilities   |
| Barrier Type:   | Sink - Rim or Countertop  |
| Code<br>References:   | 2010 ADAS 606.3   |
| Performance Sta   | ndard: No Quantity: LF As-built : 3   |
| Barrier<br>Description:   | Sink rim or surface not max. 34" high   |
| Findings:   | 36" high  |
| Rec. Solution:  | Reposition existing sink or provide additional sink for use in area   |
| Barrier Severity:   | 1 Necessary Cost Est \$1,110.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:  |   |
| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 8AN  |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:   | Floor 1 - Workroom 0109A  |
| X Coordinate:   | N/A Y Coordinate: N/A   |
| Barrier Area:   | Laboratory Facilities   |
| Barrier Type:   | Sink - Knee Clearance   |
| Code<br>References:   | 2010 ADAS 606.2 & 306   |
| nercicites.   |   |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1   |
|   | ndard: No Quantity: EACH As-built: 1  Knee clearance not min. 27" high, 19" deep or 30" wide                                |
| Performance Sta<br>Barrier  |   |
| Performance Sta<br>Barrier<br>Description:<br>Findings:                   | Knee clearance not min. 27" high, 19" deep or 30" wide  |
| Performance Sta<br>Barrier<br>Description:<br>Findings:                   | Knee clearance not min. 27" high, 19" deep or 30" wide  No knee clearance   |
| Performance Sta<br>Barrier<br>Description:<br>Findings:<br>Rec. Solution: | No knee clearance  Replace cabinet and remount sink  1 Necessary  Cost Est \$450.00  Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8AO                       |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Workroom 0109A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Workstation - Surface  |
| Code<br>References:     | 2010 ADAS 902  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                |
| Barrier<br>Description: | Table or workstation surface height exceeds 34" high                 |
| Findings:               | 36" workstation surface height at shared central workstation         |
| Rec. Solution:          | Provide min. 1 accessible workstation of each type or overall 5%     |
| Barrier Severity:       | 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 8AP                       |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Workroom 0109A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Workstation - Knee Clearance   |
| Code<br>References:     | 2010 ADAS 902  |
| Performance Sta         | ndard: No Quantity: EACH As-built: 1                                 |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide               |
| Findings:               | No knee clearance  |
| Rec. Solution:          | Provide min. 1 accessible workstation of each type or overall 5%     |
| Barrier Severity:       | 1 Necessary Cost Est \$875.00 Facility Function: Public Status: Open |
| Implementation          |  |
| Notes:                  |  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9A  |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Signage  |
| Barrier Type:           | ISA - Accessible Entry Door  |
| Code<br>References:     | 2010 ADAS 216.6  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | No sign identifying door as accessible where all doors are not accessible                |
| Findings:               | No sign provided to indicate that east entrance is accessible at east entrance door      |
| Rec. Solution:          | Provide ISA at accessible entrance door  |
| Barrier Severity:       | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open                     |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                                   |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9B  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Door Closer - Exterior Automatic Door  |
| Code<br>References:     | Performance Standard   |
| Performance Sta         | ndard: Yes Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Door opening force exceeds 8.5 lbf   |
| Findings:               | 14 lbf and door landing slope at 3.3% at east entrance door                              |
| Rec. Solution:          | Provide automatic door opening device at one door and ISA directional sign at other door |
| Barrier Severity:       |  |
|                         | 1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open                   |
| Implementation          |  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9C  |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Door Closer - Exterior Sweep Period  |
| Code<br>References:     | 2010 ADAS 404.2.8.1  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Door closer lacks min. 5 second sweep period   |
| Findings:               | 2 second sweep at east entrance door   |
| Rec. Solution:          | Provide automatic door opening device at one door and ISA directional sign at other door |
| Barrier Severity:       | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open                     |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                   |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9D  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Hardware - Operation   |
| Code<br>References:     | 2010 ADAS 404.2.7  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Hardware not operable with a closed fist   |
| Findings:               | Door hardware not operable with a closed fist at east entrance door                      |
| Rec. Solution:          | Provide new hardware   |
| Barrier Severity:       | 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open                     |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                   |
| Notes:                  |  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9E                                   |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Doors or Gates  |
| Barrier Type:           | Vision Lights - Existing  |
| Code<br>References:     | 2010 ADAS 404.2.11  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | View panels in or adjacent to doors or gates not max. 43" above floor or ground |
| Findings:               | 43-1/2" high at east entrance door  |
| Rec. Solution:          | Replace door/gate or vision panel   |
| Barrier Severity:       | 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open          |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                          |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9F                                   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Doors or Gates  |
| Barrier Type:           | Door 10" Bottom Surface - Kickplate   |
| Code<br>References:     | 2010 ADAS 404.2.10  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Door/Gate lacks min. 10" smooth uninterrupted bottom surface                    |
| Findings:               | 9-1/2" high indented panel in door at east entrance door                        |
| Rec. Solution:          | Provide smooth kick plate min. 10" high at push side of door                    |
| Barrier Severity:       | 1 Necessary Cost Est \$225.00 Facility Function: Public Status: Open            |
| Implementation          |   |
| Notes:                  | Filolity. 2 implementation Filase.  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9G                                  |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Clear Width  |
| Code<br>References:     | 2010 ADAS 404.2.3  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Clear width passage through door, sliding/folding door or gate is not min. 32" |
| Findings:               | 30" wide at east entrance door   |
| Rec. Solution:          | Replace door or gate and frame   |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open             |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                         |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9H                                  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Threshold - Height exceeding 1/2"  |
| Code<br>References:     | 2010 ADAS 404.2.5  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Door/Gate threshold exceeds 1/2" in height                                     |
| Findings:               | 5/8" high at east entrance door  |
| Rec. Solution:          | Provide new door threshold   |
| Barrier Severity:       | 1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open           |
| Implementation          |  |
| Notes:                  |  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 91   |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Doors or Gates  |
| Barrier Type:           | Headroom - Existing   |
| Code<br>References:     | 2010 ADAS 404.2.3   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Door/Gate clearance not min. 80" high   |
| Findings:               | 78-1/2" high at east entrance door  |
| Rec. Solution:          | Replace door or gate  |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open                      |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                  |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9J   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Signage   |
| Barrier Type:           | Tactile Exit Signs - Door   |
| Code<br>References:     | 2010 ADAS 216.4.1   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Ground floor doors that exit to exterior lacks tactile exit sign                        |
| Findings:               | Exit door with low level illuminated sign lacks tactile exit sign at east entrance door |
| Rec. Solution:          | Provide sign stating "EXIT" at exit side of door  |
| Barrier Severity:       | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open                    |
| Implementation          |   |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9K  |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Signage  |
| Barrier Type:           | Permanent Room/Space - Tactile Characters  |
| Code<br>References:     | 2010 ADAS 216.2  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | No tactile characters at sign identifying permanent rooms and spaces with visual signs |
| Findings:               | No tactile signage provided at door within public route at west entrance door          |
| Rec. Solution:          | Provide accessible sign at second door leading to classroom                            |
| Barrier Severity:       | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open                   |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                                 |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9L  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Signage  |
| Barrier Type:           | ISA - Non-Accessible Entry   |
| Code<br>References:     | 2010 ADAS 216.6  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Sign directing people to accessible entrance needed where all doors are not accessible |
| Findings:               | ISA directional sign not provided at second entry to classroom (west entrance door)    |
| Rec. Solution:          | Provide ISA directional sign with arrow directing people to accessible entrance        |
| Barrier Severity:       | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open                   |
| Implementation          |  |
| Notes:                  |  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9M                                   |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Doors or Gates  |
| Barrier Type:           | Hardware - Operation  |
| Code<br>References:     | 2010 ADAS 404.2.7   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Hardware not operable with a closed fist  |
| Findings:               | Door hardware not operable with a closed fist at west entrance door             |
| Rec. Solution:          | Provide new hardware  |
| Barrier Severity:       | 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open            |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                          |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9N                                   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Doors or Gates  |
| Barrier Type:           | Clear Width   |
| Code<br>References:     | 2010 ADAS 404.2.3   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Clear width passage through door, sliding/folding door or gate is not min. 32"  |
| Findings:               | 29" wide at west entrance door  |
| Rec. Solution:          | Provide ISA directional sign with arrow directing people to accessible entrance |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open              |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                          |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 90                                   |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Doors or Gates  |
| Barrier Type:           | Threshold - Height exceeding 1/2"   |
| Code<br>References:     | 2010 ADAS 404.2.5   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Door/Gate threshold exceeds 1/2" in height                                      |
| Findings:               | 5/8" lip at west entrance door  |
| Rec. Solution:          | Provide new door threshold  |
| Barrier Severity:       | 1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open            |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                          |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9P                                   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Doors or Gates  |
| Barrier Type:           | Headroom - Existing   |
| Code<br>References:     | 2010 ADAS 404.2.3   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Door/Gate clearance not min. 80" high   |
| Findings:               | 79" high at west entrance door  |
| Rec. Solution:          | Provide ISA directional sign with arrow directing people to accessible entrance |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open              |
| Implementation          |   |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9Q   |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Doors or Gates  |
| Barrier Type:           | Front App/pull 18" SEC - Relocate Door  |
| Code<br>References:     | 2010 ADAS Figure 404.2.4.1  |
| Performance Sta         | ndard: No Quantity: EACH As-built: 1  |
| Barrier<br>Description: | Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side  |
| Findings:               | 7-1/2" strike edge clearance  |
| Rec. Solution:          | Provide automatic door opening device at one door and ISA sign at other door            |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open                      |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                  |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9R   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Signage   |
| Barrier Type:           | Tactile Exit Signs - Door   |
| Code<br>References:     | 2010 ADAS 216.4.1   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Ground floor doors that exit to exterior lacks tactile exit sign                        |
| Findings:               | Exit door with low level illuminated sign lacks tactile exit sign at west entrance door |
| Rec. Solution:          | Provide sign stating "EXIT" at exit side of door  |
| Barrier Severity:       | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open                    |
| Implementation          |   |
| Notes:                  | Priority: 3 Implementation Phase: Implementation Date:                                  |



| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9S   |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:   | Floor 1 - Classroom 0108  |
| X Coordinate:   | N/A Y Coordinate: N/A   |
| Barrier Area:   | Laboratory Facilities   |
| Barrier Type:   | Electrical Switches - High Unobstructed   |
| Code<br>References:   | 2010 ADAS 308.2.1   |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:   | Light switch control box top edge not at max. 48" high  |
| Findings:   | 50" high  |
| Rec. Solution:  | Relocate switch box top edge to max. 48" high   |
| Barrier Severity:   | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:  |   |
|   |   |
| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9T   |
| Field Date:<br>Bldg Name:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9T  Merryfield Hall Reference Dwg: 2 of 3  |
|   |   |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Classroom 0108  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Alarms  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Alarms  Fire Pull - Operation  2010 ADAS 309.4  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Alarms  Fire Pull - Operation  2010 ADAS 309.4  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Alarms  Fire Pull - Operation  2010 ADAS 309.4  ndard: No Quantity: EACH As-built: 1  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Alarms  Fire Pull - Operation  2010 ADAS 309.4  Indard: No Quantity: EACH As-built: 1  Fire pull has no fist operable hardware   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Classroom 0108 N/A Y Coordinate: N/A Alarms Fire Pull - Operation 2010 ADAS 309.4  mdard: No Quantity: EACH As-built: 1  Fire pull has no fist operable hardware  Fire pull not fist operable  Replace fire pull when remodeling  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Alarms  Fire Pull - Operation  2010 ADAS 309.4  Indard: No Quantity: EACH As-built: 1  Fire pull has no fist operable hardware  Fire pull not fist operable  Replace fire pull when remodeling  A Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9U   |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Alarms  |
| Barrier Type:           | Fire Pull - Height  |
| Code<br>References:     | 2010 ADAS 308.2.2   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description: | Fire pulls not between 42" and 48" high   |
| Findings:               | 67" high  |
| Rec. Solution:          | Replace fire pull when remodeling   |
| Barrier Severity:       | 4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open                       |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                                      |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9V   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Protruding Object   |
| Code<br>References:     | 2010 ADAS 307.2   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Wall mounted object (dispensers) protrudes more than 4" from wall                           |
| Findings:               | Mechanical box protrudes 4-1/2" at 66-1/4" high   |
| Rec. Solution:          | Relocate. remove object (dispenser) or provide detectable warning for the visually impaired |
| Barrier Severity:       | 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open                        |
| Implementation          |   |
|                         | Priority: 1 Implementation Phase: Implementation Date:                                      |



| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 9W   |
|--|---|
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Classroom 0108  |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  | Laboratory Facilities   |
| Barrier Type:  | Door Landing - Level  |
| Code<br>References:  | 2010 ADAS 404.2.4.4   |
| Performance Sta  | ndard: No Quantity: SF As-built : 40  |
| Barrier<br>Description:  | Door landing is not level on both sides of door   |
| Findings:  | 14.3% slope at door landing to Room 109   |
| Rec. Solution:   | Demolish and reconstruct level landing  |
| Barrier Severity:  | 1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open  |
| Implementation   | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:   |   |
| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 9X   |
|  |   |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Bldg Name:<br>Location:  | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Classroom 0108  |
|  |   |
| Location:  | Floor 1 - Classroom 0108  |
| Location:<br>X Coordinate:   | Floor 1 - Classroom 0108  N/A Y Coordinate: N/A   |
| Location:<br>X Coordinate:<br>Barrier Area:  | Floor 1 - Classroom 0108  N/A Y Coordinate: N/A  Stairways  |
| Location:<br>X Coordinate:<br>Barrier Area:<br>Barrier Type:<br>Code   | Floor 1 - Classroom 0108  N/A Y Coordinate: N/A  Stairways  Vertical Access - Lift  2010 ADAS 403.1   |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Stairways  Vertical Access - Lift  2010 ADAS 403.1  |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Stairways  Vertical Access - Lift  2010 ADAS 403.1  Indard: No Quantity: JOB As-built: 0  |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Stairways  Vertical Access - Lift  2010 ADAS 403.1  ndard: No Quantity: JOB As-built: 0  No form of vertical access provided at stairway to reach upper floors  |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Stairways  Vertical Access - Lift  2010 ADAS 403.1  ndard: No Quantity: JOB As-built: 0  No form of vertical access provided at stairway to reach upper floors  No vertical access to loft  |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Stairways  Vertical Access - Lift  2010 ADAS 403.1  ndard: No Quantity: JOB As-built: 0  No form of vertical access provided at stairway to reach upper floors  No vertical access to loft  No remediation recommended. Loft consists of a small storage area less than 5% of total floor s  1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open |



| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 9Y   |
|--|---|
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Classroom 0108  |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  | Stairways   |
| Barrier Type:  | Handrail - Opening Limitations  |
| Code<br>References:  | Performance Standard  |
| Performance Sta  | ndard: Yes Quantity: LF As-built : 10   |
| Barrier<br>Description:  | Guard or handrail have openings that allow passage of a 4" sphere   |
| Findings:  | Guardrail 9" openings   |
| Rec. Solution:   | Replace handrails   |
| Barrier Severity:  | 1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open  |
| Implementation   | Priority: 3 Implementation Phase: Implementation Date:  |
| Notes:   |   |
| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 9Z   |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Classroom 0108  |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  |   |
|  | Laboratory Facilities   |
| Barrier Type:  | Laboratory Facilities  Actuator/Control - Side Reach High Unobstructed  |
| Barrier Type:<br>Code<br>References:   |   |
| Code   | Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3   |
| Code<br>References:  | Actuator/Control - Side Reach High Unobstructed 2010 ADAS 305.3   |
| Code<br>References:<br>Performance Sta<br>Barrier                              | Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 1  |
| Code References: Performance Sta Barrier Description:                          | Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 1  Control or mechanism not at min. 15" or max. 48" high   |
| Code References: Performance Sta Barrier Description: Findings:                | Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 1  Control or mechanism not at min. 15" or max. 48" high  Oven controls 79" high  Relocate control or mechanism to min. 15" or max. 48" high or provide assistance   |
| Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Actuator/Control - Side Reach High Unobstructed  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 1  Control or mechanism not at min. 15" or max. 48" high  Oven controls 79" high  Relocate control or mechanism to min. 15" or max. 48" high or provide assistance  3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open |



| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AA   |
|---|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:   | Floor 1 - Classroom 0108   |
| X Coordinate:   | N/A Y Coordinate: N/A  |
| Barrier Area:   | Laboratory Facilities  |
| Barrier Type:   | Door Hardware - Operation  |
| Code<br>References:   | 2010 ADAS 404.2.7  |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:   | Operating controls involve tight grasping, pinching or twisting  |
| Findings:   | Storage closet hardware not operable with a closed fist  |
| Rec. Solution:  | Replace hardware   |
| Barrier Severity:   | 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open   |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:  |  |
| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AB   |
|   | 1/2//2017 Report Sate  2/22/2017 Sather III   SAB  |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
|   |  |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Classroom 0108   |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A   |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Shelves or Cabinet  2010 ADAS 603.4   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Shelves or Cabinet  2010 ADAS 603.4   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A Y Coordinate: N/A  Laboratory Facilities  Shelves or Cabinet  2010 ADAS 603.4  ndard: No Quantity: EACH As-built: 1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Shelves or Cabinet  2010 ADAS 603.4  ndard: No Quantity: EACH As-built: 1  Shelf or cabinet not mounted between 40" and 48" above floor or ground  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Classroom 0108 N/A Y Coordinate: N/A Laboratory Facilities Shelves or Cabinet 2010 ADAS 603.4  ndard: No Quantity: EACH As-built: 1 Shelf or cabinet not mounted between 40" and 48" above floor or ground  8" - 66-1/2" high  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A Y Coordinate: N/A  Laboratory Facilities  Shelves or Cabinet  2010 ADAS 603.4  As-built: 1  Shelf or cabinet not mounted between 40" and 48" above floor or ground  8" - 66-1/2" high  Provide additional shelf/cabinet at accessible height or provide assistance  2 Recommended Cost Est \$75.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AC   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Sink - 30" x 48" Clearance   |
| Code<br>References:     | 2010 ADAS 305  |
| Performance Sta         | andard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description: | Sink lacks 30" x 48" clear floor space   |
| Findings:               | 44" clear floor space at sink measured to stored stacks of pails   |
| Rec. Solution:          | Remove obstructions  |
| Barrier Severity:       | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open                                     |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AD   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Sink - Faucet  |
| Code<br>References:     | 2010 ADAS 606.4 & 309  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Faucets lack controls and operating mechanisms involve tight grasping, pinching or twisting of the wrist |
| Findings:               | Faucet not fist operable   |
| Rec. Solution:          | Replace faucet   |
| Barrier Severity:       | 1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open                                     |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:                  |  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AE                                      |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Actuator/Control - Forward Reach Obstructed (10"-25")                               |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44" |
| Findings:               | Faucet 45" high and 23" deep over an obstruction 37-1/4" high                       |
| Rec. Solution:          | Relocate control or mechanism to max. 44" high                                      |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open                |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AF                                      |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Sink - Rim or Countertop  |
| Code<br>References:     | 2010 ADAS 606.3   |
| Performance Sta         | ndard: No Quantity: LF As-built : 3   |
| Barrier<br>Description: | Sink rim or surface not max. 34" high   |
| Findings:               | 37-1/2" high  |
| Rec. Solution:          | Reposition existing sink or provide additional sink for use in area                 |
| Barrier Severity:       | 1 Necessary Cost Est \$1,110.00 Facility Function: Public Status: Open              |
| Implementation          |   |
| Notes:                  |   |



| Field Date:                         | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AG   |
|-------------------------------------|--|
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:                           | Floor 1 - Classroom 0108   |
| X Coordinate:                       | N/A Y Coordinate: N/A  |
| Barrier Area:                       | Laboratory Facilities  |
| Barrier Type:                       | Sink - Knee Clearance  |
| Code<br>References:                 | 2010 ADAS 606.2 & 306  |
| Performance Sta                     | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:             | Knee clearance not min. 27" high, 19" deep or 30" wide                                     |
| Findings:                           | 22-1/2" high knee clearance  |
| Rec. Solution:                      | Replace cabinet and remount sink   |
| Barrier Severity:                   | 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open                       |
| Implementation                      | Priority: 2 Implementation Phase: Implementation Date:                                     |
| Notes:                              |  |
| Field Date:                         | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AH   |
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:                           | Floor 1 - Classroom 0108   |
| X Coordinate:                       | N/A Y Coordinate: N/A  |
| Barrier Area:                       | Laboratory Facilities  |
| Barrier Type:                       | Sink - Exposed Pipes   |
| Code<br>References:                 | 2010 ADAS 606.5  |
| Performance Sta                     | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:             | Exposed hot water/drain pipes not insulated or configured so as to protect against contact |
| Findings:                           | No insulation provided   |
| Rec. Solution:                      |  |
|                                     | Provide insulation at drain pipes  |
| Barrier Severity:                   |  |
| Barrier Severity:<br>Implementation | 2 Recommended Cost Est \$120.00 Facility Function: Public Status: Open                     |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AI                       |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Workstation - Surface  |
| Code<br>References:     | 2010 ADAS 902  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                               |
| Barrier<br>Description: | Table or workstation surface height exceeds 34" high                 |
| Findings:               | 37-1/2" high workstation surface height                              |
| Rec. Solution:          | Provide min. 1 accessible workstation of each type or overall 5%     |
| Barrier Severity:       | 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes: Sink wo          | rkstation  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AJ                       |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Workstation - Knee Clearance   |
| Code<br>References:     | 2010 ADAS 902  |
| Performance Sta         | andard: No Quantity: EACH As-built: 1                                |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide               |
| Findings:               | 28" wide knee clearance  |
| Rec. Solution:          | Provide min. 1 accessible workstation of each type or overall 5%     |
| Barrier Severity:       | 1 Necessary Cost Est \$875.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |



| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AK  |
|--|---|
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Classroom 0108  |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  | Laboratory Facilities   |
| Barrier Type:  | Counter - Surface   |
| Code<br>References:  | 2010 ADAS 902   |
| Performance Sta  | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:  | Counter or workstation surface height exceeds 34" high  |
| Findings:  | 36" workstation surface height  |
| Rec. Solution:   | Replace table or provide alternative accessible and integrated counter  |
| Barrier Severity:  | 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open  |
| Implementation   | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:   |   |
| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AL  |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Classroom 0108  |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  |   |
|  | Laboratory Facilities   |
| Barrier Type:  |   |
| Barrier Type:<br>Code<br>References:   | Laboratory Facilities   |
| Code   | Laboratory Facilities  Counter - Knee Clearance  2010 ADAS 305.3  |
| Code<br>References:  | Laboratory Facilities  Counter - Knee Clearance  2010 ADAS 305.3  |
| Code<br>References:<br>Performance Sta<br>Barrier                              | Laboratory Facilities  Counter - Knee Clearance  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 1  |
| Code<br>References:<br>Performance Sta<br>Barrier<br>Description:              | Laboratory Facilities  Counter - Knee Clearance  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 1  Knee clearance not min. 27" high, 19" deep or 30" wide  |
| Code References: Performance Sta Barrier Description: Findings:                | Laboratory Facilities  Counter - Knee Clearance  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 1  Knee clearance not min. 27" high, 19" deep or 30" wide  No knee clearance   |
| Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Laboratory Facilities  Counter - Knee Clearance  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 1  Knee clearance not min. 27" high, 19" deep or 30" wide  No knee clearance  Provide min. 3 ft segment of accessible counter. Flip-up counters, adiacent tables and similar de 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AM   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Electrical Outlets - Forward Reach Obstructed (10"-25")  |
| Code<br>References:     | 2010 ADAS 306.3.2  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Outlet located over an 10" to 25" obstruction max. 34" high located above 44"  |
| Findings:               | 40" high and 28-1/2" deep over an obstruction 36" high   |
| Rec. Solution:          | Relocate control or mechanism to max. 44" high   |
| Barrier Severity:       | 2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open   |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AN   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Actuator/Control - Forward Reach Obstructed (≤10")   |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Control or mechanism over an obstruction max. 34" high located above 48"   |
| Findings:               | Mixer 52" high and 15-1/2" deep over an obstruction 36" high   |
| . 0-                    |  |
| Rec. Solution:          | Relocate control or mechanism to max. 48" high or provide assistance   |
| _                       |  |
| Rec. Solution:          | Relocate control or mechanism to max. 48" high or provide assistance  3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AO  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Actuator/Control - Forward Reach Obstructed (≤10")  |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Control or mechanism over an obstruction max. 34" high located above 48"                                |
| Findings:               | Paper towel dispenser and stored lab equipment 44" - 46" high and 30" deep over an obstruction 36" high |
| Rec. Solution:          | Relocate control or mechanism to max. 48" high  |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open                                    |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AP  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Shelves or Cabinet  |
| Code<br>References:     | 2010 ADAS 603.4   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Shelf or cabinet not mounted between 40" and 48" above floor or ground                                  |
| Findings:               | 61" - 72" high  |
| Rec. Solution:          | Provide additional shelf/cabinet at accessible height or provide assistance                             |
| Barrier Severity:       | 2 Recommended Cost Est \$75.00 Facility Function: Public Status: Open                                   |
| Implementation          |   |
| Notes:                  | Priority: 2 Implementation Phase: Implementation Date:  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AQ                              |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                       |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Clear Floor Space - Controls  |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | ndard: No Quantity: JOB As-built : 1  |
| Barrier<br>Description: | Clear floor space of min. 30" by 48" not provided                           |
| Findings:               | Buckets block clear floor space at sieves and tray shelving                 |
| Rec. Solution:          | Move stored items at control or mechanism                                   |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open          |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                      |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AR                              |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                       |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Shelves or Cabinet  |
| Code<br>References:     | 2010 ADAS 603.4   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                       |
| Barrier<br>Description: | Shelf or cabinet not mounted between 40" and 48" above floor or ground      |
| Findings:               | Sieve tray shelving 3" - 60" high   |
| Rec. Solution:          | Provide additional shelf/cabinet at accessible height or provide assistance |
| Barrier Severity:       | 2 Recommended Cost Est \$75.00 Facility Function: Public Status: Open       |
| Implementation          |   |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AS                       |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Workstation - Ratio  |
| Code<br>References:     | 2010 ADAS 902  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                               |
| Barrier<br>Description: | At least 1 table or 5% of all workstations is not accessible         |
| Findings:               | 6 shared workstations with no accessible workstation provided        |
| Rec. Solution:          | Provide min. 1 accessible workstation                                |
| Barrier Severity:       | 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AT                       |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Workstation - Knee Clearance   |
| Code<br>References:     | 2010 ADAS 902  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                               |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide               |
| Findings:               | 9-1/4" deep knee clearance   |
| Rec. Solution:          | Provide min. 1 accessible workstation of each type or overall 5%     |
| Barrier Severity:       | 1 Necessary Cost Est \$875.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AU  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Workstation - Protruding Object   |
| Code<br>References:     | 2010 ADAS 307.2   |
| Performance Sta         | andard: No Quantity: EACH As-built: 3   |
| Barrier<br>Description: | Table creates protruding object in accessible route   |
| Findings:               | Center workstations protrudes 9-1/4" at 32" - 34" high  |
| Rec. Solution:          | Provide detectable warning for the visually impaired or place stools along countertop as detect |
| Barrier Severity:       | 2 Necessary Cost Est \$2,625.00 Facility Function: Public Status: Open                          |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AV  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Electrical Outlets - Forward Reach Obstructed (10"-25")   |
| Code<br>References:     | 2010 ADAS 306.3.2   |
| Performance Sta         | andard: No Quantity: EACH As-built: 1   |
| Barrier<br>Description: | Outlet located over an 10" to 25" obstruction max. 34" high located above 44"                   |
| Findings:               | 36" high and 32" deep over an obstruction 34" high  |
| Rec. Solution:          | Relocate control or mechanism to max. 44" high  |
| Barrier Severity:       | 2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open                          |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:                  |   |



| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AW  |
|--|---|
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Classroom 0108  |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  | Laboratory Facilities   |
| Barrier Type:  | Sink - Knee Clearance   |
| Code<br>References:  | 2010 ADAS 606.2 & 306   |
| Performance Sta  | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:  | Knee clearance not min. 27" high, 19" deep or 30" wide  |
| Findings:  | 23-3/4" high knee clearance with accessible surface height  |
| Rec. Solution:   | Replace cabinet and remount sink  |
| Barrier Severity:  | 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open  |
| Implementation   | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:   |   |
| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AX  |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
|  |   |
| Location:  | Floor 1 - Classroom 0108  |
| Location:<br>X Coordinate:   | Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  |
|  |   |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| X Coordinate:<br>Barrier Area:   | N/A Y Coordinate: N/A  Laboratory Facilities  |
| X Coordinate:<br>Barrier Area:<br>Barrier Type:<br>Code  | N/A Y Coordinate: N/A  Laboratory Facilities  Sink - Exposed Pipes  2010 ADAS 606.5   |
| X Coordinate: Barrier Area: Barrier Type: Code References:   | N/A Y Coordinate: N/A  Laboratory Facilities  Sink - Exposed Pipes  2010 ADAS 606.5   |
| X Coordinate:<br>Barrier Area:<br>Barrier Type:<br>Code<br>References:<br>Performance Sta<br>Barrier                     | N/A Y Coordinate: N/A  Laboratory Facilities  Sink - Exposed Pipes  2010 ADAS 606.5  Indard: No Quantity: EACH As-built: 1  |
| X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | N/A  Laboratory Facilities  Sink - Exposed Pipes  2010 ADAS 606.5  Indard: No Quantity: EACH As-built: 1  Exposed hot water/drain pipes not insulated or configured so as to protect against contact  |
| X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | N/A  Laboratory Facilities  Sink - Exposed Pipes  2010 ADAS 606.5  ndard: No Quantity: EACH As-built: 1  Exposed hot water/drain pipes not insulated or configured so as to protect against contact  No insulation provided  Provide insulation at drain pipes  |
| X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | N/A Y Coordinate: N/A  Laboratory Facilities  Sink - Exposed Pipes  2010 ADAS 606.5  Indard: No Quantity: EACH As-built: 1  Exposed hot water/drain pipes not insulated or configured so as to protect against contact  No insulation provided  Provide insulation at drain pipes  2 Recommended Cost Est \$120.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AY                         |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Eye Wash - Bubbler Height  |
| Code<br>References:     | 2010 ADAS 602.4  |
| Performance Sta         | andard: No Quantity: JOB As-built : 1                                  |
| Barrier<br>Description: | Eye wash bubbler height not max. 36"                                   |
| Findings:               | 44" high   |
| Rec. Solution:          | Reposition eve wash or provide additional eve wash for use in area     |
| Barrier Severity:       | 1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                 |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9AZ                         |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Eye Wash - Knee Clearance  |
| Code<br>References:     | 2010 ADAS 602.2 & 306  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                                 |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide                 |
| Findings:               | 23" high knee clearance  |
| Rec. Solution:          | Remove stored items  |
| Barrier Severity:       | 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open   |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                 |
| Notes:                  |  |



| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BA  |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:   | Floor 1 - Classroom 0108  |
| X Coordinate:   | N/A Y Coordinate: N/A   |
| Barrier Area:   | Laboratory Facilities   |
| Barrier Type:   | Workstation - Surface   |
| Code<br>References:   | 2010 ADAS 902   |
| Performance Sta   | ndard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description:   | Table or workstation surface height exceeds 34" high  |
| Findings:   | 36" workstation surface height at 3 workstation sections in classroom   |
| Rec. Solution:  | Provide min. 2 accessible workstations of each type or overall 5%   |
| Barrier Severity:   | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:  |   |
| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BB  |
|   | 2/22/2017   |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
|   |   |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Knee Clearance  2010 ADAS 902  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Knee Clearance  2010 ADAS 902  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier                                       | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Knee Clearance  2010 ADAS 902  ndard: No Quantity: EACH As-built: 0  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Knee Clearance  2010 ADAS 902  ndard: No Quantity: EACH As-built: 0  Knee clearance not min. 27" high, 19" deep or 30" wide  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Classroom 0108 N/A Y Coordinate: N/A Laboratory Facilities Workstation - Knee Clearance 2010 ADAS 902  ndard: No Quantity: EACH As-built: 0  Knee clearance not min. 27" high, 19" deep or 30" wide  No knee clearance provided at workstations   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Knee Clearance  2010 ADAS 902  March Mo Quantity: EACH As-built: 0  Knee clearance not min. 27" high, 19" deep or 30" wide  No knee clearance provided at workstations  Provide min. 1 accessible workstation of each type or overall 5%  1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BC                                      |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Actuator/Control - Forward Reach Obstructed (10"-25")                               |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | andard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44" |
| Findings:               | Spigots 40-1/2" high and 14-1/2" and 22" deep over an obstruction 36" high          |
| Rec. Solution:          | Relocate control or mechanism to max. 44" high                                      |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open                |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BD                                      |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Electrical Outlets - Forward Reach Obstructed (10"-25")                             |
| Code<br>References:     | 2010 ADAS 306.3.2   |
| Performance Sta         | andard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Outlet located over an 10" to 25" obstruction max. 34" high located above 44"       |
| Findings:               | 38-1/2" high and 32" deep over an obstruction 36" high                              |
| Rec. Solution:          | Relocate control or mechanism to max. 44" high                                      |
| Barrier Severity:       | 2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open              |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BE   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Sink - Faucet  |
| Code<br>References:     | 2010 ADAS 606.4 & 309  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Faucets lack controls and operating mechanisms involve tight grasping, pinching or twisting of the wrist |
| Findings:               | Faucet not fist operable   |
| Rec. Solution:          | Replace faucet   |
| Barrier Severity:       | 1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open                                     |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BF   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Sink - Rim or Countertop   |
| Code<br>References:     | 2010 ADAS 606.3  |
| Performance Sta         | ndard: No Quantity: LF As-built : 1  |
| Barrier<br>Description: | Sink rim or surface not max. 34" high  |
| Findings:               | 36" high   |
| Rec. Solution:          | Reposition existing sink or provide additional sink for use in area                                      |
| Barrier Severity:       |  |
| •                       | 1 Necessary Cost Est \$370.00 Facility Function: Public Status: Open                                     |
| Implementation          |  |



| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BG  |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:   | Floor 1 - Classroom 0108  |
| X Coordinate:   | N/A Y Coordinate: N/A   |
| Barrier Area:   | Laboratory Facilities   |
| Barrier Type:   | Sink - Knee Clearance   |
| Code<br>References:   | 2010 ADAS 606.2 & 306   |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:   | Knee clearance not min. 27" high, 19" deep or 30" wide  |
| Findings:   | No knee clearance   |
| Rec. Solution:  | Replace cabinet and remount sink  |
| Barrier Severity:   | 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:  |   |
| Fireld Born   |   |
| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BH  |
| Bldg Name:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BH  Merryfield Hall Reference Dwg: 2 of 3   |
|   |   |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Classroom 0108  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Surface  2010 ADAS 902   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Surface  2010 ADAS 902   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Surface  2010 ADAS 902  ndard: No Quantity: EACH As-built: 1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Surface  2010 ADAS 902  Indard: No Quantity: EACH As-built: 1  Table or workstation surface height exceeds 34" high   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Classroom 0108 N/A Y Coordinate: N/A Laboratory Facilities Workstation - Surface 2010 ADAS 902  ndard: No Quantity: EACH As-built: 1  Table or workstation surface height exceeds 34" high  36-1/2" workstation surface height at alternate use workstation  Provide min. 1 accessible workstation of each type or overall 5%   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Surface  2010 ADAS 902  Indard: No Quantity: EACH As-built: 1  Table or workstation surface height exceeds 34" high  36-1/2" workstation surface height at alternate use workstation  Provide min. 1 accessible workstation of each type or overall 5%  3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open |



| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BI  |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:   | Floor 1 - Classroom 0108  |
| X Coordinate:   | N/A Y Coordinate: N/A   |
| Barrier Area:   | Laboratory Facilities   |
| Barrier Type:   | Workstation - Knee Clearance  |
| Code<br>References:   | 2010 ADAS 902   |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:   | Knee clearance not min. 27" high, 19" deep or 30" wide  |
| Findings:   | No knee clearance at alternate use workstation  |
| Rec. Solution:  | Provide min. 1 accessible workstation of each type or overall 5%  |
| Barrier Severity:   | 1 Necessary Cost Est \$875.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:  |   |
|   |   |
| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BJ  |
| Field Date:<br>Bldg Name:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BJ  Merryfield Hall Reference Dwg: 2 of 3   |
|   |   |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Classroom 0108  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Electrical Outlets - Forward Reach Obstructed (10"-25")  2010 ADAS 306.3.2   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Electrical Outlets - Forward Reach Obstructed (10"-25")  2010 ADAS 306.3.2   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Electrical Outlets - Forward Reach Obstructed (10"-25")  2010 ADAS 306.3.2  ndard: No Quantity: EACH As-built: 1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Electrical Outlets - Forward Reach Obstructed (10"-25")  2010 ADAS 306.3.2  ndard: No Quantity: EACH As-built: 1  Outlet located over an 10" to 25" obstruction max. 34" high located above 44"  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A Y Coordinate: N/A  Laboratory Facilities  Electrical Outlets - Forward Reach Obstructed (10"-25")  2010 ADAS 306.3.2  ndard: No Quantity: EACH As-built: 1  Outlet located over an 10" to 25" obstruction max. 34" high located above 44"  38" high and 25-1/2" deep over an obstruction 36-1/2" high at alternate use workstation   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Electrical Outlets - Forward Reach Obstructed (10"-25")  2010 ADAS 306.3.2  ndard: No Quantity: EACH As-built: 1  Outlet located over an 10" to 25" obstruction max. 34" high located above 44"  38" high and 25-1/2" deep over an obstruction 36-1/2" high at alternate use workstation  Relocate control or mechanism to max. 44" high  2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open |



| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BK  |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:   | Floor 1 - Classroom 0108  |
| X Coordinate:   | N/A Y Coordinate: N/A   |
| Barrier Area:   | Laboratory Facilities   |
| Barrier Type:   | Actuator/Control - Side Reach High Unobstructed   |
| Code<br>References:   | 2010 ADAS 305.3   |
| Performance Sta   | ndard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description:   | Control or mechanism not at min. 15" or max. 48" high   |
| Findings:   | Humboldt lab machine controls 55" high at alternate use workstation   |
| Rec. Solution:  | Provide assistance  |
| Barrier Severity:   | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:  |   |
|   |   |
| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BL  |
| Field Date:<br>Bldg Name:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BL  Merryfield Hall Reference Dwg: 2 of 3   |
|   |   |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Clear Floor Space   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Clear Floor Space  Passageway - Min. 36" (Stored Item)  2010 ADAS 403.5.1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Clear Floor Space  Passageway - Min. 36" (Stored Item)  2010 ADAS 403.5.1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Clear Floor Space  Passageway - Min. 36" (Stored Item)  2010 ADAS 403.5.1  Indard: No Quantity: JOB As-built: 1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Clear Floor Space  Passageway - Min. 36" (Stored Item)  2010 ADAS 403.5.1  Indard: No Quantity: JOB As-built: 1  Circulation route not min. 36" wide between elements   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Classroom 0108 N/A Y Coordinate: N/A  Clear Floor Space Passageway - Min. 36" (Stored Item) 2010 ADAS 403.5.1  ndard: No Quantity: JOB As-built: 1  Circulation route not min. 36" wide between elements  23" wide circulation route between equipment  Removed stored items  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Clear Floor Space  Passageway - Min. 36" (Stored Item)  2010 ADAS 403.5.1  Indard: No Quantity: JOB As-built: 1  Circulation route not min. 36" wide between elements  23" wide circulation route between equipment  Removed stored items  1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BM   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Coat Hook - Height   |
| Code<br>References:     | 2010 ADAS 603.4  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Clothing hooks not max. 48" high AFF   |
| Findings:               | 74" high   |
| Rec. Solution:          | Provide additional hook in new location  |
| Barrier Severity:       | 2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open                                   |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BN   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Sink - Faucet  |
| Code<br>References:     | 2010 ADAS 606.4 & 309  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Faucets lack controls and operating mechanisms involve tight grasping, pinching or twisting of the wrist |
| Findings:               | Faucet not fist operable at elongated sink   |
| Rec. Solution:          | Replace faucet   |
| Barrier Severity:       | 1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open                                     |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:                  |  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BO                                      |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Actuator/Control - Forward Reach Obstructed (10"-25")                               |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | andard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44" |
| Findings:               | Faucet 42" high and 29" deep over an obstruction 36-1/2" high at elongated sink     |
| Rec. Solution:          | Relocate control or mechanism to max. 44" high                                      |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open                |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BP                                      |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Sink - Rim or Countertop  |
| Code<br>References:     | 2010 ADAS 606.3   |
| Performance Sta         | andard: No Quantity: LF As-built: 1   |
| Barrier<br>Description: | Sink rim or surface not max. 34" high   |
| Findings:               | 36-1/2" high at elongated sink  |
| Rec. Solution:          | Reposition existing sink or provide additional sink for use in area                 |
| Barrier Severity:       | 1 Necessary Cost Est \$370.00 Facility Function: Public Status: Open                |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |



| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BQ   |
|---|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:   | Floor 1 - Classroom 0108   |
| X Coordinate:   | N/A Y Coordinate: N/A  |
| Barrier Area:   | Laboratory Facilities  |
| Barrier Type:   | Sink - Knee Clearance  |
| Code<br>References:   | 2010 ADAS 606.2 & 306  |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:   | Knee clearance not min. 27" high, 19" deep or 30" wide   |
| Findings:   | No knee clearance at elongated sink  |
| Rec. Solution:  | Replace cabinet and remount sink   |
| Barrier Severity:   | 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open   |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:  |  |
|   |  |
| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BR   |
| Field Date:<br>Bldg Name:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BR  Merryfield Hall Reference Dwg: 2 of 3  |
|   |  |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Classroom 0108   |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A   |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Surface  2010 ADAS 902  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Surface  2010 ADAS 902  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Surface  2010 ADAS 902  ndard: No Quantity: EACH As-built: 1  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Surface  2010 ADAS 902  ndard: No Quantity: EACH As-built: 1  Table or workstation surface height exceeds 34" high   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Classroom 0108 N/A Y Coordinate: N/A Laboratory Facilities Workstation - Surface 2010 ADAS 902  ndard: No Quantity: EACH As-built: 1  Table or workstation surface height exceeds 34" high  36-1/2" workstation surface height at elongated workstation  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Workstation - Surface  2010 ADAS 902  ndard: No Quantity: EACH As-built: 1  Table or workstation surface height exceeds 34" high  36-1/2" workstation surface height at elongated workstation  Provide min. 1 accessible workstation of each type or overall 5%  3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BS                                      |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Workstation - Knee Clearance  |
| Code<br>References:     | 2010 ADAS 902   |
| Performance Sta         | andard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide                              |
| Findings:               | No knee clearance at elongated workstation  |
| Rec. Solution:          | Provide min. 1 accessible workstation of each type or overall 5%                    |
| Barrier Severity:       | 1 Necessary Cost Est \$875.00 Facility Function: Public Status: Open                |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BT                                      |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Actuator/Control - Forward Reach Obstructed (10"-25")                               |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | andard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Control or mechanism over an 10" to 25" obstruction max. 34" high located above 44" |
| Findings:               | Lab equipment 44-1/2" high and 30" deep over an obstruction 36-1/2" high            |
| Rec. Solution:          | Relocate control or mechanism to max. 44" high or provide assistance                |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open                  |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BU                              |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                       |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Shelves or Cabinet  |
| Code<br>References:     | 2010 ADAS 603.4   |
| Performance Sta         | andard: No Quantity: EACH As-built : 2                                      |
| Barrier<br>Description: | Shelf or cabinet not mounted between 40" and 48" above floor or ground      |
| Findings:               | 7-1/2" - 72" high   |
| Rec. Solution:          | Provide additional shelf/cabinet at accessible height or provide assistance |
| Barrier Severity:       | 2 Recommended Cost Est \$150.00 Facility Function: Public Status: Open      |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                      |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BV                              |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                       |
| Location:               | Floor 1 - Classroom 0108  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Coat Hook - Clear Floor Space   |
| Code<br>References:     | 2010 ADAS 603.4   |
| Performance Sta         | andard: No Quantity: EACH As-built : 2                                      |
| Barrier<br>Description: | Clothing hooks not located within 30" x 48" clear floor space               |
| Findings:               | Workstation and washer blocks clear floor space at tubing hooks             |
| Rec. Solution:          | Relocate hooks or provide additional hooks in accessible location           |
| Barrier Severity:       | 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open      |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                      |
| Notes:                  |   |



| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BW  |
|--|---|
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Classroom 0108  |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  | Laboratory Facilities   |
| Barrier Type:  | Coat Hook - Height  |
| Code<br>References:  | 2010 ADAS 603.4   |
| Performance Sta  | ndard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description:  | Clothing hooks not max. 48" high AFF  |
| Findings:  | Tubing hooks 56" and 68" high   |
| Rec. Solution:   | Provide additional hook in new location   |
| Barrier Severity:  | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open  |
| Implementation   | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:   |   |
| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BX  |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Classroom 0108  |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  | Laboratory Facilities   |
| Parriar Tunas  | Jeason atony 1 actitates  |
| Barrier Type:  | Sink - Faucet   |
| Code<br>References:  |   |
| Code   | Sink - Faucet 2010 ADAS 606.4 & 309   |
| Code<br>References:  | Sink - Faucet 2010 ADAS 606.4 & 309   |
| Code<br>References:<br>Performance Sta<br>Barrier                              | Sink - Faucet  2010 ADAS 606.4 & 309  Indard: No Quantity: EACH As-built: 1  Faucets lack controls and operating mechanisms involve tight grasping, pinching or twisting of   |
| Code References: Performance Sta Barrier Description:                          | Sink - Faucet  2010 ADAS 606.4 & 309  Indard: No Quantity: EACH As-built: 1  Faucets lack controls and operating mechanisms involve tight grasping, pinching or twisting of the wrist   |
| Code References: Performance Sta Barrier Description: Findings:                | Sink - Faucet  2010 ADAS 606.4 & 309  Indard: No Quantity: EACH As-built: 1  Faucets lack controls and operating mechanisms involve tight grasping, pinching or twisting of the wrist  Faucet not fist operable at instructional desk  Replace faucet   |
| Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Sink - Faucet  2010 ADAS 606.4 & 309  Indard: No Quantity: EACH As-built: 1  Faucets lack controls and operating mechanisms involve tight grasping, pinching or twisting of the wrist  Faucet not fist operable at instructional desk  Replace faucet  1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open |



| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BY  |
|--|---|
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Classroom 0108  |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  | Laboratory Facilities   |
| Barrier Type:  | Sink - Rim or Countertop  |
| Code<br>References:  | 2010 ADAS 606.3   |
| Performance Sta  | ndard: No Quantity: LF As-built : 1   |
| Barrier<br>Description:  | Sink rim or surface not max. 34" high   |
| Findings:  | 36" high at instructional desk  |
| Rec. Solution:   | Reposition existing sink or provide additional sink for use in area   |
| Barrier Severity:  | 1 Necessary Cost Est \$370.00 Facility Function: Public Status: Open  |
| Implementation   | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:   |   |
| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 9BZ  |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Fl 4 . Cl 04.00   |
|  | Floor 1 - Classroom 0108  |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| X Coordinate:<br>Barrier Area:   |   |
|  | N/A Y Coordinate: N/A   |
| Barrier Area:  | N/A Y Coordinate: N/A  Laboratory Facilities  |
| Barrier Area:<br>Barrier Type:<br>Code   | N/A Y Coordinate: N/A  Laboratory Facilities  Sink - Knee Clearance  2010 ADAS 606.2 & 306  |
| Barrier Area:<br>Barrier Type:<br>Code<br>References:  | N/A Y Coordinate: N/A  Laboratory Facilities  Sink - Knee Clearance  2010 ADAS 606.2 & 306  |
| Barrier Area:<br>Barrier Type:<br>Code<br>References:<br>Performance Sta<br>Barrier                        | N/A Y Coordinate: N/A  Laboratory Facilities  Sink - Knee Clearance  2010 ADAS 606.2 & 306  ndard: No Quantity: EACH As-built: 1  |
| Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | N/A  V Coordinate: N/A  Laboratory Facilities  Sink - Knee Clearance  2010 ADAS 606.2 & 306  ndard: No Quantity: EACH As-built: 1  Knee clearance not min. 27" high, 19" deep or 30" wide   |
| Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | N/A  Laboratory Facilities  Sink - Knee Clearance  2010 ADAS 606.2 & 306  ndard: No Quantity: EACH As-built: 1  Knee clearance not min. 27" high, 19" deep or 30" wide  No knee clearance at instructional desk   |
| Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | N/A  Laboratory Facilities  Sink - Knee Clearance  2010 ADAS 606.2 & 306  ndard: No Quantity: EACH As-built: 1  Knee clearance not min. 27" high, 19" deep or 30" wide  No knee clearance at instructional desk  Replace cabinet and remount sink  1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9CA                       |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Workstation - Surface  |
| Code<br>References:     | 2010 ADAS 902  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                |
| Barrier<br>Description: | Table or workstation surface height exceeds 34" high                 |
| Findings:               | 36" workstation surface height at instructional desk                 |
| Rec. Solution:          | Provide min. 1 accessible workstation of each type or overall 5%     |
| Barrier Severity:       | 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9CB                       |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Workstation - Knee Clearance   |
| Code<br>References:     | 2010 ADAS 902  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide               |
| Findings:               | No knee clearance at instructional desk                              |
| Rec. Solution:          | Provide min. 1 accessible workstation of each type or overall 5%     |
| Barrier Severity:       | 1 Necessary Cost Est \$875.00 Facility Function: Public Status: Open |
|                         | 1 Necessary Cost Est \$875.00 Facility Function: Public Status: Open |
| Implementation          |  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9CC                           |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                    |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Clear Floor Space  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | ndard: No Quantity: SF As-built : 30                                     |
| Barrier<br>Description: | Clear floor space of min. 30" by 48" not provided                        |
| Findings:               | 33" deep clear floor space between podium and wall                       |
| Rec. Solution:          | Remodel area to provide wheelchair space                                 |
| Barrier Severity:       | 2 Recommended Cost Est \$5,250.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                   |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9CD                           |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                    |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Podium - Surface Height  |
| Code<br>References:     | 2010 ADAS 902.3  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                    |
| Barrier<br>Description: | Surface height exceeds 34" high  |
| Findings:               | 39" surface height at instructional desk                                 |
| Rec. Solution:          | Provide min. 1 accessible podium   |
| Barrier Severity:       | 3 Hindrance Cost Est \$1,275.00 Facility Function: Public Status: Open   |
| Implementation          |  |
|                         |  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9CE                                   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Podium - Knee Clearance  |
| Code<br>References:     | 2010 ADAS 902.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description: | Podium knee clearance not min. 27" high, 19" deep or 30" wide                    |
| Findings:               | No knee clearance  |
| Rec. Solution:          | Provide min. 1 accessible podium   |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open               |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9CF                                   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed                                  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high                            |
| Findings:               | Machine controls 60" high  |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high or provide assistance |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open               |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |



| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9CG   |
|---|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:   | Floor 1 - Classroom 0108   |
| X Coordinate:   | N/A Y Coordinate: N/A  |
| Barrier Area:   | Laboratory Facilities  |
| Barrier Type:   | Clear Floor Space - Controls   |
| Code<br>References:   | 2010 ADAS 305.3  |
| Performance Sta   | ndard: No Quantity: JOB As-built : 1   |
| Barrier<br>Description:   | Clear floor space of min. 30" by 48" not provided  |
| Findings:   | Machine blocks clear floor space at projector  |
| Rec. Solution:  | Move stored items at control or mechanism  |
| Barrier Severity:   | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open   |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:  |  |
|   |  |
| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9CH   |
| Field Date:<br>Bldg Name:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 9CH  Merryfield Hall Reference Dwg: 2 of 3  |
|   |  |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Classroom 0108   |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A   |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Projector Screen Pull  2010 ADAS 305.3  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Projector Screen Pull  2010 ADAS 305.3  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Classroom 0108 N/A Y Coordinate: N/A Laboratory Facilities Projector Screen Pull 2010 ADAS 305.3  Indard: No Quantity: EACH As-built: 1  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Projector Screen Pull  2010 ADAS 305.3  Indard: No Quantity: EACH As-built: 1  Screen pull not at max. 48" high for side reach   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Classroom 0108 N/A Y Coordinate: N/A Laboratory Facilities Projector Screen Pull 2010 ADAS 305.3  Indard: No Quantity: EACH As-built: 1  Screen pull not at max. 48" high for side reach  60" high  Relocate to max. 48" high or provide extension   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0108  N/A  Y Coordinate: N/A  Laboratory Facilities  Projector Screen Pull  2010 ADAS 305.3  Indard: No Quantity: EACH As-built: 1  Screen pull not at max. 48" high for side reach  60" high  Relocate to max. 48" high or provide extension  3 Hindrance Cost Est \$75.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 9CI   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0108   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high                                  |
| Findings:               | Instron machine controls 59" high  |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high or provide assistance       |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open                     |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                 |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10A   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Lounge 0107  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Signage  |
| Barrier Type:           | Permanent Room/Space - Tactile Characters  |
| Code<br>References:     | 2010 ADAS 216.2  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | No tactile characters at sign identifying permanent rooms and spaces with visual signs |
| Findings:               | No tactile signage provided at door within public route                                |
| Rec. Solution:          | Provide accessible sign  |
| Barrier Severity:       | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open                   |
| Implementation          |  |
| Notes:                  |  |



| Field Date:                 | 1/27/2017 Report Date 2/22/2017 Barrier #: 10B  |
|-----------------------------|---|
| Bldg Name:                  | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:                   | Floor 1 - Lounge 0107   |
| X Coordinate:               | N/A Y Coordinate: N/A   |
| Barrier Area:               | Signage   |
| Barrier Type:               | ISA - Accessible Entry Door   |
| Code<br>References:         | 2010 ADAS 216.6   |
| Performance Sta             | andard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:     | No sign identifying door as accessible where all doors are not accessible   |
| Findings:                   | No sign provided to indicate that entrance is accessible  |
| Rec. Solution:              | Provide ISA at accessible entrance door   |
| Barrier Severity:           | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open  |
| Implementation              | Priority: 3 Implementation Phase: Implementation Date:  |
| Notes:                      |   |
| Field Date:                 | 1/27/2017 Report Date 2/22/2017 Barrier #: 10C  |
| Bldg Name:                  | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:                   | Floor 1 - Lounge 0107   |
| X Coordinate:               | N/A Y Coordinate: N/A   |
| Barrier Area:               | Controls and Mechanisms   |
| Barrier Type:               | Clear Floor Space - Stored Elements   |
| Code<br>References:         | 2010 ADAS 305.3   |
| Performance Sta             | ndard: No Quantity: JOB As-built : 1  |
| Barrier                     |   |
| Description:                | Clear floor space for wheelchair not provided at control or mechanism   |
| Findings:                   | Clear floor space for wheelchair not provided at control or mechanism  Main entry door swing blocks clear floor space at automatic door opening device  |
| ·                           |   |
| Findings:                   | Main entry door swing blocks clear floor space at automatic door opening device  Relocate door actuator to location exclusive of door swing   |
| Findings:<br>Rec. Solution: | Main entry door swing blocks clear floor space at automatic door opening device  Relocate door actuator to location exclusive of door swing  1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10D                                  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Lounge 0107   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Doors or Gates  |
| Barrier Type:           | Automatic Doors - Sign  |
| Code<br>References:     | Performance Standard  |
| Performance Sta         | ndard: Yes Quantity: JOB As-built : 2   |
| Barrier<br>Description: | ISA symbol at automatic door opening device not min. 4" x 4" in size            |
| Findings:               | Existing symbol 1-3/4" high. Nor visible from a distance                        |
| Rec. Solution:          | Recommended: Provide ISA symbol min. 4" x 4" in size at both sides              |
| Barrier Severity:       | 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open            |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                          |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10E                                  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Lounge 0107   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Doors or Gates  |
| Barrier Type:           | Automatic Doors - Timing  |
| Code<br>References:     | 2010 ADAS 404.3   |
| Performance Sta         | ndard: No Quantity: JOB As-built : 1  |
| Barrier<br>Description: | Door does not re-open when encountering an obstruction other than the door jamb |
| Findings:               | Door does not re-open   |
| Rec. Solution:          | Repair actuation device   |
| Barrier Severity:       | 1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open          |
| Implementation          |   |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10F                                      |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Lounge 0107   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Doors or Gates  |
| Barrier Type:           | Vision Lights - Existing  |
| Code<br>References:     | 2010 ADAS 404.2.11  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | View panels in or adjacent to doors or gates not max. 43" above floor or ground     |
| Findings:               | 51" high  |
| Rec. Solution:          | Replace door/gate or vision panel   |
| Barrier Severity:       | 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open              |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10G                                      |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Lounge 0107   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Signage   |
| Barrier Type:           | Tactile Exit Signs - Passage  |
| Code<br>References:     | Performance Standard  |
| Performance Sta         | ndard: Yes Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Exit thru an exit enclosure/exit passageway lacks tactile exit sign                 |
| Findings:               | Passageway to exterior exit with low level illuminated sign lacks tactile exit sign |
| Rec. Solution:          | Provide sign stating "EXIT ROUTE" at exit side of door                              |
| Barrier Severity:       | 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open              |
|                         | 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open              |
| Implementation          |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10H                            |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                     |
| Location:               | Floor 1 - Lounge 0107   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Alarms  |
| Barrier Type:           | Fire Pull - Operation   |
| Code<br>References:     | 2010 ADAS 309.4   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                     |
| Barrier<br>Description: | Fire pull has no fist operable hardware                                   |
| Findings:               | Fire pull not fist operable   |
| Rec. Solution:          | Replace fire pull when remodeling   |
| Barrier Severity:       | 4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                    |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10I                            |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                     |
| Location:               | Floor 1 - Lounge 0107   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Alarms  |
| Barrier Type:           | Fire Pull - Height  |
| Code<br>References:     | 2010 ADAS 308.2.2   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 0                                     |
| Barrier<br>Description: | Fire pulls not between 42" and 48" high                                   |
| Findings:               | 49" high  |
| Rec. Solution:          | Replace fire pull when remodeling   |
| Barrier Severity:       | 4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open     |
| Implementation          |   |
|                         | Priority: 1 Implementation Phase: Implementation Date:                    |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10J                              |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                       |
| Location:               | Floor 1 - Lounge 0107   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Controls and Mechanisms   |
| Barrier Type:           | Clear Floor Space - Stored Elements   |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | ndard: No Quantity: JOB As-built : 1  |
| Barrier<br>Description: | Clear floor space for wheelchair not provided at control or mechanism       |
| Findings:               | Items block clear floor space at outlet                                     |
| Rec. Solution:          | Move stored items   |
| Barrier Severity:       | 1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open        |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                      |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10K                              |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                       |
| Location:               | Floor 1 - Lounge 0107   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Accessible Route - Cords  |
| Code<br>References:     | 2010 ADAS 303.3   |
| Performance Sta         | ndard: No Quantity: JOB As-built : 1  |
| Barrier<br>Description: | Change in level greater than 1/2" in clear floor space at cords             |
| Findings:               | Electrical cords, hoses and piping create trip hazard in multiple locations |
| Rec. Solution:          | Provide accessible cord cover or otherwise remove barrier to access         |
| Barrier Severity:       | 1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open         |
| Implementation          |   |
| Notes:                  | implementation hase.  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10L                              |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                       |
| Location:               | Floor 1 - Lounge 0107   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Counters and Tables   |
| Barrier Type:           | Table - Knee Clearance  |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                       |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide                      |
| Findings:               | 21" high knee clearance at storage table with carboys                       |
| Rec. Solution:          | Provide min. 1 accessible table. Avoid pedestal base tables.                |
| Barrier Severity:       | 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open        |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                      |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10M                              |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                       |
| Location:               | Floor 1 - Lounge 0107   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Shelves or Cabinet  |
| Code<br>References:     | 2010 ADAS 603.4   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                       |
| Barrier<br>Description: | Shelf or cabinet not mounted between 40" and 48" above floor or ground      |
| Findings:               | 10" - 70" high  |
| Rec. Solution:          | Provide additional shelf/cabinet at accessible height or provide assistance |
| Barrier Severity:       | 2 Recommended Cost Est \$75.00 Facility Function: Public Status: Open       |
| Implementation          |   |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10N                         |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                  |
| Location:               | Floor 1 - Lounge 0107  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Walkways   |
| Barrier Type:           | Running Slope - Existing (5.0% - 8.2%)                                 |
| Code<br>References:     | 2010 ADAS 403.3  |
| Performance Sta         | ndard: No Quantity: SF As-built : 46                                   |
| Barrier<br>Description: | Walkway running slope exceeds 5.0% (5.0% - 5.5%) creating a ramp       |
| Findings:               | 5.8% running slope at ramp and door landing to Lab 108                 |
| Rec. Solution:          | Provide new handrails at both sides of ramp with level top landing     |
| Barrier Severity:       | 1 Necessary Cost Est \$5,750.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                 |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 100                         |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                  |
| Location:               | Floor 1 - Lounge 0107  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Counters and Tables  |
| Barrier Type:           | Table - Knee Clearance   |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                  |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide                 |
| Findings:               | Stored items block knee clearance                                      |
| Rec. Solution:          | Move stored objects  |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open     |
| Implementation          |  |
| Notes:                  |  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10P                                   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Lounge 0107  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed                                  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high                            |
| Findings:               | Glass tank controls 51" high   |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high or provide assistance |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open               |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10Q                                   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Lounge 0107  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Shelves or Cabinet   |
| Code<br>References:     | 2010 ADAS 603.4  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Shelf or cabinet not mounted between 40" and 48" above floor or ground           |
| Findings:               | 55" -79" high  |
| Rec. Solution:          | Provide additional shelf/cabinet at accessible height or provide assistance      |
| Barrier Severity:       | 2 Recommended Cost Est \$75.00 Facility Function: Public Status: Open            |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10R  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Lounge 0107   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Protruding Object   |
| Code<br>References:     | 2010 ADAS 307.2   |
| Performance Sta         | andard: No Quantity: EACH As-built : 2  |
| Barrier<br>Description: | Wall mounted object (dispensers) protrudes more than 4" from wall                           |
| Findings:               | Cabinets protrude 13" at 55" high at both sides of room                                     |
| Rec. Solution:          | Relocate, remove object (dispenser) or provide detectable warning for the visually impaired |
| Barrier Severity:       | 1 Necessary Cost Est \$1,100.00 Facility Function: Public Status: Open                      |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                                      |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10S  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Lounge 0107   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed   |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | andard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high                                       |
| Findings:               | Blue tank controls 50" high   |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high or provide assistance            |
| Parriar Cavarity        |   |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open                          |
| Implementation          |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10T                                  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Lounge 0107   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Counters and Tables   |
| Barrier Type:           | Table - Pedestal Base   |
| Code<br>References:     | 2010 ADAS 306.2.2 & 306.2.3   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide                          |
| Findings:               | Pedestal base blocks knee clearance   |
| Rec. Solution:          | Provide min. 1 accessible table. Avoid pedestal base tables.                    |
| Barrier Severity:       | 2 Recommended Cost Est \$450.00 Facility Function: Public Status: Open          |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                          |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10U                                  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Lounge 0107   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Workstation - Surface   |
| Code<br>References:     | 2010 ADAS 902   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Table or workstation surface height exceeds 34" high                            |
| Findings:               | PC cart/workstation surface height 43"  |
| Rec. Solution:          | Relocate PC to provide min. 1 accessible workstation of each type or overall 5% |
| Barrier Severity:       | 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open            |
| Implementation          |   |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10V                          |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                   |
| Location:               | Floor 1 - Lounge 0107   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Workstation - Knee Clearance  |
| Code<br>References:     | 2010 ADAS 902   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 0                                   |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide                  |
| Findings:               | No knee clearance   |
| Rec. Solution:          | Provide min. 1 accessible workstation of each type or overall 5%        |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open      |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                  |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10W                          |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                   |
| Location:               | Floor 1 - Lounge 0107   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Abrupt Change in Level  |
| Code<br>References:     | 2010 ADAS 303.3   |
| Performance Sta         | ndard: No Quantity: LF As-built : 7                                     |
| Barrier<br>Description: | Change in level greater than 1/2" in walkway                            |
| Findings:               | 2" lip in walkway surface   |
| Rec. Solution:          | Repair to remove trip hazard  |
| Barrier Severity:       | 1 Necessary Cost Est \$1,750.00 Facility Function: Public Status: Open  |
|                         | Thecessary cost est  \$1,750.00 Tacinty function.  Public Status.  Open |
| Implementation          |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10X  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Lounge 0107   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Protruding Object   |
| Code<br>References:     | 2010 ADAS 307.2   |
| Performance Sta         | andard: No Quantity: EACH As-built : 3  |
| Barrier<br>Description: | Wall mounted object (dispensers) protrudes more than 4" from wall                           |
| Findings:               | Mechanical boxes protrude 4-1/2" - 6" at 43" - 60" high                                     |
| Rec. Solution:          | Relocate, remove object (dispenser) or provide detectable warning for the visually impaired |
| Barrier Severity:       | 1 Necessary Cost Est \$1,650.00 Facility Function: Public Status: Open                      |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                                      |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10Y  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Lounge 0107   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Laboratory Facilities   |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed   |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | andard: No Quantity: EACH As-built : 0  |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high                                       |
| Findings:               | Machine control 11" high at equipment on ground   |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high or provide assistance            |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open                          |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                      |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10Z   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Lounge 0107  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Floor Surface - Slope  |
| Code<br>References:     | 2010 ADAS 302 & 303  |
| Performance Sta         | ndard: No Quantity: SF As-built : 10   |
| Barrier<br>Description: | Floor surface slope exceeds 2.0%   |
| Findings:               | 2.3% slope   |
| Rec. Solution:          | Remodel to provide level clear floor space at controls/mechanisms  |
| Barrier Severity:       | 2 Necessary Cost Est \$5,750.00 Facility Function: Public Status: Open   |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10AA  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Lounge 0107  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Laboratory Facilities  |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high  |
| Findings:               | Promax cylinder 65" high   |
| i iliuliigs.            |  |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high or provide assistance   |
| _                       | Relocate control or mechanism to min. 15" or max. 48" high or provide assistance  3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open |
| Rec. Solution:          | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 10AB  |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Lounge 0107  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Alarms   |
| Barrier Type:           | Horn - No Strobe   |
| Code<br>References:     | 2010 ADAS 702  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Horn provided in location where no strobe is provided                                  |
| Findings:               | No strobe device provided  |
| Rec. Solution:          | Provide strobe in common use area  |
| Barrier Severity:       | 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open                   |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                                 |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 11A   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Open Lab Computer 0107B  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Signage  |
| Barrier Type:           | Permanent Room/Space - Tactile Characters  |
| Code<br>References:     | 2010 ADAS 216.2  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | No tactile characters at sign identifying permanent rooms and spaces with visual signs |
| Findings:               | No tactile signage provided at door within public route                                |
| Rec. Solution:          | Provide accessible sign  |
| Barrier Severity:       | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open                   |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                                 |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 11B   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Open Lab Computer 0107B  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Threshold - Height exceeding 1/2"  |
| Code<br>References:     | 2010 ADAS 404.2.5  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Door/Gate threshold exceeds 1/2" in height   |
| Findings:               | 1" lip   |
| Rec. Solution:          | Provide new door threshold   |
| Barrier Severity:       | 1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open                   |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                 |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 11C   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Open Lab Computer 0107B  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Front App/pull 18" SEC - Blocked   |
| Code<br>References:     | 2010 ADAS Figure 404.2.4.1   |
| Performance Sta         | ndard: No Quantity: ADMINI As-built : 1  |
| Barrier<br>Description: | Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side |
| Findings:               | Trash bin blocks strike edge clearance   |
| Rec. Solution:          | Remove stored item   |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open                     |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                 |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 11D   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Open Lab Computer 0107B  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Counters and Tables  |
| Barrier Type:           | Table - Knee Clearance   |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide                                 |
| Findings:               | 23" high knee clearance at 4 tables provided   |
| Rec. Solution:          | Provide min. 1 accessible table. Avoid pedestal base tables.                           |
| Barrier Severity:       | 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open                   |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                 |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 11E   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Open Lab Computer 0107B  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Classrooms   |
| Barrier Type:           | Desk - Knee Clearance  |
| Code<br>References:     | 2010 ADAS 902  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Knee clearance of at least 27" high, 30" wide and 8" deep not provided underneath desk |
| Findings:               | No knee clearance at desk  |
| Rec. Solution:          | Reposition desk to provide knee clearance  |
| Barrier Severity:       | 1 Necessary Cost Est \$875.00 Facility Function: Public Status: Open                   |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                 |
| Notes:                  |  |



| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 11F  |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:   | Floor 1 - Open Lab Computer 0107B   |
| X Coordinate:   | N/A Y Coordinate: N/A   |
| Barrier Area:   | Controls and Mechanisms   |
| Barrier Type:   | Clear Floor Space - Stored Elements   |
| Code<br>References:   | 2010 ADAS 305.3   |
| Performance Sta   | ndard: No Quantity: JOB As-built : 1  |
| Barrier<br>Description:   | Clear floor space for wheelchair not provided at control or mechanism   |
| Findings:   | Table blocks clear floor space at electrical switch   |
| Rec. Solution:  | Move stored items   |
| Barrier Severity:   | 1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:  |   |
|   |   |
| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 11G  |
| Field Date:<br>Bldg Name:   | 1/26/2017   Report Date   2/22/2017   Barrier #:   11G  |
|   |   |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Open Lab Computer 0107B   |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Open Lab Computer 0107B  N/A  Y Coordinate: N/A   |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Open Lab Computer 0107B  N/A  Y Coordinate: N/A  Controls and Mechanisms  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Open Lab Computer 0107B  N/A  Y Coordinate: N/A  Controls and Mechanisms  Electrical Switches - Height  2010 ADAS 308.2   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Open Lab Computer 0107B  N/A  Y Coordinate: N/A  Controls and Mechanisms  Electrical Switches - Height  2010 ADAS 308.2   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier                                       | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Open Lab Computer 0107B  N/A  Y Coordinate: N/A  Controls and Mechanisms  Electrical Switches - Height  2010 ADAS 308.2  ndard: No Quantity: EACH As-built: 1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Open Lab Computer 0107B  N/A  Y Coordinate: N/A  Controls and Mechanisms  Electrical Switches - Height  2010 ADAS 308.2  ndard: No Quantity: EACH As-built: 1  Light switch control box top edge not at max. 48" high   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Open Lab Computer 0107B N/A Y Coordinate: N/A  Controls and Mechanisms Electrical Switches - Height 2010 ADAS 308.2  ndard: No Quantity: EACH As-built: 1  Light switch control box top edge not at max. 48" high   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Open Lab Computer 0107B  N/A  Y Coordinate: N/A  Controls and Mechanisms  Electrical Switches - Height  2010 ADAS 308.2  ndard: No Quantity: EACH As-built: 1  Light switch control box top edge not at max. 48" high  48-7/8" high  Relocate switch box top edge to max. 48" high  Relocate switch box top edge to max. 48" high  3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 11H                        |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                 |
| Location:               | Floor 1 - Open Lab Computer 0107B                                     |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Controls and Mechanisms   |
| Barrier Type:           | Clear Floor Space - Stored Elements                                   |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | ndard: No Quantity: JOB As-built : 1                                  |
| Barrier<br>Description: | Clear floor space for wheelchair not provided at control or mechanism |
| Findings:               | Tables block clear floor space at white boards                        |
| Rec. Solution:          | Move stored items   |
| Barrier Severity:       | 1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open  |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                |
| Notes:                  |   |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 11I                        |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                 |
| Location:               | Floor 1 - Open Lab Computer 0107B                                     |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Clear Floor Space   |
| Barrier Type:           | Passageway - Min. 36" (Stored Item)                                   |
| Code<br>References:     | 2010 ADAS 403.5.1   |
| Performance Sta         | ndard: No Quantity: JOB As-built : 1                                  |
| Barrier<br>Description: | Circulation route not min. 36" wide between elements                  |
| Findings:               | 31" clear width between whiteboards                                   |
| Rec. Solution:          | Move whiteboards to provide accessible circulation route              |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open    |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                |
| Notes:                  |   |



| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 11J   |
|---|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:   | Floor 1 - Open Lab Computer 0107B  |
| X Coordinate:   | N/A Y Coordinate: N/A  |
| Barrier Area:   | Alarms   |
| Barrier Type:   | Horn/Strobe - Common Use Area  |
| Code<br>References:   | 2010 ADAS 702.1  |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:   | No horn/strobes in common use areas  |
| Findings:   | No device provided   |
| Rec. Solution:  | Provide strobe in common use area  |
| Barrier Severity:   | 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open   |
| Implementation  | Priority: 1 Implementation Phase: Implementation Date:   |
| Notes:  |  |
|   |  |
| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 12A   |
| Field Date:<br>Bldg Name:   | 1/26/2017Report Date2/22/2017Barrier #:12AMerryfield HallReference Dwg:2 of 3  |
|   |  |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
| Bldg Name:<br>Location:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  Signage   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  Signage  Permanent Room/Space - Tactile Characters  2010 ADAS 216.2   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  Signage  Permanent Room/Space - Tactile Characters  2010 ADAS 216.2   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  Signage  Permanent Room/Space - Tactile Characters  2010 ADAS 216.2  ndard: No Quantity: EACH As-built: 1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A Y Coordinate: N/A  Signage  Permanent Room/Space - Tactile Characters  2010 ADAS 216.2  ndard: No Quantity: EACH As-built: 1  No tactile characters at sign identifying permanent rooms and spaces with visual signs   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Entrance Hall H0101 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2  ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs  No tactile signage provided at door within public route  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Entrance Hall H0101 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2  ndard: No Quantity: EACH As-built: 1 No tactile characters at sign identifying permanent rooms and spaces with visual signs  No tactile signage provided at door within public route  Provide accessible sign  1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 12B                         |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                  |
| Location:               | Floor 1 - Entrance Hall H0101  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Door Closer - Exterior Automatic Door                                  |
| Code<br>References:     | Performance Standard   |
| Performance Sta         | andard: Yes Quantity: EACH As-built : 1                                |
| Barrier<br>Description: | Door opening force exceeds 8.5 lbf                                     |
| Findings:               | 10 lbf with 3.1% door landing slope                                    |
| Rec. Solution:          | Provide automatic door opening device                                  |
| Barrier Severity:       | 1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                 |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 12C                         |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                  |
| Location:               | Floor 1 - Entrance Hall H0101  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Door Closer - Exterior Sweep Period                                    |
| Code<br>References:     | 2010 ADAS 404.2.8.1  |
| Performance Sta         | andard: No Quantity: EACH As-built : 0                                 |
| Barrier<br>Description: | Door closer lacks min. 5 second sweep period                           |
| Findings:               | 1 second sweep   |
| Rec. Solution:          | Provide automatic door opening device                                  |
| Barrier Severity:       | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open   |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                 |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 12D                                  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Entrance Hall H0101   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Doors or Gates  |
| Barrier Type:           | Vision Lights - Existing  |
| Code<br>References:     | 2010 ADAS 404.2.11  |
| Performance Sta         | andard: No Quantity: EACH As-built : 2  |
| Barrier<br>Description: | View panels in or adjacent to doors or gates not max. 43" above floor or ground |
| Findings:               | 51" high  |
| Rec. Solution:          | Replace door/gate or vision panel   |
| Barrier Severity:       | 3 Hindrance Cost Est \$4,500.00 Facility Function: Public Status: Open          |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                          |
| Notes:                  |   |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 12E                                  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Entrance Hall H0101   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Doors or Gates  |
| Barrier Type:           | Clear Width   |
| Code<br>References:     | 2010 ADAS 404.2.3   |
| Performance Sta         | andard: No Quantity: EACH As-built : 2  |
| Barrier<br>Description: | Clear width passage through door, sliding/folding door or gate is not min. 32"  |
| Findings:               | 26" wide  |
| Rec. Solution:          | Replace door or gate and frame  |
| Barrier Severity:       | 1 Necessary Cost Est \$4,500.00 Facility Function: Public Status: Open          |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                          |
| Notes:                  |   |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 12F   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Entrance Hall H0101  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Threshold - Height 1/2" with Ramp  |
| Code<br>References:     | 2010 ADAS 404.2.5  |
| Performance Sta         | ndard: No Quantity: SF As-built : 60   |
| Barrier<br>Description: | Door/Gate threshold bevel at max 1/2" lip exceeds 1:2 or 50% slope   |
| Findings:               | 1/2" concrete lip with sloped threshold and additional 1/4" high lip for 2-1/2" total rise at door threshold |
| Rec. Solution:          | Provide ramp leading to new level landing at door  |
| Barrier Severity:       | 1 Necessary Cost Est \$13,500.00 Facility Function: Public Status: Open                                      |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 12G   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Entrance Hall H0101  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Door 10" Bottom Surface - Door Hardware  |
| Code<br>References:     | 2010 ADAS 404.2.10   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Door hardware interrupts min. 10" smooth bottom surface  |
| Findings:               | Door hardware extends into bottom 10" of door  |
| Rec. Solution:          | Remove element at bottom of door at push side  |
| Barrier Severity:       | 1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open  |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:                  |  |



| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 12H   |
|---|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:   | Floor 1 - Entrance Hall H0101  |
| X Coordinate:   | N/A Y Coordinate: N/A  |
| Barrier Area:   | Doors or Gates   |
| Barrier Type:   | Doormat  |
| Code<br>References:   | 2010 ADAS 302.2 & Advisory 302.2   |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:   | Doormat not anchored to floor (possible trip hazard)   |
| Findings:   | Doormat not secured  |
| Rec. Solution:  | Secure exiting doormat or replace  |
| Barrier Severity:   | 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open   |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:  |  |
|   |  |
| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 12I   |
| Field Date:<br>Bldg Name:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 12I  Merryfield Hall Reference Dwg: 2 of 3  |
|   |  |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Entrance Hall H0101  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  Signage   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  Signage  Tactile Exit Signs - Door  2010 ADAS 216.4.1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  Signage  Tactile Exit Signs - Door  2010 ADAS 216.4.1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A Y Coordinate: N/A  Signage  Tactile Exit Signs - Door  2010 ADAS 216.4.1  ndard: No Quantity: EACH As-built: 1  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A Y Coordinate: N/A  Signage  Tactile Exit Signs - Door  2010 ADAS 216.4.1  ndard: No Quantity: EACH As-built: 1  Ground floor doors that exit to exterior lacks tactile exit sign   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  Signage  Tactile Exit Signs - Door  2010 ADAS 216.4.1  Indard: No Quantity: EACH As-built: 1  Ground floor doors that exit to exterior lacks tactile exit sign  Exit door with low level illuminated sign lacks tactile exit sign   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Entrance Hall H0101 N/A Y Coordinate: N/A Signage Tactile Exit Signs - Door 2010 ADAS 216.4.1  Indard: No Quantity: EACH As-built: 1 Ground floor doors that exit to exterior lacks tactile exit sign  Exit door with low level illuminated sign lacks tactile exit sign  Provide sign stating "EXIT" at exit side of door  1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 12J   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Entrance Hall H0101  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Signage  |
| Barrier Type:           | Permanent Room/Space - Tactile Characters  |
| Code<br>References:     | 2010 ADAS 216.2  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 3  |
| Barrier<br>Description: | No tactile characters at sign identifying permanent rooms and spaces with visual signs |
| Findings:               | No tactile signage provided at door within public route at rooms 115, 104, 106         |
| Rec. Solution:          | Provide accessible signs   |
| Barrier Severity:       | 1 Necessary Cost Est \$750.00 Facility Function: Public Status: Open                   |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                                 |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 12K   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Entrance Hall H0101  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Signage  |
| Barrier Type:           | Lobby Info Sign  |
| Code<br>References:     | Performance Standard   |
| Performance Sta         | ndard: Yes Quantity: EACH As-built : 1   |
| Barrier<br>Description: | No lobby informational sign with location of accessible elements                       |
| Findings:               | Accessible sign not provided   |
| Rec. Solution:          | Provide lobby informational sign   |
| Barrier Severity:       | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open                   |
| Implementation          |  |
| Notes:                  | implementation russe.  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 12L  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Entrance Hall H0101   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Corridors   |
| Barrier Type:           | Strobe  |
| Code<br>References:     | 2010 ADAS 702.1   |
| Performance Sta         | andard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | No strobe provided in corridor where horn is provided where fire alarm exists in building |
| Findings:               | No strobe where horn is provided  |
| Rec. Solution:          | Provide strobe in common use area   |
| Barrier Severity:       | 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open                    |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                    |
| Notes:                  |   |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 12M  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Entrance Hall H0101   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Alarms  |
| Barrier Type:           | Fire Pull - Operation   |
| Code<br>References:     | 2010 ADAS 309.4   |
| Performance Sta         | andard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Fire pull has no fist operable hardware   |
| Findings:               | Fire pull not fist operable   |
| Rec. Solution:          | Replace fire pull when remodeling   |
| Barrier Severity:       | 4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open                 |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                                    |
| Notes:                  |   |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 12N   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Entrance Hall H0101  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Alarms   |
| Barrier Type:           | Fire Pull - Height   |
| Code<br>References:     | 2010 ADAS 308.2.2  |
| Performance Sta         | andard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description: | Fire pulls not between 42" and 48" high  |
| Findings:               | 61" high   |
| Rec. Solution:          | Replace fire pull when remodeling  |
| Barrier Severity:       | 4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open                    |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                                   |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 120   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Entrance Hall H0101  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Corridors  |
| Barrier Type:           | Protruding Object  |
| Code<br>References:     | 2010 ADAS 307  |
| Performance Sta         | andard: No Quantity: EACH As-built : 2   |
| Barrier<br>Description: | Protruding object in in circulation path protrudes more than 4" between 27" and 80" high |
| Findings:               | Mechanical boxes protrudes 4-1/4" and 5-7/8" at 38" and 63" high                         |
| Rec. Solution:          | Remove object or provide detectable warning (wing walls)                                 |
| Barrier Severity:       | 1 Necessary Cost Est \$1,100.00 Facility Function: Public Status: Open                   |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                                   |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 12P  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Entrance Hall H0101   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Signage   |
| Barrier Type:           | Visual Information Provided (Exhibitions)   |
| Code<br>References:     | ADA Title II Technical Assistance Manual 3.2000 Denial of participation                     |
| Performance Sta         | ndard: No Quantity: JOB As-built : 1  |
| Barrier<br>Description: | Visual sign providing information for program, service or activity not accessible           |
| Findings:               | Accessible information not provided   |
| Rec. Solution:          | Provide information in alternate format to provide access to people with vision impairments |
| Barrier Severity:       | 1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open                      |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                                      |
| Notes:                  |   |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 12Q  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Entrance Hall H0101   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Corridors   |
| Barrier Type:           | Electrical Switches - High Unobstructed   |
| Code<br>References:     | 2010 ADAS 308.2.1   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Light switch control box top edge not at max. 48" high                                      |
| Findings:               | 49" high  |
| Rec. Solution:          | Relocate switch box top edge to max. 48" high   |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open                        |
| Implementation          |   |
| Notes:                  |   |



| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 12R  |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:   | Floor 1 - Entrance Hall H0101   |
| X Coordinate:   | N/A Y Coordinate: N/A   |
| Barrier Area:   | Alarms  |
| Barrier Type:   | Fire Pull - Operation   |
| Code<br>References:   | 2010 ADAS 309.4   |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:   | Fire pull has no fist operable hardware   |
| Findings:   | Fire pull not fist operable   |
| Rec. Solution:  | Replace fire pull when remodeling   |
| Barrier Severity:   | 4 Low Severity Cost Est \$3,500.00 Facility Function: Public Status: Open   |
| Implementation  | Priority: 1 Implementation Phase: Implementation Date:  |
| Notes:  |   |
| r   |   |
| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 12S  |
| Field Date:<br>Bldg Name:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 12S  Merryfield Hall Reference Dwg: 2 of 3   |
|   |   |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Entrance Hall H0101   |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A   |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  Alarms   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  Alarms  Fire Pull - Height  2010 ADAS 308.2.2  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  Alarms  Fire Pull - Height  2010 ADAS 308.2.2  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  Alarms  Fire Pull - Height  2010 ADAS 308.2.2  ndard: No Quantity: EACH As-built: 0  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  Alarms  Fire Pull - Height  2010 ADAS 308.2.2  ndard: No Quantity: EACH As-built: 0  Fire pulls not between 42" and 48" high  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Entrance Hall H0101 N/A Y Coordinate: N/A Alarms Fire Pull - Height 2010 ADAS 308.2.2  ndard: No Quantity: EACH As-built: 0  Fire pulls not between 42" and 48" high  60-1/2" high  Replace fire pull when remodeling   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Entrance Hall H0101  N/A Y Coordinate: N/A  Alarms  Fire Pull - Height  2010 ADAS 308.2.2  ndard: No Quantity: EACH As-built: 0  Fire pulls not between 42" and 48" high  60-1/2" high  Replace fire pull when remodeling  4 Low Severity Cost Est \$0.00 Facility Function: Public Status: Open |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 12T                                       |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Entrance Hall H0101  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Controls and Mechanisms  |
| Barrier Type:           | Actuator/Control - Hi/low Reach  |
| Code<br>References:     | 2010 ADAS 308.2.2  |
| Performance Sta         | andard: No Quantity: EACH As-built: 1  |
| Barrier<br>Description: | Use of control involves low reach of less than 15" above floor or more than 48" high |
| Findings:               | Hand sanitizer control 55" high  |
| Rec. Solution:          | Relocate to area at min. 15" or max. 48" high  |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open                 |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                               |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 12U                                       |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Entrance Hall H0101  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Signage  |
| Barrier Type:           | Tactile Exit Signs - Door  |
| Code<br>References:     | 2010 ADAS 216.4.1  |
| Performance Sta         | andard: No Quantity: EACH As-built: 1  |
| Barrier<br>Description: | Ground floor doors that exit to exterior lacks tactile exit sign                     |
| Findings:               | Exit door with low level illuminated sign lacks tactile exit sign                    |
| Rec. Solution:          | Provide sign stating "EXIT" at exit side of door                                     |
| Barrier Severity:       | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open                 |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                               |
| Notes:                  |  |



| Field Date:                         | 1/26/2017 Report Date 2/22/2017 Barrier #: 12V   |
|-------------------------------------|--|
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:                           | Floor 1 - Entrance Hall H0101  |
| X Coordinate:                       | N/A Y Coordinate: N/A  |
| Barrier Area:                       | Doors or Gates   |
| Barrier Type:                       | Door Closer - Exterior Adjustment  |
| Code<br>References:                 | Performance Standard   |
| Performance Sta                     | ndard: Yes Quantity: EACH As-built : 2   |
| Barrier<br>Description:             | Door opening force exceeds 8.5 lbf   |
| Findings:                           | 12 lbf   |
| Rec. Solution:                      | Replace or adjust existing closer  |
| Barrier Severity:                   | 1 Necessary Cost Est \$900.00 Facility Function: Public Status: Open   |
| Implementation                      | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:                              |  |
| Field Date:                         | 1/26/2017 Report Date 2/22/2017 Barrier #: 12W   |
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:                           | Floor 1 - Entrance Hall H0101  |
| X Coordinate:                       | N/A Y Coordinate: N/A  |
| Barrier Area:                       | Doors or Gates   |
| Barrier Type:                       | Door Closer - Exterior Sweep Period  |
| Code<br>References:                 | 2010 ADAS 404.2.8.1  |
| Performance Sta                     | ndard: No Quantity: EACH As-built : 0  |
| Barrier<br>Description:             | Door closer lacks min. 5 second sweep period   |
| Findings:                           | 1 second sweep   |
| Rec. Solution:                      | Replace or adjust existing closer  |
|                                     | The product of the triangle of triangle of the triangle of triangl |
| Barrier Severity:                   |  |
| Barrier Severity:<br>Implementation | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open   |



| Field Date:                         | 1/26/2017 Report Date 2/22/2017 Barrier #: 12X                                  |
|-------------------------------------|---|
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:                           | Floor 1 - Entrance Hall H0101   |
| X Coordinate:                       | N/A Y Coordinate: N/A   |
| Barrier Area:                       | Doors or Gates  |
| Barrier Type:                       | Vision Lights - Existing  |
| Code<br>References:                 | 2010 ADAS 404.2.11  |
| Performance Sta                     | ndard: No Quantity: EACH As-built : 2   |
| Barrier<br>Description:             | View panels in or adjacent to doors or gates not max. 43" above floor or ground |
| Findings:                           | 48" high  |
| Rec. Solution:                      | Replace door/gate or vision panel   |
| Barrier Severity:                   | 3 Hindrance Cost Est \$4,500.00 Facility Function: Public Status: Open          |
| Implementation                      | Priority: 2 Implementation Phase: Implementation Date:                          |
| Notes:                              |   |
| Field Date:                         | 1/26/2017 Report Date 2/22/2017 Barrier #: 12Y                                  |
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:                           | Floor 1 - Entrance Hall H0101   |
| X Coordinate:                       | N/A Y Coordinate: N/A   |
| Barrier Area:                       | Doors or Gates  |
| Barrier Type:                       | Doormat   |
| Code<br>References:                 | 2010 ADAS 302.2 & Advisory 302.2  |
| Performance Sta                     | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:             | Doormat not anchored to floor (possible trip hazard)                            |
| Findings:                           | Doormat not secured   |
| Rec. Solution:                      | Secure exiting doormat or replace   |
|                                     |   |
| Barrier Severity:                   |   |
| Barrier Severity:<br>Implementation | 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open            |



| Field Date:  | 1/26/2017 Report Date 2/22/2017 Barrier #: 12Z  |
|--|---|
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Entrance Hall H0101   |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  | Signage   |
| Barrier Type:  | Permanent Room/Space - Tactile Characters   |
| Code<br>References:  | 2010 ADAS 216.2   |
| Performance Sta  | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:  | No tactile characters at sign identifying permanent rooms and spaces with visual signs  |
| Findings:  | No tactile signage provided at door within public route   |
| Rec. Solution:   | Provide accessible sign   |
| Barrier Severity:  | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open  |
| Implementation   | Priority: 3 Implementation Phase: Implementation Date:  |
| Notes:   |   |
| Field Date:  | 1/26/2017 Report Date 2/22/2017 Barrier #: 12AA   |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| =  | Interryricia riaii  |
| Location:  | Floor 1 - Entrance Hall H0101   |
| _  |   |
| Location:  | Floor 1 - Entrance Hall H0101   |
| Location:<br>X Coordinate:   | Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A   |
| Location:<br>X Coordinate:<br>Barrier Area:  | Floor 1 - Entrance Hall H0101  N/A Y Coordinate: N/A  Signage   |
| Location:<br>X Coordinate:<br>Barrier Area:<br>Barrier Type:<br>Code   | Floor 1 - Entrance Hall H0101  N/A Y Coordinate: N/A  Signage  ISA - Non-Accessible Entry  2010 ADAS 216.6  |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  Signage  ISA - Non-Accessible Entry  2010 ADAS 216.6   |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  Signage  ISA - Non-Accessible Entry  2010 ADAS 216.6  Indard: No Quantity: EACH As-built: 1  |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  Signage  ISA - Non-Accessible Entry  2010 ADAS 216.6  ndard: No Quantity: EACH As-built: 1  Sign directing people to accessible entrance needed where all doors are not accessible   |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  Signage  ISA - Non-Accessible Entry  2010 ADAS 216.6  Indard: No Quantity: EACH As-built: 1  Sign directing people to accessible entrance needed where all doors are not accessible  ISA sign currently provided on entry door but may not be visible upon approach  |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Floor 1 - Entrance Hall H0101  N/A  Y Coordinate: N/A  Signage  ISA - Non-Accessible Entry  2010 ADAS 216.6  Isign directing people to accessible entrance needed where all doors are not accessible  ISA sign currently provided on entry door but may not be visible upon approach  Provide ISA directional sign at this door indicating location of and route to accessible entrance  1 Necessary  Cost Est \$250.00  Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 13A  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0105  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Signage   |
| Barrier Type:           | Location - 48" to 60" high  |
| Code<br>References:     | 2010 ADAS 703.4.1   |
| Performance Sta         | andard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Braille/Tactile information on sign not mounted between 48" and 60" from ground or floor          |
| Findings:               | 63" high and Braille located 1/4" below raised character  |
| Rec. Solution:          | Provide Braille/tactile sign at latch side of door  |
| Barrier Severity:       | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open                              |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:  |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 13B  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0105  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Signage   |
| Barrier Type:           | ISA - Non-Accessible Entry  |
| Code<br>References:     | 2010 ADAS 216.6   |
| Performance Sta         | andard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Sign directing people to accessible entrance needed where all doors are not accessible            |
| Findings:               | Accessible sign not provided at either of two doors   |
| Rec. Solution:          | Provide ISA directional sign at this door indicating location of and route to accessible entrance |
| Barrier Severity:       | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open                              |
| Implementation          |   |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 13C                                 |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0105   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Classrooms   |
| Barrier Type:           | Door Hardware - Operation  |
| Code<br>References:     | 2010 ADAS 404.2.7  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Operating controls involve tight grasping, pinching or twisting                |
| Findings:               | Hardware not operable with a closed fist                                       |
| Rec. Solution:          | Replace hardware   |
| Barrier Severity:       | 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open           |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                         |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 13D                                 |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Classroom 0105   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Classrooms   |
| Barrier Type:           | Door 10" Bottom Surface - Kickplate  |
| Code<br>References:     | 2010 ADAS 404.2.10   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Door/Gate lacks min. 10" smooth uninterrupted bottom surface                   |
| Findings:               | 6-1/4" high to indented panel in door  |
| Rec. Solution:          | Provide kick plate at push side of door, if door is made wheelchair accessible |
| Barrier Severity:       | 1 Necessary Cost Est \$225.00 Facility Function: Public Status: Open           |
| Implementation          |  |
| Notes:                  |  |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 13E                                |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0105  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Classrooms  |
| Barrier Type:           | Door Landing - Level  |
| Code<br>References:     | 2010 ADAS 404.2.4.4   |
| Performance Sta         | andard: No Quantity: SF As-built : 0  |
| Barrier<br>Description: | Door landing is not level on both sides of door                               |
| Findings:               | 33.0% slope at door threshold   |
| Rec. Solution:          | Demolish and reconstruct level landing, if door is made wheelchair accessible |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open            |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                        |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 13F                                |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0105  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Classrooms  |
| Barrier Type:           | Door Clearance Blocked  |
| Code<br>References:     | 2010 ADAS Figure 404.2.4.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 0  |
| Barrier<br>Description: | Trash bin or stored items block strike edge clearance at exit side of door    |
| Findings:               | Desk blocks strike edge clearance   |
| Rec. Solution:          | Relocate items, if door is made wheelchair accessible                         |
| Barrier Severity:       | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open          |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                        |
| Notes:                  |   |



| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 13G  |
|--|---|
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Classroom 0105  |
| X Coordinate:  | N/A Y Coordinate: N/A   |
| Barrier Area:  | Signage   |
| Barrier Type:  | Permanent Room/Space - Tactile Characters   |
| Code<br>References:  | 2010 ADAS 216.2   |
| Performance Sta  | ndard: No Quantity: EACH As-built : 2   |
| Barrier<br>Description:  | No tactile characters at sign identifying permanent rooms and spaces with visual signs  |
| Findings:  | No tactile signage provided at door within public route   |
| Rec. Solution:   | Provide accessible sign   |
| Barrier Severity:  | 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open  |
| Implementation   | Priority: 3 Implementation Phase: Implementation Date:  |
| Notes: Entry do  | oor and room 105A. No visual sign on other door to 104E   |
| Field Date:  | 1/27/2017 Report Date 2/22/2017 Barrier #: 13H  |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:  | Floor 1 - Classroom 0105  |
| X Coordinate:  |   |
|  | N/A Y Coordinate: N/A   |
| Barrier Area:  | N/A Y Coordinate: N/A Classrooms  |
|  |   |
| Barrier Area:  | Classrooms  |
| Barrier Area:<br>Barrier Type:<br>Code   | Classrooms Door Vision Lights 2010 ADAS 404.2.11  |
| Barrier Area:<br>Barrier Type:<br>Code<br>References:  | Classrooms Door Vision Lights 2010 ADAS 404.2.11  |
| Barrier Area: Barrier Type: Code References: Performance Sta Barrier                                       | Classrooms  Door Vision Lights  2010 ADAS 404.2.11  ndard: No Quantity: EACH As-built: 1  |
| Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Classrooms  Door Vision Lights  2010 ADAS 404.2.11  ndard: No Quantity: EACH As-built: 1  View panels in or adjacent to doors or gates not max. 43" above floor or ground   |
| Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Classrooms  Door Vision Lights  2010 ADAS 404.2.11  ndard: No Quantity: EACH As-built: 1  View panels in or adjacent to doors or gates not max. 43" above floor or ground  44" high   |
| Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Classrooms  Door Vision Lights  2010 ADAS 404.2.11  Indard: No Quantity: EACH As-built: 1  View panels in or adjacent to doors or gates not max. 43" above floor or ground  44" high  Replace door/gate or vision panel  3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open |



| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 13I  |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:   | Floor 1 - Classroom 0105  |
| X Coordinate:   | N/A Y Coordinate: N/A   |
| Barrier Area:   | Classrooms  |
| Barrier Type:   | Door Landing - Level  |
| Code<br>References:   | 2010 ADAS 404.2.4.4   |
| Performance Sta   | ndard: No Quantity: JOB As-built : 1  |
| Barrier<br>Description:   | Door landing is not level on both sides of door   |
| Findings:   | 30.8% slope at door threshold   |
| Rec. Solution:  | Provide automatic door opening device   |
| Barrier Severity:   | 1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:  |   |
| Et ald Book   |   |
| Field Date:   | 1/27/2017 Report Date 2/22/2017 Barrier #: 13J  |
| Field Date:<br>Bldg Name:   | 1/27/2017   Report Date   2/22/2017   Barrier #:   13J   Merryfield Hall   Reference Dwg:   2 of 3  |
|   |   |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Classroom 0105  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0105  N/A  Y Coordinate: N/A  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0105  N/A  Y Coordinate: N/A  Classrooms  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0105  N/A  Y Coordinate: N/A  Classrooms  Clear Floor Space - Stored Elements  2010 ADAS 305.3  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0105  N/A  Y Coordinate: N/A  Classrooms  Clear Floor Space - Stored Elements  2010 ADAS 305.3  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Classroom 0105  N/A  Y Coordinate: N/A  Classrooms  Clear Floor Space - Stored Elements  2010 ADAS 305.3  ndard: No Quantity: JOB As-built: 1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Classroom 0105  N/A Y Coordinate: N/A  Classrooms  Clear Floor Space - Stored Elements  2010 ADAS 305.3  ndard: No Quantity: JOB As-built: 1  Clear floor space for wheelchair not provided at control or mechanism  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Classroom 0105 N/A Y Coordinate: N/A  Classrooms Clear Floor Space - Stored Elements 2010 ADAS 305.3  ndard: No Quantity: JOB As-built: 1  Clear floor space for wheelchair not provided at control or mechanism  Desk blocks electrical switch, pencil sharpener, and emergency phone clear floor space  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Classroom 0105  N/A Y Coordinate: N/A  Classrooms  Clear Floor Space - Stored Elements  2010 ADAS 305.3  ndard: No Quantity: JOB As-built: 1  Clear floor space for wheelchair not provided at control or mechanism  Desk blocks electrical switch, pencil sharpener, and emergency phone clear floor space  Move stored items  3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 13K                                      |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0105  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Classrooms  |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed                                     |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | andard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high                               |
| Findings:               | Emergency phone 51" high  |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high                          |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open                |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 13L                                      |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0105  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Classrooms  |
| Barrier Type:           | Electrical Outlets - Hi/Low Reach   |
| Code<br>References:     | 2010 ADAS 205.1 & 309.3   |
| Performance Sta         | andard: No Quantity: EACH As-built: 1   |
| Barrier<br>Description: | Use of outlet involves low reach of less than 15" above floor or more than 48" high |
| Findings:               | 51" high  |
| Rec. Solution:          | Relocate outlet to area at min. 15" or max. 48" high                                |
| Barrier Severity:       | 2 Recommended Cost Est \$750.00 Facility Function: Public Status: Open              |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 13M                        |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                 |
| Location:               | Floor 1 - Classroom 0105  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Classrooms  |
| Barrier Type:           | Floor Surface - Slope   |
| Code<br>References:     | 2010 ADAS 302 & 303   |
| Performance Sta         | ndard: No Quantity: SF As-built : 0                                   |
| Barrier<br>Description: | Floor surface slope exceeds 2.0%                                      |
| Findings:               | 5.1% slope in path to accessible desk                                 |
| Rec. Solution:          | Relocate desk to accessible location                                  |
| Barrier Severity:       | 2 Necessary Cost Est \$0.00 Facility Function: Public Status: Open    |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 13N                        |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                 |
| Location:               | Floor 1 - Classroom 0105  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Classrooms  |
| Barrier Type:           | Clear Floor Space - Stored Elements                                   |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | ndard: No Quantity: JOB As-built : 1                                  |
| Barrier<br>Description: | Clear floor space for wheelchair not provided at control or mechanism |
| Findings:               | Table blocks whiteboard and projector clear floor space               |
| Rec. Solution:          |   |
|                         | Rearrange desks to provide accessible circulation route               |
| Barrier Severity:       |   |
|                         | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open    |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 130                        |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                 |
| Location:               | Floor 1 - Classroom 0105  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Classrooms  |
| Barrier Type:           | Protruding Object - Wall-mounted                                      |
| Code<br>References:     | 2010 ADAS 307.2   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                 |
| Barrier<br>Description: | Wall mounted object protrudes more than 4" from wall                  |
| Findings:               | Chalkboard protrudes 7-7/8" at 31-1/2" high                           |
| Rec. Solution:          | Remove object or provide detectable warning for the visually impaired |
| Barrier Severity:       | 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open  |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 13P                        |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                 |
| Location:               | Floor 1 - Classroom 0105  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Classrooms  |
| Barrier Type:           | Projector Screen Pull   |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                 |
| Barrier<br>Description: | Screen pull not at max. 48" high for side reach                       |
| Findings:               | Projector screen pull 84" high  |
| Rec. Solution:          | Relocate to max. 48" high or provide extension                        |
| Barrier Severity:       | 3 Hindrance Cost Est \$75.00 Facility Function: Public Status: Open   |
| Implementation          |   |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 13Q  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0105  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Classrooms  |
| Barrier Type:           | Desk - Knee Clearance   |
| Code<br>References:     | 2010 ADAS 902   |
| Performance Sta         | andard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide                                |
| Findings:               | 16-3/4" deep knee clearance at instructors desk where students may give presentations |
| Rec. Solution:          | Reposition desk to provide knee clearance   |
| Barrier Severity:       | 1 Necessary Cost Est \$875.00 Facility Function: Public Status: Open                  |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                |
| Notes:                  |   |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 13R  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Classroom 0105  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Classrooms  |
| Barrier Type:           | Clear Floor Space - Stored Elements   |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | andard: No Quantity: JOB As-built : 1   |
| Barrier<br>Description: | Clear floor space for wheelchair not provided at control or mechanism                 |
| Findings:               | Instructors desk blocks clear floor space at phone                                    |
| Rec. Solution:          | Rearrange desks to provide accessible circulation route                               |
| Barrier Severity:       | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open                    |
| Implementation          |   |
| Notes:                  |   |



| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 13S                       |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Classroom 0105   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Classrooms   |
| Barrier Type:           | Actuator/Control - Side Reach High Unobstructed                      |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                               |
| Barrier<br>Description: | Control or mechanism not at min. 15" or max. 48" high                |
| Findings:               | Phone 50" high   |
| Rec. Solution:          | Relocate control or mechanism to min. 15" or max. 48" high           |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |
| Field Date:             | 1/27/2017 Report Date 2/22/2017 Barrier #: 13T                       |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                |
| Location:               | Floor 1 - Classroom 0105   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Classrooms   |
| Barrier Type:           | Passageway - Min. 36" (Stored Item)                                  |
| Code<br>References:     | 2010 ADAS 404.2.9  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                               |
| Barrier<br>Description: | Passageway is not min. 36" wide                                      |
| Findings:               | Circulation route through classroom not min. 36"                     |
| Rec. Solution:          | Rearrange desks to provide accessible circulation route              |
| Barrier Severity:       | 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |



| Field Date:                         | 1/27/2017 Report Date 2/22/2017 Barrier #: 13U  |
|-------------------------------------|---|
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:                           | Floor 1 - Classroom 0105  |
| X Coordinate:                       | N/A Y Coordinate: N/A   |
| Barrier Area:                       | Classrooms  |
| Barrier Type:                       | Desk - Integration  |
| Code<br>References:                 | 2010 ADAS 307.2   |
| Performance Sta                     | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:             | Desk not integrated into assembly seating   |
| Findings:                           | Desk identified as accessible is not integrated into typical seating                        |
| Rec. Solution:                      | Move desk to integrated setting   |
| Barrier Severity:                   | 2 Necessary Cost Est \$875.00 Facility Function: Public Status: Open                        |
| Implementation                      | Priority: 2 Implementation Phase: Implementation Date:                                      |
| Notes: 36 total                     | desks with 2 desks identified as accessible located in front of classroom                   |
| Field Date:                         | 1/27/2017 Report Date 2/22/2017 Barrier #: 13V  |
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:                           | Floor 1 - Classroom 0105  |
| X Coordinate:                       | N/A Y Coordinate: N/A   |
| Barrier Area:                       | Classrooms  |
| Barrier Type:                       | Alarm - No Horn/Strobe  |
| Code<br>References:                 | 2010 ADAS 702.1   |
| Performance Sta                     | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:             | Where a fire alarm is installed, no horn/strobe provided                                    |
| Findings:                           |   |
|                                     | No device provided  |
| Rec. Solution:                      | No device provided  Provide horn/strobe   |
| Rec. Solution:<br>Barrier Severity: |   |
|                                     | Provide horn/strobe  1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open |



| Field Date:             | 1/28/2017 Report Date 2/22/2017 Barrier #: 14A                               |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Room 0107A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Hardware - Operation   |
| Code<br>References:     | 2010 ADAS 404.2.7  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Hardware not operable with a closed fist                                     |
| Findings:               | Door hardware not operable with a closed fist                                |
| Rec. Solution:          | Provide new hardware   |
| Barrier Severity:       | 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open         |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                       |
| Notes: No visua         | al sign  |
| Field Date:             | 1/28/2017 Report Date 2/22/2017 Barrier #: 14B                               |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Room 0107A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Front App/pull 60" - Blocked   |
| Code<br>References:     | 2010 ADAS Figure 404.2.4.1   |
| Performance Sta         | ndard: No Quantity: ADMINI As-built : 1                                      |
| Barrier<br>Description: | Door/Gate at with min. 18" at pull side lacks min. 60" perpendicular to door |
| Findings:               | Table reduces perpendicular door clearance to 46-1/2"                        |
| · ·                     |  |
| Rec. Solution:          | Rearrange furniture to provide accessible maneuvering clearance              |
| _                       |  |
| Rec. Solution:          | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open           |



| Field Date:             | 1/28/2017 Report Date 2/22/2017 Barrier #: 14C  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Room 0107A  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Doors or Gates  |
| Barrier Type:           | Front App/push 12" SEC  |
| Code<br>References:     | 2010 ADAS Figure 404.2.4.1  |
| Performance Sta         | andard: No Quantity: ADMINI As-built : 1  |
| Barrier<br>Description: | Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer |
| Findings:               | Trash bin and desk blocks strike edge clearance   |
| Rec. Solution:          | Remove stored item  |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open                          |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                      |
| Notes:                  |   |
| Field Date:             | 1/28/2017 Report Date 2/22/2017 Barrier #: 14D  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Room 0107A  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Controls and Mechanisms   |
| Barrier Type:           | Clear Floor Space - Stored Elements   |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | andard: No Quantity: JOB As-built : 0   |
| Barrier<br>Description: | Clear floor space for wheelchair not provided at control or mechanism                       |
| Findings:               | Shelves block clear floor space at electrical outlet  |
| Rec. Solution:          | Rearrange furniture to provide accessible maneuvering clearance                             |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open                          |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                      |
| Notes:                  |   |



| Field Date:   | 1/28/2017 Report Date 2/22/2017 Barrier #: 14E   |
|---|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:   | Floor 1 - Room 0107A   |
| X Coordinate:   | N/A Y Coordinate: N/A  |
| Barrier Area:   | Controls and Mechanisms  |
| Barrier Type:   | Shelves or Cabinets  |
| Code<br>References:   | 2010 ADAS 305.3  |
| Performance Sta   | ndard: No Quantity: JOB As-built : 1   |
| Barrier<br>Description:   | Shelf or cabinet not mounted max. 48" above floor or ground  |
| Findings:   | Shelf or cabinet not accessible. Provide assistance.   |
| Rec. Solution:  | Provide additional shelf at accessible height or provide assistance  |
| Barrier Severity:   | 3 Hindrance Cost Est \$0.00 Facility Function: Public Status: Open   |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes: 3 shelvir  | ng units provided in room.   |
|   |  |
| Field Date:   | 1/28/2017 Report Date 2/22/2017 Barrier #: 14F   |
| Bldg Name:  | 1/28/2017Report Date2/22/2017Barrier #:14FMerryfield HallReference Dwg:2 of 3  |
|   |  |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
| Bldg Name:<br>Location:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Room 0107A  N/A  Y Coordinate: N/A  Controls and Mechanisms  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Room 0107A  N/A  Y Coordinate: N/A   |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Room 0107A  N/A  Y Coordinate: N/A  Controls and Mechanisms  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Room 0107A  N/A  Y Coordinate: N/A  Controls and Mechanisms  Clear Floor Space - Stored Elements  2010 ADAS 305.3  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Room 0107A  N/A  Y Coordinate: N/A  Controls and Mechanisms  Clear Floor Space - Stored Elements  2010 ADAS 305.3  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Room 0107A  N/A  Y Coordinate: N/A  Controls and Mechanisms  Clear Floor Space - Stored Elements  2010 ADAS 305.3  ndard: No Quantity: JOB As-built: 1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Room 0107A  N/A Y Coordinate: N/A  Controls and Mechanisms  Clear Floor Space - Stored Elements  2010 ADAS 305.3  ndard: No Quantity: JOB As-built: 1  Clear floor space for wheelchair not provided at control or mechanism  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Room 0107A N/A Y Coordinate: N/A  Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3  ndard: No Quantity: JOB As-built: 1  Clear floor space for wheelchair not provided at control or mechanism  Desk blocks clear floor space at electrical switch  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Room 0107A N/A Y Coordinate: N/A  Controls and Mechanisms Clear Floor Space - Stored Elements 2010 ADAS 305.3  ndard: No Quantity: JOB As-built: 1  Clear floor space for wheelchair not provided at control or mechanism  Desk blocks clear floor space at electrical switch  Move stored items  1 Necessary  Cost Est \$125.00  Facility Function: Public Status: Open |



| Field Date:               | 1/28/2017 Report Date 2/22/2017 Barrier #: 14G  |
|---------------------------|---|
| Bldg Name:                | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:                 | Floor 1 - Room 0107A  |
| X Coordinate:             | N/A Y Coordinate: N/A   |
| Barrier Area:             | Controls and Mechanisms   |
| Barrier Type:             | Electrical Switches - Height  |
| Code<br>References:       | 2010 ADAS 308.2   |
| Performance Sta           | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:   | Light switch control box top edge not at max. 48" high  |
| Findings:                 | 50" high  |
| Rec. Solution:            | Relocate switch box top edge to max. 48" high   |
| Barrier Severity:         | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open                                  |
| Implementation            | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes: Door she side of d | own at left leads to lounge 107 but door is not in operation. Door does not exist on Lounge 107 loor. |
| Field Date:               | 1/28/2017 Report Date 2/22/2017 Barrier #: 14H  |
| Bldg Name:                | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:                 | Floor 1 - Room 0107A  |
| X Coordinate:             | N/A Y Coordinate: N/A   |
| Barrier Area:             | Counters and Tables   |
| Barrier Type:             | Desk - Knee Clearance   |
| Code<br>References:       | 2010 ADAS 902.3   |
| Performance Sta           | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:   | Knee clearance not min. 27" high, 19" deep or 30" wide  |
| Findings:                 | 24-1/2" to 26-1/4" high and 20" to 28" wide knee clearance at 8 desks                                 |
| Rec. Solution:            | Provide min. one accessible desk or workstation   |
| Barrier Severity:         | 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open                                  |
| Implementation            | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes: No acces           | ssible desks provided in room   |



| Field Date:             | 1/28/2017 Report Date 2/22/2017 Barrier #: 14I                         |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                  |
| Location:               | Floor 1 - Room 0107A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Controls and Mechanisms  |
| Barrier Type:           | Coat Hook - Clear Floor Space  |
| Code<br>References:     | 2010 ADAS 603.4  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                  |
| Barrier<br>Description: | Clothing hooks not located within 30" x 48" clear floor space          |
| Findings:               | Desk blocks clear floor space at coat hook                             |
| Rec. Solution:          | Provide additional hook in accessible location                         |
| Barrier Severity:       | 2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                 |
| Notes:                  |  |
| Field Date:             | 1/28/2017 Report Date 2/22/2017 Barrier #: 14J                         |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                  |
| Location:               | Floor 1 - Room 0107A   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Controls and Mechanisms  |
| Barrier Type:           | Coat Hook - Height   |
| Code<br>References:     | 2010 ADAS 308.2  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 0                                  |
| Barrier<br>Description: | Clothing hooks not max. 48" high AFF                                   |
| Findings:               | 73" high   |
| Rec. Solution:          | Provide additional hook in accessible location                         |
| Barrier Severity:       | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open   |
| Implementation          |  |
| Notes:                  |  |



| Field Date:   | 1/28/2017 Report Date 2/22/2017 Barrier #: 14K  |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:   | Floor 1 - Room 0107A  |
| X Coordinate:   | N/A Y Coordinate: N/A   |
| Barrier Area:   | Turning Space   |
| Barrier Type:   | Circular Turning Space - Min. 60"   |
| Code<br>References:   | 2010 ADAS 304.3.1   |
| Performance Sta   | ndard: No Quantity: SF As-built : 0   |
| Barrier<br>Description:   | Circular turning space not minimum of 60" in diameter (including toe/knee space)  |
| Findings:   | 60" turning circle not provided   |
| Rec. Solution:  | Rearrange furniture to provide accessible maneuvering clearance   |
| Barrier Severity:   | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 3 Implementation Phase: Implementation Date:  |
| Notes:  |   |
| Field Date:   | 1/28/2017 Report Date 2/22/2017 Barrier #: 14L  |
| ricia bate.   | 1/28/2017 Report Date   2/22/2017 Barrier #.   14L  |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
|   |   |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Room 0107A  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Room 0107A  N/A  Y Coordinate: N/A  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Room 0107A  N/A  Y Coordinate: N/A  Controls and Mechanisms   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Room 0107A N/A Y Coordinate: N/A  Controls and Mechanisms Electrical Outlets - Hi/Low Reach 2010 ADAS 308.2.2   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Room 0107A N/A Y Coordinate: N/A  Controls and Mechanisms Electrical Outlets - Hi/Low Reach 2010 ADAS 308.2.2   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Room 0107A N/A Y Coordinate: N/A  Controls and Mechanisms Electrical Outlets - Hi/Low Reach 2010 ADAS 308.2.2  Indard: No Quantity: EACH As-built: 1  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Room 0107A  N/A  Y Coordinate: N/A  Controls and Mechanisms  Electrical Outlets - Hi/Low Reach  2010 ADAS 308.2.2  Indard: No Quantity: EACH As-built: 1  Use of outlet involves low reach of less than 15" above floor or more than 48" high  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Room 0107A N/A Y Coordinate: N/A Controls and Mechanisms Electrical Outlets - Hi/Low Reach 2010 ADAS 308.2.2  Indard: No Quantity: EACH As-built: 1 Use of outlet involves low reach of less than 15" above floor or more than 48" high  Relocate outlet to area at min. 15" or max. 48" high   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Room 0107A  N/A  Y Coordinate: N/A  Controls and Mechanisms  Electrical Outlets - Hi/Low Reach  2010 ADAS 308.2.2  Indard: No Quantity: EACH As-built: 1  Use of outlet involves low reach of less than 15" above floor or more than 48" high  48-1/2" high  Relocate outlet to area at min. 15" or max. 48" high  3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open |



| Field Date:   | 1/28/2017 Report Date 2/22/2017 Barrier #: 14M  |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:   | Floor 1 - Room 0107A  |
| X Coordinate:   | N/A Y Coordinate: N/A   |
| Barrier Area:   | Alarms  |
| Barrier Type:   | Horn/Strobe - Common Use Area   |
| Code<br>References:   | 2010 ADAS 702.1   |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:   | No horn/strobes in common use areas   |
| Findings:   | No device provided  |
| Rec. Solution:  | Provide strobe in common use area   |
| Barrier Severity:   | 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 1 Implementation Phase: Implementation Date:  |
| Notes:  |   |
|   |   |
| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 15A  |
| Bldg Name:  | 1/26/2017   Report Date   2/22/2017   Barrier #:   15A   Merryfield Hall   Reference Dwg:   2 of 3  |
|   |   |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 2 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 0113   |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Women's Restroom 0113  N/A  Y Coordinate: N/A   |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Women's Restroom 0113  N/A  Y Coordinate: N/A  Restrooms  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Women's Restroom 0113  N/A  Y Coordinate: N/A  Restrooms  Sign - ISA at Accessible Restroom  2010 ADAS 216.8  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Women's Restroom 0113  N/A  Y Coordinate: N/A  Restrooms  Sign - ISA at Accessible Restroom  2010 ADAS 216.8  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier                                       | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 0113 N/A Y Coordinate: N/A Restrooms Sign - ISA at Accessible Restroom 2010 ADAS 216.8  ndard: No Quantity: EACH As-built: 1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Women's Restroom 0113  N/A  Y Coordinate: N/A  Restrooms  Sign - ISA at Accessible Restroom  2010 ADAS 216.8  ndard: No Quantity: EACH As-built: 1  No ISA symbol on wall sign posted at accessible toilet room   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 0113 N/A Y Coordinate: N/A Restrooms Sign - ISA at Accessible Restroom 2010 ADAS 216.8  ndard: No Quantity: EACH As-built: 1 No ISA symbol on wall sign posted at accessible toilet room  No ISA sign provided at restroom   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Women's Restroom 0113  N/A Y Coordinate: N/A  Restrooms Sign - ISA at Accessible Restroom 2010 ADAS 216.8  ndard: No Quantity: EACH As-built: 1  No ISA symbol on wall sign posted at accessible toilet room  No ISA sign provided at restroom  Provide ISA symbol on restroom wall sign  1 Necessary  Cost Est \$250.00  Facility Function: Public Status: Open |



| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 15B   |
|---|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:   | Floor 1 - Women's Restroom 0113  |
| X Coordinate:   | N/A Y Coordinate: N/A  |
| Barrier Area:   | Signage  |
| Barrier Type:   | Braille - On Door  |
| Code<br>References:   | 2010 ADAS 703.4.2  |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:   | Sign containing Braille/tactile info located on a door   |
| Findings:   | Tactile sign on door could present a hazard for the visually impaired when reading   |
| Rec. Solution:  | Move sign to wall at latch side of door  |
| Barrier Severity:   | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open   |
| Implementation  | Priority: 3 Implementation Phase: Implementation Date:   |
| Notes:  |  |
|   |  |
| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 15C   |
| Field Date:<br>Bldg Name:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 15C  Merryfield Hall Reference Dwg: 2 of 3  |
|   |  |
| Bldg Name:  | Merryfield Hall Reference Dwg: 2 of 3  |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 0113  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Women's Restroom 0113  N/A  Y Coordinate: N/A  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Women's Restroom 0113  N/A  Y Coordinate: N/A  Restrooms   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Women's Restroom 0113  N/A  Y Coordinate: N/A  Restrooms  Door Closer - Interior Automatic Door  2010 ADAS 404.2.9   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Women's Restroom 0113  N/A  Y Coordinate: N/A  Restrooms  Door Closer - Interior Automatic Door  2010 ADAS 404.2.9   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Women's Restroom 0113  N/A Y Coordinate: N/A  Restrooms  Door Closer - Interior Automatic Door  2010 ADAS 404.2.9  ndard: No Quantity: EACH As-built: 1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 2 of 3  Floor 1 - Women's Restroom 0113  N/A Y Coordinate: N/A  Restrooms  Door Closer - Interior Automatic Door  2010 ADAS 404.2.9  ndard: No Quantity: EACH As-built: 1  Door opening force exceeds 5 lbf   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 2 of 3 Floor 1 - Women's Restroom 0113 N/A Y Coordinate: N/A Restrooms Door Closer - Interior Automatic Door 2010 ADAS 404.2.9  ndard: No Quantity: EACH As-built: 1  Door opening force exceeds 5 lbf  16 lbf  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 2 of 3  Floor 1 - Women's Restroom 0113  N/A Y Coordinate: N/A  Restrooms  Door Closer - Interior Automatic Door  2010 ADAS 404.2.9  ndard: No Quantity: EACH As-built: 1  Door opening force exceeds 5 lbf  16 lbf  Provide automatic door opening device  1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open |



| Field Date:                         | 1/26/2017 Report Date 2/22/2017 Barrier #: 15D                                   |
|-------------------------------------|--|
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:                           | Floor 1 - Women's Restroom 0113  |
| X Coordinate:                       | N/A Y Coordinate: N/A  |
| Barrier Area:                       | Restrooms  |
| Barrier Type:                       | Door Closer - Interior Sweep Period  |
| Code<br>References:                 | 2010 ADAS 404.2.8.1  |
| Performance Sta                     | ndard: No Quantity: EACH As-built : 0  |
| Barrier<br>Description:             | Door closer lacks min. 5 second sweep period or does not stop 5" from door frame |
| Findings:                           | 3 second sweep   |
| Rec. Solution:                      | Provide automatic door opening device  |
| Barrier Severity:                   | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open             |
| Implementation                      | Priority: 3 Implementation Phase: Implementation Date:                           |
| Notes:                              |  |
| Field Date:                         | 1/26/2017 Report Date 2/22/2017 Barrier #: 15E                                   |
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:                           | Floor 1 - Women's Restroom 0113  |
| X Coordinate:                       | N/A Y Coordinate: N/A  |
| Barrier Area:                       | Restrooms  |
| Barrier Type:                       | Door Clearance - SEC Blocked   |
| Code<br>References:                 | 2010 ADAS Figure 404.2.4.3   |
| Performance Sta                     | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:             | Trash bin or stored items block strike edge clearance at exit side of door       |
| Findings:                           | Trash bin blocks strike edge clearance   |
| Rec. Solution:                      | Relocate items   |
|                                     |  |
| Barrier Severity:                   | 2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open           |
| Barrier Severity:<br>Implementation |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 15F  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Women's Restroom 0113   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Restrooms   |
| Barrier Type:           | Dispensers - Protruding Object  |
| Code<br>References:     | 2010 ADAS 307.2   |
| Performance Sta         | andard: No Quantity: EACH As-built : 2  |
| Barrier<br>Description: | Protruding dispenser creates protruding object in path of travel  |
| Findings:               | Paper towel and soap dispensers protrude 5-3/4" and 10" at 34" and 44" high. Trash bin is not a permanent warning |
| Rec. Solution:          | Relocate dispenser or provide cane-detectable warning   |
| Barrier Severity:       | 2 Recommended Cost Est \$1,100.00 Facility Function: Public Status: Open  |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:  |
| Notes:                  |   |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 15G  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Women's Restroom 0113   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Restrooms   |
| Barrier Type:           | Lavatory - Rim Height   |
| Code<br>References:     | 2010 ADAS 606.3   |
| Performance Sta         | andard: No Quantity: JOB As-built : 1   |
| Barrier<br>Description: | Lavatory rim or counter edge is higher than 34" AFF   |
| Findings:               | 35" high  |
| Rec. Solution:          | Remount lavatory  |
| Barrier Severity:       | 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open  |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:  |
| Notes:                  |   |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 15H                               |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Women's Restroom 0113  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Lavatory - Drainpipes  |
| Code<br>References:     | 2010 ADAS 606.5  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                                       |
| Barrier<br>Description: | Hot water and drainpipes accessible under lavatory not insulated or covered  |
| Findings:               | Insulation does not fully cover drain pipes                                  |
| Rec. Solution:          | Insulate drainpipes and hot water pipes                                      |
| Barrier Severity:       | 2 Recommended Cost Est \$220.00 Facility Function: Public Status: Open       |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                       |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 15I                               |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Women's Restroom 0113  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Mirror   |
| Code<br>References:     | 2010 ADAS 603.3  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                                       |
| Barrier<br>Description: | Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface |
| Findings:               | 42" high   |
| Rec. Solution:          | Replace or remount mirror  |
| Barrier Severity:       | 3 Hindrance Cost Est \$375.00 Facility Function: Public Status: Open         |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                       |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 15J  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Women's Restroom 0113   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Restrooms   |
| Barrier Type:           | Floor Drain - Existing  |
| Code<br>References:     | 2010 ADAS 304.2   |
| Performance Sta         | ndard: No Quantity: SF As-built: 80   |
| Barrier<br>Description: | Floor drain located within clear floor space of fixture                                     |
| Findings:               | 1/4" abrupt lip at drain inlet in center of room and in front of lavatory clear floor space |
| Rec. Solution:          | Remodel drain inlet and floor with a flush transition to drain with a max. 2.0% slope       |
| Barrier Severity:       | 3 Hindrance Cost Est \$20,000.00 Facility Function: Public Status: Open                     |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                                      |
| Notes:                  |   |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 15K  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Women's Restroom 0113   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Restrooms   |
| Barrier Type:           | Toilet - Rear Grab Bar  |
| Code<br>References:     | 2010 ADAS 604.5.2   |
| Performance Sta         | ndard: No Quantity: JOB As-built : 1  |
| Barrier<br>Description: | Rear grab bar not at least 36" long   |
| Findings:               | 30-1/2" long  |
| Rec. Solution:          | Replace grab bars with reinforcement  |
| Barrier Severity:       | 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open                        |
| Implementation          |   |
| Notes:                  |   |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 15L                           |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                    |
| Location:               | Floor 1 - Women's Restroom 0113  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Toilet - Rear Grab Bar   |
| Code<br>References:     | 2010 ADAS 604.5.2  |
| Performance Sta         | andard: No Quantity: JOB As-built : 1                                    |
| Barrier<br>Description: | Rear grab bar not centered 12" from wall and 24" on the other side of WC |
| Findings:               | 15" on center  |
| Rec. Solution:          | Replace grab bars with reinforcement                                     |
| Barrier Severity:       | 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open     |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                   |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 15M                           |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                    |
| Location:               | Floor 1 - Women's Restroom 0113  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Toilet - Side Grab Bar   |
| Code<br>References:     | 2010 ADAS 604.5.1  |
| Performance Sta         | andard: No Quantity: JOB As-built : 1                                    |
| Barrier<br>Description: | Side grab bar does not extend min. 54" from rear wall                    |
| Findings:               | 47" from rear wall   |
| Rec. Solution:          | Replace grab bars with reinforcement                                     |
| Barrier Severity:       | 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open     |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                   |
| Notes:                  |  |



| Field Date:                         | 1/26/2017 Report Date 2/22/2017 Barrier #: 15N                                   |
|-------------------------------------|--|
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:                           | Floor 1 - Women's Restroom 0113  |
| X Coordinate:                       | N/A Y Coordinate: N/A  |
| Barrier Area:                       | Restrooms  |
| Barrier Type:                       | Toilet Transfer - Floor-mounted  |
| Code<br>References:                 | 2010 ADAS 604.8.1.1  |
| Performance Sta                     | ndard: No Quantity: SF As-built : 25   |
| Barrier<br>Description:             | Min. 60" wide x 59" deep clear floor space not provided at floor-mounted fixture |
| Findings:                           | 38-1/2" from wall to lavatory  |
| Rec. Solution:                      | Remodel to provide front transfer space  |
| Barrier Severity:                   | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open             |
| Implementation                      | Priority: 3 Implementation Phase: Implementation Date:                           |
| Notes:                              |  |
| Field Date:                         | 1/26/2017 Report Date 2/22/2017 Barrier #: 150                                   |
| Bldg Name:                          | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:                           | Floor 1 - Women's Restroom 0113  |
| X Coordinate:                       | N/A Y Coordinate: N/A  |
| Barrier Area:                       | Restrooms  |
| Barrier Type:                       | Toilet Paper Dispenser   |
| Code<br>References:                 | 2010 ADAS 604.7  |
| Performance Sta                     | ndard: No Quantity: EACH As-built: 1   |
| Barrier<br>Description:             | Toilet tissue dispenser not within 7" to 9" from front edge of toilet            |
| Findings:                           | 11" from rim   |
| Rec. Solution:                      | Reposition or replace toilet paper dispenser                                     |
|                                     | Inchosition of replace toller paper disperiser                                   |
| Barrier Severity:                   |  |
| Barrier Severity:<br>Implementation | 3 Hindrance Cost Est \$225.00 Facility Function: Public Status: Open             |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 15P                                   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Women's Restroom 0113  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Seat Cover Dispenser   |
| Code<br>References:     | 2010 ADAS 307.2  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Seat cover dispenser not located on an accessible route. Blocked by water closet |
| Findings:               | Access to dispenser blocked by water closet                                      |
| Rec. Solution:          | Replace or remount dispenser on an accessible route with clear floor space       |
| Barrier Severity:       | 2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open           |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 15Q                                   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Women's Restroom 0113  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Alarm - Horn/Strobe  |
| Code<br>References:     | 2010 ADAS 702.1  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Where a fire alarm is installed, no horn/strobe provided                         |
| Findings:               | No device provided   |
| Rec. Solution:          | Provide horn/strobe in sanitary facility   |
| Barrier Severity:       | 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open           |
| Implementation          |  |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 16A                                     |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Men's Restroom 0112  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Signage  |
| Barrier Type:           | Braille - On Door  |
| Code<br>References:     | 2010 ADAS 703.4.2  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Sign containing Braille/tactile info located on a door                             |
| Findings:               | Tactile sign on door could present a hazard for the visually impaired when reading |
| Rec. Solution:          | Move sign to wall at latch side of door  |
| Barrier Severity:       | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open               |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                             |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 16B                                     |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Men's Restroom 0112  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Door Closer - Interior Automatic Door  |
| Code<br>References:     | 2010 ADAS 404.2.9  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Door opening force exceeds 5 lbf   |
| Findings:               | 14 lbf   |
| Rec. Solution:          | Provide automatic door opening device  |
| Barrier Severity:       | 1 Necessary Cost Est \$5,000.00 Facility Function: Public Status: Open             |
| Implementation          |  |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 16C                                   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Men's Restroom 0112  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Door Closer - Interior Sweep Period  |
| Code<br>References:     | 2010 ADAS 404.2.8.1  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 0  |
| Barrier<br>Description: | Door closer lacks min. 5 second sweep period or does not stop 5" from door frame |
| Findings:               | 2 second sweep   |
| Rec. Solution:          | Provide automatic door opening device  |
| Barrier Severity:       | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open             |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 16D                                   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Men's Restroom 0112  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Controls and Mechanisms  |
| Barrier Type:           | Clear Floor Space - Stored Elements  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | ndard: No Quantity: JOB As-built : 1   |
| Barrier<br>Description: | Clear floor space for wheelchair not provided at control or mechanism            |
| Findings:               | Trash bin blocks clear floor space at electrical switch and outlet               |
| Rec. Solution:          | Move stored item   |
| Barrier Severity:       | 1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open             |
| Implementation          |  |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 16E  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Men's Restroom 0112   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Restrooms   |
| Barrier Type:           | Dispensers - Protruding Object  |
| Code<br>References:     | 2010 ADAS 307.2   |
| Performance Sta         | andard: No Quantity: EACH As-built : 2  |
| Barrier<br>Description: | Protruding dispenser creates protruding object in path of travel                              |
| Findings:               | Paper towel and soap dispensers protrude 5-3/4" and 10" at 35" and 44" high                   |
| Rec. Solution:          | Relocate dispenser or provide cane-detectable warning. Trash bin is not a permanent detectabl |
| Barrier Severity:       | 2 Recommended Cost Est \$1,100.00 Facility Function: Public Status: Open                      |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:  |
| Notes:                  |   |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 16F  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Men's Restroom 0112   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Restrooms   |
| Barrier Type:           | Lavatory - Rim Height   |
| Code<br>References:     | 2010 ADAS 606.3   |
| Performance Sta         | andard: No Quantity: JOB As-built : 1   |
| Barrier<br>Description: | Lavatory rim or counter edge is higher than 34" AFF   |
| Findings:               | 35-1/4" high  |
| Rec. Solution:          | Replace lavatory  |
| Barrier Severity:       | 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open                          |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:  |
| Notes:                  |   |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 16G  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Men's Restroom 0112   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Restrooms   |
| Barrier Type:           | Lavatory - Drainpipes   |
| Code<br>References:     | 2010 ADAS 606.5   |
| Performance Sta         | andard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Hot water and drainpipes accessible under lavatory not insulated or covered                 |
| Findings:               | No insulation provided  |
| Rec. Solution:          | Insulate drainpipes and hot water pipes   |
| Barrier Severity:       | 2 Recommended Cost Est \$220.00 Facility Function: Public Status: Open                      |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                                      |
| Notes:                  |   |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 16H  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3   |
| Location:               | Floor 1 - Men's Restroom 0112   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Restrooms   |
| Barrier Type:           | Floor Drain - Existing  |
| Code<br>References:     | 2010 ADAS 304.2   |
| Performance Sta         | andard: No Quantity: SF As-built: 80  |
| Barrier<br>Description: | Floor drain located within clear floor space of fixture                                     |
| Findings:               | 1/4" abrupt lip at drain inlet in center of room and in front of lavatory clear floor space |
| Rec. Solution:          | Remodel drain inlet and floor with a flush transition to drain with a max. 2.0% slope       |
| Barrier Severity:       | 3 Hindrance Cost Est \$20,000.00 Facility Function: Public Status: Open                     |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                                      |
| Notes:                  |   |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 16I                           |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                    |
| Location:               | Floor 1 - Men's Restroom 0112  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Toilet - Rear Grab Bar   |
| Code<br>References:     | 2010 ADAS 604.5.2  |
| Performance Sta         | ndard: No Quantity: JOB As-built : 1                                     |
| Barrier<br>Description: | Rear grab bar not at least 36" long                                      |
| Findings:               | 30-1/2" long   |
| Rec. Solution:          | Replace grab bars with reinforcement                                     |
| Barrier Severity:       | 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open     |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                   |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 16J                           |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                    |
| Location:               | Floor 1 - Men's Restroom 0112  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Toilet - Rear Grab Bar   |
| Code<br>References:     | 2010 ADAS 604.5.2  |
| Performance Sta         | ndard: No Quantity: JOB As-built : 1                                     |
| Barrier<br>Description: | Rear grab bar not centered 12" from wall and 24" on the other side of WC |
| Findings:               | 14-1/2" on center  |
| Rec. Solution:          | Replace grab bars with reinforcement                                     |
| Barrier Severity:       | 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open     |
| Implementation          |  |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 16K                                   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Men's Restroom 0112  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Toilet - Side Grab Bar   |
| Code<br>References:     | 2010 ADAS 604.5.1  |
| Performance Sta         | andard: No Quantity: JOB As-built : 1  |
| Barrier<br>Description: | Side grab bar does not extend min. 54" from rear wall                            |
| Findings:               | 46-1/2" from rear wall   |
| Rec. Solution:          | Replace grab bars with reinforcement   |
| Barrier Severity:       | 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open             |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 16L                                   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Men's Restroom 0112  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Toilet Transfer - Floor-mounted  |
| Code<br>References:     | 2010 ADAS 604.8.1.1  |
| Performance Sta         | andard: No Quantity: SF As-built: 25   |
| Barrier<br>Description: | Min. 60" wide x 59" deep clear floor space not provided at floor-mounted fixture |
| Findings:               | 38" wide from wall to lavatory   |
| Rec. Solution:          | Remodel to provide front transfer space  |
| Barrier Severity:       | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open             |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 16M                        |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                 |
| Location:               | Floor 1 - Men's Restroom 0112   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Restrooms   |
| Barrier Type:           | Toilet - Flush Handle   |
| Code<br>References:     | 2010 ADAS 604.6   |
| Performance Sta         | ndard: No Quantity: JOB As-built : 1                                  |
| Barrier<br>Description: | Handle does not point to wide side of stall or compartment            |
| Findings:               | Handle pointing towards small side of stall/room                      |
| Rec. Solution:          | Replace water closet  |
| Barrier Severity:       | 1 Necessary Cost Est \$850.00 Facility Function: Public Status: Open  |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                |
| Notes:                  |   |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 16N                        |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                 |
| Location:               | Floor 1 - Men's Restroom 0112   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Restrooms   |
| Barrier Type:           | Toilet Paper Dispenser  |
| Code<br>References:     | 2010 ADAS 604.7   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                 |
| Barrier<br>Description: | Toilet tissue dispenser not within 7" to 9" from front edge of toilet |
| Findings:               | 11" from rim  |
| Rec. Solution:          | Reposition or replace toilet paper dispenser                          |
| Barrier Severity:       | 3 Hindrance Cost Est \$225.00 Facility Function: Public Status: Open  |
| Implementation          |   |
| Notes:                  | · · · · · · · · · · · · · · · · · · ·                                 |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 160                                   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Men's Restroom 0112  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Seat Cover Dispenser   |
| Code<br>References:     | 2010 ADAS 307.2  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Seat cover dispenser not located on an accessible route. Blocked by water closet |
| Findings:               | Access to dispenser blocked by water closet                                      |
| Rec. Solution:          | Replace or remount dispenser on an accessible route with clear floor space       |
| Barrier Severity:       | 2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open           |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 16P                                   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Men's Restroom 0112  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Restrooms  |
| Barrier Type:           | Alarm - Horn/Strobe  |
| Code<br>References:     | 2010 ADAS 702.1  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Where a fire alarm is installed, no horn/strobe provided                         |
| Findings:               | No device provided   |
| Rec. Solution:          | Provide horn/strobe in sanitary facility   |
| Barrier Severity:       | 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open           |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |



| Field Date:  | 1/26/2017 Report Date 2/22/2017 Barrier #: 17A   |
|--|--|
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:  | Floor 1 - Stairway S0101   |
| X Coordinate:  | N/A Y Coordinate: N/A  |
| Barrier Area:  | Stairways  |
| Barrier Type:  | Sign - Enclosed Exit Stairway Door   |
| Code<br>References:  | 2010 ADAS 216.4.1  |
| Performance Sta  | ndard: Yes Quantity: EACH As-built : 1   |
| Barrier<br>Description:  | Door leading directly into an exit stairway lacks tactile exit sign  |
| Findings:  | Door to exit stair with low level illuminated sign lacks tactile exit sign   |
| Rec. Solution:   | Provide sign stating "EXIT STAIR DOWN (or UP)" at latch side of door   |
| Barrier Severity:  | 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open   |
| Implementation   | Priority: 3 Implementation Phase: Implementation Date:   |
| Notes:   |  |
| Field Date:  | 1/26/2017 Report Date 2/22/2017 Barrier #: 17B   |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3  |
| •  | INTERPRETATION TO STATE OF THE PROPERTY OF THE |
| Location:  | Floor 1 - Stairway S0101   |
|  |  |
| Location:  | Floor 1 - Stairway S0101   |
| Location:<br>X Coordinate:   | Floor 1 - Stairway S0101  N/A  Y Coordinate: N/A   |
| Location:<br>X Coordinate:<br>Barrier Area:  | Floor 1 - Stairway S0101  N/A Y Coordinate: N/A  Doors or Gates  |
| Location:<br>X Coordinate:<br>Barrier Area:<br>Barrier Type:<br>Code   | Floor 1 - Stairway S0101  N/A  Y Coordinate: N/A  Doors or Gates  Door Closer - Interior Adjustment  2010 ADAS 404.2.9   |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Floor 1 - Stairway S0101  N/A  Y Coordinate: N/A  Doors or Gates  Door Closer - Interior Adjustment  2010 ADAS 404.2.9   |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Floor 1 - Stairway S0101  N/A  Y Coordinate: N/A  Doors or Gates  Door Closer - Interior Adjustment  2010 ADAS 404.2.9  Indard: No Quantity: EACH As-built: 1  |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Floor 1 - Stairway S0101  N/A  Y Coordinate: N/A  Doors or Gates  Door Closer - Interior Adjustment  2010 ADAS 404.2.9  andard: No Quantity: EACH As-built: 1  Door opening force exceeds 5 lbf  |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Floor 1 - Stairway S0101 N/A Y Coordinate: N/A  Doors or Gates  Door Closer - Interior Adjustment 2010 ADAS 404.2.9  Indard: No Quantity: EACH As-built: 1  Door opening force exceeds 5 lbf  Replace or adjust existing closer  |
| Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Floor 1 - Stairway S0101  N/A  Y Coordinate: N/A  Doors or Gates  Door Closer - Interior Adjustment  2010 ADAS 404.2.9  Indard: No Quantity: EACH As-built: 1  Door opening force exceeds 5 lbf  12 lbf  Replace or adjust existing closer  1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open   |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 17C                                   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Stairway S0101   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Door Closer - Interior Sweep Period  |
| Code<br>References:     | 2010 ADAS 404.2.8.1  |
| Performance Sta         | andard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description: | Door closer lacks min. 5 second sweep period or does not stop 5" from door frame |
| Findings:               | 2 second sweep   |
| Rec. Solution:          | Replace closer or provide automatic door opening device                          |
| Barrier Severity:       | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open             |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 17D                                   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Stairway S0101   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Vision Lights - Existing   |
| Code<br>References:     | 2010 ADAS 404.2.11   |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | View panels in or adjacent to doors or gates not max. 43" above floor or ground  |
| Findings:               | 57" high   |
| Rec. Solution:          | Replace door/gate or vision panel  |
| Barrier Severity:       | 3 Hindrance Cost Est \$2,250.00 Facility Function: Public Status: Open           |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 17E   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Stairway S0101   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Stairways  |
| Barrier Type:           | Sign - Enclosed Exit Stairway Discharge  |
| Code<br>References:     | ICC A117.1   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Tactile stairway signage not provided to indicate stair level or discharge level       |
| Findings:               | No sign provided   |
| Rec. Solution:          | Provide sign indicating stair level and discharge level (raised star) where applicable |
| Barrier Severity:       | 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open                 |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                                 |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 17F   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:               | Floor 1 - Stairway S0101   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Stairways  |
| Barrier Type:           | Handrail Extension - Bottom  |
| Code<br>References:     | 2010 ADAS 505.10.3   |
| Performance Sta         | ndard: No Quantity: LF As-built : 2  |
| Barrier<br>Description: | Extension not sloped for length of one tread beyond the last riser nosing              |
| Findings:               | Extension not sloped for the length of one tread long                                  |
| Rec. Solution:          | Provide handrails at both sides of stairway  |
| Barrier Severity:       | 2 Recommended Cost Est \$450.00 Facility Function: Public Status: Open                 |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                                 |
| Notes:                  |  |



| Field Date:  | 1/26/2017 Report Date 2/22/2017 Barrier #: 17G   |
|--|--|
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:  | Floor 1 - Stairway S0101   |
| X Coordinate:  | N/A Y Coordinate: N/A  |
| Barrier Area:  | Stairways  |
| Barrier Type:  | Handrail Extension - Top   |
| Code<br>References:  | 2010 ADAS 505.10.2   |
| Performance Sta  | ndard: No Quantity: LF As-built : 2  |
| Barrier<br>Description:  | Extension does not extend horizontally above landing for min. 12" from first riser nosing  |
| Findings:  | Extension not sloped for the length of one tread long  |
| Rec. Solution:   | Provide handrails at both sides of stairway  |
| Barrier Severity:  | 2 Recommended Cost Est \$450.00 Facility Function: Public Status: Open   |
| Implementation   | Priority: 3 Implementation Phase: Implementation Date:   |
| Notes:   |  |
| Field Date:  | 1/26/2017 Report Date 2/22/2017 Barrier #: 17H   |
| Bldg Name:   | Merryfield Hall Reference Dwg: 2 of 3  |
| Location:  | Floor 1 - Stairway S0101   |
| X Coordinate:  |  |
|  | N/A Y Coordinate: N/A  |
| Barrier Area:  | N/A Y Coordinate: N/A Stairways  |
| Barrier Area:<br>Barrier Type:   |  |
|  | Stairways  |
| Barrier Type:<br>Code  | Stairways Handrail Grip 2010 ADAS 505.10.2   |
| Barrier Type:<br>Code<br>References:   | Stairways Handrail Grip 2010 ADAS 505.10.2   |
| Barrier Type:<br>Code<br>References:<br>Performance Sta<br>Barrier                           | Stairways Handrail Grip 2010 ADAS 505.10.2  ndard: No Quantity: LF As-built: 25  |
| Barrier Type:<br>Code<br>References:<br>Performance Sta<br>Barrier<br>Description:           | Stairways  Handrail Grip  2010 ADAS 505.10.2  ndard: No Quantity: LF As-built: 25  Handrail grip is not continuous   |
| Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Stairways  Handrail Grip  2010 ADAS 505.10.2  ndard: No Quantity: LF As-built: 25  Handrail grip is not continuous  Handrail supports force user to open grip at each support  |
| Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Stairways  Handrail Grip  2010 ADAS 505.10.2  ndard: No Quantity: LF As-built: 25  Handrail grip is not continuous  Handrail supports force user to open grip at each support  Provide handrails at both sides of stairway  2 Recommended Cost Est \$5,625.00 Facility Function: Public Status: Open |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 17I                           |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                    |
| Location:               | Floor 1 - Stairway S0101   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Stairways  |
| Barrier Type:           | Contrasting Color - ADA  |
| Code<br>References:     | 2010 ADAS Advisory 504.4   |
| Performance Sta         | ndard: Yes Quantity: LF or TR As-built : 23                              |
| Barrier<br>Description: | No contrasting color on each tread of interior stairway                  |
| Findings:               | Treads lack contrasting color defined as 70% contrast                    |
| Rec. Solution:          | Recommended: Consider providing contrasting color on each tread          |
| Barrier Severity:       | 2 Recommended Cost Est \$805.00 Facility Function: Public Status: Open   |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                   |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 17J                           |
| Bldg Name:              | Merryfield Hall Reference Dwg: 2 of 3                                    |
| Location:               | Floor 1 - Stairway S0101   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Stairways  |
| Barrier Type:           | Vertical Access - Elevator   |
| Code<br>References:     | 2010 ADAS 403.1  |
| Performance Sta         | ndard: No Quantity: JOB As-built : 1                                     |
| Barrier<br>Description: | No form of vertical access provided at stairway to reach upper floors    |
| Findings:               | No vertical access provided to the second floor                          |
| Rec. Solution:          | Provide a passenger elevator to reach upper floors                       |
| Barrier Severity:       | 1 Necessary Cost Est \$250,000.00 Facility Function: Public Status: Open |
| Implementation          |  |
| Notes:                  | Priority: 3 Implementation Phase: Implementation Date:                   |



| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 18   |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3   |
| Location:   | Floor 2 - Stairway S0201  |
| X Coordinate:   | N/A Y Coordinate: N/A   |
| Barrier Area:   | Stairways   |
| Barrier Type:   | Sign - Enclosed Exit Stairway Level   |
| Code<br>References:   | ICC A117.1  |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:   | Tactile stairway signage not provided to indicate floor level   |
| Findings:   | No sign provided  |
| Rec. Solution:  | Provide sign  |
| Barrier Severity:   | 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 3 Implementation Phase: Implementation Date:  |
| Notes: Second   | floor   |
|   |   |
| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 19A  |
| Field Date:<br>Bldg Name:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 19A  Merryfield Hall Reference Dwg: 3 of 3   |
|   |   |
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Vestibule V0201   |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Vestibule V0201  N/A  Y Coordinate: N/A   |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Vestibule V0201  N/A  Y Coordinate: N/A  Signage  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Vestibule V0201  N/A  Y Coordinate: N/A  Signage  Permanent Room/Space - Tactile Characters  2010 ADAS 216.2  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Vestibule V0201  N/A  Y Coordinate: N/A  Signage  Permanent Room/Space - Tactile Characters  2010 ADAS 216.2  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall Reference Dwg: 3 of 3  Floor 2 - Vestibule V0201  N/A Y Coordinate: N/A  Signage  Permanent Room/Space - Tactile Characters  2010 ADAS 216.2  ndard: No Quantity: EACH As-built: 2  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 3 of 3  Floor 2 - Vestibule V0201  N/A Y Coordinate: N/A  Signage  Permanent Room/Space - Tactile Characters  2010 ADAS 216.2  ndard: No Quantity: EACH As-built: 2  No tactile characters at sign identifying permanent rooms and spaces with visual signs  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 3 of 3 Floor 2 - Vestibule V0201 N/A Y Coordinate: N/A Signage Permanent Room/Space - Tactile Characters 2010 ADAS 216.2  No Quantity: EACH As-built: 2  No tactile characters at sign identifying permanent rooms and spaces with visual signs  No tactile signage provided at doors within public route  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 3 of 3  Floor 2 - Vestibule V0201 N/A Y Coordinate: N/A  Signage Permanent Room/Space - Tactile Characters  2010 ADAS 216.2  No Quantity: EACH As-built: 2  No tactile characters at sign identifying permanent rooms and spaces with visual signs  No tactile signage provided at doors within public route  Provide accessible signs  1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 19B                       |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3                                |
| Location:               | Floor 2 - Vestibule V0201  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Signage  |
| Barrier Type:           | Lobby Info Sign  |
| Code<br>References:     | Performance Standard   |
| Performance Sta         | andard: Yes Quantity: EACH As-built: 1                               |
| Barrier<br>Description: | No lobby informational sign with location of accessible elements     |
| Findings:               | Accessible sign not provided   |
| Rec. Solution:          | Provide lobby informational sign                                     |
| Barrier Severity:       | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:               |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 19C                       |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3                                |
| Location:               | Floor 2 - Vestibule V0201  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Controls and Mechanisms  |
| Barrier Type:           | Electrical Switches - Height   |
| Code<br>References:     | 2010 ADAS 308.2  |
| Performance Sta         | andard: No Quantity: EACH As-built: 1                                |
| Barrier<br>Description: | Light switch control box top edge not at max. 48" high               |
| Findings:               | 49" high   |
| Rec. Solution:          | Relocate switch box top edge to max. 48" high                        |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 19D  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3   |
| Location:               | Floor 2 - Vestibule V0201   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Alarms  |
| Barrier Type:           | Fire Extinguisher - Protruding Object   |
| Code<br>References:     | 2010 ADAS 307.2   |
| Performance Sta         | andard: No Quantity: JOB As-built : 1   |
| Barrier<br>Description: | Fire extinguisher protrudes into circulation path more than 4" between 27" and 80"    |
| Findings:               | Fire extinguisher protrudes 4-1/4" at 33" high  |
| Rec. Solution:          | Remount extinguisher with leading edge below 27" or provide detectable warning        |
| Barrier Severity:       | 4 Low Severity Cost Est \$550.00 Facility Function: Public Status: Open               |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                                |
| Notes:                  |   |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 19E  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3   |
| Location:               | Floor 2 - Vestibule V0201   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Clear Floor Space   |
| Barrier Type:           | Protruding Object   |
| Code<br>References:     | 2010 ADAS 307   |
| Performance Sta         | andard: No Quantity: EACH As-built: 1   |
| Barrier<br>Description: | Protruding object in circulation path protrudes more than 4" between 27" and 80" high |
| Findings:               | Fire riser protrudes 12" at 64" high  |
| Rec. Solution:          | Remove object or provide detectable warning (wing walls)                              |
| Barrier Severity:       | 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open                  |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                                |
| Notes:                  |   |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 19F                               |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3  |
| Location:               | Floor 2 - Vestibule V0201  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Corridors  |
| Barrier Type:           | Floor Surface - Condition  |
| Code<br>References:     | 2010 ADAS 302.1  |
| Performance Sta         | andard: No Quantity: LF As-built : 10  |
| Barrier<br>Description: | Floor surface is not firm and stable (cracked, broken or loose debris, etc.) |
| Findings:               | Tiles are broken or missing and debris covers some floor areas               |
| Rec. Solution:          | Repair surface to make firm and stable                                       |
| Barrier Severity:       | 1 Necessary Cost Est \$1,250.00 Facility Function: Public Status: Open       |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                       |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 19G                               |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3  |
| Location:               | Floor 2 - Vestibule V0201  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Controls and Mechanisms  |
| Barrier Type:           | Clear Floor Space - Stored Elements  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | andard: No Quantity: JOB As-built : 1  |
| Barrier<br>Description: | Clear floor space for wheelchair not provided at control or mechanism        |
| Findings:               | Cabinet blocks clear floor space at electrical outlet                        |
| Rec. Solution:          | Move stored items  |
| Barrier Severity:       | INIOVE Stored Items  |
|                         |  |
| Implementation          | 1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open         |



| Field Date:                         | 1/26/2017 Report Date 2/22/2017 Barrier #: 19H   |
|-------------------------------------|--|
| Bldg Name:                          | Merryfield Hall Reference Dwg: 3 of 3  |
| Location:                           | Floor 2 - Vestibule V0201  |
| X Coordinate:                       | N/A Y Coordinate: N/A  |
| Barrier Area:                       | Controls and Mechanisms  |
| Barrier Type:                       | Electrical Outlets - Hi/Low Reach  |
| Code<br>References:                 | 2010 ADAS 308.2.2  |
| Performance Sta                     | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:             | Use of outlet involves low reach of less than 15" above floor or more than 48" high  |
| Findings:                           | 73" high   |
| Rec. Solution:                      | Relocate outlet to area at min. 15" or max. 48" high   |
| Barrier Severity:                   | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open   |
| Implementation                      | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:                              |  |
| Field Date:                         | 1/26/2017 Report Date 2/22/2017 Barrier #: 19I   |
| Bldg Name:                          | Merryfield Hall Reference Dwg: 3 of 3  |
| Location:                           | Floor 2 - Vestibule V0201  |
| X Coordinate:                       | N/A Y Coordinate: N/A  |
| Barrier Area:                       | Counters and Tables  |
| Barrier Type:                       | Table - Knee Clearance   |
| Code<br>References:                 | 2010 ADAS 305.3  |
| Performance Sta                     | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:             | Knee clearance not min. 27" high, 19" deep or 30" wide   |
| Findings:                           | 26-3/4" high knee clearance  |
|                                     |  |
| Rec. Solution:                      | Provide min. 1 accessible table. Avoid pedestal base tables.   |
| Rec. Solution:<br>Barrier Severity: | Provide min. 1 accessible table. Avoid pedestal base tables.  3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open |
|                                     | 3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open   |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 19J                       |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3                                |
| Location:               | Floor 2 - Vestibule V0201  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Controls and Mechanisms  |
| Barrier Type:           | Mailbox - High Reach Range   |
| Code<br>References:     | 2010 ADAS 308.2.2  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                               |
| Barrier<br>Description: | Mailbox opening is above 48" high                                    |
| Findings:               | 33" - 65" high   |
| Rec. Solution:          | Relocate to provide opening at max. 48" high                         |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 19K                       |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3                                |
| Location:               | Floor 2 - Vestibule V0201  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Alarms   |
| Barrier Type:           | Horn - No Strobe   |
| Code<br>References:     | 2010 ADAS 702  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                               |
| Barrier<br>Description: | Horn provided in location where no strobe is provided                |
| Findings:               | No strobe device provided  |
| Rec. Solution:          | Provide strobe in common use area                                    |
| Barrier Severity:       | 1 Necessary Cost Est \$550.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:               |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 20A                                |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3   |
| Location:               | Floor 2 - Hall H0201  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Signage   |
| Barrier Type:           | Tactile Exit Signs - To Exit Door   |
| Code<br>References:     | Performance Standard  |
| Performance Sta         | ndard: Yes Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Exit door leading directly to an exit to the exterior lacks tactile exit sign |
| Findings:               | Door leading to exit door to exterior lacks tactile exit sign                 |
| Rec. Solution:          | Provide sign stating "EXIT ROUTE" at exit side of door                        |
| Barrier Severity:       | 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open        |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                        |
| Notes:                  |   |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 20B                                |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3   |
| Location:               | Floor 2 - Hall H0201  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Doors or Gates  |
| Barrier Type:           | Hardware - Operation  |
| Code<br>References:     | 2010 ADAS 404.2.7   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Hardware not operable with a closed fist                                      |
| Findings:               | Door hardware not operable with a closed fist                                 |
| Rec. Solution:          | Provide new hardware  |
| Barrier Severity:       | 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open          |
| Implementation          |   |
| Notes:                  |   |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 20C  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3   |
| Location:               | Floor 2 - Hall H0201  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Doors or Gates  |
| Barrier Type:           | Door 10" Bottom Surface - Kickplate   |
| Code<br>References:     | 2010 ADAS 404.2.10  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Door/Gate lacks min. 10" smooth uninterrupted bottom surface                                |
| Findings:               | Bottom of door not smooth and uninterrupted to indented panel at bottom of door             |
| Rec. Solution:          | Provide smooth kick plate min. 10" high at push side of door                                |
| Barrier Severity:       | 1 Necessary Cost Est \$225.00 Facility Function: Public Status: Open                        |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                      |
| Notes:                  |   |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 20D  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3   |
| Location:               | Floor 2 - Hall H0201  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Doors or Gates  |
| Barrier Type:           | Front App/push 12" SEC  |
| Code<br>References:     | 2010 ADAS Figure 404.2.4.1  |
| Performance Sta         | andard: No Quantity: ADMINI As-built : 1  |
| Barrier<br>Description: | Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer |
| Findings:               | Table blocks strike edge clearance at entry to hall   |
| Rec. Solution:          | Remove stored item  |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open                          |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                      |
| Notes:                  |   |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 20E                                      |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3   |
| Location:               | Floor 2 - Hall H0201  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Corridors   |
| Barrier Type:           | Electrical Outlets - Hi/Low Reach   |
| Code<br>References:     | 2010 ADAS 205.1 & 309.3   |
| Performance Sta         | ndard: No Quantity: LF As-built : 1   |
| Barrier<br>Description: | Use of outlet involves low reach of less than 15" above floor or more than 48" high |
| Findings:               | 13" high  |
| Rec. Solution:          | Relocate outlet to area at min. 15" or max. 48" high                                |
| Barrier Severity:       | 2 Recommended Cost Est \$225.00 Facility Function: Public Status: Open              |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 20F                                      |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3   |
| Location:               | Floor 2 - Hall H0201  |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Corridors   |
| Barrier Type:           | Horn/Strobe Device  |
| Code<br>References:     | 2010 ADAS 702.1   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | No horn or strobe in corridor where fire alarm exists in building                   |
| Findings:               | No horn/strobe provided   |
| Rec. Solution:          | Provide horn/strobe in common use area  |
| Barrier Severity:       | 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open              |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 20G                             |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3                                      |
| Location:               | Floor 2 - Hall H0201   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Signage  |
| Barrier Type:           | Tactile Exit Signs - Stairway  |
| Code<br>References:     | Performance Standard   |
| Performance Sta         | ndard: Yes Quantity: EACH As-built : 1                                     |
| Barrier<br>Description: | Door leading directly into an exit stairway lacks tactile exit sign        |
| Findings:               | Door to exit stair with low level illuminated sign lacks tactile exit sign |
| Rec. Solution:          | Provide sign stating "EXIT STAIR DOWN (or UP)" at latch side of door       |
| Barrier Severity:       | 2 Recommended Cost Est \$250.00 Facility Function: Public Status: Open     |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                     |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 20H                             |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3                                      |
| Location:               | Floor 2 - Hall H0201   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Doormat  |
| Code<br>References:     | 2010 ADAS 302.2 & Advisory 302.2   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                      |
| Barrier<br>Description: | Doormat not anchored to floor (possible trip hazard)                       |
| Findings:               | Doormat not secured  |
| Rec. Solution:          | Secure exiting doormat or replace  |
| Barrier Severity:       | 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open       |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                     |
| Notes:                  |  |



| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 201   |
|---|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3  |
| Location:   | Floor 2 - Hall H0201   |
| X Coordinate:   | N/A Y Coordinate: N/A  |
| Barrier Area:   | Doors or Gates   |
| Barrier Type:   | Door Closer - Exterior Adjustment  |
| Code<br>References:   | Performance Standard   |
| Performance Sta   | ndard: Yes Quantity: EACH As-built : 1   |
| Barrier<br>Description:   | Door opening force exceeds 8.5 lbf   |
| Findings:   | 15 lbf   |
| Rec. Solution:  | Replace or adjust existing closer  |
| Barrier Severity:   | 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open   |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:  |  |
| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 20J   |
|   | 1/26/2017 Report Date   2/22/2017 Barrier #:   20J   |
| Bldg Name:  | Merryfield Hall  Reference Dwg: 3 of 3   |
|   |  |
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3  |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 3 of 3 Floor 2 - Hall H0201   |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Hall H0201  N/A  Y Coordinate: N/A   |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Hall H0201  N/A  Y Coordinate: N/A  Doors or Gates   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Hall H0201  N/A  Y Coordinate: N/A  Doors or Gates  Door Closer - Exterior Sweep Period  2010 ADAS 404.2.8.1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Hall H0201  N/A  Y Coordinate: N/A  Doors or Gates  Door Closer - Exterior Sweep Period  2010 ADAS 404.2.8.1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall Reference Dwg: 3 of 3  Floor 2 - Hall H0201  N/A  Y Coordinate: N/A  Doors or Gates  Door Closer - Exterior Sweep Period  2010 ADAS 404.2.8.1  ndard: No Quantity: EACH As-built: 0  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 3 of 3  Floor 2 - Hall H0201  N/A  Poors or Gates  Door Closer - Exterior Sweep Period  2010 ADAS 404.2.8.1  ndard: No Quantity: EACH As-built: 0  Door closer lacks min. 5 second sweep period   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 3 of 3 Floor 2 - Hall H0201 N/A Poors or Gates Door Closer - Exterior Sweep Period 2010 ADAS 404.2.8.1  ndard: No Quantity: EACH As-built: 0  Door closer lacks min. 5 second sweep period  2 second sweep  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 3 of 3 Floor 2 - Hall H0201 N/A Y Coordinate: N/A Doors or Gates Door Closer - Exterior Sweep Period 2010 ADAS 404.2.8.1  ndard: No Quantity: EACH As-built: 0 Door closer lacks min. 5 second sweep period  2 second sweep  Replace or adiust existing closer 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 20K                       |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3                                |
| Location:               | Floor 2 - Hall H0201   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Hardware - Operation   |
| Code<br>References:     | 2010 ADAS 404.2.7  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                               |
| Barrier<br>Description: | Hardware not operable with a closed fist                             |
| Findings:               | Door hardware not operable with a closed fist                        |
| Rec. Solution:          | Provide new hardware   |
| Barrier Severity:       | 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 20L                       |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3                                |
| Location:               | Floor 2 - Hall H0201   |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Threshold - Height exceeding 1/2"                                    |
| Code<br>References:     | 2010 ADAS 404.2.5  |
| Performance Sta         | andard: No Quantity: EACH As-built: 1                                |
| Barrier<br>Description: | Door/Gate threshold exceeds 1/2" in height                           |
| Findings:               | 1-1/4" high  |
| Rec. Solution:          | Provide new door threshold   |
| Barrier Severity:       | 1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 21A   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3  |
| Location:               | Floor 2 - Workroom 0204  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Signage  |
| Barrier Type:           | Permanent Room/Space - Tactile Characters  |
| Code<br>References:     | 2010 ADAS 216.2  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | No tactile characters at sign identifying permanent rooms and spaces with visual signs |
| Findings:               | No tactile signage provided at door within public route                                |
| Rec. Solution:          | Provide accessible sign  |
| Barrier Severity:       | 1 Necessary Cost Est \$250.00 Facility Function: Public Status: Open                   |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                                 |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 21B   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3  |
| Location:               | Floor 2 - Workroom 0204  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Door Closer - Interior Adjustment  |
| Code<br>References:     | 2010 ADAS 404.2.9  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Door opening force exceeds 5 lbf   |
| Findings:               | 12 lbf   |
| Rec. Solution:          | Replace or adjust existing closer  |
| Barrier Severity:       | 1 Necessary Cost Est \$450.00 Facility Function: Public Status: Open                   |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                 |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 21C                                   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3  |
| Location:               | Floor 2 - Workroom 0204  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Door Closer - Interior Sweep Period  |
| Code<br>References:     | 2010 ADAS 404.2.8.1  |
| Performance Sta         | andard: No Quantity: EACH As-built : 0   |
| Barrier<br>Description: | Door closer lacks min. 5 second sweep period or does not stop 5" from door frame |
| Findings:               | 2 second sweep   |
| Rec. Solution:          | Replace closer or provide automatic door opening device                          |
| Barrier Severity:       | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open             |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 21D                                   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3  |
| Location:               | Floor 2 - Workroom 0204  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Hardware - Operation   |
| Code<br>References:     | 2010 ADAS 404.2.7  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Hardware not operable with a closed fist   |
| Findings:               | Door hardware not operable with a closed fist                                    |
| Rec. Solution:          | Provide new hardware   |
| Barrier Severity:       | 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open             |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                           |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 21E   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3  |
| Location:               | Floor 2 - Workroom 0204  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Signage  |
| Barrier Type:           | Permanent Room/Space - Tactile Characters  |
| Code<br>References:     | 2010 ADAS 216.2  |
| Performance Sta         | andard: No Quantity: EACH As-built : 6   |
| Barrier<br>Description: | No tactile characters at sign identifying permanent rooms and spaces with visual signs |
| Findings:               | No tactile signage provided at rooms 203, 203A, 204A, 204C, 204D within public route   |
| Rec. Solution:          | Provide accessible sign  |
| Barrier Severity:       | 1 Necessary Cost Est \$1,500.00 Facility Function: Public Status: Open                 |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                                 |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 21F   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3  |
| Location:               | Floor 2 - Workroom 0204  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Controls and Mechanisms  |
| Barrier Type:           | Clear Floor Space - Stored Elements  |
| Code<br>References:     | 2010 ADAS 305.3  |
| Performance Sta         | andard: No Quantity: JOB As-built: 1   |
| Barrier<br>Description: | Clear floor space for wheelchair not provided at control or mechanism                  |
| Findings:               | Trash bin blocks clear floor space at electrical switch                                |
| Rec. Solution:          | Move stored items  |
| Barrier Severity:       | 1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open                   |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                                 |
| Notes:                  |  |



| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 21G   |
|---|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3  |
| Location:   | Floor 2 - Workroom 0204  |
| X Coordinate:   | N/A Y Coordinate: N/A  |
| Barrier Area:   | Controls and Mechanisms  |
| Barrier Type:   | Electrical Switches - Height   |
| Code<br>References:   | 2010 ADAS 308.2  |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description:   | Light switch control box top edge not at max. 48" high   |
| Findings:   | 50-7/8" high   |
| Rec. Solution:  | Relocate switch box top edge to max. 48" high  |
| Barrier Severity:   | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open   |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:  |  |
|   |  |
| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 21H   |
| Field Date:<br>Bldg Name:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 21H  Merryfield Hall Reference Dwg: 3 of 3  |
|   |  |
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3  |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 3 of 3 Floor 2 - Workroom 0204  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A  Y Coordinate: N/A  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A  Y Coordinate: N/A  Clear Floor Space   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A  Y Coordinate: N/A  Clear Floor Space  Protruding Object  2010 ADAS 307   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A  Y Coordinate: N/A  Clear Floor Space  Protruding Object  2010 ADAS 307   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A  Y Coordinate: N/A  Clear Floor Space  Protruding Object  2010 ADAS 307  ndard: No Quantity: EACH As-built: 1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A  Y Coordinate: N/A  Clear Floor Space  Protruding Object  2010 ADAS 307  ndard: No Quantity: EACH As-built: 1  Protruding object in circulation path protrudes more than 4" between 27" and 80" high  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 3 of 3 Floor 2 - Workroom 0204 N/A Y Coordinate: N/A Clear Floor Space Protruding Object 2010 ADAS 307  Indard: No Quantity: EACH As-built: 1 Protruding object in circulation path protrudes more than 4" between 27" and 80" high  Mechanical box protrudes 7-1/8" at 37-1/2" high  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A Y Coordinate: N/A  Clear Floor Space Protruding Object 2010 ADAS 307  Indiard: No Quantity: EACH As-built: 1  Protruding object in circulation path protrudes more than 4" between 27" and 80" high  Mechanical box protrudes 7-1/8" at 37-1/2" high  Remove object or provide detectable warning (wing walls)  Remove object or provide detectable warning (wing walls)  I Necessary Cost Est \$550.00 Facility Function: Public Status: Open |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 211                       |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3                                |
| Location:               | Floor 2 - Workroom 0204  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Controls and Mechanisms  |
| Barrier Type:           | Mailbox - High Reach Range   |
| Code<br>References:     | 2010 ADAS 308.2.2  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                               |
| Barrier<br>Description: | Mailbox opening is above 48" high                                    |
| Findings:               | Faculty mailboxes 8" - 64-1/2" high                                  |
| Rec. Solution:          | Relocate to provide opening at max. 48" high or provide assistance   |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 21J                       |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3                                |
| Location:               | Floor 2 - Workroom 0204  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Clear Floor Space  |
| Barrier Type:           | Passageway - Min. 36" (Stored Item)                                  |
| Code<br>References:     | 2010 ADAS 403.5.1  |
| Performance Sta         | andard: No Quantity: JOB As-built : 1                                |
| Barrier<br>Description: | Circulation route not min. 36" wide between elements                 |
| Findings:               | 24" wide circulation route around center table                       |
| Rec. Solution:          | Rearrange table to provide accessible circulation route              |
| Barrier Severity:       | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open   |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:               |
| Notes:                  |  |



| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 21K   |
|---|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3  |
| Location:   | Floor 2 - Workroom 0204  |
| X Coordinate:   | N/A Y Coordinate: N/A  |
| Barrier Area:   | Clear Floor Space  |
| Barrier Type:   | Cords in Accessible Route  |
| Code<br>References:   | 2010 ADAS 303.3  |
| Performance Sta   | ndard: No Quantity: JOB As-built : 1   |
| Barrier<br>Description:   | Change in level greater than 1/2" in clear floor space at cords  |
| Findings:   | Cords create trip hazard   |
| Rec. Solution:  | Provide accessible cord cover or otherwise remove barrier to access  |
| Barrier Severity:   | 1 Necessary Cost Est \$75.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:  |  |
|   |  |
| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 21L   |
| Field Date:<br>Bldg Name:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 21L  Merryfield Hall Reference Dwg: 3 of 3  |
|   |  |
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3  |
| Bldg Name:<br>Location:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A  Y Coordinate: N/A  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A  Y Coordinate: N/A  Counters and Tables   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A  Y Coordinate: N/A  Counters and Tables  Table - Knee Clearance  2010 ADAS 305.3  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A  Y Coordinate: N/A  Counters and Tables  Table - Knee Clearance  2010 ADAS 305.3  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A  Y Coordinate: N/A  Counters and Tables  Table - Knee Clearance  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 1  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A  Y Coordinate: N/A  Counters and Tables  Table - Knee Clearance  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 1  Knee clearance not min. 27" high, 19" deep or 30" wide   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 3 of 3 Floor 2 - Workroom 0204 N/A Y Coordinate: N/A  Counters and Tables Table - Knee Clearance 2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 1  Knee clearance not min. 27" high, 19" deep or 30" wide  26-1/4" high knee clearance   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A Y Coordinate: N/A  Counters and Tables  Table - Knee Clearance  2010 ADAS 305.3  ndard: No Quantity: EACH As-built: 1  Knee clearance not min. 27" high, 19" deep or 30" wide  26-1/4" high knee clearance  Provide min. 1 accessible table. Avoid pedestal base tables.  3 Hindrance Cost Est \$450.00 Facility Function: Public Status: Open |



| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 21M   |
|---|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3  |
| Location:   | Floor 2 - Workroom 0204  |
| X Coordinate:   | N/A Y Coordinate: N/A  |
| Barrier Area:   | Controls and Mechanisms  |
| Barrier Type:   | Clear Floor Space - Stored Elements  |
| Code<br>References:   | 2010 ADAS 305.3  |
| Performance Sta   | ndard: No Quantity: JOB As-built : 1   |
| Barrier<br>Description:   | Clear floor space for wheelchair not provided at control or mechanism  |
| Findings:   | Boxes block clear floor space at printer, outlet, and mailbox  |
| Rec. Solution:  | Move stored items  |
| Barrier Severity:   | 1 Necessary Cost Est \$125.00 Facility Function: Public Status: Open   |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:   |
| Notes:  |  |
|   |  |
| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 21N   |
| Field Date:<br>Bldg Name:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 21N  Merryfield Hall Reference Dwg: 3 of 3  |
|   |  |
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3  |
| Bldg Name:<br>Location:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A  Y Coordinate: N/A  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A  Y Coordinate: N/A  Controls and Mechanisms   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A  Y Coordinate: N/A  Controls and Mechanisms  Mailbox - High Reach Range  2010 ADAS 308.2.2  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A  Y Coordinate: N/A  Controls and Mechanisms  Mailbox - High Reach Range  2010 ADAS 308.2.2  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A  Y Coordinate: N/A  Controls and Mechanisms  Mailbox - High Reach Range  2010 ADAS 308.2.2  ndard: No Quantity: EACH As-built: 1  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A Y Coordinate: N/A  Controls and Mechanisms  Mailbox - High Reach Range  2010 ADAS 308.2.2  Indard: No Quantity: EACH As-built: 1  Mailbox opening is above 48" high  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 3 of 3 Floor 2 - Workroom 0204 N/A Y Coordinate: N/A  Controls and Mechanisms Mailbox - High Reach Range 2010 ADAS 308.2.2  Indard: No Quantity: EACH As-built: 1  Mailbox opening is above 48" high  57" high drop box opening   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Workroom 0204  N/A  Y Coordinate: N/A  Controls and Mechanisms  Mailbox - High Reach Range  2010 ADAS 308.2.2  Indard: No Quantity: EACH As-built: 1  Mailbox opening is above 48" high  57" high drop box opening  Relocate to provide opening at max. 48" high or provide assistance  3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 210   |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3  |
| Location:               | Floor 2 - Workroom 0204  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Alarms   |
| Barrier Type:           | Horn/Strobe - Common Use Area  |
| Code<br>References:     | 2010 ADAS 702.1  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | No horn/strobes in common use areas  |
| Findings:               | No device provided   |
| Rec. Solution:          | Provide strobe in common use area  |
| Barrier Severity:       | 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open                 |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                                 |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 22A   |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3  |
| Location:               | Floor 2 - Breakroom 0204E  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Signage  |
| Barrier Type:           | Permanent Room/Space - Tactile Characters  |
| Code<br>References:     | 2010 ADAS 216.2  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 2  |
| Barrier<br>Description: | No tactile characters at sign identifying permanent rooms and spaces with visual signs |
| Findings:               | No tactile signage provided at main entry and room 201A within public route            |
| Rec. Solution:          | Provide accessible signs   |
| Barrier Severity:       | 1 Necessary Cost Est \$500.00 Facility Function: Public Status: Open                   |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                                 |
| Notes:                  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 22B                                 |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3  |
| Location:               | Floor 2 - Breakroom 0204E  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Hardware - Operation   |
| Code<br>References:     | 2010 ADAS 404.2.7  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 2  |
| Barrier<br>Description: | Hardware not operable with a closed fist                                       |
| Findings:               | Door hardware not operable with a closed fist                                  |
| Rec. Solution:          | Provide new hardware   |
| Barrier Severity:       | 1 Necessary Cost Est \$600.00 Facility Function: Public Status: Open           |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                         |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 22C                                 |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3  |
| Location:               | Floor 2 - Breakroom 0204E  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Doors or Gates   |
| Barrier Type:           | Clear Width  |
| Code<br>References:     | 2010 ADAS 404.2.3  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | Clear width passage through door, sliding/folding door or gate is not min. 32" |
| Findings:               | 29-3/4" wide   |
| Rec. Solution:          | Replace door or gate and frame   |
| Barrier Severity:       | 1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open         |
| Implementation          |  |
| Notes:                  |  |



| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 22D  |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3   |
| Location:   | Floor 2 - Breakroom 0204E   |
| X Coordinate:   | N/A Y Coordinate: N/A   |
| Barrier Area:   | Doors or Gates  |
| Barrier Type:   | Front App/push 12" SEC  |
| Code<br>References:   | 2010 ADAS Figure 404.2.4.1  |
| Performance Sta   | ndard: No Quantity: ADMINI As-built : 1   |
| Barrier<br>Description:   | Door/Gate at push side with min. 48" lacks min. 12" strike edge clearance with latch/closer   |
| Findings:   | Vacuum blocks strike edge clearance   |
| Rec. Solution:  | Remove stored item  |
| Barrier Severity:   | 1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:  |   |
|   |   |
| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 22E  |
| Field Date: Bldg Name:  | 1/26/2017   Report Date   2/22/2017   Barrier #:   22E   Merryfield Hall   Reference Dwg:   3 of 3  |
|   |   |
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 0204E   |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A   |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Doors or Gates   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Doors or Gates  Front App/pull 18" SEC - Relocate Door  2010 ADAS Figure 404.2.4.1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Doors or Gates  Front App/pull 18" SEC - Relocate Door  2010 ADAS Figure 404.2.4.1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Doors or Gates  Front App/pull 18" SEC - Relocate Door  2010 ADAS Figure 404.2.4.1  ndard: No Quantity: EACH As-built: 1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Doors or Gates  Front App/pull 18" SEC - Relocate Door  2010 ADAS Figure 404.2.4.1  ndard: No Quantity: EACH As-built: 1  Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Doors or Gates  Front App/pull 18" SEC - Relocate Door  2010 ADAS Figure 404.2.4.1  ndard: No Quantity: EACH As-built: 1  Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side  Counter reduces strike edge clearance to 4-1/2"  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Doors or Gates  Front App/pull 18" SEC - Relocate Door  2010 ADAS Figure 404.2.4.1  ndard: No Quantity: EACH As-built: 1  Door/Gate at pull side with min. 60" lacks min. 18" strike edge clearance at pull side  Counter reduces strike edge clearance to 4-1/2"  Relocate door or remodel to provide maneuvering clearance  1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 22F  |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3   |
| Location:               | Floor 2 - Breakroom 0204E   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Counters and Tables   |
| Barrier Type:           | Counter - Surface Height  |
| Code<br>References:     | 2010 ADAS 902.3   |
| Performance Sta         | andard: No Quantity: EACH As-built : 1  |
| Barrier<br>Description: | No section at least 3 feet long between 28" and 34" provided at existing counter                  |
| Findings:               | 35-1/2" high  |
| Rec. Solution:          | Provide min. 3 ft long section of counter at max. 34" high  |
| Barrier Severity:       | 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open                              |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:  |
| Notes:                  |   |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 22G  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3   |
| Location:               | Floor 2 - Breakroom 0204E   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Counters and Tables   |
| Barrier Type:           | Counter - Knee Clearance  |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | andard: No Quantity: EACH As-built: 1   |
| Barrier<br>Description: | Knee clearance not min. 27" high, 19" deep or 30" wide  |
| Findings:               | No knee clearance   |
| Rec. Solution:          | Provide min. 3 ft segment of accessible counter. Flip-up counters, adiacent tables and similar de |
| Barrier Severity:       | 3 Hindrance Cost Est \$875.00 Facility Function: Public Status: Open                              |
| Implementation          |   |
| Notes:                  |   |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 22H                                      |
|-------------------------|---|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3   |
| Location:               | Floor 2 - Breakroom 0204E   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Controls and Mechanisms   |
| Barrier Type:           | First Aid Kit - Obstructed Reach Range  |
| Code<br>References:     | 2010 ADAS 305.3   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Opening mechanism on first aid kit not at max. 44" over an obstruction of max. 25"  |
| Findings:               | 58" high and 24" deep   |
| Rec. Solution:          | Relocate control or mechanism   |
| Barrier Severity:       | 1 Necessary Cost Est \$275.00 Facility Function: Public Status: Open                |
| Implementation          | Priority: 2 Implementation Phase: Implementation Date:                              |
| Notes:                  |   |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 22I                                      |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3   |
| Location:               | Floor 2 - Breakroom 0204E   |
| X Coordinate:           | N/A Y Coordinate: N/A   |
| Barrier Area:           | Controls and Mechanisms   |
| Barrier Type:           | Electrical Outlets - Hi/Low Reach   |
| Code<br>References:     | 2010 ADAS 308.2.2   |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description: | Use of outlet involves low reach of less than 15" above floor or more than 48" high |
| Findings:               | 49" high  |
| Rec. Solution:          | Relocate outlet to area at min. 15" or max. 48" high                                |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open                |
| Implementation          |   |
| Notes:                  |   |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 22J                         |
|-------------------------|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3                                  |
| Location:               | Floor 2 - Breakroom 0204E  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Alarms   |
| Barrier Type:           | Horn/Strobe - Common Use Area  |
| Code<br>References:     | 2010 ADAS 702.1  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                  |
| Barrier<br>Description: | No horn/strobes in common use areas                                    |
| Findings:               | No device provided   |
| Rec. Solution:          | Provide strobe in common use area                                      |
| Barrier Severity:       | 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open |
| Implementation          | Priority: 1 Implementation Phase: Implementation Date:                 |
| Notes:                  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 22K                         |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3                                  |
| Location:               | Floor 2 - Breakroom 0204E  |
| X Coordinate:           | N/A Y Coordinate: N/A  |
| Barrier Area:           | Controls and Mechanisms  |
| Barrier Type:           | Electrical Switches - Height   |
| Code<br>References:     | 2010 ADAS 308.2  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                  |
| Barrier<br>Description: | Light switch control box top edge not at max. 48" high                 |
| Findings:               | 49-1/2" high   |
| Rec. Solution:          | Relocate switch box top edge to max. 48" high                          |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open   |
| Implementation          |  |
| Notes:                  |  |



| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 22L  |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3   |
| Location:   | Floor 2 - Breakroom 0204E   |
| X Coordinate:   | N/A Y Coordinate: N/A   |
| Barrier Area:   | Restrooms   |
| Barrier Type:   | Urinal - Alcove   |
| Code<br>References:   | 2010 ADAS 305.7.1   |
| Performance Sta   | ndard: No Quantity: SF As-built : 0   |
| Barrier<br>Description:   | Urinal located in alcove lacks at least 36" clear width in alcove more than 24" deep  |
| Findings:   | Lavatory alcove 26" wide and 39" deep   |
| Rec. Solution:  | Remodel sanitary facility to provide access   |
| Barrier Severity:   | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 3 Implementation Phase: Implementation Date:  |
| Notes:  |   |
|   |   |
| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 22M  |
| Field Date:<br>Bldg Name:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 22M  Merryfield Hall Reference Dwg: 3 of 3   |
|   |   |
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E   |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A   |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Lavatory - Clear Floor Space  2010 ADAS 606.2   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Lavatory - Clear Floor Space  2010 ADAS 606.2   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Lavatory - Clear Floor Space  2010 ADAS 606.2  ndard: No Quantity: JOB As-built: 80   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Lavatory - Clear Floor Space  2010 ADAS 606.2  ndard: No Quantity: JOB As-built: 80  No clear floor space 30" x 48" at lavatory to allow forward approach  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 0204E N/A Y Coordinate: N/A Restrooms Lavatory - Clear Floor Space 2010 ADAS 606.2  ndard: No Quantity: JOB As-built: 80 No clear floor space 30" x 48" at lavatory to allow forward approach  26" wide alcove  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Lavatory - Clear Floor Space  2010 ADAS 606.2  ndard: No Quantity: JOB As-built: 80  No clear floor space 30" x 48" at lavatory to allow forward approach  26" wide alcove  Remodel to provide min. 1 accessible lavatory  1 Necessary Cost Est \$46,000.00 Facility Function: Public Status: Open |



| Field Date:  | 1/26/2017 Report Date 2/22/2017 Barrier #: 22N   |
|--|--|
| Bldg Name:   | Merryfield Hall Reference Dwg: 3 of 3  |
| Location:  | Floor 2 - Breakroom 0204E  |
| X Coordinate:  | N/A Y Coordinate: N/A  |
| Barrier Area:  | Restrooms  |
| Barrier Type:  | Lavatory - Centerline  |
| Code<br>References:  | 2010 ADAS 606  |
| Performance Sta  | ndard: No Quantity: JOB As-built : 1   |
| Barrier<br>Description:  | Lavatory adjacent to wall not min. 15" to the centerline of fixture  |
| Findings:  | 12-1/2" to centerline of fixture   |
| Rec. Solution:   | Relocate or replace lavatory   |
| Barrier Severity:  | 2 Recommended Cost Est \$450.00 Facility Function: Public Status: Open   |
| Implementation   | Priority: 3 Implementation Phase: Implementation Date:   |
| Notes:   |  |
| Field Date:  | 1/26/2017 Report Date 2/22/2017 Barrier #: 220   |
| Bldg Name:   | Merryfield Hall Reference Dwg: 3 of 3  |
|  |  |
| Location:  | Floor 2 - Breakroom 0204E  |
| Location:<br>X Coordinate:   |  |
|  | Floor 2 - Breakroom 0204E  |
| X Coordinate:  | Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  |
| X Coordinate:<br>Barrier Area:   | Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms   |
| X Coordinate:<br>Barrier Area:<br>Barrier Type:<br>Code  | Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Lavatory - Rim Height  2010 ADAS 606.3   |
| X Coordinate: Barrier Area: Barrier Type: Code References:   | Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Lavatory - Rim Height  2010 ADAS 606.3   |
| X Coordinate:<br>Barrier Area:<br>Barrier Type:<br>Code<br>References:<br>Performance Sta<br>Barrier                     | Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Lavatory - Rim Height  2010 ADAS 606.3  ndard: No Quantity: JOB As-built: 0  |
| X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Lavatory - Rim Height  2010 ADAS 606.3  ndard: No Quantity: JOB As-built: 0  Lavatory rim or counter edge is higher than 34" AFF   |
| X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Lavatory - Rim Height  2010 ADAS 606.3  ndard: No Quantity: JOB As-built: 0  Lavatory rim or counter edge is higher than 34" AFF  34-1/4" high   |
| X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Lavatory - Rim Height  2010 ADAS 606.3  ndard: No Quantity: JOB As-built: 0  Lavatory rim or counter edge is higher than 34" AFF  34-1/4" high  Replace lavatory  1 Necessary Cost Est \$0.00 Facility Function: Public Status: Open |



| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 22P  |
|---|---|
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3   |
| Location:   | Floor 2 - Breakroom 0204E   |
| X Coordinate:   | N/A Y Coordinate: N/A   |
| Barrier Area:   | Restrooms   |
| Barrier Type:   | Lavatory - Drainpipes   |
| Code<br>References:   | 2010 ADAS 606.5   |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1   |
| Barrier<br>Description:   | Hot water and drainpipes accessible under lavatory not insulated or covered   |
| Findings:   | No insulation provided  |
| Rec. Solution:  | Insulate drainpipes and hot water pipes   |
| Barrier Severity:   | 2 Recommended Cost Est \$220.00 Facility Function: Public Status: Open  |
| Implementation  | Priority: 3 Implementation Phase: Implementation Date:  |
| Notes:  |   |
|   |   |
| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 22Q  |
| Field Date:<br>Bldg Name:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 22Q  Merryfield Hall Reference Dwg: 3 of 3   |
|   |   |
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3   |
| Bldg Name:<br>Location:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E   |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A   |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Mirror  2010 ADAS 603.3   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Mirror  2010 ADAS 603.3   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Mirror  2010 ADAS 603.3  ndard: No Quantity: EACH As-built: 1   |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Mirror  2010 ADAS 603.3  ndard: No Quantity: EACH As-built: 1  Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 0204E N/A Y Coordinate: N/A Restrooms Mirror 2010 ADAS 603.3  ndard: No Quantity: EACH As-built: 1  Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface  52" high  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Restrooms  Mirror  2010 ADAS 603.3  Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface  52" high  Replace or remount mirror  3 Hindrance  Cost Est \$375.00  Facility Function: Public  Status: Open |



| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 22R   |  |  |  |  |
|---|--|--|--|--|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3  |  |  |  |  |
| Location:   | Floor 2 - Breakroom 0204E  |  |  |  |  |
| X Coordinate:   | N/A Y Coordinate: N/A  |  |  |  |  |
| Barrier Area:   | Restrooms  |  |  |  |  |
| Barrier Type:   | Dispensers - Height  |  |  |  |  |
| Code<br>References:   | 2010 ADAS 307.2  |  |  |  |  |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1  |  |  |  |  |
| Barrier<br>Description:   | 1   1   1   1   1   1   1   1   1   1  |  |  |  |  |
| Findings:   | Paper towel dispenser 51" high   |  |  |  |  |
| Rec. Solution:  | Remount no higher than 48" above floor   |  |  |  |  |
| Barrier Severity:   |  |  |  |  |  |
| Implementation  | Priority: 3 Implementation Phase: Implementation Date:   |  |  |  |  |
| Notes:  |  |  |  |  |  |
|   |  |  |  |  |  |
| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 22S   |  |  |  |  |
| Field Date:<br>Bldg Name:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 22S  Merryfield Hall Reference Dwg: 3 of 3  |  |  |  |  |
|   |  |  |  |  |  |
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3  |  |  |  |  |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 0204E  |  |  |  |  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  |  |  |  |  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms   |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Dispensers - Protruding Object  2010 ADAS 307.2  |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Dispensers - Protruding Object  2010 ADAS 307.2  |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Dispensers - Protruding Object  2010 ADAS 307.2  ndard: No Quantity: EACH As-built: 1  |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Dispensers - Protruding Object  2010 ADAS 307.2  ndard: No Quantity: EACH As-built: 1  Protruding dispenser creates protruding object in path of travel   |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 3 of 3 Floor 2 - Breakroom 0204E N/A Y Coordinate: N/A Restrooms Dispensers - Protruding Object 2010 ADAS 307.2  ndard: No Quantity: EACH As-built: 1 Protruding dispenser creates protruding object in path of travel  Paper towel dispenser protrudes 10" at 52" high   |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 3 of 3  Floor 2 - Breakroom 0204E  N/A  Y Coordinate: N/A  Restrooms  Dispensers - Protruding Object  2010 ADAS 307.2  Protruding dispenser creates protruding object in path of travel  Paper towel dispenser protrudes 10" at 52" high  Relocate dispenser or provide cane-detectable warning  2 Recommended Cost Est \$550.00 Facility Function: Public Status: Open |  |  |  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 23A                       |  |  |  |  |
|-------------------------|--|--|--|--|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3                                |  |  |  |  |
| Location:               | Floor 2 - Unisex Toilet Room 0204F                                   |  |  |  |  |
| X Coordinate:           | N/A Y Coordinate: N/A  |  |  |  |  |
| Barrier Area:           | Restrooms  |  |  |  |  |
| Barrier Type:           | Sign - No Braille/tactile Sign                                       |  |  |  |  |
| Code<br>References:     | 2010 ADAS 703.2.3  |  |  |  |  |
| Performance Sta         | andard: No Quantity: EACH As-built : 1                               |  |  |  |  |
| Barrier<br>Description: | No Braille/tactile sign at latch side of door                        |  |  |  |  |
| Findings:               | No Braille/tactile sign provided at restroom                         |  |  |  |  |
| Rec. Solution:          | Provide Braille/tactile sign at latch side of door                   |  |  |  |  |
| Barrier Severity:       |  |  |  |  |  |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:               |  |  |  |  |
| Notes:                  |  |  |  |  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 23B                       |  |  |  |  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3                                |  |  |  |  |
| Location:               | Floor 2 - Unisex Toilet Room 0204F                                   |  |  |  |  |
| X Coordinate:           | N/A Y Coordinate: N/A  |  |  |  |  |
| Barrier Area:           | Restrooms  |  |  |  |  |
| Barrier Type:           | Door Hardware - Operation  |  |  |  |  |
| Code<br>References:     | 2010 ADAS 404.2.7  |  |  |  |  |
| Performance Sta         | andard: No Quantity: EACH As-built: 1                                |  |  |  |  |
| Barrier<br>Description: | Operating controls involve tight grasping, pinching or twisting      |  |  |  |  |
| Findings:               | Hardware not operable with a closed fist                             |  |  |  |  |
| Rec. Solution:          | Replace hardware   |  |  |  |  |
| Barrier Severity:       | 1 Necessary Cost Est \$300.00 Facility Function: Public Status: Open |  |  |  |  |
| Implomentation          | Truction:  Fubic states:  Open                                       |  |  |  |  |
| пприетнентаціон         | Priority: 3 Implementation Phase: Implementation Date:               |  |  |  |  |



| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 23C   |  |  |  |  |
|---|--|--|--|--|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3  |  |  |  |  |
| Location:   | Floor 2 - Unisex Toilet Room 0204F   |  |  |  |  |
| X Coordinate:   | N/A Y Coordinate: N/A  |  |  |  |  |
| Barrier Area:   | Restrooms  |  |  |  |  |
| Barrier Type:   | Door Clear Width   |  |  |  |  |
| Code<br>References:   | 2010 ADAS 404.2.3  |  |  |  |  |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1  |  |  |  |  |
| Barrier<br>Description:   | Door clear width is not min. 32"   |  |  |  |  |
| Findings:   | 23" clear width  |  |  |  |  |
| Rec. Solution:  | Replace door/gate and frame  |  |  |  |  |
| Barrier Severity:   | 1 Necessary Cost Est \$2,250.00 Facility Function: Public Status: Open   |  |  |  |  |
| Implementation  | Priority: 3 Implementation Phase: Implementation Date:   |  |  |  |  |
| Notes:  |  |  |  |  |  |
|   |  |  |  |  |  |
| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 23D   |  |  |  |  |
| Field Date:<br>Bldg Name:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 23D  Merryfield Hall Reference Dwg: 3 of 3  |  |  |  |  |
|   |  |  |  |  |  |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 3 of 3  |  |  |  |  |
| Bldg Name:<br>Location:   | Merryfield Hall Reference Dwg: 3 of 3 Floor 2 - Unisex Toilet Room 0204F   |  |  |  |  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A  Y Coordinate: N/A  Restrooms  Stall Door Closer   |  |  |  |  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A  Y Coordinate: N/A  Restrooms  |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A  Y Coordinate: N/A  Restrooms  Stall Door Closer  2010 ADAS 604.8.1.2  |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A  Y Coordinate: N/A  Restrooms  Stall Door Closer  2010 ADAS 604.8.1.2  |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier                                       | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A  Y Coordinate: N/A  Restrooms  Stall Door Closer  2010 ADAS 604.8.1.2  ndard: No Quantity: JOB As-built: 1   |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A  Y Coordinate: N/A  Restrooms  Stall Door Closer  2010 ADAS 604.8.1.2  Indard: No Quantity: JOB As-built: 1  Stall door not equipped with an automatic closing device  |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 3 of 3 Floor 2 - Unisex Toilet Room 0204F N/A Y Coordinate: N/A Restrooms Stall Door Closer 2010 ADAS 604.8.1.2  Indard: No Quantity: JOB As-built: 1 Stall door not equipped with an automatic closing device  Door does not self close  Replace compartment hinge with adjustable mechanism   |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A  Y Coordinate: N/A  Restrooms  Stall Door Closer  2010 ADAS 604.8.1.2  Indard: No Quantity: JOB As-built: 1  Stall door not equipped with an automatic closing device  Door does not self close  Replace compartment hinge with adjustable mechanism  2 Recommended Cost Est \$1,650.00 Facility Function: Public Status: Open |  |  |  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 23E                               |  |  |  |  |
|-------------------------|--|--|--|--|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3  |  |  |  |  |
| Location:               | Floor 2 - Unisex Toilet Room 0204F   |  |  |  |  |
| X Coordinate:           | N/A Y Coordinate: N/A  |  |  |  |  |
| Barrier Area:           | Restrooms  |  |  |  |  |
| Barrier Type:           | Maneuvering Clearance  |  |  |  |  |
| Code<br>References:     | 2010 ADAS 603.2.1  |  |  |  |  |
| Performance Sta         | ndard: No Quantity: SF As-built : 80   |  |  |  |  |
| Barrier<br>Description: | Entry door encroaches into min. 60" turning space by more than 12"           |  |  |  |  |
| Findings:               | Door encroaches into turning space   |  |  |  |  |
| Rec. Solution:          | Remodel toilet room to provide wheelchair access after elevator is installed |  |  |  |  |
| Barrier Severity:       | 2 Recommended Cost Est \$46,000.00 Facility Function: Public Status: Open    |  |  |  |  |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                       |  |  |  |  |
| Notes:                  |  |  |  |  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 23F                               |  |  |  |  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3  |  |  |  |  |
| Location:               | Floor 2 - Unisex Toilet Room 0204F   |  |  |  |  |
| X Coordinate:           | N/A Y Coordinate: N/A  |  |  |  |  |
| Barrier Area:           | Restrooms  |  |  |  |  |
| Barrier Type:           | Electrical Switches  |  |  |  |  |
| Code<br>References:     | 2010 ADAS 205.1 & 309.3  |  |  |  |  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1  |  |  |  |  |
| Barrier<br>Description: | Light switch control box top edge not at max. 48" high                       |  |  |  |  |
| Findings:               | 51" high   |  |  |  |  |
| Rec. Solution:          | Relocate switch box top edge to max. 48" high                                |  |  |  |  |
| Barrier Severity:       | 3 Hindrance Cost Est \$750.00 Facility Function: Public Status: Open         |  |  |  |  |
| Implementation          |  |  |  |  |  |
| Notes:                  |  |  |  |  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 23G                                   |  |  |  |  |
|-------------------------|--|--|--|--|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3  |  |  |  |  |
| Location:               | Floor 2 - Unisex Toilet Room 0204F   |  |  |  |  |
| X Coordinate:           | N/A Y Coordinate: N/A  |  |  |  |  |
| Barrier Area:           | Restrooms  |  |  |  |  |
| Barrier Type:           | Toilet Transfer - Floor-mounted  |  |  |  |  |
| Code<br>References:     | 2010 ADAS 604.8.1.1  |  |  |  |  |
| Performance Sta         | andard: No Quantity: SF As-built : 25  |  |  |  |  |
| Barrier<br>Description: | Min. 60" wide x 59" deep clear floor space not provided at floor-mounted fixture |  |  |  |  |
| Findings:               | 58" deep x 60" wide but obstructed by shelves and pipe                           |  |  |  |  |
| Rec. Solution:          | Remodel toilet room to provide wheelchair access after elevator is installed     |  |  |  |  |
| Barrier Severity:       | 2 Recommended Cost Est \$0.00 Facility Function: Public Status: Open             |  |  |  |  |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                           |  |  |  |  |
| Notes:                  |  |  |  |  |  |
| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 23H                                   |  |  |  |  |
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3  |  |  |  |  |
| Location:               | Floor 2 - Unisex Toilet Room 0204F   |  |  |  |  |
| X Coordinate:           | N/A Y Coordinate: N/A  |  |  |  |  |
| Barrier Area:           | Restrooms  |  |  |  |  |
| Barrier Type:           | Toilet - Grab Bars   |  |  |  |  |
| Code<br>References:     | 2010 ADAS 604.5  |  |  |  |  |
| Performance Sta         | andard: No Quantity: JOB As-built : 1  |  |  |  |  |
| Barrier<br>Description: | No grab bars provided at water closet  |  |  |  |  |
| Findings:               | No grab bars provided  |  |  |  |  |
| Rec. Solution:          | Provide side and rear grab bars with reinforcement                               |  |  |  |  |
| Barrier Severity:       | 1 Necessary Cost Est \$900.00 Facility Function: Public Status: Open             |  |  |  |  |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                           |  |  |  |  |
| Notes:                  |  |  |  |  |  |



| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 23I  |  |  |  |  |
|---|---|--|--|--|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3   |  |  |  |  |
| Location:   | Floor 2 - Unisex Toilet Room 0204F  |  |  |  |  |
| X Coordinate:   | N/A Y Coordinate: N/A   |  |  |  |  |
| Barrier Area:   | Restrooms   |  |  |  |  |
| Barrier Type:   | Toilet - Seat Height  |  |  |  |  |
| Code<br>References:   | 2010 ADAS 604.4   |  |  |  |  |
| Performance Sta   | ndard: No Quantity: JOB As-built : 1  |  |  |  |  |
| Barrier<br>Description:   | Water closet seat not between 17" to 19" high   |  |  |  |  |
| Findings:   | 15-1/2" high  |  |  |  |  |
| Rec. Solution:  | Replace water closet  |  |  |  |  |
| Barrier Severity:   | 2 Recommended Cost Est \$850.00 Facility Function: Public Status: Open  |  |  |  |  |
| Implementation  | Priority: 3 Implementation Phase: Implementation Date:  |  |  |  |  |
| Notes:  |   |  |  |  |  |
|   |   |  |  |  |  |
| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 23J  |  |  |  |  |
| Field Date:<br>Bldg Name:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 23J  Merryfield Hall Reference Dwg: 3 of 3   |  |  |  |  |
|   |   |  |  |  |  |
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3   |  |  |  |  |
| Bldg Name:<br>Location:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  |  |  |  |  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A  Y Coordinate: N/A  |  |  |  |  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A  Y Coordinate: N/A  Restrooms   |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A  Y Coordinate: N/A  Restrooms  Toilet Centerline  2010 ADAS 604.2   |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A  Y Coordinate: N/A  Restrooms  Toilet Centerline  2010 ADAS 604.2   |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A  Y Coordinate: N/A  Restrooms  Toilet Centerline  2010 ADAS 604.2  ndard: No Quantity: JOB As-built: 1  |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A  Y Coordinate: N/A  Restrooms  Toilet Centerline  2010 ADAS 604.2  ndard: No Quantity: JOB As-built: 1  Water closet centerline not between 16" and 18" O. C.  |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 3 of 3 Floor 2 - Unisex Toilet Room 0204F N/A Y Coordinate: N/A Restrooms Toilet Centerline 2010 ADAS 604.2  Indard: No Quantity: JOB As-built: 1 Water closet centerline not between 16" and 18" O. C.  30" on center   |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall Reference Dwg: 3 of 3 Floor 2 - Unisex Toilet Room 0204F N/A Y Coordinate: N/A Restrooms Toilet Centerline 2010 ADAS 604.2  ndard: No Quantity: JOB As-built: 1 Water closet centerline not between 16" and 18" O. C.  30" on center  Relocate water closet  3 Hindrance Cost Est \$850.00 Facility Function: Public Status: Open |  |  |  |  |



| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 23K  |  |  |  |  |
|---|---|--|--|--|--|
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3   |  |  |  |  |
| Location:   | Floor 2 - Unisex Toilet Room 0204F  |  |  |  |  |
| X Coordinate:   | N/A Y Coordinate: N/A   |  |  |  |  |
| Barrier Area:   | Restrooms   |  |  |  |  |
| Barrier Type:   | Toilet Paper Dispenser  |  |  |  |  |
| Code<br>References:   | 2010 ADAS 604.7   |  |  |  |  |
| Performance Sta   | ndard: No Quantity: EACH As-built : 1   |  |  |  |  |
| Barrier<br>Description:   | Toilet tissue dispenser not within 7" to 9" from front edge of toilet   |  |  |  |  |
| Findings:   | 24" high  |  |  |  |  |
| Rec. Solution:  | Reposition or replace toilet paper dispenser  |  |  |  |  |
| Barrier Severity:   | 3 Hindrance Cost Est \$225.00 Facility Function: Public Status: Open  |  |  |  |  |
| Implementation  | Priority: 3 Implementation Phase: Implementation Date:  |  |  |  |  |
| Notes:  |   |  |  |  |  |
|   |   |  |  |  |  |
| Field Date:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 23L  |  |  |  |  |
| Field Date:<br>Bldg Name:   | 1/26/2017 Report Date 2/22/2017 Barrier #: 23L  Merryfield Hall Reference Dwg: 3 of 3   |  |  |  |  |
|   |   |  |  |  |  |
| Bldg Name:  | Merryfield Hall Reference Dwg: 3 of 3   |  |  |  |  |
| Bldg Name:<br>Location:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  |  |  |  |  |
| Bldg Name:<br>Location:<br>X Coordinate:  | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A  Y Coordinate: N/A  |  |  |  |  |
| Bldg Name:<br>Location:<br>X Coordinate:<br>Barrier Area:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A  Y Coordinate: N/A  Restrooms   |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A  Y Coordinate: N/A  Restrooms  Seat Cover Dispenser  2010 ADAS 307.2  |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References:   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A  Y Coordinate: N/A  Restrooms  Seat Cover Dispenser  2010 ADAS 307.2  |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta   | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A  Y Coordinate: N/A  Restrooms  Seat Cover Dispenser  2010 ADAS 307.2  ndard: No Quantity: EACH As-built: 1  |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description:                          | Merryfield Hall Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A Y Coordinate: N/A  Restrooms Seat Cover Dispenser  2010 ADAS 307.2  Indard: No Quantity: EACH As-built: 1  Seat cover dispenser not located on an accessible route. Blocked by water closet  |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings:                | Merryfield Hall Reference Dwg: 3 of 3 Floor 2 - Unisex Toilet Room 0204F N/A Y Coordinate: N/A Restrooms Seat Cover Dispenser 2010 ADAS 307.2  Indard: No Quantity: EACH As-built: 1  Seat cover dispenser not located on an accessible route. Blocked by water closet  Access to dispenser blocked by water closet  Replace or remount dispenser on an accessible route with clear floor space   |  |  |  |  |
| Bldg Name: Location: X Coordinate: Barrier Area: Barrier Type: Code References: Performance Sta Barrier Description: Findings: Rec. Solution: | Merryfield Hall  Reference Dwg: 3 of 3  Floor 2 - Unisex Toilet Room 0204F  N/A  Restrooms  Seat Cover Dispenser  2010 ADAS 307.2  Indard: No Quantity: EACH As-built: 1  Seat cover dispenser not located on an accessible route. Blocked by water closet  Access to dispenser blocked by water closet  Replace or remount dispenser on an accessible route with clear floor space  2 Recommended Cost Est \$125.00 Facility Function: Public Status: Open |  |  |  |  |



| Field Date:             | 1/26/2017 Report Date 2/22/2017 Barrier #: 23M                         |  |  |  |  |
|-------------------------|--|--|--|--|--|
| Bldg Name:              | Merryfield Hall Reference Dwg: 3 of 3                                  |  |  |  |  |
| Location:               | Floor 2 - Unisex Toilet Room 0204F                                     |  |  |  |  |
| X Coordinate:           | N/A Y Coordinate: N/A  |  |  |  |  |
| Barrier Area:           | Restrooms  |  |  |  |  |
| Barrier Type:           | Alarm - Horn/Strobe  |  |  |  |  |
| Code<br>References:     | 2010 ADAS 702.1  |  |  |  |  |
| Performance Sta         | ndard: No Quantity: EACH As-built : 1                                  |  |  |  |  |
| Barrier<br>Description: | Where a fire alarm is installed, no horn/strobe provided               |  |  |  |  |
| Findings:               | No device provided   |  |  |  |  |
| Rec. Solution:          | Provide horn/strobe in sanitary facility                               |  |  |  |  |
| Barrier Severity:       | 1 Necessary Cost Est \$5,500.00 Facility Function: Public Status: Open |  |  |  |  |
| Implementation          | Priority: 3 Implementation Phase: Implementation Date:                 |  |  |  |  |
| Notes:                  |  |  |  |  |  |





# SUMMARY REPORT

| Cost Estimate Total         | \$777.070.00 |                           |        |
|-----------------------------|--------------|---------------------------|--------|
| Cost Estimate - Priority 1: | \$65,350.00  | % of Total Cost Estimate: | 8.41%  |
| Cost Estimate - Priority 2: | \$243,060.00 | % of Total Cost Estimate: | 31.28% |
| Cost Estimate - Priority 3: | \$468,660.00 | % of Total Cost Estimate: | 60.31% |
|                             |              |                           |        |